

Document: Form 291	Abbreviated Statement of Intent	
Issue: 5		
Related to: 4GNE 4GNW		
Page No. 1 of 5		

Unit	NW
Transport Scotland Manager	[REDACTED]
Scheme ID	16/NW/0310/100
Route/ Location	A83 Cairndow Summit
Link section/ Chainage	16520/05/1104
OI Number	TBC
L.A Number	TBC
Work code/ Type	0310
Description of Works	Filter Drain Material Renewal
Estimated Investigation Cost	-
Estimated Design Cost	[REDACTED]
Estimated Construction Cost	[REDACTED]

Description of Defect/ Problem:

Carriageway run off during periods of heavy rain which seems to be coming from the rock face at adjacent hillside.

Contaminated and silted filter drain for 200m. A drainage Investigation was carried out so see the extend of contamination.

The drainage issue scores No. 207 on the Drainage Strategy.

Proposed Solution:

Carry out a filter drain renewal scheme to address this affected filter drain by excavating the existing silted filter drain material and then Import new Filter Material.

Approx. 200m long x 1m wide and 0.3m deep.
60m³ in total.

Photographic Evidence from Site

Photograph 1



Photograph 2



Document:	Form 291
Issue:	5
Related to:	4GNE 4GNW
Page No.	2 of 5

Abbreviated Statement of Intent



Photograph 3



Photograph 4



Photograph 5



Document:	Form 291
Issue:	5
Related to:	4GNE 4GNW
Page No.	4 of 5

Abbreviated Statement of Intent



Flood Report

* CUSTOMER COMPLAINT *

Document: 4GNW-F143	4G NW Term Maintenance Contract	BEAR	
Issue: 3			
Related to: Procedure	Flood Report		
Page No. 1 of 1			
Doc. owner: Network Manager			

RMMf Defect ID:	D-NW162255867.
CCMf OI Number (if applicable):	
Incident Response Call Log Ref: (if applicable):	
Date: 05-10-16	Approximate Time of Incident: 17:00
Route: A83	
Location: CAIRNDOW SUMMIT, OPP S/W PUMPING STATION.	
Link/Section/Chainage: 16520/05 1104m	
Grid Ref:	
Description of Flood:	
Cause of Flood:	C/WAY RUN OFF DURING PERIODS OF HEAVY RAIN
Sketch/Photos:	RUN OFF FROM ROCK FACE AT ADJACENT HILLSIDE
Immediate Action Taken:	
Proposed Action:	INVESTIGATION TO DETERMINE NATURE & EXTENT OF EXISTING PIPE.
Proposed Further Investigations Required:	YES
Date of record: 05-10-16	Signed: [Redacted]
	Print Name: [Redacted]




Document:	Form 291
Issue:	5
Related to:	4GNE 4GNW
Page No.	5 of 5

Abbreviated Statement of Intent



Scheme Location



Prepared by	[Redacted]	Date	07/12/2016
Checked by	[Redacted]	Date	07/12/2016
Approved TS		Date	