General Details						Incident Details									
Incident ID	000)44256				Incident Ca	ıt		DMR	DMRS					
Contract	STS	SW				Incident Ty	ре		Minor	Minor Pothole					
Issued	14/0	07/2016 1	4:06:50			O/I Ref			16SW	16SW03850					
Status	0					Defect Ref			D-SW	D-SW162086657.					
BeCogent Ref:						Police Inc. N	No:								
Weather						Incident De	Incident Description								
Other Cause		Pothole Lane 1, passed as S/B C/way. Tango 2 confirms it was the N/B C/Way.													
								(In response to ORI jc-sw4g-004-A)							
		Chainage 34 D-SW162086657													
Organisation		Contacts			Co	ontact Phone Contact Mobile Contact Ema					nail				
Scotland Transerv	<i>'</i>	Tango 2													
				L	ocatio	n Details									
Region			Route	**************************************		Junction		***************************************	Mar	Marker Post					
			A898												
Location Descripti	on	A898(N) D-SW162	Erskine B 2086657.	r											
Easting			246093	Northing		672350 Link/Sed				ction 18515/50					
Vehicle Respon	nse	Time C	alled	Ti	me Allo	ocated	Time Ar	rived		Time Depai	ted				
TANGO 2		14	/07/2016	14:15:00	14/07/	2016 14:15:00	14/07	/2016 1	4:35:00	14/07/20	16 15:05:00				
	alse														
Vehicles Invol Make/Model V	e tration	Colour Driver			Foreign Slight Injuries Vehicle			Serious Injuries							
Damage															
Action Date 14/07/2016 14:1 14/07/2016 14:5 14/07/2016 14:5 14/07/2016 15:3	0:00 0:00	1 x Tub \ T2 stands	re /iafix used s down	to fill poth		ane 1 on S/B C	C/way. T2	attends	5						

General Details							Incident Details								
Incident ID	000	49184					Incident Cat				DMRS				
Contract	STS	SW SW	<u> </u>				Incident Ty	ре		Minor Pothole					
Issued	29/12/2016 16:02:52						O/I Ref								
Status	To .						Defect Ref								
BeCogent Ref:							Police Inc. No:								
Weather						ĺ	Incident Description								
Other Cause							Pothole & Claims Form Request								
Organisation	isation Contacts					Conf	tact Phone	t Email							
Scotland Transerv Tango 2															
					Loca	tion	Details								
Region			Route			Junction			Marker Post						
			A898												
Location Descript	Slip to A8 MOI SW1 D-SW162														
Easting			Northing			672843 Link/Se			ection 18515/91						
Vehicle Respo	nse														
ISURef		Time Ca	Called Time			Alloc	ated	Time Ar	rived		Time Departed				
TANGO 2 2		29/	9/12/2016 16:00:00 29/			12/20	016 16:00:00	29/12	/2016 16	:15:00	29/12/2016 16:25:00				
No Trace	False					_									
Vehicles Invol															
, , , , , , , , , , , , , , , , , , , ,	Vehicl Regist	e tration	Colour Driver			Foreign Vehicle		Slight	Injuries	Seriou Injurie	us Fatal Injuries es				
Damage															

Action Date Actions Taken 29/12/2016 16:13:00 From: @hotmail.co.uk] Sent: 29 December 2016 15:51 To: southwestcontrol <southwestcontrol@scotlandtranserv.co.uk>; Communications <communications@scotlandtranserv.co.uk> Subject: Claim of Pot Hole Damage - A82 Slip, Erskine Bridge. Importance: High Dear Sir/Madam The following covering Email details damage to my vehicle caused by a pothole to go along with an official claim I am making. A pothole on the A82 slip road, off the Erskine Bridge caused damage to my vehicle on the morning of Sunday 25th December, (Christmas morning) when I was driving in a I was driving home when I crossed the Erskine Bridge and took the A82 slip road off it toward Dumbarton. At approx. 0845hrs my vehicle came in to contact with a particularly large pot hole in the middle of the road. My front offside wheel went straight in to the pot hole and almost immediately my tyre blew out and I nearly lost control of the vehicle. The damage caused was chips on my alloy wheel and a blown out tyre, the tyre of which, subsequently had to be replaced. Maintenance of this road falls within the responsibility of yourselves, Transerv Scotland. Your authority has a legal responsibility to maintain roads to a safe standard under the Highways Act 1980. This includes repairing defects such as the pothole that damaged my vehicle. I am therefore making a claim for compensation for the repair costs of Please find attached evidence detailing the pothole that I hit and the damage caused, including: PDF Attachment 1 – Pictures of the pothole that caused the damage PDF Attachment 2 – Pictures of damage of vehicle tyre and map location of pot hole Picture Attachment 3 – repair costs of new fitted tyre. Please confirm in writing that the authority will reimburse me for full repair costs, along with details of the payment method. If I don't receive a satisfactory response to this letter, please be aware that I will have no 29/12/2016 16:13:00 T2 attends

29/12/2016 16:35:00 1 x bag of viafix used.

	Ge	eneral De	tails]			Incid	ent C	Detai	ls					
Incident ID	000)49505					Incident Ca	it			DMRS						
Contract	STS	SW					Incident Ty	ре			Minor Pothole						
Issued	ssued 11/01/2017 11:43:49							O/I Ref					16SW08746				
Status							Defect Ref		D-SW17235032185								
BeCogent Ref:	Cogent Ref:							Police Inc. No:									
Weather Fine + high winds							Incident Description										
Other Cause	ause						Potholes and worn/damaged road surface.										
Organisation		Contacts				Con	tact Phone	Contac	Contact Mobile C		Contact En		mail				
Public																	
							D-4-11-			L							
Loca						ation	tion Details										
Region			Route			Junction				Marker Post							
			A898														
Location Descript	tion	MOI-SW	1739354A	898 Ersl	kine Br	ridge n/b slip to A82 e/b, D-SW17235032185											
Easting			247128	Northi	ng		672815 Link/Se				ction 18515/94						
Vehicle Respo	nse								Territoria								
ISURef		Time Ca	alled		Time	Allo	cated	Time /	Arrived	edecolograment		Time [Departe	d			
TANGO 2		11.	/01/2017	11:43:00	11/	01/2	017 11:43:00	11/0	1/2017	12:0	2:00	11/0	1/2017	12:20:00			
No Trace	False)															
Vehicles Invol	lved																
	∕ehicl Regist	le tration	Colour	A A A A A A A A A A A A A A A A A A A	Oriver		Foreign Vehicle	Sligl	nt Injurie		erious uries		Fatal	Injuries			
Damage																	
Action Date		Actions	Taken														
11/01/2017 11:4	43:00	***************************************		in lane 1	at loc	us.				2010/10/6-10/6-10			200 (10 m 1990)				
11/01/2017 11:4																	
11/01/2017 12:0		_	_														
11/01/2017 12:2	20:00		reports 1					n. Filled	using 3	tubs	of c	old tar.	Road s	surface			

12/01/2017 02:12:00 emailed to stsv defects

General Details							Incident Details										
Incident ID	000	61877				Incident Ca		DMRS									
Contract	STSW						Incident Typ		Minor Pothole								
Issued	24/0	01/2018 1	9:35:53				O/I Ref	1	17SW11837								
Status	0					Defect Ref		D-SW18235530408									
BeCogent Ref:	Cogent Ref:							Police Inc. No:									
Weather	Fine no high winds							Incident Description									
Other Cause				•			Unfortunately on my way from Glasgow to Dumbarton tonight I was unable to avoid a large pothole on the inside lane of the bridge. This requires immediate attention. Please advise who I bill for any damage to my tyre/vehicle?										
Organisation		Contacts			[0	Coi	ntact Phone	ntact Phone Contact Mobile Contact Email									
Public		Public															
					Loca	tio	n Details										
Region			Route			Junction					Marker Post						
			A898														
Location Descripti	ion			je lane 1 r 8	n/b												
Easting			246196 Northing		g			672418	Link/S	Section	on	18515	/51				
Vehicle Respo	nse		0000 5000						e a de sep								
ISURef		Time Ca	alled	-	Time A	Allocated Time Arrive			rived		T	ime D	eparted				
Nightshift		24	24/01/2018 19:40:00 24/				1/2018 19:40:00 25/01/2			/2018 01:15:00 25			1/2018 (1:30:00			
No Trace	False																
Vehicles Invol	ved																
Make/Model Vehicle Registration			Colour	Dr	iver		Foreign Vehicle	Slight	Injurie		rious uries		Fatal In	juries			
Damage																	
Action Date 24/01/2018 19:4 25/01/2018 01:3)		s Duty												
25/01/2018 01:44:00 Passed to STSV-Defects for permanent repair.											:						