

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 25/10/2017 and 01/02/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'AGAINST: DRAFFAN UPASS TO B7086 UPASS',) Or

(Section is 'AGAINST: SLIP ROAD TO B7078 KIRKMUIRHILL',) Or

(Section is 'AGAINST: B7086 UPASS TO START OF CONCRETE',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
10780/59 : AGAINST: DRAFFAN UPASS TO B7086 UPASS									
Safety Inspection of M74 Main on 25 October 2017									
<i>No defects recorded</i>									
Safety Patrol of M74 Tannochside V1 on 29 October 2017									
<i>No defects recorded</i>									
Safety Inspection of M74 Main on 01 November 2017									
<i>No defects recorded</i>									
Safety Patrol of M74 Tannochside V1 on 05 November 2017									
<i>No defects recorded</i>									
Safety Inspection of M74 Main on 08 November 2017									
<i>No defects recorded</i>									
Safety Patrol of M74 Tannochside V1 on 12 November 2017									
<i>No defects recorded</i>									
Safety Inspection of M74 Main on 15 November 2017									
<i>No defects recorded</i>									
Safety Patrol of M74 Tannochside V1 on 19 November 2017									
<i>No defects recorded</i>									
Safety Inspection of M74 Main on 22 November 2017									
<i>No defects recorded</i>									
Safety Patrol of M74 Tannochside V1 on 26 November 2017									
<i>No defects recorded</i>									
Safety Inspection of M74 Main on 29 November 2017									
<i>No defects recorded</i>									
Safety Patrol of M74 Tannochside V1 on 03 December 2017									
<i>No defects recorded</i>									
Safety Inspection of M74 Main on 06 December 2017									
<i>No defects recorded</i>									
Safety Patrol of M74 Tannochside V1 on 10 December 2017									
<i>No defects recorded</i>									
Safety Inspection of M74 Main on 13 December 2017									
<i>No defects recorded</i>									
Safety Patrol of M74 Tannochside V1 on 17 December 2017									
<i>No defects recorded</i>									
Safety Inspection of M74 Main on 20 December 2017									
SW85-317014-235510271	430m	30m	CARRIAGEWAY	Pothole (POTH)	CAT 1	17/01/2018	Completed Defects	11/01/2018	M74 S/B J8 TO J9 M/P32 5 +25 MTR
Safety Patrol of M74 Tannochside V1 on 24 December 2017									
<i>No defects recorded</i>									
Safety Inspection of M74 Main on 27 December 2017									
<i>No defects recorded</i>									
Safety Patrol of M74 Tannochside V1 on 31 December 2017									
<i>No defects recorded</i>									
Safety Inspection of M74 Main on 03 January 2018									
<i>No defects recorded</i>									
Safety Patrol of M74 Tannochside V1 on 07 January 2018									
<i>No defects recorded</i>									
Safety Inspection of M74 Main on 10 January 2018									
<i>No defects recorded</i>									
Safety Patrol of M74 Tannochside V1 on 14 January 2018									
<i>No defects recorded</i>									

Safety Inspection of M74 Main on 17 January 2018*No defects recorded***Safety Patrol of M74 Tannochside V1 on 21 January 2018***No defects recorded***Safety Inspection of M74 Main on 24 January 2018**

SW85-317788-235529074	1,488m	0m	FENCES_AND_BARRIERS	Accident damage (ACCD)	CAT 1	21/02/2018	Completed Defects	20/02/2018	M74 SB JCT 8-9 5M PRIOR TO 33 OVER 6
-----------------------	--------	----	---------------------	------------------------	-------	------------	-------------------	------------	--------------------------------------

Safety Patrol of M74 Tannochside V1 on 28 January 2018*No defects recorded***Safety Inspection of M74 Main on 31 January 2018***No defects recorded***10780/16 : AGAINST: B7086 UPASS TO START OF CONCRETE****Safety Inspection of M74 Main on 25 October 2017***No defects recorded***Safety Patrol of M74 Tannochside V1 on 29 October 2017***No defects recorded***Safety Inspection of M74 Main on 01 November 2017***No defects recorded***Safety Patrol of M74 Tannochside V1 on 05 November 2017***No defects recorded***Safety Inspection of M74 Main on 08 November 2017***No defects recorded***Safety Patrol of M74 Tannochside V1 on 12 November 2017***No defects recorded***Safety Inspection of M74 Main on 15 November 2017***No defects recorded***Safety Patrol of M74 Tannochside V1 on 19 November 2017***No defects recorded***Safety Inspection of M74 Main on 22 November 2017**

SW85-316378-235476745	113m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/12/2017	Completed Defects	29/11/2017	M74 SB JCT 9-10 AT MP 34 OVER 1 LANE 1 OS WT
SW85-316378-235476746	151m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/12/2017	Completed Defects	29/11/2017	M74 SB JCT 9-10 40M PAST MP 34 OVER 1 LANE 1 NS WT

Safety Patrol of M74 Tannochside V1 on 26 November 2017*No defects recorded***Safety Inspection of M74 Main on 29 November 2017***No defects recorded***Safety Patrol of M74 Tannochside V1 on 03 December 2017***No defects recorded***Safety Inspection of M74 Main on 06 December 2017**

SW85-316714-235489363	1,988m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	03/01/2018	Completed Defects	20/12/2017	JCT 9 TO 10 AT MP 35/9 S/B
-----------------------	--------	----	-------------	----------------	-------	------------	-------------------	------------	----------------------------

Safety Patrol of M74 Tannochside V1 on 10 December 2017*No defects recorded***Safety Inspection of M74 Main on 13 December 2017**

SW85-316864-235496103	1,996m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	10/01/2018	Completed Defects	10/01/2018	M74 SB JCT 9-10 40M PRIOR TO MP 36 OVER 0 LANE 1 NS WT
-----------------------	--------	----	-------------	----------------	-------	------------	-------------------	------------	--

Safety Patrol of M74 Tannochside V1 on 17 December 2017*No defects recorded***Safety Inspection of M74 Main on 20 December 2017**

SW85-317014-235510273	1,990m	1,990m	CARRIAGEWAY	Pothole (POTH)	CAT 1	17/01/2018	Completed Defects	12/01/2018	M74 S/B J9 TO J10 M/P 35/9 N/S/L N/S/W/T
SW85-317014-235510272	364m	364m	CARRIAGEWAY	Pothole (POTH)	CAT 1	17/01/2018	Completed Defects	11/01/2018	M74 S/B J9 TO J10 M/P34/3 +50MTR N/S/L/ N/S/W T

Safety Patrol of M74 Tannochside V1 on 24 December 2017*No defects recorded***Safety Inspection of M74 Main on 27 December 2017***No defects recorded***Safety Patrol of M74 Tannochside V1 on 31 December 2017***No defects recorded*

Safety Inspection of M74 Main on 03 January 2018*No defects recorded***Safety Patrol of M74 Tannochside V1 on 07 January 2018***No defects recorded***Safety Inspection of M74 Main on 10 January 2018***No defects recorded***Safety Patrol of M74 Tannochside V1 on 14 January 2018***No defects recorded***Safety Inspection of M74 Main on 17 January 2018***No defects recorded***Safety Patrol of M74 Tannochside V1 on 21 January 2018***No defects recorded***Safety Inspection of M74 Main on 24 January 2018**

SW85-317788-235529075	2,000m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	21/02/2018	Completed Defects	07/02/2018	M74 SB JCT 9-10 50M PRIOR TO MP 36 OVER 0 LANE 1 NS WT
-----------------------	--------	----	-------------	----------------	-------	------------	-------------------	------------	--

Safety Patrol of M74 Tannochside V1 on 28 January 2018*No defects recorded***Safety Inspection of M74 Main on 31 January 2018***No defects recorded***10780/61 : AGAINST: SLIP ROAD TO B7078 KIRKMUIRHILL****Safety Inspection of M74 Slips on 26 October 2017***No defects recorded***Safety Patrol of M74 Tannochside V1 on 29 October 2017***No defects recorded***Safety Inspection of M74 Slips on 02 November 2017***No defects recorded***Safety Patrol of M74 Tannochside V1 on 05 November 2017***No defects recorded***Safety Inspection of M74 Slips on 09 November 2017***No defects recorded***Safety Patrol of M74 Tannochside V1 on 12 November 2017***No defects recorded***Safety Inspection of M74 Slips on 16 November 2017***No defects recorded***Safety Patrol of M74 Tannochside V1 on 19 November 2017***No defects recorded***Safety Inspection of M74 Slips on 23 November 2017***No defects recorded***Safety Patrol of M74 Tannochside V1 on 26 November 2017***No defects recorded***Safety Inspection of M74 Slips on 30 November 2017**

SW85-316500-235483542	10m	1,200m	CARRIAGEWAY	Litter Grade D (LITD)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M74 SB JCT 9 OFFSLIP
-----------------------	-----	--------	-------------	-----------------------	-------	------------	-----------------------	------------	----------------------

Safety Patrol of M74 Tannochside V1 on 03 December 2017*No defects recorded***Safety Inspection of M74 Slips on 07 December 2017**

SW85-316745-235493947	392m	392m	CARRIAGEWAY	Litter Grade D (LITD)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M74 S/B J9 OFFSLIP
-----------------------	------	------	-------------	-----------------------	-------	------------	-----------------------	------------	--------------------

Safety Patrol of M74 Tannochside V1 on 10 December 2017*No defects recorded***Safety Inspection of M74 Slips on 14 December 2017***No defects recorded***Safety Patrol of M74 Tannochside V1 on 17 December 2017***No defects recorded***Safety Inspection of M74 Slips on 21 December 2017***No defects recorded***Safety Patrol of M74 Tannochside V1 on 24 December 2017***No defects recorded***Safety Inspection of M74 Slips on 28 December 2017***No defects recorded***Safety Patrol of M74 Tannochside V1 on 31 December 2017***No defects recorded***Safety Inspection of M74 Slips on 04 January 2018**

No defects recorded

Safety Patrol of M74 Tannochside V1 on 07 January 2018

No defects recorded

Safety Inspection of M74 Slips on 11 January 2018

No defects recorded

Safety Patrol of M74 Tannochside V1 on 14 January 2018

No defects recorded

Safety Inspection of M74 Slips on 18 January 2018

No defects recorded

Safety Patrol of M74 Tannochside V1 on 21 January 2018

No defects recorded

Safety Inspection of M74 Slips on 25 January 2018

No defects recorded

Safety Patrol of M74 Tannochside V1 on 28 January 2018

No defects recorded

Safety Inspection of M74 Slips on 01 February 2018

No defects recorded