Personal Injury Accident Statistics - A96 Approx. 100 metres either side of Eastfield Junction, Inverness

Year			Slight
2013	0	0	1
2014	0	0	0
2015	0	0	0
2016	0	0	2
2017	0	0	0
2018 (up to 30 March)	0	0	0
TOTAL	0	0	3

	TOTAL
	1
	0
Ī	0
	2
Ī	0
Ī	0
ļ	3

CR =	Car
HG =	Goods Vehicle
MC =	Motorcycle
OT =	Other Motor Vehicle
PC =	Pedal Cycle
MC =	Motorcycle
TR =	Agricultural Vehicle
MB =	Minibus

BC = Bus or Coach

Key - Vehicle Manoeuvre
SOS = Slowing or Stopping
GA = Going Ahead
OT = Overtaking
GR = Turning Right
GL = Turning Left
PK = Parking
UT = U-Turn
MO = Moving Off
DE D

Source: Transport Scotland Accident Manager Database Notes:

Statistics for the Northern Legacy Police Force area

Date Extracted - 3 September 2018


Date Period: 01/01/2013 - 30/03/2018

Please note that the information provided is based on the current figures available. The following are potential reasons for an accident not appearing on our system:

- Transport Scotland only holds accident information which is provided to us by Police Scotland.
- Transport Scotland does not hold information relating to damage only accidents (i.e. not involving an injury).
- Transport Scotland only holds accident information for the trunk road network.
- The accident information Transport Scotland holds is subject to change. E.g. we receive late returns from Police Scotland, who are responsible for recording details of injury accidents.
- Annual Scottish accident figures are published by Transport Scotland on a yearly basis and can be found by entering Reported Road Casualties Scotland into your search engine.

Day	Date	Time	Severity	Road	Section	Weather	Accrefno	Easting	Northing	Light Conditions	Surface Conditions	Casualties	Vehicles	V1 Type	V1 Mn	V2 Type	V2 Mn	Year
Th	14-Feb-13	1130	SLIGHT	A96	A96 (12685/85)	FINE (WITHOUT HIGH WINDS)	NN04349	269489	845877	DAYLIGHT	DRY	1	2	CR	GA	CR	GA	2013
We	25-May-16	1916	SLIGHT	A96	A96 (12685/85)	FINE (WITHOUT HIGH WINDS)	NN12851	269431	845836	UNKNOWN	DRY	1	1	мс	GA			2016
Th	10-Nov-16	1230	SLIGHT	A96	A96 (12685/55)	FINE (WITHOUT HIGH WINDS)	NN28708	269577	845920	UNKNOWN	WET / DAMP	i	3	HG	GA	CR	от	2016

3 records found. Fatal: 0, Serious: 0, Slight: 3



Accident, Vehicle and Casualty Details

Accident Reference: NN04349

Date/Time: 14 February 2013 11

Severity: SLIGHT

Road/Link/Section/Chainage: A96 12685/85 (159m)

Junction Road Code: A9

Junction Location: APPROACHING JUNCTION OR WAITING/PARKED AT JU

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions:

Light

Vehicle Details

Veh. No	Vehicle Type CAR	Direction E W	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR	Direction E W	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No. Casua	ulty Class <u>s</u>	Sex	Age	Severity
1 DRIVE	-			SLIGHT

Contributory Factors

Accident Reference: NN12851

Date/Time: 25 May 2016 1916

Severity: SLIGHT

Road/Link/Section/Chainage: A96 12685/85 (57m)

Junction Road Code: U

Junction Location: LEAVING ROUNDABOUT

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions:

Light

Vehicle Details

Veh. No Vehicle Type

1 MOTORCYCLE OVER
500CC

Direction Location EW ON MAIN

Junction Location LEAVING ROUNDABOUT Manoeuvres GOING AHEAD **Skidded/overturned** SKIDDED Hit Object in Cway NONE Hit Object off Cway NONE

OTHER

ОТ

Casualty Details

Veh. No.

Casualty Class DRIVER

Sex

CARRIAGEWAY - NOT

IN RESTRICTED LANE

Age

Severity SLIGHT

Contributory Factors

Accident Reference: NN28708

Date/Time: 10 November 2016 1

Severity: SLIGHT

Road/Link/Section/Chainage: A96 12685/55 (101m)

Junction Road Code: U

Junction Location: LEAVING ROUNDABOUT

Weather Conditions: Fine

Road Surface Conditions: Wet

Lighting Conditions:

Light

Vehicle Details

Veh. No	Vehicle Type GOODS VEHICLE 7.5 TONNES MGW AND OVER	Direction W E	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location LEAVING ROUNDABOUT	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR	Direction W E	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location LEAVING ROUNDABOUT	Manoeuvres OVERTAKING MOVING VEHICLE ON ITS OFFSIDE	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 3	Vehicle Type GOODS VEHICLE 7.5 TONNES MGW AND OVER	Direction E W	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No. Casualty Class 2 DRIVER	Sex Age Severity SLIGHT	
----------------------------------	-------------------------	--

Contributory Factors