

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/12/2017 and 31/01/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'Roadhead Rbt to Clerksbridge toll Rbt'.)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
14335/10 : Roadhead Rbt to Clerksbridge toll Rbt									
Safety Inspection of A737 & A738 Westway V1 on 04 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A737 & A738 Westway V1 on 11 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A737 & A738 Westway V1 on 18 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A737 & A738 Westway V1 on 22 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A737 & A738 Westway V1 on 29 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A737 & A738 Westway V1 on 05 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A737 & A738 Westway V1 on 08 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A737 & A738 Westway V1 on 15 January 2018									
SW77-317599-235521016	615m	615m	CARRIAGEWAY	Pothole (POTH)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A737 WB AT NETHER BAREOD FARM
Safety Inspection of A737 & A738 Westway V1 on 22 January 2018									
SW77-317754-235529066	768m	768m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/02/2018	Completed Defects	06/02/2018	A737 WB AT BRIDGE BETWEEN RHEAD - CLERKSBRIDGE
SW77-317754-235529068	811m	811m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/02/2018	Completed Defects	06/02/2018	A737 WB RHEAD - CLERKSBRIDGE
SW77-317754-235529067	785m	790m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/02/2018	Completed Defects	06/02/2018	A737 WB RHEAD - CLERKSBRIDGE
SW77-317754-235529069	817m	827m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/02/2018	Completed Defects	06/02/2018	A737 WB RHEAD - CLERKSBRIDGE
SW77-317754-235529065	384m	384m	CARRIAGEWAY	Pothole (POTH)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
Safety Inspection of A737 & A738 Westway V1 on 29 January 2018									
SW77-318061-235531955	656m	660m	CARRIAGEWAY	Pothole (POTH)	CAT 1	26/02/2018	Completed Defects	07/02/2018	A737 EB 70M PRIOR NETHERFOD FARM
SW77-318061-235531953	830m	835m	CARRIAGEWAY	Pothole (POTH)	CAT 1	26/02/2018	Completed Defects	07/02/2018	A737 EB CLERKSBRIDGE - ROADHEAD
SW77-318061-235531952	1,083m	1,083m	CARRIAGEWAY	Pothole (POTH)	CAT 1	26/02/2018	Completed Defects	07/02/2018	A737 15M PRIOR TO BEND SIGN @ CLERKSBRIDGE
SW77-318061-235531954	708m	718m	CARRIAGEWAY	Pothole (POTH)	CAT 1	26/02/2018	Completed Defects	07/02/2018	A737 100M PRIOR NETHERBARFOD FARM
SW77-318061-235531956	447m	447m	CARRIAGEWAY	Pothole (POTH)	CAT 1	26/02/2018	Completed Defects	07/02/2018	A737 EB 100M AFTER NETHERFOD FARM

