

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 22/08/2016 and 22/08/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Road is 'A85',)
 (Section Code is 11940/34) Or
 (Section Code is 11940/71)

| Defect Reference | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|--|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|
| 11940/34 : JCT CROFT RD TO JCT CORRAN PARK MINI RBT | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 23 August 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Detailed Inspection TEMPLATE of A85 A828 JCT CONNELL TO A816 (ARGYLL SQUARE) JCT on 26 August 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 30 August 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 06 September 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 13 September 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 20 September 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 27 September 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 04 October 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 11 October 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 18 October 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 25 October 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 01 November 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 08 November 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 15 November 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 22 November 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 29 November 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 06 December 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 13 December 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 20 December 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 27 December 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 03 January 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 10 January 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 17 January 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 24 January 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 31 January 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 07 February 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 14 February 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |

| Defect Reference | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|--|---------|-------|----------------|---------------------------|-----------------|--------------------------|-------------------|-----------------|-------------------------------|
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 21 February 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 28 February 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 07 March 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 21 March 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 22 March 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 28 March 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 04 April 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 11 April 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 18 April 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 25 April 2017 | | | | | | | | | |
| NWG23-263603-235103647 | 285m | 0m | LIGHTING_POINT | Lamp failure (LAMP) | CAT 2 | 01/01/9999 | Completed Defects | 30/04/2017 | STRATHNAVER GUEST HOUSE |
| NWG23-263603-235103648 | 291m | 0m | GULLY | Blockage (BLOK) | CAT 1 | 26/04/2017 | Completed Defects | 04/05/2017 | STRATHNAVER |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 02 May 2017 | | | | | | | | | |
| NWG23-265974-235128904 | 182m | 0m | GULLY | Blockage (BLOK) | CAT 1 | 30/05/2017 | Completed Defects | 24/05/2017 | ACROSS FROM KINGS KNOLL HOTEL |
| NWG23-265974-235128903 | 191m | 0m | GULLY | Blockage (BLOK) | CAT 1 | 30/05/2017 | Completed Defects | 24/05/2017 | KINGS KNOLL HOTEL |
| NWG23-265974-235128905 | 145m | 0m | MANHOLE | Rocking under load (IRLD) | CAT 1 | 30/05/2017 | Completed Defects | 24/05/2017 | DUNOLLIE ROAD |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 09 May 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 23 May 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 30 May 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 07 June 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 13 June 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 20 June 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 27 June 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 04 July 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 11 July 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 18 July 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 25 July 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 01 August 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 08 August 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 15 August 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 22 August 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 29 August 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 05 September 2017 | | | | | | | | | |

| Defect Reference | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|---|---------|-------|---------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 12 September 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 19 September 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 26 September 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 03 October 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 10 October 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 17 October 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 24 October 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 31 October 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 07 November 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 14 November 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 21 November 2017 | | | | | | | | | |
| NWG23-316322-235473342 | 174m | 0m | GULLY | Blockage (BLOK) | CAT 1 | 19/12/2017 | Completed Defects | 19/12/2017 | DUNOLLIE ROAD |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 28 November 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 05 December 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 12 December 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 19 December 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 22 December 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 29 December 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 05 January 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 09 January 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Detailed Inspection TEMPLATE of A85 A828 JCT CONNELL TO A816 (ARGYLL SQUARE) JCT on 15 December 2017 | | | | | | | | | |
| NWG11253123-143 | 469m | 0m | ROAD_MARKINGS | Wear (for example erosion) (WEAR) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | INSIDE MINI RBT, OPPOSITE CORRAN HALLS, OBAN. |
| NWG11253123-144 | 470m | 0m | GULLY | Difference in level with road (IDLV) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | @ MINI RBT, OPPOSITE CORRAN HALLS, OBAN. |
| NWG11253123-207 | 276m | 0m | ROAD_MARKINGS | Wear (for example erosion) (WEAR) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | OBAN EAST, FILTER LANE. |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 16 January 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 23 January 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 30 January 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 06 February 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 13 February 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 20 February 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 27 February 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |

| Defect Reference | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|--|------------|----------|-----------|---------------------------|--------------------|-----------------------------|-----------------------|--------------------|--|
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 06 March 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 13 March 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 20 March 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 27 March 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 03 April 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 10 April 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 17 April 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 24 April 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 01 May 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 08 May 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 15 May 2018 | | | | | | | | | |
| NW34347682-235787817 | 174m | 0m | MANHOLE | Rocking under load (IRLD) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | JUST EAST OF KINGS KNOLL HOTEL OBAN |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 22 May 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 29 May 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 05 June 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 12 June 2018 | | | | | | | | | |
| NW34360527-235844239 | 143m | 0m | MANHOLE | Rocking under load (IRLD) | CAT 1 | 10/07/2018 | Completed Defects | 06/07/2018 | 100M EAST OF KINGS KNOLL HOTEL |
| NW34360527-235844240 | 56m | 0m | MANHOLE | Rocking under load (IRLD) | CAT 1 | 10/07/2018 | Completed Defects | 06/07/2018 | 300 MTS EAST OF KINGS KNOLL HOTEL OBAN |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 15 June 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 18 June 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 22 June 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 25 June 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 29 June 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 02 July 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 02 July 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 09 July 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 13 July 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 16 July 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 20 July 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 23 July 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 30 July 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 03 August 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 06 August 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 10 August 2018 | | | | | | | | | |

| Defect Reference | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|---|---------|-------|-----------|---------------------------------------|-----------------|--------------------------|-----------------------|-----------------|----------------------------------|
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 13 August 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 17 August 2018 | | | | | | | | | |
| NW34391651-235951157 | 145m | 0m | MANHOLE | Rocking under load (IRLD) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | :EAST OF KINGS KNOLL,,HOTEL OBAN |
| NW34391651-235951159 | 56m | 0m | MANHOLE | Difference in component levels (ICLV) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | EAST OF KINGS KNOLL HOTEL OBAN |
| NW34391651-235951160 | 11m | 0m | MANHOLE | Rocking under load (IRLD) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | EAST OF KINGS KNOLL HOTEL OBAN |
| NW34391651-235951158 | 111m | 0m | MANHOLE | Rocking under load (IRLD) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | EAST OF KINGS KNOLL HOTEL OBAN |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 20 August 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| 11940/71 : With: JCT CORRAN PARK MINI RBT TO JCT WILLIAM ST | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 23 August 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Detailed Inspection TEMPLATE of A85 A828 JCT CONNELL TO A816 (ARGYLL SQUARE) JCT on 26 August 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 30 August 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 06 September 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 13 September 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 20 September 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 27 September 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 04 October 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 11 October 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 18 October 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 25 October 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 01 November 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 08 November 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 15 November 2016 | | | | | | | | | |
| NWG10208805-2349851 | 40m | 40m | BOLLARDS | Damaged (DAMG) | CAT 1 | 01/01/9999 | Completed Defects | 15/11/2016 | TORLUNDY GUEST HOUSE |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 22 November 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 29 November 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 06 December 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 13 December 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 20 December 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 27 December 2016 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 03 January 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 10 January 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 17 January 2017 | | | | | | | | | |

| Defect Reference | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|---|---------|-------|-----------|----------------|-----------------|--------------------------|------------------------------|-----------------|----------------------|
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 24 January 2017 | | | | | | | | | |
| NWG10237462-235040678 | 299m | 0m | GULLY | Missing (MISS) | CAT 1 | 21/02/2017 | Completed Defects | 14/02/2017 | OLD HYDRO SHOP |
| NWG10237462-235040676 | 300m | 300m | KERB | Other (OTHR) | CAT 2 | 25/01/2017 | Awaiting CCMS Permanent Date | 01/01/9999 | HYDRO OBAN |
| NWG10237462-235040677 | 306m | 306m | KERB | Other (OTHR) | CAT 2 | 25/01/2017 | Awaiting CCMS Permanent Date | 01/01/9999 | BLOCKBUSTERS. OBAN |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 31 January 2017 | | | | | | | | | |
| NWG23-240350-235047998 | 208m | 0m | KERB | Other (OTHR) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | ORIGINAL KITCHENS |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 07 February 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 14 February 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 21 February 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 28 February 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 07 March 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 21 March 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 22 March 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 28 March 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 04 April 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 11 April 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 18 April 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 25 April 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 02 May 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 09 May 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 16 May 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 23 May 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 30 May 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 07 June 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 13 June 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 20 June 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 27 June 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 04 July 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 11 July 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 18 July 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 25 July 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 01 August 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 08 August 2017 | | | | | | | | | |

| Defect Reference | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|---|------------|----------|---------------|---|--------------------|-----------------------------|--------------------------|--------------------|----------------------|
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 15 August 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 22 August 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 29 August 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 05 September 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 12 September 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 19 September 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 26 September 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 03 October 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 10 October 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 17 October 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 24 October 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 31 October 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 07 November 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 14 November 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 21 November 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 28 November 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 05 December 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 12 December 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 19 December 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 22 December 2017 | | | | | | | | | |
| NWG23-317065-235512879 | 38m | 0m | BOLLARDS | Damaged (DAMG) | CAT 1 | 19/01/2018 | Completed Defects | 17/01/2018 | HAMILTON HOUSE B+B |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 29 December 2017 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 05 January 2018 | | | | | | | | | |
| NWG23-317390-235513686 | 234m | 0m | BOLLARDS | Accident damage (ACCD) | CAT 1 | 02/02/2018 | Completed Defects | 31/01/2018 | OBAN CINEMA |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 09 January 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Detailed Inspection TEMPLATE of A85 A828 JCT CONNELL TO A816 (ARGYLL SQUARE) JCT on 15 December 2017 | | | | | | | | | |
| NWG11253123-148 | 30m | 0m | TRAFFIC_SIGNS | Physical condition of post (COPT) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | OBAN, E/B VERGE. |
| NWG11253123-162 | 285m | 0m | TRAFFIC_SIGNS | Physical condition of post (COPT) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | OBAN, E/B FOOTWAY. |
| NWG11253123-164 | 280m | 0m | FOOTWAY | Slab cracking (SLCK) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | OBAN, W/B FOOTWAY. |
| NWG11253123-155 | 222m | 0m | TRAFFIC_SIGNS | Physical condition of post (COPT) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | OBAN, E/B FOOTWAY. |
| NWG11253123-156 | 221m | 0m | BOLLARDS | Missing (MISS) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | OBAN, W/B FOOTWAY. |

| Defect Reference | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|------------------|---------|-------|---------------|-----------------------------------|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| NWG11253123-152 | 119m | 0m | GULLY | Blockage (BLOK) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | OBAN, E/B FOOTWAY. |
| NWG11253123-158 | 244m | 0m | BOLLARDS | Missing (MISS) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | OBAN, W/B FOOTWAY. |
| NWG11253123-163 | 280m | 0m | TRAFFIC_SIGNS | Physical condition of post (COPT) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | OBAN, E/B FOOTWAY. |
| NWG11253123-149 | 31m | 0m | TRAFFIC_SIGNS | Missing (MISS) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | OBAN, E/B VERGE. |
| NWG11253123-151 | 62m | 0m | CHANNEL | Blockage (BLOK) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | OBAN, E/B FOOTWAY. |
| NWG11253123-147 | 29m | 0m | TRAFFIC_SIGNS | Physical condition of post (COPT) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | OBAN, W/B VERGE. |
| NWG11253123-159 | 266m | 0m | FOOTWAY | Slab cracking (SLCK) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | OBAN, E/B FOOTWAY. |
| NWG11253123-161 | 288m | 0m | FOOTWAY | Slab cracking (SLCK) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | OBAN, E/B FOOTWAY. |
| NWG11253123-153 | 188m | 0m | CHANNEL | Blockage (BLOK) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | OBAN, E/B FOOTWAY. |
| NWG11253123-154 | 194m | 0m | KERB | Missing (MISS) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | OBAN, E/B FOOTWAY. |
| NWG11253123-150 | 38m | 0m | BOLLARDS | Damaged (DAMG) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | OBAN, E/B FOOTWAY. |
| NWG11253123-157 | 241m | 0m | FOOTWAY | Slab cracking (SLCK) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | OBAN, E/B FOOTWAY. |
| NWG11253123-160 | 266m | 0m | FOOTWAY | Slab cracking (SLCK) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | OBAN, E/B FOOTWAY. |

Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 16 January 2018

No defects recorded

Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 23 January 2018

No defects recorded

Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban on 30 January 2018

No defects recorded

Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 06 February 2018

No defects recorded

Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 13 February 2018

No defects recorded

Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 20 February 2018

No defects recorded

Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 27 February 2018

| | | | | | | | | | |
|------------------------|------|----|------------------------|-----------------------------------|-------|------------|-----------------------|------------|---------------|
| NWG23-322548-235549657 | 317m | 0m | ROAD_MARKINGS _LONG | Wear (for example erosion) (WEAR) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | GEORGE STREET |
|------------------------|------|----|------------------------|-----------------------------------|-------|------------|-----------------------|------------|---------------|

Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 06 March 2018

No defects recorded

Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 13 March 2018

No defects recorded

Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 20 March 2018

No defects recorded

Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 27 March 2018

No defects recorded

Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 03 April 2018

No defects recorded

Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 10 April 2018

No defects recorded



| Defect Reference | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|--|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 17 April 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 24 April 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 01 May 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 08 May 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 15 May 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 22 May 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 29 May 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 05 June 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 12 June 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 15 June 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 18 June 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 22 June 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 25 June 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 29 June 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 02 July 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 02 July 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 09 July 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 13 July 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 16 July 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 20 July 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 23 July 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 30 July 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 03 August 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 06 August 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 10 August 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 13 August 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 17 August 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A82 Safety Tyndrum, A828 & A85 Oban - Dalmally on 20 August 2018 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |