

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 26/05/2018 and 07/08/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'JCT BALLOCHDOWAN TO OLD SMYRTON',) Or

(Section is 'JCT AT CARLOCK HOUSE TO JCT AT BALLOCHDOWAN',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
11611/68 : JCT BALLOCHDOWAN TO OLD SMYRTON									
Safety Inspection of A77 Ayr South V1 on 31 May 2018									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 07 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 14 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 21 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 28 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 05 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 12 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 19 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 26 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 02 August 2018									
<i>No defects recorded</i>									
11611/57 : JCT AT CARLOCK HOUSE TO JCT AT BALLOCHDOWAN									
Safety Inspection of A77 Ayr South V1 on 31 May 2018									
SW82356191-235816774	773m	774m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	28/06/2018	Completed Defects	31/05/2018	A77 SB CW CARLOCK HOUSE
SW82356191-235816773	300m	301m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	28/06/2018	Completed Defects	31/05/2018	A77 NB CW CARLOCK HILL ON HFS
Safety Inspection of A77 Ayr South V1 on 07 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 14 June 2018									
SW80-363687-235858063	536m	537m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/07/2018	Completed Defects	14/06/2018	A77 NB CW 100M PRIOR TO CARLOCK HILL JCT
SW80-363687-235858064	749m	750m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/07/2018	Completed Defects	14/06/2018	A77 SB CW 125M SOUTH OF CARLOCK HILL JCT
Safety Inspection of A77 Ayr South V1 on 21 June 2018									
SW80-367289-235862778	340m	341m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	19/07/2018	Completed Defects	21/06/2018	A77 NB CW MINAR JCT TOP OF CARLOCK HILL
SW80-367289-235862779	1,488m	1,489m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	19/07/2018	Completed Defects	21/06/2018	A77 SB CW 50M SOUTH OF MINAR JCT
Safety Inspection of A77 Ayr South V1 on 28 June 2018									
SW80-370510-235861174	516m	517m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	26/07/2018	Completed Defects	28/06/2018	A78 SB CW 425M BEFORE CARLOCK HOUSE
SW80-370510-235861172	473m	474m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	26/07/2018	Completed Defects	28/06/2018	A78 SB CW 450M BEFORE CARLOCK HOUSE
SW80-370510-235861175	561m	562m	CARRIAGEWAY	Pothole VIAFIX	CAT 1	26/07/2018	Completed	28/06/2018	A78 SB CW 420M BEFORE

				(POTV)			Defects		CARLOCK HOUSE
SW80-370510-235861173	474m	475m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	26/07/2018	Completed Defects	28/06/2018	A78 SB CW 445M BEFORE CARLOCK HOUSE
Safety Inspection of A77 Ayr South V1 on 05 July 2018									
SW82374127-235892362	1,481m	1,482m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	02/08/2018	Completed Defects	05/07/2018	A77 SB CW 100M PRIOR TO 1ST LAYBY AT START OF CARLOCK HILL
Safety Inspection of A77 Ayr South V1 on 12 July 2018									
No defects recorded									
Safety Inspection of A77 Ayr South V1 on 19 July 2018									
SW82380667-235914373	831m	832m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/08/2018	Completed Defects	19/07/2018	A77 SB CW 500M PRIOR TO CARLOCK HOUSE
SW82380667-235914374	839m	840m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/08/2018	Completed Defects	19/07/2018	A77 SB CW 505M PRIOR TO CARLOCK HOUSE
Safety Inspection of A77 Ayr South V1 on 26 July 2018									
SW82383889-235917511	922m	923m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	23/08/2018	Completed Defects	26/07/2018	A77 595 PRIOR TO CARLOCK HOUSE
SW82383889-235917512	922m	923m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	23/08/2018	Completed Defects	26/07/2018	A77 SB CW 589M PRIOR TO CARLOCK HOUSE
SW82383889-235917508	946m	947m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	23/08/2018	Completed Defects	26/07/2018	A77 SB CW 600 YARDS BEFORE CARLOCK HOUSE
SW82383889-235917510	922m	923m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	23/08/2018	Completed Defects	26/07/2018	A77 SB 590M PRIOR TO CARLOCK HOUSE
SW82383889-235917513	917m	918m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/08/2018	Completed Defects	08/08/2018	A77 588 M PRIOR TO CARLOCK HOUSE
SW82383889-235917509	947m	948m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	23/08/2018	Completed Defects	26/07/2018	A77 SB CW 599M PRIOR TO CARLOCK HOUSE
Safety Inspection of A77 Ayr South V1 on 02 August 2018									
SW80-387291-235943988	1,453m	1,454m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	30/08/2018	Completed Defects	02/08/2018	A77 SB CW JCT AT CARLOCK STRAIGHT
SW80-387291-235943990	917m	918m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	30/08/2018	Completed Defects	02/08/2018	A77 SB 600M PRIOR TO CARLOCK HOUSE
SW80-387291-235943989	1,456m	1,457m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	30/08/2018	Completed Defects	02/08/2018	A77 SB CW JCT AT CARLOCK STRAIGHT

