

# Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/10/2016 and 01/12/2016, and defects raised outside of inspections on the same Section(s) during this period.

(Road is 'A702',)  
(Section Code is 13563/07) Or

(Section Code is 13563/69) Or

(Section Code is 13564/05) Or

(Section Code is 13564/62)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>13563/07 : C57 SILVERBURN RD TO JCT GRANGE DELL</b>									
Safety Inspection of Amey A702 Safety Inspection on 05 October 2016									
SE67193340-2242854	1,836m	0m	CARRIAGEWAY	Flooding (FLOD)	CAT 1	02/11/2016	Completed Defects	31/10/2016	layby after lawhead farm
Safety Inspection of Amey A702 Safety Inspection on 12 October 2016									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 19 October 2016									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 26 October 2016									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 02 November 2016									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 09 November 2016									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 16 November 2016									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 23 November 2016									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 30 November 2016									
No defects recorded									
<b>13563/69 : JCT GRANGE DELL TO C41 BELLWOOD RD</b>									
Safety Inspection of Amey A702 Safety Inspection on 05 October 2016									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 12 October 2016									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 19 October 2016									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 26 October 2016									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 02 November 2016									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 09 November 2016									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 16 November 2016									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 23 November 2016									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 30 November 2016									
No defects recorded									
<b>13564/05 : C41 BELLWOOD RD TO U71 GLENCORSE KIRK RD</b>									
Safety Inspection of Amey A702 Safety Inspection on 05 October 2016									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 12 October 2016									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 19 October 2016									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 26 October 2016									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
<b>Safety Inspection of Amey A702 Safety Inspection on 02 November 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey A702 Safety Inspection on 09 November 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey A702 Safety Inspection on 16 November 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey A702 Safety Inspection on 23 November 2016</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey A702 Safety Inspection on 30 November 2016</b>									
SE67215388-2353244	1,165m	0m	GULLY	Other (OTHR)	CAT 1	28/12/2016	Completed Defects	21/12/2016	<i>nb 2nd last gully in new surface after flatterstone</i>

**13564/62 : U71 GLENCORSE KIRK RD TO C40 BUSHLOAN RD**

**Safety Inspection of Amey A702 Safety Inspection on 05 October 2016**  
*No defects recorded*

**Safety Inspection of Amey A702 Safety Inspection on 12 October 2016**  
*No defects recorded*

**Safety Inspection of Amey A702 Safety Inspection on 19 October 2016**  
*No defects recorded*

**Safety Inspection of Amey A702 Safety Inspection on 26 October 2016**  
*No defects recorded*

**Safety Inspection of Amey A702 Safety Inspection on 02 November 2016**  
*No defects recorded*

**Safety Inspection of Amey A702 Safety Inspection on 09 November 2016**  
*No defects recorded*

**Safety Inspection of Amey A702 Safety Inspection on 16 November 2016**  
*No defects recorded*

**Safety Inspection of Amey A702 Safety Inspection on 23 November 2016**  
*No defects recorded*

**Safety Inspection of Amey A702 Safety Inspection on 30 November 2016**  
*No defects recorded*