

Address 1	L.A. Code	Defect	Description	Date Ordered	Date Originated	Date Completed	Stage	Action	Client Target Due	Originated	Latest Cost	Link ID	Section Reference	Location	Selection Due	Order Target Due	Activity	Client Perf.	Over-run	Unit Type	RSP	Action Type Description	Priority
14940/10 A726 E/B: CARMUNNOCK BYPASS RBT TO PHILLIPSHILL INTERCHANGE FLYOVER	3260J	LAMP	Lamp # R34 out.	08/01/2018	08/01/2018	08/01/2018	APPROVED	P1	13/01/2018	08/01/2018	0	14940	14940/10	A726 EB Carmunock to Philliphill		13/01/2018	SLF	0	0	LIGHTING POINT	3	CAT-1 Permanent	4 5 DAYS
14940/10 A726 E/B: CARMUNNOCK BYPASS RBT TO PHILLIPSHILL INTERCHANGE FLYOVER	3231J	POTH	Large Pot-hole in Lane 2 at centre of Flyover 600 x 300 Carry out Repair With Visals	08/12/2018	08/12/2018	08/12/2018	APPROVED	P1	08/12/2018	08/12/2018 11:50		14940	14940/10	A726 East Philliphill Flyover		08/12/2018	INC	0	0	CANAL/GRANITE	3	CAT-1 Permanent	0 IMMEDIATE
14940/11 A726 W/B: PHILLIPSHILL INTERCHANGE FLYOVER TO CARMUNNOCK BYPASS R/B/OUT	3260J	LAMP	Lamp # R49 out.	08/01/2018	08/01/2018	08/01/2018	APPROVED	P1	13/01/2018	08/01/2018	0	14940	14940/11	WB Philliphill to Carmunock		13/01/2018	SLF	0	0	LIGHTING POINT	3	CAT-1 Permanent	4 5 DAYS
14945/10 A726 E/B: PHILLIPSHILL INTERCHANGE FLYOVER TO WEST KAMNS R/B/OUT	3251J	LAMP	No U Turn Sign Lamp out.	11/12/2018	11/12/2018	11/12/2018	APPROVED	P1	16/12/2018	11/12/2018	0	14945	14945/10	A726 Philliphill to Westkams		16/12/2018	CS	1	0	SIGNS	8	CAT-1 Permanent	4 5 DAYS