

Document: Form 149	Incident Response Report	BEAR TRANSPORT
Issue: 5		
Related to: All Contracts		
Page No. 1 of 2		

Unit	NW	Route	A03	Link/Section	16520/58	Incident Reference	56412
Date	13/7/18	Latitude		Longitude		Chainage (ILO enters)	

Type of incident (refer guidance)	RTA	
XSP (refer guidance)	Direction of travel (refer guidance)	

Exact location details (refer guidance)	STONE POINT CINDERARY	Photos of incident	Yes	No
---	-----------------------	--------------------	-----	----

Disruption type (refer guidance)	GRAVEL ON ROAD - FOR TRUCK ACCIDENT	Diversion used (refer guidance)	N/A
----------------------------------	-------------------------------------	---------------------------------	-----

Weather conditions (refer guidance)	DRY + SUNNY	Road conditions (refer guidance)	DRY - NEW SURFACE
-------------------------------------	-------------	----------------------------------	-------------------

ISU / TRISS called out by	CONTROL	Mol Reference No. (ILO enters)	NW1872589
---------------------------	---------	--------------------------------	-----------

ISU or TRISS	ISU / TRISS vehicle reg.	A, Incident start time	B, Time arrived at site	C, Response time (B-A)	Response on time?	Time off site
	KX66 YRL	18:00	18:55	00:55	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	21:00

D, Reason for failure to meet response time if C is more than 1 hour (7am to 7pm) or 1.5 hours (7pm to 7am) for ISU or 20 minutes for TRISS

E, Operations Manager or deputy confirmation of reason for failure to meet response time at D	Signature	Date
---	-----------	------

Flood Reports	ISU / TRISS completes Flood Report where: flood is over 3cms deep or water lying represents a hazard to road users / may interrupt the free flow of traffic or b) may cause damage to other Structures or the carriageway or c) may cause damage to adjacent property or land. ILO populates in IRIS and enters RMMf defect reference	Yes	<input checked="" type="checkbox"/> No
---------------	---	-----	--

Response details	ARRIVED ON SITE - PUT SLOW SIGN OUT AND WAITED ON ROAD SWEEPER TO COME AND CLEAR ROAD OF STONES	Photos of work	Yes	No
------------------	---	----------------	-----	----

Further works required on site - OI(s) to be raised	advise on further work, eg permanent patch 2.0m x 1.0m required, new sign plate and 2 posts required etc	N/A
---	--	-----

Damage to Crown Property details	eg damage to verge / fencing / signs / carriageway / lighting units / bollards - or enter "NO DCP"	N/A
----------------------------------	--	-----

Car registration number / names details of persons involved

SEPA notified	Dead animal details	including red, roe or fallow deer, otter, badger, red squirrel, raptor species
No	Yes	

Emergency Services in attendance	<input checked="" type="checkbox"/> Police	<input type="checkbox"/> Ambulance	<input type="checkbox"/> Fire	Police Incident Number
----------------------------------	--	------------------------------------	-------------------------------	------------------------

Initial resources attended incident

Name	On site	Off site	Vehicle/Plant	On site	Off site	Comments
	18:55	21:00	VAN KX66 YRL (ISU)	18:55	21:00	
	18:55	21:00				

Secondary or Contingency resources attended incident

Time Called Out	Name	On site	Off site	Vehicle/Plant	On site	Off site	Comments

I hereby certify that the details and resources stated above accurately represent the Incident and the subsequent ISU / TRISS response.

Sign/ Print name/ Date Incident Liaison on site	Sign/ Print name/ Date Manager/ Supervisor
---	--

Signature	Signature
-----------	-----------

Print Name/ Date	Print Name/ Date
	23/7/18