

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 28/10/2017 and 28/11/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Section Code is 15010/05) Or

(Section Code is 15010/06)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	---------	-------	-----------	-------------	-----------------	--------------------------	----------------	-----------------	----------------------

15010/05 : WITH: BIRNIEHILL RBT TO WHITEMOSS RBT (KINGSWAY)

Detailed Inspections - Category A Footways of E Kilbride CatA Footways 3 on 20 November 2017

No defects recorded

Detailed Inspections - Category A Footways of E Kilbride CatA Footways 3 on 18 December 2017

No defects recorded

Detailed Inspections - Category A Footways of E Kilbride CatA Footways 3 on 15 January 2018

No defects recorded

Detailed Inspections - Category A Footways of E Kilbride CatA Footways 3 on 12 February 2018

No defects recorded

Detailed Inspections - Category A Footways of E Kilbride CatA Footways 3 on 12 March 2018

No defects recorded

Detailed Inspections - Category A Footways of E Kilbride CatA Footways 3 on 09 April 2018

No defects recorded

Detailed Inspections - Category A Footways of E Kilbride CatA Footways 3 on 04 May 2018

No defects recorded

Detailed Inspections - Category A Footways of E Kilbride CatA Footways 3 on 04 June 2018

No defects recorded

Detailed Inspections - Category A Footways of E Kilbride CatA Footways 3 on 02 July 2018

No defects recorded

Detailed Inspections - Category A Footways of E Kilbride CatA Footways 3 on 30 July 2018

No defects recorded

Detailed Inspections - Category A Footways of E Kilbride CatA Footways 3 on 27 August 2018

No defects recorded

Detailed Inspections - Category A Footways of E Kilbride CatA Footways 3 on 24 September 2018

No defects recorded

Detailed Inspections - Category A Footways of E Kilbride CatA Footways 3 on 22 October 2018

SW85-425273-4	92m	92m	FOOTWAY	Overgrown by vegetation (OVGV)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A725 PATHWAY
---------------	-----	-----	---------	--------------------------------	-------	------------	-----------------------	------------	--------------

Detailed Inspections - Category A Footways of E Kilbride CatA Footways 3 on 19 November 2018

No defects recorded

15010/06 : AGAINST: WMOSS RBT TO BIRNIEHILL RBT (KINGSWAY)

Detailed Inspections - Category A Footways of E Kilbride CatA Footways 3 on 20 November 2017

No defects recorded

Detailed Inspections - Category A Footways of E Kilbride CatA Footways 3 on 18 December 2017

No defects recorded

Detailed Inspections - Category A Footways of E Kilbride CatA Footways 3 on 15 January 2018

No defects recorded

Detailed Inspections - Category A Footways of E Kilbride CatA Footways 3 on 12 February 2018

No defects recorded

Detailed Inspections - Category A Footways of E Kilbride CatA Footways 3 on 12 March 2018

No defects recorded

Detailed Inspections - Category A Footways of E Kilbride CatA Footways 3 on 09 April 2018

No defects recorded

Detailed Inspections - Category A Footways of E Kilbride CatA Footways 3 on 04 May 2018

No defects recorded

Detailed Inspections - Category A Footways of E Kilbride CatA Footways 3 on 04 June 2018

No defects recorded

Detailed Inspections - Category A Footways of E Kilbride CatA Footways 3 on 02 July 2018

No defects recorded

Detailed Inspections - Category A Footways of E Kilbride CatA Footways 3 on 30 July 2018

No defects recorded

Detailed Inspections - Category A Footways of E Kilbride CatA Footways 3 on 27 August 2018

No defects recorded

Detailed Inspections - Category A Footways of E Kilbride CatA Footways 3 on 24 September 2018

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

No defects recorded

Detailed Inspections - Category A Footways of E Kilbride CatA Footways 3 on 22 October 2018

No defects recorded

Detailed Inspections - Category A Footways of E Kilbride CatA Footways 3 on 19 November 2018

No defects recorded