

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/01/2018 and 31/12/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'THE MOORINGS TO GOGO ST JUNCTION',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
14015/72 : THE MOORINGS TO GOGO ST JUNCTION									
Safety Inspection of A78 Ayr V1 on 03 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A78 Ayr V1 on 10 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A78 Ayr V1 on 17 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A78 Ayr V1 on 24 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A78 Ayr V1 on 31 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A78 Ayr V1 on 07 February 2018									
<i>No defects recorded</i>									
Detailed Inspections - Category B Footways of A78 Largs Footways V1 on 12 February 2018									
SW82318557-2	302m	352m	FOOTWAY	Bituminous surfacing - extensive cracking (BECK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	largs, opposite pearson garage
Safety Inspection of A78 Ayr V1 on 14 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A78 Ayr V1 on 21 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A78 Ayr V1 on 28 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A78 Ayr V1 on 07 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A78 Ayr V1 on 14 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A78 Ayr V1 on 21 March 2018									
SW82329917-235603130	130m	131m	CARRIAGEWAY	Pothole (POTH)	CAT 1	18/04/2018	Completed Defects	21/03/2018	A78 NB FW, LARGS, OUTSIDE GREGGS
Safety Inspection of A78 Ayr V1 on 28 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A78 Ayr V1 on 04 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A78 Ayr V1 on 11 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A78 Ayr V1 on 18 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A78 Ayr V1 on 25 April 2018									
<i>No defects recorded</i>									
Detailed Inspection TEMPLATE of A78 Ayr V1 on 11 April 2018									
SW82331779-348	268m	368m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW82331779-349	308m	410m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW82331779-343	22m	62m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW82331779-344	64m	164m	CARRIAGEWAY	Localised	CAT 2	01/01/9999	Cat 2 Awaiting	01/01/9999	

Asset ID	Length	Width	Category	Defect Description	CAT	Date	Action	Completion Date	Notes
SW82331779-346	171m	0m	CARRIAGEWAY	cracking (LOCK) Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW82331779-347	207m	307m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW82331779-345	130m	230m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	

Detailed Inspection - All other Footways of A78 Ayr V1

No defects recorded

Detailed Inspection - Covers, Gratings and Frames of A78 Ayr V1

No defects recorded

Detailed Inspection - Gully, Catchpit, Manhole etc of A78 Ayr V1

No defects recorded

Detailed Inspection - Kerbs, Channels, Edgings of A78 Ayr V1

No defects recorded

Safety Inspection of A78 Ayr V1 on 02 May 2018

No defects recorded

Safety Inspection of A78 Ayr V1 on 09 May 2018

No defects recorded

Detailed Inspections - Category B Footways of A78 Largs Footways V1 on 14 May 2018

SW82349142-1	72m	73m	FOOTWAY	Bituminous surfacing - potholes (BPOT)	CAT 1	11/06/2018	Completed Defects	15/05/2018	A78 SB FW, OUTSIDE THE GEORGE PUB, LARGS, NEXT TO BENCH
--------------	-----	-----	---------	--	-------	------------	-------------------	------------	---

Safety Inspection of A78 Ayr V1 on 16 May 2018

No defects recorded

Safety Inspection of A78 Ayr V1 on 23 May 2018

No defects recorded

Safety Inspection of A78 Ayr V1 on 30 May 2018

No defects recorded

Safety Inspection of A78 Ayr V1 on 06 June 2018

No defects recorded

Safety Inspection of A78 Ayr V1 on 13 June 2018

No defects recorded

Safety Inspection of A78 Ayr V1 on 20 June 2018

No defects recorded

Detailed Inspection TEMPLATE of A78 Ayr V1 on 21 June 2018

No defects recorded

Safety Inspection of A78 Ayr V1 on 27 June 2018

SW82370027-235867563	340m	341m	MANHOLE	Rocking under load (IRLD)	3RD PTY	25/07/2018	Completed Defects	14/11/2018	A78 NB CW OPPOSITE SUZUKI GARAGE MAIN ST LARGS
----------------------	------	------	---------	---------------------------	---------	------------	-------------------	------------	--

Safety Inspection of A78 Ayr V1 on 04 July 2018

No defects recorded

Safety Inspection of A78 Ayr V1 on 11 July 2018

No defects recorded

Safety Inspection of A78 Ayr V1 on 18 July 2018

No defects recorded

Safety Inspection of A78 Ayr V1 on 25 July 2018

No defects recorded

Safety Inspection of A78 Ayr V1 on 01 August 2018

No defects recorded

Detailed Inspections - Category B Footways of A78 Largs Footways V1 on 01 August 2018

No defects recorded

Safety Inspection of A78 Ayr V1 on 08 August 2018

SW80-390200-235944306	312m	313m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	05/09/2018	Completed Defects	08/08/2018	A78 SB FOOTPATH OUTSIDE SUZUKI GARAGE LARGS MAIN ST
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	---

Safety Inspection of A78 Ayr V1 on 15 August 2018

No defects recorded

Safety Inspection of A78 Ayr V1 on 22 August 2018

No defects recorded

Safety Inspection of A78 Ayr V1 on 29 August 2018

No defects recorded

Safety Inspection of A78 Ayr V1 on 05 September 2018

No defects recorded

Safety Inspection of A78 Ayr V1 on 12 September 2018

No defects recorded

Safety Inspection of A78 Ayr V1 on 19 September 2018

No defects recorded

Safety Inspection of A78 Ayr V1 on 26 September 2018

No defects recorded

Safety Inspection of A78 Ayr V1 on 03 October 2018

No defects recorded

Safety Inspection of A78 Ayr V1 on 10 October 2018

No defects recorded

Safety Inspection of A78 Ayr V1 on 17 October 2018

No defects recorded

Safety Inspection of A78 Ayr V1 on 24 October 2018

SW82425913-236154324	165m	166m	ROAD_MARKINGS _HATCHED	Wear (for example erosion) (WEAR)	CAT 1	21/11/2018	Completed Defects	24/02/2019	A78 SB CW OUTSIDE BLUE LAGOON LARGS AT TRAFFIC LIGHTS
----------------------	------	------	---------------------------	--	-------	------------	----------------------	------------	---

Safety Inspection of A78 Ayr V1 on 31 October 2018

No defects recorded

Detailed Inspections - Category B Footways of A78 Largs Footways V1 on 31 October 2018

SW80-426214-4	108m	118m	FOOTWAY	Bituminous surfacing - local cracking (BLCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A78 NB CW OUTSIDE TIMPSONS LARGS
SW80-426214-2	305m	306m	FOOTWAY	Bituminous surfacing - potholes (BPOT)	CAT 1	01/11/2018	Awaiting CCMS Permanent	31/10/2018	A78 SB 15M FROM PEARSONS GARAGE LARGS
SW80-426214-3	305m	306m	FOOTWAY	Bituminous surfacing - potholes (BPOT)	CAT 1	01/11/2018	Awaiting CCMS Permanent	31/10/2018	A78 SB 10M FROM PEARSONS GARAGE LARGS
SW80-426214-1	122m	124m	FOOTWAY	Slab profile - uneven/trips (SLPF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	OUTSIDE INDIGO SQUARE LARGS

Safety Inspection of A78 Ayr V1 on 07 November 2018

No defects recorded

Safety Inspection of A78 Ayr V1 on 14 November 2018

SW82426560-236228428	321m	321m	GULLY	Rocking under load (IRLD)	3RD PTY	12/12/2018	Awaiting CCMS Permanent	01/01/9999	A78 NB CW AT PEDESTRIAN CROSSING OUTSIDE SUZUKI GARAGE LARGS
----------------------	------	------	-------	------------------------------	---------	------------	----------------------------	------------	--

Safety Inspection of A78 Ayr V1 on 21 November 2018

No defects recorded

Safety Inspection of A78 Ayr V1 on 28 November 2018

No defects recorded

Safety Inspection of A78 Ayr V1 on 05 December 2018

No defects recorded

Safety Inspection of A78 Ayr V1 on 12 December 2018

No defects recorded

Safety Inspection of A78 Ayr V1 on 19 December 2018

No defects recorded

Safety Inspection of A78 Ayr V1 on 26 December 2018

No defects recorded

