

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 03/02/2019 and 16/02/2019, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'AGAINST: GREENHEAD RD TO A914 DUMBUCK',) Or

(Section is 'AGAINST: A914 DUMBUCK TO DUNGLASS RBT',) Or

(Section is 'WITH: DUNGLASS RBT TO A914 DUMBUCK',) Or

(Section is 'WITH: A914 DUMBUCK TO GREENHEAD ROAD',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
10810/05 : WITH: DUNGLASS RBT TO A914 DUMBUCK									
Safety Inspection of A82 Inspection on 07 February 2019									
SW77-429480-236310217	1,239m	1,239m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	08/02/2019	Completed Defects	07/02/2019	A82 NB AT MILLERSLEA
Safety Inspection of A82 Inspection on 14 February 2019									
<i>No defects recorded</i>									
10813/05 : WITH: A914 DUMBUCK TO GREENHEAD ROAD									
Safety Inspection of A82 Inspection on 07 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A82 Inspection on 14 February 2019									
<i>No defects recorded</i>									
10813/06 : AGAINST: GREENHEAD RD TO A914 DUMBUCK									
Safety Inspection of A82 Inspection on 07 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A82 Inspection on 14 February 2019									
SW77-430224-236328625	1,424m	1,424m	MANHOLE	Rocking under load (IRLD)	CAT 1	14/03/2019	Awaiting CCMS Temp Date	01/01/9999	A82 SB GLASGOW RD T/LIGHTS
SW77-430224-236328626	1,422m	1,422m	GULLY	Rocking under load (IRLD)	CAT 1	14/03/2019	Awaiting CCMS Temp Date	01/01/9999	A82 SB GLASGOW RD TRAFFIC LIGHTS
10810/06 : AGAINST: A914 DUMBUCK TO DUNGLASS RBT									
Safety Inspection of A82 Inspection on 07 February 2019									
SW77-429480-236310218	684m	685m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	08/02/2019	Completed Defects	07/02/2019	A82 SB AT BP PETROL STATION
SW77-429480-236310219	720m	721m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	08/02/2019	Completed Defects	07/02/2019	A82 SB AT BP GARAGE
SW77-429480-236310221	742m	742m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	08/02/2019	Completed Defects	07/02/2019	A82 SB AT BP ENTRANCE
SW77-429480-236310220	771m	771m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	08/02/2019	Completed Defects	07/02/2019	A82 SB AT BP GARAGE
Safety Inspection of A82 Inspection on 14 February 2019									
<i>No defects recorded</i>									

