

# Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/01/2018 and 31/03/2019, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'WITH: ON SLIP FROM A76/A71 TO M77 DBFO BOUNDARY','HURLFORD INTERCHANGE ROUNDABOUT','WITH: ON SLIP FROM A76/A71 TO OFF SLIP TO B7038','WITH: HURLFORD INTERCHANGE-JCT OF N/B TR.ROAD','AGAINST: OFF SLIP A76/A71 TO 300M N WHATRIGGS BRID','AGAINST: HURLFORD INTERCHANGE-JCT OF S/B TR.ROAD','WITH: OFF SLIP TO A76/A71 TO ON SLIP FROM A76/A71','WITH: N/B SLIP RD EXIT-HURLFORD INTERCHANGE','WITH: 300M N WHATRIGGS BR TO OFF SLIP TO A76/A71','\*','\*','AGAINST: 300M N OF WHATRIGGS BR TO E. AYRSHIRE BDY','WITH: EAST AYRSHIRE BDY TO 300M N OF WHATRIGGS BR','AGAINST: EAST AYRSHIRE BDY TO SPITALHILL SLIP ROAD','WITH: SPITALHILL SLIP RD TO EAST AYRSHIRE BOUNDARY','AGAINST: K&C DIST BDY STH BND-95M S OF SLIP ROAD','WITH: SPITALHILL SL.RD N/BD-K&L DIST BDY','AGAINST: SPITALHILL SLIP ROAD TO EAST LODGE','WITH: EAST LODGE TO SPITALHILL SLIP ROAD','AGAINST: EAST LODGE TO SYMINGTON SB','WITH: SYMINGTON NB TO EAST LODGE','AGAINST: SYMINGTON SB TO DUTCH HOUSE RBT','WITH: DUTCH HOUSE ROUNDABOUT TO SYMINGTON NB','DUTCH HOUSE ROUNDABOUT','AGAINST: DUTCH HOUSE RBT TO SANDYFORD TOLL RBT','AGAINST: DUTCH HOUSE RBT TO A719 JCT SANDYFORD TOL','WITH: SANDYFORD TOLL R/BOUT to Dutch House Rbt','WITH: A719 JCT SANDYFORD TOLL TO DUTCH HOUSE RBT','SANDYFORD TOLL ROUNDABOUT','Against: Start of 4 lane to Whitletts Rbt','Against: Sandyford Toll Rbt to start of 4 lane','AGAINST: SANDYFORD TOLL R/BOUT TO WHITLETTS R/BOUT','AGAINST: A719 JCT SANDYFORD TOLL TO WHITLETTS RBT','WITH: WHITLETTS ROUNDABOUT TO SANDYFORD TOLL RBT','WITH: WHITLETTS RBT TO A719 JCT SANDYFORD TOLL','Whitletts Roundabout','WHITLETTS ROUNDABOUT','AGAINST: WHITLETTS RBT TO END EXIT WHITLETTS RBT','WITH: START ENTRY WHITLETTS RBT TO WHITLETTS RBT','Against: SB Exit from Whitletts Rbt','With: NB Entry to Whitletts Rbt','Start of 3 Lane to Rbt approach','HOLMSTON ROUNDABOUT TO START ENTRY WHITLETTS RBT','Holmston Rbt to start of 3 lane','HOLMSTON ROUNDABOUT','Start of Single 4-Lane to Holmston Roundabout','End of Climbing Lane to Start of 4 Lane Single','Bankhead Rbt to End of Climbing Lane','BANKHEAD ROUNDABOUT TO HOLMSTON ROUNDABOUT','BANKHEAD ROUNDABOUT','A79 JUNCTION MAYBOLE RD AYR TO BANKHEAD RBT','B7034 JUNCTION TO JUNCTION A79 MAYBOLE ROAD AYR','CULROY BURN BRIDGE TO B7034 JUNCTION','JUNCTION KEWNSTON TO CULROY BURN BRIDGE','SMITHSTON BRIDGE TO JUNCTION KEWNSTON','JUNCTION DRUMELLAN TO SMITHSTON BRIDGE','LYONSTON FARM TO JUNCTION DRUMELLAN','JUNCTION B7023 CULZEAN ROAD TO LYONSTON FARM','JCT JOHN KNOX ST TO JCT B7023 CULZEAN RD','JUNCTION LADYLAND ROAD TO JUNCTION JOHN KNOX ST','30MPH SIGN MAYBOLE TO JUNCTION LADYLAND ROAD','JCT BROOMKNOWES FM TO 30 MPH SIGN MAYBOLE','JCT BLANEFIELD TO JUNCTION BROOMKNOWES FARM','OLD TOLL COTTAGE TO JUNCTION BLANEFIELD','JUNCTION KIRK BRAE KIRKOSWALD TO OLD TOLL COTTAGE','HIGH PARK TO JUNCTION KIRK BRAE KIRKOSWALD','NTH END TURNBERRY CLIMBING LANE TO HIGH PARK','TURNBERRY CLIMBING LANE','A719 JUNCTION TO HIGH PARK','A719 JCT TO STH END TURNBERRY CLIMBING LANE','DIPPLE,FACTORY ENTRANCE TO A719 JUNCTION','BRIDGEMILL ROUNDABOUT TO DIPPLE,FACTORY ENTRANCE','BRIDGEMILL ROUNDABOUT','RAILWAY BRIDGE TO BRIDGEMILL ROUNDABOUT','JUNCTION MONTGOMERIE STREET TO RAILWAY BRIDGE','END OF GRAVEYARD TO JUNCTION MONTGOMERIE STREET','SHALLOCHPARK ROUNDABOUT TO JUNCTION KIRKPATRICK ST','STUMPY CORNER JUNCTION TO END OF GRAVEYARD','DUFF STREET TO KIRKPATRICK STREET RBT','WESLEY ROAD TO DUFF STREET','Against: STUMPY CORNER TO WESLEY ROAD','HENRIETTA STREET RBT TO STUMPY CORNER','HENRIETTA STREET ROUNDABOUT','DUNCAN STREET TO HENRIETTA STREET RBT','JUNCTION KIRKPATRICK ST TO JUNCTION DUFF STREET','YOUNG STREET TO DUNCAN STREET','B734 KIRKPATRICK STREET RBT TO YOUNG STREET','B734 KIRKPATRICK STREET ROUNDABOUT','A714 SHALLOCHPARK RBT TO B734 KIRKPATRICK ST RBT','A714 SHALLOCHPARK ROUNDABOUT','ARDMILLAN CASTLE TO A714 SHALLOCHPARK ROUNDABOUT','ARDMILLAN LODGE TO SHALLOCHPARK ROUNDABOUT/B','ARDMILLAN LODGE TO SHALLOCHPARK ROUNDABOUT','ARDMILLAN LODGE TO SHALLOCHPARK ROUNDABOUT/A','ARDMILLAN LODGE TO SHALLOCHPARK ROUNDABOUT','LENDALFOOT BRIDGE TO ARDMILLAN CASTLE','CARLETON FISHERIES TO LENDALFOOT BRIDGE','\*','\*','JUNCTION LITTLE BENNANE TO CARLETON FISHERIES','Bennane Jct to Little Bennane Jct','\*','\*','End of SB climbing lane to Bennane Jct','B734 JUNCTION TO JUNCTION LITTLE BENNANE','B734 Jct to end of SB climbing lane','End of NB climbing lane to B734 Jct','Start to End of NB climbing lane','BALANTRAE BAY JCT TO B734 JCT','B7044 Jct to Start of climbing lane','B7044 JCT TO BALANTRAE BAY JCT','OLD SMYRTON TO B7044 JUNCTION','JCT BALLOCHDOWAN TO OLD SMYRTON','JCT AT CARLOCK HOUSE TO JCT AT BALLOCHDOWAN','JCT AT CARLOCK HOUSE TO JCT AT BALLOCHDOWAN','NORTH MARK BRIDGE TO JUNCTION AT CARLOCK HOUSE','HAGGSTONE CL NORTH END TO NORTH MARK BRIDGE','HAGGSTONE CLIMBING LANE','JUNCTION FINNARTS FARM TO NORTH MARK BRIDGE','SOUTH AYRSHIRE BOUNDARY TO HAGGSTONE CL SOUTH END','SOUTH AYRSHIRE BOUNDARY TO JUNCTION FINNARTS FARM','JUNCTION BONNY BRAES TO SOUTH AYRSHIRE BOUNDARY','DERESTRICTION SIGN CAIRNRYAN TO JCT BONNY BRAES','DRUMMUCKLOCH FARM TO DERESTRICTION SIGN CAIRNRYAN','JUNCTION BEOCH TO DRUMMUCKLOCH FARM','A751 DUMFRIES JUNCTION TO JUNCTION BEOCH','MCMASTERS ROAD TO A751 DUMFRIES JUNCTION','A718 JUNCTION TO MCMASTERS ROAD','STAIR DRIVE A75 JUNCTION TO A718 JUNCTION','WITH: START OF M77 TO MALLETSHEUGH INT. OFF SLIP'.)

| Defect Reference  | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|---|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|
| <b>11601/05 : STAIR DRIVE A75 JUNCTION TO A718 JUNCTION</b>                       |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 03 January 2018</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 10 January 2018</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 17 January 2018</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 24 January 2018</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 31 January 2018</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 07 February 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 14 February 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 21 February 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 28 February 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |

| Defect Reference   | Start<br>m | End<br>m | Item Type   | Item Detail                                | Defect<br>Category | Required<br>Completion Date | Current Status       | Completion<br>Date | Location Description           |
|--|------------|----------|-------------|--|--------------------|-----------------------------|----------------------|--------------------|--------------------------------|
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 07 March 2018</b>   |            |          |             |  |                    |                             |                      |                    |                                |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |                                |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 14 March 2018</b>   |            |          |             |  |                    |                             |                      |                    |                                |
| SW81-327800-235583893  | 12m        | 0m       | CARRIAGEWAY | Pothole<br>(POTH)                          | CAT 1              | 15/03/2018                  | Completed<br>Defects | 14/03/2018         | A75 @ STAIR DRIVE JCT          |
| SW81-327800-235583897  | 165m       | 0m       | CARRIAGEWAY | Pothole<br>(POTH)                          | CAT 1              | 15/03/2018                  | Completed<br>Defects | 14/03/2018         | A77 STAIR DRIVE                |
| SW81-327800-235583895  | 90m        | 0m       | CARRIAGEWAY | Pothole<br>(POTH)                          | CAT 1              | 15/03/2018                  | Completed<br>Defects | 14/03/2018         | A77 STAIR DRIVE                |
| SW81-327800-235583898  | 162m       | 0m       | CARRIAGEWAY | Pothole<br>(POTH)                          | CAT 1              | 15/03/2018                  | Completed<br>Defects | 14/03/2018         | A77 STAIR DRIVE                |
| SW81-327800-235583894  | 33m        | 0m       | CARRIAGEWAY | Pothole<br>(POTH)                          | CAT 1              | 15/03/2018                  | Completed<br>Defects | 14/03/2018         | A75 @ STAIR DRIVE JCT          |
| SW81-327800-235583896  | 100m       | 0m       | CARRIAGEWAY | Pothole<br>(POTH)                          | CAT 1              | 15/03/2018                  | Completed<br>Defects | 14/03/2018         | A77 STAIR DRIVE                |
| SW81-327800-235583892  | 29m        | 0m       | CARRIAGEWAY | Pothole<br>(POTH)                          | CAT 1              | 15/03/2018                  | Completed<br>Defects | 14/03/2018         | A75 @ STAIR DRIVE JCT          |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 21 March 2018</b>   |            |          |             |  |                    |                             |                      |                    |                                |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |                                |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 28 March 2018</b>   |            |          |             |  |                    |                             |                      |                    |                                |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |                                |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 04 April 2018</b>   |            |          |             |  |                    |                             |                      |                    |                                |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |                                |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 11 April 2018</b>   |            |          |             |  |                    |                             |                      |                    |                                |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |                                |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 18 April 2018</b>   |            |          |             |  |                    |                             |                      |                    |                                |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |                                |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 25 April 2018</b>   |            |          |             |  |                    |                             |                      |                    |                                |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |                                |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 02 May 2018</b>  |            |          |             |  |                    |                             |                      |                    |                                |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |                                |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 09 May 2018</b>  |            |          |             |  |                    |                             |                      |                    |                                |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |                                |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 16 May 2018</b>  |            |          |             |  |                    |                             |                      |                    |                                |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |                                |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 23 May 2018</b>  |            |          |             |  |                    |                             |                      |                    |                                |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |                                |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 30 May 2018</b>  |            |          |             |  |                    |                             |                      |                    |                                |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |                                |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 06 June 2018</b> |            |          |             |  |                    |                             |                      |                    |                                |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |                                |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 13 June 2018</b> |            |          |             |  |                    |                             |                      |                    |                                |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |                                |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 20 June 2018</b> |            |          |             |  |                    |                             |                      |                    |                                |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |                                |
| <b>Detailed Inspection TEMPLATE of A77 Dfs Detail on 27 June 2018</b>            |            |          |             |  |                    |                             |                      |                    |                                |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |                                |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 27 June 2018</b> |            |          |             |  |                    |                             |                      |                    |                                |
| SW81-370039-235865517  | 125m       | 0m       | CARRIAGEWAY | Pothole VIAFIX<br>(POTV)                   | CAT 1              | 28/06/2018                  | Completed<br>Defects | 27/06/2018         | A77 E/B C/WAY @ STAIR<br>DRIVE |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 04 July 2018</b> |            |          |             |  |                    |                             |                      |                    |                                |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |                                |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 11 July 2018</b> |            |          |             |  |                    |                             |                      |                    |                                |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |                                |
| <b>Detailed Inspection TEMPLATE of A77 Dfs Detail on 16 July 2018</b>            |            |          |             |  |                    |                             |                      |                    |                                |
| SW81-332073-3  | 10m        | 190m     | CARRIAGEWAY | Bituminous<br>surfacing<br>fretting (BFRT) | CAT 2              | 01/01/9999                  | Completed<br>Defects | 10/08/2018         |                                |

| Defect Reference | Start m | End m | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description |
|------------------|---------|-------|-------------|--------------------------------------|-----------------|--------------------------|-------------------|-----------------|----------------------|
| SW81-332073-2    | 11m     | 190m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Completed Defects | 10/08/2018      |                      |
| SW81-332073-4    | 107m    | 114m  | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Completed Defects | 10/08/2018      |                      |

**Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 18 July 2018**

*No defects recorded*

**Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 25 July 2018**

*No defects recorded*

**Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 01 August 2018**

*No defects recorded*

**Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 08 August 2018**

*No defects recorded*

**Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 15 August 2018**

*No defects recorded*

**Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 22 August 2018**

*No defects recorded*

**Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 29 August 2018**

*No defects recorded*

**Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 05 September 2018**

*No defects recorded*

**Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 12 September 2018**

*No defects recorded*

**Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 19 September 2018**

*No defects recorded*

**Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 26 September 2018**

*No defects recorded*

**Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 03 October 2018**

*No defects recorded*

**Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 10 October 2018**

*No defects recorded*

**Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 17 October 2018**

*No defects recorded*

**Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 24 October 2018**

*No defects recorded*

**Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 31 October 2018**

*No defects recorded*

**Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 07 November 2018**

*No defects recorded*

**Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 14 November 2018**

*No defects recorded*

**Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 21 November 2018**

*No defects recorded*

**Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 28 November 2018**

*No defects recorded*

**Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 05 December 2018**

*No defects recorded*

**Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 12 December 2018**

*No defects recorded*

**Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 19 December 2018**

*No defects recorded*

**Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 24 December 2018**

*No defects recorded*

**Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 31 December 2018**

*No defects recorded*

**Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 07 January 2019**

*No defects recorded*

**Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 09 January 2019**

*No defects recorded*

**Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 16 January 2019**

*No defects recorded*

**Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 23 January 2019**

*No defects recorded*

**Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 30 January 2019**

*No defects recorded*

**Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 06 February 2019**



| Defect Reference   | Start m | End m | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description |
|--|---------|-------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|----------------------|
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 13 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 20 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 27 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 06 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 13 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 20 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 27 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                      |
| <b>11601/25 : A718 JUNCTION TO MCMASTERS ROAD</b>                                    |         |       |             |                       |                 |                          |                   |                 |                      |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 03 January 2018</b>     |         |       |             |                       |                 |                          |                   |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                      |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 10 January 2018</b>     |         |       |             |                       |                 |                          |                   |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                      |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 17 January 2018</b>     |         |       |             |                       |                 |                          |                   |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                      |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 24 January 2018</b>     |         |       |             |                       |                 |                          |                   |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                      |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 31 January 2018</b>     |         |       |             |                       |                 |                          |                   |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                      |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 07 February 2018</b>    |         |       |             |                       |                 |                          |                   |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                      |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 14 February 2018</b>    |         |       |             |                       |                 |                          |                   |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                      |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 21 February 2018</b>    |         |       |             |                       |                 |                          |                   |                 |                      |
| SW81-321674-235545622  | 208m    | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 22/02/2018               | Completed Defects | 21/02/2018      | A77 LONDON RD        |
| SW81-321674-235545621  | 524m    | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 22/02/2018               | Completed Defects | 21/02/2018      | A77 LONDON RD        |
| SW81-321674-235545620  | 528m    | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 22/02/2018               | Completed Defects | 21/02/2018      | A77 LONDON RD        |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 28 February 2018</b>    |         |       |             |                       |                 |                          |                   |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                      |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 07 March 2018</b>       |         |       |             |                       |                 |                          |                   |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                      |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 14 March 2018</b>       |         |       |             |                       |                 |                          |                   |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                      |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 21 March 2018</b>       |         |       |             |                       |                 |                          |                   |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                      |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 28 March 2018</b>       |         |       |             |                       |                 |                          |                   |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                      |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 04 April 2018</b>       |         |       |             |                       |                 |                          |                   |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                      |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 11 April 2018</b>       |         |       |             |                       |                 |                          |                   |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                      |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 18 April 2018</b>       |         |       |             |                       |                 |                          |                   |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                      |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 25 April 2018</b>       |         |       |             |                       |                 |                          |                   |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 02 May 2018</b>      |         |       |             |                       |                 |                          |                   |                 |                      |
| SW81-343546-235661444  | 17m     | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 03/05/2018               | Completed Defects | 02/05/2018      | A77 @ STAIR DRIVE    |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 09 May 2018</b>      |         |       |             |                       |                 |                          |                   |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 16 May 2018</b>      |         |       |             |                       |                 |                          |                   |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                      |

| Defect Reference  | Start m | End m | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description              |
|---|---------|-------|-------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|-----------------------------------|
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 23 May 2018</b>       |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 30 May 2018</b>       |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 06 June 2018</b>      |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 13 June 2018</b>      |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 20 June 2018</b>      |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <b>Detailed Inspection TEMPLATE of A77 Dfs Detail on 27 June 2018</b>                 |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 27 June 2018</b>      |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 04 July 2018</b>      |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 11 July 2018</b>      |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <b>Detailed Inspection TEMPLATE of A77 Dfs Detail on 16 July 2018</b>                 |         |       |             |                                      |                 |                          |                       |                 |                                   |
| SW81-332073-6   | 374m    | 385m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                   |
| SW81-332073-7   | 451m    | 465m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                   |
| SW81-332073-9   | 603m    | 615m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                   |
| SW81-332073-8   | 498m    | 543m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                   |
| SW81-332073-10  | 681m    | 752m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                   |
| SW81-332073-5   | 275m    | 300m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 18 July 2018</b>      |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 25 July 2018</b>      |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 01 August 2018</b>    |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 08 August 2018</b>    |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 15 August 2018</b>    |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 22 August 2018</b>    |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 29 August 2018</b>    |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 05 September 2018</b> |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 12 September 2018</b> |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 19 September 2018</b> |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 26 September 2018</b> |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 03 October 2018</b>   |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 10 October 2018</b>   |         |       |             |                                      |                 |                          |                       |                 |                                   |
| SW79-419746-236111235   | 758m    | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 11/10/2018               | Completed Defects     | 10/10/2018      | A77 S/B C/WAY S OF MCMASTERS ROAD |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 17 October 2018</b>   |         |       |             |                                      |                 |                          |                       |                 |                                   |

| Defect Reference   | Start m | End m | Item Type           | Item Detail           | Defect Category | Required Completion Date | Current Status          | Completion Date | Location Description   |
|--|---------|-------|---------------------|-----------------------|-----------------|--------------------------|-------------------------|-----------------|--|
| SW79-422974-236143077  | 726m    | 0m    | FENCES_AND_BARRIERS | Other (OTHR)          | 3RD PTY         | 14/11/2018               | Awaiting CCMS Temp Date | 01/01/9999      | A77 N/B F/PATH OPPOSITE NEWFIELD HOUSE SOUTH OF MCMASTERS ROAD |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 24 October 2018</b>  |         |       |                     |                       |                 |                          |                         |                 |  |
| No defects recorded  |         |       |                     |                       |                 |                          |                         |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 31 October 2018</b>  |         |       |                     |                       |                 |                          |                         |                 |  |
| SW79-426104-236179898  | 56m     | 0m    | FOOTWAY             | Other (OTHR)          | CAT 1           | 01/11/2018               | Completed Defects       | 31/10/2018      | A77 N/B F/WAY 50M N OF STAIR DRIVE                             |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 07 November 2018</b> |         |       |                     |                       |                 |                          |                         |                 |  |
| No defects recorded  |         |       |                     |                       |                 |                          |                         |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 14 November 2018</b> |         |       |                     |                       |                 |                          |                         |                 |  |
| No defects recorded  |         |       |                     |                       |                 |                          |                         |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 21 November 2018</b> |         |       |                     |                       |                 |                          |                         |                 |  |
| No defects recorded  |         |       |                     |                       |                 |                          |                         |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 28 November 2018</b> |         |       |                     |                       |                 |                          |                         |                 |  |
| No defects recorded  |         |       |                     |                       |                 |                          |                         |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 05 December 2018</b> |         |       |                     |                       |                 |                          |                         |                 |  |
| No defects recorded  |         |       |                     |                       |                 |                          |                         |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 12 December 2018</b> |         |       |                     |                       |                 |                          |                         |                 |  |
| No defects recorded  |         |       |                     |                       |                 |                          |                         |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 19 December 2018</b> |         |       |                     |                       |                 |                          |                         |                 |  |
| No defects recorded  |         |       |                     |                       |                 |                          |                         |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 24 December 2018</b> |         |       |                     |                       |                 |                          |                         |                 |  |
| No defects recorded  |         |       |                     |                       |                 |                          |                         |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 31 December 2018</b> |         |       |                     |                       |                 |                          |                         |                 |  |
| No defects recorded  |         |       |                     |                       |                 |                          |                         |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 07 January 2019</b>  |         |       |                     |                       |                 |                          |                         |                 |  |
| No defects recorded  |         |       |                     |                       |                 |                          |                         |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 09 January 2019</b>  |         |       |                     |                       |                 |                          |                         |                 |  |
| No defects recorded  |         |       |                     |                       |                 |                          |                         |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 16 January 2019</b>  |         |       |                     |                       |                 |                          |                         |                 |  |
| No defects recorded  |         |       |                     |                       |                 |                          |                         |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 23 January 2019</b>  |         |       |                     |                       |                 |                          |                         |                 |  |
| No defects recorded  |         |       |                     |                       |                 |                          |                         |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 30 January 2019</b>  |         |       |                     |                       |                 |                          |                         |                 |  |
| No defects recorded  |         |       |                     |                       |                 |                          |                         |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 06 February 2019</b> |         |       |                     |                       |                 |                          |                         |                 |  |
| No defects recorded  |         |       |                     |                       |                 |                          |                         |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 13 February 2019</b> |         |       |                     |                       |                 |                          |                         |                 |  |
| No defects recorded  |         |       |                     |                       |                 |                          |                         |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 20 February 2019</b> |         |       |                     |                       |                 |                          |                         |                 |  |
| No defects recorded  |         |       |                     |                       |                 |                          |                         |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 27 February 2019</b> |         |       |                     |                       |                 |                          |                         |                 |  |
| No defects recorded  |         |       |                     |                       |                 |                          |                         |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 06 March 2019</b>    |         |       |                     |                       |                 |                          |                         |                 |  |
| No defects recorded  |         |       |                     |                       |                 |                          |                         |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 13 March 2019</b>    |         |       |                     |                       |                 |                          |                         |                 |  |
| No defects recorded  |         |       |                     |                       |                 |                          |                         |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 20 March 2019</b>    |         |       |                     |                       |                 |                          |                         |                 |  |
| No defects recorded  |         |       |                     |                       |                 |                          |                         |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 27 March 2019</b>    |         |       |                     |                       |                 |                          |                         |                 |  |
| SW79-458893-236489717  | 605m    | 0m    | CARRIAGEWAY         | Pothole VIAFIX (POTV) | CAT 1           | 28/03/2019               | Completed Defects       | 27/03/2019      | A77 S/B C/WAY 100M NORTH OF LADIES WALK                        |

#### 11605/05 : MCMASTERS ROAD TO A751 DUMFRIES JUNCTION

|  |  |  |  |  |  |  |  |  |  |
|--|--|--|--|--|--|--|--|--|--|
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 03 January 2018</b> |  |  |  |  |  |  |  |  |  |
| No defects recorded  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 10 January 2018</b> |  |  |  |  |  |  |  |  |  |
| No defects recorded  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 17 January 2018</b> |  |  |  |  |  |  |  |  |  |
| No defects recorded  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 24 January 2018</b> |  |  |  |  |  |  |  |  |  |
| No defects recorded  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 31 January 2018</b> |  |  |  |  |  |  |  |  |  |
| No defects recorded  |  |  |  |  |  |  |  |  |  |

| Defect Reference  | Start m | End m | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description               |
|---|---------|-------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|------------------------------------|
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 07 February 2018</b> |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 14 February 2018</b> |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 21 February 2018</b> |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 28 February 2018</b> |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 07 March 2018</b>    |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 14 March 2018</b>    |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 21 March 2018</b>    |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 28 March 2018</b>    |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 04 April 2018</b>    |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 11 April 2018</b>    |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 18 April 2018</b>    |         |       |             |                       |                 |                          |                   |                 |                                    |
| SW81-338586-235658111   | 301m    | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 19/04/2018               | Completed Defects | 18/04/2018      | A77 S/B C/WAY AT STRANRAER N G/WAY |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 25 April 2018</b>    |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 02 May 2018</b>   |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 09 May 2018</b>   |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 16 May 2018</b>   |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 23 May 2018</b>   |         |       |             |                       |                 |                          |                   |                 |                                    |
| SW81-352553-235789878   | 2,601m  | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 24/05/2018               | Completed Defects | 23/05/2018      | A77 N/B C/WAY @ A751 JCT           |
| SW81-352553-235789880   | 2,606m  | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 24/05/2018               | Completed Defects | 23/05/2018      | A77 N/B C/WAY @ A751 JCT           |
| SW81-352553-235789877   | 2,592m  | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 24/05/2018               | Completed Defects | 23/05/2018      | A77 N/B C/WAY @ A751 JCT           |
| SW81-352553-235789879   | 2,605m  | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 24/05/2018               | Completed Defects | 23/05/2018      | A77 N/B C/WAY @ A751 JCT           |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 30 May 2018</b>   |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 06 June 2018</b>  |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 13 June 2018</b>  |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 20 June 2018</b>  |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Detailed Inspection TEMPLATE of A77 Dfs Detail on 27 June 2018</b>             |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 27 June 2018</b>  |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 04 July 2018</b>  |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 11 July 2018</b>  |         |       |             |                       |                 |                          |                   |                 |                                    |
| SW81-376906-235909970   | 425m    | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 12/07/2018               | Completed Defects | 11/07/2018      | A77 N/B C/WAY @ STRANRAER N G/WAY  |
| SW81-376906-235909969   | 420m    | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 12/07/2018               | Completed Defects | 11/07/2018      | A77 N/B C/WAY @ STRANRAER N G/WAY  |
| <b>Detailed Inspection TEMPLATE of A77 Dfs Detail on 16 July 2018</b>             |         |       |             |                       |                 |                          |                   |                 |                                    |

| Defect Reference | Start m | End m  | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|--------|-------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW81-332073-13   | 103m    | 0m     | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW81-332073-17   | 335m    | 385m   | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW81-332073-24   | 907m    | 920m   | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW81-332073-27   | 1,082m  | 1,100m | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW81-332073-32   | 1,437m  | 1,450m | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW81-332073-33   | 1,512m  | 1,552m | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW81-332073-23   | 715m    | 735m   | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW81-332073-30   | 1,382m  | 1,400m | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW81-332073-26   | 966m    | 1,000m | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW81-332073-28   | 1,305m  | 1,340m | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW81-332073-19   | 353m    | 420m   | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW81-332073-15   | 303m    | 330m   | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW81-332073-29   | 1,363m  | 1,387m | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW81-332073-11   | 9m      | 18m    | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW81-332073-12   | 95m     | 115m   | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW81-332073-31   | 1,419m  | 1,450m | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW81-332073-25   | 959m    | 0m     | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW81-332073-14   | 174m    | 246m   | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW81-332073-16   | 307m    | 320m   | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW81-332073-18   | 343m    | 0m     | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW81-332073-20   | 537m    | 586m   | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |

Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 18 July 2018



| Defect Reference  | Start m | End m | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                     |
|---|---------|-------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|--|
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 25 July 2018</b>      |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 01 August 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 08 August 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 15 August 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 22 August 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 29 August 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 05 September 2018</b> |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 12 September 2018</b> |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 19 September 2018</b> |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 26 September 2018</b> |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 03 October 2018</b>   |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 10 October 2018</b>   |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 17 October 2018</b>   |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 24 October 2018</b>   |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 31 October 2018</b>   |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 07 November 2018</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 14 November 2018</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 21 November 2018</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 28 November 2018</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 05 December 2018</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 12 December 2018</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 19 December 2018</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| SW79-427501-236264629   | 387m    | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 20/12/2018               | Completed Defects | 19/12/2018      | A77 N/B C/WAY 50M S OF STRANRAER N G/WAY |
| SW79-427501-236264630   | 408m    | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 20/12/2018               | Completed Defects | 19/12/2018      | A77 N/B C/WAY 30M S OF STRANRAER N G/WAY |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 24 December 2018</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 31 December 2018</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 07 January 2019</b>   |         |       |             |                       |                 |                          |                   |                 |  |
| SW79-427983-236270767   | 2,612m  | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 08/01/2019               | Completed Defects | 07/01/2019      | A751 N/B C/WAY @ A77 JCT                 |
| SW79-427983-236270766   | 2,612m  | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 08/01/2019               | Completed Defects | 07/01/2019      | A751 N/B C/WAY @ A77 JCT                 |
| SW79-427983-236270768   | 2,612m  | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 08/01/2019               | Completed Defects | 07/01/2019      | A751 N/B C/WAY @ A77 JCT                 |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 09 January 2019</b>   |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 16 January 2019</b>   |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |  |

| Defect Reference   | Start m | End m | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                     |
|--|---------|-------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|--|
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 23 January 2019</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 30 January 2019</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 06 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 13 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 20 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 27 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 06 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| SW79-440813-236342249  | 2,609m  | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 07/03/2019               | Completed Defects | 06/03/2019      | A751 N/B C/WAY @ A77 JCT                 |
| SW79-440813-236342250  | 2,619m  | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 07/03/2019               | Completed Defects | 06/03/2019      | A751 N/B C/WAY @ A77 JCT                 |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 13 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| SW79-446498-236345176  | 412m    | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 14/03/2019               | Completed Defects | 13/03/2019      | A77 N/B C/WAY @ STRANRAER N G/WAY        |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 20 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 27 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>11610/05 : A751 DUMFRIES JUNCTION TO JUNCTION BEOCH</b>                           |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 03 January 2018</b>     |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 10 January 2018</b>     |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 17 January 2018</b>     |         |       |             |                       |                 |                          |                   |                 |  |
| SW81-317651-235519579  | 697m    | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 14/02/2018               | Completed Defects | 03/02/2018      | A77 N/B C/WAY 1KM NORTH OF A751 JCT      |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 24 January 2018</b>     |         |       |             |                       |                 |                          |                   |                 |  |
| SW81-317782-235528545  | 754m    | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 21/02/2018               | Completed Defects | 03/02/2018      | A77 S/B C/WAY 600M NORTH OF A751 JCT     |
| SW81-317782-235528544  | 462m    | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 21/02/2018               | Completed Defects | 03/02/2018      | A77 N/B C/WAY 400M NORTH OF THE A751 JCT |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 31 January 2018</b>     |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 07 February 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 14 February 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| SW81-319705-235542980  | 103m    | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 15/02/2018               | Completed Defects | 14/02/2018      | A77 N/B C/WAY AT A751 JCT                |
| SW81-319705-235542981  | 103m    | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 15/02/2018               | Completed Defects | 14/02/2018      | A77 S/B C/WAY @ A751 JCT                 |
| SW81-319705-235542977  | 103m    | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 15/02/2018               | Completed Defects | 14/02/2018      | A77 S/B C/WAY @ A751 JCT                 |
| SW81-319705-235542984  | 107m    | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 15/02/2018               | Completed Defects | 14/02/2018      | A77 S/B C/WAY @ A751 JCT                 |
| SW81-319705-235542974  | 105m    | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 15/02/2018               | Completed Defects | 14/02/2018      | A77 S/B C/WAY @ A751 JCT                 |
| SW81-319705-235542976  | 102m    | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 15/02/2018               | Completed Defects | 14/02/2018      | A77 S/B C/WAY @ A751 JCT                 |

| Defect Reference  | Start m | End m  | Item Type   | Item Detail             | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description        |
|---|---------|--------|-------------|-------------------------|-----------------|--------------------------|-----------------------|-----------------|-----------------------------|
| SW81-319705-235542978   | 106m    | 0m     | CARRIAGEWAY | Pothole (POTH)          | CAT 1           | 15/02/2018               | Completed Defects     | 14/02/2018      | A77 S/B C/WAY @ A751 JCT    |
| SW81-319705-235542983   | 107m    | 0m     | CARRIAGEWAY | Pothole (POTH)          | CAT 1           | 15/02/2018               | Completed Defects     | 14/02/2018      | A77 S/B C/WAY @ A751 JCT    |
| SW81-319705-235542985   | 102m    | 0m     | CARRIAGEWAY | Pothole (POTH)          | CAT 1           | 15/02/2018               | Completed Defects     | 14/02/2018      | A77 S/B C/WAY @ A751 JCT    |
| SW81-319705-235542979   | 103m    | 0m     | CARRIAGEWAY | Pothole (POTH)          | CAT 1           | 15/02/2018               | Completed Defects     | 14/02/2018      | A77 S/B C/WAY @ A751 JCT    |
| SW81-319705-235542982   | 106m    | 0m     | CARRIAGEWAY | Pothole (POTH)          | CAT 1           | 15/02/2018               | Completed Defects     | 14/02/2018      | A77 S/B C/WAY @ A751 JCT    |
| SW81-319705-235542975   | 104m    | 0m     | CARRIAGEWAY | Pothole (POTH)          | CAT 1           | 15/02/2018               | Completed Defects     | 14/02/2018      | A77 S/B C/WAY @ A751 JCT    |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 21 February 2018</b> |         |        |             |                         |                 |                          |                       |                 |                             |
| No defects recorded   |         |        |             |                         |                 |                          |                       |                 |                             |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 28 February 2018</b> |         |        |             |                         |                 |                          |                       |                 |                             |
| No defects recorded   |         |        |             |                         |                 |                          |                       |                 |                             |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 07 March 2018</b>    |         |        |             |                         |                 |                          |                       |                 |                             |
| No defects recorded   |         |        |             |                         |                 |                          |                       |                 |                             |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 14 March 2018</b>    |         |        |             |                         |                 |                          |                       |                 |                             |
| No defects recorded   |         |        |             |                         |                 |                          |                       |                 |                             |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 21 March 2018</b>    |         |        |             |                         |                 |                          |                       |                 |                             |
| No defects recorded   |         |        |             |                         |                 |                          |                       |                 |                             |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 28 March 2018</b>    |         |        |             |                         |                 |                          |                       |                 |                             |
| No defects recorded   |         |        |             |                         |                 |                          |                       |                 |                             |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 04 April 2018</b>    |         |        |             |                         |                 |                          |                       |                 |                             |
| No defects recorded   |         |        |             |                         |                 |                          |                       |                 |                             |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 11 April 2018</b>    |         |        |             |                         |                 |                          |                       |                 |                             |
| No defects recorded   |         |        |             |                         |                 |                          |                       |                 |                             |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 18 April 2018</b>    |         |        |             |                         |                 |                          |                       |                 |                             |
| SW81-338586-235658112   | 986m    | 0m     | CARRIAGEWAY | Pothole VIAFIX (POTV)   | CAT 1           | 19/04/2018               | Completed Defects     | 18/04/2018      | A77 S/B CWY 100M S OF BEOCH |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 25 April 2018</b>    |         |        |             |                         |                 |                          |                       |                 |                             |
| No defects recorded   |         |        |             |                         |                 |                          |                       |                 |                             |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 02 May 2018</b>   |         |        |             |                         |                 |                          |                       |                 |                             |
| No defects recorded   |         |        |             |                         |                 |                          |                       |                 |                             |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 09 May 2018</b>   |         |        |             |                         |                 |                          |                       |                 |                             |
| No defects recorded   |         |        |             |                         |                 |                          |                       |                 |                             |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 16 May 2018</b>   |         |        |             |                         |                 |                          |                       |                 |                             |
| SW81-349340-235789869   | 1,664m  | 0m     | CARRIAGEWAY | Pothole VIAFIX (POTV)   | CAT 1           | 17/05/2018               | Completed Defects     | 16/05/2018      | A77 N/B C/WAY @ BEOCH JCT   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 23 May 2018</b>   |         |        |             |                         |                 |                          |                       |                 |                             |
| SW81-352553-235789881   | 41m     | 0m     | CARRIAGEWAY | Pothole VIAFIX (POTV)   | CAT 1           | 24/05/2018               | Completed Defects     | 23/05/2018      | A77 N/B C/WAY @ A751 JCT    |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 30 May 2018</b>   |         |        |             |                         |                 |                          |                       |                 |                             |
| No defects recorded   |         |        |             |                         |                 |                          |                       |                 |                             |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 06 June 2018</b>  |         |        |             |                         |                 |                          |                       |                 |                             |
| No defects recorded   |         |        |             |                         |                 |                          |                       |                 |                             |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 13 June 2018</b>  |         |        |             |                         |                 |                          |                       |                 |                             |
| No defects recorded   |         |        |             |                         |                 |                          |                       |                 |                             |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 20 June 2018</b>  |         |        |             |                         |                 |                          |                       |                 |                             |
| No defects recorded   |         |        |             |                         |                 |                          |                       |                 |                             |
| <b>Detailed Inspection TEMPLATE of A77 Dfs Detail on 27 June 2018</b>             |         |        |             |                         |                 |                          |                       |                 |                             |
| SW86-357233-2   | 1,670m  | 1,680m | WOODLAND    | Invasive species (INVS) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                             |
| SW86-357233-3   | 1,674m  | 1,664m | WOODLAND    | Invasive species (INVS) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                             |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 27 June 2018</b>  |         |        |             |                         |                 |                          |                       |                 |                             |
| No defects recorded   |         |        |             |                         |                 |                          |                       |                 |                             |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|--|---------|--------|-------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 04 July 2018</b>   |         |        |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 11 July 2018</b>   |         |        |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 18 July 2018</b>   |         |        |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 25 July 2018</b>   |         |        |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 01 August 2018</b> |         |        |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 08 August 2018</b> |         |        |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 15 August 2018</b> |         |        |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 22 August 2018</b> |         |        |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 29 August 2018</b> |         |        |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |                      |
| <b>Detailed Inspection TEMPLATE of A77 Dfs Detail on 16 July 2018</b>              |         |        |             |                                      |                 |                          |                       |                 |                      |
| SW79-332073-46   | 708m    | 755m   | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW79-332073-48   | 824m    | 884m   | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW79-332073-62   | 1,483m  | 1,553m | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW79-332073-64   | 1,671m  | 1,681m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW79-332073-50   | 970m    | 992m   | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW79-332073-52   | 1,060m  | 1,076m | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW79-332073-59   | 1,305m  | 1,351m | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW79-332073-60   | 1,379m  | 1,410m | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW79-332073-38   | 255m    | 355m   | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW79-332073-39   | 307m    | 315m   | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW79-332073-57   | 1,253m  | 1,273m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW79-332073-56   | 1,184m  | 1,121m | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW79-332073-35   | 49m     | 109m   | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW79-332073-42   | 471m    | 0m     | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW79-332073-53   | 1,084m  | 1,107m | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |

| Defect Reference  | Start m | End m  | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description             |
|---|---------|--------|-------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|----------------------------------|
| SW79-332073-47  | 790m    | 850m   | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                  |
| SW79-332073-49  | 895m    | 927m   | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                  |
| SW79-332073-63  | 1,493m  | 1,525m | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                  |
| SW79-332073-34  | 49m     | 109m   | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                  |
| SW79-332073-36  | 129m    | 203m   | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                  |
| SW79-332073-43  | 553m    | 615m   | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                  |
| SW79-332073-45  | 708m    | 808m   | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                  |
| SW79-332073-37  | 203m    | 263m   | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                  |
| SW79-332073-40  | 420m    | 442m   | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                  |
| SW79-332073-41  | 443m    | 503m   | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                  |
| SW79-332073-54  | 1,144m  | 1,166m | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                  |
| SW79-332073-55  | 1,184m  | 1,214m | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                  |
| SW79-332073-44  | 570m    | 595m   | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                  |
| SW79-332073-51  | 1,031m  | 1,049m | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                  |
| SW79-332073-58  | 1,292m  | 1,332m | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                  |
| SW79-332073-61  | 1,381m  | 1,430m | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 05 September 2018</b> |         |        |             |                                      |                 |                          |                       |                 |                                  |
| SW79-403475-235960873   | 886m    | 0m     | CARRIAGEWAY | Pothole (POTH)                       | CAT 1           | 06/09/2018               | Completed Defects     | 05/09/2018      | A77 S/B C/WAY 800M N OF A751 JCT |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 12 September 2018</b> |         |        |             |                                      |                 |                          |                       |                 |                                  |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |                                  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 19 September 2018</b> |         |        |             |                                      |                 |                          |                       |                 |                                  |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |                                  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 26 September 2018</b> |         |        |             |                                      |                 |                          |                       |                 |                                  |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |                                  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 03 October 2018</b>   |         |        |             |                                      |                 |                          |                       |                 |                                  |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |                                  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 10 October 2018</b>   |         |        |             |                                      |                 |                          |                       |                 |                                  |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |                                  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 17 October 2018</b>   |         |        |             |                                      |                 |                          |                       |                 |                                  |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |                                  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 24 October 2018</b>   |         |        |             |                                      |                 |                          |                       |                 |                                  |

| Defect Reference   | Start m | End m | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status               | Completion Date | Location Description                    |
|--|---------|-------|-------------|-----------------------|-----------------|--------------------------|------------------------------|-----------------|---|
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 31 October 2018</b>  |         |       |             |                       |                 |                          |                              |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 07 November 2018</b> |         |       |             |                       |                 |                          |                              |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 14 November 2018</b> |         |       |             |                       |                 |                          |                              |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 21 November 2018</b> |         |       |             |                       |                 |                          |                              |                 |   |
| SW79-426749-236224110  | 717m    | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 22/11/2018               | Completed Defects            | 21/11/2018      | A77 S/B C/WAY 500M N OF A751 JCT        |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 28 November 2018</b> |         |       |             |                       |                 |                          |                              |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 05 December 2018</b> |         |       |             |                       |                 |                          |                              |                 |   |
| SW79-427168-236234666  | 98m     | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 06/12/2018               | Completed Defects            | 05/12/2018      | A77 N/B C/WAY 30M N OF A751 JCT         |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 12 December 2018</b> |         |       |             |                       |                 |                          |                              |                 |   |
| SW79-427346-236234663  | 1,669m  | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 13/12/2018               | Completed Defects            | 12/12/2018      | A77 N/B C/WAY @ BEOCH FARM JCT.         |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 19 December 2018</b> |         |       |             |                       |                 |                          |                              |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 24 December 2018</b> |         |       |             |                       |                 |                          |                              |                 |   |
| SW79-427603-236264628  | 757m    | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 25/12/2018               | Completed Defects            | 24/12/2018      | A77 S/B C/WAY 700M N OF A751 JCT        |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 31 December 2018</b> |         |       |             |                       |                 |                          |                              |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 07 January 2019</b>  |         |       |             |                       |                 |                          |                              |                 |   |
| SW79-427983-236270765  | 1m      | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 08/01/2019               | Completed Defects            | 07/01/2019      | A751 N/B C/WAY @ A77 JCT                |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 09 January 2019</b>  |         |       |             |                       |                 |                          |                              |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 16 January 2019</b>  |         |       |             |                       |                 |                          |                              |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 23 January 2019</b>  |         |       |             |                       |                 |                          |                              |                 |   |
| SW79-428335-236284146  | 715m    | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 24/01/2019               | Completed Defects            | 23/01/2019      | A77 S/B C/WAY 500M N OF A751 JCT        |
| SW79-428335-236284147  | 717m    | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 24/01/2019               | Completed Defects            | 23/01/2019      | A77 S/B C/WAY 500M N OF A751 JCT        |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 30 January 2019</b>  |         |       |             |                       |                 |                          |                              |                 |   |
| SW79-428609-236284147  | 766m    | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 31/01/2019               | Completed Defects            | 30/01/2019      | A77 S/B C/WAY 300M S OF DALMINNOCH FARM |
| SW79-428609-236284148  | 744m    | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 31/01/2019               | Completed Defects            | 30/01/2019      | A77 S/B C/WAY 300M S OF DALMINNOCH FARM |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 06 February 2019</b> |         |       |             |                       |                 |                          |                              |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 13 February 2019</b> |         |       |             |                       |                 |                          |                              |                 |   |
| SW79-429966-236310248  | 766m    | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 14/02/2019               | Awaiting CCMS Permanent Date | 13/02/2019      | A77 S/B C/WAY 500M N OF A751 JCT        |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 20 February 2019</b> |         |       |             |                       |                 |                          |                              |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 27 February 2019</b> |         |       |             |                       |                 |                          |                              |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 06 March 2019</b>    |         |       |             |                       |                 |                          |                              |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 13 March 2019</b>    |         |       |             |                       |                 |                          |                              |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 20 March 2019</b>    |         |       |             |                       |                 |                          |                              |                 |   |
| SW79-452164-236467198  | 720m    | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 21/03/2019               | Completed Defects            | 20/03/2019      | A77 S/B C/WAY 700M N OF A751 JCT        |

| Defect Reference  | Start m | End m  | Item Type     | Item Detail             | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description              |
|---|---------|--------|---------------|-------------------------|-----------------|--------------------------|-----------------------|-----------------|-----------------------------------|
| SW79-452164-236467199   | 715m    | 0m     | CARRIAGEWAY   | Pothole VIAFIX (POTV)   | CAT 1           | 21/03/2019               | Completed Defects     | 20/03/2019      | A77 S/B C/WAY 700M N OF A751 JCT  |
| SW79-452164-236467196   | 1,670m  | 0m     | CARRIAGEWAY   | Pothole VIAFIX (POTV)   | CAT 1           | 21/03/2019               | Completed Defects     | 20/03/2019      | A77 N/B C/WAY @ BEOCH FARM        |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 27 March 2019</b> |         |        |               |                         |                 |                          |                       |                 |                                   |
| No defects recorded   |         |        |               |                         |                 |                          |                       |                 |                                   |
| <b>11610/18 : JUNCTION BEOCH TO DRUMMUCKLOCH FARM</b>                             |         |        |               |                         |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 03 January 2018</b>  |         |        |               |                         |                 |                          |                       |                 |                                   |
| No defects recorded   |         |        |               |                         |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 10 January 2018</b>  |         |        |               |                         |                 |                          |                       |                 |                                   |
| No defects recorded   |         |        |               |                         |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 17 January 2018</b>  |         |        |               |                         |                 |                          |                       |                 |                                   |
| No defects recorded   |         |        |               |                         |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 24 January 2018</b>  |         |        |               |                         |                 |                          |                       |                 |                                   |
| No defects recorded   |         |        |               |                         |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 31 January 2018</b>  |         |        |               |                         |                 |                          |                       |                 |                                   |
| No defects recorded   |         |        |               |                         |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 07 February 2018</b> |         |        |               |                         |                 |                          |                       |                 |                                   |
| No defects recorded   |         |        |               |                         |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 14 February 2018</b> |         |        |               |                         |                 |                          |                       |                 |                                   |
| No defects recorded   |         |        |               |                         |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 21 February 2018</b> |         |        |               |                         |                 |                          |                       |                 |                                   |
| No defects recorded   |         |        |               |                         |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 28 February 2018</b> |         |        |               |                         |                 |                          |                       |                 |                                   |
| No defects recorded   |         |        |               |                         |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 07 March 2018</b>    |         |        |               |                         |                 |                          |                       |                 |                                   |
| No defects recorded   |         |        |               |                         |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 14 March 2018</b>    |         |        |               |                         |                 |                          |                       |                 |                                   |
| No defects recorded   |         |        |               |                         |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 21 March 2018</b>    |         |        |               |                         |                 |                          |                       |                 |                                   |
| SW81-329803-235583957   | 86m     | 0m     | TRAFFIC_SIGNS | Accident damage (ACCD)  | CAT 1           | 18/04/2018               | Completed Defects     | 23/03/2018      | A77 S/B VERGE 100M SOUTH OF BEOCH |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 28 March 2018</b>    |         |        |               |                         |                 |                          |                       |                 |                                   |
| No defects recorded   |         |        |               |                         |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 04 April 2018</b>    |         |        |               |                         |                 |                          |                       |                 |                                   |
| No defects recorded   |         |        |               |                         |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 11 April 2018</b>    |         |        |               |                         |                 |                          |                       |                 |                                   |
| No defects recorded   |         |        |               |                         |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 18 April 2018</b>    |         |        |               |                         |                 |                          |                       |                 |                                   |
| No defects recorded   |         |        |               |                         |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 25 April 2018</b>    |         |        |               |                         |                 |                          |                       |                 |                                   |
| No defects recorded   |         |        |               |                         |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 02 May 2018</b>   |         |        |               |                         |                 |                          |                       |                 |                                   |
| No defects recorded   |         |        |               |                         |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 09 May 2018</b>   |         |        |               |                         |                 |                          |                       |                 |                                   |
| No defects recorded   |         |        |               |                         |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 16 May 2018</b>   |         |        |               |                         |                 |                          |                       |                 |                                   |
| No defects recorded   |         |        |               |                         |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 23 May 2018</b>   |         |        |               |                         |                 |                          |                       |                 |                                   |
| No defects recorded   |         |        |               |                         |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 30 May 2018</b>   |         |        |               |                         |                 |                          |                       |                 |                                   |
| No defects recorded   |         |        |               |                         |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 06 June 2018</b>  |         |        |               |                         |                 |                          |                       |                 |                                   |
| No defects recorded   |         |        |               |                         |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 13 June 2018</b>  |         |        |               |                         |                 |                          |                       |                 |                                   |
| No defects recorded   |         |        |               |                         |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 20 June 2018</b>  |         |        |               |                         |                 |                          |                       |                 |                                   |
| No defects recorded   |         |        |               |                         |                 |                          |                       |                 |                                   |
| <b>Detailed Inspection TEMPLATE of A77 Dfs Detail on 27 June 2018</b>             |         |        |               |                         |                 |                          |                       |                 |                                   |
| SW86-357233-5   | 1,151m  | 1,131m | WOODLAND      | Invasive species (INVS) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                   |

| Defect Reference  | Start m | End m | Item Type | Item Detail             | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|---|---------|-------|-----------|-------------------------|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW86-357233-4   | 409m    | 359m  | WOODLAND  | Invasive species (INVS) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 27 June 2018</b>      |         |       |           |                         |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 04 July 2018</b>      |         |       |           |                         |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 11 July 2018</b>      |         |       |           |                         |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 18 July 2018</b>      |         |       |           |                         |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 25 July 2018</b>      |         |       |           |                         |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 01 August 2018</b>    |         |       |           |                         |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 08 August 2018</b>    |         |       |           |                         |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 15 August 2018</b>    |         |       |           |                         |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 22 August 2018</b>    |         |       |           |                         |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 29 August 2018</b>    |         |       |           |                         |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <b>Detailed Inspection TEMPLATE of A77 Dfs Detail on 16 July 2018</b>                 |         |       |           |                         |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 05 September 2018</b> |         |       |           |                         |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 12 September 2018</b> |         |       |           |                         |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 19 September 2018</b> |         |       |           |                         |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 26 September 2018</b> |         |       |           |                         |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 03 October 2018</b>   |         |       |           |                         |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 10 October 2018</b>   |         |       |           |                         |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 17 October 2018</b>   |         |       |           |                         |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 24 October 2018</b>   |         |       |           |                         |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 31 October 2018</b>   |         |       |           |                         |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 07 November 2018</b>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 14 November 2018</b>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 21 November 2018</b>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 28 November 2018</b>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 05 December 2018</b>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 12 December 2018</b>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 19 December 2018</b>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 24 December 2018</b>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 31 December 2018</b>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 07 January 2019</b>   |         |       |           |                         |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 09 January 2019</b>   |         |       |           |                         |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |           |                         |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 16 January 2019</b>   |         |       |           |                         |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |           |                         |                 |                          |                       |                 |                      |



| Defect Reference   | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|--|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 23 January 2019</b>  |         |       |           |             |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 30 January 2019</b>  |         |       |           |             |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 06 February 2019</b> |         |       |           |             |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 13 February 2019</b> |         |       |           |             |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 20 February 2019</b> |         |       |           |             |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 27 February 2019</b> |         |       |           |             |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 06 March 2019</b>    |         |       |           |             |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 13 March 2019</b>    |         |       |           |             |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 20 March 2019</b>    |         |       |           |             |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 27 March 2019</b>    |         |       |           |             |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |             |                 |                          |                |                 |                      |

#### 11610/36 : DRUMMUCKLOCH FARM TO DERESTRICTION SIGN CAIRNRYAN

|   |        |    |             |                 |       |            |                   |            |  |
|---|--------|----|-------------|-----------------|-------|------------|-------------------|------------|--|
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 03 January 2018</b>  |        |    |             |                 |       |            |                   |            |  |
| No defects recorded   |        |    |             |                 |       |            |                   |            |  |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 10 January 2018</b>  |        |    |             |                 |       |            |                   |            |  |
| SW81-317457-235518239   | 722m   | 0m | CARRIAGEWAY | Pothole (POTH)  | CAT 1 | 07/02/2018 | Completed Defects | 10/01/2018 | A77 S/B C/WAY 50M NORTH OF S G/WAY       |
| SW81-317457-235518246   | 610m   | 0m | CARRIAGEWAY | Pothole (POTH)  | CAT 1 | 07/02/2018 | Completed Defects | 05/02/2018 | A77 S/B C/WAY 50M S OF CAIRNRYAN S G/WAY |
| SW81-317457-235518240   | 740m   | 0m | CARRIAGEWAY | Pothole (POTH)  | CAT 1 | 07/02/2018 | Completed Defects | 10/01/2018 | A77 S/B C/WAY 50M N OF S G/WAY           |
| SW81-317457-235518245   | 612m   | 0m | CARRIAGEWAY | Pothole (POTH)  | CAT 1 | 07/02/2018 | Completed Defects | 05/02/2018 | A77 S/B C/WAY 50M S OF CAIRNRYAN S G/WAY |
| SW81-317457-235518247   | 610m   | 0m | CARRIAGEWAY | Pothole (POTH)  | CAT 1 | 07/02/2018 | Completed Defects | 05/02/2018 | A77 S/B C/WAY 50M S OF CAIRNRYAN S G/WAY |
| SW81-317457-235518249   | 362m   | 0m | CARRIAGEWAY | Pothole (POTH)  | CAT 1 | 07/02/2018 | Completed Defects | 05/02/2018 | A77 S/B C/WAY @ ROSEBANK COTTAGE         |
| SW81-317457-235518241   | 723m   | 0m | CARRIAGEWAY | Pothole (POTH)  | CAT 1 | 07/02/2018 | Completed Defects | 10/01/2018 | A77 N/B C/WAY 50M N OF S G/WAY           |
| SW81-317457-235518248   | 514m   | 0m | CARRIAGEWAY | Pothole (POTH)  | CAT 1 | 07/02/2018 | Completed Defects | 05/02/2018 | A77 S/B C/WAY 200M S OF CAIRNRYAN        |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 17 January 2018</b>  |        |    |             |                 |       |            |                   |            |  |
| SW81-317651-235519585   | 2,376m | 0m | CARRIAGEWAY | Pothole (POTH)  | CAT 1 | 14/02/2018 | Completed Defects | 05/02/2018 | A77 S/B C/WAY 500M SOUTH OF BARRS YARD   |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 24 January 2018</b>  |        |    |             |                 |       |            |                   |            |  |
| No defects recorded   |        |    |             |                 |       |            |                   |            |  |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 31 January 2018</b>  |        |    |             |                 |       |            |                   |            |  |
| No defects recorded   |        |    |             |                 |       |            |                   |            |  |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 07 February 2018</b> |        |    |             |                 |       |            |                   |            |  |
| No defects recorded   |        |    |             |                 |       |            |                   |            |  |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 14 February 2018</b> |        |    |             |                 |       |            |                   |            |  |
| SW81-319705-235542971   | 844m   | 0m | CARRIAGEWAY | Flooding (FLOD) | CAT 1 | 14/03/2018 | Completed Defects | 16/02/2018 | A77 S/B C/WAY 300M N OF S G/WAY          |
| SW81-319705-235542973   | 388m   | 0m | CARRIAGEWAY | Pothole (POTH)  | CAT 1 | 15/02/2018 | Completed Defects | 14/02/2018 | A77 S/B C/WAY AT ROSEBANK COTTAGE        |

| Defect Reference  | Start m | End m | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                                       |
|---|---------|-------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|--|
| SW81-319705-235542972   | 665m    | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 14/03/2018               | Completed Defects | 14/02/2018      | A77 N/B C/WAY CAIRNRYAN S G/WAY                            |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 21 February 2018</b> |         |       |             |                       |                 |                          |                   |                 |  |
| SW81-321674-235545625   | 473m    | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 22/02/2018               | Completed Defects | 21/02/2018      | A77 CAIRNRYAN  |
| SW81-321674-235545626   | 322m    | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 22/02/2018               | Completed Defects | 21/02/2018      | A77 CAIRNRYAN  |
| SW81-321674-235545624   | 475m    | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 22/02/2018               | Completed Defects | 21/02/2018      | A77 CAIRNRYAN  |
| SW81-321674-235545623   | 506m    | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 22/02/2018               | Completed Defects | 21/02/2018      | A77 CAIRNRYAN  |
| SW81-321674-235545627   | 322m    | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 22/02/2018               | Completed Defects | 21/02/2018      | A77 CAIRNRYAN  |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 28 February 2018</b> |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 07 March 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| SW81-325796-235550016   | 236m    | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 08/03/2018               | Completed Defects | 07/03/2018      | A77 CAIRNRYAN  |
| SW81-325796-235550015   | 248m    | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 08/03/2018               | Completed Defects | 07/03/2018      | A77 CAIRNRYAN  |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 14 March 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| SW81-327800-235583899   | 629m    | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 15/03/2018               | Completed Defects | 14/03/2018      | A77 CAIRNRYAN  |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 21 March 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| SW81-329803-235583956   | 2,278m  | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 22/03/2018               | Completed Defects | 21/03/2018      | A77 CAIRNRYAN  |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 28 March 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| SW81-331777-235608157   | 361m    | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 29/03/2018               | Completed Defects | 28/03/2018      | A77 ROSEBANK COTTAGE                                       |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 04 April 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| SW81-334517-235618360   | 320m    | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 05/04/2018               | Completed Defects | 04/04/2018      | A77 S/B C/WAY @ ROSEBANK COTTAGE                           |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 11 April 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 18 April 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 25 April 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 02 May 2018</b>   |         |       |             |                       |                 |                          |                   |                 |  |
| SW81-343546-235661443   | 715m    | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 03/05/2018               | Completed Defects | 02/05/2018      | A77 N/B C/WAY @ CAIRNRYAN S G/WAY                          |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 09 May 2018</b>   |         |       |             |                       |                 |                          |                   |                 |  |
| SW81-346484-235706618   | 360m    | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 10/05/2018               | Completed Defects | 09/05/2018      | A77 S/B C/WAY @ ROSEBANK COTTAGE                           |
| SW81-346484-235706619   | 317m    | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 10/05/2018               | Completed Defects | 09/05/2018      | A77 S/B C/WAY AT ROSEBANK COTTAGE                          |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 16 May 2018</b>   |         |       |             |                       |                 |                          |                   |                 |  |
| SW81-349340-235789870   | 2,607m  | 0m    | GULLY       | Blockage (BLOK)       | CAT 1           | 13/06/2018               | Completed Defects | 16/05/2018      | A77 N/B C/WAY OPPOSITE TRAFFIC ISLAND 100M S OF BARRS YARD |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 23 May 2018</b>   |         |       |             |                       |                 |                          |                   |                 |  |

| Defect Reference   | Start m | End m  | Item Type     | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description   |
|--|---------|--------|---------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|--|
| SW81-352553-235789884  | 1,385m  | 0m     | TRAFFIC_SIGNS | Damaged (DAMG)                       | CAT 1           | 20/06/2018               | Completed Defects     | 17/07/2018      | A77 CENTER ISLAND OPPOSITE P&O FERRY TERMINAL @ CAIRNRYAN VILLAGE HALL |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 30 May 2018</b>    |         |        |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 06 June 2018</b>   |         |        |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 13 June 2018</b>   |         |        |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 20 June 2018</b>   |         |        |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Detailed Inspection TEMPLATE of A77 Dfs Detail on 27 June 2018</b>              |         |        |               |                                      |                 |                          |                       |                 |  |
| SW86-357233-1  | 949m    | 929m   | WOODLAND      | Invasive species (INVS)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 27 June 2018</b>   |         |        |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 04 July 2018</b>   |         |        |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 11 July 2018</b>   |         |        |               |                                      |                 |                          |                       |                 |  |
| SW81-376906-235909971  | 1,234m  | 0m     | GULLY         | Rocking under load (IRLD)            | CAT 1           | 08/08/2018               | Completed Defects     | 03/09/2018      | A77 S/B C/WAY 50M NORTH OF P & O FERRY TERMINAL CAIRNRYAN              |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 18 July 2018</b>   |         |        |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 25 July 2018</b>   |         |        |               |                                      |                 |                          |                       |                 |  |
| SW81-383408-235920998  | 669m    | 0m     | CARRIAGEWAY   | Pothole VIAFIX (POTV)                | CAT 1           | 26/07/2018               | Completed Defects     | 25/07/2018      | A77 S/B C/WAY @ CAIRNRYAN S G/WAY                                      |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 01 August 2018</b> |         |        |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 08 August 2018</b> |         |        |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 15 August 2018</b> |         |        |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 22 August 2018</b> |         |        |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 29 August 2018</b> |         |        |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Detailed Inspection TEMPLATE of A77 Dfs Detail on 16 July 2018</b>              |         |        |               |                                      |                 |                          |                       |                 |  |
| SW79-332073-71   | 552m    | 580m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW79-332073-65   | 98m     | 120m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW79-332073-67   | 153m    | 180m   | CARRIAGEWAY   | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW79-332073-82   | 2,308m  | 2,298m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW79-332073-81   | 2,375m  | 2,360m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW79-332073-69   | 279m    | 290m   | CARRIAGEWAY   | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW79-332073-70   | 361m    | 376m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW79-332073-66   | 134m    | 142m   | CARRIAGEWAY   | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |

| Defect Reference  | Start m | End m  | Item Type     | Item Detail                                | Defect Category | Required Completion Date | Current Status               | Completion Date | Location Description  |
|---|---------|--------|---------------|--|-----------------|--------------------------|------------------------------|-----------------|---|
| SW79-332073-83  | 2,283m  | 2,270m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action        | 01/01/9999      |   |
| SW79-332073-72  | 722m    | 735m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action        | 01/01/9999      |   |
| SW79-332073-68  | 213m    | 240m   | CARRIAGEWAY   | Localised cracking (LOCK)                  | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action        | 01/01/9999      |   |
| SW79-332073-84  | 1,027m  | 0m     | TRAFFIC_SIGNS | Physical condition of post (COPT)          | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action        | 01/01/9999      |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 05 September 2018</b> |         |        |               |  |                 |                          |                              |                 |   |
| No defects recorded   |         |        |               |  |                 |                          |                              |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 12 September 2018</b> |         |        |               |  |                 |                          |                              |                 |   |
| No defects recorded   |         |        |               |  |                 |                          |                              |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 19 September 2018</b> |         |        |               |  |                 |                          |                              |                 |   |
| No defects recorded   |         |        |               |  |                 |                          |                              |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 26 September 2018</b> |         |        |               |  |                 |                          |                              |                 |   |
| No defects recorded   |         |        |               |  |                 |                          |                              |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 03 October 2018</b>   |         |        |               |  |                 |                          |                              |                 |   |
| SW79-416503-236101717   | 2,364m  | 0m     | CARRIAGEWAY   | Pothole VIAFIX (POTV)                      | CAT 1           | 04/10/2018               | Completed Defects            | 03/10/2018      | A77 S/B C/WAY 250M S OF BARRS YARD                                |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 10 October 2018</b>   |         |        |               |  |                 |                          |                              |                 |   |
| No defects recorded   |         |        |               |  |                 |                          |                              |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 17 October 2018</b>   |         |        |               |  |                 |                          |                              |                 |   |
| SW79-422974-236143075   | 2,412m  | 0m     | MANHOLE       | Cracked or broken (IBCK)                   | 3RD PTY         | 14/11/2018               | Awaiting CCMS Temp Date      | 01/01/9999      | A77 S/B FOOTPATH OUTSIDE VIRGINA COTTAGE 200M SOUTH OF BARRS YARD |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 24 October 2018</b>   |         |        |               |  |                 |                          |                              |                 |   |
| No defects recorded   |         |        |               |  |                 |                          |                              |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 31 October 2018</b>   |         |        |               |  |                 |                          |                              |                 |   |
| No defects recorded   |         |        |               |  |                 |                          |                              |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 07 November 2018</b>  |         |        |               |  |                 |                          |                              |                 |   |
| No defects recorded   |         |        |               |  |                 |                          |                              |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 14 November 2018</b>  |         |        |               |  |                 |                          |                              |                 |   |
| No defects recorded   |         |        |               |  |                 |                          |                              |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 21 November 2018</b>  |         |        |               |  |                 |                          |                              |                 |   |
| No defects recorded   |         |        |               |  |                 |                          |                              |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 28 November 2018</b>  |         |        |               |  |                 |                          |                              |                 |   |
| No defects recorded   |         |        |               |  |                 |                          |                              |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 05 December 2018</b>  |         |        |               |  |                 |                          |                              |                 |   |
| SW79-427168-236234668   | 349m    | 0m     | CARRIAGEWAY   | Pothole VIAFIX (POTV)                      | CAT 1           | 06/12/2018               | Completed Defects            | 05/12/2018      | A77 S/B C/WAY 300M S OF CAIRNRYAN S G/WAY                         |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 12 December 2018</b>  |         |        |               |  |                 |                          |                              |                 |   |
| SW79-427346-236234662   | 365m    | 0m     | CARRIAGEWAY   | Pothole VIAFIX (POTV)                      | CAT 1           | 13/12/2018               | Completed Defects            | 12/12/2018      | A77 S/B C/WAY 300M S OF CAIRNRYAN S G/WAY                         |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 19 December 2018</b>  |         |        |               |  |                 |                          |                              |                 |   |
| SW79-427501-236264632   | 1,131m  | 0m     | CARRIAGEWAY   | Patch - loss of material (fretting) (PLMT) | 3RD PTY         | 16/01/2019               | Awaiting CCMS Permanent Date | 01/01/9999      | A77 S/B C/WAY @ HOMESTEAD B&B CAIRNRYAN                           |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 24 December 2018</b>  |         |        |               |  |                 |                          |                              |                 |   |
| No defects recorded   |         |        |               |  |                 |                          |                              |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 31 December 2018</b>  |         |        |               |  |                 |                          |                              |                 |   |
| No defects recorded   |         |        |               |  |                 |                          |                              |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 07 January 2019</b>   |         |        |               |  |                 |                          |                              |                 |   |
| No defects recorded   |         |        |               |  |                 |                          |                              |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 09 January 2019</b>   |         |        |               |  |                 |                          |                              |                 |   |
| SW79-428019-236271218   | 366m    | 0m     | CARRIAGEWAY   | Pothole (POTH)                             | CAT 1           | 06/02/2019               | Completed Defects            | 25/01/2019      | A77 S/B C/WAY 300M S OF CAIRNRYAN S G/WAY                         |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 16 January 2019</b>   |         |        |               |  |                 |                          |                              |                 |   |
| No defects recorded   |         |        |               |  |                 |                          |                              |                 |   |

| Defect Reference   | Start m | End m | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description               |
|--|---------|-------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|------------------------------------|
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 23 January 2019</b>  |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 30 January 2019</b>  |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 06 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 13 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 20 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 27 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 06 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 13 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 20 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 27 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>11610/66 : DERESTRICTION SIGN CAIRNRYAN TO JCT BONNY BRAES</b>                    |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 03 January 2018</b>     |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 10 January 2018</b>     |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 17 January 2018</b>     |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 24 January 2018</b>     |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 31 January 2018</b>     |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 07 February 2018</b>    |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 14 February 2018</b>    |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 21 February 2018</b>    |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 28 February 2018</b>    |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 07 March 2018</b>       |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 14 March 2018</b>       |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 21 March 2018</b>       |         |       |             |                       |                 |                          |                   |                 |                                    |
| SW81-329803-235583955  | 163m    | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 22/03/2018               | Completed Defects | 21/03/2018      | A77 CAIRNRYAN                      |
| SW81-329803-235583954  | 644m    | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 22/03/2018               | Completed Defects | 21/03/2018      | A77 CAIRNRYAN                      |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 28 March 2018</b>       |         |       |             |                       |                 |                          |                   |                 |                                    |
| SW81-331777-235608156  | 61m     | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 29/03/2018               | Completed Defects | 28/03/2018      | A77 N/B C/WAY BARRS YARD CAIRNRYAN |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 04 April 2018</b>       |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 11 April 2018</b>       |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 18 April 2018</b>       |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 25 April 2018</b>       |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 02 May 2018</b>      |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 09 May 2018</b>      |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |                                    |

| Defect Reference  | Start m | End m | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                    |
|---|---------|-------|-------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 16 May 2018</b>       |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 23 May 2018</b>       |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 30 May 2018</b>       |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 06 June 2018</b>      |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 13 June 2018</b>      |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 20 June 2018</b>      |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Dfs Detail on 27 June 2018</b>                 |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 27 June 2018</b>      |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 04 July 2018</b>      |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 11 July 2018</b>      |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 18 July 2018</b>      |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 25 July 2018</b>      |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 01 August 2018</b>    |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 08 August 2018</b>    |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 15 August 2018</b>    |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Dfs Detail on 16 July 2018</b>                 |         |       |             |                                      |                 |                          |                       |                 |   |
| SW79-332073-76  | 625m    | 617m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW79-332073-73  | 724m    | 700m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW79-332073-80  | 64m     | 84m   | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW79-332073-75  | 663m    | 655m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW79-332073-77  | 591m    | 558m  | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW79-332073-79  | 411m    | 403m  | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW79-332073-78  | 518m    | 508m  | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW79-332073-74  | 696m    | 672m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 22 August 2018</b>    |         |       |             |                                      |                 |                          |                       |                 |   |
| SW79-396805-235960871   | 660m    | 0m    | CARRIAGEWAY | Pothole (POTH)                       | CAT 1           | 23/08/2018               | Completed Defects     | 22/08/2018      | A77 N/B C/WAY 200M S OF CAIRNRYAN R/ABT |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 29 August 2018</b>    |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 05 September 2018</b> |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 12 September 2018</b> |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 19 September 2018</b> |         |       |             |                                      |                 |                          |                       |                 |   |

| Defect Reference   | Start m | End m | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description  |
|--|---------|-------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|---|
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 26 September 2018</b>                        |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 03 October 2018</b>                          |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 10 October 2018</b>                          |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 17 October 2018</b>                          |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 24 October 2018</b>                          |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 31 October 2018</b>                          |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 07 November 2018</b>                         |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 14 November 2018</b>                         |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 21 November 2018</b>                         |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 28 November 2018</b>                         |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 05 December 2018</b>                         |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 12 December 2018</b>                         |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 19 December 2018</b>                         |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 24 December 2018</b>                         |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 31 December 2018</b>                         |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 07 January 2019</b>                          |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 09 January 2019</b><br>SW79-428019-236271217 | 347m    | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 10/01/2019               | Completed Defects | 09/01/2019      | A77 S/B C/WAY 100M N OF BARRS YARD                          |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 16 January 2019</b>                          |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 23 January 2019</b>                          |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 30 January 2019</b>                          |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 06 February 2019</b>                         |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 13 February 2019</b>                         |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 20 February 2019</b>                         |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 27 February 2019</b>                         |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 06 March 2019</b><br>SW79-440813-236342247   | 660m    | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 07/03/2019               | Completed Defects | 06/03/2019      | A77 N/B C/WAY 50M SOUTH OF STENNA TERMINAL/ CAIRNRYAN R/ABT |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 13 March 2019</b>                            |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 20 March 2019</b>                            |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 27 March 2019</b>                            |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |

**11610/75 : JUNCTION BONNY BRAES TO SOUTH AYRSHIRE BOUNDARY**

**Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 03 January 2018**

*No defects recorded*

**Safety Inspection of A75 W, A751 & A77 Dumfries V1 on 10 January 2018**

*No defects recorded*

| Defect Reference  | Start m | End m | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                          |
|---|---------|-------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|---|
| SW81-317457-235518242   | 1,988m  | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 07/02/2018               | Completed Defects | 10/01/2018      | A77 S/B C/WAY 100M S OF AYRSHIRE BORDER       |
| SW81-317457-235518243   | 1,994m  | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 07/02/2018               | Completed Defects | 10/01/2018      | A77 S/B C/WAY 100M S OF AYRSHIRE BORDER       |
| SW81-317457-235518244   | 1,872m  | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 07/02/2018               | Completed Defects | 10/01/2018      | A77 S/B C/WAY 200M S OF AYRSHIRE BORDER       |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 17 January 2018</b>  |         |       |             |                       |                 |                          |                   |                 |   |
| SW81-317651-235519581   | 2,054m  | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 14/02/2018               | Completed Defects | 05/02/2018      | A77 N/B C/WAY 100M SOUTH OF MARCHBURN COTTAGE |
| SW81-317651-235519582   | 2,035m  | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 14/02/2018               | Completed Defects | 05/02/2018      | A77 N/B C/WAY 100M SOUTH OF MARCHBURN COTTAGE |
| SW81-317651-235519584   | 2,026m  | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 14/02/2018               | Completed Defects | 05/02/2018      | A77 S/B C/WAY 100M SOUTH OF MARCHBURN COTTAGE |
| SW81-317651-235519580   | 2,150m  | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 14/02/2018               | Completed Defects | 05/02/2018      | A77 N/B C/WAY @ MARCHBURN COTTAGE             |
| SW81-317651-235519583   | 2,037m  | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 14/02/2018               | Completed Defects | 05/02/2018      | A77 N/B C/WAY 100M SOUTH OF MARCHBURN COTTAGE |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 24 January 2018</b>  |         |       |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 31 January 2018</b>  |         |       |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 07 February 2018</b> |         |       |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 14 February 2018</b> |         |       |             |                       |                 |                          |                   |                 |   |
| SW81-319705-235542966   | 2,179m  | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 15/02/2018               | Completed Defects | 14/02/2018      | A77 N/B @ MARCHBURN                           |
| SW81-319705-235542970   | 2,037m  | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 15/02/2018               | Completed Defects | 14/02/2018      | A77 N/B @ MARCHBURN                           |
| SW81-319705-235542967   | 2,179m  | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 15/02/2018               | Completed Defects | 14/02/2018      | A77 N/B @ MARCHBURN                           |
| SW81-319705-235542969   | 2,002m  | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 15/02/2018               | Completed Defects | 14/02/2018      | A77 N/B @ MARCHBURN                           |
| SW81-319705-235542964   | 2,171m  | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 15/02/2018               | Completed Defects | 14/02/2018      | A77 N/B @ MARCHBURN                           |
| SW81-319705-235542965   | 2,176m  | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 15/02/2018               | Completed Defects | 14/02/2018      | A77 N/B @ MARCHBURN                           |
| SW81-319705-235542968   | 2,179m  | 0m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 15/02/2018               | Completed Defects | 14/02/2018      | A77 N/B @ MARCHBURN                           |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 21 February 2018</b> |         |       |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 28 February 2018</b> |         |       |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 07 March 2018</b>    |         |       |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 14 March 2018</b>    |         |       |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 21 March 2018</b>    |         |       |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 28 March 2018</b>    |         |       |             |                       |                 |                          |                   |                 |   |
| SW81-331777-235608155   | 2,172m  | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 29/03/2018               | Completed Defects | 28/03/2018      | A77 N/B @ MARCHBURN                           |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 04 April 2018</b>    |         |       |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 11 April 2018</b>    |         |       |             |                       |                 |                          |                   |                 |   |



| Defect Reference   | Start m | End m  | Item Type     | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                        |
|--|---------|--------|---------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| SW81-336634-235619316  | 1,930m  | 0m     | CARRIAGEWAY   | Pothole VIAFIX (POTV)                | CAT 1           | 12/04/2018               | Completed Defects     | 11/04/2018      | A77 S/B 250M S OF AYRSHIRE BOARDER          |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 18 April 2018</b>     |         |        |               |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 W, A751 &amp; A77 Dumfries V1 on 25 April 2018</b>     |         |        |               |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 02 May 2018</b>    |         |        |               |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 09 May 2018</b>    |         |        |               |                                      |                 |                          |                       |                 |   |
| SW81-346484-235706617  | 1,896m  | 0m     | CARRIAGEWAY   | Pothole VIAFIX (POTV)                | CAT 1           | 10/05/2018               | Completed Defects     | 09/05/2018      | A77 S/B C/WAY 500M S OF AYRSHIRE BOUNDARY   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 16 May 2018</b>    |         |        |               |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 23 May 2018</b>    |         |        |               |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 30 May 2018</b>    |         |        |               |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 06 June 2018</b>   |         |        |               |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 13 June 2018</b>   |         |        |               |                                      |                 |                          |                       |                 |   |
| SW81-363139-235815073  | 1,039m  | 0m     | TRAFFIC_SIGNS | Obscured sign (OBSG)                 | CAT 1           | 14/06/2018               | Completed Defects     | 11/06/2018      | A77 S/B C/WAY 500M SOUTH OF AYRSHIRE BORDER |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 20 June 2018</b>   |         |        |               |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Dfs Detail on 27 June 2018</b>              |         |        |               |                                      |                 |                          |                       |                 |   |
| SW86-357233-6  | 545m    | 565m   | WOODLAND      | Invasive species (INVS)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 27 June 2018</b>   |         |        |               |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 04 July 2018</b>   |         |        |               |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 11 July 2018</b>   |         |        |               |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 18 July 2018</b>   |         |        |               |                                      |                 |                          |                       |                 |   |
| SW81-380201-235913284  | 2,033m  | 0m     | TRAFFIC_SIGNS | Physical condition of post (COPT)    | CAT 1           | 15/08/2018               | Completed Defects     | 11/10/2018      | A77 S/B VERGE 150 M S OF AYRSHIRE BORDER    |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 25 July 2018</b>   |         |        |               |                                      |                 |                          |                       |                 |   |
| SW81-383408-235921001  | 1,593m  | 0m     | GULLY         | Blockage (BLOK)                      | CAT 1           | 22/08/2018               | Completed Defects     | 17/08/2018      | A77 S/B C/WAY 1.6KM N OF CAIRNRYAN RBT      |
| SW81-383408-235920997  | 1,243m  | 0m     | GULLY         | Blockage (BLOK)                      | CAT 1           | 22/08/2018               | Completed Defects     | 17/08/2018      | A77 S/B C/WAY 1.2 KM N OF CAIRNRYAN RBT     |
| SW81-383408-235920996  | 1,331m  | 0m     | GULLY         | Blockage (BLOK)                      | CAT 1           | 22/08/2018               | Completed Defects     | 07/09/2018      | A77 S/B C/WAY 1.3 KM N OF CAIRNRYAN RBT     |
| SW81-383408-235920994  | 1,553m  | 0m     | GULLY         | Blockage (BLOK)                      | CAT 1           | 22/08/2018               | Completed Defects     | 17/08/2018      | A77 S/B C/WAY 1.5 KM N OF CAIRNRYAN RBT     |
| SW81-383408-235920995  | 1,458m  | 0m     | GULLY         | Blockage (BLOK)                      | CAT 1           | 22/08/2018               | Completed Defects     | 17/08/2018      | A77 S/B C/WAY 1.4 KM N OF CAIRNRYAN RBT     |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 01 August 2018</b> |         |        |               |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 08 August 2018</b> |         |        |               |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 15 August 2018</b> |         |        |               |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Dfs Detail on 16 July 2018</b>              |         |        |               |                                      |                 |                          |                       |                 |   |
| SW81-332073-22   | 1,872m  | 1,896m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |

| Defect Reference  | Start m | End m  | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                        |
|---|---------|--------|-------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| SW81-332073-21  | 1,974m  | 1,995m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 22 August 2018</b>    |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 29 August 2018</b>    |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 05 September 2018</b> |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 12 September 2018</b> |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 19 September 2018</b> |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 26 September 2018</b> |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 03 October 2018</b>   |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 10 October 2018</b>   |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 17 October 2018</b>   |         |        |             |                                      |                 |                          |                       |                 |   |
| SW79-422974-236143076   | 698m    | 0m     | CARRIAGEWAY | Pothole (POTH)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | A77 S/B C/WAY 700M NORTH OF STENA RBT       |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 24 October 2018</b>   |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 31 October 2018</b>   |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 07 November 2018</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 14 November 2018</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 21 November 2018</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 28 November 2018</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 05 December 2018</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| SW79-427168-236234667   | 699m    | 0m     | CARRIAGEWAY | Pothole (POTH)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | A77 S/B C/WAY 300M N OF CAIRNRYAN N GATEWAY |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 12 December 2018</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 19 December 2018</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| SW79-427501-236264631   | 530m    | 0m     | GULLY       | Blockage (BLOK)                      | CAT 1           | 16/01/2019               | Completed Defects     | 19/12/2018      | A77 S/B C/WAY 150M NORTH OF CAIRNRYAN       |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 24 December 2018</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 31 December 2018</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 07 January 2019</b>   |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 09 January 2019</b>   |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 16 January 2019</b>   |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 23 January 2019</b>   |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 30 January 2019</b>   |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 06 February 2019</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 13 February 2019</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 20 February 2019</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 27 February 2019</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |

| Defect Reference  | Start m | End m  | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                                |
|---|---------|--------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|---|
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 06 March 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 13 March 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 20 March 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| SW79-452164-236467197   | 1,847m  | 0m     | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 21/03/2019               | Completed Defects | 20/03/2019      | A77 S/B C/WAY 400M SOUTH OF THE AYRSHIRE BORDER     |
| <b>Safety Inspection of A75 Cardoness - Stranraer, A77, A751 on 27 March 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>11611/31 : NORTH MARK BRIDGE TO JUNCTION AT CARLOCK HOUSE</b>                  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>                   |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>                   |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>                   |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>                   |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b>                  |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b>                  |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b>                  |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b>                  |         |        |             |                       |                 |                          |                   |                 |   |
| SW82321955-235548237  | 1,538m  | 0m     | VERGE       | Litter Grade C (LITC) | 3RD PTY         | 23/02/2018               | Completed Defects | 29/03/2018      | layby northbound south of the bottom of carlck hill |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>                     |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>                     |         |        |             |                       |                 |                          |                   |                 |   |
| SW82326075-235554318  | 556m    | 756m   | CARRIAGEWAY | Other (OTHR)          | CAT 2           | 01/01/9999               | Completed Defects | 30/03/2018      |   |
| SW82326075-235554317  | 817m    | 1,017m | CARRIAGEWAY | Other (OTHR)          | CAT 2           | 01/01/9999               | Completed Defects | 30/03/2018      |   |
| SW82326075-235554319  | 399m    | 599m   | CARRIAGEWAY | Other (OTHR)          | CAT 2           | 01/01/9999               | Completed Defects | 30/03/2018      |   |
| SW82326075-235554321  | 1,105m  | 1,106m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 05/04/2018               | Completed Defects | 08/03/2018      | A77 SB CW, AT FARM JCT, NTH OF GLENAPP CHURCH       |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>                     |         |        |             |                       |                 |                          |                   |                 |   |
| SW82328086-235590008  | 1,509m  | 1,510m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 12/04/2018               | Completed Defects | 16/03/2018      | A77 NB CW, AT LAYBY STH OF CARLOCH HILL             |
| SW82328086-235590009  | 2,974m  | 2,976m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 12/04/2018               | Completed Defects | 16/03/2018      | A77 BOTH CW, 300M STH OF CARLOCH HOUSE              |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>                     |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>                     |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>                     |         |        |             |                       |                 |                          |                   |                 |   |
| SW82334882-235613708  | 3,050m  | 0m     | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 06/04/2018               | Completed Defects | 05/04/2018      | A77 N/B AT CARLOCK HILL                             |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>                     |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>                     |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>                     |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>                       |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |

| Defect Reference   | Start m | End m  | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                    |
|--|---------|--------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>          |         |        |                    |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |         |        |                    |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |         |        |                    |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |         |        |                    |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |   |
| SW86-357213-8  | 51m     | 31m    | WOODLAND           | Invasive species (INVS)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |   |
| SW80-370510-235861171  | 214m    | 215m   | TREE               | Overhanging/overgrown (OVER)         | CAT 1           | 26/07/2018               | Completed Defects     | 28/06/2018      | A78 NB CW 250M NORTH OF GLEN APP CHURCH |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |   |
| SW82332071-156   | 184m    | 185m   | BOLLARDS           | Damaged (DAMG)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-163   | 463m    | 550m   | TRAFFIC_SIGNS      | Surface corrosion (SFCO)             | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-152   | 60m     | 100m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-190   | 1,386m  | 1,450m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-172   | 791m    | 800m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-179   | 988m    | 1,050m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-185   | 1,199m  | 1,275m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-194   | 1,533m  | 1,600m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-201   | 1,816m  | 1,900m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-208   | 2,132m  | 2,200m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |

| Defect Reference | Start m | End m  | Item Type          | Item Detail                                    | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|--------|--------------------|--|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82332071-219   | 2,675m  | 2,750m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-226   | 2,980m  | 3,025m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-233   | 3,270m  | 3,325m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-166   | 561m    | 650m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-167   | 585m    | 625m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-175   | 878m    | 950m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-176   | 909m    | 975m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-197   | 1,647m  | 1,725m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-198   | 1,695m  | 1,750m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-211   | 2,269m  | 2,350m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-212   | 2,324m  | 2,400m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-215   | 2,482m  | 2,525m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-229   | 3,106m  | 3,175m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-230   | 3,154m  | 3,225m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-159   | 299m    | 375m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-161   | 393m    | 450m   | SAFETY_FENCE       | Corroded - metal post (fence / barrier) (CMTP) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-192   | 1,463m  | 1,525m | FILTER_DRAIN       | Other (OTHR)                                   | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |

| Defect Reference | Start m | End m  | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|--------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82332071-169   | 670m    | 750m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-183   | 1,134m  | 1,200m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-203   | 1,894m  | 1,975m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-205   | 1,987m  | 2,025m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-220   | 2,723m  | 2,800m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-222   | 2,819m  | 2,900m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-155   | 146m    | 225m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-157   | 219m    | 275m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-171   | 739m    | 825m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-173   | 817m    | 875m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-178   | 963m    | 1,050m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-180   | 1,032m  | 1,033m | TRAFFIC_SIGNS      | Surface corrosion (SFCO)             | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-207   | 2,084m  | 2,150m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-209   | 2,167m  | 2,225m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-216   | 2,526m  | 2,600m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-218   | 2,632m  | 2,633m | TRAFFIC_SIGNS      | Surface corrosion (SFCO)             | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-158   | 251m    | 300m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-160   | 338m    | 339m   | TRAFFIC_SIGNS      | Surface corrosion (SFCO)             | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |

| Defect Reference | Start m | End m  | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|--------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82332071-191   | 1,415m  | 1,416m | TRAFFIC_SIGNS      | Surface corrosion (SFCO)             | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-168   | 638m    | 639m   | TRAFFIC_SIGNS      | Surface corrosion (SFCO)             | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-182   | 1,103m  | 1,150m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-184   | 1,169m  | 1,225m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-204   | 1,946m  | 2,025m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-206   | 2,030m  | 2,100m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-221   | 2,769m  | 2,850m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-223   | 2,872m  | 2,950m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-162   | 427m    | 500m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-164   | 501m    | 575m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-153   | 86m     | 150m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-189   | 1,351m  | 1,352m | TRAFFIC_SIGNS      | Surface corrosion (SFCO)             | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-186   | 1,235m  | 1,350m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-193   | 1,496m  | 1,497m | TRAFFIC_SIGNS      | Surface corrosion (SFCO)             | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-200   | 1,784m  | 1,850m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-202   | 1,849m  | 1,925m | TRAFFIC_SIGNS      | Surface corrosion (SFCO)             | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-225   | 2,945m  | 2,946m | TRAFFIC_SIGNS      | Surface corrosion (SFCO)             | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-227   | 3,017m  | 3,100m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-232   | 3,236m  | 3,300m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |

| Defect Reference | Start m | End m  | Item Type          | Item Detail                                    | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|--------|--------------------|--|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82332071-234   | 3,303m  | 3,400m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-154   | 108m    | 109m   | TRAFFIC_SIGNS      | Surface corrosion (SFCO)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-165   | 515m    | 600m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-188   | 1,320m  | 1,400m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-170   | 703m    | 775m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-181   | 1,057m  | 1,100m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-187   | 1,274m  | 1,375m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-199   | 1,737m  | 1,775m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-210   | 2,218m  | 2,300m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-217   | 2,577m  | 2,625m | SAFETY_FENCE       | Corroded - metal post (fence / barrier) (CMTP) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-224   | 2,908m  | 2,909m | TRAFFIC_SIGNS      | Surface corrosion (SFCO)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-151   | 31m     | 100m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-174   | 853m    | 900m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-177   | 936m    | 1,025m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-195   | 1,569m  | 1,650m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-196   | 1,607m  | 1,675m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-213   | 2,375m  | 2,450m | SAFETY_FENCE       | Corroded - metal post (fence / barrier) (CMTP) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-214   | 2,434m  | 2,500m | SAFETY_FENCE       | Corroded - metal post (fence / barrier) (CMTP) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |



| Defect Reference  | Start m | End m  | Item Type          | Item Detail                       | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                                       |
|---|---------|--------|--------------------|-----------------------------------|-----------------|--------------------------|-----------------------|-----------------|--|
| SW82332071-228  | 3,063m  | 3,150m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-231  | 3,196m  | 3,250m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>    |         |        |                    |                                   |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>    |         |        |                    |                                   |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>    |         |        |                    |                                   |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>    |         |        |                    |                                   |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>    |         |        |                    |                                   |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b> |         |        |                    |                                   |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b> |         |        |                    |                                   |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b> |         |        |                    |                                   |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b> |         |        |                    |                                   |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>   |         |        |                    |                                   |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>   |         |        |                    |                                   |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>   |         |        |                    |                                   |                 |                          |                       |                 |  |
| SW82423458-236136741  | 3,294m  | 3,295m | CARRIAGEWAY        | Pothole VIAFIX (POTV)             | CAT 1           | 15/11/2018               | Completed Defects     | 18/10/2018      | A77 SB CW, 50M STH OF CARLOCK HOUSE JCT, STH OF BALLANTRAE |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>   |         |        |                    |                                   |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>  |         |        |                    |                                   |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>  |         |        |                    |                                   |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>  |         |        |                    |                                   |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b>  |         |        |                    |                                   |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b>  |         |        |                    |                                   |                 |                          |                       |                 |  |
| SW82426917-236234295  | 3,327m  | 3,328m | CARRIAGEWAY        | Pothole VIAFIX (POTV)             | CAT 1           | 30/11/2018               | Completed Defects     | 29/11/2018      | A77 SB CW 20M FROM CARLOCK HOUSE JCT                       |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b>  |         |        |                    |                                   |                 |                          |                       |                 |  |
| SW80-427220-236234307   | 2,734m  | 2,934m | CHANNEL            | Detritus / Refuse (DETR)          | CAT 1           | 07/12/2018               | Completed Defects     | 06/12/2018      | A77 NB CW 100M SOUTH OF CARLOCK HOUSE JCT CARLOCK HILL     |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b>  |         |        |                    |                                   |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b>  |         |        |                    |                                   |                 |                          |                       |                 |  |
| SW82427527-236264592  | 3,325m  | 3,326m | MANHOLE            | Rocking under load (IRLD)         | 3RD PTY         | 17/01/2019               | Completed Defects     | 20/12/2018      | A77 NB CW 50M SOUTH OF CARLOCK HOUSE JCT CARLOCK HILL      |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b>  |         |        |                    |                                   |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>   |         |        |                    |                                   |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>   |         |        |                    |                                   |                 |                          |                       |                 |  |
| SW82428044-236270546  | 2,930m  | 2,931m | CARRIAGEWAY        | Pothole (POTH)                    | CAT 1           | 07/02/2019               | Completed Defects     | 11/01/2019      | A77 NB CW 100M SOUTH OF CARLOCK HOUSE JCT CARLOCK HILL     |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description  |
|--|---------|--------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|---|
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>11611/68 : JCT BALLOCHDOWAN TO OLD SMYRTON</b>                |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| SW82317326-235513697   | 447m    | 448m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 01/02/2018               | Completed Defects | 26/01/2018      | 600 metres north of minor jct. sb cw 150meters prior to deer sign |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| SW82317471-235518216   | 291m    | 292m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 08/02/2018               | Completed Defects | 08/02/2018      | A77 ON CL, 300M STH OF OLD SMRYTON, STH OF BALLANTRAE             |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| SW82317666-235521313   | 973m    | 975m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 15/02/2018               | Completed Defects | 06/03/2018      | A77 ON CL, OPPOSITE AUCHENCROSH FARM, STH OF BALLANTRAE           |
| SW82317666-235521314   | 262m    | 263m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 15/02/2018               | Completed Defects | 15/02/2018      | A77 SB CW, 700M STH OF AUCHENCROSH FARM, STH OF BALLANTRAE        |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| SW82319037-235539795   | 481m    | 485m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 08/03/2018               | Completed Defects | 09/02/2018      | A77 SB CW, 400M STH OF AUCHENCROSH, STH OF BALLANTRAE             |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| SW82319984-235544948   | 968m    | 969m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 15/03/2018               | Completed Defects | 15/02/2018      | A77 SB CW, 10M STH OF AUCHENCROSH FARM                            |
| SW82319984-235544949   | 1,026m  | 1,028m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 15/03/2018               | Completed Defects | 15/02/2018      | A77 SB CW AND CL, 50M NTH OF AUCHENCROSH FARM                     |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| SW82321955-235548240   | 274m    | 275m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 22/03/2018               | Completed Defects | 23/02/2018      | A77 BEY3EEN AUCHINCROSH AND MINOR JUNCTION SIB CW                 |
| SW82321955-235548242   | 703m    | 704m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 22/03/2018               | Completed Defects | 23/02/2018      | A77 SOUTH OF AUCHINCROSH KENNELS NB CW NOS 25, 26, 27             |
| SW82321955-235548244   | 866m    | 867m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 22/03/2018               | Completed Defects | 23/02/2018      | A77 BETWEEN AUCHINCROSH FARM AND K4NNELS NB CW                    |

| Defect Reference  | Start m | End m  | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status          | Completion Date | Location Description  |
|---|---------|--------|-------------|-----------------------|-----------------|--------------------------|-------------------------|-----------------|---|
| SW82321955-235548239  | 292m    | 293m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 22/03/2018               | Completed Defects       | 23/02/2018      | A77 SOUTBOUND CARRIAGEWAY BETWEEN AUCHINCROSH AND SMYRTON SIB CW      |
| SW82321955-235548241  | 394m    | 0m     | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 22/03/2018               | Completed Defects       | 23/02/2018      | A77 BETWEEN AUCHINCROSH AND MINOR SIB CW                              |
| SW82321955-235548243  | 695m    | 696m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 22/03/2018               | Completed Defects       | 23/02/2018      | A77 SIB CW SOUTH OF AUCHINCROSH KENNELS                               |
| SW82321955-235548238  | 252m    | 253m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 22/03/2018               | Completed Defects       | 23/02/2018      | SOUTHBOUND CW BETWEEN AUCHINCROSH AND MINOR JUNCTION SOUTH OF SMYRTON |
| SW82321955-235548245  | 0m      | 0m     | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 22/03/2018               | Completed Defects       | 22/02/2018      | A77 BETWEEN SMYRTON AND AUCHINCROSH FARM NIB CW                       |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b> |         |        |             |                       |                 |                          |                         |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                         |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b> |         |        |             |                       |                 |                          |                         |                 |   |
| SW82326075-235554314  | 1,083m  | 1,084m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 05/04/2018               | Completed Defects       | 08/03/2018      | A77 NB CW, 50M STH AUCHENCROSH FARM                                   |
| SW82326075-235554313  | 843m    | 845m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 05/04/2018               | Completed Defects       | 08/03/2018      | A77 NB CW, 300M NTH OF AUCHENCROSH FARM                               |
| SW82326075-235554315  | 1,131m  | 1,132m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 05/04/2018               | Completed Defects       | 08/03/2018      | A77 NB CW, 100M STH OF AUCHENCROSH FARM                               |
| SW82326075-235554316  | 1,159m  | 1,160m | CARRIAGEWAY | Pothole (POTH)        | 3RD PTY         | 05/04/2018               | Awaiting CCMS Temp Date | 01/01/9999      | A77 NB CW, 120M STH OF AUCHENCROSH                                    |
| SW82326075-235554312  | 983m    | 984m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 05/04/2018               | Completed Defects       | 08/03/2018      | A77 NB CW, 400M NTH OF AUCHENCROSH FARM                               |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b> |         |        |             |                       |                 |                          |                         |                 |   |
| SW82328086-235590017  | 469m    | 470m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 12/04/2018               | Completed Defects       | 15/03/2018      | A77 SB CW, 450M NTH OF JCT BALLOCHDOWAN                               |
| SW82328086-235590016  | 522m    | 526m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 12/04/2018               | Completed Defects       | 15/03/2018      | A77 SB CW, 500M NTH OF JCT BALLOCH DOWAN                              |
| SW82328086-235590018  | 407m    | 408m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 12/04/2018               | Completed Defects       | 15/03/2018      | A77 SB CW, 400M NTH OF JCT BALLOCHDOWAN                               |
| SW82328086-235590020  | 933m    | 934m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 12/04/2018               | Completed Defects       | 15/03/2018      | A77 NB CW, OUTSIDE AUCHENCROSH FARM                                   |
| SW82328086-235590019  | 219m    | 220m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 12/04/2018               | Completed Defects       | 15/03/2018      | A77 NB CW, 200M NTH OF JCT BALLOCHDOWAN                               |
| SW82328086-235590021  | 1,596m  | 1,597m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 12/04/2018               | Completed Defects       | 15/03/2018      | A77 SB CW, OUTSIDE OLD SMRYTON  |
| SW82328086-235590015  | 277m    | 278m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 12/04/2018               | Completed Defects       | 15/03/2018      | A77 SB CW, 300M NTH OF JCT BALLOCH DOWAN                              |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b> |         |        |             |                       |                 |                          |                         |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                         |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b> |         |        |             |                       |                 |                          |                         |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                         |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b> |         |        |             |                       |                 |                          |                         |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                         |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b> |         |        |             |                       |                 |                          |                         |                 |   |
| SW82336916-235633864  | 815m    | 816m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 10/05/2018               | Completed Defects       | 12/04/2018      | A77 NB CW, 400M NTH OF AUCHENCROSH FARM STH OF BALLANTRAE             |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b> |         |        |             |                       |                 |                          |                         |                 |   |

| Defect Reference   | Start m | End m  | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                  |
|--|---------|--------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|---------------------------------------|
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>        |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| SW82341166-235669116   | 319m    | 0m     | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 27/04/2018               | Completed Defects     | 26/04/2018      | A77 NB AUCHENCROSH CENTRE LINE        |
| SW82341166-235669117   | 451m    | 0m     | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 27/04/2018               | Completed Defects     | 26/04/2018      | A77 NB AUCHENCROSH LANE 1 NS WT       |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>          |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>          |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| SW86-357213-5  | 567m    | 50m    | WOODLAND           | Invasive species (INVS)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                       |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| SW80-394061-235954863  | 419m    | 420m   | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 17/08/2018               | Completed Defects     | 16/08/2018      | A77 S/B C/W 700M SOUTH OF AUCHENCROSH |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |                                       |
| SW82332071-347   | 638m    | 718m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                       |
| SW82332071-348   | 636m    | 716m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                       |
| SW82332071-365   | 1,529m  | 1,600m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                       |
| SW82332071-337   | 357m    | 457m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                       |
| SW82332071-344   | 568m    | 648m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                       |

| Defect Reference | Start m | End m  | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|--------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82332071-351   | 703m    | 783m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-355   | 1,239m  | 1,319m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-362   | 1,460m  | 1,540m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-338   | 402m    | 502m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-361   | 1,471m  | 1,571m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-363   | 1,453m  | 1,523m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-340   | 397m    | 477m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-342   | 484m    | 564m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-357   | 1,259m  | 1,359m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-359   | 1,331m  | 1,411m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-343   | 504m    | 604m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-345   | 562m    | 642m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-352   | 1,147m  | 1,247m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-354   | 1,152m  | 1,232m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-339   | 401m    | 481m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-341   | 479m    | 559m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-356   | 1,234m  | 1,314m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-358   | 1,338m  | 1,420m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-349   | 710m    | 810m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |

| Defect Reference  | Start m | End m  | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                                 |
|---|---------|--------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|--|
| SW82332071-350  | 709m    | 789m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-364  | 1,568m  | 1,600m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-346  | 615m    | 715m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-353  | 1,149m  | 1,229m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-360  | 1,358m  | 1,458m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>    |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW82410364-236066537  | 1,507m  | 1,508m | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 21/09/2018               | Completed Defects     | 20/09/2018      | A77 SB CW 200M SOUTH OF SMYRTON JCT                  |
| SW82410364-236066536  | 434m    | 435m   | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 21/09/2018               | Completed Defects     | 20/09/2018      | A77 SB CW 400M SOUTH AUCHENCROSH SOUTH OF BALLANTRAE |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>   |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>   |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>   |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>   |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>  |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW82426212-236179761  | 1m      | 2m     | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 02/11/2018               | Completed Defects     | 01/11/2018      | A77 SB CW 235M FROM AUCHENCROSH                      |
| SW82426212-236179758  | 603m    | 605m   | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 02/11/2018               | Completed Defects     | 01/11/2018      | A77 NB CW 200M FROM AUCHENCROSH                      |
| SW82426212-236179759  | 10m     | 11m    | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 02/11/2018               | Completed Defects     | 01/11/2018      | A77 NB CW 205M FROM AUCHENCROSH                      |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>  |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>  |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b>  |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b>  |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW82426917-236234297  | 301m    | 303m   | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 30/11/2018               | Completed Defects     | 29/11/2018      | A77 SB CW 415M AFTER AUCHENCROSH FARM                |
| SW82426917-236234296  | 379m    | 381m   | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 30/11/2018               | Completed Defects     | 29/11/2018      | A77 SB CW 400M AFTER AUCHENCROSH FARM                |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b>  |         |        |                    |                                      |                 |                          |                       |                 |  |

| Defect Reference   | Start m | End m | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                         |
|--|---------|-------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|--|
| SW80-427220-236234308  | 755m    | 775m  | CARRIAGEWAY | Other (OTHR)          | 3RD PTY         | 03/01/2019               | Completed Defects | 07/05/2019      | A77 50M SOUTH OF AUCHENCROSH FARM            |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b> |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b> |         |       |             |                       |                 |                          |                   |                 |  |
| SW82427527-236264595   | 383m    | 384m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 17/01/2019               | Completed Defects | 12/01/2019      | A77 SB CW 150M SOUTH OF AUCHENCROSH FARM JCT |
| SW82427527-236264594   | 503m    | 504m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 17/01/2019               | Completed Defects | 12/01/2019      | A77 SB CW 125M SOUTH OF AUCHENCROSH FARM JCT |
| SW82427527-236264596   | 383m    | 385m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 17/01/2019               | Completed Defects | 12/01/2019      | A77 NB CW 125M SOUTH OF AUCHENCROSH FARM JCT |
| SW82427527-236264593   | 510m    | 511m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 17/01/2019               | Completed Defects | 12/01/2019      | A77 SB CW 100M SOUTH OF AUCHENCROSH FARM JCT |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b> |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| SW82427890-236270547   | 227m    | 230m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 31/01/2019               | Completed Defects | 03/01/2019      | A77 SB CW, 230M NTH OF JCT BALLOCHDOWAN      |
| SW82427890-236270548   | 245m    | 246m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 31/01/2019               | Completed Defects | 03/01/2019      | A77 NB CW, 245M NTH OF JCT BALLOCHDOWAN      |
| SW82427890-236270550   | 239m    | 240m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 31/01/2019               | Completed Defects | 03/01/2019      | A77 ON CL, 265M NTH OF JCT BALLOCHDOWAN      |
| SW82427890-236270549   | 258m    | 260m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 31/01/2019               | Completed Defects | 03/01/2019      | A77 CL, 260M NTH OF JCT BALLOCHDOWAN         |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| SW82428228-236270556   | 661m    | 662m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 14/02/2019               | Completed Defects | 18/01/2019      | A77 NB CW 310M SOUTH OF AUCHENCROSH FARM     |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| SW82428625-236291430   | 445m    | 446m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 01/02/2019               | Completed Defects | 31/01/2019      | A77 NB CW 505M SOUTH AUCHENCROSH             |
| SW82428625-236291429   | 460m    | 461m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 01/02/2019               | Completed Defects | 31/01/2019      | A77 NB CW 500M SOUTH OF AUCHENCROSH          |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |  |
| SW82429489-236310398   | 431m    | 432m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 07/03/2019               | Completed Defects | 07/02/2019      | A77 SB CW, 420M NTH OF JCT BALLOCHDOWAN      |
| SW82429489-236310399   | 449m    | 450m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 07/03/2019               | Completed Defects | 07/02/2019      | A77 SB CW, 425M NTH OF JCT BALLOCHDOWAN      |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |  |
| SW82430228-236328526   | 682m    | 683m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 14/03/2019               | Completed Defects | 01/03/2019      | A77 N/B 150M PRIOR TO AUCHENCROSH            |
| SW82430228-236328525   | 680m    | 681m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 14/03/2019               | Completed Defects | 01/03/2019      | A77 N/B 150M PRIOR TO AUCHENCROSH            |
| SW82430228-236328524   | 758m    | 759m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 14/03/2019               | Completed Defects | 01/03/2019      | A77 S/B OPP AUCHENCROSH                      |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |  |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                                 |
|--|---------|--------|-------------|-----------------------|-----------------|--------------------------|-----------------------|-----------------|--|
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>    |         |        |             |                       |                 |                          |                       |                 |  |
| SW82447370-236454235   | 419m    | 421m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 15/03/2019               | Completed Defects     | 14/03/2019      | A77 N/B 1M NORTH OF CARLOCK HILL                     |
| SW82447370-236454236   | 457m    | 459m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 15/03/2019               | Completed Defects     | 14/03/2019      | A77 N/B 1500M PRIOR TO CARLOCK HILL                  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>    |         |        |             |                       |                 |                          |                       |                 |  |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>    |         |        |             |                       |                 |                          |                       |                 |  |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                       |                 |  |
| <b>11611/79 : OLD SMYRTON TO B7044 JUNCTION</b>                  |         |        |             |                       |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>  |         |        |             |                       |                 |                          |                       |                 |  |
| SW82317326-235513696   | 3,344m  | 3,464m | GULLY       | Flooding (FLOD)       | CAT 1           | 01/02/2018               | Completed Defects     | 30/01/2018      | SOUTH OF STINCHER BRIDG3                             |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>  |         |        |             |                       |                 |                          |                       |                 |  |
| SW82317471-235518217   | 3,488m  | 3,789m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 08/02/2018               | Completed Defects     | 25/01/2018      | A77 SB CW, BRIDGE AT BALLANTRAE STH GATEWAY          |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>  |         |        |             |                       |                 |                          |                       |                 |  |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>  |         |        |             |                       |                 |                          |                       |                 |  |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b> |         |        |             |                       |                 |                          |                       |                 |  |
| SW82318129-235532270   | 2,202m  | 2,203m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 01/03/2018               | Completed Defects     | 01/02/2018      | A77 SB CW, PRIOR TO WATER TANKS, AT SLOW SIGN        |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b> |         |        |             |                       |                 |                          |                       |                 |  |
| SW82319037-235539793   | 1,308m  | 1,318m | CARRIAGEWAY | Pothole (POTH)        | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | A77 AT WATERTANKS STH OF BALLANTRAE                  |
| SW82319037-235539794   | 2,204m  | 2,206m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 08/03/2018               | Completed Defects     | 09/02/2018      | A77 SB CW, 150M NTH OF WATERTANKS, STH OF BALLANTRAE |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b> |         |        |             |                       |                 |                          |                       |                 |  |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b> |         |        |             |                       |                 |                          |                       |                 |  |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>    |         |        |             |                       |                 |                          |                       |                 |  |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>    |         |        |             |                       |                 |                          |                       |                 |  |
| SW82326075-235554311   | 3,554m  | 6,555m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 05/04/2018               | Completed Defects     | 08/03/2018      | A77 NB CW, ON BRIDGE DECK, BALLANTRAE                |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>    |         |        |             |                       |                 |                          |                       |                 |  |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>    |         |        |             |                       |                 |                          |                       |                 |  |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>    |         |        |             |                       |                 |                          |                       |                 |  |
| SW80-332117-235613707  | 3,565m  | 3,566m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 26/04/2018               | Completed Defects     | 29/03/2018      | A77 NB CW, 20M STH OF MAINS RD JCT, BALLANTRAE       |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>    |         |        |             |                       |                 |                          |                       |                 |  |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>    |         |        |             |                       |                 |                          |                       |                 |  |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>    |         |        |             |                       |                 |                          |                       |                 |  |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>    |         |        |             |                       |                 |                          |                       |                 |  |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>      |         |        |             |                       |                 |                          |                       |                 |  |
| SW82344114-235554290   | 2,548m  | 0m     | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 04/05/2018               | Completed Defects     | 03/05/2018      | A77 SB 200M PAST AUCHAIRNE LANE 1 NS WT              |



| Defect Reference   | Start m | End m  | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                                      |
|--|---------|--------|-------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| SW82344114-235554291   | 2,494m  | 0m     | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 04/05/2018               | Completed Defects     | 03/05/2018      | A77 SB 300M PAST AUCHRANIE LANE 1 NS WT                   |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>          |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |         |        |             |                                      |                 |                          |                       |                 |   |
| SW82349855-235793432   | 3,393m  | 3,394m | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 14/06/2018               | Completed Defects     | 17/05/2018      | A77 SB CW 50M SOUTH GATEWAY FOR BALLENTY                  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |         |        |             |                                      |                 |                          |                       |                 |   |
| SW82356191-235816775   | 355m    | 336m   | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 28/06/2018               | Completed Defects     | 31/05/2018      | A77 CL OUTSIDE HIGH KILPHIN                               |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |         |        |             |                                      |                 |                          |                       |                 |   |
| SW80-359626-235827125  | 3m      | 4m     | CARRIAGEWAY | Pothole (POTH)                       | CAT 1           | 05/07/2018               | Completed Defects     | 07/06/2018      | A77 SB CW AT OLD SMYRTON BUS STOP                         |
| SW80-359626-235827126  | 341m    | 342m   | CARRIAGEWAY | Pothole (POTH)                       | CAT 1           | 05/07/2018               | Completed Defects     | 07/06/2018      | A77 NB CW 50M SOUTH OF HIGH KILPHIN                       |
| SW80-359626-235827127  | 343m    | 344m   | CARRIAGEWAY | Pothole (POTH)                       | CAT 1           | 05/07/2018               | Completed Defects     | 07/06/2018      | A77 NB CW 40M SOUTH HIGH KILPHIN                          |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |         |        |             |                                      |                 |                          |                       |                 |   |
| SW80-363687-235858065  | 610m    | 611m   | CARRIAGEWAY | Pothole (POTH)                       | CAT 1           | 12/07/2018               | Completed Defects     | 14/06/2018      | A77 SB CW 200M AFTER KILPHIN HOUSE                        |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |         |        |             |                                      |                 |                          |                       |                 |   |
| SW82374127-235892360   | 2,738m  | 2,739m | CARRIAGEWAY | Miscellaneous surface Defects (MSRF) | CAT 1           | 02/08/2018               | Completed Defects     | 01/08/2018      | A77 SB CW 100M AFTER AUCHENCAIRN JCT                      |
| SW82374127-235892359   | 2,742m  | 2,743m | CARRIAGEWAY | Miscellaneous surface Defects (MSRF) | CAT 1           | 02/08/2018               | Completed Defects     | 01/08/2018      | A77 SB CW 95M AFTER AUCHCAIRN JCT                         |
| SW82374127-235892361   | 2,738m  | 2,739m | CARRIAGEWAY | Miscellaneous surface Defects (MSRF) | CAT 1           | 02/08/2018               | Completed Defects     | 01/08/2018      | A77 SB CW 105M AFTER AUCHENCAIRN JCT                      |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |         |        |             |                                      |                 |                          |                       |                 |   |
| SW82380667-235914376   | 550m    | 551m   | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 16/08/2018               | Completed Defects     | 19/07/2018      | A77 NB CW 255M AFTER HIGH KILPHIN                         |
| SW82380667-235914375   | 544m    | 545m   | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 16/08/2018               | Completed Defects     | 19/07/2018      | A77 NB CW 250M AFTER HIGH KILPHIN                         |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |         |        |             |                                      |                 |                          |                       |                 |   |
| SW80-397303-235954864  | 1,343m  | 1,346m | CARRIAGEWAY | Surface texture worn (SRTX)          | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | A77S/B C/W 500M NORTH OF KILPHIN FARM SOUTH OF BALLANTRAE |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |         |        |             |                                      |                 |                          |                       |                 |   |

| Defect Reference | Start m | End m  | Item Type          | Item Detail                           | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|--------|--------------------|---------------------------------------|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82332071-371   | 134m    | 234m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)     | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-378   | 490m    | 570m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)  | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-385   | 1,349m  | 1,419m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)  | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-367   | 6m      | 86m    | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)  | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-381   | 745m    | 835m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)  | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-382   | 1,145m  | 1,225m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)  | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-373   | 184m    | 264m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)  | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-375   | 248m    | 248m   | TRAFFIC_SIGNS      | Physical condition of fittings (COFT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-390   | 2,926m  | 3,026m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)     | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-377   | 485m    | 565m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)  | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-379   | 649m    | 729m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)  | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-386   | 2,728m  | 2,750m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)  | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-388   | 2,790m  | 2,870m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)  | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-372   | 177m    | 257m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)  | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-374   | 232m    | 332m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)     | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-376   | 282m    | 362m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)  | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-389   | 2,796m  | 2,896m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)     | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-368   | 6m      | 86m    | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)  | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-370   | 93m     | 173m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)  | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-369   | 93m     | 163m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)  | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |

| Defect Reference  | Start m | End m  | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description   |
|---|---------|--------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|--|
| SW82332071-380  | 645m    | 725m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-387  | 2,792m  | 3,892m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-366  | 0m      | 100m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-383  | 1,238m  | 1,318m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-384  | 1,237m  | 1,317m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>    |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW80-400497-235984890   | 3,546m  | 3,547m | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 31/08/2018               | Completed Defects     | 30/08/2018      | A77 N/B C/W JUST AFTER BRIDGE BALLANTRAE SOUTH                 |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW80-403929-235984878   | 3,143m  | 3,143m | GULLY              | Blockage (BLOK)                      | CAT 1           | 04/10/2018               | Completed Defects     | 10/09/2018      | A77 N/B C/W OPPOSITE LAGGANHOUSE JCT SOUTH OF BALLANTRAE       |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>   |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>   |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW82420227-236118417  | 3,333m  | 3,333m | GULLY              | Blockage (BLOK)                      | CAT 1           | 08/11/2018               | Completed Defects     | 31/10/2018      | A77 SB CW 25M FROM BALLANTRAE SOUTH GATEWAY                    |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>   |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>   |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>  |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>  |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>  |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b>  |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b>  |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW82426917-236234298  | 1,406m  | 1,408m | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 30/11/2018               | Completed Defects     | 29/11/2018      | A77 SB CW 500M NORTH OF LAIGH KILPHIN FARM                     |
| SW82426917-236234299  | 3,266m  | 3,267m | TRAFFIC_SIGNS      | Pointing wrong way (RWAY)            | CAT 1           | 30/11/2018               | Completed Defects     | 29/11/2018      | A77 NB CW 200M SOUTH OF LENDALFOOT                             |
| SW82426917-236234293  | 2,323m  | 2,333m | MANHOLE            | Cracked or broken (IBCK)             | 3RD PTY         | 27/12/2018               | Completed Defects     | 07/05/2019      | A77 SB CW 150M AFTER AUCHAIRNE JCT SOUTH OF BALLANTRAE         |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b>  |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b>  |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW82427366-236262602  | 1,338m  | 1,340m | CARRIAGEWAY        | Pothole (POTH)                       | CAT 1           | 10/01/2019               | Completed Defects     | 13/12/2018      | A77 SB CW, FRETTING, 200M STH OF WATERTANKS, STH OF BALLANTRAE |

| Defect Reference   | Start m | End m  | Item Type     | Item Detail               | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description   |
|--|---------|--------|---------------|---------------------------|-----------------|--------------------------|-------------------|-----------------|--|
| SW82427366-236262601   | 1,338m  | 1,340m | CARRIAGEWAY   | Pothole (POTH)            | CAT 1           | 10/01/2019               | Completed Defects | 13/12/2018      | A77 NB CW, FRETTEING, 200M STH OF WATER TANKS, STH OF BALLANTRAE                   |
| SW82427366-236262603   | 2,032m  | 2,033m | CARRIAGEWAY   | Pothole (POTH)            | CAT 1           | 10/01/2019               | Completed Defects | 14/12/2018      | A77 SB CW, 100M NTH OF WATERTANKS, STH OF BALLANTRAE                               |
| SW82427366-236262600   | 666m    | 667m   | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1           | 10/01/2019               | Completed Defects | 13/12/2018      | A77 NB CW, 20M NTH OF KILPHIN HOUSE STH OF BALANTRAE                               |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b> |         |        |               |                           |                 |                          |                   |                 |  |
| SW82427527-236264597   | 2,745m  | 2,745m | CARRIAGEWAY   | Pothole (POTH)            | CAT 1           | 17/01/2019               | Completed Defects | 20/12/2018      | A77 NB CW SOUTH OF WATER TANKS HILL ON ANTI SKID                                   |
| SW82427527-236264599   | 3,475m  | 3,476m | TRAFFIC_SIGNS | Pointing wrong way (RWAY) | CAT 1           | 21/12/2018               | Completed Defects | 20/12/2018      | A77 NB CW 200M SOUTH OF BALLANTRAE   |
| SW82427527-236264601   | 586m    | 5,870m | TRAFFIC_SIGNS | Other (OTHR)              | CAT 1           | 17/01/2019               | Completed Defects | 07/02/2019      | A77 SB CW 15 M SOUTH OF LAIGH KILPHIN JCT NORTH OF SMYRTON AT CORNER WITH ANTISKID |
| SW82427527-236264598   | 2,726m  | 2,727m | CARRIAGEWAY   | Pothole (POTH)            | CAT 1           | 17/01/2019               | Completed Defects | 20/12/2018      | A77 NB CW AT BOTTOM OF WATER TANKS HILL ON ANTI SKID SOUTH OF BALLANTRAE           |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b> |         |        |               |                           |                 |                          |                   |                 |  |
| No defects recorded  |         |        |               |                           |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>  |         |        |               |                           |                 |                          |                   |                 |  |
| No defects recorded  |         |        |               |                           |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>  |         |        |               |                           |                 |                          |                   |                 |  |
| No defects recorded  |         |        |               |                           |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>  |         |        |               |                           |                 |                          |                   |                 |  |
| No defects recorded  |         |        |               |                           |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>  |         |        |               |                           |                 |                          |                   |                 |  |
| SW82428351-236284303   | 2,112m  | 2,112m | TRAFFIC_SIGNS | Damaged (DAMG)            | CAT 1           | 21/02/2019               | Completed Defects | 19/02/2019      | A77 NB VERGE, 150M STH OF WATERTANKS, STH OF BALLANTRAE                            |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>  |         |        |               |                           |                 |                          |                   |                 |  |
| No defects recorded  |         |        |               |                           |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b> |         |        |               |                           |                 |                          |                   |                 |  |
| SW82429489-236310400   | 2,538m  | 2,539m | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1           | 07/03/2019               | Completed Defects | 08/02/2019      | A77 SB CW, 150M STH OF AUCHAIRNE STH OF BALLANTRAE                                 |
| SW82429489-236310402   | 3,552m  | 3,553m | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1           | 07/03/2019               | Completed Defects | 07/02/2019      | A77 51M STH OF COLMONELL JCT BALLANTRAE  |
| SW82429489-236310401   | 3,561m  | 3,562m | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1           | 07/03/2019               | Completed Defects | 07/02/2019      | A77 NB CW, 50M STH OF COLMONELL JCT BALLANTRAE                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b> |         |        |               |                           |                 |                          |                   |                 |  |
| No defects recorded  |         |        |               |                           |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b> |         |        |               |                           |                 |                          |                   |                 |  |
| No defects recorded  |         |        |               |                           |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b> |         |        |               |                           |                 |                          |                   |                 |  |
| No defects recorded  |         |        |               |                           |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>    |         |        |               |                           |                 |                          |                   |                 |  |
| No defects recorded  |         |        |               |                           |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>    |         |        |               |                           |                 |                          |                   |                 |  |
| No defects recorded  |         |        |               |                           |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>    |         |        |               |                           |                 |                          |                   |                 |  |
| SW82453127-236489179   | 2,746m  | 2,746m | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1           | 22/03/2019               | Completed Defects | 21/03/2019      | A77 S/B @ OLD SMYRTON HILL   |
| SW82453127-236489176   | 2,236m  | 2,236m | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1           | 22/03/2019               | Completed Defects | 21/03/2019      | A77 S/B AT OLD SMYRTON HILL  |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                                     |
|--|---------|--------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|--|
| SW82453127-236489178   | 2,696m  | 2,696m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 22/03/2019               | Completed Defects | 21/03/2019      | A77 S/B OLD SMYRTON HILL                                 |
| SW82453127-236489180   | 2,707m  | 2,707m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 22/03/2019               | Completed Defects | 21/03/2019      | A77 S/B @ OLD SMYRTON HILL                               |
| SW82453127-236489181   | 2,774m  | 2,774m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 22/03/2019               | Completed Defects | 21/03/2019      | A77 S/B @ OLD SMYRTON HILL                               |
| SW82453127-236489177   | 2,679m  | 2,679m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 22/03/2019               | Completed Defects | 21/03/2019      | A77 S/B @ OLD SMYRTON HILL                               |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>    |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>11614/35 : JUNCTION LITTLE BENNANE TO CARLETON FISHERIES</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| SW82317326-235513695   | 3,215m  | 3,216m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 01/02/2018               | Completed Defects | 26/01/2018      | 200 METRES SOUTH OF THE LAY Y SOUTH OF LENDALFOOT S/B CW |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| SW82317666-235521316   | 2,187m  | 2,190m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 15/02/2018               | Completed Defects | 16/02/2018      | A77 SB CW, AT BENANNE SPA, STH OF LENDALFOOT             |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| SW82319984-235544952   | 2,201m  | 2,202m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 15/03/2018               | Completed Defects | 16/02/2018      | A77 SB CW, OPP BENNANE SPA                               |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>    |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>    |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>    |         |        |             |                       |                 |                          |                   |                 |  |
| SW82328086-235590025   | 3,368m  | 3,372m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 12/04/2018               | Completed Defects | 15/03/2018      | A77 BOTH CW, 300M STH OF LENDALFOOT                      |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>    |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>    |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>    |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>    |         |        |             |                       |                 |                          |                   |                 |  |
| SW82336916-235633867   | 2,199m  | 2,200m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 10/05/2018               | Completed Defects | 12/04/2018      | A77 SB CW, OPP PEBBLES SPA, STH OF LENDLFOOT             |
| SW82336916-235633868   | 2,133m  | 2,134m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 10/05/2018               | Completed Defects | 12/04/2018      | A77 SB CW, 20M STH OF PEBBLES SPA, STH OF LENDALFOOT     |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>    |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>    |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>      |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>      |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |  |

| Defect Reference   | Start m | End m  | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                       |
|--|---------|--------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|--|
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW82349855-235793433   | 3,423m  | 3,424m | TRAFFIC_SIGNS      | Obscured sign (OBSG)                 | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | A77 NB CW 200M SOUTH OF LENDALFOOT         |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW82352984-235812703   | 3,323m  | 3,324m | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 21/06/2018               | Completed Defects     | 24/05/2018      | SB CW 350M SOUTH OF LENDALFOOT             |
| SW82352984-235812704   | 3,423m  | 3,424m | TRAFFIC_SIGNS      | Obscured sign (OBSG)                 | CAT 2           | 01/01/9999               | Completed Defects     | 02/05/2018      | NB VERGE 200M SOUTH OF LENDALFOOT          |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW80-394061-235954865  | 3,379m  | 3,380m | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 17/08/2018               | Completed Defects     | 16/08/2018      | A77 N/B C/W 250M SOUTH OF LENDALFOOT       |
| SW80-394061-235954864  | 3,258m  | 3,259m | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 17/08/2018               | Completed Defects     | 16/08/2018      | A77 ON CENTRE LINE 40M SOUTH OF LENDALFOOT |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW82332071-445   | 840m    | 720m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-446   | 855m    | 895m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-435   | 425m    | 445m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-438   | 558m    | 638m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-467   | 1,996m  | 2,076m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-468   | 2,122m  | 2,222m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-485   | 3,570m  | 3,571m | TRAFFIC_SIGNS      | Physical condition of post (COPT)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |

| Defect Reference | Start m | End m  | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|--------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82332071-442   | 719m    | 759m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-449   | 970m    | 1,030m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-431   | 310m    | 311m   | TRAFFIC_SIGNS      | Physical condition of post (COPT)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-457   | 1,187m  | 1,267m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-464   | 1,766m  | 1,866m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-471   | 2,654m  | 2,854m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-482   | 3,328m  | 3,329m | TRAFFIC_SIGNS      | Physical condition of post (COPT)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-428   | 193m    | 213m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-441   | 660m    | 740m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-448   | 932m    | 1,012m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-450   | 969m    | 1,069m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-463   | 1,516m  | 1,596m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-465   | 1,805m  | 1,885m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-472   | 2,721m  | 2,801m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-474   | 2,925m  | 3,005m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-429   | 235m    | 334m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-426   | 160m    | 162m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-452   | 1,059m  | 1,139m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-454   | 1,087m  | 1,187m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |

| Defect Reference | Start m | End m  | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|--------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82332071-459   | 1,230m  | 1,290m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-461   | 1,358m  | 1,438m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-476   | 3,155m  | 3,355m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-478   | 3,240m  | 3,220m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-432   | 332m    | 432m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-434   | 414m    | 494m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-439   | 561m    | 641m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-456   | 1,165m  | 1,265m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-479   | 3,261m  | 3,262m | TRAFFIC_SIGNS      | Physical condition of post (COPT)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-481   | 3,302m  | 3,382m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-425   | 141m    | 241m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-427   | 169m    | 180m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-451   | 1,020m  | 1,100m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-453   | 1,094m  | 1,174m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-430   | 242m    | 262m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-458   | 1,197m  | 1,277m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-460   | 1,287m  | 1,367m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-475   | 3,110m  | 3,180m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-477   | 3,197m  | 3,237m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-443   | 751m    | 791m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |



| Defect Reference | Start m | End m  | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|--------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82332071-444   | 792m    | 732m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-436   | 494m    | 495m   | CARRIAGEWAY        | Pothole (POTH)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-437   | 565m    | 665m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-469   | 2,144m  | 2,224m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-470   | 2,338m  | 2,538m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-483   | 3,364m  | 3,365m | TRAFFIC_SIGNS      | Physical condition of post (COPT)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-484   | 3,423m  | 3,623m | FOOTWAY            | Other (OTHR)                         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-440   | 653m    | 753m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-447   | 893m    | 973m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-433   | 364m    | 564m   | FILTER_DRAIN       | Weed growth (WEED)                   | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-455   | 1,162m  | 1,222m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-462   | 1,460m  | 1,540m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-466   | 1,914m  | 1,994m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-473   | 2,888m  | 3,088m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-480   | 3,308m  | 3,388m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |

**Safety Inspection of A77 Ayr South V1 on 30 August 2018**

No defects recorded

**Safety Inspection of A77 Ayr South V1 on 06 September 2018**

No defects recorded

**Safety Inspection of A77 Ayr South V1 on 13 September 2018**

No defects recorded

**Safety Inspection of A77 Ayr South V1 on 20 September 2018**

No defects recorded

**Safety Inspection of A77 Ayr South V1 on 27 September 2018**

No defects recorded

**Safety Inspection of A77 Ayr South V1 on 04 October 2018**

No defects recorded

**Safety Inspection of A77 Ayr South V1 on 11 October 2018**

No defects recorded

**Safety Inspection of A77 Ayr South V1 on 18 October 2018**

No defects recorded

**Safety Inspection of A77 Ayr South V1 on 25 October 2018**

| Defect Reference   | Start m | End m  | Item Type     | Item Detail               | Defect Category | Required Completion Date | Current Status          | Completion Date | Location Description                               |
|--|---------|--------|---------------|---------------------------|-----------------|--------------------------|-------------------------|-----------------|--|
| <i>No defects recorded</i>                                       |         |        |               |                           |                 |                          |                         |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b> |         |        |               |                           |                 |                          |                         |                 |  |
| <i>No defects recorded</i>                                       |         |        |               |                           |                 |                          |                         |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b> |         |        |               |                           |                 |                          |                         |                 |  |
| <i>No defects recorded</i>                                       |         |        |               |                           |                 |                          |                         |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b> |         |        |               |                           |                 |                          |                         |                 |  |
| <i>No defects recorded</i>                                       |         |        |               |                           |                 |                          |                         |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b> |         |        |               |                           |                 |                          |                         |                 |  |
| SW82426764-236231622   | 3,413m  | 3,414m | TRAFFIC_SIGNS | Missing (MISS)            | CAT 2           | 20/12/2018               | Awaiting CCMS Temp Date | 01/01/9999      | A78 NB CW 200M SOUTH OF LENDALFOOT                 |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b> |         |        |               |                           |                 |                          |                         |                 |  |
| <i>No defects recorded</i>                                       |         |        |               |                           |                 |                          |                         |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b> |         |        |               |                           |                 |                          |                         |                 |  |
| <i>No defects recorded</i>                                       |         |        |               |                           |                 |                          |                         |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b> |         |        |               |                           |                 |                          |                         |                 |  |
| <i>No defects recorded</i>                                       |         |        |               |                           |                 |                          |                         |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b> |         |        |               |                           |                 |                          |                         |                 |  |
| <i>No defects recorded</i>                                       |         |        |               |                           |                 |                          |                         |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b> |         |        |               |                           |                 |                          |                         |                 |  |
| <i>No defects recorded</i>                                       |         |        |               |                           |                 |                          |                         |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>  |         |        |               |                           |                 |                          |                         |                 |  |
| SW82427890-236270551   | 2,188m  | 2,189m | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1           | 31/01/2019               | Completed Defects       | 03/01/2019      | A77 SB CW, OUTSIDE BENNANE SPA, STH OF LENDALFOOT  |
| SW82427890-236270553   | 2,159m  | 2,160m | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1           | 31/01/2019               | Completed Defects       | 03/01/2019      | A77 NB CW, OUTSIDE BENANE SPA STH OF LENDALFOOT    |
| SW82427890-236270552   | 2,159m  | 2,160m | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1           | 31/01/2019               | Completed Defects       | 03/01/2019      | A77 ON CL, OUTSIDE BENANNE HOUSE STH OF LENDALFOOT |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>  |         |        |               |                           |                 |                          |                         |                 |  |
| SW82428044-236270550   | 2,216m  | 2,217m | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1           | 11/01/2019               | Completed Defects       | 10/01/2019      | A77 SB CW OUTSIDE BENNANE SHORE HOLIDAY PARK       |
| SW82428044-236270549   | 2,220m  | 2,221m | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1           | 11/01/2019               | Completed Defects       | 10/01/2019      | A77 SB CW OUTSIDE BENNANE SHORE HOLIDAY PARK       |
| SW82428044-236270548   | 2,289m  | 2,290m | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1           | 11/01/2019               | Completed Defects       | 10/01/2019      | A77 SB CW OUTSIDE BENNANE SHORE HOLIDAY PARK       |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>  |         |        |               |                           |                 |                          |                         |                 |  |
| SW82428228-236270547   | 3,420m  | 3,421m | TRAFFIC_SIGNS | Pointing wrong way (RWAY) | CAT 1           | 18/01/2019               | Completed Defects       | 17/01/2019      | A77 200M SOUTH OF LENDALFOOT                       |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>  |         |        |               |                           |                 |                          |                         |                 |  |
| SW82428351-236284320   | 3,338m  | 3,339m | TRAFFIC_SIGNS | Damaged (DAMG)            | CAT 1           | 21/02/2019               | Completed Defects       | 24/01/2019      | A77 SB VERGE, LENDALFOOT 300M STH OF STH GATEWAY   |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>  |         |        |               |                           |                 |                          |                         |                 |  |
| SW82428625-236291431   | 2,191m  | 2,192m | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1           | 01/02/2019               | Completed Defects       | 31/01/2019      | A77 NB CW AT PEBBLES SPA SOUTH OF LENDALFOOT       |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b> |         |        |               |                           |                 |                          |                         |                 |  |
| <i>No defects recorded</i>                                       |         |        |               |                           |                 |                          |                         |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b> |         |        |               |                           |                 |                          |                         |                 |  |
| <i>No defects recorded</i>                                       |         |        |               |                           |                 |                          |                         |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b> |         |        |               |                           |                 |                          |                         |                 |  |
| <i>No defects recorded</i>                                       |         |        |               |                           |                 |                          |                         |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b> |         |        |               |                           |                 |                          |                         |                 |  |
| <i>No defects recorded</i>                                       |         |        |               |                           |                 |                          |                         |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>    |         |        |               |                           |                 |                          |                         |                 |  |
| <i>No defects recorded</i>                                       |         |        |               |                           |                 |                          |                         |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>    |         |        |               |                           |                 |                          |                         |                 |  |
| <i>No defects recorded</i>                                       |         |        |               |                           |                 |                          |                         |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>    |         |        |               |                           |                 |                          |                         |                 |  |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                     |
|--|---------|--------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|--|
| SW82453127-236489182   | 2,093m  | 2,093m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 22/03/2019               | Completed Defects | 21/03/2019      | A77 N/B @ BENNANE CARAVAN PARK           |
| SW82453127-236489183   | 2,169m  | 2,169m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 22/03/2019               | Completed Defects | 21/03/2019      | A77 N/B @ BENNANE CARAVAN PARK           |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>        |         |        |             |                       |                 |                          |                   |                 |  |
| SW82459990-236492549   | 427m    | 428m   | GULLY       | Blockage (BLOK)       | CAT 1           | 25/04/2019               | Completed Defects | 08/04/2019      | A77 N/B OPP SOUTERS INN KIRKOSWALD       |
| <b>11614/85 : CARLETON FISHERIES TO LENDALFOOT BRIDGE</b>            |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>      |         |        |             |                       |                 |                          |                   |                 |  |
| SW82317326-235513694   | 89m     | 0m     | GULLY       | Flooding (FLOD)       | CAT 1           | 01/02/2018               | Completed Defects | 21/02/2018      | LENDALFOOT VILLAGE                       |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>      |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>      |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>      |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b>     |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b>     |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b>     |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b>     |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>        |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>        |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>        |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>        |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>        |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>        |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>        |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>        |         |        |             |                       |                 |                          |                   |                 |  |
| SW82338893-235633868   | 619m    | 619m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 20/04/2018               | Completed Defects | 19/04/2018      | A77 N/B @CARLETON CRES - 50 MTRS N/S/W/T |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>        |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>          |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>          |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description   |
|--|---------|--------|-------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|--|
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |         |        |             |                                      |                 |                          |                       |                 |  |
| SW80-370510-235861176  | 193m    | 194m   | CARRIAGEWAY | Miscellaneous surface Defects (MSRF) | CAT 1           | 26/07/2018               | Completed Defects     | 26/07/2018      | A78 SB CW 600M PRIOR TO LENDALFOOT SOUTH GATEWAY AT WHITE WOODEN COTTAGE |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |         |        |             |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |         |        |             |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |         |        |             |                                      |                 |                          |                       |                 |  |
| SW82380667-235914370   | 19m     | 20m    | GULLY       | Cracked or broken (IBCK)             | CAT 1           | 16/08/2018               | Completed Defects     | 06/08/2018      | A77 NB CW OPPOSITE CARLTON FISHERY                                       |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |         |        |             |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |         |        |             |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |         |        |             |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |         |        |             |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |         |        |             |                                      |                 |                          |                       |                 |  |
| SW80-397303-235954866  | 208m    | 210m   | CARRIAGEWAY | Other (OTHR)                         | CAT 1           | 20/09/2018               | Completed Defects     | 10/09/2018      | A77 OUTSIDE BAY COTTAGE LENDALFOOT                                       |
| SW80-397303-235954867  | 209m    | 211m   | CARRIAGEWAY | Other (OTHR)                         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | A77 S/B C/W OUTSIDE BAY COTTAGE LENDALFOOT                               |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |         |        |             |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>       |         |        |             |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b>    |         |        |             |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b>    |         |        |             |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b>    |         |        |             |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b>    |         |        |             |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>      |         |        |             |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>      |         |        |             |                                      |                 |                          |                       |                 |  |
| SW82420227-236118419   | 204m    | 205m   | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 12/10/2018               | Completed Defects     | 11/10/2018      | A77 SB CW 40M AFTER SOUTH GATEWAY LENDALFOOT                             |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>      |         |        |             |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>      |         |        |             |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>     |         |        |             |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>     |         |        |             |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>     |         |        |             |                                      |                 |                          |                       |                 |  |
| SW82426587-236223178   | 1,040m  | 1,041m | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 16/11/2018               | Completed Defects     | 15/11/2018      | A77 NB CW LENDALFOOT AT BRIDGW OVER RIVER                                |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b>     |         |        |             |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b>     |         |        |             |                                      |                 |                          |                       |                 |  |
| SW82426917-236234300   | 70m     | 71m    | GULLY       | Blockage (BLOK)                      | CAT 1           | 30/11/2018               | Completed Defects     | 29/11/2018      | A77 LENDALFOOT NORTH GATEWAY   |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b>     |         |        |             |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |  |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail              | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description   |
|--|---------|--------|-------------|--------------------------|-----------------|--------------------------|-------------------|-----------------|--|
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b> |         |        |             |                          |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |        |             |                          |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b> |         |        |             |                          |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |        |             |                          |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b> |         |        |             |                          |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |        |             |                          |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>  |         |        |             |                          |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |        |             |                          |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>  |         |        |             |                          |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |        |             |                          |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>  |         |        |             |                          |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |        |             |                          |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>  |         |        |             |                          |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |        |             |                          |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>  |         |        |             |                          |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |        |             |                          |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b> |         |        |             |                          |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |        |             |                          |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b> |         |        |             |                          |                 |                          |                   |                 |  |
| SW82430228-236328527   | 687m    | 688m   | CARRIAGEWAY | Pothole (POTH)           | CAT 1           | 14/03/2019               | Completed Defects | 28/02/2019      | A77 N/B CARLTON CRESCENT LENDAL FOOT                                 |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b> |         |        |             |                          |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |        |             |                          |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b> |         |        |             |                          |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |        |             |                          |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>    |         |        |             |                          |                 |                          |                   |                 |  |
| SW82441664-236344798   | 710m    | 710m   | MANHOLE     | Cracked or broken (IBCK) | 3RD PTY         | 04/04/2019               | Completed Defects | 07/03/2019      | A77 S/B ABOUT 1 MILE BEFORE LENDALFOOT @ 200YDS PEOPLE CROSSING SIGN |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>    |         |        |             |                          |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |        |             |                          |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>    |         |        |             |                          |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |        |             |                          |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>    |         |        |             |                          |                 |                          |                   |                 |  |
| SW82459990-236492546   | 359m    | 360m   | GULLY       | Blockage (BLOK)          | CAT 1           | 25/04/2019               | Completed Defects | 15/04/2019      | A77 N/B 30M PRIOR TO CARLTON CRES LENDAL FOOT                        |
| SW82459990-236492545   | 383m    | 839m   | GULLY       | Blockage (BLOK)          | CAT 1           | 25/04/2019               | Completed Defects | 15/04/2019      | A77 N/B OPP CARLTON CRES LENDAL FOOT                                 |
| SW82459990-236492547   | 336m    | 337m   | GULLY       | Blockage (BLOK)          | CAT 1           | 25/04/2019               | Completed Defects | 15/04/2019      | A77 N/B 40M PRIOR TO CARLTON CRES LENDAL FOOT                        |
| <b>11617/05 : LENDALFOOT BRIDGE TO ARDMILLAN CASTLE</b>          |         |        |             |                          |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>  |         |        |             |                          |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |        |             |                          |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>  |         |        |             |                          |                 |                          |                   |                 |  |
| SW82317471-235518219   | 1,624m  | 1,625m | CARRIAGEWAY | Pothole (POTH)           | CAT 1           | 08/02/2018               | Completed Defects | 09/02/2018      | A77 NB CW, AT STH END OF STRAIDS PASS BENDS                          |
| SW82317471-235518220   | 1,754m  | 1,760m | CARRIAGEWAY | Pothole (POTH)           | CAT 1           | 08/02/2018               | Completed Defects | 09/02/2018      | A77 NB CW, 150M NTH OF STH END OF STRAIDS PASS BENDS                 |
| SW82317471-235518221   | 1,788m  | 1,789m | CARRIAGEWAY | Pothole (POTH)           | CAT 1           | 08/02/2018               | Completed Defects | 09/02/2018      | A77 ON CL, 200M NTH OF END OF STRAIDS PASS BENDS                     |
| SW82317471-235518222   | 1,851m  | 1,853m | CARRIAGEWAY | Pothole (POTH)           | CAT 1           | 08/02/2018               | Completed Defects | 09/02/2018      | A77 NB AND SB CW, 200M NTH OF END OF STRAIDS PASS BENDS              |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>  |         |        |             |                          |                 |                          |                   |                 |  |
| SW82317666-235521317   | 3,097m  | 3,100m | CARRIAGEWAY | Pothole (POTH)           | CAT 1           | 15/02/2018               | Completed Defects | 09/02/2018      | A77 NB CW AND SB CW, STRAIDS PASS STH OF GIRVAN                      |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail    | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description   |
|--|---------|--------|-------------|----------------|-----------------|--------------------------|-------------------|-----------------|--|
| SW82317666-235521318   | 5,186m  | 5,188m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 15/02/2018               | Completed Defects | 08/02/2018      | A77 SB CW, OUTSIDE ARDWELL FARM, STH OF GIRVAN   |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>  |         |        |             |                |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| SW82319037-235539784   | 2,238m  | 2,240m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 08/03/2018               | Completed Defects | 09/02/2018      | A77 NB CW, AT NB LAYBY, STRAIDS PASS   |
| SW82319037-235539787   | 2,020m  | 2,021m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 08/03/2018               | Completed Defects | 09/02/2018      | A77 SB CW, 120M STH OF NB LAYBY STRAIDS PASS   |
| SW82319037-235539791   | 1,798m  | 1,799m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 08/03/2018               | Completed Defects | 09/02/2018      | A77 SB CW, 230M STH OF NB LAYBY, STRAIDS PASS  |
| SW82319037-235539781   | 2,948m  | 2,950m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 08/03/2018               | Completed Defects | 08/02/2018      | A77 SB CW, STRAIDS PASS  |
| SW82319037-235539783   | 2,291m  | 2,295m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 08/03/2018               | Completed Defects | 09/02/2018      | A77 SB CW, 100M NTH OF LAYBY AT STRAIDS PASS ON HILL   |
| SW82319037-235539788   | 1,938m  | 1,939m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 08/03/2018               | Completed Defects | 09/02/2018      | A77 NB CW, 150M STH OF NB LAYBY, STRAIDS PASS  |
| SW82319037-235539790   | 1,843m  | 1,845m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 08/03/2018               | Completed Defects | 09/02/2018      | A77 BOTH CW, 220M STH OF NB LAYBY STRAIDS PASS   |
| SW82319037-235539792   | 1,788m  | 1,744m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 08/03/2018               | Completed Defects | 09/02/2018      | A77 BOTH CW, CLUSTER OF POTHLES OVER 100M STRETCH, 11 HOLES, 250M STH OF NB LAYBY STRAIDS PASS |
| SW82319037-235539785   | 2,156m  | 2,157m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 08/03/2018               | Completed Defects | 09/02/2018      | A77 STRAIDS PASS, STH OF NB LAYBY  |
| SW82319037-235539786   | 2,096m  | 2,097m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 08/03/2018               | Completed Defects | 09/02/2018      | A77 STH OF NB LAYBY STRAIDS PASS, 100M   |
| SW82319037-235539782   | 2,897m  | 2,910m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 08/03/2018               | Completed Defects | 08/02/2018      | A77 BOTH CW, STRAIDS PASS, STH GIRVAN  |
| SW82319037-235539789   | 1,883m  | 1,884m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 08/03/2018               | Completed Defects | 09/02/2018      | A77 NB CW, 200M STH OF NB LAYBY STRAIDS PASS   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| SW82319984-235544954   | 1,643m  | 1,645m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 15/03/2018               | Completed Defects | 16/02/2018      | A77 SB CW, AT STH END OF STRAIDS PASS  |
| SW82319984-235544955   | 4,737m  | 4,738m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 15/03/2018               | Completed Defects | 16/02/2018      | A77 NB CW, 400M STH OF ARDWELL FARM, STH OF GIRVAN   |
| SW82319984-235544953   | 1,581m  | 1,582m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 15/03/2018               | Completed Defects | 16/02/2018      | A77 NB CW, AT STH END OF STRAIDS PASS  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| SW82321955-235548233   | 1,659m  | 1,660m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 22/03/2018               | Completed Defects | 22/02/2018      | NB CW AT SOUTHSIDE OF STRAID PASS SOUTH OF GIRVAN  |
| SW82321955-235548229   | 0m      | 0m     | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 22/03/2018               | Completed Defects | 22/02/2018      | A77 STRAID PASS STH OF GIRVAN  |
| SW82321955-235548227   | 2,040m  | 2,041m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 22/03/2018               | Completed Defects | 22/02/2018      | A77 STRAID PASS  |
| SW82321955-235548230   | 1,899m  | 1,900m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 22/03/2018               | Completed Defects | 22/02/2018      | A77 STRAID PASS STH OF GIRVAN  |

| Defect Reference  | Start m | End m  | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description   |
|---|---------|--------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|--|
| SW82321955-235548232  | 1,730m  | 1,731m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 22/03/2018               | Completed Defects | 22/02/2018      | NB CW SOUTHSIDE OF STRAID PASS   |
| SW82321955-235548228  | 1,942m  | 1,944m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 22/03/2018               | Completed Defects | 22/02/2018      | A77 STRAID PASS  |
| SW82321955-235548234  | 1,652m  | 1,653m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 22/03/2018               | Completed Defects | 22/02/2018      | POTHOLE  |
| SW82321955-235548231  | 1,795m  | 1,796m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 22/03/2018               | Completed Defects | 22/02/2018      | AT pedestrian 200yds sign in straid pass sth of girvan sb cw                         |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| SW82326075-235554325  | 313m    | 314m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 05/04/2018               | Completed Defects | 08/03/2018      | A77 NB CW, 250M NTH OF LENDALFOOT NTH GATEWAY  |
| SW82326075-235554324  | 275m    | 276m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 05/04/2018               | Completed Defects | 08/03/2018      | A77 NB CW, 200M NTH OF LENDALFOOT NTH GATEWAY  |
| SW82326075-235554326  | 2,587m  | 2,588m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 05/04/2018               | Completed Defects | 08/03/2018      | A77 NB CW, 500M NTH OF LAYBY BETWEEN STRAIDS PASS AND KENNEDYS PASS, AT OLD LANDSLIP |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| SW82328086-235590027  | 4,701m  | 4,702m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 12/04/2018               | Completed Defects | 15/03/2018      | A77 SB CW, 300M STH OF ARDWELL FARM  |
| SW82328086-235590026  | 1,646m  | 1,650m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 12/04/2018               | Completed Defects | 25/03/2018      | A77 BOTH CW, MULTIPLE HOLES FROM STH START OF STRAIDS PASS TO 100M NTH OF LAYBY      |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| SW82330474-235608110  | 2,224m  | 2,225m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 19/04/2018               | Completed Defects | 23/03/2018      | A77 NB CW, 20M NTH OF NB LAYBY, STRAIDS PASS   |
| SW82330474-235608106  | 1,833m  | 1,834m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 19/04/2018               | Completed Defects | 23/03/2018      | A77 NB CW, 150M NTH OF STRAIDS PASS STAR   |
| SW82330474-235608107  | 1,892m  | 1,893m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 19/04/2018               | Completed Defects | 23/03/2018      | A77 NB CW, 170M NTH OF STRAIDS PASS BENDS START                                      |
| SW82330474-235608109  | 2,062m  | 2,063m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 19/04/2018               | Completed Defects | 23/03/2018      | A77 NB CW, 50M STH OF NB LAYBY STRAIDS PASS  |
| SW82330474-235608105  | 1,609m  | 1,610m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 19/04/2018               | Completed Defects | 23/03/2018      | A77 SB CW, START OF STRAIDS PASS BENDS   |
| SW82330474-235608111  | 2,238m  | 2,239m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 19/04/2018               | Completed Defects | 23/03/2018      | A77 ON CL, 30M NTH OF NB LAYBY, STRAIDS PASS   |
| SW82330474-235608112  | 2,242m  | 2,243m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 19/04/2018               | Completed Defects | 23/03/2018      | A77 SB CW, 50M TH OF NB LAYBY, STRAIDS PASS  |
| SW82330474-235608108  | 1,888m  | 1,889m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 19/04/2018               | Completed Defects | 23/03/2018      | A77 NB CW, 175M NTH OF START OF STRAIDS PASS BENDS                                   |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| SW82336916-235633869  | 5,559m  | 5,600m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 10/05/2018               | Completed Defects | 12/04/2018      | A77 NB CW, 200M NTH OF ARDWELL FARM, STH OF GIRVAN                                   |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                             |
|--|---------|--------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|--|
| SW82338893-235633870   | 5,162m  | 5,162m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 20/04/2018               | Completed Defects | 19/04/2018      | M77 N/B/ AT ARDWELL FARM N/S/W/T                 |
| SW82338893-235633869   | 5,162m  | 5,162m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 20/04/2018               | Completed Defects | 19/04/2018      | A77 S/B @ ARDWELL FARM O/S/W/T AND N/S/W/T       |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>        |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>          |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>          |         |        |             |                       |                 |                          |                   |                 |  |
| SW82346930-235712684   | 4,625m  | 4,626m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 07/06/2018               | Completed Defects | 10/05/2018      | A77 NB CW 300 SOUTH OF ARDWELL FARM              |
| SW82346930-235712685   | 4,589m  | 4,590m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 07/06/2018               | Completed Defects | 10/05/2018      | A77 SB CW 400 M SOUTH OF ARDWELL FARM            |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |         |        |             |                       |                 |                          |                   |                 |  |
| SW82352984-235812705   | 5,159m  | 5,160m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 21/06/2018               | Completed Defects | 24/05/2018      | A77 NB CW OPPOSITE ARDWELL FARM                  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |         |        |             |                       |                 |                          |                   |                 |  |
| SW80-363687-235858067  | 3,457m  | 2,458m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 12/07/2018               | Completed Defects | 15/06/2018      | A77 CL 299 M SOUTH OF BIG ROCK                   |
| SW80-363687-235858066  | 3,471m  | 3,472m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 12/07/2018               | Completed Defects | 15/06/2018      | A77 CL 300M SOUTH OF BIG ROCK                    |
| SW80-363687-235858068  | 5,201m  | 5,202m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 12/07/2018               | Completed Defects | 19/07/2018      | A77 SB CW 25M NORTH OF ARDWELL FARM              |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |         |        |             |                       |                 |                          |                   |                 |  |
| SW82374127-235892358   | 313m    | 314m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 02/08/2018               | Completed Defects | 01/08/2018      | A77 NB CW 250M PRIOR TO LENDALFOOT NORTH GATEWAY |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |         |        |             |                       |                 |                          |                   |                 |  |
| SW82380667-235914377   | 5,576m  | 5,577m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 16/08/2018               | Completed Defects | 19/07/2018      | A77 NB CW 250M AFTER ARDWELL FARM                |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |         |        |             |                       |                 |                          |                   |                 |  |
| SW82383889-235917502   | 4,970m  | 4,971m | GULLY       | Blockage (BLOK)       | CAT 1           | 23/08/2018               | Completed Defects | 03/08/2018      | A77 SB CW 100M AFTER ARDWELL FARM                |
| SW82383889-235917503   | 3,594m  | 3,595m | GULLY       | Blockage (BLOK)       | CAT 1           | 23/08/2018               | Completed Defects | 03/08/2018      | A77 SB CW KENEDYS PASS                           |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |         |        |             |                       |                 |                          |                   |                 |  |



| Defect Reference   | Start m | End m  | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description  |
|--|---------|--------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| SW80-397303-235954868  | 2,129m  | 2,130m | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 24/08/2018               | Completed Defects     | 23/08/2018      | A77 N/B C/W 500M FROM START OF STRAID PASS NORTH OF LENDAL FOOT |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |   |
| SW82332071-486   | 935m    | 1,015m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-499   | 3,625m  | 3,705m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-502   | 5,145m  | 5,185m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Completed Defects     | 23/11/2018      |   |
| SW82332071-489   | 2,329m  | 2,409m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-496   | 3,540m  | 3,640m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Completed Defects     | 28/02/2019      |   |
| SW82332071-506   | 5,676m  | 5,756m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Completed Defects     | 23/11/2018      |   |
| SW82332071-503   | 5,180m  | 5,260m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Completed Defects     | 23/11/2018      |   |
| SW82332071-505   | 5,486m  | 5,566m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Completed Defects     | 23/11/2018      |   |
| SW82332071-497   | 3,525m  | 3,625m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Completed Defects     | 28/02/2019      |   |
| SW82332071-493   | 3,321m  | 3,401m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-495   | 3,473m  | 3,563m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-507   | 5,824m  | 5,904m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Completed Defects     | 23/11/2018      |   |
| SW82332071-509   | 6,032m  | 6,052m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-488   | 1,399m  | 1,469m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-490   | 2,347m  | 2,427m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-492   | 2,698m  | 2,778m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-494   | 3,456m  | 3,536m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-508   | 5,885m  | 5,895m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-510   | 6,216m  | 6,316m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Completed Defects     | 28/02/2019      |   |

| Defect Reference  | Start m | End m  | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description   |
|---|---------|--------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|--|
| SW82332071-500  | 4,979m  | 4,980m | TRAFFIC_SIGNS      | Physical condition of post (COPT)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-501  | 5,148m  | 5,188m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Completed Defects     | 23/11/2018      |  |
| SW82332071-487  | 918m    | 998m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-491  | 2,668m  | 2,748m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-498  | 3,607m  | 3,687m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-504  | 5,142m  | 5,242m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Completed Defects     | 23/11/2018      |  |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>    |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>   |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>   |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>   |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>   |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>  |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>  |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW82426441-236211988  | 4,191m  | 4,192m | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 09/11/2018               | Completed Defects     | 08/11/2018      | A77 SB CW 100M PRIOR TO KENNEDYS PASS                            |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>  |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW82426587-236223175  | 1,871m  | 1,872m | CARRIAGEWAY        | Pothole (POTH)                       | CAT 1           | 13/12/2018               | Completed Defects     | 15/11/2018      | A77 SB CW AT STRAID PASS 500M NORTH OF LAYBY NORTH OF LENDALFOOT |
| SW82426587-236223176  | 1,859m  | 1,860m | CARRIAGEWAY        | Pothole (POTH)                       | CAT 1           | 13/12/2018               | Completed Defects     | 15/11/2018      | A77 SB CW AT STRAID PASS 550M NORTH OF LAYBY NORTH OF LENDALFOOT |
| SW82426587-236223174  | 3,846m  | 3,846m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | A78 SB CW LAYBY AT KENNEDYS PASS                                 |
| SW82426587-236223177  | 2,048m  | 2,049m | CARRIAGEWAY        | Pothole (POTH)                       | CAT 1           | 13/12/2018               | Completed Defects     | 15/11/2018      | A77 SB CW AT STRAID PASS 600m NORTH OF LAYBY NORTH OF LENDALFOOT |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b>  |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW82426764-236231623  | 239m    | 240m   | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 23/11/2018               | Completed Defects     | 22/11/2018      | A77 NB CW 200M NORTH OF LENDALFOOT                               |
| SW82426764-236231621  | 186m    | 187m   | TRAFFIC_SIGNS      | Missing (MISS)                       | CAT 1           | 20/12/2018               | Completed Defects     | 27/11/2018      | A77 SB CW 200M NORTH OF LENDALFOOT                               |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b>  |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b>  |         |        |                    |                                      |                 |                          |                       |                 |  |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                                  |
|--|---------|--------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|---|
| SW80-427220-236234310  | 1,948m  | 1,949m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 03/01/2019               | Completed Defects | 06/12/2018      | A77 NB CW AT STRAID PASS                              |
| SW80-427220-236234311  | 4,651m  | 4,652m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 03/01/2019               | Completed Defects | 06/12/2018      | A77 SB CW 150M SOUTH OF ARDWELL FARM                  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| SW82427366-236262608   | 2,027m  | 2,028m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 10/01/2019               | Completed Defects | 13/12/2018      | A77 ON CL, STRAIDS PASS, 50M STH OF LAYBY             |
| SW82427366-236262607   | 190m    | 191m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 10/01/2019               | Completed Defects | 13/12/2018      | A77 SB CW, LENDALFOOT NTH GATEWAY                     |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| SW82427527-236264605   | 4,148m  | 4,149m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 17/01/2019               | Completed Defects | 12/01/2019      | A77 SB CW 150M PRIOR TO KENNEDYS PASS AT SPEED CAMERA |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| SW82428228-236270546   | 4,898m  | 4,899m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 18/01/2019               | Completed Defects | 17/01/2019      | A77 SB CW 150M SOUTH OF ARDWELL FARM                  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| SW82428351-236284321   | 47m     | 48m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 21/02/2019               | Completed Defects | 06/02/2019      | A77 NB CW, 80M STH OF LENDALFOOT NTH GATEWAY          |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| SW82459990-236492548   | 1,030m  | 1,031m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 29/03/2019               | Completed Defects | 28/03/2019      | A77 S/B OPP LAY BY PRIOR TO LENDAL FOOT               |
| <b>11620/05 : A714 SHALLOCHPARK ROUNDABOUT</b>                   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |

| Defect Reference   | Start<br>m | End<br>m | Item Type | Item Detail | Defect<br>Category | Required<br>Completion Date | Current Status | Completion<br>Date | Location Description |
|--|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b>     |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>          |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>          |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>       |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |

| Defect Reference   | Start<br>m | End<br>m | Item Type     | Item Detail             | Defect<br>Category | Required<br>Completion Date | Current Status       | Completion<br>Date | Location Description                           |
|--|------------|----------|---------------|-------------------------|--------------------|-----------------------------|----------------------|--------------------|--|
| <i>No defects recorded</i>   |            |          |               |                         |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>    |            |          |               |                         |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |               |                         |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>    |            |          |               |                         |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |               |                         |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>    |            |          |               |                         |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |               |                         |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>    |            |          |               |                         |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |               |                         |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>   |            |          |               |                         |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |               |                         |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>   |            |          |               |                         |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |               |                         |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>   |            |          |               |                         |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |               |                         |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b>   |            |          |               |                         |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |               |                         |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b>   |            |          |               |                         |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |               |                         |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b>   |            |          |               |                         |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |               |                         |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b>   |            |          |               |                         |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |               |                         |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b>   |            |          |               |                         |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |               |                         |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b>   |            |          |               |                         |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |               |                         |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>    |            |          |               |                         |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |               |                         |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>    |            |          |               |                         |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |               |                         |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>    |            |          |               |                         |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |               |                         |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>    |            |          |               |                         |                    |                             |                      |                    |  |
| SW82428351-236284322   | 126m       | 127m     | TRAFFIC_SIGNS | Obscured sign<br>(OBSG) | 3RD PTY            | 21/02/2019                  | Completed<br>Defects | 24/01/2019         | A77 SHALLOWPARK RBT, OPP<br>NB ENTRANCE TO RBT |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>    |            |          |               |                         |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |               |                         |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b>   |            |          |               |                         |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |               |                         |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b>   |            |          |               |                         |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |               |                         |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b>   |            |          |               |                         |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |               |                         |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b>   |            |          |               |                         |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |               |                         |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>      |            |          |               |                         |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |               |                         |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>      |            |          |               |                         |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |               |                         |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>      |            |          |               |                         |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |               |                         |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>      |            |          |               |                         |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |               |                         |                    |                             |                      |                    |  |
| <b>11620/07 : A714 SHALLOCHPARK RBT TO B734 KIRKPATRICK ST RBT</b> |            |          |               |                         |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>    |            |          |               |                         |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |               |                         |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>    |            |          |               |                         |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |               |                         |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>    |            |          |               |                         |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |               |                         |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>    |            |          |               |                         |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |               |                         |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b>   |            |          |               |                         |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |               |                         |                    |                             |                      |                    |  |

| Defect Reference   | Start<br>m | End<br>m | Item Type | Item Detail | Defect<br>Category | Required<br>Completion Date | Current Status | Completion<br>Date | Location Description |
|--|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b>     |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b>     |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b>     |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>          |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>          |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>       |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |

| Defect Reference  | Start<br>m | End<br>m | Item Type   | Item Detail              | Defect<br>Category | Required<br>Completion Date | Current Status       | Completion<br>Date | Location Description                 |
|---|------------|----------|-------------|--------------------------|--------------------|-----------------------------|----------------------|--------------------|--------------------------------------|
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b> |            |          |             |                          |                    |                             |                      |                    |                                      |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b> |            |          |             |                          |                    |                             |                      |                    |                                      |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>   |            |          |             |                          |                    |                             |                      |                    |                                      |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>   |            |          |             |                          |                    |                             |                      |                    |                                      |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>   |            |          |             |                          |                    |                             |                      |                    |                                      |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>   |            |          |             |                          |                    |                             |                      |                    |                                      |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| SW82426917-236234301  | 412m       | 413m     | CARRIAGEWAY | Pothole VIAFIX<br>(POTV) | CAT 1              | 30/11/2018                  | Completed<br>Defects | 29/11/2018         | A77 SB CW OUTSIDE CAR<br>WASH GIRVAN |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>   |            |          |             |                          |                    |                             |                      |                    |                                      |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>   |            |          |             |                          |                    |                             |                      |                    |                                      |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>   |            |          |             |                          |                    |                             |                      |                    |                                      |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>   |            |          |             |                          |                    |                             |                      |                    |                                      |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>   |            |          |             |                          |                    |                             |                      |                    |                                      |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>     |            |          |             |                          |                    |                             |                      |                    |                                      |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>     |            |          |             |                          |                    |                             |                      |                    |                                      |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>     |            |          |             |                          |                    |                             |                      |                    |                                      |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>     |            |          |             |                          |                    |                             |                      |                    |                                      |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <b>11620/44 : WESLEY ROAD TO DUFF STREET</b>                      |            |          |             |                          |                    |                             |                      |                    |                                      |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>   |            |          |             |                          |                    |                             |                      |                    |                                      |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>   |            |          |             |                          |                    |                             |                      |                    |                                      |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |                                      |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>   |            |          |             |                          |                    |                             |                      |                    |                                      |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |                                      |

| Defect Reference   | Start<br>m | End<br>m | Item Type | Item Detail | Defect<br>Category | Required<br>Completion Date | Current Status | Completion<br>Date | Location Description |
|--|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b>     |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b>     |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b>     |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b>     |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>          |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>          |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>       |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |            |          |           |             |                    |                             |                |                    |                      |



| Defect Reference | Start m | End m | Item Type   | Item Detail                      | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|-------|-------------|----------------------------------|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82332071-540   | 197m    | 207m  | CARRIAGEWAY | Patch - material cracking (PMCK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-539   | 148m    | 149m  | CARRIAGEWAY | Cracking around ironwork (CKIR)  | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |

**Safety Inspection of A77 Ayr South V1 on 06 September 2018**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 13 September 2018**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 20 September 2018**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 27 September 2018**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 04 October 2018**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 11 October 2018**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 18 October 2018**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 25 October 2018**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 01 November 2018**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 08 November 2018**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 15 November 2018**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 22 November 2018**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 29 November 2018**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 06 December 2018**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 13 December 2018**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 20 December 2018**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 27 December 2018**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 03 January 2019**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 10 January 2019**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 17 January 2019**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 24 January 2019**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 31 January 2019**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 07 February 2019**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 14 February 2019**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 21 February 2019**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 28 February 2019**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 07 March 2019**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 14 March 2019**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 21 March 2019**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 28 March 2019**

*No defects recorded*

| Defect Reference  | Start<br>m | End<br>m | Item Type   | Item Detail              | Defect<br>Category | Required<br>Completion Date | Current Status       | Completion<br>Date | Location Description                           |
|---|------------|----------|-------------|--------------------------|--------------------|-----------------------------|----------------------|--------------------|--|
| <b>11620/59 : STUMPY CORNER JUNCTION TO END OF GRAVEYARD</b>  |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 04 January 2018      |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 11 January 2018      |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 18 January 2018      |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 25 January 2018      |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 01 February 2018     |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 08 February 2018     |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 15 February 2018     |            |          |             |                          |                    |                             |                      |                    |  |
| SW82319984-235544956  | 180m       | 181m     | CARRIAGEWAY | Pothole<br>(POTH)        | CAT 1              | 15/03/2018                  | Completed<br>Defects | 15/02/2018         | A77 SB CW, GIRVAN 400M<br>NTH OF STUMPY CORNER |
| Safety Inspection of A77 Ayr South V1 on 22 February 2018     |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 01 March 2018        |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 08 March 2018        |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 15 March 2018        |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 22 March 2018        |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 29 March 2018        |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 05 April 2018        |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 12 April 2018        |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 19 April 2018        |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 26 April 2018        |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 03 May 2018          |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 10 May 2018          |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 17 May 2018          |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 24 May 2018          |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 31 May 2018          |            |          |             |                          |                    |                             |                      |                    |  |
| SW82356191-235816777  | 106m       | 107m     | CARRIAGEWAY | Pothole VIAFIX<br>(POTV) | CAT 1              | 28/06/2018                  | Completed<br>Defects | 31/05/2018         | A77 NB CW OUTSIDE<br>MOBILITY SHOP GIRVAN      |
| Safety Inspection of A77 Ayr South V1 on 07 June 2018         |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 14 June 2018         |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 21 June 2018         |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |  |
| Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018 |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 28 June 2018         |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 05 July 2018         |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 12 July 2018         |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 19 July 2018         |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 26 July 2018         |            |          |             |                          |                    |                             |                      |                    |  |

| Defect Reference   | Start m | End m | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                   |
|--|---------|-------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|--|
| SW82383889-235917500   | 47m     | 48m   | MANHOLE            | Rocking under load (IRLD)            | 3RD PTY         | 23/08/2018               | Completed Defects     | 08/11/2018      | A77 SB CW OUTSIDE PAULS BARBERS GIRVAN |
| SW82383889-235917501   | 43m     | 44m   | MANHOLE            | Rocking under load (IRLD)            | 3RD PTY         | 23/08/2018               | Completed Defects     | 26/08/2018      | A77 NB CW OUTSIDE PAULS BARBERS GIRVAN |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |         |       |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |         |       |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |         |       |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |         |       |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |                    |                                      |                 |                          |                       |                 |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |         |       |                    |                                      |                 |                          |                       |                 |  |
| SW82332071-547   | 80m     | 120m  | CARRIAGEWAY        | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-549   | 96m     | 180m  | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-545   | 25m     | 50m   | CARRIAGEWAY        | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-550   | 99m     | 180m  | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-544   | 17m     | 27m   | CARRIAGEWAY        | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-546   | 74m     | 100m  | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-548   | 103m    | 180m  | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>       |         |       |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b>    |         |       |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b>    |         |       |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b>    |         |       |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b>    |         |       |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>      |         |       |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>      |         |       |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>      |         |       |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>      |         |       |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>     |         |       |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>     |         |       |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>     |         |       |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b>     |         |       |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b>     |         |       |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b>     |         |       |                    |                                      |                 |                          |                       |                 |  |

| Defect Reference  | Start m | End m | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                |
|---|---------|-------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|-------------------------------------|
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>   |         |       |             |                       |                 |                          |                   |                 |                                     |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>   |         |       |             |                       |                 |                          |                   |                 |                                     |
| SW82428044-236270554  | 106m    | 107m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 11/01/2019               | Completed Defects | 10/01/2019      | A77 SB CW OUTSIDE SHAKE FIT GIRVAN  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>   |         |       |             |                       |                 |                          |                   |                 |                                     |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>   |         |       |             |                       |                 |                          |                   |                 |                                     |
| SW82428351-236284323  | 13m     | 14m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 21/02/2019               | Completed Defects | 25/01/2019      | A77 SB CW STUMBY CORNER GIRVAN      |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>   |         |       |             |                       |                 |                          |                   |                 |                                     |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>     |         |       |             |                       |                 |                          |                   |                 |                                     |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>     |         |       |             |                       |                 |                          |                   |                 |                                     |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>     |         |       |             |                       |                 |                          |                   |                 |                                     |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>     |         |       |             |                       |                 |                          |                   |                 |                                     |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <b>11620/65 : END OF GRAVEYARD TO JUNCTION MONTGOMERIE STREET</b> |         |       |             |                       |                 |                          |                   |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>   |         |       |             |                       |                 |                          |                   |                 |                                     |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>   |         |       |             |                       |                 |                          |                   |                 |                                     |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>   |         |       |             |                       |                 |                          |                   |                 |                                     |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>   |         |       |             |                       |                 |                          |                   |                 |                                     |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>     |         |       |             |                       |                 |                          |                   |                 |                                     |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>     |         |       |             |                       |                 |                          |                   |                 |                                     |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>     |         |       |             |                       |                 |                          |                   |                 |                                     |
| SW82328086-235590032  | 123m    | 126m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 12/04/2018               | Completed Defects | 15/03/2018      | A77 NB CW, OUTSIDE GRAVEYARD GIRVAN |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>     |         |       |             |                       |                 |                          |                   |                 |                                     |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>     |         |       |             |                       |                 |                          |                   |                 |                                     |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                     |

| Defect Reference   | Start m | End m | Item Type          | Item Detail                       | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                      |
|--|---------|-------|--------------------|-----------------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>        |         |       |                    |                                   |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                    |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>        |         |       |                    |                                   |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                    |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>        |         |       |                    |                                   |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                    |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>        |         |       |                    |                                   |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                    |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>          |         |       |                    |                                   |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                    |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>          |         |       |                    |                                   |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                    |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |         |       |                    |                                   |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                    |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |         |       |                    |                                   |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                    |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |         |       |                    |                                   |                 |                          |                       |                 |   |
| SW82356191-235816778   | 98m     | 99m   | CARRIAGEWAY        | Pothole VIAFIX (POTV)             | CAT 1           | 28/06/2018               | Completed Defects     | 31/05/2018      | A77 NB CL OUTSIDE GIRVAN CEMETRY          |
| SW82356191-235816779   | 97m     | 98m   | CARRIAGEWAY        | Pothole VIAFIX (POTV)             | CAT 1           | 28/06/2018               | Completed Defects     | 31/05/2018      | A77 NB CW OUTSIDE 5 OLD ST GIRVAN CEMETRY |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |         |       |                    |                                   |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                    |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |         |       |                    |                                   |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                    |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |         |       |                    |                                   |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                    |                                   |                 |                          |                       |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |         |       |                    |                                   |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                    |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |         |       |                    |                                   |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                    |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |         |       |                    |                                   |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                    |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |         |       |                    |                                   |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                    |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |         |       |                    |                                   |                 |                          |                       |                 |   |
| SW82380667-235914378   | 48m     | 49m   | CARRIAGEWAY        | Pothole VIAFIX (POTV)             | CAT 1           | 16/08/2018               | Completed Defects     | 19/07/2018      | A77 SB CW OUTSIDE GIRVAN CEMATRY          |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |         |       |                    |                                   |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                    |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |         |       |                    |                                   |                 |                          |                       |                 |   |
| SW80-387291-235943986  | 102m    | 103m  | CARRIAGEWAY        | Pothole VIAFIX (POTV)             | CAT 1           | 30/08/2018               | Completed Defects     | 02/08/2018      | A77 NB CW OUTSIDE GIRVAN CEMETRY          |
| SW80-387291-235943987  | 102m    | 103m  | CARRIAGEWAY        | Pothole VIAFIX (POTV)             | CAT 1           | 30/08/2018               | Completed Defects     | 02/08/2018      | A77 NB OUTSIDE GIRVAN CEMETREY            |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |         |       |                    |                                   |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                    |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |         |       |                    |                                   |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                    |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |         |       |                    |                                   |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                    |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>       |         |       |                    |                                   |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                    |                                   |                 |                          |                       |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |         |       |                    |                                   |                 |                          |                       |                 |   |
| SW82332071-552   | 9m      | 89m   | CARRIAGEWAY        | Localised cracking (LOCK)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-551   | 9m      | 100m  | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |

| Defect Reference  | Start m | End m | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                |
|---|---------|-------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|-------------------------------------|
| SW82332071-553  | 91m     | 150m  | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                     |
| SW82332071-555  | 101m    | 150m  | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                     |
| SW82332071-554  | 101m    | 150m  | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b> |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| No defects recorded   |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b> |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| No defects recorded   |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b> |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| No defects recorded   |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b> |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| No defects recorded   |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>   |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| No defects recorded   |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>   |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| No defects recorded   |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>   |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| No defects recorded   |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>   |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| No defects recorded   |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>  |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| No defects recorded   |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>  |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| No defects recorded   |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>  |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| No defects recorded   |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b>  |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| No defects recorded   |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b>  |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| No defects recorded   |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b>  |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| No defects recorded   |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b>  |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| No defects recorded   |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b>  |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| No defects recorded   |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b>  |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| No defects recorded   |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>   |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| No defects recorded   |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>   |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| No defects recorded   |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>   |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| No defects recorded   |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>   |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| SW82428351-236284324  | 120m    | 121m  | CARRIAGEWAY        | Pothole (POTH)                       | CAT 1           | 21/02/2019               | Completed Defects     | 06/02/2019      | A77 CL, GIRVAN, OUTSIDE GRAVEYARD   |
| SW82428351-236284325  | 113m    | 114m  | CARRIAGEWAY        | Pothole (POTH)                       | CAT 1           | 21/02/2019               | Completed Defects     | 06/02/2019      | A77 ON CL, GIRVAN OUTSIDE GRAVEYARD |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>   |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| No defects recorded   |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b>  |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| No defects recorded   |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b>  |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| No defects recorded   |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b>  |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| No defects recorded   |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b>  |         |       |                    |                                      |                 |                          |                       |                 |                                     |
| No defects recorded   |         |       |                    |                                      |                 |                          |                       |                 |                                     |

| Defect Reference  | Start m | End m | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description               |
|---|---------|-------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|------------------------------------|
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b> |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>                                    |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b> |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>                                    |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b> |         |       |             |                       |                 |                          |                   |                 |                                    |
| <i>No defects recorded</i>                                    |         |       |             |                       |                 |                          |                   |                 |                                    |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b> |         |       |             |                       |                 |                          |                   |                 |                                    |
| SW82459990-236492543  | 100m    | 101m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 29/03/2019               | Completed Defects | 28/03/2019      | A77 S/B OPP NO 5 OLD STREET GIRVAN |
| SW82459990-236492544  | 44m     | 45m   | GULLY       | Blockage (BLOK)       | CAT 1           | 25/04/2019               | Completed Defects | 09/04/2019      | A77 S/B OPP CEMETRY GIRVAN         |

#### 11620/72 : JUNCTION MONTGOMERIE STREET TO RAILWAY BRIDGE

|  |  |  |  |  |  |  |  |  |  |
|--|--|--|--|--|--|--|--|--|--|
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>      |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>      |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>      |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>      |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b>     |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b>     |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b>     |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b>     |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>        |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>        |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>        |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>        |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>        |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>        |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>        |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>        |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>        |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>          |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>          |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |

| Defect Reference   | Start m | End m | Item Type                 | Item Detail                       | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                                |
|--|---------|-------|---------------------------|-----------------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |         |       |                           |                                   |                 |                          |                       |                 |   |
| No defects recorded  |         |       |                           |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |         |       |                           |                                   |                 |                          |                       |                 |   |
| No defects recorded  |         |       |                           |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |         |       |                           |                                   |                 |                          |                       |                 |   |
| No defects recorded  |         |       |                           |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |         |       |                           |                                   |                 |                          |                       |                 |   |
| No defects recorded  |         |       |                           |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |         |       |                           |                                   |                 |                          |                       |                 |   |
| SW82383889-235917499   | 18m     | 19m   | ROAD_MARKINGS<br>_LONG    | Wear (for example erosion) (WEAR) | CAT 1           | 23/08/2018               | Completed Defects     | 06/09/2018      | A77 PEDESTRIAN LIGHTS OUTSIDE ASDA IN GIRVAN        |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |         |       |                           |                                   |                 |                          |                       |                 |   |
| No defects recorded  |         |       |                           |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |         |       |                           |                                   |                 |                          |                       |                 |   |
| No defects recorded  |         |       |                           |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |         |       |                           |                                   |                 |                          |                       |                 |   |
| No defects recorded  |         |       |                           |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |         |       |                           |                                   |                 |                          |                       |                 |   |
| No defects recorded  |         |       |                           |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>       |         |       |                           |                                   |                 |                          |                       |                 |   |
| No defects recorded  |         |       |                           |                                   |                 |                          |                       |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |         |       |                           |                                   |                 |                          |                       |                 |   |
| SW82332071-557   | 116m    | 136m  | FOOTWAY                   | Other (OTHR)                      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-558   | 167m    | 200m  | FOOTWAY                   | Other (OTHR)                      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-559   | 208m    | 248m  | ROAD_MARKINGS<br>_LONG    | Wear (for example erosion) (WEAR) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-560   | 272m    | 280m  | CARRIAGEWAY               | Localised cracking (LOCK)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-556   | 96m     | 126m  | FOOTWAY                   | Other (OTHR)                      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b>    |         |       |                           |                                   |                 |                          |                       |                 |   |
| SW80-403929-235984879  | 5m      | 6m    | ROAD_MARKINGS<br>_LONG    | Wear (for example erosion) (WEAR) | CAT 1           | 07/09/2018               | Completed Defects     | 06/09/2018      | A77 N/B C/W PEDESTRIAN CROSSING OUTSIDE ASDA GIRVAN |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b>    |         |       |                           |                                   |                 |                          |                       |                 |   |
| No defects recorded  |         |       |                           |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b>    |         |       |                           |                                   |                 |                          |                       |                 |   |
| No defects recorded  |         |       |                           |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b>    |         |       |                           |                                   |                 |                          |                       |                 |   |
| No defects recorded  |         |       |                           |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>      |         |       |                           |                                   |                 |                          |                       |                 |   |
| No defects recorded  |         |       |                           |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>      |         |       |                           |                                   |                 |                          |                       |                 |   |
| No defects recorded  |         |       |                           |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>      |         |       |                           |                                   |                 |                          |                       |                 |   |
| No defects recorded  |         |       |                           |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>      |         |       |                           |                                   |                 |                          |                       |                 |   |
| SW82425931-236166523   | 36m     | 38m   | ROAD_MARKINGS<br>_HATCHED | Wear (for example erosion) (WEAR) | CAT 1           | 22/11/2018               | Completed Defects     | 24/02/2019      | A77 SB CW AT TRAFFIC LIGHTS OUTSIDE OF ASDA GIRVAN  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>     |         |       |                           |                                   |                 |                          |                       |                 |   |
| No defects recorded  |         |       |                           |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>     |         |       |                           |                                   |                 |                          |                       |                 |   |
| No defects recorded  |         |       |                           |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>     |         |       |                           |                                   |                 |                          |                       |                 |   |



| Defect Reference | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|------------------|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|
|------------------|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 22 November 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 29 November 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 06 December 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 13 December 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 20 December 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 27 December 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 03 January 2019**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 10 January 2019**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 17 January 2019**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 24 January 2019**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 31 January 2019**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 07 February 2019**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 14 February 2019**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 21 February 2019**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 28 February 2019**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 07 March 2019**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 14 March 2019**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 21 March 2019**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 28 March 2019**  
*No defects recorded*

**11620/90 : RAILWAY BRIDGE TO BRIDGEMILL ROUNDABOUT**

**Safety Inspection of A77 Ayr South V1 on 04 January 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 11 January 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 18 January 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 25 January 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 01 February 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 08 February 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 15 February 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 22 February 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 01 March 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 08 March 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 15 March 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 22 March 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 29 March 2018**  
*No defects recorded*

| Defect Reference   | Start<br>m | End<br>m | Item Type   | Item Detail                     | Defect<br>Category | Required<br>Completion Date | Current Status           | Completion<br>Date | Location Description |
|--|------------|----------|-------------|---------------------------------|--------------------|-----------------------------|--------------------------|--------------------|----------------------|
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>        |            |          |             |                                 |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                 |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>        |            |          |             |                                 |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                 |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>        |            |          |             |                                 |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                 |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>        |            |          |             |                                 |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                 |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>          |            |          |             |                                 |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                 |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>          |            |          |             |                                 |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                 |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |            |          |             |                                 |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                 |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |            |          |             |                                 |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                 |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |            |          |             |                                 |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                 |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |            |          |             |                                 |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                 |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |            |          |             |                                 |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                 |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |            |          |             |                                 |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                 |                    |                             |                          |                    |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |            |          |             |                                 |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                 |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |            |          |             |                                 |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                 |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |            |          |             |                                 |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                 |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |            |          |             |                                 |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                 |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |            |          |             |                                 |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                 |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |            |          |             |                                 |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                 |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |            |          |             |                                 |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                 |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |            |          |             |                                 |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                 |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |            |          |             |                                 |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                 |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |            |          |             |                                 |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                 |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>       |            |          |             |                                 |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                 |                    |                             |                          |                    |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |            |          |             |                                 |                    |                             |                          |                    |                      |
| SW82332071-561   | 97m        | 105m     | CARRIAGEWAY | Localised<br>cracking<br>(LOCK) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b>    |            |          |             |                                 |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                 |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b>    |            |          |             |                                 |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                 |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b>    |            |          |             |                                 |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                 |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b>    |            |          |             |                                 |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                 |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>      |            |          |             |                                 |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                 |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>      |            |          |             |                                 |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                 |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>      |            |          |             |                                 |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                 |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>      |            |          |             |                                 |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                 |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>     |            |          |             |                                 |                    |                             |                          |                    |                      |

| Defect Reference | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|------------------|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|
|------------------|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|

*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 08 November 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 15 November 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 22 November 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 29 November 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 06 December 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 13 December 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 20 December 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 27 December 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 03 January 2019**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 10 January 2019**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 17 January 2019**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 24 January 2019**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 31 January 2019**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 07 February 2019**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 14 February 2019**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 21 February 2019**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 28 February 2019**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 07 March 2019**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 14 March 2019**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 21 March 2019**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 28 March 2019**  
*No defects recorded*

**11622/05 : BRIDGEMILL ROUNDABOUT**

**Safety Inspection of A77 Ayr South V1 on 04 January 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 11 January 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 18 January 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 25 January 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 01 February 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 08 February 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 15 February 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 22 February 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 01 March 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 08 March 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 15 March 2018**  
*No defects recorded*

| Defect Reference   | Start<br>m | End<br>m | Item Type | Item Detail | Defect<br>Category | Required<br>Completion Date | Current Status | Completion<br>Date | Location Description |
|--|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>          |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>          |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>       |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |

| Defect Reference   | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|--|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|
| <i>No defects recorded</i>                                       |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>                                       |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>                                       |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>                                       |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>                                       |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>                                       |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>                                       |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>                                       |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>                                       |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>                                       |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>                                       |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>                                       |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>                                       |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>                                       |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>                                       |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>                                       |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>                                       |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>                                       |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>                                       |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>    |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>                                       |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>    |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>                                       |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>    |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>                                       |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>    |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>                                       |         |       |           |             |                 |                          |                |                 |                      |

**11622/07 : BRIDGEMILL ROUNDABOUT TO DIPPLE,FACTORY ENTRANCE**

|   |        |        |             |                |       |            |                   |            |  |
|---|--------|--------|-------------|----------------|-------|------------|-------------------|------------|--|
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b> |        |        |             |                |       |            |                   |            |  |
| SW82317326-235513699  | 2,790m | 2,792m | CARRIAGEWAY | Pothole (POTH) | CAT 1 | 01/02/2018 | Completed Defects | 27/02/2018 | northbound carriageay opposite burnside farm north of girvan |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b> |        |        |             |                |       |            |                   |            |  |
| <i>No defects recorded</i>                                      |        |        |             |                |       |            |                   |            |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b> |        |        |             |                |       |            |                   |            |  |
| SW82317666-235521320  | 2,798m | 2,800m | CARRIAGEWAY | Pothole (POTH) | CAT 1 | 15/02/2018 | Completed Defects | 27/02/2018 | A77 NB CW, OPPOSITE BURNSIDE COTTAGE, NTH OF GIRVAN          |
| SW82317666-235521321  | 4,060m | 4,061m | CARRIAGEWAY | Pothole (POTH) | CAT 1 | 15/02/2018 | Completed Defects | 26/02/2018 | A77 SB CW, OPPOSITE DIPPLE FACTORY NTH OF GIRVAN             |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b> |        |        |             |                |       |            |                   |            |  |
| SW82317793-235529555  | 2,362m | 2,365m | CARRIAGEWAY | Pothole (POTH) | CAT 1 | 22/02/2018 | Completed Defects | 26/02/2018 | A77 SB CW, 400M STH OF BURNSIDE COTTAGE, NTH OF GIRVAN       |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail                   | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                                      |
|--|---------|--------|-------------|-------------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| SW82317793-235529554   | 2,423m  | 2,425m | CARRIAGEWAY | Pothole (POTH)                | CAT 1           | 22/02/2018               | Completed Defects     | 26/02/2018      | A77 SB CW, 300M STH OF BURNSIDE COTTAGE, NTH OF GIRVAN    |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b> |         |        |             |                               |                 |                          |                       |                 |   |
| SW82318129-235532268   | 2,904m  | 3,104m | CARRIAGEWAY | Pothole (POTH)                | CAT 1           | 01/03/2018               | Completed Defects     | 01/02/2018      | A77 AROUND BURNSIDE COTTAGE                               |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b> |         |        |             |                               |                 |                          |                       |                 |   |
| SW82319037-235539780   | 4,217m  | 4,019m | CARRIAGEWAY | Pothole (POTH)                | CAT 1           | 08/03/2018               | Completed Defects     | 08/02/2018      | A77 SB CW, ST BUS STOP OPP DIPPLE FACTORY, NTH OF GIRVAN  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b> |         |        |             |                               |                 |                          |                       |                 |   |
| SW82319984-235544957   | 3,009m  | 3,010m | CARRIAGEWAY | Pothole (POTH)                | CAT 1           | 15/03/2018               | Completed Defects     | 16/02/2018      | A77 SB CW, OUTSIDE BURNSIDE COTTAGE                       |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b> |         |        |             |                               |                 |                          |                       |                 |   |
| SW82321955-235548226   | 3,010m  | 3,012m | CARRIAGEWAY | Pothole (POTH)                | CAT 1           | 22/03/2018               | Completed Defects     | 26/02/2018      | just prior to burnside farm a77 between girvan and dipple |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>    |         |        |             |                               |                 |                          |                       |                 |   |
| SW82323945-235550797   | 1,332m  | 1,334m | CARRIAGEWAY | Debris in traffic Lane (DBTL) | CAT 1           | 29/03/2018               | Completed Defects     | 01/03/2018      | A77 NB CW, 1300M NTH OF BRIDGEMILL RBT, NTH OF GIRVAN     |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>    |         |        |             |                               |                 |                          |                       |                 |   |
| SW82326075-235554307   | 1,566m  | 1,568m | CARRIAGEWAY | Pothole (POTH)                | CAT 1           | 05/04/2018               | Completed Defects     | 08/03/2018      | A77 NB CW, 1500M NTH OF BRIDGEMILL RBT, NTH OF GIRVAN     |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>    |         |        |             |                               |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                               |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>    |         |        |             |                               |                 |                          |                       |                 |   |
| SW82330474-235608124   | 2,891m  | 2,991m | FOOTWAY     | Excessive muck (MUCK)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | A77 NB FOOTWAY, BURNSIDE COTTAGES FOOTPATH                |
| SW82330474-235608113   | 2,901m  | 2,903m | CARRIAGEWAY | Pothole (POTH)                | CAT 1           | 19/04/2018               | Completed Defects     | 23/03/2018      | A77 NB CW, OUTSIDE THE CURRAGH, NTH OF GIRVAN             |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>    |         |        |             |                               |                 |                          |                       |                 |   |
| SW80-332117-235613706  | 2,904m  | 2,905m | CARRIAGEWAY | Pothole (POTH)                | CAT 1           | 26/04/2018               | Completed Defects     | 29/03/2018      | A77 NB CW, OPPOSITE BURNSIDE COTTAGES                     |
| SW80-332117-235613705  | 2,908m  | 2,909m | CARRIAGEWAY | Pothole (POTH)                | CAT 1           | 26/04/2018               | Completed Defects     | 29/03/2018      | A77 SB CW, 200M NTH OF BURNSIDE COTTAGES                  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>    |         |        |             |                               |                 |                          |                       |                 |   |
| SW82334882-235613709   | 2,813m  | 0m     | CARRIAGEWAY | Pothole (POTH)                | CAT 1           | 06/04/2018               | Completed Defects     | 06/04/2018      | A77 N/B OPP BURNSIDE FARM                                 |
| SW82334882-235613706   | 3,009m  | 0m     | CARRIAGEWAY | Pothole VIAFIX (POTV)         | CAT 1           | 06/04/2018               | Completed Defects     | 05/04/2018      | A77 S/B AT THE CURRAGH                                    |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>    |         |        |             |                               |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                               |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>    |         |        |             |                               |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                               |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>    |         |        |             |                               |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                               |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>      |         |        |             |                               |                 |                          |                       |                 |   |
| SW82344114-235554294   | 2,424m  | 0m     | CARRIAGEWAY | Pothole (POTH)                | CAT 1           | 31/05/2018               | Completed Defects     | 31/05/2018      | A77 SB 200M STH OF BURNSIDE COTTAGES LANE 1 NS WT         |
| SW82344114-235554292   | 2,431m  | 0m     | CARRIAGEWAY | Pothole (POTH)                | CAT 1           | 31/05/2018               | Completed Defects     | 31/05/2018      | A77 SB 200M STH OF BURNSIDE COTTAGES LANE 1 NS WT         |
| SW82344114-235554293   | 2,424m  | 0m     | CARRIAGEWAY | Pothole (POTH)                | CAT 1           | 31/05/2018               | Completed Defects     | 31/05/2018      | A77 SB 200M STH OF BURNSIDE COTTAGES LANE 1 NS WT         |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>      |         |        |             |                               |                 |                          |                       |                 |   |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail             | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                                     |
|--|---------|--------|-------------|-------------------------|-----------------|--------------------------|-----------------------|-----------------|--|
| <i>No defects recorded</i>   |         |        |             |                         |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |         |        |             |                         |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |             |                         |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |         |        |             |                         |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |             |                         |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |         |        |             |                         |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |             |                         |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |         |        |             |                         |                 |                          |                       |                 |  |
| SW80-359626-235827128  | 2,931m  | 2,932m | CARRIAGEWAY | Pothole (POTH)          | CAT 1           | 05/07/2018               | Completed Defects     | 07/06/2018      | A77 NB CW OUTSIDE CURRAGH FARM                           |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |         |        |             |                         |                 |                          |                       |                 |  |
| SW80-363687-235858069  | 2,956m  | 2,957m | CARRIAGEWAY | Pothole (POTH)          | CAT 1           | 12/07/2018               | Completed Defects     | 14/06/2018      | A77 SB CW 25M PRIOR TO CURRUGH FARM                      |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |         |        |             |                         |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |             |                         |                 |                          |                       |                 |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |         |        |             |                         |                 |                          |                       |                 |  |
| SW86-357213-4  | 1,725m  | 1,675m | WOODLAND    | Invasive species (INVS) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW86-357213-3  | 3,878m  | 3,858m | WOODLAND    | Invasive species (INVS) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |         |        |             |                         |                 |                          |                       |                 |  |
| SW80-370510-235861169  | 2,801m  | 2,802m | CARRIAGEWAY | Pothole (POTH)          | CAT 1           | 26/07/2018               | Completed Defects     | 26/07/2018      | A78 NB CW BURNSIDE FARM SOUTH OF DIPPLE FACTORY          |
| SW80-370510-235861170  | 2,806m  | 2,807m | CARRIAGEWAY | Pothole (POTH)          | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | A78 NB CW BURNSIDE FARM NORTH OF GIRVAN                  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |         |        |             |                         |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |             |                         |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |         |        |             |                         |                 |                          |                       |                 |  |
| SW82377424-235909967   | 3,511m  | 3,511m | CARRIAGEWAY | Pothole (POTH)          | CAT 1           | 09/08/2018               | Completed Defects     | 23/07/2018      | A77 SB CW, 500M STH OF THE DIPPLE FACTORY, NTH OF GIRVAN |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |         |        |             |                         |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |             |                         |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |         |        |             |                         |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |             |                         |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |         |        |             |                         |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |             |                         |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |         |        |             |                         |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |             |                         |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |         |        |             |                         |                 |                          |                       |                 |  |
| SW80-394061-235954858  | 2,368m  | 2,369m | CARRIAGEWAY | Pothole VIAFIX (POTV)   | CAT 1           | 17/08/2018               | Completed Defects     | 16/08/2018      | A77 S/B C/W 200M SOUTH OF BURNSIDE FARM NORTH OF GIRVAN  |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |         |        |             |                         |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |             |                         |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>       |         |        |             |                         |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |             |                         |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b>    |         |        |             |                         |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |             |                         |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b>    |         |        |             |                         |                 |                          |                       |                 |  |
| SW82407181-236053599   | 2,377m  | 2,378m | CARRIAGEWAY | Pothole VIAFIX (POTV)   | CAT 1           | 14/09/2018               | Completed Defects     | 13/09/2018      | A77 S/B C/W 300M SOUTH BURNSIDE FARM NORTH OF GIRVAN     |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b>    |         |        |             |                         |                 |                          |                       |                 |  |
| SW82410364-236066533   | 2,816m  | 2,817m | CARRIAGEWAY | Pothole VIAFIX (POTV)   | CAT 1           | 21/09/2018               | Completed Defects     | 20/09/2018      | A77 NB CW OPPOSITE BURNSIDE FARM                         |
| SW82410364-236066534   | 2,402m  | 2,403m | CARRIAGEWAY | Pothole VIAFIX (POTV)   | CAT 1           | 21/09/2018               | Completed Defects     | 20/09/2018      | A77 SB CW 400M SOUTH OF BURNSIDE FARM                    |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b>    |         |        |             |                         |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |             |                         |                 |                          |                       |                 |  |

| Defect Reference   | Start m | End m  | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                                    |
|--|---------|--------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>      |         |        |                    |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>      |         |        |                    |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>      |         |        |                    |                                      |                 |                          |                       |                 |   |
| SW82423458-236136742   | 2,322m  | 2,323m | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 15/11/2018               | Completed Defects     | 18/10/2018      | A77 SB CW, 200M STH OF BURNSIDE COTTAGES, NTH OF GIRVAN |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |   |
| SW82332071-678   | 3,201m  | 3,281m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-679   | 3,380m  | 3,460m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-672   | 1,534m  | 1,554m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-683   | 4,146m  | 4,246m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-669   | 548m    | 549m   | TRAFFIC_SIGNS      | Physical condition of post (COPT)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-684   | 4,192m  | 4,272m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-673   | 1,885m  | 1,886m | TRAFFIC_SIGNS      | Physical condition of post (COPT)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-675   | 2,711m  | 2,791m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Completed Defects     | 26/10/2018      |   |
| SW82332071-685   | 4,191m  | 4,271m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-682   | 3,927m  | 4,027m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-680   | 3,448m  | 3,468m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-681   | 3,601m  | 3,661m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-670   | 1,100m  | 1,180m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-671   | 1,439m  | 1,440m | TRAFFIC_SIGNS      | Physical condition of post (COPT)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-676   | 2,789m  | 2,869m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Completed Defects     | 26/10/2018      |   |
| SW82332071-677   | 2,914m  | 2,994m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-674   | 2,339m  | 2,419m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>      |         |        |                    |                                      |                 |                          |                       |                 |   |



| Defect Reference   | Start m | End m  | Item Type     | Item Detail               | Defect Category | Required Completion Date | Current Status               | Completion Date | Location Description                                 |
|--|---------|--------|---------------|---------------------------|-----------------|--------------------------|------------------------------|-----------------|--|
| SW82425931-236166524   | 4,265m  | 4,266m | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1           | 26/10/2018               | Completed Defects            | 25/10/2018      | A77 SB CW OUTSIDE DIPPLE FACTORY NORTH OF GIRVAN     |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b> |         |        |               |                           |                 |                          |                              |                 |  |
| No defects recorded  |         |        |               |                           |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b> |         |        |               |                           |                 |                          |                              |                 |  |
| No defects recorded  |         |        |               |                           |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b> |         |        |               |                           |                 |                          |                              |                 |  |
| SW82426587-236223173   | 3,008m  | 3,009m | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1           | 16/11/2018               | Completed Defects            | 15/11/2018      | A77 SB CW 50 YARDS FROM THE CURRAGH                  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b> |         |        |               |                           |                 |                          |                              |                 |  |
| No defects recorded  |         |        |               |                           |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b> |         |        |               |                           |                 |                          |                              |                 |  |
| SW82426917-236234302   | 4,286m  | 4,287m | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1           | 30/11/2018               | Completed Defects            | 29/11/2018      | A77 SB CW OUTSIDE DIPPLE FACTORY                     |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b> |         |        |               |                           |                 |                          |                              |                 |  |
| No defects recorded  |         |        |               |                           |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b> |         |        |               |                           |                 |                          |                              |                 |  |
| SW82427366-236262613   | 3,005m  | 3,006m | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1           | 10/01/2019               | Completed Defects            | 13/12/2018      | A77 SB CW, OUTSIDE BURNSIDE COTTAGES NTH ENTRANCE    |
| SW82427366-236262614   | 3,898m  | 3,899m | GULLY         | Cracked or broken (IBCK)  | 3RD PTY         | 10/01/2019               | Awaiting CCMS Permanent Date | 01/01/9999      | A77 SB CW, 400M STH OF DIPPLE, NTH OF GIRVAN         |
| SW82427366-236262615   | 3,692m  | 3,693m | GULLY         | Cracked or broken (IBCK)  | 3RD PTY         | 14/12/2018               | Awaiting CCMS Permanent Date | 01/01/9999      | A77 SB CW, 600M STH OF DIPPLE FACTORY, NTH OF GIRVAN |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b> |         |        |               |                           |                 |                          |                              |                 |  |
| SW82427527-236264590   | 3,136m  | 3,137m | CARRIAGEWAY   | Pothole (POTH)            | CAT 1           | 17/01/2019               | Completed Defects            | 12/01/2019      | A77 SB CW THE CURRAGH FARM                           |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b> |         |        |               |                           |                 |                          |                              |                 |  |
| SW82427658-236270446   | 68m     | 69m    | TRAFFIC_SIGNS | Pointing wrong way (RWAY) | CAT 1           | 28/12/2018               | Completed Defects            | 27/12/2018      | A77 SB CW AT ROUNDABOUT NORTH OF GIRVAN              |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>  |         |        |               |                           |                 |                          |                              |                 |  |
| SW82427890-236270555   | 1,873m  | 1,874m | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1           | 31/01/2019               | Completed Defects            | 03/01/2019      | A77 SB CW, AT WATRBOARD JCT NTH OF GIRVAN            |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>  |         |        |               |                           |                 |                          |                              |                 |  |
| SW82428044-236270555   | 3,008m  | 3,009m | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1           | 11/01/2019               | Completed Defects            | 10/01/2019      | A77 SB CW AT ENTRANCE TO THE CURRAGH FARM            |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>  |         |        |               |                           |                 |                          |                              |                 |  |
| No defects recorded  |         |        |               |                           |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>  |         |        |               |                           |                 |                          |                              |                 |  |
| No defects recorded  |         |        |               |                           |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>  |         |        |               |                           |                 |                          |                              |                 |  |
| SW82428625-236291424   | 4,272m  | 4,273m | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1           | 01/02/2019               | Completed Defects            | 31/01/2019      | A77 SB CW AT ENTRANCE TO DIPPLE FACTORY              |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b> |         |        |               |                           |                 |                          |                              |                 |  |
| SW82429489-236310406   | 3,041m  | 3,042m | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1           | 07/03/2019               | Completed Defects            | 07/02/2019      | A77 SB CW, OUTSIDE BURNSIDE COTTAGE, NTH OF GIRVAN   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b> |         |        |               |                           |                 |                          |                              |                 |  |
| SW82430228-236328528   | 3,594m  | 3,599m | CARRIAGEWAY   | Pothole (POTH)            | CAT 1           | 14/03/2019               | Completed Defects            | 27/02/2019      | A77 S/B 300M AFTER DUNY MUCK FARM                    |
| SW82430228-236328529   | 3,439m  | 3,444m | CARRIAGEWAY   | Pothole (POTH)            | CAT 1           | 14/03/2019               | Completed Defects            | 27/02/2019      | A77 S/B 550M AFTER DUNYMUCK FARM                     |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b> |         |        |               |                           |                 |                          |                              |                 |  |
| SW82433243-236330732   | 4,239m  | 4,239m | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1           | 22/02/2019               | Completed Defects            | 21/02/2019      | A77 S/B 80MTRS BEFORE DIPPLE FACTORY                 |

| Defect Reference   | Start m | End m  | Item Type     | Item Detail    | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description  |
|--|---------|--------|---------------|----------------|-----------------|--------------------------|-------------------|-----------------|---|
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b> |         |        |               |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |               |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>    |         |        |               |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |               |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>    |         |        |               |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |               |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>    |         |        |               |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |               |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>    |         |        |               |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |               |                |                 |                          |                   |                 |   |
| <b>11622/59 : DIPPLE,FACTORY ENTRANCE TO A719 JUNCTION</b>       |         |        |               |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>  |         |        |               |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |               |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>  |         |        |               |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |               |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>  |         |        |               |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |               |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>  |         |        |               |                |                 |                          |                   |                 |   |
| SW82317793-235529556   | 2,652m  | 2,653m | CARRIAGEWAY   | Pothole (POTH) | CAT 1           | 22/02/2018               | Completed Defects | 08/02/2018      | A77 SB CW PH OROUND GULLY, 50M NTH OF TURNBURRY STH GATEWAY |
| SW82317793-235529558   | 2,439m  | 2,440m | CARRIAGEWAY   | Pothole (POTH) | CAT 1           | 22/02/2018               | Completed Defects | 08/02/2018      | A77 SB CW, 80M STH OF TURNBURRY STH GATEWAY                 |
| SW82317793-235529559   | 2,132m  | 2,134m | CARRIAGEWAY   | Pothole (POTH) | CAT 1           | 22/02/2018               | Completed Defects | 08/02/2018      | A77 SB CW, 400M STH OF TURNBURRY STH GATEWAY                |
| SW82317793-235529557   | 2,489m  | 2,490m | CARRIAGEWAY   | Pothole (POTH) | CAT 1           | 22/02/2018               | Completed Defects | 08/02/2018      | A77SB CW, TURNURRY STH GATEWAY                              |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b> |         |        |               |                |                 |                          |                   |                 |   |
| SW82318129-235532267   | 285m    | 585m   | CARRIAGEWAY   | Pothole (POTH) | CAT 1           | 01/03/2018               | Completed Defects | 01/02/2018      | A77 BOTH CW, DIPPLE FACTORY                                 |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b> |         |        |               |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |               |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b> |         |        |               |                |                 |                          |                   |                 |   |
| SW82319984-235544958   | 59m     | 60m    | CARRIAGEWAY   | Pothole (POTH) | CAT 1           | 15/03/2018               | Completed Defects | 15/02/2018      | A77 SB CW, OPPOSITE DIPPLE FACTORY                          |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b> |         |        |               |                |                 |                          |                   |                 |   |
| SW82321955-235548225   | 909m    | 910m   | CARRIAGEWAY   | Pothole (POTH) | CAT 1           | 22/03/2018               | Completed Defects | 27/02/2018      | 200 meters north of Dowhil Farm northbound carriageway      |
| SW82321955-235548224   | 1,811m  | 1,822m | CARRIAGEWAY   | Pothole (POTH) | CAT 1           | 22/03/2018               | Completed Defects | 27/02/2018      | AT ENTRANCE TO BALKENNA TEA ROOM N/B C/W                    |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>    |         |        |               |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |               |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>    |         |        |               |                |                 |                          |                   |                 |   |
| SW82326075-235554306   | 906m    | 907m   | CARRIAGEWAY   | Pothole (POTH) | CAT 1           | 05/04/2018               | Completed Defects | 08/03/2018      | A77 NB CW, 200M NTH OF TURNBURRY HOLIDAY PARK               |
| SW82326075-235554302   | 2,281m  | 2,282m | CARRIAGEWAY   | Pothole (POTH) | CAT 1           | 05/04/2018               | Completed Defects | 09/03/2018      | A77 ON CL, 300M STH OF TURNBURRY STH GATEWAY                |
| SW82326075-235554303   | 2,333m  | 2,334m | CARRIAGEWAY   | Pothole (POTH) | CAT 1           | 05/04/2018               | Completed Defects | 09/03/2018      | A77 ON CL, 220M STH OF TURNBURRY STH GATEWAY                |
| SW82326075-235554305   | 2,402m  | 2,403m | TRAFFIC_SIGNS | Damaged (DAMG) | CAT 1           | 05/04/2018               | Completed Defects | 21/03/2018      | A77 NB VERGE, 100M STH OF TURNBURRY STH GATEWAY             |
| SW82326075-235554304   | 2,402m  | 2,403m | CARRIAGEWAY   | Pothole (POTH) | CAT 1           | 05/04/2018               | Completed Defects | 09/03/2018      | A77 NB CW, 100M STH OF TURNBURRY STH GATEWAY                |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>    |         |        |               |                |                 |                          |                   |                 |   |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                                  |
|--|---------|--------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|---|
| SW82328086-235590033   | 320m    | 323m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 12/04/2018               | Completed Defects | 15/03/2018      | A77 BOTH CW, DIPPLE FACTORY                           |
| SW82328086-235590034   | 2,429m  | 2,432m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 12/04/2018               | Completed Defects | 16/03/2018      | A77 BOTH CW, TURNBERRY STH GATEWAY, 100M - GATEWAY    |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>        |         |        |             |                       |                 |                          |                   |                 |   |
| SW82330474-235608114   | 2,142m  | 2,143m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 19/04/2018               | Completed Defects | 22/03/2018      | A77 SB CW, 400M STH OF TURNBERRY STH GATEWAY          |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>        |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>        |         |        |             |                       |                 |                          |                   |                 |   |
| SW82334882-235613710   | 33m     | 0m     | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 06/04/2018               | Completed Defects | 05/04/2018      | A77 N/B OUTSIDE FMC GIRVIN                            |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>        |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>        |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>        |         |        |             |                       |                 |                          |                   |                 |   |
| SW82341166-235669119   | 341m    | 0m     | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 27/04/2018               | Completed Defects | 26/04/2018      | A77 NB DIPPLE FACTORY TO TURNBERRY LANE 1 NS WT       |
| SW82341166-235669118   | 332m    | 0m     | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 27/04/2018               | Completed Defects | 26/04/2018      | A77 NB DIPPLE FACTORY TO TURNBERRY LANE 1 NS WT       |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>          |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>          |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |         |        |             |                       |                 |                          |                   |                 |   |
| SW82356191-235816780   | 238m    | 284m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 28/06/2018               | Completed Defects | 31/05/2018      | A77 SB CW JUST AFTER LAYBY NORTH OF DIPPLE FACTORY    |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |         |        |             |                       |                 |                          |                   |                 |   |
| SW80-359626-235827130  | 2,509m  | 2,510m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 05/07/2018               | Completed Defects | 07/06/2018      | A77 CL AT TURNBERRY SOUTH GATEWAY                     |
| SW80-359626-235827129  | 2,476m  | 2,477m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 05/07/2018               | Completed Defects | 07/06/2018      | A77 NB CW CL 50M SOUTH OF TURNBERRY SOUTH GATEWAY     |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |         |        |             |                       |                 |                          |                   |                 |   |
| SW82377424-235909968   | 294m    | 295m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 09/08/2018               | Completed Defects | 12/07/2018      | A77 ON CL, OPP LAYBY AT DIPPLE FACTORY, NTH OF GIRVAN |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |         |        |             |                       |                 |                          |                   |                 |   |
| SW82380667-235914379   | 154m    | 155m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 16/08/2018               | Completed Defects | 19/07/2018      | A77 SB CW 50M PRIOR TO DIPPLE FACTORY                 |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |

| Defect Reference   | Start m | End m  | Item Type     | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                                    |
|--|---------|--------|---------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |         |        |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |         |        |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |         |        |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>       |         |        |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b>    |         |        |               |                                      |                 |                          |                       |                 |   |
| SW80-403929-235984880  | 917m    | 918m   | CARRIAGEWAY   | Pothole VIAFIX (POTV)                | CAT 1           | 07/09/2018               | Completed Defects     | 06/09/2018      | A77 N/B C/W 300M NORTH OF BALKENNA CAFE NORTH OF GIRVAN |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b>    |         |        |               |                                      |                 |                          |                       |                 |   |
| SW82407181-236053603   | 1,856m  | 1,857m | CARRIAGEWAY   | Pothole VIAFIX (POTV)                | CAT 1           | 14/09/2018               | Completed Defects     | 13/09/2018      | A77 N/B CW OPPOSITE BALKENNA TEAROOM SOUTH OF TURNBERRY |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b>    |         |        |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b>    |         |        |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>      |         |        |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>      |         |        |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>      |         |        |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |         |        |               |                                      |                 |                          |                       |                 |   |
| SW82332071-687   | 816m    | 896m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-690   | 1,792m  | 1,793m | TRAFFIC_SIGNS | Physical condition of post (COPT)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-692   | 2,125m  | 2,205m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-689   | 1,406m  | 1,486m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-686   | 812m    | 892m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-691   | 1,813m  | 1,893m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-688   | 1,074m  | 1,154m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>      |         |        |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>     |         |        |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>     |         |        |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>     |         |        |               |                                      |                 |                          |                       |                 |   |
| SW82426587-236223180   | 1,843m  | 1,844m | CARRIAGEWAY   | Pothole VIAFIX (POTV)                | CAT 1           | 16/11/2018               | Completed Defects     | 15/11/2018      | A77 NB CW OUTSIDE BALKENNA TEAROOMS                     |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b>     |         |        |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b>     |         |        |               |                                      |                 |                          |                       |                 |   |
| SW82426917-236234303   | 902m    | 903m   | CARRIAGEWAY   | Pothole VIAFIX (POTV)                | CAT 1           | 30/11/2018               | Completed Defects     | 29/11/2018      | A77 SB CW OUTSIDE TURNBERRY HOLIDAY PARK ENTRANCE       |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b>     |         |        |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |   |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail               | Defect Category | Required Completion Date | Current Status      | Completion Date | Location Description                                      |
|--|---------|--------|-------------|---------------------------|-----------------|--------------------------|---------------------|-----------------|---|
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b> |         |        |             |                           |                 |                          |                     |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                           |                 |                          |                     |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b> |         |        |             |                           |                 |                          |                     |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                           |                 |                          |                     |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b> |         |        |             |                           |                 |                          |                     |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                           |                 |                          |                     |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>  |         |        |             |                           |                 |                          |                     |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                           |                 |                          |                     |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>  |         |        |             |                           |                 |                          |                     |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                           |                 |                          |                     |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>  |         |        |             |                           |                 |                          |                     |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                           |                 |                          |                     |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>  |         |        |             |                           |                 |                          |                     |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                           |                 |                          |                     |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>  |         |        |             |                           |                 |                          |                     |                 |   |
| SW82428625-236291423   | 288m    | 289m   | CARRIAGEWAY | Pothole VIAFIX (POTV)     | CAT 1           | 01/02/2019               | Completed Defects   | 31/01/2019      | A77 NB CW LAYBY NORTH OF DIPPLE FACTORY                   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b> |         |        |             |                           |                 |                          |                     |                 |   |
| SW82429489-236310408   | 872m    | 873m   | CARRIAGEWAY | Pothole VIAFIX (POTV)     | CAT 1           | 07/03/2019               | Completed Defects   | 07/02/2019      | A77 NB CW, 410M NTH OF TEAROOM NTH OF DIPPLE              |
| SW82429489-236310407   | 853m    | 854m   | CARRIAGEWAY | Pothole VIAFIX (POTV)     | CAT 1           | 07/03/2019               | Completed Defects   | 07/02/2019      | A77 NB CW, 400M NTH OF TEAROOM NTH OF DIPPLE              |
| SW82429489-236310409   | 875m    | 876m   | CARRIAGEWAY | Pothole VIAFIX (POTV)     | CAT 1           | 07/03/2019               | Completed Defects   | 07/02/2019      | A77 NB CW 415M NTH OF TEAROOM NTH OF GIRVAN               |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b> |         |        |             |                           |                 |                          |                     |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                           |                 |                          |                     |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b> |         |        |             |                           |                 |                          |                     |                 |   |
| SW82433243-236330733   | 2,679m  | 2,679m | MANHOLE     | Rocking under load (IRLD) | 3RD PTY         | 21/03/2019               | Third Party Defects | 01/01/9999      | A77 N/B @ 100MTRS BEFORE MAIDENS JT TURNBERRY             |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b> |         |        |             |                           |                 |                          |                     |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                           |                 |                          |                     |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>    |         |        |             |                           |                 |                          |                     |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                           |                 |                          |                     |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>    |         |        |             |                           |                 |                          |                     |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                           |                 |                          |                     |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>    |         |        |             |                           |                 |                          |                     |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                           |                 |                          |                     |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>    |         |        |             |                           |                 |                          |                     |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                           |                 |                          |                     |                 |   |
| <b>11626/22 : HIGH PARK TO JUNCTION KIRK BRAE KIRKOSWALD</b>     |         |        |             |                           |                 |                          |                     |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>  |         |        |             |                           |                 |                          |                     |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                           |                 |                          |                     |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>  |         |        |             |                           |                 |                          |                     |                 |   |
| SW82317471-235518224   | 354m    | 355m   | CARRIAGEWAY | Pothole (POTH)            | CAT 1           | 08/02/2018               | Completed Defects   | 26/02/2018      | A77 SB CW, 200M NTH OF LAYBY, DALQUATT, STH OF KIRKOSWALD |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>  |         |        |             |                           |                 |                          |                     |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                           |                 |                          |                     |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>  |         |        |             |                           |                 |                          |                     |                 |   |
| SW82317793-235529560   | 2,007m  | 2,008m | CARRIAGEWAY | Pothole (POTH)            | CAT 1           | 22/02/2018               | Completed Defects   | 08/02/2018      | A77 B CW, 20M NTH OF KIRKOSWALD STH GATEWAY               |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b> |         |        |             |                           |                 |                          |                     |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                           |                 |                          |                     |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b> |         |        |             |                           |                 |                          |                     |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                           |                 |                          |                     |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b> |         |        |             |                           |                 |                          |                     |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                           |                 |                          |                     |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b> |         |        |             |                           |                 |                          |                     |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                           |                 |                          |                     |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>    |         |        |             |                           |                 |                          |                     |                 |   |

| Defect Reference  | Start m | End m  | Item Type     | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                                     |
|---|---------|--------|---------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|--|
| <i>No defects recorded</i>                                    |         |        |               |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b> |         |        |               |                       |                 |                          |                   |                 |  |
| SW82326075-235554298  | 1,370m  | 1,371m | CARRIAGEWAY   | Pothole (POTH)        | CAT 1           | 05/04/2018               | Completed Defects | 08/03/2018      | A77 SB CW, OUTSIDE CROFTENGEE COTTAGE, STH OF KIRKOSWALD |
| SW82326075-235554296  | 1,883m  | 1,884m | TRAFFIC_SIGNS | Damaged (DAMG)        | CAT 1           | 05/04/2018               | Completed Defects | 21/03/2018      | A77 SB VERGE, 100M STH OF KIRKOSWALD                     |
| SW82326075-235554300  | 672m    | 673m   | CARRIAGEWAY   | Pothole (POTH)        | CAT 1           | 05/04/2018               | Completed Defects | 08/03/2018      | A77 BOTH CW, 650M NTH OF DALQUATT FARM                   |
| SW82326075-235554299  | 687m    | 689m   | CARRIAGEWAY   | Pothole (POTH)        | CAT 1           | 05/04/2018               | Completed Defects | 08/03/2018      | A77 NB CW, 700M NTH OF DALQUATT FARMS                    |
| SW82326075-235554297  | 1,413m  | 1,414m | CARRIAGEWAY   | Pothole (POTH)        | CAT 1           | 05/04/2018               | Completed Defects | 08/03/2018      | A77 SB CW, 600M STH OF KIRKOSWALD STH GATEWAY            |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b> |         |        |               |                       |                 |                          |                   |                 |  |
| SW82328086-235590035  | 280m    | 281m   | CARRIAGEWAY   | Pothole (POTH)        | CAT 1           | 12/04/2018               | Completed Defects | 16/03/2018      | A77 NB CW, 100M NTH OF DALQUATT LAYBY                    |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b> |         |        |               |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                    |         |        |               |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b> |         |        |               |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                    |         |        |               |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b> |         |        |               |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                    |         |        |               |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b> |         |        |               |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                    |         |        |               |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b> |         |        |               |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                    |         |        |               |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b> |         |        |               |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                    |         |        |               |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>   |         |        |               |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                    |         |        |               |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>   |         |        |               |                       |                 |                          |                   |                 |  |
| SW82346930-235712678  | 232m    | 233m   | CARRIAGEWAY   | Pothole VIAFIX (POTV) | CAT 1           | 07/06/2018               | Completed Defects | 10/05/2018      | A77 SB CW, OPP DALQUATT LAYBY                            |
| SW82346930-235712679  | 37m     | 38m    | CARRIAGEWAY   | Pothole VIAFIX (POTV) | CAT 1           | 07/06/2018               | Completed Defects | 10/05/2018      | A77 SB CW, OPP BALLOCHNEIL FARM, NTH OF TURNBURY         |
| SW82346930-235712680  | 86m     | 87m    | CARRIAGEWAY   | Pothole VIAFIX (POTV) | CAT 1           | 07/06/2018               | Completed Defects | 10/05/2018      | A77 NB CW, 50M STH OF DALQUATT LAYBY                     |
| SW82346930-235712676  | 684m    | 685m   | CARRIAGEWAY   | Pothole VIAFIX (POTV) | CAT 1           | 07/06/2018               | Completed Defects | 10/05/2018      | A77 SB CW, 200M NTH OF DALQUATT LAYBY                    |
| SW82346930-235712677  | 607m    | 608m   | CARRIAGEWAY   | Pothole VIAFIX (POTV) | CAT 1           | 07/06/2018               | Completed Defects | 10/05/2018      | A77 SB CW, 150M NTH OF DALQUATT LAYBY                    |
| SW82346930-235712681  | 732m    | 733m   | CARRIAGEWAY   | Pothole VIAFIX (POTV) | CAT 1           | 07/06/2018               | Completed Defects | 10/05/2018      | A77 NB CW, 220M NTH OF DALQUATT LAYBY                    |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>   |         |        |               |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                    |         |        |               |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>   |         |        |               |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                    |         |        |               |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>   |         |        |               |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                    |         |        |               |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>  |         |        |               |                       |                 |                          |                   |                 |  |
| SW80-359626-235827131   | 404m    | 405m   | CARRIAGEWAY   | Pothole (POTH)        | CAT 1           | 05/07/2018               | Completed Defects | 10/07/2018      | A77 SB CW 100M NORTH OF DALQUATT LAYBY                   |
| SW80-359626-235827133   | 413m    | 414m   | CARRIAGEWAY   | Pothole (POTH)        | CAT 1           | 05/07/2018               | Completed Defects | 10/07/2018      | A77 SB CW 106M NORTH OF DALQUATT LAYBY                   |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                       |
|--|---------|--------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|--|
| SW80-359626-235827132  | 409m    | 410m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 05/07/2018               | Completed Defects | 10/07/2018      | A77 SB CW 105 M NORTH OF DALQUHAT LAYBY    |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |         |        |             |                       |                 |                          |                   |                 |  |
| SW80-363687-235858074  | 506m    | 507m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 12/07/2018               | Completed Defects | 15/06/2018      | A77 SB CW 595M NORTH OF DALQUHAT LAYBY     |
| SW80-363687-235858075  | 499m    | 500m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 12/07/2018               | Completed Defects | 15/06/2018      | A77 SB CW 590M NORTH OF DALQUHAT LAYBY     |
| SW80-363687-235858071  | 206m    | 207m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 12/07/2018               | Completed Defects | 14/06/2018      | A77 SB CW START OF DALQUHAT LAYBY          |
| SW80-363687-235858070  | 216m    | 217m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 12/07/2018               | Completed Defects | 14/06/2018      | A77 NB CW START OF DALQUHAT LAYBY          |
| SW80-363687-235858072  | 218m    | 219m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 12/07/2018               | Completed Defects | 14/06/2018      | A77 SB CW DALQUAT LAYBY                    |
| SW80-363687-235858073  | 506m    | 507m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 12/07/2018               | Completed Defects | 15/06/2018      | A77 SB CW 600M NORTH OF DALQUHAT LAYBY     |
| SW80-363687-235858076  | 499m    | 500m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 12/07/2018               | Completed Defects | 15/06/2018      | A77 CL APPROX 590M NORTH DALQUHAT LAYBY    |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |         |        |             |                       |                 |                          |                   |                 |  |
| SW80-367289-235862783  | 675m    | 676m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 19/07/2018               | Completed Defects | 22/06/2018      | A77 NB 785M NTH OF DALQUAT LAYBY           |
| SW80-367289-235862782  | 681m    | 682m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 19/07/2018               | Completed Defects | 22/06/2018      | A77 NB CW CL 790M NORTH OF DALQUHAT LAYBY  |
| SW80-367289-235862776  | 2,116m  | 2,117m | GULLY       | Other (OTHR)          | CAT 1           | 19/07/2018               | Completed Defects | 25/06/2018      | A77 SB CW 25M AFTER SOUTERS PUB KIRKOSWALD |
| SW80-367289-235862781  | 689m    | 690m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 19/07/2018               | Completed Defects | 22/06/2018      | A77 NB CW CL 800M NORTH OF DALQUHAT LAYBY  |
| SW80-367289-235862777  | 2,074m  | 2,075m | GULLY       | Other (OTHR)          | CAT 1           | 19/07/2018               | Completed Defects | 25/06/2018      | A77 SB CW 50M AFTER SOUTERS PUB KIRKOSWALD |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |         |        |             |                       |                 |                          |                   |                 |  |
| SW82374127-235892353   | 673m    | 674m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 02/08/2018               | Completed Defects | 06/07/2018      | A77 CL 880M NORTH OF DALQHAT LAYBY         |
| SW82374127-235892355   | 655m    | 656m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 02/08/2018               | Completed Defects | 06/07/2018      | A76 NB CW 875M NORTH OF DALQHAT LAYBY      |
| SW82374127-235892357   | 403m    | 404m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 02/08/2018               | Completed Defects | 06/07/2018      | A77 SB CW 300M NORTH OF DALQHAT LAYBY      |
| SW82374127-235892351   | 701m    | 702m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 02/08/2018               | Completed Defects | 06/07/2018      | A77 CL 900M NORTH OF DALQHAT LAYBY         |
| SW82374127-235892352   | 684m    | 685m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 02/08/2018               | Completed Defects | 06/07/2018      | A77 CL 890M NORTH OF DALQHAT LAYBY         |
| SW82374127-235892354   | 675m    | 676m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 02/08/2018               | Completed Defects | 06/07/2018      | A77 NB CW 885 M NORTH OF DALQHAT LAYBY     |
| SW82374127-235892356   | 653m    | 654m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 02/08/2018               | Completed Defects | 06/07/2018      | A77 CL 875M NORTH OF DALQHAT LAYBY         |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |         |        |             |                       |                 |                          |                   |                 |  |

| Defect Reference  | Start m | End m  | Item Type          | Item Detail                       | Defect Category | Required Completion Date | Current Status               | Completion Date | Location Description   |
|---|---------|--------|--------------------|-----------------------------------|-----------------|--------------------------|------------------------------|-----------------|--|
| <i>No defects recorded</i>  |         |        |                    |                                   |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>      |         |        |                    |                                   |                 |                          |                              |                 |  |
| SW82383889-235917497  | 526m    | 527m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR) | CAT 1           | 23/08/2018               | Awaiting CCMS Permanent Date | 01/01/9999      | A77 SB CW 400M PRIOR TO DALQUAT LAYBY                                |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>    |         |        |                    |                                   |                 |                          |                              |                 |  |
| <i>No defects recorded</i>  |         |        |                    |                                   |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>    |         |        |                    |                                   |                 |                          |                              |                 |  |
| SW80-390684-235944662   | 1,982m  | 1,883m | BOLLARDS           | Damaged (DAMG)                    | CAT 1           | 06/09/2018               | Completed Defects            | 20/08/2018      | A77 CENTRAL ISLAND AT KIRKOSWALD STH GATEWAY                         |
| SW80-390684-235944663   | 1,990m  | 1,991m | GULLY              | Other (OTHR)                      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action        | 01/01/9999      | A77 NB CW 10M PRIOR TO KIRKLANDS GARDEN CENTRE KIRKOSALD             |
| SW80-390684-235944655   | 2,090m  | 2,091m | GULLY              | Blockage (BLOK)                   | CAT 1           | 06/09/2018               | Completed Defects            | 06/09/2018      | A77 NB CW 20M PRIOR TO SOUTER INN KIRKOSWALD                         |
| SW80-390684-235944653   | 2,116m  | 2,117m | GULLY              | Cracked or broken (IBCK)          | CAT 1           | 06/09/2018               | Completed Defects            | 05/09/2018      | A77 SB CW 10M AFTER SOUTER INN                                       |
| SW80-390684-235944657   | 2,073m  | 2,074m | GULLY              | Blockage (BLOK)                   | CAT 1           | 06/09/2018               | Completed Defects            | 06/09/2018      | A77 SB CW 25M AFTER SOUTER INN KIRK OSWALD                           |
| SW80-390684-235944664   | 2,030m  | 2,031m | GULLY              | Other (OTHR)                      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action        | 01/01/9999      | A77 SB CW OPPOSITE KIRKLANDS GARDEN CENTRE KIRKOSWALD                |
| SW80-390684-235944660   | 1,956m  | 1,957m | GULLY              | Blockage (BLOK)                   | CAT 1           | 06/09/2018               | Completed Defects            | 06/09/2018      | A77 SB CW AT 25M AFTER KIRKLANDS GARDEN CENTER                       |
| SW80-390684-235944661   | 1,957m  | 1,958m | TRAFFIC_SIGNS      | Dirty sign (DIRT)                 | CAT 1           | 06/09/2018               | Completed Defects            | 09/08/2018      | A77 SB CW SOUTH GATEWAY KIRKOSWALD                                   |
| SW80-390684-235944656   | 2,037m  | 2,038m | GULLY              | Blockage (BLOK)                   | CAT 1           | 06/09/2018               | Completed Defects            | 06/09/2018      | A77 SB CW OPPOSITE KIRKLANDS GARDEN CENTER KIRKOSWALD                |
| SW80-390684-235944658   | 1,996m  | 1,997m | GULLY              | Blockage (BLOK)                   | CAT 1           | 06/09/2018               | Completed Defects            | 06/09/2018      | A77 NB CW 10M PRIOR TO KIRKLANDS GARDEN CENTER KIRKOSWALD            |
| SW80-390684-235944665   | 2,040m  | 0m     | GULLY              | Other (OTHR)                      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action        | 01/01/9999      | A77 SB CW OPPOSITE KIRKLANDS GARDEN CENTRE KIRKOSWALD                |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>    |         |        |                    |                                   |                 |                          |                              |                 |  |
| <i>No defects recorded</i>  |         |        |                    |                                   |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>    |         |        |                    |                                   |                 |                          |                              |                 |  |
| <i>No defects recorded</i>  |         |        |                    |                                   |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>    |         |        |                    |                                   |                 |                          |                              |                 |  |
| <i>No defects recorded</i>  |         |        |                    |                                   |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b> |         |        |                    |                                   |                 |                          |                              |                 |  |
| <i>No defects recorded</i>  |         |        |                    |                                   |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b> |         |        |                    |                                   |                 |                          |                              |                 |  |
| SW82407181-236053598  | 1,997m  | 1,998m | GULLY              | Rocking under load (IRLD)         | CAT 1           | 11/10/2018               | Completed Defects            | 19/09/2018      | A77 N/B C/W PRIOR TO GARDEN CENTRE PRIOR TO KIRKOSWALD SOUTH GATEWAY |
| SW82407181-236053597  | 1,998m  | 1,999m | CARRIAGEWAY        | Pothole VIAFIX (POTV)             | CAT 1           | 14/09/2018               | Completed Defects            | 13/09/2018      | A77 N/B C/W KIRKOSWALD SOUTH GATEWAY                                 |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b> |         |        |                    |                                   |                 |                          |                              |                 |  |
| <i>No defects recorded</i>  |         |        |                    |                                   |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b> |         |        |                    |                                   |                 |                          |                              |                 |  |
| <i>No defects recorded</i>  |         |        |                    |                                   |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>   |         |        |                    |                                   |                 |                          |                              |                 |  |
| <i>No defects recorded</i>  |         |        |                    |                                   |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>   |         |        |                    |                                   |                 |                          |                              |                 |  |
| <i>No defects recorded</i>  |         |        |                    |                                   |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>   |         |        |                    |                                   |                 |                          |                              |                 |  |



| Defect Reference   | Start m | End m  | Item Type     | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                             |
|--|---------|--------|---------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|--|
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |         |        |               |                                      |                 |                          |                       |                 |  |
| SW82332071-719   | 1,900m  | 1,980m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-720   | 1,975m  | 2,055m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-709   | 162m    | 242m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-716   | 1,403m  | 1,483m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-710   | 226m    | 306m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-712   | 588m    | 648m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-714   | 630m    | 830m   | FILTER_DRAIN  | Weed growth (WEED)                   | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-718   | 1,853m  | 1,933m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-715   | 1,318m  | 1,408m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-717   | 1,694m  | 1,695m | TRAFFIC_SIGNS | Physical condition of post (COPT)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-711   | 576m    | 656m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-713   | 377m    | 577m   | FILTER_DRAIN  | Weed growth (WEED)                   | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>      |         |        |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>     |         |        |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>     |         |        |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>     |         |        |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b>     |         |        |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b>     |         |        |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b>     |         |        |               |                                      |                 |                          |                       |                 |  |
| SW80-427220-236234306  | 1,971m  | 1,972m | GULLY         | Other (OTHR)                         | CAT 1           | 07/12/2018               | Completed Defects     | 06/12/2018      | A77 NB CW 10M FROM KIRKLAND JCT                  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b>     |         |        |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b>     |         |        |               |                                      |                 |                          |                       |                 |  |
| SW82427527-236264610   | 231m    | 232m   | CARRIAGEWAY   | Pothole (POTH)                       | CAT 1           | 17/01/2019               | Completed Defects     | 20/12/2018      | A77 SB CW OPPOSITE LAYBY NORTH OF DALQUAT        |
| SW82427527-236264608   | 242m    | 243m   | CARRIAGEWAY   | Pothole (POTH)                       | CAT 1           | 17/01/2019               | Completed Defects     | 21/12/2018      | A77 NB CW 15M BEFORE LAYBY NORTH OF DALQUAT FARM |
| SW82427527-236264607   | 231m    | 232m   | CARRIAGEWAY   | Pothole (POTH)                       | CAT 1           | 17/01/2019               | Completed Defects     | 21/12/2018      | A77 NB CW 10M BEFORE LAYBY NORTH OF DALQUAT      |

| Defect Reference  | Start m | End m  | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                                      |
|---|---------|--------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|---|
| SW82427527-236264609  | 238m    | 239m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 17/01/2019               | Completed Defects | 20/12/2018      | A77 SB CW OPPOSITE LAYBY NORTH OF DALQUAT                 |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>     |         |        |             |                       |                 |                          |                   |                 |   |
| SW82427890-236270559  | 131m    | 132m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 31/01/2019               | Completed Defects | 04/01/2019      | A77 NB CW, 60M STH OF LAYBY AT DALQUATT                   |
| SW82427890-236270560  | 411m    | 412m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 31/01/2019               | Completed Defects | 04/01/2019      | A77 NB CW, 300M NTH OF LAYBY AT DALQUATT                  |
| SW82427890-236270556  | 29m     | 30m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 31/01/2019               | Completed Defects | 04/01/2019      | A77 NB CW, STH OF LAYBY AT DALQUATT FARM, NTH OF TURNBURY |
| SW82427890-236270558  | 107m    | 108m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 31/01/2019               | Completed Defects | 04/01/2019      | A77 NB CW, 60M STH OF LAYBY AT DALQUATT                   |
| SW82427890-236270561  | 557m    | 558m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 31/01/2019               | Completed Defects | 04/01/2019      | A77 NB CW, 400M NTH OF LAYBY NTH OF DALQUATT              |
| SW82427890-236270562  | 545m    | 546m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 31/01/2019               | Completed Defects | 04/01/2019      | A77 SB CW, 310M NTH OF LAYBY AT DALQUATT                  |
| SW82427890-236270557  | 96m     | 97m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 31/01/2019               | Completed Defects | 04/01/2019      | A77 NB CW, 60M STH OF LAYBY AT DALQUATT FARM              |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>     |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>     |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>     |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>     |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| SW82429489-236310414  | 1,986m  | 1,987m | GULLY       | Other (OTHR)          | CAT 1           | 07/03/2019               | Completed Defects | 22/02/2019      | A77 NB CW, KIRKOSALD STH GATEWAY                          |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| SW82436659-236335202  | 2,037m  | 2,038m | GULLY       | Damaged (DAMG)        | CAT 1           | 28/03/2019               | Completed Defects | 11/03/2019      | A77 S/B KIRKOSWALD OPP KIRKLAND GARDENS                   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>       |         |        |             |                       |                 |                          |                   |                 |   |
| SW82441664-236344799  | 249m    | 249m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 08/03/2019               | Completed Defects | 07/03/2019      | A77 S/B HIGH PARK TO KIRK BRAE                            |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>       |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>       |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>       |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>11626/43 : JUNCTION KIRK BRAE KIRKOSWALD TO OLD TOLL COTTAGE</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>     |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>     |         |        |             |                       |                 |                          |                   |                 |   |
| SW82317471-235518227  | 410m    | 411m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 08/02/2018               | Completed Defects | 08/02/2018      | A77 SB CW, 300M NTH OF WHISKEY EXPERIENCE, KIRKOSWALD     |
| SW82317471-235518229  | 584m    | 585m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 08/02/2018               | Completed Defects | 16/02/2018      | A77 NB CW, ON ANTI SKID, KIRKOSWALD NTH GATEWAY           |

| Defect Reference   | Start m | End m | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description   |
|--|---------|-------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|--|
| SW82317471-235518228   | 519m    | 520m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 08/02/2018               | Completed Defects | 08/02/2018      | A77 NB CW, 200M STH OF KIRKOSWALD NTH GATEWAY                  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| SW82317666-235521322   | 187m    | 188m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 15/02/2018               | Completed Defects | 16/02/2018      | A77 SB CW, OPPOSITE NO.44 MAIN ROAD KIRKOSWALD                 |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| SW82317793-235529562   | 325m    | 326m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 22/02/2018               | Completed Defects | 08/02/2018      |  |
| SW82317793-235529561   | 325m    | 326m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 22/02/2018               | Completed Defects | 08/02/2018      | A77 NB CW, 50M NTH OF WHISKEY EXPERIENCE, KIRKOSWALD           |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b> |         |       |             |                       |                 |                          |                   |                 |  |
| SW82318129-235532266   | 192m    | 193m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 01/03/2018               | Completed Defects | 01/02/2018      | A77 KIRKLOSALD   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b> |         |       |             |                       |                 |                          |                   |                 |  |
| SW82319037-235539779   | 206m    | 207m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 08/03/2018               | Completed Defects | 08/02/2018      | A77 ON CW, OPPOSITE NO.44, KIRKOSWALD                          |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b> |         |       |             |                       |                 |                          |                   |                 |  |
| SW82319984-235544961   | 223m    | 225m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 15/03/2018               | Completed Defects | 15/02/2018      | A77 SB CW, 40M STH OF WHISKEY EXPERIENCE, KIRKOSWALD           |
| SW82319984-235544960   | 255m    | 256m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 15/03/2018               | Completed Defects | 15/02/2018      | A77 SB CW, OPP WHISKEY EXPERIENCE, KIRKOSWALD                  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b> |         |       |             |                       |                 |                          |                   |                 |  |
| SW82321955-235548222   | 233m    | 236m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 22/03/2018               | Completed Defects | 26/02/2018      | MAIN STREET KIRKOSWALD JUST NORTH OF WHISKY EXPERIENCE S\B\C\W |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| SW82330474-235608119   | 127m    | 128m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 19/04/2018               | Completed Defects | 23/03/2018      | A77 NB CW, KIRKOSWALD, 20M NTH OF SHOP                         |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>      |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>      |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>      |         |       |             |                       |                 |                          |                   |                 |  |
| SW82349855-235793438   | 114m    | 115m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 14/06/2018               | Completed Defects | 17/05/2018      | A77 SB CW BUS STOP SOUTH OF SOUTER JHONNYS KIRKOSWALD          |
| SW82349855-235793437   | 105m    | 106m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 14/06/2018               | Completed Defects | 17/05/2018      | A77 NB CW 66 MAIN STREET KIRKOSWALD                            |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>      |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>      |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |       |             |                       |                 |                          |                   |                 |  |

| Defect Reference   | Start m | End m | Item Type   | Item Detail                           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description  |
|--|---------|-------|-------------|---------------------------------------|-----------------|--------------------------|-------------------|-----------------|---|
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |         |       |             |                                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |         |       |             |                                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |         |       |             |                                       |                 |                          |                   |                 |   |
| SW80-367289-235862775  | 14m     | 15m   | GULLY       | Other (OTHR)                          | CAT 1           | 19/07/2018               | Completed Defects | 25/06/2018      | A77 SB CW OUTSIDE SOUTERS INN KIRKOSWALD                                |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |         |       |             |                                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |         |       |             |                                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |         |       |             |                                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |         |       |             |                                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |         |       |             |                                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |         |       |             |                                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |         |       |             |                                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |         |       |             |                                       |                 |                          |                   |                 |   |
| SW80-390684-235944652  | 122m    | 123m  | MANHOLE     | Difference in component levels (ICLV) | 3RD PTY         | 06/09/2018               | Completed Defects | 08/11/2018      | A77 SB CW OPPOSITE POST OFFICE KIRKOSWALD                               |
| SW80-390684-235944654  | 18m     | 19m   | GULLY       | Blockage (BLOK)                       | CAT 1           | 06/09/2018               | Completed Defects | 21/08/2018      | A77 NB CW OPPOSITE SOUTERS IN KIRKOSWOLD                                |
| SW80-390684-235944651  | 213m    | 214m  | KERB        | Damaged (DAMG)                        | CAT 1           | 06/09/2018               | Completed Defects | 03/09/2018      | A77 SB CW OUTSIDE THE STORE KIRKOSWALD                                  |
| SW80-390684-235944659  | 202m    | 203m  | GULLY       | Blockage (BLOK)                       | CAT 1           | 06/09/2018               | Completed Defects | 06/09/2018      | A77 NB CW OPPOSITE THE STORE KIRKOSWALD                                 |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |         |       |             |                                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |         |       |             |                                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>       |         |       |             |                                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b>    |         |       |             |                                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b>    |         |       |             |                                       |                 |                          |                   |                 |   |
| SW82407181-236053596   | 60m     | 61m   | CARRIAGEWAY | Pothole VIAFIX (POTV)                 | CAT 1           | 14/09/2018               | Completed Defects | 13/09/2018      | A77 S/B C/W OPPOSITE SOUTER JOHNIES COTTAGE KIRKOSWALD                  |
| SW82407181-236053595   | 168m    | 20m   | CARRIAGEWAY | Opening of longitudinal joint (OLJT)  | CAT 1           | 11/10/2018               | Completed Defects | 14/09/2018      | A77 ON CENTRE LINE OPPOSITE SOUTER JOHNIES COTTAGE MAIN ROAD KIRKOSWALD |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b>    |         |       |             |                                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b>    |         |       |             |                                       |                 |                          |                   |                 |   |
| SW80-413634-236087128  | 207m    | 212m  | KERB        | Damaged (DAMG)                        | CAT 1           | 25/10/2018               | Completed Defects | 23/10/2018      | A77 SB OUTSIDE THE STORE KIRKOSWALD                                     |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>      |         |       |             |                                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>      |         |       |             |                                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>      |         |       |             |                                       |                 |                          |                   |                 |   |
| SW82423458-236136745   | 44m     | 45m   | CARRIAGEWAY | Pothole VIAFIX (POTV)                 | CAT 1           | 15/11/2018               | Completed Defects | 18/10/2018      | A77 NB CW, KIRKOSWALD, OPP SOUTER JOHNNYS                               |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |         |       |             |                                       |                 |                          |                   |                 |   |

| Defect Reference   | Start m | End m | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                                   |
|--|---------|-------|-------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|--|
| SW82332071-721   | 90m     | 170m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-722   | 303m    | 383m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>  |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b> |         |       |             |                                      |                 |                          |                       |                 |  |
| SW82426212-236179756   | 207m    | 208m  | GULLY       | Rocking under load (IRLD)            | CAT 1           | 29/11/2018               | Completed Defects     | 07/12/2018      | A77 NB CW OPPOSITE THE STORE KIRKOSWALD                |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b> |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b> |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b> |         |       |             |                                      |                 |                          |                       |                 |  |
| SW82426764-236231627   | 77m     | 78m   | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 23/11/2018               | Completed Defects     | 22/11/2018      | A77 NB CW OUTSIDE SOUTERS INN KIRKOSWALD               |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b> |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b> |         |       |             |                                      |                 |                          |                       |                 |  |
| SW80-427220-236234312  | 301m    | 302m  | GULLY       | Blockage (BLOK)                      | CAT 1           | 03/01/2019               | Completed Defects     | 06/12/2018      | A77 NB CW 20 NORTH OF THE WHISKY EXPERIENCE KIRKOSWALD |
| SW80-427220-236234313  | 287m    | 288m  | GULLY       | Blockage (BLOK)                      | CAT 1           | 03/01/2019               | Completed Defects     | 06/12/2018      | A77 NB CW OUTSIDE THE WHISKY EXPERIENCE KIRKOSWALD     |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b> |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b> |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b> |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>  |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>  |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>  |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>  |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>  |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b> |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b> |         |       |             |                                      |                 |                          |                       |                 |  |
| SW82430228-236328522   | 196m    | 197m  | CARRIAGEWAY | Other (OTHR)                         | CAT 1           | 14/03/2019               | Completed Defects     | 14/02/2019      | A77 S/B OPP 4 KIRKOSWALD MAIN ST                       |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b> |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b> |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>    |         |       |             |                                      |                 |                          |                       |                 |  |
| SW82441664-236344800   | 154m    | 154m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 08/03/2019               | Completed Defects     | 07/03/2019      | A77 N/B @ NO 52 MAIN ST KIRKOSWALD                     |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>    |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>    |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>    |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |

11626/48 : OLD TOLL COTTAGE TO JUNCTION BLANEFIELD

| Defect Reference   | Start m | End m  | Item Type   | Item Detail                                | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                                    |
|--|---------|--------|-------------|--|-----------------|--------------------------|-------------------|-----------------|---|
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>  |         |        |             |  |                 |                          |                   |                 |   |
| SW82317326-235513692   | 885m    | 887m   | CARRIAGEWAY | Pothole (POTH)                             | CAT 1           | 01/02/2018               | Completed Defects | 10/01/2018      | sb cw at whitegates north of kirkoswald                 |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>  |         |        |             |  |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |  |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>  |         |        |             |  |                 |                          |                   |                 |   |
| SW82317666-235521327   | 1,370m  | 1,371m | CARRIAGEWAY | Pothole (POTH)                             | CAT 1           | 15/02/2018               | Completed Defects | 09/02/2018      | A77 NB CW, 600M NTH OF WHITEGATES, NTH OF KIRKOSWALD    |
| SW82317666-235521323   | 1,445m  | 1,448m | CARRIAGEWAY | Pothole (POTH)                             | CAT 1           | 15/02/2018               | Completed Defects | 09/02/2018      | A77 SB CW, 500M NTH OF WHITEGATES, NTH OF KIRKOSWALD    |
| SW82317666-235521325   | 948m    | 950m   | CARRIAGEWAY | Pothole (POTH)                             | CAT 1           | 15/02/2018               | Completed Defects | 05/03/2018      | A77 SB CW, 200M NTH OF WHITEGATES, NTH OF KIRKOSWALD    |
| SW82317666-235521324   | 1,126m  | 1,128m | CARRIAGEWAY | Pothole (POTH)                             | CAT 1           | 15/02/2018               | Completed Defects | 09/02/2018      | A77 SB CW, 400M NTH OF WHITEGATES, NTH OF KIRKOSWALD    |
| SW82317666-235521326   | 1,287m  | 1,288m | CARRIAGEWAY | Pothole (POTH)                             | CAT 1           | 15/02/2018               | Completed Defects | 23/02/2018      | A77 NB CW, 550M NTH OF WHITEGATES, NTH OF KIRKOSWALD    |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>  |         |        |             |  |                 |                          |                   |                 |   |
| SW82317793-235529563   | 32m     | 34m    | CARRIAGEWAY | Pothole (POTH)                             | CAT 1           | 22/02/2018               | Completed Defects | 08/02/2018      | A77 SB CW, 50M STH OF KIRKOSWALD NTH GATEWAY            |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b> |         |        |             |  |                 |                          |                   |                 |   |
| SW82318129-235532265   | 2,212m  | 2,222m | CARRIAGEWAY | Pothole (POTH)                             | CAT 1           | 01/03/2018               | Completed Defects | 01/02/2018      | A77 MOSSIDE LAYBY                                       |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b> |         |        |             |  |                 |                          |                   |                 |   |
| SW82319037-235539776   | 2,069m  | 2,075m | CARRIAGEWAY | Pothole (POTH)                             | CAT 1           | 08/03/2018               | Completed Defects | 08/02/2018      | A77 NB CW, OPP SB LAYBY, MOSSIDE                        |
| SW82319037-235539778   | 859m    | 870m   | CARRIAGEWAY | Pothole (POTH)                             | CAT 1           | 08/03/2018               | Completed Defects | 08/02/2018      | A77 ON CL, OPPOSITE WHITEGATES, NTH OF KIRKOSWALD       |
| SW82319037-235539775   | 2,031m  | 2,035m | CARRIAGEWAY | Pothole (POTH)                             | CAT 1           | 08/03/2018               | Completed Defects | 08/02/2018      | A77 NB CW, OPPOSITE SB LAYBY, MOSSIDE                   |
| SW82319037-235539777   | 2,093m  | 2,099m | CARRIAGEWAY | Pothole (POTH)                             | CAT 1           | 08/03/2018               | Completed Defects | 08/02/2018      | A77 NB CW, OPP SB LAYBY, MOSSIDE                        |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b> |         |        |             |  |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |  |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b> |         |        |             |  |                 |                          |                   |                 |   |
| SW82321955-235548220   | 1,169m  | 1,179m | CARRIAGEWAY | Patch - loss of material (fretting) (PLMT) | CAT 1           | 22/03/2018               | Completed Defects | 23/02/2018      | 1200 METERS NORTH OF AUCHINBLANE                        |
| SW82321955-235548219   | 1,244m  | 1,247m | CARRIAGEWAY | Pothole (POTH)                             | CAT 1           | 22/03/2018               | Completed Defects | 23/02/2018      | A77 NB CW AT AUCHINBLANE 1300 M NORTH OF KIRKOSWALD     |
| SW82321955-235548221   | 925m    | 926m   | CARRIAGEWAY | Pothole (POTH)                             | CAT 1           | 22/03/2018               | Completed Defects | 23/02/2018      | A77 SIB CW JUST NORTH OF WHITEGATES NORTH OF KIRKOSWALD |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>    |         |        |             |  |                 |                          |                   |                 |   |
| SW82323945-235550798   | 28m     | 29m    | CARRIAGEWAY | Pothole (POTH)                             | CAT 1           | 29/03/2018               | Completed Defects | 01/03/2018      | A77 NB CW, AT KIRKOSWALD NTH GATEWAY                    |
| SW82323945-235550800   | 2,611m  | 2,612m | CARRIAGEWAY | Pothole (POTH)                             | CAT 1           | 29/03/2018               | Completed Defects | 02/03/2018      | A77 NB CW, 600M NTH OF MOSSIDE LAYBY, NTH OF KIRKOSWALD |
| SW82323945-235550799   | 2,078m  | 2,079m | CARRIAGEWAY | Pothole (POTH)                             | CAT 1           | 29/03/2018               | Completed Defects | 01/03/2018      | A77 NB CW, OPPOSITE MOSSIDE LAYBY, NTH OF KIRKOSWALD    |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail             | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description   |
|--|---------|--------|-------------|-------------------------|-----------------|--------------------------|-----------------------|-----------------|--|
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>        |         |        |             |                         |                 |                          |                       |                 |  |
| SW82326075-235554294   | 2,689m  | 2,690m | CARRIAGEWAY | Pothole (POTH)          | CAT 1           | 05/04/2018               | Completed Defects     | 08/03/2018      | A77 SB CW, 100M NTH OF SB MOSSIDE LAYBY                      |
| SW82326075-235554295   | 1,643m  | 1,645m | CARRIAGEWAY | Pothole (POTH)          | CAT 1           | 05/04/2018               | Completed Defects     | 08/03/2018      | A77 SB CW, 300M STH OF MOSSIDE LAYBY                         |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>        |         |        |             |                         |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                         |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>        |         |        |             |                         |                 |                          |                       |                 |  |
| SW82330474-235608120   | 2,118m  | 2,119m | CARRIAGEWAY | Pothole (POTH)          | CAT 1           | 19/04/2018               | Completed Defects     | 23/03/2018      | A77 NB CW, AT MOSSIDE LAYBY                                  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>        |         |        |             |                         |                 |                          |                       |                 |  |
| SW80-332117-235613702  | 2,044m  | 2,045m | CARRIAGEWAY | Pothole (POTH)          | CAT 1           | 26/04/2018               | Completed Defects     | 29/03/2018      | A77 NB CW, OPPOSITE MOSSIDE SB LAYBY                         |
| SW80-332117-235613704  | 316m    | 319m   | CARRIAGEWAY | Pothole (POTH)          | CAT 1           | 26/04/2018               | Completed Defects     | 29/03/2018      | A77 NB CW, 265M NTH OF KIRKOSAL NTH GATEWAY                  |
| SW80-332117-235613703  | 331m    | 333m   | CARRIAGEWAY | Pothole (POTH)          | CAT 1           | 26/04/2018               | Completed Defects     | 29/03/2018      | A77 NB CW, 250M NTH OF KRKSWALD NTH GATEWAY                  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>        |         |        |             |                         |                 |                          |                       |                 |  |
| SW82334882-235613705   | 1,427m  | 0m     | CARRIAGEWAY | Pothole VIAFIX (POTV)   | CAT 1           | 06/04/2018               | Completed Defects     | 05/04/2018      | A77 OLD TOLL COTTAGE TO BLANEFIELD JCT                       |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>        |         |        |             |                         |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                         |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>        |         |        |             |                         |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                         |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>        |         |        |             |                         |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                         |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>          |         |        |             |                         |                 |                          |                       |                 |  |
| SW82344114-235554295   | 1,056m  | 0m     | CARRIAGEWAY | Pothole VIAFIX (POTV)   | CAT 1           | 04/05/2018               | Completed Defects     | 03/05/2018      | A77 SB AUCHENBLAINE LANE 1 NS WT                             |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>          |         |        |             |                         |                 |                          |                       |                 |  |
| SW82346930-235712675   | 1,418m  | 1,419m | CARRIAGEWAY | Pothole VIAFIX (POTV)   | CAT 1           | 07/06/2018               | Completed Defects     | 10/05/2018      | A77 SB CW 50M NORTH OF THE WHITE GATES NORTH OF KIRKOSWALD   |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |         |        |             |                         |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                         |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |         |        |             |                         |                 |                          |                       |                 |  |
| SW82352984-235812708   | 881m    | 882m   | CARRIAGEWAY | Pothole VIAFIX (POTV)   | CAT 1           | 21/06/2018               | Completed Defects     | 24/05/2018      | A77 SB CW WHITEGATES 600M NORTH OF KIRKOSWALD                |
| SW82352984-235812710   | 2,107m  | 2,108m | CARRIAGEWAY | Pothole VIAFIX (POTV)   | CAT 1           | 21/06/2018               | Completed Defects     | 24/05/2018      | A77 SB CW AT LAYBY SOUTH OF MOSSIDE COTTAGE SOUTH OF MAYBOLE |
| SW82352984-235812709   | 2,153m  | 2,154m | CARRIAGEWAY | Pothole VIAFIX (POTV)   | CAT 1           | 21/06/2018               | Completed Defects     | 24/05/2018      | A77 SB CW MOSSIDE COTTAGE SOUTH OF MAYBOLE                   |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |         |        |             |                         |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                         |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |         |        |             |                         |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                         |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |         |        |             |                         |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                         |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |         |        |             |                         |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                         |                 |                          |                       |                 |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |         |        |             |                         |                 |                          |                       |                 |  |
| SW86-357213-2  | 443m    | 463m   | WOODLAND    | Invasive species (INVS) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |         |        |             |                         |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                         |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |         |        |             |                         |                 |                          |                       |                 |  |

| Defect Reference   | Start m | End m  | Item Type     | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description  |
|--|---------|--------|---------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |         |        |               |                                      |                 |                          |                       |                 |   |
| SW82377424-235909973   | 2,098m  | 2,099m | CARRIAGEWAY   | Pothole (POTH)                       | CAT 1           | 09/08/2018               | Completed Defects     | 12/07/2018      | A77 ON CL, 20M STH OF MOSSIDE LAYY, NTH OF KIRKOSWALD           |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |         |        |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |         |        |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |         |        |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |         |        |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |         |        |               |                                      |                 |                          |                       |                 |   |
| SW80-394061-235954868  | 2,938m  | 2,938m | TRAFFIC_SIGNS | Other (OTHR)                         | CAT 1           | 17/08/2018               | Completed Defects     | 16/08/2018      | A77 N/B VERGE 200M SOUTH OF CROSSREAGUAL ABBEY SOUTH OF MAYBOLE |
| SW80-394061-235954857  | 1,409m  | 1,410m | CARRIAGEWAY   | Pothole VIAFIX (POTV)                | CAT 1           | 17/08/2018               | Completed Defects     | 16/08/2018      | A77 S/B C/W 250M SOUTH OF MOSSIDE LAYBY                         |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |         |        |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>       |         |        |               |                                      |                 |                          |                       |                 |   |
| SW80-400497-235984886  | 1,002m  | 1,003m | CARRIAGEWAY   | Pothole VIAFIX (POTV)                | CAT 1           | 31/08/2018               | Completed Defects     | 30/08/2018      | A77 S/B C/W 500M SOUTH OF MOSSIDE LAYBY SOUTH OF MAYBOLE        |
| SW80-400497-235984887  | 1,008m  | 1,009m | CARRIAGEWAY   | Pothole VIAFIX (POTV)                | CAT 1           | 31/08/2018               | Completed Defects     | 30/08/2018      | A77S/B C/W 505M SOUTH OF MOSSIDE LAYBY SOUTH OF MAYBOLE         |
| SW80-400497-235984884  | 1,400m  | 1,401m | CARRIAGEWAY   | Pothole VIAFIX (POTV)                | CAT 1           | 31/08/2018               | Completed Defects     | 30/08/2018      | 400M SOUTH OF MOSSIDEE LAYBY NORTH OF KIRKOSWALD                |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b>    |         |        |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b>    |         |        |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b>    |         |        |               |                                      |                 |                          |                       |                 |   |
| SW82410364-236066539   | 2,076m  | 2,077m | CARRIAGEWAY   | Pothole VIAFIX (POTV)                | CAT 1           | 21/09/2018               | Completed Defects     | 20/09/2018      | A77 NB CW 50M NORTH OF MOSSIDE LAYBY NORTH OF KIRKOSWALD        |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b>    |         |        |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>      |         |        |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>      |         |        |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |         |        |               |                                      |                 |                          |                       |                 |   |
| SW82332071-641   | 556m    | 636m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-644   | 1,173m  | 1,253m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-645   | 1,248m  | 1,328m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-638   | 122m    | 202m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-640   | 346m    | 426m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-647   | 1,712m  | 1,792m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |



| Defect Reference   | Start m | End m  | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description   |
|--|---------|--------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|--|
| SW82332071-648   | 2,181m  | 2,261m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Completed Defects     | 14/12/2018      |  |
| SW82332071-650   | 2,347m  | 2,427m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Completed Defects     | 14/12/2018      |  |
| SW82332071-639   | 311m    | 391m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-646   | 1,615m  | 1,695m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-642   | 815m    | 895m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-643   | 964m    | 1,064m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-649   | 2,172m  | 2,250m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Completed Defects     | 14/12/2018      |  |
| SW82332071-651   | 2,785m  | 2,765m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Completed Defects     | 14/12/2018      |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>  |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW82423458-236136746   | 1,255m  | 1,258m | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 15/11/2018               | Completed Defects     | 18/10/2018      | A77 NB CW, AUCHENBLANE, 300M NTH OF WHITEGATES                 |
| SW82423458-236136747   | 1,457m  | 1,460m | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 15/11/2018               | Completed Defects     | 18/10/2018      | A77 SB CW, 400M STH OF MOSSIDE LAYBY, NTHO OF KIRKOSWALD       |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>  |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW82426441-236211991   | 1,868m  | 1,869m | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 09/11/2018               | Completed Defects     | 08/11/2018      | A77 SB CW AT MEMORIAL LAYBY SOUTH OF MAYBOLE                   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW82426587-236223182   | 1,975m  | 1,976m | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 16/11/2018               | Completed Defects     | 15/11/2018      | A77 SB CW AT MEMORIAL LAYBY SOUTH OF CRSS RAGEL ABBEY          |
| SW82426587-236223184   | 2,863m  | 2,864m | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 16/11/2018               | Completed Defects     | 15/11/2018      | A77 NB CW 700 YAARDS FROM CROSSRAGUEL ABBEY                    |
| SW82426587-236223183   | 2,083m  | 2,084m | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 16/11/2018               | Completed Defects     | 15/11/2018      | A77 NB CW JUST AFTER MEMORIAL LAYBY SOUTH OF CROSSRAGUEL ABBEY |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW82426764-236231625   | 1,878m  | 1,879m | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 23/11/2018               | Completed Defects     | 22/11/2018      | A77 SB CW 15M FROM MEMORIAL LAYBY                              |
| SW82426764-236231628   | 1,450m  | 1,452m | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 23/11/2018               | Completed Defects     | 22/11/2018      | A77 SB CW 400M SOUTH OF MEMORIAL LAYBY                         |
| SW82426764-236231629   | 1,420m  | 1,422m | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 23/11/2018               | Completed Defects     | 22/11/2018      | A77 SB CW 410M SOUTH OF MEMORIAL LAYBY                         |
| SW82426764-236231626   | 1,883m  | 1,884m | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 23/11/2018               | Completed Defects     | 22/11/2018      | A77 SB CW 20M FROM MEMORIAL LAYBY                              |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                                    |
|--|---------|--------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|---|
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| SW82427366-236262616   | 1,444m  | 1,445m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 10/01/2019               | Completed Defects | 14/12/2018      | A77 SB CW, 200M STH OF MOSSIDE LAYBY, NTH OF KIRKOSWALD |
| SW82427366-236262617   | 1,424m  | 1,425m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 10/01/2019               | Completed Defects | 14/12/2018      | A77 SB CW, 210M STH OF MOSSIDE LAYBY                    |
| SW82427366-236262620   | 1,263m  | 1,264m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 10/01/2019               | Completed Defects | 14/12/2018      | A77 SB CW, 410M STH OF MOSSIDE LAYBY                    |
| SW82427366-236262622   | 1,177m  | 1,178m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 10/01/2019               | Completed Defects | 14/12/2018      | A77 SB CW, 450M STH OF MOSSIDE LAYBY                    |
| SW82427366-236262618   | 1,347m  | 1,348m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 10/01/2019               | Completed Defects | 14/12/2018      | A77 SB CW, 300M STH OF MOSSIDE LAYBY                    |
| SW82427366-236262619   | 1,324m  | 1,325m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 10/01/2019               | Completed Defects | 14/12/2018      | A77 SB CW, 310M STH OF MOSSIDE LAYBY                    |
| SW82427366-236262621   | 1,203m  | 1,204m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 10/01/2019               | Completed Defects | 14/12/2018      | A77 SB CW, 420M STH OF MOSSIDE LAYBY                    |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| SW82427527-236264611   | 2,844m  | 2,845m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 17/01/2019               | Completed Defects | 12/01/2019      | A77 NB CW 550 YARDS SOUTH OF CROSSRAGUEL ABBEY          |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| SW82428044-236270557   | 904m    | 905m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 11/01/2019               | Completed Defects | 10/01/2019      | A77 SB CW 200M NORTH OF KIRKOSWALD                      |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| SW82428351-236284326   | 82m     | 83m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 21/02/2019               | Completed Defects | 06/02/2019      | A77 NB CW, KIRKOSWALD NTH GATEWAY                       |
| SW82428351-236284327   | 2,611m  | 2,612m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 21/02/2019               | Completed Defects | 06/02/2019      | A77 NB CW, 500M NTH OF MOSSIDE LAYBY                    |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| SW82428625-236291432   | 1,065m  | 1,066m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 01/02/2019               | Completed Defects | 31/01/2019      | A77 SB CW 1/2 MILE SOUTH OF MOSSIDE LAYBY               |
| SW82428625-236291418   | 1,442m  | 1,443m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 01/02/2019               | Completed Defects | 31/01/2019      | A77 SB CW SOUTH OF MOSSIDE LAYBY                        |
| SW82428625-236291433   | 1,027m  | 1,028m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 01/02/2019               | Completed Defects | 31/01/2019      | A77 SB CW 1/2 MILE SOUTH OF MOSSIDE LIAYBY              |
| SW82428625-236291420   | 1,116m  | 1,117m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 01/02/2019               | Completed Defects | 31/01/2019      | A77 SB CW APROX 250M SOUTH OF MOSSIDE LAYBY             |
| SW82428625-236291434   | 1,007m  | 1,008m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 01/02/2019               | Completed Defects | 31/01/2019      | A77 SB CW 1/2MILE SOUTH OF MOSSIDE LAYBY                |
| SW82428625-236291419   | 1,191m  | 1,192m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 01/02/2019               | Completed Defects | 31/01/2019      | A77 200M SOUTH OF MOSSIDE LAYBY                         |
| SW82428625-236291421   | 1,056m  | 1,057m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 01/02/2019               | Completed Defects | 31/01/2019      | A77 SB CW 1/2 MILE SOUTH OF MOSSIDE LAYBY               |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                        |
|--|---------|--------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|---|
| SW82430228-236328530   | 2,852m  | 2,853m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 14/03/2019               | Completed Defects | 28/02/2018      | A77 N/B 650M PRIOR TO CROSSRAGUEL           |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| SW82436659-236335201   | 871m    | 876m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 28/03/2019               | Completed Defects | 08/03/2019      | A77 S/B AT WHITE GATES KIRKOSWALD           |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| SW82453127-236489172   | 1,410m  | 1,410m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 22/03/2019               | Completed Defects | 21/03/2019      | A77 S/B OLD TOLL COTTAGE TO BLANEFIELD JCT  |
| SW82453127-236489174   | 1,207m  | 1,207m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 22/03/2019               | Completed Defects | 21/03/2019      | A77 S/B OLD TOLL COTTAGE TO BLANEFIELD FARM |
| SW82453127-236489173   | 1,221m  | 1,221m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 22/03/2019               | Completed Defects | 21/03/2019      | A77 S/B OLD TOLL COTTAGE TO BLANEFIELD JCT  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>11626/79 : JCT BLANEFIELD TO JUNCTION BROOMKNOWES FARM</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| SW82317326-235513691   | 1,722m  | 1,723m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 01/02/2018               | Completed Defects | 08/02/2018      | 100meters south of mossie lay by sb cw      |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>      |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>      |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |

| Defect Reference   | Start m | End m  | Item Type     | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description   |
|--|---------|--------|---------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|--|
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |         |        |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |         |        |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |         |        |               |                                      |                 |                          |                       |                 |  |
| SW82356191-235816781   | 1,187m  | 1,188m | CARRIAGEWAY   | Pothole (POTH)                       | CAT 1           | 28/06/2018               | Completed Defects     | 01/06/2018      | A77 NB CW CL 100M SOUTH OF BALTERSTERN FARM SOUTH OF MAYBOLE |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |         |        |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |         |        |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |         |        |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |         |        |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |         |        |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |         |        |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |         |        |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |         |        |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |         |        |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |         |        |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |         |        |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |         |        |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |         |        |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>       |         |        |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b>    |         |        |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b>    |         |        |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b>    |         |        |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b>    |         |        |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>      |         |        |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>      |         |        |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>      |         |        |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>      |         |        |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |         |        |               |                                      |                 |                          |                       |                 |  |
| SW82332071-728   | 559m    | 639m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-730   | 591m    | 592m   | TRAFFIC_SIGNS | Physical condition of post (COPT)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-746   | 1,884m  | 1,964m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-748   | 2,123m  | 2,203m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |

| Defect Reference | Start m | End m  | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|--------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82332071-733   | 761m    | 861m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-735   | 825m    | 905m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-742   | 1,386m  | 1,466m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-744   | 1,610m  | 1,690m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-723   | 21m     | 101m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-725   | 300m    | 380m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-739   | 1,043m  | 1,143m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-740   | 1,155m  | 1,235m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-736   | 837m    | 917m   | FOOTWAY            | Other (OTHR)                         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-743   | 1,516m  | 1,596m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-724   | 192m    | 270m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-729   | 566m    | 646m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-732   | 683m    | 763m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-745   | 1,773m  | 1,853m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-747   | 2,016m  | 2,096m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-727   | 468m    | 568m   | FOOTWAY            | Other (OTHR)                         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-731   | 622m    | 722m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-734   | 783m    | 863m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-741   | 1,234m  | 1,314m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-726   | 400m    | 480m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |

| Defect Reference   | Start m | End m  | Item Type     | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                               |
|--|---------|--------|---------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|--|
| SW82332071-737   | 895m    | 975m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-738   | 965m    | 1,045m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b> |         |        |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b> |         |        |               |                                      |                 |                          |                       |                 |  |
| SW82426441-236211992   | 1,107m  | 1,108m | TRAFFIC_SIGNS | Pointing wrong way (RWAY)            | CAT 1           | 09/11/2018               | Completed Defects     | 08/11/2018      | A77 SB CW 500M BEFORE CROSSRAGUEL ABBEY            |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b> |         |        |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b> |         |        |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b> |         |        |               |                                      |                 |                          |                       |                 |  |
| SW82426917-236234304   | 2,126m  | 2,127m | TRAFFIC_SIGNS | Pointing wrong way (RWAY)            | CAT 1           | 30/11/2018               | Completed Defects     | 29/11/2018      | A77 SB CW 200M FROMCMAYBOLE SOUTH GATEWAY          |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b> |         |        |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b> |         |        |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b> |         |        |               |                                      |                 |                          |                       |                 |  |
| SW82427527-236264589   | 2,067m  | 2,068m | TRAFFIC_SIGNS | Pointing wrong way (RWAY)            | CAT 1           | 21/12/2018               | Completed Defects     | 20/12/2018      | A77 SB CW 200M SOUTH OF MAYBOLE SOUTH GATEWAY      |
| SW82427527-236264591   | 695m    | 696m   | CARRIAGEWAY   | Pothole (POTH)                       | CAT 1           | 17/01/2019               | Completed Defects     | 11/01/2019      | A77 SB CW AT LAYBY 100M NORTH OF CROSSRAGUEL ABBEY |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b> |         |        |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>  |         |        |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>  |         |        |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>  |         |        |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>  |         |        |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>  |         |        |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b> |         |        |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b> |         |        |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b> |         |        |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b> |         |        |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>    |         |        |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>    |         |        |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>    |         |        |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>    |         |        |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>11629/05 : JCT BROOMKNOWES FM TO 30 MPH SIGN MAYBOLE</b>      |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>  |         |        |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>  |         |        |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>  |         |        |               |                                      |                 |                          |                       |                 |  |

| Defect Reference   | Start m | End m | Item Type   | Item Detail    | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                             |
|--|---------|-------|-------------|----------------|-----------------|--------------------------|-------------------|-----------------|--|
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>      |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b>     |         |       |             |                |                 |                          |                   |                 |  |
| SW82318129-235532264   | 227m    | 230m  | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 01/03/2018               | Completed Defects | 01/02/2018      | A77 MAYBOLE STH GATEWAY                          |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b>     |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b>     |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b>     |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>        |         |       |             |                |                 |                          |                   |                 |  |
| SW82323945-235550801   | 113m    | 114m  | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 29/03/2018               | Completed Defects | 02/03/2018      | A77 NB CW, MAYBOLE STH GATEWAY                   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>        |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>        |         |       |             |                |                 |                          |                   |                 |  |
| SW82328086-235590036   | 20m     | 28m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 12/04/2018               | Completed Defects | 16/03/2018      | A77 BOTH CW, MAYBOLE STH GATEWAY, 100M STH TO GW |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>        |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>        |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>        |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>        |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>        |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>        |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>          |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>          |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |         |       |             |                |                 |                          |                   |                 |  |

| Defect Reference   | Start m | End m | Item Type     | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                          |
|--|---------|-------|---------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>       |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b>    |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b>    |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b>    |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b>    |         |       |               |                                      |                 |                          |                       |                 |   |
| SW80-413634-236087131  | 191m    | 195m  | TREE          | Overhanging/overgrown (OVER)         | CAT 1           | 28/09/2018               | Completed Defects     | 27/09/2018      | A77 NB CW 100M NORTH OF MAYBOLE SOUTH GATEWAY |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>      |         |       |               |                                      |                 |                          |                       |                 |   |
| SW82416981-236101750   | 146m    | 147m  | CARRIAGEWAY   | Pothole VIAFIX (POTV)                | CAT 1           | 05/10/2018               | Completed Defects     | 04/10/2018      | A77 NB CW AT LAYBY AT MAYBOLE SOUTH GATE      |
| SW82416981-236101752   | 164m    | 165m  | CARRIAGEWAY   | Pothole VIAFIX (POTV)                | CAT 1           | 05/10/2018               | Completed Defects     | 04/10/2018      | A77 NB CW 25M PRIOR TO MAYBOLE SOUTH GATEWAY  |
| SW82416981-236101751   | 153m    | 154m  | CARRIAGEWAY   | Pothole VIAFIX (POTV)                | CAT 1           | 05/10/2018               | Completed Defects     | 04/10/2018      | A77 NB CW 20M PRIOR TO MAYBOLE SOUTH GATEWAY  |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>      |         |       |               |                                      |                 |                          |                       |                 |   |
| SW82420227-236118421   | 183m    | 184m  | TRAFFIC_SIGNS | Pointing wrong way (RWAY)            | CAT 1           | 12/10/2018               | Completed Defects     | 11/10/2018      | A78 NB CW 100M FROM MAYBOLE SOUTH GATEWAY     |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>      |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>      |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |         |       |               |                                      |                 |                          |                       |                 |   |
| SW82332071-749   | 126m    | 206m  | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>     |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>     |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>     |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b>     |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b>     |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b>     |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b>     |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b>     |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b>     |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>      |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>      |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>      |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>      |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>      |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b>     |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |   |



| Defect Reference   | Start m | End m | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description   |
|--|---------|-------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|--|
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b>                                 |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b>                                 |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b>                                 |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>                                    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>                                    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>                                    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>                                    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>11629/11 : 30MPH SIGN MAYBOLE TO JUNCTION LADYLAND ROAD</b>                                   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>                                  |         |       |             |                       |                 |                          |                   |                 |  |
| SW82317326-235513690   | 188m    | 190m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 01/02/2018               | Completed Defects | 26/01/2018      | opposite maybole academy at splitter island sb cw at last bungalow |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>                                  |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 18 January 2018</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>                                  |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>                                  |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b>                                 |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b>                                 |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 15 February 2018</b> |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b>                                 |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b>                                 |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>                                    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>                                    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>                                    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 16 March 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>                                    |         |       |             |                       |                 |                          |                   |                 |  |
| SW82330474-235608121   | 125m    | 126m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 19/04/2018               | Completed Defects | 22/03/2018      | A77 SB CW, OPPOSITE CARRICK ACADEMY, MAYBOLE                       |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>                                    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>                                    |         |       |             |                       |                 |                          |                   |                 |  |
| SW82334882-235613703   | 89m     | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 06/04/2018               | Completed Defects | 05/04/2018      | A77 N/B AT ENTRANCE TO CARRICK ACADEMY                             |
| SW82334882-235613704   | 122m    | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 06/04/2018               | Completed Defects | 05/04/2018      | A77 S/B OPP CARRICK ACADEMY  |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 12 April 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>                                    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>                                    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>                                    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |

| Defect Reference   | Start m | End m | Item Type   | Item Detail    | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                                     |
|--|---------|-------|-------------|----------------|-----------------|--------------------------|-------------------|-----------------|--|
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>                                    |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 10 May 2018</b>    |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>                                    |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>                                    |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>                                    |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>                                    |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 07 June 2018</b>   |         |       |             |                |                 |                          |                   |                 |  |
| SW80-359134-1  | 231m    | 232m  | FOOTWAY     | Other (OTHR)   | CAT 1           | 05/07/2018               | Completed Defects | 07/06/2018      | A77 OUTSIDE CHECKERS DINER MAYBOLE                       |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>                                   |         |       |             |                |                 |                          |                   |                 |  |
| SW80-359626-235827134  | 13m     | 14m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 05/07/2018               | Completed Defects | 03/07/2018      | A77 SB CW OPPOSITE DULNAIN COTTAGE KIRKOSWALD RD MAYBOLE |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>                                   |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>                                   |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b>                           |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>                                   |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 05 July 2018</b>   |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>                                   |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>                                   |         |       |             |                |                 |                          |                   |                 |  |
| SW82377424-235909975   | 89m     | 92m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 09/08/2018               | Completed Defects | 24/07/2018      | A77 SB CW, OPPOSITE CARRICK ACADEMY AT ISLAND, MAYBOLE   |
| SW82377424-235909974   | 158m    | 160m  | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 09/08/2018               | Completed Defects | 24/07/2018      | A77 SB CW, OPPOSITE CARRICK ACADEMY MAYBOLE              |
| SW82377424-235909976   | 606m    | 610m  | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 09/08/2018               | Completed Defects | 24/07/2018      | A77 SB CW, KIRKOSALD ROAD NO.4 MAYBOLE                   |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>                                   |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>                                   |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 02 August 2018</b> |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>                                 |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>                                 |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>                                 |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>                                 |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>                                 |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 31 August 2018</b> |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b>                              |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b>                              |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b>                              |         |       |             |                |                 |                          |                   |                 |  |

| Defect Reference  | Start m | End m | Item Type   | Item Detail                            | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                             |
|---|---------|-------|-------------|--|-----------------|--------------------------|-----------------------|-----------------|--|
| SW82410364-236066540  | 604m    | 605m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                  | CAT 1           | 21/09/2018               | Completed Defects     | 20/09/2018      | A77 NB CW LADYLAND ROAD MAYBOLE                  |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 24 September 2018</b> |         |       |             |  |                 |                          |                       |                 |  |
| SW82411118-1  | 558m    | 559m  | FOOTWAY     | Bituminous surfacing - potholes (BPOT) | CAT 1           | 25/09/2018               | Completed Defects     | 24/09/2018      | CHECKERS DINER MAYBOLE<                          |
| SW82411118-2  | 503m    | 504m  | FOOTWAY     | Bituminous surfacing - potholes (BPOT) | CAT 1           | 25/09/2018               | Completed Defects     | 24/09/2018      | JAMIESON PLANT HIRE MAYBOLE                      |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b>                                 |         |       |             |  |                 |                          |                       |                 |  |
| No defects recorded   |         |       |             |  |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>                                   |         |       |             |  |                 |                          |                       |                 |  |
| No defects recorded   |         |       |             |  |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>                                   |         |       |             |  |                 |                          |                       |                 |  |
| No defects recorded   |         |       |             |  |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>                                   |         |       |             |  |                 |                          |                       |                 |  |
| SW82423458-236136749  | 589m    | 590m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                  | CAT 1           | 15/11/2018               | Completed Defects     | 18/10/2018      | A77 ON NB CW, OPPOSITE OLD COTTAGE MAYBOLE       |
| SW82423458-236136748  | 439m    | 440m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                  | CAT 1           | 15/11/2018               | Completed Defects     | 18/10/2018      | A77 NB CW, MAYBOLE, OUTSIDE JAMIESONS YARD       |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 25 October 2018</b>   |         |       |             |  |                 |                          |                       |                 |  |
| No defects recorded   |         |       |             |  |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>                                   |         |       |             |  |                 |                          |                       |                 |  |
| No defects recorded   |         |       |             |  |                 |                          |                       |                 |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b>                              |         |       |             |  |                 |                          |                       |                 |  |
| SW82332071-750  | 141m    | 221m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT)   | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-751  | 377m    | 457m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT)   | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>                                  |         |       |             |  |                 |                          |                       |                 |  |
| No defects recorded   |         |       |             |  |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>                                  |         |       |             |  |                 |                          |                       |                 |  |
| No defects recorded   |         |       |             |  |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>                                  |         |       |             |  |                 |                          |                       |                 |  |
| No defects recorded   |         |       |             |  |                 |                          |                       |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 22 November 2018</b>  |         |       |             |  |                 |                          |                       |                 |  |
| No defects recorded   |         |       |             |  |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b>                                  |         |       |             |  |                 |                          |                       |                 |  |
| SW82426764-236231624  | 531m    | 532m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                  | CAT 1           | 23/11/2018               | Completed Defects     | 22/11/2018      | A77 NB CW AT DAILLY JCT MAYBOLE                  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b>                                  |         |       |             |  |                 |                          |                       |                 |  |
| No defects recorded   |         |       |             |  |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b>                                  |         |       |             |  |                 |                          |                       |                 |  |
| No defects recorded   |         |       |             |  |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b>                                  |         |       |             |  |                 |                          |                       |                 |  |
| SW82427366-236262623  | 493m    | 494m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                  | CAT 1           | 10/01/2019               | Completed Defects     | 14/12/2018      | A77 NB CW, OUTSIDE JAMIESONS PLANT HIRE, MAYBOLE |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 20 December 2018</b>  |         |       |             |  |                 |                          |                       |                 |  |
| No defects recorded   |         |       |             |  |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b>                                  |         |       |             |  |                 |                          |                       |                 |  |
| No defects recorded   |         |       |             |  |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b>                                  |         |       |             |  |                 |                          |                       |                 |  |
| No defects recorded   |         |       |             |  |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>                                   |         |       |             |  |                 |                          |                       |                 |  |
| No defects recorded   |         |       |             |  |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>                                   |         |       |             |  |                 |                          |                       |                 |  |
| No defects recorded   |         |       |             |  |                 |                          |                       |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 17 January 2019</b>   |         |       |             |  |                 |                          |                       |                 |  |

| Defect Reference   | Start m | End m | Item Type   | Item Detail                                  | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description        |
|--|---------|-------|-------------|--|-----------------|--------------------------|-----------------------|-----------------|-----------------------------|
| <i>No defects recorded</i>   |         |       |             |  |                 |                          |                       |                 |                             |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>                                  |         |       |             |  |                 |                          |                       |                 |                             |
| <i>No defects recorded</i>   |         |       |             |  |                 |                          |                       |                 |                             |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>                                  |         |       |             |  |                 |                          |                       |                 |                             |
| <i>No defects recorded</i>   |         |       |             |  |                 |                          |                       |                 |                             |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>                                  |         |       |             |  |                 |                          |                       |                 |                             |
| <i>No defects recorded</i>   |         |       |             |  |                 |                          |                       |                 |                             |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b>                                 |         |       |             |  |                 |                          |                       |                 |                             |
| <i>No defects recorded</i>   |         |       |             |  |                 |                          |                       |                 |                             |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b>                                 |         |       |             |  |                 |                          |                       |                 |                             |
| <i>No defects recorded</i>   |         |       |             |  |                 |                          |                       |                 |                             |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 15 February 2019</b> |         |       |             |  |                 |                          |                       |                 |                             |
| SW82429956-30  | 236m    | 246m  | FOOTWAY     | Bituminous surfacing - local cracking (BLCK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                             |
| SW82429956-2   | 148m    | 150m  | FOOTWAY     | Bituminous surfacing - local cracking (BLCK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                             |
| SW82429956-4   | 324m    | 325m  | FOOTWAY     | Bituminous surfacing - local cracking (BLCK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                             |
| SW82429956-1   | 134m    | 136m  | FOOTWAY     | Bituminous surfacing - local cracking (BLCK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                             |
| SW82429956-26  | 597m    | 598m  | FOOTWAY     | Bituminous surfacing - potholes (BPOT)       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                             |
| SW82429956-5   | 357m    | 359m  | FOOTWAY     | Bituminous surfacing - local cracking (BLCK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                             |
| SW82429956-27  | 470m    | 480m  | FOOTWAY     | Bituminous surfacing - local cracking (BLCK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                             |
| SW82429956-29  | 311m    | 313m  | FOOTWAY     | Bituminous surfacing - local cracking (BLCK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                             |
| SW82429956-6   | 398m    | 400m  | FOOTWAY     | Bituminous surfacing - local cracking (BLCK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                             |
| SW82429956-3   | 309m    | 310m  | FOOTWAY     | Bituminous surfacing - local cracking (BLCK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                             |
| SW82429956-28  | 438m    | 448m  | FOOTWAY     | Bituminous surfacing - local cracking (BLCK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                             |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b>                                 |         |       |             |  |                 |                          |                       |                 |                             |
| SW82433243-236330736   | 597m    | 597m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                        | CAT 1           | 22/02/2019               | Completed Defects     | 21/02/2019      | A77 N/B @LADYLAND ROAD JCT  |
| SW82433243-236330737   | 607m    | 607m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                        | CAT 1           | 22/02/2019               | Completed Defects     | 21/02/2019      | A77 N/B @ LADYLAND ROAD JCT |

| Defect Reference     | Start m | End m | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                               |
|----------------------|---------|-------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|--|
| SW82433243-236330734 | 50m     | 50m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 22/02/2019               | Completed Defects | 21/02/2019      | A77 N/B 60MTRS BEFORE CARRICK SCHOOL               |
| SW82433243-236330738 | 596m    | 596m  | GULLY       | Blockage (BLOK)       | CAT 1           | 21/03/2019               | Completed Defects | 12/03/2019      | A77 N/B @ NO 4 KIRKOSWALD ROAD @ LALYLAND ROAD JCT |
| SW82433243-236330735 | 591m    | 591m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 22/02/2019               | Completed Defects | 21/02/2019      | A77 N/B @ MAYBOLE LADYLAND ROAD JCT                |

**Safety Inspection of A77 Ayr South V1 on 28 February 2019**

No defects recorded

**Safety Inspection of A77 Ayr South V1 on 07 March 2019**

No defects recorded

**Safety Inspection of A77 Ayr South V1 on 14 March 2019**

No defects recorded

**Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 15 March 2019**

|               |      |      |         |  |       |            |                       |            |  |
|---------------|------|------|---------|--|-------|------------|-----------------------|------------|--|
| SW82446495-4  | 379m | 384m | FOOTWAY | Bituminous surfacing - extensive cracking (BECK) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 |  |
| SW82446495-18 | 50m  | 60m  | FOOTWAY | Bituminous surfacing - extensive cracking (BECK) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 |  |
| SW82446495-19 | 6m   | 16m  | FOOTWAY | Bituminous surfacing - extensive cracking (BECK) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 |  |
| SW82446495-3  | 313m | 315m | FOOTWAY | Bituminous surfacing - extensive cracking (BECK) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 |  |
| SW82446495-6  | 515m | 520m | FOOTWAY | Bituminous surfacing - extensive cracking (BECK) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 |  |
| SW82446495-1  | 233m | 235m | FOOTWAY | Bituminous surfacing - extensive cracking (BECK) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 |  |
| SW82446495-2  | 278m | 288m | FOOTWAY | Bituminous surfacing - extensive cracking (BECK) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 |  |
| SW82446495-5  | 494m | 500m | FOOTWAY | Bituminous surfacing - extensive cracking (BECK) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 |  |
| SW82446495-17 | 483m | 490m | FOOTWAY | Bituminous surfacing - extensive cracking (BECK) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 |  |

**Safety Inspection of A77 Ayr South V1 on 21 March 2019**

No defects recorded

**Safety Inspection of A77 Ayr South V1 on 28 March 2019**

No defects recorded



| Defect Reference  | Start<br>m | End<br>m | Item Type   | Item Detail           | Defect<br>Category | Required<br>Completion Date | Current Status        | Completion<br>Date | Location Description                           |
|---|------------|----------|-------------|-----------------------|--------------------|-----------------------------|-----------------------|--------------------|--|
| <b>11629/32 : JUNCTION LADYLAND ROAD TO JUNCTION JOHN KNOX ST</b>                         |            |          |             |                       |                    |                             |                       |                    |  |
| Safety Inspection of A77 Ayr South V1 on 04 January 2018                                  |            |          |             |                       |                    |                             |                       |                    |  |
| No defects recorded   |            |          |             |                       |                    |                             |                       |                    |  |
| Safety Inspection of A77 Ayr South V1 on 11 January 2018                                  |            |          |             |                       |                    |                             |                       |                    |  |
| No defects recorded   |            |          |             |                       |                    |                             |                       |                    |  |
| Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 18 January 2018  |            |          |             |                       |                    |                             |                       |                    |  |
| No defects recorded   |            |          |             |                       |                    |                             |                       |                    |  |
| Safety Inspection of A77 Ayr South V1 on 18 January 2018                                  |            |          |             |                       |                    |                             |                       |                    |  |
| SW82317666-235521328  | 142m       | 152m     | CARRIAGEWAY | Failed repair (RFAL)  | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         | A77 SB CW, WHITEHALL STREET MAYBOLE            |
| Safety Inspection of A77 Ayr South V1 on 25 January 2018                                  |            |          |             |                       |                    |                             |                       |                    |  |
| No defects recorded   |            |          |             |                       |                    |                             |                       |                    |  |
| Safety Inspection of A77 Ayr South V1 on 01 February 2018                                 |            |          |             |                       |                    |                             |                       |                    |  |
| No defects recorded   |            |          |             |                       |                    |                             |                       |                    |  |
| Safety Inspection of A77 Ayr South V1 on 08 February 2018                                 |            |          |             |                       |                    |                             |                       |                    |  |
| No defects recorded   |            |          |             |                       |                    |                             |                       |                    |  |
| Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 15 February 2018 |            |          |             |                       |                    |                             |                       |                    |  |
| No defects recorded   |            |          |             |                       |                    |                             |                       |                    |  |
| Safety Inspection of A77 Ayr South V1 on 15 February 2018                                 |            |          |             |                       |                    |                             |                       |                    |  |
| No defects recorded   |            |          |             |                       |                    |                             |                       |                    |  |
| Safety Inspection of A77 Ayr South V1 on 22 February 2018                                 |            |          |             |                       |                    |                             |                       |                    |  |
| No defects recorded   |            |          |             |                       |                    |                             |                       |                    |  |
| Safety Inspection of A77 Ayr South V1 on 01 March 2018                                    |            |          |             |                       |                    |                             |                       |                    |  |
| No defects recorded   |            |          |             |                       |                    |                             |                       |                    |  |
| Safety Inspection of A77 Ayr South V1 on 08 March 2018                                    |            |          |             |                       |                    |                             |                       |                    |  |
| No defects recorded   |            |          |             |                       |                    |                             |                       |                    |  |
| Safety Inspection of A77 Ayr South V1 on 15 March 2018                                    |            |          |             |                       |                    |                             |                       |                    |  |
| No defects recorded   |            |          |             |                       |                    |                             |                       |                    |  |
| Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 16 March 2018    |            |          |             |                       |                    |                             |                       |                    |  |
| SW82327808-1  | 54m        | 104m     | FOOTWAY     | Other (OTHR)          | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         | MAYBOLE FOOTWAY                                |
| SW82327808-2  | 159m       | 209m     | FOOTWAY     | Other (OTHR)          | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         | MAYBOLE FOOTWAY                                |
| Safety Inspection of A77 Ayr South V1 on 22 March 2018                                    |            |          |             |                       |                    |                             |                       |                    |  |
| No defects recorded   |            |          |             |                       |                    |                             |                       |                    |  |
| Safety Inspection of A77 Ayr South V1 on 29 March 2018                                    |            |          |             |                       |                    |                             |                       |                    |  |
| No defects recorded   |            |          |             |                       |                    |                             |                       |                    |  |
| Safety Inspection of A77 Ayr South V1 on 05 April 2018                                    |            |          |             |                       |                    |                             |                       |                    |  |
| SW82334882-235613711  | 193m       | 0m       | CARRIAGEWAY | Pothole (POTH)        | CAT 1              | 03/05/2018                  | Completed Defects     | 18/04/2018         | A77 S/B OUTSIDE NUMBER 15A MAYBOLE HIGH STREET |
| SW82334882-235613702  | 311m       | 0m       | CATCHPIT    | Missing (MISS)        | 3RD PTY            | 06/04/2018                  | Completed Defects     | 05/04/2018         |  |
| Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 12 April 2018    |            |          |             |                       |                    |                             |                       |                    |  |
| No defects recorded   |            |          |             |                       |                    |                             |                       |                    |  |
| Safety Inspection of A77 Ayr South V1 on 12 April 2018                                    |            |          |             |                       |                    |                             |                       |                    |  |
| SW82336916-235633870  | 154m       | 174m     | CARRIAGEWAY | Failed repair (RFAL)  | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         | A77 MAYBOLE OPPOSITE CHIPPY                    |
| Safety Inspection of A77 Ayr South V1 on 19 April 2018                                    |            |          |             |                       |                    |                             |                       |                    |  |
| No defects recorded   |            |          |             |                       |                    |                             |                       |                    |  |
| Safety Inspection of A77 Ayr South V1 on 26 April 2018                                    |            |          |             |                       |                    |                             |                       |                    |  |
| No defects recorded   |            |          |             |                       |                    |                             |                       |                    |  |
| Safety Inspection of A77 Ayr South V1 on 03 May 2018                                      |            |          |             |                       |                    |                             |                       |                    |  |
| No defects recorded   |            |          |             |                       |                    |                             |                       |                    |  |
| Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 10 May 2018      |            |          |             |                       |                    |                             |                       |                    |  |
| No defects recorded   |            |          |             |                       |                    |                             |                       |                    |  |
| Safety Inspection of A77 Ayr South V1 on 10 May 2018                                      |            |          |             |                       |                    |                             |                       |                    |  |
| SW82346930-235712671  | 225m       | 226m     | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1              | 07/06/2018                  | Completed Defects     | 10/05/2018         | A77 NB CW AT JCT FOR POLICE STATION MAYBOLE    |

| Defect Reference  | Start m | End m | Item Type   | Item Detail               | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                   |
|---|---------|-------|-------------|---------------------------|-----------------|--------------------------|-------------------|-----------------|--|
| SW82346930-235712674  | 14m     | 15m   | CARRIAGEWAY | Pothole VIAFIX (POTV)     | CAT 1           | 07/06/2018               | Completed Defects | 10/05/2018      | A77 SB CW DAILLY JUNCTION MAYBOLE      |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>                                       |         |       |             |                           |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                           |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>                                       |         |       |             |                           |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                           |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>                                       |         |       |             |                           |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                           |                 |                          |                   |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 07 June 2018</b>      |         |       |             |                           |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                           |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>                                      |         |       |             |                           |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                           |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>                                      |         |       |             |                           |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                           |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>                                      |         |       |             |                           |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                           |                 |                          |                   |                 |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b>                              |         |       |             |                           |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                           |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>                                      |         |       |             |                           |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                           |                 |                          |                   |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 05 July 2018</b>      |         |       |             |                           |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                           |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>                                      |         |       |             |                           |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                           |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>                                      |         |       |             |                           |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                           |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>                                      |         |       |             |                           |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                           |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>                                      |         |       |             |                           |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                           |                 |                          |                   |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 02 August 2018</b>    |         |       |             |                           |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                           |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>                                    |         |       |             |                           |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                           |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>                                    |         |       |             |                           |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                           |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>                                    |         |       |             |                           |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                           |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>                                    |         |       |             |                           |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                           |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>                                    |         |       |             |                           |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                           |                 |                          |                   |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 31 August 2018</b>    |         |       |             |                           |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                           |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b>                                 |         |       |             |                           |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                           |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b>                                 |         |       |             |                           |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                           |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b>                                 |         |       |             |                           |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                           |                 |                          |                   |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 24 September 2018</b> |         |       |             |                           |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                           |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b>                                 |         |       |             |                           |                 |                          |                   |                 |  |
| SW80-413634-236087126   | 137m    | 138m  | GULLY       | Rocking under load (IRLD) | CAT 1           | 25/10/2018               | Completed Defects | 02/11/2018      | A77 SB CW OUTSIDE 27 WHITEHALL MAYBOLE |
| SW80-413634-236087127   | 140m    | 142m  | GULLY       | Rocking under load (IRLD) | CAT 1           | 25/10/2018               | Completed Defects | 22/10/2018      | A77 SB CW OUTSIDE 27 WHITEHALL MAYBOLE |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>                                   |         |       |             |                           |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                           |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>                                   |         |       |             |                           |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                           |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>                                   |         |       |             |                           |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                           |                 |                          |                   |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 25 October 2018</b>   |         |       |             |                           |                 |                          |                   |                 |  |

| Defect Reference   | Start m | End m | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                       |
|--|---------|-------|-------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|--|
| SW80-425909-1  | 143m    | 144m  | FOOTWAY     | Slab profile - uneven/trips (SLPF)   | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>                                  |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b>                             |         |       |             |                                      |                 |                          |                       |                 |  |
| SW82332071-752   | 85m     | 165m  | FOOTWAY     | Other (OTHR)                         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-753   | 231m    | 311m  | FOOTWAY     | Other (OTHR)                         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>                                 |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>                                 |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>                                 |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 22 November 2018</b> |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b>                                 |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b>                                 |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b>                                 |         |       |             |                                      |                 |                          |                       |                 |  |
| SW80-427220-236234305  | 165m    | 165m  | GULLY       | Blockage (BLOK)                      | CAT 1           | 03/01/2019               | Completed Defects     | 06/12/2018      | A77 S/B C/W 100M PRIOR TO THE MAYBOLE ARMS |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b>                                 |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 20 December 2018</b> |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b>                                 |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b>                                 |         |       |             |                                      |                 |                          |                       |                 |  |
| SW82427658-236270457   | 28m     | 29m   | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 28/12/2018               | Completed Defects     | 27/12/2018      | A77 NB CW OUTSIDE 2 KIRKOSWALD ROAD        |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>                                  |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>                                  |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 17 January 2019</b>  |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>                                  |         |       |             |                                      |                 |                          |                       |                 |  |
| SW82428228-236270557   | 149m    | 150m  | GULLY       | Difference in level with road (IDLV) | CAT 1           | 14/02/2019               | Completed Defects     | 13/02/2019      | A77 SB CW OUTSIDE NUMBER 17 WHITEHALL      |
| SW82428228-236270558   | 156m    | 157m  | GULLY       | Difference in level with road (IDLV) | CAT 1           | 14/02/2019               | Completed Defects     | 13/02/2019      | A77 B CW OUTSIDE 17 WHITEHALL MAYBOLE      |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>                                  |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>                                  |         |       |             |                                      |                 |                          |                       |                 |  |
| SW82428625-236291437   | 183m    | 184m  | GULLY       | Difference in level with road (IDLV) | CAT 1           | 28/02/2019               | Completed Defects     | 01/02/2019      | A77 OUTSIDE 27 WHITEHALL MAYBOLE           |
| SW82428625-236291438   | 155m    | 165m  | CHANNEL     | Blockage (BLOK)                      | CAT 1           | 28/02/2019               | Completed Defects     | 01/02/2019      | A77 SB CW OUTSIDE 27 WHITEHALL MAYBOLE     |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b>                                 |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b>                                 |         |       |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 15 February 2019</b> |         |       |             |                                      |                 |                          |                       |                 |  |



| Defect Reference  | Start m | End m | Item Type | Item Detail                                      | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|---|---------|-------|-----------|--|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82429956-10   | 100m    | 104m  | FOOTWAY   | Bituminous surfacing - local cracking (BLCK)     | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82429956-7  | 39m     | 42m   | FOOTWAY   | Bituminous surfacing - local cracking (BLCK)     | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82429956-25   | 113m    | 120m  | FOOTWAY   | Bituminous surfacing - local cracking (BLCK)     | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82429956-14   | 255m    | 275m  | FOOTWAY   | Bituminous surfacing - local cracking (BLCK)     | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82429956-8  | 55m     | 57m   | FOOTWAY   | Bituminous surfacing - local cracking (BLCK)     | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82429956-12   | 241m    | 251m  | FOOTWAY   | Bituminous surfacing - local cracking (BLCK)     | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82429956-9  | 92m     | 94m   | FOOTWAY   | Bituminous surfacing - local cracking (BLCK)     | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82429956-11   | 233m    | 234m  | FOOTWAY   | Bituminous surfacing - potholes (BPOT)           | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82429956-13   | 255m    | 265m  | FOOTWAY   | Bituminous surfacing - local cracking (BLCK)     | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b>                              |         |       |           |  |                 |                          |                       |                 |                      |
| No defects recorded   |         |       |           |  |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b>                              |         |       |           |  |                 |                          |                       |                 |                      |
| No defects recorded   |         |       |           |  |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>                                 |         |       |           |  |                 |                          |                       |                 |                      |
| No defects recorded   |         |       |           |  |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>                                 |         |       |           |  |                 |                          |                       |                 |                      |
| No defects recorded   |         |       |           |  |                 |                          |                       |                 |                      |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 15 March 2019</b> |         |       |           |  |                 |                          |                       |                 |                      |
| SW82446495-8  | 235m    | 240m  | FOOTWAY   | Bituminous surfacing - extensive cracking (BECK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82446495-7  | 16m     | 20m   | FOOTWAY   | Bituminous surfacing - extensive cracking (BECK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82446495-16   | 50m     | 65m   | FOOTWAY   | Bituminous surfacing - extensive cracking (BECK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>                                 |         |       |           |  |                 |                          |                       |                 |                      |
| No defects recorded   |         |       |           |  |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>                                 |         |       |           |  |                 |                          |                       |                 |                      |
| No defects recorded   |         |       |           |  |                 |                          |                       |                 |                      |

| Defect Reference  | Start<br>m | End<br>m | Item Type   | Item Detail              | Defect<br>Category | Required<br>Completion Date | Current Status       | Completion<br>Date | Location Description                          |
|---|------------|----------|-------------|--------------------------|--------------------|-----------------------------|----------------------|--------------------|---|
| <b>11629/45 : JCT JOHN KNOX ST TO JCT B7023 CULZEAN RD</b>                                |            |          |             |                          |                    |                             |                      |                    |   |
| Safety Inspection of A77 Ayr South V1 on 04 January 2018                                  |            |          |             |                          |                    |                             |                      |                    |   |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |   |
| Safety Inspection of A77 Ayr South V1 on 11 January 2018                                  |            |          |             |                          |                    |                             |                      |                    |   |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |   |
| Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 18 January 2018  |            |          |             |                          |                    |                             |                      |                    |   |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |   |
| Safety Inspection of A77 Ayr South V1 on 18 January 2018                                  |            |          |             |                          |                    |                             |                      |                    |   |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |   |
| Safety Inspection of A77 Ayr South V1 on 25 January 2018                                  |            |          |             |                          |                    |                             |                      |                    |   |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |   |
| Safety Inspection of A77 Ayr South V1 on 01 February 2018                                 |            |          |             |                          |                    |                             |                      |                    |   |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |   |
| Safety Inspection of A77 Ayr South V1 on 08 February 2018                                 |            |          |             |                          |                    |                             |                      |                    |   |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |   |
| Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 15 February 2018 |            |          |             |                          |                    |                             |                      |                    |   |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |   |
| Safety Inspection of A77 Ayr South V1 on 15 February 2018                                 |            |          |             |                          |                    |                             |                      |                    |   |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |   |
| Safety Inspection of A77 Ayr South V1 on 22 February 2018                                 |            |          |             |                          |                    |                             |                      |                    |   |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |   |
| Safety Inspection of A77 Ayr South V1 on 01 March 2018                                    |            |          |             |                          |                    |                             |                      |                    |   |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |   |
| Safety Inspection of A77 Ayr South V1 on 08 March 2018                                    |            |          |             |                          |                    |                             |                      |                    |   |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |   |
| Safety Inspection of A77 Ayr South V1 on 15 March 2018                                    |            |          |             |                          |                    |                             |                      |                    |   |
| SW82328086-235590037  | 173m       | 174m     | GULLY       | Other (OTHR)             | 3RD PTY            | 12/04/2018                  | Completed<br>Defects | 26/08/2018         | A77 SB CW, OUTSIDE<br>SIMPSONS BAKERY MAYBOLE |
| Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 16 March 2018    |            |          |             |                          |                    |                             |                      |                    |   |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |   |
| Safety Inspection of A77 Ayr South V1 on 22 March 2018                                    |            |          |             |                          |                    |                             |                      |                    |   |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |   |
| Safety Inspection of A77 Ayr South V1 on 29 March 2018                                    |            |          |             |                          |                    |                             |                      |                    |   |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |   |
| Safety Inspection of A77 Ayr South V1 on 05 April 2018                                    |            |          |             |                          |                    |                             |                      |                    |   |
| SW82334882-235613701  | 69m        | 0m       | CARRIAGEWAY | Pothole<br>(POTH)        | CAT 1              | 03/05/2018                  | Completed<br>Defects | 18/04/2018         | A77 10M BEFORE NO 57<br>MAYBOLE HIGH STREET   |
| Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 12 April 2018    |            |          |             |                          |                    |                             |                      |                    |   |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |   |
| Safety Inspection of A77 Ayr South V1 on 12 April 2018                                    |            |          |             |                          |                    |                             |                      |                    |   |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |   |
| Safety Inspection of A77 Ayr South V1 on 19 April 2018                                    |            |          |             |                          |                    |                             |                      |                    |   |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |   |
| Safety Inspection of A77 Ayr South V1 on 26 April 2018                                    |            |          |             |                          |                    |                             |                      |                    |   |
| SW82341166-235669120  | 161m       | 0m       | CARRIAGEWAY | Pothole VIAFIX<br>(POTV) | CAT 1              | 27/04/2018                  | Completed<br>Defects | 26/04/2018         | A77 NB MAYBOLE CASTLE<br>LANE 1               |
| Safety Inspection of A77 Ayr South V1 on 03 May 2018                                      |            |          |             |                          |                    |                             |                      |                    |   |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |   |
| Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 10 May 2018      |            |          |             |                          |                    |                             |                      |                    |   |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |   |
| Safety Inspection of A77 Ayr South V1 on 10 May 2018                                      |            |          |             |                          |                    |                             |                      |                    |   |
| SW82346930-235712673  | 179m       | 180m     | CARRIAGEWAY | Pothole VIAFIX<br>(POTV) | CAT 1              | 07/06/2018                  | Completed<br>Defects | 10/05/2018         | A77 SB CW OUTSIDE<br>SIMPSONS BAKERY MAYBOLE  |
| Safety Inspection of A77 Ayr South V1 on 17 May 2018                                      |            |          |             |                          |                    |                             |                      |                    |   |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |   |
| Safety Inspection of A77 Ayr South V1 on 24 May 2018                                      |            |          |             |                          |                    |                             |                      |                    |   |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |   |
| Safety Inspection of A77 Ayr South V1 on 31 May 2018                                      |            |          |             |                          |                    |                             |                      |                    |   |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |   |
| Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 07 June 2018     |            |          |             |                          |                    |                             |                      |                    |   |
| No defects recorded   |            |          |             |                          |                    |                             |                      |                    |   |
| Safety Inspection of A77 Ayr South V1 on 07 June 2018                                     |            |          |             |                          |                    |                             |                      |                    |   |

| Defect Reference  | Start m | End m | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                      |
|---|---------|-------|-------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| SW80-359626-235827135   | 161m    | 162m  | GULLY       | Cracked or broken (IBCK)             | CAT 1           | 05/07/2018               | Completed Defects     | 07/06/2018      | A77 SB CW OUTSIDE SIMPSONS BAKERS MAYBOLE |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>                                      |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>                                      |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b>                              |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>                                      |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 05 July 2018</b>      |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>                                      |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>                                      |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>                                      |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>                                      |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 02 August 2018</b>    |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>                                    |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>                                    |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>                                    |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>                                    |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>                                    |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 31 August 2018</b>    |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b>                                 |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b>                                 |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b>                                 |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 24 September 2018</b> |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b>                                 |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>                                   |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>                                   |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>                                   |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 25 October 2018</b>   |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>                                   |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b>                              |         |       |             |                                      |                 |                          |                       |                 |   |
| SW82332071-754  | 90m     | 170m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>                                  |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>                                  |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>                                  |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 22 November 2018</b>  |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |

| Defect Reference   | Start m | End m | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                        |
|--|---------|-------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|---|
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b> |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b> |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b> |         |       |             |                       |                 |                          |                   |                 |   |
| SW80-427220-236234314  | 84m     | 85m   | GULLY       | Blockage (BLOK)       | CAT 1           | 03/01/2019               | Completed Defects | 06/12/2018      | A77 SB CW OUTSIDE PREMIER MAYBOLE           |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b> |         |       |             |                       |                 |                          |                   |                 |   |
| SW82427366-236262624   | 155m    | 156m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 10/01/2019               | Completed Defects | 14/12/2018      | A77 SB CW, OUTSIDE SIMPSONS BAKERY, MAYBOLE |

**Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 20 December 2018**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 20 December 2018**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 27 December 2018**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 03 January 2019**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 10 January 2019**

*No defects recorded*

**Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 17 January 2019**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 17 January 2019**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 24 January 2019**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 31 January 2019**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 07 February 2019**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 14 February 2019**

*No defects recorded*

**Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 15 February 2019**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 21 February 2019**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 28 February 2019**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 07 March 2019**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 14 March 2019**

*No defects recorded*

**Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 15 March 2019**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 21 March 2019**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 28 March 2019**

*No defects recorded*

**11629/52 : JUNCTION B7023 CULZEAN ROAD TO LYONSTON FARM**

**Safety Inspection of A77 Ayr South V1 on 04 January 2018**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 11 January 2018**

*No defects recorded*

**Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 18 January 2018**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 18 January 2018**

|                      |    |    |             |                |       |            |                   |            |  |
|----------------------|----|----|-------------|----------------|-------|------------|-------------------|------------|--|
| SW82317666-235521330 | 0m | 2m | CARRIAGEWAY | Pothole (POTH) | CAT 1 | 15/02/2018 | Completed Defects | 05/03/2018 | A77 NB CW, 250M STH OF LAYBY AT DRUMELLAN FARM, NTH OF MAYBOLE |
|----------------------|----|----|-------------|----------------|-------|------------|-------------------|------------|--|

**Safety Inspection of A77 Ayr South V1 on 25 January 2018**

*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 01 February 2018**

*No defects recorded*



| Defect Reference   | Start m | End m | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                             |
|--|---------|-------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|--|
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b>                                 |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 15 February 2018</b> |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b>                                 |         |       |             |                       |                 |                          |                   |                 |  |
| SW82319984-235544962   | 436m    | 437m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 15/03/2018               | Completed Defects | 15/02/2018      | A77 SB CW, AT BUS STOP MCDOWELL TERR, MAYBOLE    |
| SW82319984-235544963   | 364m    | 365m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 15/03/2018               | Completed Defects | 15/02/2018      | A77 SB CW, OPP REDBRAE JCT, MAYBOLE              |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b>                                 |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>                                    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>                                    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>                                    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 16 March 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>                                    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>                                    |         |       |             |                       |                 |                          |                   |                 |  |
| SW80-332117-235613701  | 548m    | 549m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 26/04/2018               | Completed Defects | 29/03/2018      | A77 NB CW, MAYBOLE, 20M NTH OF KIRKMICHAEL JCT   |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>                                    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 12 April 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>                                    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>                                    |         |       |             |                       |                 |                          |                   |                 |  |
| SW82338893-235633871   | 342m    | 342m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 20/04/2018               | Completed Defects | 19/04/2018      | A77 N/B @ MAYBOLE @REDBRAE JT                    |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>                                    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>                                      |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 10 May 2018</b>      |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>                                      |         |       |             |                       |                 |                          |                   |                 |  |
| SW82346930-235712672   | 148m    | 149m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 07/06/2018               | Completed Defects | 10/05/2018      | A77 CL OPPOSITE BUS STOP SOUTH OF CHURCH MAYBOLE |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>                                      |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>                                      |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>                                      |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 07 June 2018</b>     |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>                                     |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>                                     |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>                                     |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b>                             |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>                                     |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 05 July 2018</b>     |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>                                     |         |       |             |                       |                 |                          |                   |                 |  |

| Defect Reference  | Start m | End m | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                              |
|---|---------|-------|-------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| SW82374127-235892350  | 365m    | 366m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 02/08/2018               | Completed Defects     | 05/07/2018      | A77 SB CW OUTSIDE REDBRAE JCT MAYBOLE             |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>                                      |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>                                      |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>                                      |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 02 August 2018</b>    |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>                                    |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>                                    |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>                                    |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>                                    |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>                                    |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 31 August 2018</b>    |         |       |             |                                      |                 |                          |                       |                 |   |
| SW80-400016-2   | 357m    | 358m  | FOOTWAY     | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | OUT SIDE WOODSIDE COTTAGE CASSILIS TERSCE MAYBOLE |
| SW80-400016-1   | 503m    | 510m  | FOOTWAY     | Other (OTHR)                         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | OUTSIDE NO3 CASSILISS TERRACE MAYBOLE             |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b>                                 |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b>                                 |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b>                                 |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 24 September 2018</b> |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b>                                 |         |       |             |                                      |                 |                          |                       |                 |   |
| SW80-413634-236087132   | 302m    | 303m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 28/09/2018               | Completed Defects     | 27/09/2018      | A77 SB CW OPPOSITE JACKS GAIT JCT MAYBOLE         |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>                                   |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>                                   |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>                                   |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 25 October 2018</b>   |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>                                   |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b>                              |         |       |             |                                      |                 |                          |                       |                 |   |
| SW82332071-755  | 24m     | 104m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-756  | 83m     | 123m  | FOOTWAY     | Other (OTHR)                         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-759  | 365m    | 425m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-758  | 261m    | 341m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-760  | 436m    | 516m  | FOOTWAY     | Other (OTHR)                         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |

| Defect Reference   | Start m | End m | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status               | Completion Date | Location Description                                       |
|--|---------|-------|-------------|--------------------------------------|-----------------|--------------------------|------------------------------|-----------------|--|
| SW82332071-757   | 133m    | 213m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action        | 01/01/9999      |  |
| SW82332071-761   | 557m    | 637m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action        | 01/01/9999      |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>                                 |         |       |             |                                      |                 |                          |                              |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>                                 |         |       |             |                                      |                 |                          |                              |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>                                 |         |       |             |                                      |                 |                          |                              |                 |  |
| SW82426587-236223185   | 579m    | 580m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 16/11/2018               | Completed Defects            | 15/11/2018      | A77 NB CW 50 AFTER MAYBOLE NORTH GATEWAY                   |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 22 November 2018</b> |         |       |             |                                      |                 |                          |                              |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b>                                 |         |       |             |                                      |                 |                          |                              |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b>                                 |         |       |             |                                      |                 |                          |                              |                 |  |
| SW82426917-236234306   | 283m    | 284m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 30/11/2018               | Completed Defects            | 29/11/2018      | A77 SB CW OPPOSITE JACKS GAIT JCT MAYBOLE                  |
| SW82426917-236234305   | 290m    | 291m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 30/11/2018               | Completed Defects            | 29/11/2018      | A77 SB CW OPPOSITE JACKS GAIT JCT                          |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b>                                 |         |       |             |                                      |                 |                          |                              |                 |  |
| SW80-427220-236234315  | 451m    | 452m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 07/12/2018               | Completed Defects            | 06/12/2018      | A77 SB CW AT FIRST BUSSTOP IN MAYBOLE                      |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b>                                 |         |       |             |                                      |                 |                          |                              |                 |  |
| SW82427366-236262626   | 437m    | 438m  | GULLY       | Cracked or broken (IBCK)             | 3RD PTY         | 10/01/2019               | Awaiting CCMS Temp Date      | 01/01/9999      | A77 SB CW, MCDOWELL TERRANCE MAYBOLE                       |
| SW82427366-236262625   | 148m    | 149m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 10/01/2019               | Completed Defects            | 14/12/2018      | A77 ON CL, OUTSIDE BOWLING GREEN MAYBOLE                   |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 20 December 2018</b> |         |       |             |                                      |                 |                          |                              |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b>                                 |         |       |             |                                      |                 |                          |                              |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b>                                 |         |       |             |                                      |                 |                          |                              |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>                                  |         |       |             |                                      |                 |                          |                              |                 |  |
| SW82427890-236270563   | 431m    | 432m  | GULLY       | Other (OTHR)                         | 3RD PTY         | 31/01/2019               | Awaiting CCMS Permanent Date | 01/01/9999      | A77 MCDOWELL TERRACE, MAYBOLE                              |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>                                  |         |       |             |                                      |                 |                          |                              |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                              |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 17 January 2019</b>  |         |       |             |                                      |                 |                          |                              |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>                                  |         |       |             |                                      |                 |                          |                              |                 |  |
| No defects recorded  |         |       |             |                                      |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>                                  |         |       |             |                                      |                 |                          |                              |                 |  |
| SW82428351-236284331   | 296m    | 297m  | CARRIAGEWAY | Pothole (POTH)                       | CAT 1           | 21/02/2019               | Completed Defects            | 07/02/2019      | A77 SB CW, 30M STH OF JACKS GAIT JCT, MAYBOLE              |
| SW82428351-236284332   | 373m    | 371m  | CARRIAGEWAY | Pothole (POTH)                       | CAT 1           | 21/02/2019               | Completed Defects            | 07/02/2019      | A77 SB CW OPP REDBRAE JCT MAYBOLE                          |
| SW82428351-236284328   | 83m     | 84m   | CARRIAGEWAY | Pothole (POTH)                       | CAT 1           | 21/02/2019               | Completed Defects            | 07/02/2019      | A77 ON CL, CASSILLIS ROAD MAYBOLE, OUTSIDE QUICK SALE SHOP |
| SW82428351-236284333   | 372m    | 373m  | CARRIAGEWAY | Pothole (POTH)                       | CAT 1           | 21/02/2019               | Completed Defects            | 07/02/2019      | A77 SB CW, OPP REDBRAE JCT MAYBOLE                         |
| SW82428351-236284330   | 296m    | 297m  | CARRIAGEWAY | Pothole (POTH)                       | CAT 1           | 21/02/2019               | Completed Defects            | 07/02/2019      | A77 SB CW, 40M STH OF JACKS GAIT JCT MAYBOLE               |

| Defect Reference   | Start m | End m | Item Type   | Item Detail                                  | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                                  |
|--|---------|-------|-------------|--|-----------------|--------------------------|-----------------------|-----------------|---|
| SW82428351-236284329   | 296m    | 297m  | CARRIAGEWAY | Pothole (POTH)                               | CAT 1           | 21/02/2019               | Completed Defects     | 07/02/2019      | A77 SB CW, 50M STH OF JACKS GAIT JCT MAYBOLE          |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>                                  |         |       |             |  |                 |                          |                       |                 |   |
| SW82428625-236291436   | 121m    | 122m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                        | CAT 1           | 01/02/2019               | Completed Defects     | 31/01/2019      | A77 ON CENTRE LINE OUTSIDE 22 CASSILLISS ROAD MAYBOLE |
| SW82428625-236291435   | 126m    | 128m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                        | CAT 1           | 01/02/2019               | Completed Defects     | 31/01/2019      | A77 CENTRE LINE OUTSIDE 22 CASSILIS ROAD MAYBOLE      |
| SW82428625-236291416   | 281m    | 282m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                        | CAT 1           | 01/02/2019               | Completed Defects     | 31/01/2019      | A77 SB CW CASSILIS ROAD MAYBOLE                       |
| SW82428625-236291417   | 281m    | 282m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                        | CAT 1           | 01/02/2019               | Completed Defects     | 31/01/2019      | A77 SB CW CASSILIS ROAD MAYBOLE                       |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b>                                 |         |       |             |  |                 |                          |                       |                 |   |
| No defects recorded  |         |       |             |  |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b>                                 |         |       |             |  |                 |                          |                       |                 |   |
| No defects recorded  |         |       |             |  |                 |                          |                       |                 |   |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 15 February 2019</b> |         |       |             |  |                 |                          |                       |                 |   |
| SW82429956-21  | 479m    | 486m  | FOOTWAY     | Bituminous surfacing - local cracking (BLCK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82429956-24  | 86m     | 90m   | FOOTWAY     | Bituminous surfacing - local cracking (BLCK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82429956-17  | 239m    | 242m  | FOOTWAY     | Bituminous surfacing - local cracking (BLCK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82429956-18  | 374m    | 377m  | FOOTWAY     | Bituminous surfacing - local cracking (BLCK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82429956-20  | 526m    | 530m  | FOOTWAY     | Bituminous surfacing - local cracking (BLCK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82429956-16  | 162m    | 164m  | FOOTWAY     | Bituminous surfacing - local cracking (BLCK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82429956-22  | 353m    | 354m  | FOOTWAY     | Bituminous surfacing - potholes (BPOT)       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82429956-23  | 105m    | 107m  | FOOTWAY     | Bituminous surfacing - local cracking (BLCK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82429956-19  | 397m    | 400m  | FOOTWAY     | Bituminous surfacing - local cracking (BLCK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82429956-15  | 92m     | 97m   | FOOTWAY     | Bituminous surfacing - local cracking (BLCK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b>                                 |         |       |             |  |                 |                          |                       |                 |   |
| No defects recorded  |         |       |             |  |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b>                                 |         |       |             |  |                 |                          |                       |                 |   |
| No defects recorded  |         |       |             |  |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>                                    |         |       |             |  |                 |                          |                       |                 |   |



| Defect Reference  | Start m | End m | Item Type   | Item Detail                                      | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                            |
|---|---------|-------|-------------|--|-----------------|--------------------------|-----------------------|-----------------|---|
| SW82441664-236344801  | 138m    | 138m  | GULLY       | Blockage (BLOK)                                  | CAT 1           | 04/04/2019               | Completed Defects     | 02/04/2019      | A77 S/B @ MAYBOLE BOWLING CLUB TO NO 23 CALLISS |
| SW82441664-236344803  | 110m    | 110m  | GULLY       | Blockage (BLOK)                                  | CAT 1           | 04/04/2019               | Completed Defects     | 02/04/2019      | A77 S B @ NO 23 CALLISS RD                      |
| SW82441664-236344802  | 122m    | 122m  | GULLY       | Blockage (BLOK)                                  | CAT 1           | 04/04/2019               | Completed Defects     | 02/04/2019      | A77 S/B @ NO 21 CALLISS RD                      |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>                                 |         |       |             |  |                 |                          |                       |                 |   |
| SW82447370-236454234  | 446m    | 447m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                            | CAT 1           | 15/03/2019               | Completed Defects     | 14/03/2019      | A77 N/B OPP NO 11 CASLLIS TER MAYBOLE           |
| SW82447370-236454237  | 587m    | 589m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                            | CAT 1           | 15/03/2019               | Completed Defects     | 14/03/2019      | A77 N/B OPP NO 4 PARK TERRACE MAYBOLE           |
| SW82447370-236454233  | 442m    | 443m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                            | CAT 1           | 15/03/2019               | Completed Defects     | 14/03/2019      | A77 S/B OUTSIDE NO 11 CASILLIS TER MAYBOLE      |
| <b>Detailed Inspections - Category A Footways of A77 Maybole Footways V1 on 15 March 2019</b> |         |       |             |  |                 |                          |                       |                 |   |
| SW82446495-9  | 93m     | 100m  | FOOTWAY     | Bituminous surfacing - extensive cracking (BECK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82446495-11   | 436m    | 440m  | FOOTWAY     | Bituminous surfacing - extensive cracking (BECK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82446495-13   | 496m    | 500m  | FOOTWAY     | Bituminous surfacing - extensive cracking (BECK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82446495-15   | 70m     | 80m   | FOOTWAY     | Bituminous surfacing - extensive cracking (BECK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82446495-10   | 226m    | 230m  | FOOTWAY     | Bituminous surfacing - extensive cracking (BECK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82446495-12   | 596m    | 600m  | FOOTWAY     | Bituminous surfacing - extensive cracking (BECK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82446495-14   | 378m    | 380m  | FOOTWAY     | Bituminous surfacing - extensive cracking (BECK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>                                 |         |       |             |  |                 |                          |                       |                 |   |
| SW82453127-236489171  | 213m    | 213m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                            | CAT 1           | 22/03/2019               | Completed Defects     | 21/03/2019      | A77 S/B CULZEAN TO LYONSTON FARM                |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>                                 |         |       |             |  |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |  |                 |                          |                       |                 |   |
| <b>11629/76 : LYONSTON FARM TO JUNCTION DRUMELLAN</b>   |         |       |             |  |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>                               |         |       |             |  |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |  |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>                               |         |       |             |  |                 |                          |                       |                 |   |

| Defect Reference   | Start<br>m | End<br>m | Item Type   | Item Detail              | Defect<br>Category | Required<br>Completion Date | Current Status       | Completion<br>Date | Location Description                         |
|--|------------|----------|-------------|--------------------------|--------------------|-----------------------------|----------------------|--------------------|--|
| No defects recorded  |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 18 January 2018                       |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded  |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 25 January 2018                       |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded  |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 01 February 2018                      |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded  |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 08 February 2018                      |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded  |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 15 February 2018                      |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded  |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 22 February 2018                      |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded  |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 01 March 2018                         |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded  |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 08 March 2018                         |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded  |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 15 March 2018                         |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded  |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 22 March 2018                         |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded  |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 29 March 2018                         |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded  |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 05 April 2018                         |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded  |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 12 April 2018<br>SW82336916-235633871 | 156m       | 157m     | CARRIAGEWAY | Pothole VIAFIX<br>(POTV) | CAT 1              | 10/05/2018                  | Completed<br>Defects | 12/04/2018         | A77 SB CW, 50M NTH OF<br>MAYBOLE NTH GATEWAY |
| Safety Inspection of A77 Ayr South V1 on 19 April 2018                         |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded  |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 26 April 2018                         |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded  |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 03 May 2018                           |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded  |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 10 May 2018                           |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded  |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 17 May 2018                           |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded  |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 24 May 2018                           |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded  |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 31 May 2018                           |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded  |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 07 June 2018                          |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded  |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 14 June 2018                          |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded  |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 21 June 2018                          |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded  |            |          |             |                          |                    |                             |                      |                    |  |
| Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018                  |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded  |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 28 June 2018                          |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded  |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 05 July 2018                          |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded  |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 12 July 2018                          |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded  |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 19 July 2018                          |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded  |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 26 July 2018                          |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded  |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 02 August 2018                        |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded  |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 09 August 2018                        |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded  |            |          |             |                          |                    |                             |                      |                    |  |
| Safety Inspection of A77 Ayr South V1 on 16 August 2018                        |            |          |             |                          |                    |                             |                      |                    |  |
| No defects recorded  |            |          |             |                          |                    |                             |                      |                    |  |

| Defect Reference   | Start m | End m | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description  |
|--|---------|-------|-------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |         |       |             |                                      |                 |                          |                       |                 |   |
| SW80-397303-235954870  | 243m    | 244m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 24/08/2018               | Completed Defects     | 23/08/2018      | A77N/B C/W 150M NORTH OF MAYBOLE  |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>       |         |       |             |                                      |                 |                          |                       |                 |   |
| SW80-400497-235984891  | 160m    | 161m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 31/08/2018               | Completed Defects     | 30/08/2018      | A77 S/B C/W 10M PRIOR TO WELCOME TO MAYBOLE SIGN  |
| SW80-400497-235984892  | 168m    | 169m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 31/08/2018               | Completed Defects     | 30/08/2018      | MAYBOLE NORTH GATEWAY<br>A77 S/B C/W 5M PRIOR TO WELCOME TO MAYBOLE SIGN<br>MAYBOLE NORTH GATEWAY |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b>    |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b>    |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b>    |         |       |             |                                      |                 |                          |                       |                 |   |
| SW82410364-236066525   | 162m    | 163m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 21/09/2018               | Completed Defects     | 20/09/2018      | A77 SB CW 100M NORTH OF MAYBOLE GATEWAY   |
| SW82410364-236066526   | 244m    | 245m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 21/09/2018               | Completed Defects     | 20/09/2018      | A77 NB CW 150M NORTH OF MAYBOLE NORTH GATEWAY   |
| SW82410364-236066524   | 162m    | 163m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 21/09/2018               | Completed Defects     | 20/09/2018      | A77 SB CW 100M NORTH OF MAYBOLE NORTH GATEWAY   |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b>    |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>      |         |       |             |                                      |                 |                          |                       |                 |   |
| SW82416981-236101747   | 150m    | 151m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 05/10/2018               | Completed Defects     | 04/10/2018      | A77 SB CW 25M FROM MAYBOLE NORTH GATEWAY  |
| SW82416981-236101746   | 146m    | 147m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 05/10/2018               | Completed Defects     | 04/10/2018      | A77 SB CW 30M FROM MAYBOLE NORTH GATEWAY  |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>      |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>      |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>      |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |         |       |             |                                      |                 |                          |                       |                 |   |
| SW82332071-763   | 170m    | 250m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Completed Defects     | 31/03/2019      |   |
| SW82332071-765   | 450m    | 530m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Completed Defects     | 31/03/2019      |   |
| SW82332071-762   | 75m     | 155m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-764   | 319m    | 399m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Completed Defects     | 31/03/2019      |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>     |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>     |         |       |             |                                      |                 |                          |                       |                 |   |
| SW82426441-236211993   | 150m    | 153m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 09/11/2018               | Completed Defects     | 08/11/2018      | A77 SB CW AT MAYBOLE NORTH GATEWAY  |
| <b>Safety Inspection of Maybole Adhoc on 14 November 2018</b>        |         |       |             |                                      |                 |                          |                       |                 |   |
| SW80-426564-3  | 173m    | 174m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 12/12/2018               | Completed Defects     | 13/11/2018      | A77 380M STH OF DRUMELLAN   |
| SW80-426564-1  | 160m    | 161m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 12/12/2018               | Completed Defects     | 13/11/2018      | A77 400M STH OF DRUMELLAN   |

| Defect Reference   | Start m | End m | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                       |
|--|---------|-------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|--|
| SW80-426564-2  | 157m    | 158m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 12/12/2018               | Completed Defects | 13/11/2018      | A77 390M STH OF DRUMELLAN                  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b> |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b> |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b> |         |       |             |                       |                 |                          |                   |                 |  |
| SW82426917-236234307   | 138m    | 143m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 27/12/2018               | Completed Defects | 29/11/2018      | A77 SB CW AT MAYBOLE NORTH GATEWAY         |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b> |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b> |         |       |             |                       |                 |                          |                   |                 |  |
| SW82427366-236262629   | 170m    | 170m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 10/01/2019               | Completed Defects | 14/12/2018      | A77 SB CW, MAYBOLE ST GATEWAY              |
| SW82427366-236262632   | 250m    | 251m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 10/01/2019               | Completed Defects | 14/12/2018      | A77 NB CW, 150M NTH OF MAYBOLE NTH GATEWAY |
| SW82427366-236262628   | 170m    | 171m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 10/01/2019               | Completed Defects | 14/12/2018      | A77 SB CW, MAYBOLE STH GATEWAY             |
| SW82427366-236262630   | 170m    | 171m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 10/01/2019               | Completed Defects | 14/12/2018      | A77 SB CW, MAYBOLE STH GATEWAY             |
| SW82427366-236262627   | 165m    | 166m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 10/01/2019               | Completed Defects | 14/12/2018      | A77 SB CW, MAYBOLE STH GATEWAY             |
| SW82427366-236262631   | 225m    | 226m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 10/01/2019               | Completed Defects | 14/12/2018      | A77 SB CW, 120M NTH OF MAYBOLE NTH GATEWAY |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b> |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b> |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| SW82428351-236284334   | 317m    | 318m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 21/02/2019               | Completed Defects | 11/02/2019      | A77 NB CW, 240M NTH OF MAYBOLE NTH GATEWAY |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| SW82428625-236291413   | 151m    | 152m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 01/02/2019               | Completed Defects | 31/01/2019      | A77 SB CW MAYBOLE NORTH GATEWAY            |
| SW82428625-236291414   | 159m    | 160m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 01/02/2019               | Completed Defects | 31/01/2019      | A77 SB CW MAYBOLE NORTH GATEWAY            |
| SW82428625-236291415   | 156m    | 157m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 01/02/2019               | Completed Defects | 31/01/2019      | A77 SB CW MAYBOLE NORTH GATEWAY            |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded  |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |  |

| Defect Reference     | Start m | End m | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                               |
|----------------------|---------|-------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|--|
| SW82447370-236454224 | 259m    | 260m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 15/03/2019               | Completed Defects | 14/03/2019      | A77 S/B 35M AFTER 30MPH MARKER MAYBOLE             |
| SW82447370-236454226 | 224m    | 225m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 15/03/2019               | Completed Defects | 14/03/2019      | A77 S/B 40M PRIOR TO 100M COUNTDOWN MARKER MAYBOLE |
| SW82447370-236454227 | 217m    | 218m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 15/03/2019               | Completed Defects | 14/03/2019      | A77 S/B 30M PRIOR TO 100M COUNTDOWN MARKER MAYBOLE |
| SW82447370-236454230 | 163m    | 164m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 15/03/2019               | Completed Defects | 14/03/2019      | A77 SB 50M AFTER 100M COUNTDOWN MARKER MAYBOLE     |
| SW82447370-236454231 | 159m    | 160m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 15/03/2019               | Completed Defects | 14/03/2019      | A77 S/B 51M AFTER 100M COUNTDOWN MARKER MAYBOLE    |
| SW82447370-236454225 | 243m    | 244m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 15/03/2019               | Completed Defects | 14/03/2019      | A77 N/B 50M PRIOR TO 200 COUNTDOWN MARKER MAYBOLE  |
| SW82447370-236454232 | 158m    | 159m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 15/03/2019               | Completed Defects | 14/03/2019      | A77 S/B 52M AFTER 100M COUNTDOWN MARKER MAYBOLE    |
| SW82447370-236454228 | 179m    | 180m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 15/03/2019               | Completed Defects | 14/03/2019      | A77 S/B 25M AFTER 100M COUNTDOWN MARKER MAYBOLE    |
| SW82447370-236454229 | 176m    | 177m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 15/03/2019               | Completed Defects | 14/03/2019      | A77 S/B 35M AFTER 100M COUNTDOWN MARKER MAYBOLE    |

**Safety Inspection of A77 Ayr South V1 on 21 March 2019**

No defects recorded

**Safety Inspection of A77 Ayr South V1 on 28 March 2019**

No defects recorded

**11632/05 : JUNCTION DRUMELLAN TO SMITHSTON BRIDGE**

**Safety Inspection of A77 Ayr South V1 on 04 January 2018**

|                      |        |        |             |                |       |            |                   |            |  |
|----------------------|--------|--------|-------------|----------------|-------|------------|-------------------|------------|--|
| SW82317326-235513687 | 1,220m | 1,221m | CARRIAGEWAY | Pothole (POTH) | CAT 1 | 01/02/2018 | Completed Defects | 22/01/2018 | nb cw north of neth culzean farm at one mile reduce speed now sign           |
| SW82317326-235513689 | 585m   | 587m   | CARRIAGEWAY | Pothole (POTH) | CAT 1 | 01/02/2018 | Completed Defects | 04/01/2018 | 15meters north of myrehill farm nb cw near centre line                       |
| SW82317326-235513686 | 1,905m | 0m     | CARRIAGEWAY | Pothole (POTH) | CAT 1 | 01/02/2018 | Completed Defects | 09/02/2018 | AT JUNCTION WITH HIGH SMITHSTONE FARM AND JUST SOUTH OF FARM ENTRANCE S\B C\ |
| SW82317326-235513688 | 642m   | 644m   | CARRIAGEWAY | Pothole (POTH) | CAT 1 | 01/02/2018 | Completed Defects | 10/02/2018 | 100meters north of myrehil farm sb cw  |

**Safety Inspection of A77 Ayr South V1 on 11 January 2018**

No defects recorded

**Safety Inspection of A77 Ayr South V1 on 18 January 2018**

|                      |      |      |             |                |       |            |                   |            |  |
|----------------------|------|------|-------------|----------------|-------|------------|-------------------|------------|--|
| SW82317666-235521329 | 583m | 584m | CARRIAGEWAY | Pothole (POTH) | CAT 1 | 15/02/2018 | Completed Defects | 09/02/2018 | A77 SB CW, 200M STH OF LAYBY AT DRUMELLAN, NTH OF MAYBOLE      |
| SW82317666-235521331 | 458m | 459m | CARRIAGEWAY | Pothole (POTH) | CAT 1 | 15/02/2018 | Completed Defects | 05/03/2018 | A77 NB CW, 300M STH OF LAYBY AT DRUMELLAN FARM, NTH OF MAYBOLE |

**Safety Inspection of A77 Ayr South V1 on 25 January 2018**

|                      |        |        |             |                |       |            |                   |            |  |
|----------------------|--------|--------|-------------|----------------|-------|------------|-------------------|------------|--|
| SW82317793-235529564 | 1,901m | 1,911m | CARRIAGEWAY | Pothole (POTH) | CAT 1 | 22/02/2018 | Completed Defects | 09/02/2018 | A77 ON CL, 150M STH OF SMITHTON BRIDGE, NTH OF MAYBOLE |
|----------------------|--------|--------|-------------|----------------|-------|------------|-------------------|------------|--|

**Safety Inspection of A77 Ayr South V1 on 01 February 2018**

|                      |        |        |             |                |       |            |                   |            |  |
|----------------------|--------|--------|-------------|----------------|-------|------------|-------------------|------------|--|
| SW82318129-235532262 | 1,896m | 1,900m | CARRIAGEWAY | Pothole (POTH) | CAT 1 | 01/03/2018 | Completed Defects | 09/02/2018 | A77 ON CL, 150M STH OF SMITHTON BRIDGE |
|----------------------|--------|--------|-------------|----------------|-------|------------|-------------------|------------|--|

| Defect Reference   | Start m | End m  | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                                 |
|--|---------|--------|-------------|--------------------------------------|-----------------|--------------------------|-------------------|-----------------|--|
| SW82318129-235532263   | 519m    | 520m   | CARRIAGEWAY | Pothole (POTH)                       | CAT 1           | 01/03/2018               | Completed Defects | 01/02/2018      | A77 BOTH CW, DRUMELLAN NTH OF MAYBOLE                |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b>     |         |        |             |                                      |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b>     |         |        |             |                                      |                 |                          |                   |                 |  |
| SW82319984-235544964   | 1,864m  | 1,865m | CARRIAGEWAY | Pothole (POTH)                       | CAT 1           | 15/03/2018               | Completed Defects | 16/02/2018      | A77 SB CW, 150M STH OF SMITHTON BRIDGE               |
| SW82319984-235544965   | 1,939m  | 1,940m | CARRIAGEWAY | Pothole (POTH)                       | CAT 1           | 15/03/2018               | Completed Defects | 16/02/2018      | A77 NB CW, 80M STH OF SMITHTON BRIDGE                |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b>     |         |        |             |                                      |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>        |         |        |             |                                      |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>        |         |        |             |                                      |                 |                          |                   |                 |  |
| SW82326075-235554293   | 1,117m  | 1,118m | CARRIAGEWAY | Pothole (POTH)                       | CAT 1           | 05/04/2018               | Completed Defects | 08/03/2018      | A77 SB CW, 200M STH OF DALRYMPLE JCT, NTH OF MAYBOLE |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>        |         |        |             |                                      |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>        |         |        |             |                                      |                 |                          |                   |                 |  |
| SW82330474-235608122   | 1,722m  | 1,723m | CARRIAGEWAY | Pothole (POTH)                       | CAT 1           | 19/04/2018               | Completed Defects | 22/03/2018      | A77 ON CL, 150M STH OF SMITHTON BRIDGE               |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>        |         |        |             |                                      |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>        |         |        |             |                                      |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>        |         |        |             |                                      |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>        |         |        |             |                                      |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>        |         |        |             |                                      |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>          |         |        |             |                                      |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>          |         |        |             |                                      |                 |                          |                   |                 |  |
| SW82346930-235712669   | 1,929m  | 1,930m | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 07/06/2018               | Completed Defects | 10/05/2018      | A77 NB CW 100M STH OF SMITHTON BRIDGE                |
| SW82346930-235712670   | 1,581m  | 1,582m | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 07/06/2018               | Completed Defects | 10/05/2018      | A77 NB CW 200M STH OF SMITHTON BRIDGE                |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |         |        |             |                                      |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |         |        |             |                                      |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |         |        |             |                                      |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |         |        |             |                                      |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |         |        |             |                                      |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |         |        |             |                                      |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |         |        |             |                                      |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |         |        |             |                                      |                 |                          |                   |                 |  |
| SW80-370510-235861177  | 1,897m  | 1,917m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Completed Defects | 13/12/2018      | A78 SB CW 350M AFTER SMITHTON BRIDGE                 |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |         |        |             |                                      |                 |                          |                   |                 |  |
| SW82374127-235892349   | 1,083m  | 1,084m | CARRIAGEWAY | Miscellaneous surface Defects (MSRF) | CAT 1           | 02/08/2018               | Completed Defects | 02/08/2018      | A76 SB CW CL 100M AFTER DALRYMPLE JCT                |

| Defect Reference  | Start m | End m  | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description   |
|---|---------|--------|-------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|--|
| SW82374127-235892347  | 2,000m  | 2,001m | CARRIAGEWAY | Miscellaneous surface Defects (MSRF) | CAT 1           | 02/08/2018               | Completed Defects     | 02/08/2018      | A77 SB CW 100M AFTER SMITHTON BRIDGE                               |
| SW82374127-235892348  | 1,992m  | 1,993m | CARRIAGEWAY | Miscellaneous surface Defects (MSRF) | CAT 1           | 02/08/2018               | Completed Defects     | 02/08/2018      | A77 SB CW 105 M AFTER SMITHTON BRIDGE                              |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>      |         |        |             |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>      |         |        |             |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>      |         |        |             |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>    |         |        |             |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>    |         |        |             |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>    |         |        |             |                                      |                 |                          |                       |                 |  |
| SW80-394061-235954856   | 651m    | 652m   | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 17/08/2018               | Completed Defects     | 16/08/2018      | A77 S/B C/W 50M NORTH OF MYREMILL FARM NORTH OF MAYBOLE            |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>    |         |        |             |                                      |                 |                          |                       |                 |  |
| SW80-397303-235954861   | 605m    | 606m   | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 24/08/2018               | Completed Defects     | 23/08/2018      | A77S/B C/W 40M NORTH OF MYREMILL FARM NORTH OF MAYBOLE             |
| SW80-397303-235954857   | 765m    | 769m   | CARRIAGEWAY | Other (OTHR)                         | CAT 1           | 20/09/2018               | Completed Defects     | 29/08/2018      | A77 S/B 10M PRIOR TO LAYBY NORTH OF MYREMILL FARM NORTH OF MAYBOLE |
| SW80-397303-235954859   | 636m    | 637m   | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 24/08/2018               | Completed Defects     | 23/08/2018      | A77 S/B C/W 50M NORTH OF MYREMILL FARM NORTH OF MAYBOLE            |
| SW80-397303-235954856   | 824m    | 825m   | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 24/08/2018               | Completed Defects     | 23/08/2018      | A77 S/B C/W AT LAYBY NORTH OF MYREMILL FARM NORTH OF MAYBOLE       |
| SW80-397303-235954863   | 271m    | 275m   | CARRIAGEWAY | Other (OTHR)                         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | A77 S/B C/W 600M NORTH OF MAYBOLE                                  |
| SW80-397303-235954858   | 636m    | 637m   | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 24/08/2018               | Completed Defects     | 23/08/2018      | A77 S/B C/W 60M NORTH OF MYREMILL FARM NORTH OF MAYBOLE            |
| SW80-397303-235954860   | 606m    | 607m   | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 24/08/2018               | Completed Defects     | 23/08/2018      | A77 S/B C/W 40M NORTH OF MYRRMILL FARM NORTH OF MAYBOLE            |
| SW80-397303-235954862   | 605m    | 606m   | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 24/08/2018               | Completed Defects     | 23/08/2018      | A77 S/B C/W 40M NORTH OF MYREMILL FARM NORTH OF MAYBOLE            |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>    |         |        |             |                                      |                 |                          |                       |                 |  |
| SW80-400497-235984882   | 591m    | 592m   | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 31/08/2018               | Completed Defects     | 30/08/2018      | A77 S/B C/W 30M NORTH OF MYREMILL FARM NORTH OF MAYBOLE            |
| SW80-400497-235984883   | 591m    | 592m   | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 31/08/2018               | Completed Defects     | 30/08/2018      | A77 S/B C/W 30M NORTH OF MYREMILL FARM NORTH OF MAYBOLE            |
| SW80-400497-235984880   | 645m    | 646m   | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 31/08/2018               | Completed Defects     | 30/08/2018      | A77S/B C/W 50M NORTH OF MYRE MILL FARM NORTH OF MAYBOL             |
| SW80-400497-235984881   | 639m    | 640m   | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 31/08/2018               | Completed Defects     | 30/08/2018      | A77 S/B C/W 45M NORTH OF MYREMILL FARM NORTH OF MAYBOLE            |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b> |         |        |             |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b> |         |        |             |                                      |                 |                          |                       |                 |  |
| SW82407181-236053594  | 1,622m  | 1,623m | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 14/09/2018               | Completed Defects     | 13/09/2018      | A77 N/B C/W 200M SOUTH OF SMITHSTON BRIDGE                         |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b> |         |        |             |                                      |                 |                          |                       |                 |  |

| Defect Reference  | Start m | End m  | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description   |
|---|---------|--------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|--|
| SW82410364-236066531  | 1,193m  | 1,194m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 21/09/2018               | Completed Defects | 20/09/2018      | A77 NB CW 50M FROM NETHER CULZEAN FARM JCT NORTH OF MAYBOLE            |
| SW82410364-236066532  | 1,016m  | 1,017m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 21/09/2018               | Completed Defects | 20/09/2018      | A77 NB CW 50M PRIOR TO NETHER CULZEAN NORTH OF MAYBOLE                 |
| SW82410364-236066528  | 271m    | 272m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 21/09/2018               | Completed Defects | 20/09/2018      | A77 SB CW 805M NORTH OF MAYBOLE  |
| SW82410364-236066520  | 653m    | 654m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 21/09/2018               | Completed Defects | 20/09/2018      | A77 SB CW 50M NORTH OF MIARMILL FARM NORTH OF MAYBOLE                  |
| SW82410364-236066522  | 605m    | 606m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 21/09/2018               | Completed Defects | 20/09/2018      | A77 SB CW 30M NORTH OF MIARMILL FARM NORTH OF MAYBOLE                  |
| SW82410364-236066519  | 779m    | 780m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 21/09/2018               | Completed Defects | 20/09/2018      | A77 SB AT LAYBY NORTH OF MIARMILL FARM NORTH OF MAYBOLE                |
| SW82410364-236066530  | 1,130m  | 1,131m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 21/09/2018               | Completed Defects | 20/09/2018      | A77 NB CW 20M FROM NETHER CULZEAN FARM JCT NORTH OF MAYBOLE            |
| SW82410364-236066521  | 628m    | 629m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 21/09/2018               | Completed Defects | 20/09/2018      | A77 SB CW 45 M NORTH OF MIARMILL FARM NORTH OF MAYBOLE                 |
| SW82410364-236066523  | 605m    | 606m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 21/09/2018               | Completed Defects | 20/09/2018      | A77 SB CW 30M NORTH OF MIARMILL FARM NORTH OF MAYBOLE                  |
| SW82410364-236066527  | 275m    | 276m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 21/09/2018               | Completed Defects | 20/09/2018      | A77 SB CW 800M NORTH OF MAYBOLE  |
| SW82410364-236066529  | 1,084m  | 1,085m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 21/09/2018               | Completed Defects | 20/09/2018      | A77 SB CW 15M FROM NETHER CULZEN FARM JCT NORTH OF MAYBOLE             |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| SW80-413634-236087133   | 1,201m  | 1,202m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 28/09/2018               | Completed Defects | 27/09/2018      | A77 NB CW BETWEEN NETHER CULZEANFARM JCT AND B742 JCT                  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| SW82416981-236101745  | 1,108m  | 1,109m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 05/10/2018               | Completed Defects | 04/10/2018      | A77 SB CW JUST OPPOSITE NETHER CULZEAN FARM JCT                        |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| SW82420227-236118407  | 1,096m  | 1,097m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 12/10/2018               | Completed Defects | 11/10/2018      | A77 NB CW 10M NORTH OF NETHER CULZEAN FARM JCT                         |
| SW82420227-236118408  | 1,105m  | 1,106m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 12/10/2018               | Completed Defects | 11/10/2018      | A77 NB CW 15M NORTH OF NETHER CULZEAN FARM JCT                         |
| SW82420227-236118411  | 1,108m  | 1,109m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 12/10/2018               | Completed Defects | 11/10/2018      | A77 NB CW 55M NORTH OF NETHER CULZEAN FARM JCT                         |
| SW82420227-236118415  | 755m    | 756m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 12/10/2018               | Completed Defects | 11/10/2018      | A77 SB CW ON CENTRE LINE AT LAYBY BETWEEN SMITHSTON BRIDGE AND MAYBOLE |
| SW82420227-236118409  | 1,110m  | 1,111m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 12/10/2018               | Completed Defects | 11/10/2018      | A77 NB CW 40M NORTH OF NETHER CULZEAN FARM JCT                         |
| SW82420227-236118410  | 1,108m  | 1,109m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 12/10/2018               | Completed Defects | 11/10/2018      | A77 NB CW 45M NORTH OF NETHER CULZEAN FARM JCT                         |
| SW82420227-236118413  | 1,113m  | 1,114m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 12/10/2018               | Completed Defects | 11/10/2018      | A77 SB CW OPPOSITE NETHER CULZEAN FARM JCT                             |
| SW82420227-236118416  | 639m    | 640m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 12/10/2018               | Completed Defects | 11/10/2018      | A77 SB CW 50M AFTER LAYBY NORTH OF MAYBOLE                             |



| Defect Reference   | Start m | End m  | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description   |
|--|---------|--------|-------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|--|
| SW82420227-236118412   | 1,110m  | 1,111m | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 12/10/2018               | Completed Defects     | 11/10/2018      | A77 SB CW OPPOSITE NETHER CULZEAN FARM JCT                     |
| SW82420227-236118414   | 758m    | 759m   | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 12/10/2018               | Completed Defects     | 11/10/2018      | A78 SB CW 5M BEFORE LAYBY BETWEEN SMITHSTON BRIDGE AND MAYBOLE |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |         |        |             |                                      |                 |                          |                       |                 |  |
| SW82332071-658   | 1,856m  | 1,636m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Completed Defects     | 13/12/2018      |  |
| SW82332071-653   | 489m    | 568m   | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-654   | 775m    | 855m   | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-656   | 1,580m  | 1,660m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-659   | 1,942m  | 2,022m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-652   | 237m    | 307m   | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-655   | 1,117m  | 1,197m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-657   | 1,743m  | 1,863m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-660   | 2,015m  | 2,095m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>      |         |        |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>      |         |        |             |                                      |                 |                          |                       |                 |  |
| SW82425931-236166530   | 762m    | 763m   | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 26/10/2018               | Completed Defects     | 25/10/2018      | A77 SB CW 5M BEFORE LAYBY SOUTH OF MAYBOLE                     |
| SW82425931-236166531   | 765m    | 766m   | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 26/10/2018               | Completed Defects     | 25/10/2018      | A77 SB CW AT CENTRE LINE AT LAYBY SOUTH OF MAYBOLE             |
| SW82425931-236166526   | 1,112m  | 1,113m | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 26/10/2018               | Completed Defects     | 25/10/2018      | A77 NB CW 35M FROM NETHER CULZEAN FARM JCT                     |
| SW82425931-236166528   | 277m    | 278m   | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 26/10/2018               | Completed Defects     | 25/10/2018      | A77 SB CW 505M FROM MAYBOLE SOUTH GATEWAY                      |
| SW82425931-236166525   | 1,113m  | 1,114m | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 26/10/2018               | Completed Defects     | 25/10/2018      | A77 NB CW 30M FROM NETHER CULZEAN FARM JCT                     |
| SW82425931-236166527   | 279m    | 280m   | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 26/10/2018               | Completed Defects     | 25/10/2018      | A77 SB CW 500M FROM MAYBOLE SOUTH GATEWAY                      |
| SW82425931-236166529   | 748m    | 749m   | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 26/10/2018               | Completed Defects     | 25/10/2018      | A77 SB CW 10M BEFORE LAYBY SOUTH OF MAYBOLE                    |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>     |         |        |             |                                      |                 |                          |                       |                 |  |
| SW82426212-236179765   | 640m    | 641m   | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 02/11/2018               | Completed Defects     | 01/11/2018      | A77 SB CW 200M FROM LAYBY NORTH OF MAYBOLE                     |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>     |         |        |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of Maybole Adhoc on 14 November 2018</b>        |         |        |             |                                      |                 |                          |                       |                 |  |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                                |
|--|---------|--------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|---|
| SW80-426564-16   | 1,075m  | 1,076m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 12/12/2018               | Completed Defects | 13/11/2018      | A77 1080M NTH OF DRUMELLAN                          |
| SW80-426564-17   | 1,119m  | 1,120m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 12/12/2018               | Completed Defects | 13/11/2018      | A77 1190M NTH OF DRUMELLAN                          |
| SW80-426564-5  | 271m    | 272m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 12/12/2018               | Completed Defects | 14/11/2018      | A77 270M NTH OF DRUMELLAN                           |
| SW80-426564-13   | 774m    | 775m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 12/12/2018               | Completed Defects | 13/11/2018      | A77 770M NTH OF DRUMELLAN                           |
| SW80-426564-20   | 1,198m  | 1,190m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 12/12/2018               | Completed Defects | 14/11/2018      | A77 1190M NTH OF DRUMELLAN                          |
| SW80-426564-6  | 494m    | 495m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 12/12/2018               | Completed Defects | 13/11/2018      | A77 495M NTH OF DRUMELLAN                           |
| SW80-426564-7  | 599m    | 600m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 12/12/2018               | Completed Defects | 13/11/2018      | A77 600M NTH OF DRUMELLAN                           |
| SW80-426564-9  | 601m    | 610m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 12/12/2018               | Completed Defects | 13/11/2018      | A77 610M NTH OF DRUMELLAN                           |
| SW80-426564-4  | 263m    | 264m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 12/12/2018               | Completed Defects | 14/11/2018      | A77 260M NTH OF DRUMELLAN                           |
| SW80-426564-14   | 781m    | 782m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 12/12/2018               | Completed Defects | 13/11/2018      | A77 780M NTH OF DRUMELLAN                           |
| SW80-426564-15   | 1,082m  | 1,083m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 12/12/2018               | Completed Defects | 13/11/2018      | A77 1075M NTH OF DRUMELLAN                          |
| SW80-426564-11   | 643m    | 645m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 12/12/2018               | Completed Defects | 13/11/2018      | A77 650M NTH OF DRUMELLAN                           |
| SW80-426564-18   | 1,145m  | 1,146m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 12/12/2018               | Completed Defects | 13/11/2018      | A77 1145M NTH OF DRUMELLAN                          |
| SW80-426564-8  | 601m    | 602m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 12/12/2018               | Completed Defects | 13/11/2018      | A77 605M NTH OF DRUMELLAN                           |
| SW80-426564-10   | 642m    | 643m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 12/12/2018               | Completed Defects | 13/11/2018      | A77 650M NTH OF DRUMELLAN                           |
| SW80-426564-12   | 679m    | 680m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 12/12/2018               | Completed Defects | 13/11/2018      | A77 680M NTH OF DRUMELLAN                           |
| SW80-426564-19   | 1,173m  | 1,174m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 12/12/2018               | Completed Defects | 14/11/2018      | A77 1170M NTH OF DRUMELLAN                          |
| SW80-426564-21   | 1,217m  | 1,218m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 12/12/2018               | Completed Defects | 14/11/2018      | A77 1200M NTH OF DRUMELLAN                          |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| SW80-427220-236234302  | 651m    | 652m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 07/12/2018               | Completed Defects | 06/12/2018      | A77 NORTH OF MAYBOLE                                |
| SW80-427220-236234298  | 764m    | 765m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 07/12/2018               | Completed Defects | 06/12/2018      | A77 SB CW AT LAYBY 155M SOUTH OF NETHER CULZEAN JCT |
| SW80-427220-236234303  | 649m    | 650m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 07/12/2018               | Completed Defects | 06/12/2018      | A77 NORTH OF MAYBOLE                                |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                                  |
|--|---------|--------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|---|
| SW80-427220-236234304  | 622m    | 623m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 07/12/2018               | Completed Defects | 06/12/2018      | A77 NORTH OF MAYBOLE                                  |
| SW80-427220-236234300  | 655m    | 656m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 07/12/2018               | Completed Defects | 06/12/2018      | A77 NORTH OF MAYBOLE                                  |
| SW80-427220-236234297  | 751m    | 752m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 07/12/2018               | Completed Defects | 06/12/2018      | A77 SB CW AT LAYBY 150 SOUTH OF NETHER CULZEAN JCT    |
| SW80-427220-236234299  | 655m    | 656m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 07/12/2018               | Completed Defects | 06/12/2018      | A77 NORTH OF MAYBOLE                                  |
| SW80-427220-236234301  | 651m    | 652m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 07/12/2018               | Completed Defects | 06/12/2018      | A77 NORTH OF MAYBOLE                                  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| SW82427366-236262634   | 656m    | 657m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 10/01/2019               | Completed Defects | 13/12/2018      | A77 SB CW, 650M NTH OF DRUMELLAN, NTH OF MAYBOLE      |
| SW82427366-236262635   | 942m    | 943m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 10/01/2019               | Completed Defects | 14/12/2018      | A77 NB CW, 950M NTH OF DRUMELLAN, NTH OF MAYBOLE      |
| SW82427366-236262637   | 1,112m  | 1,113m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 10/01/2019               | Completed Defects | 14/12/2018      | A77 290M NTH OF DALYRMPLE JCT, NTH OF MAYBOLE, NB CW  |
| SW82427366-236262633   | 494m    | 495m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 10/01/2019               | Completed Defects | 13/12/2018      | A77 SB CW, 500M NTH OF DRUMELLAN, NTH OF MAYBOLE      |
| SW82427366-236262636   | 1,112m  | 1,113m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 10/01/2019               | Completed Defects | 13/12/2018      | A77 ON CL, 300M STH OF DALRYMPLE JCT, NTH OF MAYBOLE  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| SW82427527-236264612   | 1,115m  | 1,116m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 17/01/2019               | Completed Defects | 21/12/2018      | A77 NB CW 20M AFTER NETHER CULZEAN FARM JCT           |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| SW82428351-236284336   | 808m    | 809m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 21/02/2019               | Completed Defects | 11/02/2019      | A77 NB CW, 800M NTH OF DRUMELLAN NTH OF MAYBOLE       |
| SW82428351-236284335   | 679m    | 680m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 21/02/2019               | Completed Defects | 11/02/2019      | A77 NB CW, 680M NTH OF DRUMELLAN FARM, NTH OF MAYBOLE |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>    |         |        |             |                       |                 |                          |                   |                 |   |

| Defect Reference   | Start<br>m | End<br>m | Item Type   | Item Detail                                | Defect<br>Category | Required<br>Completion Date | Current Status       | Completion<br>Date | Location Description   |
|--|------------|----------|-------------|--|--------------------|-----------------------------|----------------------|--------------------|--|
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |  |
| <b>11632/23 : SMITHSTON BRIDGE TO JUNCTION KEWNSTON</b>              |            |          |             |  |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>      |            |          |             |  |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>      |            |          |             |  |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>      |            |          |             |  |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>      |            |          |             |  |                    |                             |                      |                    |  |
| SW82317793-235529565   | 275m       | 276m     | CARRIAGEWAY | Pothole<br>(POTH)                          | CAT 1              | 22/02/2018                  | Completed<br>Defects | 09/02/2018         | A77 SB CW, 200M NTH OF<br>SMITHTON BRIDGE, NTH OF<br>MAYBOLE |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b>     |            |          |             |  |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b>     |            |          |             |  |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b>     |            |          |             |  |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b>     |            |          |             |  |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>        |            |          |             |  |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>        |            |          |             |  |                    |                             |                      |                    |  |
| SW82326075-235554292   | 347m       | 348m     | CARRIAGEWAY | Pothole<br>(POTH)                          | CAT 1              | 05/04/2018                  | Completed<br>Defects | 08/03/2018         | A77 SB CW, 300M NTH OF<br>SMITHTON BRIDGE, NTH OF<br>MAYBOLE |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>        |            |          |             |  |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>        |            |          |             |  |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>        |            |          |             |  |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>        |            |          |             |  |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>        |            |          |             |  |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>        |            |          |             |  |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>        |            |          |             |  |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>          |            |          |             |  |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>          |            |          |             |  |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |            |          |             |  |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |            |          |             |  |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |            |          |             |  |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |            |          |             |  |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |            |          |             |  |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |            |          |             |  |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |            |          |             |  |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |            |          |             |  |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |            |          |             |  |                    |                             |                      |                    |  |
| SW82374127-235892346   | 341m       | 342m     | CARRIAGEWAY | Miscellaneous<br>surface Defects<br>(MSRF) | CAT 1              | 02/08/2018                  | Completed<br>Defects | 02/08/2018         | A77 SB CW 500M PRIOR TO<br>SMITHTON BRIDGE                   |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |            |          |             |  |                    |                             |                      |                    |  |

| Defect Reference   | Start m | End m  | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                              |
|--|---------|--------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |   |
| SW82383889-235917495   | 1,511m  | 1,512m | TRAFFIC_SIGNS      | Missing (door / lamp / bowl) (MISP)  | CAT 1           | 23/08/2018               | Completed Defects     | 26/07/2018      | A77 SB CW AT THE SOTH GATEWAY                     |
| SW82383889-235917496   | 135m    | 136m   | TRAFFIC_SIGNS      | Obscured sign (OBSG)                 | CAT 1           | 23/08/2018               | Completed Defects     | 31/07/2018      | A77 SB CW 100M PRIOR TO SMITHTON BRIDG4           |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |         |        |                    |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |         |        |                    |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |         |        |                    |                                      |                 |                          |                       |                 |   |
| SW80-394061-235954869  | 1,433m  | 1,433m | TRAFFIC_SIGNS      | Obscured sign (OBSG)                 | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | A77 100M SOUTH OF MINISHANT                       |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |         |        |                    |                                      |                 |                          |                       |                 |   |
| SW80-397303-235954871  | 1,493m  | 1,494m | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 24/08/2018               | Completed Defects     | 23/08/2018      | A77 S/B C/W 20M SOUTH OF MINISHANT SOUTH GATEWAY  |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>       |         |        |                    |                                      |                 |                          |                       |                 |   |
| SW80-400497-235984879  | 1,616m  | 1,617m | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 31/08/2018               | Completed Defects     | 30/08/2018      | A77 N/B C/W 305M NORTH OF MINISHANT SOUTH GATEWAY |
| SW80-400497-235984878  | 1,620m  | 1,621m | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 31/08/2018               | Completed Defects     | 30/08/2018      | A77 N/B C/W 300M NORTH OF MINISHANT SOUTH GATEWAY |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b>    |         |        |                    |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b>    |         |        |                    |                                      |                 |                          |                       |                 |   |
| SW82407181-236053593   | 508m    | 509m   | MANHOLE            | Missing (MISS)                       | CAT 1           | 11/10/2018               | Completed Defects     | 20/09/2018      | A77 S/B VERGE 400M NORTH OF SMITHSTON BRIDGE      |
| SW82407181-236053592   | 1,455m  | 1,456m | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 14/09/2018               | Completed Defects     | 13/09/2018      | A77 S/B C/W 50M SOUTH OF MINISHANT SOUTH GATEWAY  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b>    |         |        |                    |                                      |                 |                          |                       |                 |   |
| SW82410364-236066541   | 1,526m  | 1,527m | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 21/09/2018               | Completed Defects     | 20/09/2018      | A77 SB CW MINISHANT SOUTH GATEWAY                 |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b>    |         |        |                    |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>      |         |        |                    |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>      |         |        |                    |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |                    |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |   |
| SW82332071-662   | 238m    | 338m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Completed Defects     | 21/11/2018      |   |
| SW82332071-664   | 606m    | 706m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Completed Defects     | 21/11/2018      |   |
| SW82332071-666   | 1,009m  | 1,089m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-663   | 388m    | 488m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Completed Defects     | 21/11/2018      |   |
| SW82332071-665   | 624m    | 704m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |

| Defect Reference   | Start m | End m  | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                         |
|--|---------|--------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|--|
| SW82332071-667   | 1,580m  | 1,600m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-661   | 130m    | 230m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Completed Defects     | 21/11/2018      |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>  |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW82423458-236136750   | 1,497m  | 1,498m | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 15/11/2018               | Completed Defects     | 18/10/2018      | A77 SB CW, 100M STH OF MINISHANT STH GATEWAY |
| SW82423458-236136751   | 1,532m  | 1,533m | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 15/11/2018               | Completed Defects     | 18/10/2018      | A77 NB CW, 50M STH OF MINISHANT STH GATEWAY  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>  |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW80-427220-236234295  | 1,465m  | 1,466m | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 07/12/2018               | Completed Defects     | 06/12/2018      | A77 SB CW MINISHANT SOUTH GATEWAY            |
| SW80-427220-236234294  | 1,465m  | 1,466m | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 07/12/2018               | Completed Defects     | 06/12/2018      | A77 SB CW LEAVING MINISHANT                  |
| SW80-427220-236234296  | 1,463m  | 1,464m | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 07/12/2018               | Completed Defects     | 06/12/2018      | A77 SB CW MINISHANT SOUTH GATEWAY            |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW82427366-236262638   | 277m    | 278m   | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 10/01/2019               | Completed Defects     | 13/12/2018      | A77 ON CL, 150M NTH OF SMITHSTON BRIDGE      |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>  |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>  |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>  |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>  |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>  |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>    |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>    |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>    |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |

| Defect Reference   | Start m | End m | Item Type   | Item Detail            | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description   |
|--|---------|-------|-------------|------------------------|-----------------|--------------------------|-------------------|-----------------|--|
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>    |         |       |             |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                        |                 |                          |                   |                 |  |
| <b>11632/40 : JUNCTION KEWNSTON TO CULROY BURN BRIDGE</b>        |         |       |             |                        |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>  |         |       |             |                        |                 |                          |                   |                 |  |
| SW82317326-235513685   | 724m    | 726m  | CARRIAGEWAY | Pothole (POTH)         | CAT 1           | 01/02/2018               | Completed Defects | 22/01/2018      | OUTSIDE 8 MAIN STREET MINISHANT N/B CW   |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>  |         |       |             |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                        |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>  |         |       |             |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                        |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>  |         |       |             |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                        |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b> |         |       |             |                        |                 |                          |                   |                 |  |
| SW82318129-235532261   | 44m     | 45m   | CARRIAGEWAY | Pothole (POTH)         | CAT 1           | 01/03/2018               | Completed Defects | 02/02/2018      | A77 SB CW, MINISHANT   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b> |         |       |             |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                        |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b> |         |       |             |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                        |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b> |         |       |             |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                        |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>    |         |       |             |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                        |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>    |         |       |             |                        |                 |                          |                   |                 |  |
| SW82326075-235554291   | 247m    | 248m  | CARRIAGEWAY | Pothole (POTH)         | CAT 1           | 05/04/2018               | Completed Defects | 08/03/2018      | A77 SB CW, 250M NTH OF MINISHANT STH GATEWAY, OPP SCHOOL                       |
| SW82326075-235554290   | 145m    | 146m  | BOLLARDS    | Accident damage (ACCD) | CAT 1           | 05/04/2018               | Completed Defects | 11/04/2018      | A77 ON CL, AT TRAFFIC ISLAND OPPOSITE SCHOOL, SECOND ISLAND NTH OF NTH GATEWAY |
| SW82326075-235554289   | 782m    | 783m  | BOLLARDS    | Accident damage (ACCD) | CAT 1           | 05/04/2018               | Completed Defects | 11/04/2018      | A77 MINISHANT, ON FIRST CENTER ISLAND HEADING SOUTH                            |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>    |         |       |             |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                        |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>    |         |       |             |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                        |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>    |         |       |             |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                        |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>    |         |       |             |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                        |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>    |         |       |             |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                        |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>    |         |       |             |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                        |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>    |         |       |             |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                        |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>      |         |       |             |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                        |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>      |         |       |             |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                        |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>      |         |       |             |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                        |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>      |         |       |             |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                        |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>      |         |       |             |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                        |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>     |         |       |             |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                        |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>     |         |       |             |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                        |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>     |         |       |             |                        |                 |                          |                   |                 |  |

| Defect Reference   | Start m | End m | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                                   |
|--|---------|-------|-------------|--------------------------------------|-----------------|--------------------------|-------------------|-----------------|--|
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                   |                 |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |         |       |             |                                      |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |         |       |             |                                      |                 |                          |                   |                 |  |
| SW80-370510-235861178  | 726m    | 727m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 26/07/2018               | Completed Defects | 28/06/2018      | A78 NB CW 100M PRIOR TO LAWNMOWER GARAGE MINISHANT     |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |         |       |             |                                      |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |         |       |             |                                      |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |         |       |             |                                      |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |         |       |             |                                      |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |         |       |             |                                      |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |         |       |             |                                      |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |         |       |             |                                      |                 |                          |                   |                 |  |
| SW80-394061-235954870  | 83m     | 84m   | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 17/08/2018               | Completed Defects | 16/08/2018      | A77 N/B C/W JUST AFTER SCHOOL MINSHANT                 |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |         |       |             |                                      |                 |                          |                   |                 |  |
| SW80-397303-235954872  | 89m     | 90m   | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 24/08/2018               | Completed Defects | 23/08/2018      | A77 N/B C/W 100M NORTH OF MINISHANT SOUTH GATEWAY      |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>       |         |       |             |                                      |                 |                          |                   |                 |  |
| SW80-400497-235984877  | 496m    | 497m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 31/08/2018               | Completed Defects | 30/08/2018      | A77 S/B C/W OPPOSITE WOODEN HOUSES MAIN ROAD MINISHANT |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b>    |         |       |             |                                      |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b>    |         |       |             |                                      |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b>    |         |       |             |                                      |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b>    |         |       |             |                                      |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>      |         |       |             |                                      |                 |                          |                   |                 |  |
| SW82416981-236101753   | 239m    | 240m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 05/10/2018               | Completed Defects | 04/10/2018      | A77 NB CW 50M AFTER MINISHANT SOUTH GATEWAY            |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>      |         |       |             |                                      |                 |                          |                   |                 |  |
| SW82420227-236118422   | 704m    | 705m  | GULLY       | Cracked or broken (IBCK)             | CAT 1           | 08/11/2018               | Completed Defects | 06/11/2018      | A77 NB CW 20M BEFORE THE NORTH GATEWAY MINISHANT       |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |         |       |             |                                      |                 |                          |                   |                 |  |
| SW82332071-668   | 321m    | 341m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Completed Defects | 27/03/2019      |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>      |         |       |             |                                      |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>      |         |       |             |                                      |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>     |         |       |             |                                      |                 |                          |                   |                 |  |
| SW82426212-236179766   | 84m     | 85m   | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 02/11/2018               | Completed Defects | 01/11/2018      | A77 NB CW AT MINISHANT SOUTH GATEWAY                   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>     |         |       |             |                                      |                 |                          |                   |                 |  |
| SW82426441-236211994   | 454m    | 455m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 09/11/2018               | Completed Defects | 08/11/2018      | A77 SB CW 20M BEFORE MURE PLACE MINISHANT              |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>     |         |       |             |                                      |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b>     |         |       |             |                                      |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                   |                 |  |



| Defect Reference   | Start m | End m | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                           |
|--|---------|-------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|--|
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b> |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b> |         |       |             |                       |                 |                          |                   |                 |  |
| SW80-427220-236234316  | 368m    | 369m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 07/12/2018               | Completed Defects | 06/12/2018      | A77 SB CW BUSSTOP AT MINISHANT                 |
| SW80-427220-236234293  | 259m    | 260m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 07/12/2018               | Completed Defects | 06/12/2018      | A77 SB CW 105M FROM BUSSTOP MINISHANT          |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b> |         |       |             |                       |                 |                          |                   |                 |  |
| SW82427366-236262639   | 484m    | 485m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 10/01/2019               | Completed Defects | 14/12/2018      | A77 NB CW, AT TRAFFIC ISLAND, MINISHANT        |
| SW82427366-236262640   | 623m    | 624m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 10/01/2019               | Completed Defects | 14/12/2018      | A77 NB CW, OUTSIDE MINISHANT SHOP              |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b> |         |       |             |                       |                 |                          |                   |                 |  |
| SW82427527-236264613   | 436m    | 436m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 17/01/2019               | Completed Defects | 11/01/2019      | A77 SB CW 100M AFTER MINISHANT SHOPS ON BEND   |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b> |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| SW82428044-236270558   | 443m    | 444m  | GULLY       | Blockage (BLOK)       | CAT 1           | 11/01/2019               | Completed Defects | 10/01/2019      | A77 SB CW ACROSS FROM MURE PLACE JCT MINISHANT |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |  |
| SW82436659-236335204   | 96m     | 98m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 01/03/2019               | Completed Defects | 28/02/2019      | A77 N/B 300M AFTER GATEWAY                     |
| SW82436659-236335206   | 24m     | 29m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 28/03/2019               | Completed Defects | 19/03/2019      | A77 S/B 30M PRIOR TO LAIGH MIDTON FARM         |
| SW82436659-236335205   | 493m    | 495m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 01/03/2019               | Completed Defects | 28/02/2019      | A77 S/B OPP 1 MAIN RD MINISHANT                |
| SW82436659-236335207   | 724m    | 726m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 01/03/2019               | Completed Defects | 28/02/2019      | A77 N/B AT 12 MAIN RD MINISHANT                |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>11632/49 : CULROY BURN BRIDGE TO B7034 JUNCTION</b>           |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>  |         |       |             |                       |                 |                          |                   |                 |  |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                                   |
|--|---------|--------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|--|
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>      |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b>     |         |        |             |                       |                 |                          |                   |                 |  |
| SW82318129-235532259   | 1,567m  | 1,568m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 01/03/2018               | Completed Defects | 02/02/2018      | A77 SB CW, 100M NTH OF RIVER DOON                      |
| SW82318129-235532260   | 1,263m  | 1,264m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 01/03/2018               | Completed Defects | 02/02/2018      | A77 SB CW, ON RIVER DOON BRIDGE                        |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b>     |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b>     |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b>     |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>        |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>        |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>        |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>        |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>        |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>        |         |        |             |                       |                 |                          |                   |                 |  |
| SW82334882-235613712   | 1,554m  | 0m     | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 06/04/2018               | Completed Defects | 05/04/2018      | A77 S/B 300M PRIOR TO RIVERSIDE INN MINISHANT          |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>        |         |        |             |                       |                 |                          |                   |                 |  |
| SW82336916-235633872   | 1,280m  | 1,281m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 10/05/2018               | Completed Defects | 12/04/2018      | A77 NB CW, ON BRIDGE OVER RIVER DOON, NTH OF MINISHANT |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>        |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>        |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>          |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>          |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |         |        |             |                       |                 |                          |                   |                 |  |
| SW82383889-235917491   | 683m    | 684m   | GULLY       | Blockage (BLOK)       | CAT 1           | 23/08/2018               | Completed Defects | 03/08/2018      | A77 SB CW 50M STH OF RIVER DOON                        |

| Defect Reference   | Start m | End m  | Item Type     | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                          |
|--|---------|--------|---------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| SW82383889-235917492   | 595m    | 596m   | GULLY         | Blockage (BLOK)                      | CAT 1           | 23/08/2018               | Completed Defects     | 03/08/2018      | A77 SB CW 25M PRIOR TO RIVER DOON             |
| SW82383889-235917494   | 569m    | 570m   | GULLY         | Blockage (BLOK)                      | CAT 1           | 23/08/2018               | Completed Defects     | 03/08/2018      | A77 SB CW 425M PRIOR TO MINISHANT NTH GATEWAY |
| SW82383889-235917493   | 526m    | 527m   | GULLY         | Blockage (BLOK)                      | CAT 1           | 23/08/2018               | Completed Defects     | 03/08/2018      | A77 SB CW 400M PRIOR TO MINISHANT NTH GATEWAY |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |         |        |               |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |         |        |               |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |         |        |               |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |         |        |               |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>       |         |        |               |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b>    |         |        |               |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b>    |         |        |               |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b>    |         |        |               |                                      |                 |                          |                       |                 |   |
| SW82410364-236066542   | 1,901m  | 1,902m | CARRIAGEWAY   | Pothole VIAFIX (POTV)                | CAT 1           | 21/09/2018               | Completed Defects     | 20/09/2018      | A77 NB CW 50M PRIOR TO JCT B7034              |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b>    |         |        |               |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |         |        |               |                                      |                 |                          |                       |                 |   |
| SW82332071-587   | 1,170m  | 1,170m | TRAFFIC_SIGNS | Physical condition of post (COPT)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-589   | 1,268m  | 1,288m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-562   | 146m    | 149m   | CARRIAGEWAY   | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-574   | 693m    | 713m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-583   | 993m    | 995m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-585   | 1,128m  | 1,128m | TRAFFIC_SIGNS | Surface corrosion (SFCO)             | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-576   | 801m    | 841m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-578   | 857m    | 867m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-570   | 565m    | 568m   | MANHOLE       | Other (OTHR)                         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-571   | 630m    | 640m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-590   | 1,267m  | 1,287m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-593   | 1,532m  | 1,537m | CARRIAGEWAY   | Other (OTHR)                         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |

| Defect Reference | Start m | End m  | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|--------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82332071-567   | 530m    | 535m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-579   | 870m    | 875m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-586   | 1,150m  | 1,180m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-575   | 737m    | 767m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-582   | 995m    | 1,010m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-584   | 1,014m  | 1,024m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-577   | 840m    | 845m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-564   | 428m    | 438m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-566   | 490m    | 500m   | CARRIAGEWAY        | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-573   | 667m    | 682m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-580   | 879m    | 889m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-565   | 480m    | 495m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-581   | 938m    | 958m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-588   | 1,231m  | 1,241m | CARRIAGEWAY        | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-563   | 368m    | 448m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-568   | 555m    | 590m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-569   | 555m    | 560m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-572   | 667m    | 747m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-591   | 1,280m  | 1,285m | CARRIAGEWAY        | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-592   | 1,308m  | 1,308m | TRAFFIC_SIGNS      | Physical condition of post (COPT)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | <                    |

Safety Inspection of A77 Ayr South V1 on 04 October 2018

| Defect Reference  | Start m | End m  | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                     |
|---|---------|--------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|--|
| SW82416981-236101754  | 1,887m  | 1,887m | GULLY       | Other (OTHR)          | CAT 1           | 05/10/2018               | Completed Defects | 04/10/2018      | A77 NB CW 20M FROM JCT B7034             |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| SW82426587-236223186  | 1,554m  | 1,555m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 16/11/2018               | Completed Defects | 15/11/2018      | A77 SB CW 200 YARDS BEFORE RIVERSIDE INN |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| SW82436659-236335200  | 680m    | 681m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 01/03/2019               | Completed Defects | 28/02/2019      | A77 S/B 30M AFTER AUCHENDRANE EST        |
| SW82436659-236335199  | 700m    | 701m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 01/03/2019               | Completed Defects | 28/02/2019      | A77 N/B 20M PRIOR TO AUCHENDRANE EST     |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>     |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>     |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>     |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>     |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>11632/72 : B7034 JUNCTION TO JUNCTION A79 MAYBOLE ROAD AYR</b> |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>   |         |        |             |                       |                 |                          |                   |                 |  |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail    | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description  |
|--|---------|--------|-------------|----------------|-----------------|--------------------------|-----------------------|-----------------|---|
| <i>No defects recorded</i>                                       |         |        |             |                |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>  |         |        |             |                |                 |                          |                       |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b> |         |        |             |                |                 |                          |                       |                 |   |
| SW82318129-235532258   | 1,264m  | 1,266m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 01/03/2018               | Completed Defects     | 02/02/2018      | A77 NB CW, 300M STH OF CORTON RD END  |
| SW82318129-235532257   | 2,417m  | 2,418m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 01/03/2018               | Completed Defects     | 02/02/2018      | A77 NB CW, OPPOSITE MAYBOLE RD JCT AYR  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b> |         |        |             |                |                 |                          |                       |                 |   |
| SW82319037-235539774   | 1,238m  | 1,258m | CARRIAGEWAY | Pothole (POTH) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | A77 SB CW, APPROX 1KM STH OF DOONFOOT JCT AYR                                 |
| SW82319037-235539770   | 2,159m  | 2,169m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 08/03/2018               | Completed Defects     | 08/02/2018      | A77 NB CW, 200M STH OF MAYBOLE RD JCT AYR, MULTIPLE POTHLES                   |
| SW82319037-235539771   | 2,203m  | 2,204m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 08/03/2018               | Completed Defects     | 08/02/2018      | A77 NB, 100M STH OF MAYBOLE RD JCT, AYR                                       |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b> |         |        |             |                |                 |                          |                       |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b> |         |        |             |                |                 |                          |                       |                 |   |
| SW82321955-235548218   | 1,323m  | 1,325m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 22/03/2018               | Completed Defects     | 23/02/2018      | NORTH OF AUCHINBLANE SOUTH OF MOSSIDE LAY BY SIBCW 1500 M NORTH OF KIRKOSWALD |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>    |         |        |             |                |                 |                          |                       |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>    |         |        |             |                |                 |                          |                       |                 |   |
| SW82326075-235554327   | 1,261m  | 1,266m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 05/04/2018               | Completed Defects     | 08/03/2018      | A77 SB CW, 100M NTH OF BROOMBERRY FARM, STH OF AYR                            |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>    |         |        |             |                |                 |                          |                       |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>    |         |        |             |                |                 |                          |                       |                 |   |
| SW82330474-235608123   | 686m    | 687m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 19/04/2018               | Completed Defects     | 23/03/2018      | A77 SB CW, OUTSIDE FORD COTTAGE, NTH OF DALRYMPLE JCT, NTH MINISHANT          |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>    |         |        |             |                |                 |                          |                       |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>    |         |        |             |                |                 |                          |                       |                 |   |
| SW82334882-235613713   | 300m    | 0m     | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 03/05/2018               | Completed Defects     | 18/04/2018      | A77 N/B 400M SOUTH OF FORD LODGE  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>    |         |        |             |                |                 |                          |                       |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>    |         |        |             |                |                 |                          |                       |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>    |         |        |             |                |                 |                          |                       |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>      |         |        |             |                |                 |                          |                       |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>      |         |        |             |                |                 |                          |                       |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>      |         |        |             |                |                 |                          |                       |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>      |         |        |             |                |                 |                          |                       |                 |   |
| SW82352984-235812711   | 234m    | 235m   | GULLY       | Other (OTHR)   | CAT 1           | 21/06/2018               | Completed Defects     | 16/06/2018      | A77 SB CW 200M PRIOR TO JCT 7034 DALRYMPLE                                    |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>      |         |        |             |                |                 |                          |                       |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>     |         |        |             |                |                 |                          |                       |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>     |         |        |             |                |                 |                          |                       |                 |   |

| Defect Reference   | Start m | End m  | Item Type          | Item Detail                       | Defect Category | Required Completion Date | Current Status               | Completion Date | Location Description                                       |
|--|---------|--------|--------------------|-----------------------------------|-----------------|--------------------------|------------------------------|-----------------|--|
| SW80-363687-235858062  | 1,112m  | 1,242m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR) | CAT 1           | 12/07/2018               | Awaiting CCMS Permanent Date | 01/01/9999      | A77 CL JCT B7034 AYR YO MINISHANT                          |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |         |        |                    |                                   |                 |                          |                              |                 |  |
| No defects recorded  |         |        |                    |                                   |                 |                          |                              |                 |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |         |        |                    |                                   |                 |                          |                              |                 |  |
| SW86-357213-1  | 1,132m  | 1,122m | WOODLAND           | Invasive species (INVS)           | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action        | 01/01/9999      |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |         |        |                    |                                   |                 |                          |                              |                 |  |
| No defects recorded  |         |        |                    |                                   |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |         |        |                    |                                   |                 |                          |                              |                 |  |
| No defects recorded  |         |        |                    |                                   |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |         |        |                    |                                   |                 |                          |                              |                 |  |
| SW82377424-235909983   | 638m    | 640m   | CARRIAGEWAY        | Pothole (POTH)                    | CAT 1           | 09/08/2018               | Completed Defects            | 12/07/2018      | A77 ON CL, 100M NTH OF SB LAYBY ON BEND NTH OF RIVER DOON  |
| SW82377424-235909982   | 920m    | 921m   | CARRIAGEWAY        | Pothole (POTH)                    | CAT 1           | 09/08/2018               | Completed Defects            | 12/07/2018      | A77 ON CL, STH OF LAYBY ON BEND, STH OF RIVER DOON         |
| SW82377424-235909978   | 1,569m  | 1,570m | CARRIAGEWAY        | Pothole (POTH)                    | CAT 1           | 09/08/2018               | Completed Defects            | 13/07/2018      | A77 NB CW, 350M STH OF CORTON RD JCT                       |
| SW82377424-235909980   | 1,416m  | 1,417m | CARRIAGEWAY        | Pothole (POTH)                    | CAT 1           | 09/08/2018               | Completed Defects            | 12/07/2018      | A77 NB CW, 50M NTH OF BROOMBERRY COTTAGE STH OF CORTON     |
| SW82377424-235909981   | 1,356m  | 1,366m | CARRIAGEWAY        | Pothole (POTH)                    | CAT 1           | 09/08/2018               | Completed Defects            | 06/08/2018      | A77 ON CL, 100M STH OF BROOMBERRY COTTAGE STH O CORTON JCT |
| SW82377424-235909977   | 1,623m  | 1,624m | CARRIAGEWAY        | Pothole (POTH)                    | CAT 1           | 09/08/2018               | Completed Defects            | 13/07/2018      | A77 NB CW, 250M STH OF CORTON RD JCT STH OF AYR            |
| SW82377424-235909979   | 1,539m  | 1,550m | CARRIAGEWAY        | Pothole (POTH)                    | CAT 1           | 09/08/2018               | Completed Defects            | 12/07/2018      | A77 NB CW, OUTSIDE BROOMBERRY COTTAGE, STH OF CORTON JCT   |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |         |        |                    |                                   |                 |                          |                              |                 |  |
| No defects recorded  |         |        |                    |                                   |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |         |        |                    |                                   |                 |                          |                              |                 |  |
| No defects recorded  |         |        |                    |                                   |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |         |        |                    |                                   |                 |                          |                              |                 |  |
| No defects recorded  |         |        |                    |                                   |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |         |        |                    |                                   |                 |                          |                              |                 |  |
| No defects recorded  |         |        |                    |                                   |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |         |        |                    |                                   |                 |                          |                              |                 |  |
| No defects recorded  |         |        |                    |                                   |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |         |        |                    |                                   |                 |                          |                              |                 |  |
| No defects recorded  |         |        |                    |                                   |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>       |         |        |                    |                                   |                 |                          |                              |                 |  |
| No defects recorded  |         |        |                    |                                   |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b>    |         |        |                    |                                   |                 |                          |                              |                 |  |
| SW80-403929-235984882  | 1,736m  | 1,737m | GULLY              | Broken (BROK)                     | CAT 1           | 07/09/2018               | Completed Defects            | 06/09/2018      | A77 SB CW NORTH OF CORTON LEA JUNCTION                     |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b>    |         |        |                    |                                   |                 |                          |                              |                 |  |
| No defects recorded  |         |        |                    |                                   |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b>    |         |        |                    |                                   |                 |                          |                              |                 |  |
| No defects recorded  |         |        |                    |                                   |                 |                          |                              |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b>    |         |        |                    |                                   |                 |                          |                              |                 |  |
| SW80-413634-236087135  | 1,246m  | 1,247m | CARRIAGEWAY        | Pothole VIAFIX (POTV)             | CAT 1           | 28/09/2018               | Completed Defects            | 27/09/2018      | A77 SB CW APPROX 500M SOUTH OF DOONHOLM JCT                |
| SW80-413634-236087134  | 2,112m  | 2,113m | TRAFFIC_SIGNS      | Damaged (DAMG)                    | CAT 1           | 25/10/2018               | Completed Defects            | 24/10/2018      | A77 SB CW 100M PRIOR TO DOONHOLM JUNCTION                  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |         |        |                    |                                   |                 |                          |                              |                 |  |

| Defect Reference | Start m | End m  | Item Type     | Item Detail                                  | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|--------|---------------|--|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82332071-602   | 679m    | 684m   | CARRIAGEWAY   | Localised cracking (LOCK)                    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-603   | 721m    | 726m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-617   | 1,616m  | 1,696m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-620   | 1,910m  | 1,910m | TRAFFIC_SIGNS | Physical condition of post (COPT)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-599   | 530m    | 540m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-606   | 845m    | 865m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-613   | 1,417m  | 1,497m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-596   | 281m    | 286m   | FOOTWAY       | Bituminous surfacing - local cracking (BLCK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-598   | 502m    | 512m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-605   | 827m    | 842m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-607   | 871m    | 873m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-594   | 258m    | 302m   | FOOTWAY       | Bituminous surfacing fretting (BFRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-609   | 1,087m  | 1,167m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-611   | 1,346m  | 1,446m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-597   | 310m    | 315m   | FOOTWAY       | Bituminous surfacing - local cracking (BLCK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-604   | 760m    | 765m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-615   | 1,480m  | 1,560m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-622   | 1,961m  | 1,961m | TRAFFIC_SIGNS | Physical condition of post (COPT)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-600   | 573m    | 583m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-601   | 662m    | 682m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |



| Defect Reference   | Start m | End m  | Item Type     | Item Detail                                  | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                                    |
|--|---------|--------|---------------|--|-----------------|--------------------------|-----------------------|-----------------|---|
| SW82332071-618   | 1,848m  | 1,848m | TRAFFIC_SIGNS | Physical condition of post (COPT)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-619   | 1,861m  | 1,861m | FOOTWAY       | Bituminous surfacing - local cracking (BLCK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-595   | 276m    | 281m   | FOOTWAY       | Bituminous surfacing - local cracking (BLCK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-608   | 894m    | 896m   | CARRIAGEWAY   | Other (OTHR)                                 | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-610   | 1,281m  | 1,291m | CARRIAGEWAY   | Other (OTHR)                                 | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-612   | 1,346m  | 1,446m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-614   | 1,413m  | 1,493m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-616   | 1,523m  | 1,523m | TRAFFIC_SIGNS | Physical condition of post (COPT)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-621   | 1,960m  | 1,960m | TRAFFIC_SIGNS | Physical condition of post (COPT)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-623   | 2,085m  | 2,085m | TRAFFIC_SIGNS | Physical condition of post (COPT)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>  |         |        |               |  |                 |                          |                       |                 |   |
| No defects recorded  |         |        |               |  |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>  |         |        |               |  |                 |                          |                       |                 |   |
| No defects recorded  |         |        |               |  |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>  |         |        |               |  |                 |                          |                       |                 |   |
| SW82423458-236136752   | 188m    | 189m   | CARRIAGEWAY   | Pothole VIAFIX (POTV)                        | CAT 1           | 15/11/2018               | Completed Defects     | 18/10/2018      | A77 NB CW, 50M PRIOR TO DALYRMPLE JCT, NTH OF MINISHANT |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>  |         |        |               |  |                 |                          |                       |                 |   |
| No defects recorded  |         |        |               |  |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b> |         |        |               |  |                 |                          |                       |                 |   |
| No defects recorded  |         |        |               |  |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b> |         |        |               |  |                 |                          |                       |                 |   |
| No defects recorded  |         |        |               |  |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b> |         |        |               |  |                 |                          |                       |                 |   |
| No defects recorded  |         |        |               |  |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b> |         |        |               |  |                 |                          |                       |                 |   |
| No defects recorded  |         |        |               |  |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b> |         |        |               |  |                 |                          |                       |                 |   |
| No defects recorded  |         |        |               |  |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b> |         |        |               |  |                 |                          |                       |                 |   |
| SW80-427220-236234292  | 1,344m  | 1,345m | CARRIAGEWAY   | Pothole VIAFIX (POTV)                        | CAT 1           | 07/12/2018               | Completed Defects     | 06/12/2018      | A77 SB CW 100M FROM BUSSTOP MINISHANT                   |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b> |         |        |               |  |                 |                          |                       |                 |   |
| SW82427366-236262641   | 1,136m  | 1,137m | CARRIAGEWAY   | Pothole VIAFIX (POTV)                        | CAT 1           | 10/01/2019               | Completed Defects     | 13/12/2018      | A77 ON CL, 200M STH OF BROOMBERRY FARM, STH OF AYR      |
| SW82427366-236262642   | 1,653m  | 1,654m | CARRIAGEWAY   | Pothole VIAFIX (POTV)                        | CAT 1           | 10/01/2019               | Completed Defects     | 13/12/2018      | A77 NB CW, 150M STH OF CORTON JCT, STH OF AYR           |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b> |         |        |               |  |                 |                          |                       |                 |   |
| No defects recorded  |         |        |               |  |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b> |         |        |               |  |                 |                          |                       |                 |   |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                                |
|--|---------|--------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|---|
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| SW82436659-236335208   | 707m    | 708m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 01/03/2019               | Completed Defects | 28/02/2019      | A77 N/B 100M AFTER FORD COTTAGE                     |
| SW82436659-236335197   | 1,657m  | 1,658m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 01/03/2019               | Completed Defects | 28/02/2019      | A77 NB 300M PRIOR TO ALLOWAY JCT                    |
| SW82436659-236335198   | 1,228m  | 1,229m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 01/03/2019               | Completed Defects | 28/02/2018      | A77 N/B 20M AFTER EAST LODGE                        |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>11635/05 : A79 JUNCTION MAYBOLE RD AYR TO BANKHEAD RBT</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| SW82319037-235539773   | 220m    | 221m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 08/03/2018               | Completed Defects | 08/02/2018      | A77 NB CW, 100 NTH OF MAYBOLE RD JCT AYR            |
| SW82319037-235539772   | 13m     | 23m    | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 08/03/2018               | Completed Defects | 08/02/2018      | A77 NB CW, BETWEEN ON AND OFF AT MAYBOLE RD JCT AYR |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>    |         |        |             |                       |                 |                          |                   |                 |   |

| Defect Reference   | Start m | End m  | Item Type     | Item Detail                       | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description               |
|--|---------|--------|---------------|-----------------------------------|-----------------|--------------------------|-----------------------|-----------------|------------------------------------|
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>        |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>        |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>        |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>        |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>          |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>          |         |        |               |                                   |                 |                          |                       |                 |                                    |
| SW82346930-235712668   | 1,241m  | 1,242m | CARRIAGEWAY   | Pothole VIAFIX (POTV)             | CAT 1           | 07/06/2018               | Completed Defects     | 10/05/2018      | A77 NB CW, 5M STH OF BANKFIELD RBT |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>       |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b>    |         |        |               |                                   |                 |                          |                       |                 |                                    |
| SW80-403929-235984883  | 1,269m  | 1,270m | KERB          | Damaged (DAMG)                    | CAT 1           | 04/10/2018               | Completed Defects     | 30/10/2018      | A77 NB CW, BANKFIELD RBT           |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b>    |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b>    |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b>    |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                       |                 |                                    |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |         |        |               |                                   |                 |                          |                       |                 |                                    |
| SW82332071-625   | 984m    | 984m   | TRAFFIC_SIGNS | Physical condition of post (COPT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                    |
| SW82332071-627   | 936m    | 936m   | TRAFFIC_SIGNS | Physical condition of post (COPT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                    |

| Defect Reference   | Start m | End m  | Item Type     | Item Detail                       | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                                       |
|--|---------|--------|---------------|-----------------------------------|-----------------|--------------------------|-----------------------|-----------------|--|
| SW82332071-629   | 443m    | 543m   | FILTER_DRAIN  | Weed growth (WEED)                | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-626   | 1,240m  | 1,240m | TRAFFIC_SIGNS | Physical condition of post (COPT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-628   | 288m    | 288m   | TRAFFIC_SIGNS | Physical condition of post (COPT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-630   | 547m    | 647m   | FILTER_DRAIN  | Weed growth (WEED)                | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-624   | 137m    | 137m   | TRAFFIC_SIGNS | Physical condition of post (COPT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-631   | 774m    | 874m   | FILTER_DRAIN  | Weed growth (WEED)                | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>  |         |        |               |                                   |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>  |         |        |               |                                   |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>  |         |        |               |                                   |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>  |         |        |               |                                   |                 |                          |                       |                 |  |
| SW82425931-236166522   | 794m    | 834m   | SHRUB         | Overhanging/overgrown (OVER)      | CAT 1           | 22/11/2018               | Completed Defects     | 02/11/2018      | A77 SB CW ON EITHER SIDE OF THE BEECHES JUNCTION MINISHANT |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b> |         |        |               |                                   |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b> |         |        |               |                                   |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b> |         |        |               |                                   |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b> |         |        |               |                                   |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b> |         |        |               |                                   |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b> |         |        |               |                                   |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b> |         |        |               |                                   |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b> |         |        |               |                                   |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b> |         |        |               |                                   |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>  |         |        |               |                                   |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>  |         |        |               |                                   |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>  |         |        |               |                                   |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>  |         |        |               |                                   |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>  |         |        |               |                                   |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b> |         |        |               |                                   |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b> |         |        |               |                                   |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b> |         |        |               |                                   |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b> |         |        |               |                                   |                 |                          |                       |                 |  |
| No defects recorded  |         |        |               |                                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>    |         |        |               |                                   |                 |                          |                       |                 |  |

| Defect Reference   | Start m | End m | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status               | Completion Date | Location Description           |
|--|---------|-------|-------------|-----------------------|-----------------|--------------------------|------------------------------|-----------------|--------------------------------|
| SW82441664-236344804   | 57m     | 57m   | CARRIAGEWAY | Litter Grade C (LITC) | 3RD PTY         | 08/03/2019               | Awaiting CCMS Permanent Date | 01/01/9999      | A77 N/B MAYBOLE RD TO BANKHEAD |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>              |         |       |             |                       |                 |                          |                              |                 |                                |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |                                |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>              |         |       |             |                       |                 |                          |                              |                 |                                |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |                                |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>              |         |       |             |                       |                 |                          |                              |                 |                                |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |                                |
| <b>11638/05 : BANKHEAD ROUNDABOUT</b>                                      |         |       |             |                       |                 |                          |                              |                 |                                |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 January 2018</b>  |         |       |             |                       |                 |                          |                              |                 |                                |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |                                |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 January 2018</b>  |         |       |             |                       |                 |                          |                              |                 |                                |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |                                |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 January 2018</b>  |         |       |             |                       |                 |                          |                              |                 |                                |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |                                |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 January 2018</b>  |         |       |             |                       |                 |                          |                              |                 |                                |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |                                |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 January 2018</b>  |         |       |             |                       |                 |                          |                              |                 |                                |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |                                |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 February 2018</b> |         |       |             |                       |                 |                          |                              |                 |                                |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |                                |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 February 2018</b> |         |       |             |                       |                 |                          |                              |                 |                                |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |                                |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 February 2018</b> |         |       |             |                       |                 |                          |                              |                 |                                |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |                                |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 February 2018</b> |         |       |             |                       |                 |                          |                              |                 |                                |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |                                |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 March 2018</b>    |         |       |             |                       |                 |                          |                              |                 |                                |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |                                |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 March 2018</b>    |         |       |             |                       |                 |                          |                              |                 |                                |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |                                |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 March 2018</b>    |         |       |             |                       |                 |                          |                              |                 |                                |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |                                |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 March 2018</b>    |         |       |             |                       |                 |                          |                              |                 |                                |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |                                |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 April 2018</b>    |         |       |             |                       |                 |                          |                              |                 |                                |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |                                |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 April 2018</b>    |         |       |             |                       |                 |                          |                              |                 |                                |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |                                |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 April 2018</b>    |         |       |             |                       |                 |                          |                              |                 |                                |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |                                |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 April 2018</b>    |         |       |             |                       |                 |                          |                              |                 |                                |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |                                |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 01 May 2018</b>      |         |       |             |                       |                 |                          |                              |                 |                                |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |                                |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 May 2018</b>      |         |       |             |                       |                 |                          |                              |                 |                                |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |                                |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 May 2018</b>      |         |       |             |                       |                 |                          |                              |                 |                                |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |                                |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 May 2018</b>      |         |       |             |                       |                 |                          |                              |                 |                                |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |                                |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 May 2018</b>      |         |       |             |                       |                 |                          |                              |                 |                                |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |                                |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 June 2018</b>     |         |       |             |                       |                 |                          |                              |                 |                                |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |                                |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 June 2018</b>     |         |       |             |                       |                 |                          |                              |                 |                                |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |                                |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 June 2018</b>     |         |       |             |                       |                 |                          |                              |                 |                                |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |                                |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018</b>       |         |       |             |                       |                 |                          |                              |                 |                                |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |                                |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 June 2018</b>     |         |       |             |                       |                 |                          |                              |                 |                                |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |                                |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 July 2018</b>     |         |       |             |                       |                 |                          |                              |                 |                                |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                              |                 |                                |

| Defect Reference  | Start m | End m | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|---|---------|-------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 July 2018</b>      |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 July 2018</b>      |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 July 2018</b>      |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 July 2018</b>      |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 August 2018</b>    |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 14 August 2018</b>    |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 21 August 2018</b>    |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 28 August 2018</b>    |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 September 2018</b> |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 September 2018</b> |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 September 2018</b> |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 25 September 2018</b> |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 October 2018</b>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 October 2018</b>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 October 2018</b>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 October 2018</b>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 October 2018</b>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 November 2018</b>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 November 2018</b>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018</b>    |         |       |                    |                                      |                 |                          |                       |                 |                      |
| SW82332070-1  | 20m     | 60m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-3  | 150m    | 170m  | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-5  | 176m    | 230m  | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-2  | 17m     | 117m  | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-4  | 157m    | 170m  | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 November 2018</b>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 November 2018</b>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 December 2018</b>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 December 2018</b>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 December 2018</b>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |

| Defect Reference | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|------------------|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|
|------------------|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|

**Safety Inspection of A76 & A77 Ayr North V1 on 24 December 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 31 December 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 07 January 2019**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 08 January 2019**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 15 January 2019**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 22 January 2019**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 29 January 2019**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 05 February 2019**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 12 February 2019**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 19 February 2019**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 26 February 2019**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 05 March 2019**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 12 March 2019**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 19 March 2019**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 26 March 2019**

*No defects recorded*

**11641/05 : HOLMSTON ROUNDABOUT**

**Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 27 March 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 03 April 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 10 April 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 17 April 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 24 April 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 01 May 2018**

| Defect Reference  | Start<br>m | End<br>m | Item Type   | Item Detail                                | Defect<br>Category | Required<br>Completion Date | Current Status           | Completion<br>Date | Location Description |
|---|------------|----------|-------------|--|--------------------|-----------------------------|--------------------------|--------------------|----------------------|
| <i>No defects recorded</i>  |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 May 2018</b>       |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>  |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 May 2018</b>       |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>  |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 May 2018</b>       |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>  |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 May 2018</b>       |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>  |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 June 2018</b>      |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>  |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 June 2018</b>      |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>  |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 June 2018</b>      |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>  |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 June 2018</b>      |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>  |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018</b>        |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>  |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 July 2018</b>      |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>  |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 July 2018</b>      |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>  |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 July 2018</b>      |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>  |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 July 2018</b>      |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>  |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 July 2018</b>      |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>  |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 August 2018</b>    |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>  |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 14 August 2018</b>    |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>  |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 21 August 2018</b>    |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>  |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 28 August 2018</b>    |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>  |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 September 2018</b> |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>  |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 September 2018</b> |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>  |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 September 2018</b> |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>  |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 25 September 2018</b> |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>  |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 October 2018</b>   |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>  |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 October 2018</b>   |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>  |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 October 2018</b>   |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>  |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 October 2018</b>   |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>  |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 October 2018</b>   |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>  |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 November 2018</b>  |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>  |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 November 2018</b>  |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>  |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018</b>    |            |          |             |  |                    |                             |                          |                    |                      |
| SW82332070-27   | 13m        | 33m      | CARRIAGEWAY | Bituminous<br>surfacing<br>fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                      |
| SW82332070-28   | 32m        | 37m      | CARRIAGEWAY | Localised<br>cracking<br>(LOCK)            | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                      |



| Defect Reference   | Start m | End m | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description          |
|--|---------|-------|-------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|-------------------------------|
| SW82332070-29  | 89m     | 109m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                               |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 November 2018</b> |         |       |             |                                      |                 |                          |                       |                 |                               |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |                               |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 November 2018</b> |         |       |             |                                      |                 |                          |                       |                 |                               |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |                               |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 December 2018</b> |         |       |             |                                      |                 |                          |                       |                 |                               |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |                               |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 December 2018</b> |         |       |             |                                      |                 |                          |                       |                 |                               |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |                               |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 December 2018</b> |         |       |             |                                      |                 |                          |                       |                 |                               |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |                               |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 December 2018</b> |         |       |             |                                      |                 |                          |                       |                 |                               |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |                               |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 December 2018</b> |         |       |             |                                      |                 |                          |                       |                 |                               |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |                               |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 January 2019</b>  |         |       |             |                                      |                 |                          |                       |                 |                               |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |                               |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 January 2019</b>  |         |       |             |                                      |                 |                          |                       |                 |                               |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |                               |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 January 2019</b>  |         |       |             |                                      |                 |                          |                       |                 |                               |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |                               |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 January 2019</b>  |         |       |             |                                      |                 |                          |                       |                 |                               |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |                               |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 January 2019</b>  |         |       |             |                                      |                 |                          |                       |                 |                               |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |                               |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 February 2019</b> |         |       |             |                                      |                 |                          |                       |                 |                               |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |                               |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 February 2019</b> |         |       |             |                                      |                 |                          |                       |                 |                               |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |                               |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 February 2019</b> |         |       |             |                                      |                 |                          |                       |                 |                               |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |                               |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 February 2019</b> |         |       |             |                                      |                 |                          |                       |                 |                               |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |                               |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 March 2019</b>    |         |       |             |                                      |                 |                          |                       |                 |                               |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |                               |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 March 2019</b>    |         |       |             |                                      |                 |                          |                       |                 |                               |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |                               |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 March 2019</b>    |         |       |             |                                      |                 |                          |                       |                 |                               |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |                               |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 March 2019</b>    |         |       |             |                                      |                 |                          |                       |                 |                               |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |                               |
| <b>11650/05 : DUTCH HOUSE ROUNDABOUT</b>                                   |         |       |             |                                      |                 |                          |                       |                 |                               |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 January 2018</b>  |         |       |             |                                      |                 |                          |                       |                 |                               |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |                               |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018</b>  |         |       |             |                                      |                 |                          |                       |                 |                               |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |                               |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 January 2018</b>  |         |       |             |                                      |                 |                          |                       |                 |                               |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |                               |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018</b>  |         |       |             |                                      |                 |                          |                       |                 |                               |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |                               |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 January 2018</b>  |         |       |             |                                      |                 |                          |                       |                 |                               |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |                               |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018</b>  |         |       |             |                                      |                 |                          |                       |                 |                               |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |                               |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 January 2018</b>  |         |       |             |                                      |                 |                          |                       |                 |                               |
| SW82317767-235529086   | 37m     | 40m   | CARRIAGEWAY | Pothole (POTH)                       | CAT 1           | 20/02/2018               | Completed Defects     | 24/02/2018      | A77 ON DUTCH HOUSE RBT, ON CL |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018</b>  |         |       |             |                                      |                 |                          |                       |                 |                               |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |                               |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 January 2018</b>  |         |       |             |                                      |                 |                          |                       |                 |                               |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |                               |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018</b> |         |       |             |                                      |                 |                          |                       |                 |                               |
| No defects recorded  |         |       |             |                                      |                 |                          |                       |                 |                               |

| Defect Reference   | Start<br>m | End<br>m | Item Type   | Item Detail       | Defect<br>Category | Required<br>Completion Date | Current Status       | Completion<br>Date | Location Description                |
|--|------------|----------|-------------|-------------------|--------------------|-----------------------------|----------------------|--------------------|-------------------------------------|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 February 2018</b> |            |          |             |                   |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |                                     |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018</b> |            |          |             |                   |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 February 2018</b> |            |          |             |                   |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |                                     |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018</b> |            |          |             |                   |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 February 2018</b> |            |          |             |                   |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |                                     |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018</b> |            |          |             |                   |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 February 2018</b> |            |          |             |                   |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |                                     |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018</b>    |            |          |             |                   |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 March 2018</b>    |            |          |             |                   |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |                                     |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018</b>    |            |          |             |                   |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 March 2018</b>    |            |          |             |                   |                    |                             |                      |                    |                                     |
| SW82327521-235576661   | 100m       | 101m     | CARRIAGEWAY | Pothole<br>(POTH) | CAT 1              | 10/04/2018                  | Completed<br>Defects | 14/03/2018         | A77 ON RBT, OPPOSITE NB<br>EXIT A77 |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018</b>    |            |          |             |                   |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 March 2018</b>    |            |          |             |                   |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |                                     |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018</b>    |            |          |             |                   |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 March 2018</b>    |            |          |             |                   |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |                                     |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2018</b>    |            |          |             |                   |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 April 2018</b>    |            |          |             |                   |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |                                     |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 April 2018</b>    |            |          |             |                   |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 April 2018</b>    |            |          |             |                   |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |                                     |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 April 2018</b>    |            |          |             |                   |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 April 2018</b>    |            |          |             |                   |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |                                     |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 April 2018</b>    |            |          |             |                   |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 April 2018</b>    |            |          |             |                   |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |                                     |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 April 2018</b>    |            |          |             |                   |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 01 May 2018</b>      |            |          |             |                   |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |                                     |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 May 2018</b>      |            |          |             |                   |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 May 2018</b>      |            |          |             |                   |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |                                     |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 May 2018</b>      |            |          |             |                   |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 May 2018</b>      |            |          |             |                   |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |                                     |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 May 2018</b>      |            |          |             |                   |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 May 2018</b>      |            |          |             |                   |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |                                     |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 May 2018</b>      |            |          |             |                   |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 May 2018</b>      |            |          |             |                   |                    |                             |                      |                    |                                     |

| Defect Reference  | Start<br>m | End<br>m | Item Type | Item Detail | Defect<br>Category | Required<br>Completion Date | Current Status | Completion<br>Date | Location Description |
|---|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 01 June 2018      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 05 June 2018      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 08 June 2018      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 12 June 2018      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 15 June 2018      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 19 June 2018      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 22 June 2018      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 26 June 2018      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det</b> on 20 June 2018        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 29 June 2018      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 03 July 2018      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 06 July 2018      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 10 July 2018      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 13 July 2018      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 17 July 2018      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 20 July 2018      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 24 July 2018      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 27 July 2018      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 31 July 2018      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 03 August 2018    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 07 August 2018    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 10 August 2018    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 14 August 2018    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 17 August 2018    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 21 August 2018    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 24 August 2018    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 28 August 2018    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 31 August 2018    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 04 September 2018 |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 ( Awaiting Return )  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 11 September 2018 |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 14 September 2018 |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 18 September 2018 |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |

| Defect Reference  | Start m | End m | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|---|---------|-------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 September 2018</b> |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 25 September 2018</b> |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 September 2018</b> |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 October 2018</b>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 October 2018</b>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 October 2018</b>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 October 2018</b>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 October 2018</b>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 October 2018</b>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 October 2018</b>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 October 2018</b>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 October 2018</b>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 November 2018</b>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 November 2018</b>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 November 2018</b>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 November 2018</b>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 November 2018</b>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018</b>    |         |       |                    |                                      |                 |                          |                       |                 |                      |
| SW82332070-68   | 38m     | 127m  | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-70   | 167m    | 200m  | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-72   | 88m     | 128m  | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-69   | 36m     | 96m   | CARRIAGEWAY        | Opening of longitudinal joint (OLJT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-71   | 170m    | 200m  | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-67   | 142m    | 200m  | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 November 2018</b>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 November 2018</b>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 November 2018</b>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 30 November 2018</b>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 December 2018</b>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 07 December 2018</b>  |         |       |                    |                                      |                 |                          |                       |                 |                      |

| Defect Reference | Start<br>m | End<br>m | Item Type | Item Detail | Defect<br>Category | Required<br>Completion Date | Current Status | Completion<br>Date | Location Description |
|------------------|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|
|------------------|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|

*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 11 December 2018**  
*No defects recorded*  
**Safety Patrol of A77 Ayr North Safety Patrol V1 on 14 December 2018**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 18 December 2018**  
*No defects recorded*  
**Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 December 2018**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 24 December 2018**  
*No defects recorded*  
**Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 December 2018**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 31 December 2018**  
*No defects recorded*  
**Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 January 2019**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 07 January 2019**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 08 January 2019**  
*No defects recorded*  
**Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 January 2019**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 15 January 2019**  
*No defects recorded*  
**Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 January 2019**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 22 January 2019**  
*No defects recorded*  
**Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 January 2019**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 29 January 2019**  
*No defects recorded*  
**Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 February 2019**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 05 February 2019**  
*No defects recorded*  
**Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 February 2019**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 12 February 2019**  
*No defects recorded*  
**Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 February 2019**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 19 February 2019**  
*No defects recorded*  
**Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 February 2019**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 26 February 2019**  
*No defects recorded*  
**Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 March 2019**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 05 March 2019**  
*No defects recorded*  
**Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 March 2019**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 12 March 2019**  
*No defects recorded*  
**Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 March 2019**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 19 March 2019**  
*No defects recorded*  
**Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 March 2019**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 26 March 2019**  
*No defects recorded*  
**Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2019**  
*No defects recorded*

| Defect Reference  | Start m | End m  | Item Type   | Item Detail    | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description   |
|---|---------|--------|-------------|----------------|-----------------|--------------------------|-------------------|-----------------|--|
| <b>11650/08 : WITH: DUTCH HOUSE ROUNDABOUT TO SYMINGTON NB</b>  |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 January 2018</b>                                 |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018</b>                                 |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 January 2018</b>                                 |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Hansel Village CATA Footways on 09 January 2018</b>  |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018</b>                                 |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 January 2018</b>                                 |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018</b>                                 |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 January 2018</b>                                 |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018</b>                                 |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 January 2018</b>                                 |         |        |             |                |                 |                          |                   |                 |  |
| SW82318102-235532001  | 288m    | 290m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 27/02/2018               | Completed Defects | 14/02/2018      | A77 NB CW, 300M NTH OF DUTCHHOUSE RBT                                    |
| SW82318102-235531999  | 184m    | 284m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 27/02/2018               | Completed Defects | 14/02/2018      | A77 NB CW, LANE 1, 200M NTH OF DUTCHHOUSE RBT                            |
| SW82318102-235532000  | 242m    | 245m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 27/02/2018               | Completed Defects | 14/02/2018      | A77 NB CW, LANE 1 250M NTH OF DUTCHHOUSE RBT                             |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018</b>                                |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 February 2018</b>                                |         |        |             |                |                 |                          |                   |                 |  |
| SW82318894-235534932  | 1,760m  | 1,780m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 06/03/2018               | Completed Defects | 07/02/2018      | A77 NB CW, LANE 1, 200M STH OF HANSEL VILLAGE                            |
| SW82318894-235534931  | 1,499m  | 1,500m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 06/03/2018               | Completed Defects | 07/02/2018      | A77 NB CW, LANE 1, 400M STH OF HANSEL VILLAGE                            |
| <b>Detailed Inspections - Category A Footways of A77 Hansel Village CATA Footways on 06 February 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018</b>                                |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 February 2018</b>                                |         |        |             |                |                 |                          |                   |                 |  |
| SW82319390-235542963  | 98m     | 99m    | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 13/03/2018               | Completed Defects | 14/02/2018      | A77 NB CW, LANE 1, 100M NTH DUTCH HOUSE RBT, TO 300M                     |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018</b>                                |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 February 2018</b>                                |         |        |             |                |                 |                          |                   |                 |  |
| SW82321390-235546235  | 1,751m  | 1,752m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 20/03/2018               | Completed Defects | 21/02/2018      | A77N/B LANE1 AT FARM JCT SOUTH OF HANSEL VILAGE                          |
| SW82321390-235546234  | 1,491m  | 1,493m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 20/03/2018               | Completed Defects | 20/02/2018      | A77 N/B LANE 1 NORH OF AVERAGE SPEED CAMERAS SOUTH OF HANSEL             |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018</b>                                |         |        |             |                |                 |                          |                   |                 |  |
| SW82322248-235548888  | 1,495m  | 1,496m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 23/03/2018               | Completed Defects | 23/02/2018      | A77 N/B LANE 1 30M NORTH OF AVERAGE SPEED CAMERA SOUTH OF HANSEL VILLAGE |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 February 2018</b>                                |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018</b>                                   |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 March 2018</b>                                   |         |        |             |                |                 |                          |                   |                 |  |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail    | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description  |
|--|---------|--------|-------------|----------------|-----------------|--------------------------|-------------------|-----------------|---|
| SW82325502-235553025   | 1,708m  | 1,709m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 03/04/2018               | Completed Defects | 07/03/2018      | A77 NB CW, LANE 1, 250M STH OF HANSEL VILLAGE                     |
| SW82325502-235553022   | 253m    | 254m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 03/04/2018               | Completed Defects | 06/03/2018      | A77 NB CW, LANE 1, 253M NTH OF DUTCH HOUSE RBT                    |
| SW82325502-235553021   | 198m    | 199m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 03/04/2018               | Completed Defects | 06/03/2018      | A77 NB CW LANE 1, 190M NTH OF DUTCH HOUSE RBT                     |
| SW82325502-235553023   | 304m    | 305m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 03/04/2018               | Completed Defects | 06/03/2018      | A77 NB CW, LANE 1 280M NTH OF DUTCHHOUSE RBT                      |
| SW82325502-235553024   | 339m    | 340m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 03/04/2018               | Completed Defects | 06/03/2018      | A77 NB CW, LANE 1, 290M NTH OF DUTCH HOUSE RBT                    |
| <b>Detailed Inspections - Category A Footways of A77 Hansel Village CATA Footways on 06 March 2018</b> |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018</b>                                |         |        |             |                |                 |                          |                   |                 |   |
| SW82326369-235553165   | 1,803m  | 1,804m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 06/04/2018               | Completed Defects | 09/03/2018      | A77 NB CW, LANE 1, AT WEXFORD FARM, 400M STH OF HANSEL VILLAGE OB |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 March 2018</b>                                |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018</b>                                |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 March 2018</b>                                |         |        |             |                |                 |                          |                   |                 |   |
| SW82329522-235601241   | 2,697m  | 2,699m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 17/04/2018               | Completed Defects | 21/03/2018      | A77 NB CW, AT SYMINGTON JCT                                       |
| SW82329522-235601240   | 201m    | 202m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 17/04/2018               | Completed Defects | 21/03/2018      | A77 NB CW, ON CL, 200M NTH OF DUTCH HOUSE RBT                     |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018</b>                                |         |        |             |                |                 |                          |                   |                 |   |
| SW82330424-235608130   | 1,484m  | 1,485m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 20/04/2018               | Completed Defects | 23/03/2018      | A77 NB CW, LANE 1, 200M STH OF HANSEL OB                          |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 March 2018</b>                                |         |        |             |                |                 |                          |                   |                 |   |
| SW82331491-235609013   | 1,744m  | 1,745m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 24/04/2018               | Completed Defects | 27/03/2018      | A77 NB CW, LANE 1, AT FARM JCT 200M STH OF HANSEL                 |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2018</b>                                |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Detailed Inspections - Category A Footways of A77 Hansel Village CATA Footways on 03 April 2018</b> |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 April 2018</b>                                |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 April 2018</b>                                |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 April 2018</b>                                |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 April 2018</b>                                |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 April 2018</b>                                |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 April 2018</b>                                |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 April 2018</b>                                |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 April 2018</b>                                |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Detailed Inspections - Category A Footways of A77 Hansel Village CATA Footways on 01 May 2018</b>   |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 01 May 2018</b>                                  |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 May 2018</b>                                  |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 May 2018</b>                                  |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |

| Defect Reference  | Start m | End m  | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                               |
|---|---------|--------|-------------|--------------------------------------|-----------------|--------------------------|-------------------|-----------------|--|
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 May 2018</b><br><i>No defects recorded</i>                                 |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 May 2018</b>   |         |        |             |                                      |                 |                          |                   |                 |  |
| SW82348955-235802361  | 1,486m  | 1,487m | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 16/05/2018               | Completed Defects | 15/05/2018      | A77 NB LANE 1 500M SOUTH OF HANSEL VILLAGE         |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 May 2018</b>   |         |        |             |                                      |                 |                          |                   |                 |  |
| SW82350359-235785069  | 200m    | 201m   | CARRIAGEWAY | Opening of longitudinal joint (OLJT) | CAT 1           | 15/06/2018               | Completed Defects | 18/05/2018      | A77 NB LANE 1 200M NORTH OF DUTCH HOUSE ROUNDABOUT |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 May 2018</b><br><i>No defects recorded</i>                                 |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 May 2018</b><br><i>No defects recorded</i>                                 |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 May 2018</b>   |         |        |             |                                      |                 |                          |                   |                 |  |
| SW82355166-235815739  | 2,194m  | 1m     | GULLY       | Other (OTHR)                         | CAT 1           | 26/06/2018               | Completed Defects | 29/05/2018      | A77 NB CW 400M PRIOR TO SYMINGTON JCT              |
| <b>Detailed Inspections - Category A Footways of A77 Hansel Village CATA Footways on 01 June 2018</b><br><i>No defects recorded</i> |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 June 2018</b><br><i>No defects recorded</i>                                |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 June 2018</b><br><i>No defects recorded</i>                                |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 June 2018</b><br><i>No defects recorded</i>                                |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 June 2018</b><br><i>No defects recorded</i>                                |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 June 2018</b><br><i>No defects recorded</i>                                |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 June 2018</b><br><i>No defects recorded</i>                                |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 June 2018</b><br><i>No defects recorded</i>                                |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Hansel Village CATA Footways on 26 June 2018</b>                               |         |        |             |                                      |                 |                          |                   |                 |  |
| SW82368225-4  | 1,535m  | 1,536m | FOOTWAY     | Overgrown by vegetation (OVGV)       | CAT 1           | 24/07/2018               | Completed Defects | 26/06/2018      | A77 NB CW 800M PRIOR TO HANSEL VILLAGE FOOTBRIDGE  |
| SW82368225-6  | 1,837m  | 1,937m | FOOTWAY     | Overgrown by vegetation (OVGV)       | CAT 1           | 24/07/2018               | Completed Defects | 26/06/2018      | A77 NB CW 200M PRIOR TO HANSEL VILLAGE FOOTBRIDGE  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 June 2018</b><br><i>No defects recorded</i>                                |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018</b><br><i>No defects recorded</i>                                  |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 June 2018</b>  |         |        |             |                                      |                 |                          |                   |                 |  |
| SW80-370953-235874271   | 2,637m  | 2,638m | TREE        | Overhanging/overgrown (OVER)         | CAT 1           | 27/07/2018               | Completed Defects | 29/06/2018      | A77 NB CW 200M PRIOR TO SYMINGTON JCT              |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 July 2018</b><br><i>No defects recorded</i>                                |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 July 2018</b><br><i>No defects recorded</i>                                |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 July 2018</b><br><i>No defects recorded</i>                                |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 July 2018</b><br><i>No defects recorded</i>                                |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 July 2018</b><br><i>No defects recorded</i>                                |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 July 2018</b><br><i>No defects recorded</i>                                |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Hansel Village CATA Footways on 24 July 2018</b><br><i>No defects recorded</i> |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 July 2018</b><br><i>No defects recorded</i>                                |         |        |             |                                      |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 July 2018</b><br><i>No defects recorded</i>                                |         |        |             |                                      |                 |                          |                   |                 |  |



| Defect Reference   | Start m | End m  | Item Type      | Item Detail                    | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                             |
|--|---------|--------|----------------|--------------------------------|-----------------|--------------------------|-------------------|-----------------|--|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 July 2018</b>                                     |         |        |                |                                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                |                                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 03 August 2018</b>                                   |         |        |                |                                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                |                                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 August 2018</b>                                   |         |        |                |                                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                |                                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 10 August 2018</b>                                   |         |        |                |                                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                |                                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 14 August 2018</b>                                   |         |        |                |                                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                |                                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 17 August 2018</b>                                   |         |        |                |                                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                |                                |                 |                          |                   |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Hansel Village CATA Footways on 21 August 2018</b>    |         |        |                |                                |                 |                          |                   |                 |  |
| SW80-394975-2  | 817m    | 917m   | CYCLE_FACILITY | Overgrown by vegetation (OVGV) | CAT 1           | 22/08/2018               | Completed Defects | 21/08/2018      | A77 N/B ON FOOTWAY800M NORTH OF DUTCHHOUSE RBT   |
| SW80-394975-3  | 1,258m  | 1,358m | CYCLE_FACILITY | Overgrown by vegetation (OVGV) | CAT 1           | 22/08/2018               | Completed Defects | 21/08/2018      | A77 NB FOOTWAY 1250M NORTH OF DUTCHHOUSE RBT     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 21 August 2018</b>                                   |         |        |                |                                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                |                                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 24 August 2018</b>                                   |         |        |                |                                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                |                                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 28 August 2018</b>                                   |         |        |                |                                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                |                                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 31 August 2018</b>                                   |         |        |                |                                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                |                                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 September 2018</b>                                |         |        |                |                                |                 |                          |                   |                 |  |
| SW80-402975-236036447  | 299m    | 299m   | GULLY          | Cracked or broken (BCK)        | CAT 1           | 02/10/2018               | Completed Defects | 26/09/2018      | A77 N/B 300M NORTH OF DUTCHHOUSE ROUNDABOUT      |
| SW80-402975-236036448  | 1,498m  | 1,499m | CARRIAGEWAY    | Pothole VIAFIX (POTV)          | CAT 1           | 05/09/2018               | Completed Defects | 04/09/2018      | A77 N/B LANE 1 500M OF HANSEL VILLAGE            |
| SW80-402975-236036449  | 1,511m  | 1,512m | CARRIAGEWAY    | Pothole VIAFIX (POTV)          | CAT 1           | 05/09/2018               | Completed Defects | 04/09/2018      | A77 N/B LANE 1 490M SOUTH OF HANSEL VILLAGE      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 ( Awaiting Return )</b>                                 |         |        |                |                                |                 |                          |                   |                 |  |
| SW80-404397-236051810  | 205m    | 206m   | REMOVE_ANIMAL  | Carcass of dead animal (DEAD)  | CAT 1           | 05/10/2018               | Completed Defects | 07/09/2018      | A77N/B 200M NORTH OF DUTCHHOUSE RBT              |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 September 2018</b>                                |         |        |                |                                |                 |                          |                   |                 |  |
| SW82406268-236054637   | 2,090m  | 2,090m | GULLY          | Other (OTHR)                   | CAT 1           | 12/09/2018               | Completed Defects | 11/09/2018      | A77 N/B OPPOSITE JCT HANSEL VILLAGE              |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 14 September 2018</b>                                |         |        |                |                                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                |                                |                 |                          |                   |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Hansel Village CATA Footways on 18 September 2018</b> |         |        |                |                                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                |                                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 September 2018</b>                                |         |        |                |                                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                |                                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 September 2018</b>                                |         |        |                |                                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                |                                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 25 September 2018</b>                                |         |        |                |                                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                |                                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 September 2018</b>                                |         |        |                |                                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                |                                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 October 2018</b>                                  |         |        |                |                                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                |                                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 October 2018</b>                                  |         |        |                |                                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                |                                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 October 2018</b>                                  |         |        |                |                                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                |                                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 October 2018</b>                                  |         |        |                |                                |                 |                          |                   |                 |  |
| SW82420711-236112150   | 817m    | 818m   | GULLY          | Other (OTHR)                   | CAT 1           | 13/10/2018               | Completed Defects | 12/10/2018      | A77 NB CW 10M AFTER BUSSTOP ACROSS FROM ROWALLAN |

| Defect Reference  | Start<br>m | End<br>m | Item Type     | Item Detail                                  | Defect<br>Category | Required<br>Completion Date | Current Status        | Completion<br>Date | Location Description                                 |
|---|------------|----------|---------------|--|--------------------|-----------------------------|-----------------------|--------------------|--|
| <b>Detailed Inspections - Category A Footways of A77 Hansel Village CATA Footways on 16 October 2018</b>  |            |          |               |  |                    |                             |                       |                    |  |
| <i>No defects recorded</i>  |            |          |               |  |                    |                             |                       |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 October 2018</b>                                 |            |          |               |  |                    |                             |                       |                    |  |
| <i>No defects recorded</i>  |            |          |               |  |                    |                             |                       |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 October 2018</b>                                 |            |          |               |  |                    |                             |                       |                    |  |
| <i>No defects recorded</i>  |            |          |               |  |                    |                             |                       |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 October 2018</b>                                 |            |          |               |  |                    |                             |                       |                    |  |
| <i>No defects recorded</i>  |            |          |               |  |                    |                             |                       |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 October 2018</b>                                 |            |          |               |  |                    |                             |                       |                    |  |
| <i>No defects recorded</i>  |            |          |               |  |                    |                             |                       |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 October 2018</b>                                 |            |          |               |  |                    |                             |                       |                    |  |
| SW82426035-236177507  | 277m       | 278m     | TRAFFIC_SIGNS | Pointing wrong way (RWAY)                    | CAT 1              | 31/10/2018                  | Completed Defects     | 30/10/2018         | A77 200M FROM DUTCHHOUSE RBT ON CENTRAL RESERVATIOM  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 November 2018</b>                                |            |          |               |  |                    |                             |                       |                    |  |
| <i>No defects recorded</i>  |            |          |               |  |                    |                             |                       |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 November 2018</b>                                |            |          |               |  |                    |                             |                       |                    |  |
| <i>No defects recorded</i>  |            |          |               |  |                    |                             |                       |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 November 2018</b>                                |            |          |               |  |                    |                             |                       |                    |  |
| SW82426454-236187213  | 1,501m     | 1,502m   | CARRIAGEWAY   | Pothole VIAFIX (POTV)                        | CAT 1              | 10/11/2018                  | Completed Defects     | 09/11/2018         | A77 NB CW OPPOSITE HANSEL VILLAGE                    |
| <b>Detailed Inspections - Category A Footways of A77 Hansel Village CATA Footways on 09 November 2018</b> |            |          |               |  |                    |                             |                       |                    |  |
| <i>No defects recorded</i>  |            |          |               |  |                    |                             |                       |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 November 2018</b>                                |            |          |               |  |                    |                             |                       |                    |  |
| <i>No defects recorded</i>  |            |          |               |  |                    |                             |                       |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 November 2018</b>                                |            |          |               |  |                    |                             |                       |                    |  |
| <i>No defects recorded</i>  |            |          |               |  |                    |                             |                       |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 November 2018</b>                                |            |          |               |  |                    |                             |                       |                    |  |
| <i>No defects recorded</i>  |            |          |               |  |                    |                             |                       |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 November 2018</b>                                |            |          |               |  |                    |                             |                       |                    |  |
| <i>No defects recorded</i>  |            |          |               |  |                    |                             |                       |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 November 2018</b>                                |            |          |               |  |                    |                             |                       |                    |  |
| SW82426853-236234055  | 2,155m     | 2,156m   | CARRIAGEWAY   | Pothole (POTH)                               | CAT 1              | 25/12/2018                  | Completed Defects     | 28/11/2018         | A77 SB CW OUTSIDE LANE AT ENTRANCE TO HANSEL VILLAGE |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 30 November 2018</b>                                |            |          |               |  |                    |                             |                       |                    |  |
| <i>No defects recorded</i>  |            |          |               |  |                    |                             |                       |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 December 2018</b>                                |            |          |               |  |                    |                             |                       |                    |  |
| <i>No defects recorded</i>  |            |          |               |  |                    |                             |                       |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 07 December 2018</b>                                |            |          |               |  |                    |                             |                       |                    |  |
| <i>No defects recorded</i>  |            |          |               |  |                    |                             |                       |                    |  |
| <b>Detailed Inspections - Category A Footways of A77 Hansel Village CATA Footways on 11 December 2018</b> |            |          |               |  |                    |                             |                       |                    |  |
| <i>No defects recorded</i>  |            |          |               |  |                    |                             |                       |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 December 2018</b>                                |            |          |               |  |                    |                             |                       |                    |  |
| <i>No defects recorded</i>  |            |          |               |  |                    |                             |                       |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 14 December 2018</b>                                |            |          |               |  |                    |                             |                       |                    |  |
| <i>No defects recorded</i>  |            |          |               |  |                    |                             |                       |                    |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018</b>                                  |            |          |               |  |                    |                             |                       |                    |  |
| SW82332070-92   | 1,861m     | 1,951m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)         | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |  |
| SW82332070-80   | 1,393m     | 1,395m   | FOOTWAY       | Bituminous surfacing - local cracking (BLCK) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |  |
| SW82332070-88   | 1,716m     | 1,726m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)         | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |  |
| SW82332070-78   | 1,034m     | 1,035m   | CARRIAGEWAY   | Single crack (CRCK)                          | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |  |
| SW82332070-96   | 2,055m     | 2,155m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)         | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |  |

| Defect Reference | Start m | End m  | Item Type   | Item Detail                                  | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|--------|-------------|--|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82332070-97    | 2,153m  | 2,253m | CARRIAGEWAY | Opening of longitudinal joint (OLJT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-82    | 1,486m  | 1,496m | CARRIAGEWAY | Localised cracking (LOCK)                    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-93    | 1,935m  | 1,945m | CARRIAGEWAY | Opening of longitudinal joint (OLJT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-100   | 2,372m  | 2,382m | FOOTWAY     | Bituminous surfacing - local cracking (BLCK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-76    | 287m    | 297m   | CARRIAGEWAY | Surfacing joints (SRJT)                      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-83    | 1,498m  | 1,499m | CARRIAGEWAY | Pothole (POTH)                               | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-89    | 1,750m  | 1,760m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-102   | 2,493m  | 2,593m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-94    | 1,957m  | 2,057m | FOOTWAY     | Overgrown by vegetation (OVGV)               | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-95    | 2,030m  | 2,031m | CARRIAGEWAY | Pothole (POTH)                               | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-91    | 1,842m  | 1,742m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-98    | 2,206m  | 2,256m | FOOTWAY     | Bituminous surfacing fretting (BFRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |

**Safety Inspection of A76 & A77 Ayr North V1 on 18 December 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 December 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 24 December 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 December 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 31 December 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 January 2019**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 07 January 2019**

No defects recorded

**Detailed Inspections - Category A Footways of A77 Hansel Village CATA Footways on 08 January 2019**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 08 January 2019**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 January 2019**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 15 January 2019**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 January 2019**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 22 January 2019**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 January 2019**

| Defect Reference  | Start m | End m  | Item Type   | Item Detail                                      | Defect Category | Required Completion Date | Current Status          | Completion Date | Location Description                                    |
|---|---------|--------|-------------|--|-----------------|--------------------------|-------------------------|-----------------|---|
| SW82428408-236287020  | 251m    | 252m   | CARRIAGEWAY | Pothole (POTH)                                   | CAT 1           | 22/02/2019               | Completed Defects       | 26/01/2019      | A77 N/B LANE 1 250M NORTH OF DUTCHHOUSE RBT             |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 January 2019</b>                                 |         |        |             |  |                 |                          |                         |                 |   |
| SW82428594-236291665  | 1,486m  | 1,487m | CARRIAGEWAY | Pothole (POTH)                                   | CAT 1           | 26/02/2019               | Completed Defects       | 30/01/2019      | A77 NB CW 490M SOUTH OF HANSEL OVERBRIDGE               |
| SW82428594-236291666  | 1,484m  | 1,485m | CARRIAGEWAY | Pothole (POTH)                                   | CAT 1           | 26/02/2019               | Completed Defects       | 30/01/2019      | A77 NB CW 550M SOUTH OF HANSEL OVERBRIDGE               |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 February 2019</b>                                |         |        |             |  |                 |                          |                         |                 |   |
| No defects recorded   |         |        |             |  |                 |                          |                         |                 |   |
| <b>Detailed Inspections - Category A Footways of A77 Hansel Village CATA Footways on 04 February 2019</b> |         |        |             |  |                 |                          |                         |                 |   |
| No defects recorded   |         |        |             |  |                 |                          |                         |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 February 2019</b>                                |         |        |             |  |                 |                          |                         |                 |   |
| No defects recorded   |         |        |             |  |                 |                          |                         |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 February 2019</b>                                |         |        |             |  |                 |                          |                         |                 |   |
| No defects recorded   |         |        |             |  |                 |                          |                         |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 February 2019</b>                                |         |        |             |  |                 |                          |                         |                 |   |
| No defects recorded   |         |        |             |  |                 |                          |                         |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 February 2019</b>                                |         |        |             |  |                 |                          |                         |                 |   |
| No defects recorded   |         |        |             |  |                 |                          |                         |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 February 2019</b>                                |         |        |             |  |                 |                          |                         |                 |   |
| No defects recorded   |         |        |             |  |                 |                          |                         |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 February 2019</b>                                |         |        |             |  |                 |                          |                         |                 |   |
| No defects recorded   |         |        |             |  |                 |                          |                         |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 February 2019</b>                                |         |        |             |  |                 |                          |                         |                 |   |
| No defects recorded   |         |        |             |  |                 |                          |                         |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 March 2019</b>                                   |         |        |             |  |                 |                          |                         |                 |   |
| No defects recorded   |         |        |             |  |                 |                          |                         |                 |   |
| <b>Detailed Inspections - Category A Footways of A77 Hansel Village CATA Footways on 05 March 2019</b>    |         |        |             |  |                 |                          |                         |                 |   |
| SW82437829-2  | 750m    | 750m   | FOOTWAY     | Bituminous surfacing fretting (BFRT)             | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action   | 01/01/9999      |   |
| SW82437829-8  | 1,501m  | 1,501m | FOOTWAY     | Bituminous surfacing - extensive cracking (BECK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action   | 01/01/9999      |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 March 2019</b>                                   |         |        |             |  |                 |                          |                         |                 |   |
| No defects recorded   |         |        |             |  |                 |                          |                         |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 March 2019</b>                                   |         |        |             |  |                 |                          |                         |                 |   |
| SW82442472-236336833  | 1,453m  | 1,453m | CARRIAGEWAY | Excessive muck (MUCK)                            | 3RD PTY         | 05/04/2019               | Awaiting CCMS Temp Date | 01/01/9999      | A77 N/B DUTCH HOUSE TO HANSEL VILLAGE @ LAMP POST 5213  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 March 2019</b>                                   |         |        |             |  |                 |                          |                         |                 |   |
| No defects recorded   |         |        |             |  |                 |                          |                         |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 March 2019</b>                                   |         |        |             |  |                 |                          |                         |                 |   |
| No defects recorded   |         |        |             |  |                 |                          |                         |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 March 2019</b>                                   |         |        |             |  |                 |                          |                         |                 |   |
| No defects recorded   |         |        |             |  |                 |                          |                         |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 March 2019</b>                                   |         |        |             |  |                 |                          |                         |                 |   |
| No defects recorded   |         |        |             |  |                 |                          |                         |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 March 2019</b>                                   |         |        |             |  |                 |                          |                         |                 |   |
| No defects recorded   |         |        |             |  |                 |                          |                         |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2019</b>                                   |         |        |             |  |                 |                          |                         |                 |   |
| No defects recorded   |         |        |             |  |                 |                          |                         |                 |   |
| <b>11650/40 : WITH: SYMINGTON NB TO EAST LODGE</b>  |         |        |             |  |                 |                          |                         |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 January 2018</b>                                 |         |        |             |  |                 |                          |                         |                 |   |
| No defects recorded   |         |        |             |  |                 |                          |                         |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018</b>                                 |         |        |             |  |                 |                          |                         |                 |   |
| SW82317357-235513857  | 238m    | 239m   | CARRIAGEWAY | Pothole (POTH)                                   | CAT 1           | 02/02/2018               | Completed Defects       | 31/01/2018      | A7 N/B ON CENTRE LINE 50M NORTH OF SYMINGTON OVERBRIDGE |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail                                | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description  |
|--|---------|--------|-------------|--|-----------------|--------------------------|-------------------|-----------------|---|
| SW82317357-235513858   | 290m    | 291m   | CARRIAGEWAY | Pothole (POTH)                             | CAT 1           | 02/02/2018               | Completed Defects | 13/01/2018      | A77 N/B LANE 1 10M NORTH OF END OF ONSLIP FROM SYMINGTON                      |
| SW82317357-235513860   | 464m    | 466m   | CARRIAGEWAY | Pothole (POTH)                             | CAT 1           | 02/02/2018               | Completed Defects | 31/01/2018      | A77 N/B LANE 1 AND LANE2 60M NORTH OF COTAGES NORTH OF ON SLIP FROM SYMINGTON |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 January 2018</b>  |         |        |             |  |                 |                          |                   |                 |   |
| SW82317440-235515650   | 1,343m  | 1,345m | CARRIAGEWAY | Pothole (POTH)                             | CAT 1           | 06/02/2018               | Completed Defects | 31/01/2018      | A77 NB CW, LANE 1, 350M NTH OF HALFWAY HOUSE, NTH OF SYMINGTON                |
| SW82317440-235515662   | 720m    | 721m   | CARRIAGEWAY | Pothole (POTH)                             | CAT 1           | 06/02/2018               | Completed Defects | 31/01/2018      | A77 NB CW, LANE 2, OUTSIDE HALFWAY HOUSE                                      |
| SW82317440-235515649   | 1,196m  | 1,197m | CARRIAGEWAY | Pothole (POTH)                             | CAT 1           | 10/01/2018               | Completed Defects | 31/01/2018      | A77 NB CW LANE 1, 150M NTH OF HALFWAY HOUSE NTH OF SYMINGTON                  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018</b>  |         |        |             |  |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |  |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 January 2018</b>  |         |        |             |  |                 |                          |                   |                 |   |
| SW82317632-235520465   | 1,008m  | 1,018m | CARRIAGEWAY | Patch - loss of material (fretting) (PLMT) | CAT 1           | 13/02/2018               | Completed Defects | 31/01/2018      | LANE 2 AT THE SLIP ROAD TO OLD HALFWAY HOUSE BETWEEN SYMINGTON AND BOGENDTOLL |
| SW82317632-235520466   | 1,629m  | 1,649m | CARRIAGEWAY | Pothole (POTH)                             | CAT 1           | 13/02/2018               | Completed Defects | 09/02/2018      | LANE 1 AT ADS PRIOR TO BOGEND NB OPPOSITE WHITELEES COTTAGES                  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018</b>  |         |        |             |  |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |  |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 January 2018</b>  |         |        |             |  |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |  |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018</b>  |         |        |             |  |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |  |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 January 2018</b>  |         |        |             |  |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |  |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018</b> |         |        |             |  |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |  |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 February 2018</b> |         |        |             |  |                 |                          |                   |                 |   |
| SW82318894-235534934   | 740m    | 760m   | CARRIAGEWAY | Pothole (POTH)                             | CAT 1           | 06/03/2018               | Completed Defects | 07/02/2018      | A77 NB CW, 600M NTH OF SYMINGTON ONSLIP                                       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018</b> |         |        |             |  |                 |                          |                   |                 |   |
| SW82319109-235534717   | 417m    | 418m   | CARRIAGEWAY | Pothole (POTH)                             | CAT 1           | 09/03/2018               | Completed Defects | 09/02/2018      | A77 NB CW, LANE 1, 410M NTH OF SYMINGTON NB ONSLIP                            |
| SW82319109-235534719   | 712m    | 722m   | CARRIAGEWAY | Pothole (POTH)                             | CAT 1           | 09/03/2018               | Completed Defects | 09/02/2018      | A77 NB CW, ON CL, 720M NTH OF SYMINGTON NB ONSLIP                             |
| SW82319109-235534721   | 1,737m  | 1,757m | CARRIAGEWAY | Pothole (POTH)                             | CAT 1           | 09/03/2018               | Completed Defects | 09/02/2018      | A77 NB CW, 150M STH OF BOGEND TOLL TO BOGEND TOLL                             |
| SW82319109-235534718   | 661m    | 665m   | CARRIAGEWAY | Pothole (POTH)                             | CAT 1           | 09/03/2018               | Completed Defects | 09/02/2018      | A77 NB CW, 660M NTH OF SYMINGTON NB ONSLIP                                    |
| SW82319109-235534720   | 1,071m  | 1,073m | CARRIAGEWAY | Pothole (POTH)                             | CAT 1           | 09/03/2018               | Completed Defects | 09/02/2018      | A77 NB CW, LANE 2, OPPOSITE HALFWAY HOUSE NTH OF SYMINGTON OB                 |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 February 2018</b> |         |        |             |  |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |  |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018</b> |         |        |             |  |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |  |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 February 2018</b> |         |        |             |  |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |  |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018</b> |         |        |             |  |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |  |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 February 2018</b> |         |        |             |  |                 |                          |                   |                 |   |

| Defect Reference  | Start m | End m  | Item Type   | Item Detail    | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description   |
|---|---------|--------|-------------|----------------|-----------------|--------------------------|-------------------|-----------------|--|
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 March 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| SW82326369-235553172  | 904m    | 905m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 06/04/2018               | Completed Defects | 10/03/2018      | A77 NB CW, ON CL, 200M STH OF HALFWAY HOUSE                          |
| SW82326369-235553176  | 1,652m  | 1,653m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 06/04/2018               | Completed Defects | 10/03/2018      | A77 NB CW, ON CL, OPPOSITE SPICE ROUTE                               |
| SW82326369-235553171  | 850m    | 851m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 06/04/2018               | Completed Defects | 10/03/2018      | A77 NB CW, ON CL, 250M STH OF HALFWAY HOUSE                          |
| SW82326369-235553173  | 942m    | 943m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 06/04/2018               | Completed Defects | 10/03/2018      | A77 NB CW, 150M STH OF HALFWAY HOUSE                                 |
| SW82326369-235553175  | 1,636m  | 1,637m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 06/04/2018               | Completed Defects | 10/03/2018      | A77 NB CW, LANE 1, OPPOSITE SPICE ROUTE                              |
| SW82326369-235553174  | 998m    | 999m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 06/04/2018               | Completed Defects | 10/03/2018      | A77 NB CW, ON CL, 100M STH OF HALFWAY HOUSE                          |
| SW82326369-235553177  | 1,656m  | 1,657m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 06/04/2018               | Completed Defects | 10/03/2018      | A77 NB CW, ON CL, OPPOSITE SPICE ROUTE                               |
| SW82326369-235553170  | 800m    | 801m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 06/04/2018               | Completed Defects | 10/03/2018      | A77 NB CW, ON CL, 300M STH OF HALFWAY HOUSE                          |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 March 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| SW82328364-235586133  | 678m    | 679m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 13/04/2018               | Completed Defects | 16/03/2018      | A77 NB CW LANE 2, 450M STH OF HALFWAY HOUSE                          |
| SW82328364-235586130  | 489m    | 490m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 13/04/2018               | Completed Defects | 16/03/2018      | A77 NB CW, 600M STH OF HALFWAY HOUSE ON CL                           |
| SW82328364-235586131  | 552m    | 553m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 13/04/2018               | Completed Defects | 16/03/2018      | A77 NB CW ON CL, 550M STH OF HALFWAY HOUSE                           |
| SW82328364-235586132  | 613m    | 614m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 13/04/2018               | Completed Defects | 16/03/2018      | A77 NB CW LANE 1, 500M STH OF HALFWAY HOUSE                          |
| SW82328364-235586134  | 752m    | 753m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 13/04/2018               | Completed Defects | 16/03/2018      | A77 NB CW, ON CL, 400M STH OF HALFWAY HOUSE                          |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 March 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| SW82330424-235608131  | 293m    | 296m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 20/04/2018               | Completed Defects | 23/03/2018      | A77 NB CW, ON CL, MULTIPLE HOLES, SYMINGTON NB ONSLIP FOR 300M       |
| SW82330424-235608132  | 2,483m  | 2,485m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 20/04/2018               | Completed Defects | 24/03/2018      | A77 NB CW, ON CL, AT NB END OF 50MPH SPEED RESTRICTION, FOR 150M NTH |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 March 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| SW82331491-235609016  | 1,994m  | 1,995m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 24/04/2018               | Completed Defects | 27/03/2018      | A77 SB CW LANE 2, OPPOSITE BOGEND TOLL ONSLIP                        |
| SW82331491-235609014  | 863m    | 864m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 24/04/2018               | Completed Defects | 27/03/2018      | A77 NB CW, 100M NTH OF SYMINGTON                                     |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 April 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 April 2018</b> |         |        |             |                |                 |                          |                   |                 |  |

| Defect Reference  | Start m | End m  | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                                     |
|---|---------|--------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|--|
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 April 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 April 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 April 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 April 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| SW82339168-235634094  | 789m    | 789m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 21/04/2018               | Completed Defects | 20/04/2018      | M77 N/B SYMINGTON TO EAST LODGE @ LAMP POST GG5710       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 April 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 April 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 01 May 2018</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 May 2018</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 May 2018</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 May 2018</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 May 2018</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 May 2018</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 May 2018</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| SW82352134-235806270  | 2,266m  | 2,267m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 19/06/2018               | Completed Defects | 23/05/2018      | A77 NORTH 400M SOUTH OF EAST LODGE NB CL                 |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 May 2018</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 May 2018</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| SW82355166-235815741  | 2,574m  | 2,575m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 26/06/2018               | Completed Defects | 30/05/2018      | A77 NB CW CL 300M SOUTH EAST LODGE                       |
| SW82355166-235815740  | 927m    | 928m   | GULLY       | Other (OTHR)          | CAT 1           | 26/06/2018               | Completed Defects | 29/05/2018      | A77 NB CW 100M SOUTH OF HALFWAYHOUSE                     |
| SW82355166-235815742  | 2,609m  | 2,610m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 26/06/2018               | Completed Defects | 30/05/2018      | A77 NB CW 250M SOUTH OF EAST LODGE                       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 June 2018</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 June 2018</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 June 2018</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 June 2018</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 June 2018</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| SW80-364233-235859306   | 2,606m  | 2,607m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 13/07/2018               | Completed Defects | 15/06/2018      | A77 NB CW CL 100M PAST NATIONAL SPEED SIGN AT EAST LODGE |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 June 2018</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 June 2018</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 June 2018</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018</b>    |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 June 2018</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 July 2018</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |

| Defect Reference  | Start m | End m  | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                                       |
|---|---------|--------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|--|
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 July 2018</b>      |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 July 2018</b>      |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 July 2018</b>      |         |        |             |                       |                 |                          |                   |                 |  |
| SW82377861-235874033  | 1,193m  | 1,194m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 10/08/2018               | Completed Defects | 13/07/2018      | A77 SB CW, LANE 2, AT BUS STOP STH OF SPICE ROUTE          |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 July 2018</b>      |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 July 2018</b>      |         |        |             |                       |                 |                          |                   |                 |  |
| SW82381111-235914465  | 1,307m  | 1,308m | GULLY       | Other (OTHR)          | CAT 1           | 17/08/2018               | Completed Defects | 20/07/2018      | A77 NB CW 50M PRIOR TO SPICE HUT                           |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 July 2018</b>      |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 July 2018</b>      |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 July 2018</b>      |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 03 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 10 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 14 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 17 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 21 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 24 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 28 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 31 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 September 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| SW80-402975-236036450   | 1,982m  | 1,983m | GULLY       | Other (OTHR)          | CAT 1           | 05/09/2018               | Completed Defects | 04/09/2018      | A77 N/B BOGEND TOLL N/B OFFSLIP                            |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 ( Awaiting Return )</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| SW80-404397-236051811   | 1,789m  | 1,790m | GULLY       | Other (OTHR)          | CAT 1           | 08/09/2018               | Completed Defects | 07/09/2018      | A77 N/B LANE 200 PRIOR TO BOGEND TOLL                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 September 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 14 September 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| SW82407615-236055838  | 978m    | 979m   | GULLY       | Other (OTHR)          | CAT 1           | 15/09/2018               | Completed Defects | 14/09/2018      | A77 N/B LANE 1 OPPOSITE HELENGATE FARM SOUTH OF BOGENDTOLL |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 September 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 September 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 25 September 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 September 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 October 2018</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 October 2018</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 October 2018</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 October 2018</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |



| Defect Reference  | Start m | End m  | Item Type     | Item Detail                                  | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description              |
|---|---------|--------|---------------|--|-----------------|--------------------------|-----------------------|-----------------|-----------------------------------|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 October 2018</b><br>SW82422516-236143037 | 2,540m  | 2,541m | GULLY         | Other (OTHR)                                 | CAT 1           | 17/10/2018               | Completed Defects     | 16/10/2018      | A77 N/B 300M NORTH OF BOGEND TOLL |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 October 2018</b><br>No defects recorded  |         |        |               |  |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 October 2018</b><br>No defects recorded  |         |        |               |  |                 |                          |                       |                 |                                   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 October 2018</b><br>No defects recorded  |         |        |               |  |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 October 2018</b><br>SW82426035-236177498 | 1,270m  | 1,271m | GULLY         | Other (OTHR)                                 | CAT 1           | 31/10/2018               | Completed Defects     | 30/10/2018      | A77 NB CW 500M FROM BOGEND TOLL   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 November 2018</b><br>No defects recorded |         |        |               |  |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 November 2018</b><br>No defects recorded |         |        |               |  |                 |                          |                       |                 |                                   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 November 2018</b><br>No defects recorded |         |        |               |  |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 November 2018</b><br>No defects recorded |         |        |               |  |                 |                          |                       |                 |                                   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 November 2018</b><br>No defects recorded |         |        |               |  |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 November 2018</b><br>No defects recorded |         |        |               |  |                 |                          |                       |                 |                                   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 November 2018</b><br>No defects recorded |         |        |               |  |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 November 2018</b><br>No defects recorded |         |        |               |  |                 |                          |                       |                 |                                   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 30 November 2018</b><br>No defects recorded |         |        |               |  |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 December 2018</b><br>No defects recorded |         |        |               |  |                 |                          |                       |                 |                                   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 07 December 2018</b><br>No defects recorded |         |        |               |  |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 December 2018</b><br>No defects recorded |         |        |               |  |                 |                          |                       |                 |                                   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 14 December 2018</b><br>No defects recorded |         |        |               |  |                 |                          |                       |                 |                                   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018</b><br>SW82332070-228        | 2,750m  | 2,751m | VERGE         | Overhanging/overgrown (OVER)                 | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                   |
| SW82332070-233  | 2,857m  | 2,859m | CARRIAGEWAY   | Localised cracking (LOCK)                    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                   |
| SW82332070-224  | 2,713m  | 2,743m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                   |
| SW82332070-104  | 1,149m  | 1,150m | FOOTWAY       | Bituminous surfacing - local cracking (BLCK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                   |
| SW82332070-216  | 2,565m  | 2,585m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                   |
| SW82332070-218  | 2,601m  | 2,621m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                   |
| SW82332070-236  | 2,881m  | 2,882m | TRAFFIC_SIGNS | Dirty sign (DIRT)                            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                   |
| SW82332070-110  | 2,324m  | 2,424m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                   |

| Defect Reference | Start m | End m  | Item Type     | Item Detail                                  | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|--------|---------------|--|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82332070-234   | 2,857m  | 2,858m | FOOTWAY       | Other (OTHR)                                 | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-210   | 2,500m  | 2,505m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-209   | 2,491m  | 2,495m | CARRIAGEWAY   | Patch - loss of material (fretting) (PLMT)   | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-235   | 2,881m  | 2,882m | CARRIAGEWAY   | Pothole (POTH)                               | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-237   | 2,889m  | 2,890m | CARRIAGEWAY   | Pothole (POTH)                               | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-103   | 488m    | 588m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-109   | 2,216m  | 2,219m | CARRIAGEWAY   | Pothole (POTH)                               | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-217   | 2,600m  | 2,601m | TRAFFIC_SIGNS | Dirty sign (DIRT)                            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-219   | 2,619m  | 2,620m | ROAD_STUDS    | Missing reflector (MISR)                     | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-107   | 2,009m  | 2,019m | FOOTWAY       | Bituminous surfacing - local cracking (BLCK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |

**Safety Inspection of A76 & A77 Ayr North V1 on 18 December 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 December 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 24 December 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 December 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 31 December 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 January 2019**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 07 January 2019**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 08 January 2019**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 January 2019**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 15 January 2019**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 January 2019**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 22 January 2019**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 January 2019**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 29 January 2019**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 February 2019**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 05 February 2019**

|                      |        |        |             |                          |       |            |                   |            |  |
|----------------------|--------|--------|-------------|--------------------------|-------|------------|-------------------|------------|--|
| SW82429329-236310600 | 2,630m | 2,631m | CARRIAGEWAY | Detritus / Refuse (DETR) | CAT 1 | 05/03/2019 | Completed Defects | 06/02/2019 | A77 OUTSIDE EAST LODGE, NTH OF BOGEND TOLL |
|----------------------|--------|--------|-------------|--------------------------|-------|------------|-------------------|------------|--|

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 February 2019**

| Defect Reference   | Start m | End m  | Item Type   | Item Detail    | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                                      |
|--|---------|--------|-------------|----------------|-----------------|--------------------------|-------------------|-----------------|---|
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 February 2019</b> |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 February 2019</b> |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 February 2019</b> |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 February 2019</b> |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 February 2019</b> |         |        |             |                |                 |                          |                   |                 |   |
| SW82435554-236335866   | 2,455m  | 2,456m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 27/02/2019               | Completed Defects | 26/02/2019      | A77 N/B 25M PRIOR TO SPEED LIMIT SIGN BOGEND TOLL         |
| SW82435554-236335869   | 2,873m  | 2,875m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 27/02/2019               | Completed Defects | 26/02/2019      | A77 N/B 600M PRIOR TO SPITAL HILL OFF SLIP AT WHITE HOUSE |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 March 2019</b>    |         |        |             |                |                 |                          |                   |                 |   |
| SW82437261-236336833   | 539m    | 539m   | GULLY       | Other (OTHR)   | CAT 1           | 02/03/2019               | Completed Defects | 01/03/2019      | A77 400M NORTH OF SYMINGTON                               |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 March 2019</b>    |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 March 2019</b>    |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 March 2019</b>    |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 March 2019</b>    |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 March 2019</b>    |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 March 2019</b>    |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 March 2019</b>    |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2019</b>    |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>11650/80 : WITH: EAST LODGE TO SPITTALHILL SLIP ROAD</b>                |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 January 2018</b>  |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018</b>  |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 January 2018</b>  |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018</b>  |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 January 2018</b>  |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018</b>  |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 January 2018</b>  |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018</b>  |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 January 2018</b>  |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018</b> |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 February 2018</b> |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018</b> |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 February 2018</b> |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018</b> |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |   |

| Defect Reference   | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|--|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 February 2018</b><br><i>No defects recorded</i> |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018</b><br><i>No defects recorded</i> |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 February 2018</b><br><i>No defects recorded</i> |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018</b><br><i>No defects recorded</i>    |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 March 2018</b><br><i>No defects recorded</i>    |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018</b><br><i>No defects recorded</i>    |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 March 2018</b><br><i>No defects recorded</i>    |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018</b><br><i>No defects recorded</i>    |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 March 2018</b><br><i>No defects recorded</i>    |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018</b><br><i>No defects recorded</i>    |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 March 2018</b><br><i>No defects recorded</i>    |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2018</b><br><i>No defects recorded</i>    |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 April 2018</b><br><i>No defects recorded</i>    |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 April 2018</b><br><i>No defects recorded</i>    |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 April 2018</b><br><i>No defects recorded</i>    |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 April 2018</b><br><i>No defects recorded</i>    |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 April 2018</b><br><i>No defects recorded</i>    |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 April 2018</b><br><i>No defects recorded</i>    |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 April 2018</b><br><i>No defects recorded</i>    |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 April 2018</b><br><i>No defects recorded</i>    |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 01 May 2018</b><br><i>No defects recorded</i>      |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 May 2018</b><br><i>No defects recorded</i>      |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 May 2018</b><br><i>No defects recorded</i>      |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 May 2018</b><br><i>No defects recorded</i>      |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 May 2018</b><br><i>No defects recorded</i>      |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 May 2018</b><br><i>No defects recorded</i>      |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 May 2018</b><br><i>No defects recorded</i>      |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 May 2018</b><br><i>No defects recorded</i>      |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 May 2018</b><br><i>No defects recorded</i>      |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 June 2018</b><br><i>No defects recorded</i>     |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 June 2018</b><br><i>No defects recorded</i>     |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 June 2018</b><br><i>No defects recorded</i>     |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 June 2018</b><br><i>No defects recorded</i>     |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 June 2018</b><br><i>No defects recorded</i>     |         |       |           |             |                 |                          |                |                 |                      |

| Defect Reference  | Start<br>m | End<br>m | Item Type | Item Detail | Defect<br>Category | Required<br>Completion Date | Current Status | Completion<br>Date | Location Description |
|---|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 June 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 June 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 June 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 June 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 July 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 July 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 July 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 July 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 July 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 July 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 July 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 July 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 July 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 03 August 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 August 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 10 August 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 14 August 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 17 August 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 21 August 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 24 August 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 28 August 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 31 August 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 September 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 September 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 14 September 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 September 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 September 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 25 September 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 September 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 October 2018</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 October 2018</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 October 2018</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |

| Defect Reference   | Start<br>m | End<br>m | Item Type   | Item Detail                                | Defect<br>Category | Required<br>Completion Date | Current Status           | Completion<br>Date | Location Description |
|--|------------|----------|-------------|--|--------------------|-----------------------------|--------------------------|--------------------|----------------------|
| <b>Safety Patrol of A77 Ayr North</b>                                    |            |          |             | Safety Patrol V1 on 12 October 2018        |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b>                   |            |          |             | on 16 October 2018                         |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                                    |            |          |             | Safety Patrol V1 on 19 October 2018        |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b>                   |            |          |             | on 23 October 2018                         |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                                    |            |          |             | Safety Patrol V1 on 26 October 2018        |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b>                   |            |          |             | on 30 October 2018                         |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                                    |            |          |             | Safety Patrol V1 on 02 November 2018       |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b>                   |            |          |             | on 06 November 2018                        |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                                    |            |          |             | Safety Patrol V1 on 09 November 2018       |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b>                   |            |          |             | on 13 November 2018                        |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                                    |            |          |             | Safety Patrol V1 on 16 November 2018       |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b>                   |            |          |             | on 20 November 2018                        |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                                    |            |          |             | Safety Patrol V1 on 23 November 2018       |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b>                   |            |          |             | on 27 November 2018                        |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                                    |            |          |             | Safety Patrol V1 on 30 November 2018       |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b>                   |            |          |             | on 04 December 2018                        |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                                    |            |          |             | Safety Patrol V1 on 07 December 2018       |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b>                   |            |          |             | on 11 December 2018                        |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                                    |            |          |             | Safety Patrol V1 on 14 December 2018       |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b>                   |            |          |             | on 18 December 2018                        |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                                    |            |          |             | Safety Patrol V1 on 21 December 2018       |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b>                   |            |          |             | on 24 December 2018                        |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                                    |            |          |             | Safety Patrol V1 on 28 December 2018       |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b>                   |            |          |             | on 31 December 2018                        |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                                    |            |          |             | Safety Patrol V1 on 04 January 2019        |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b>                   |            |          |             | on 07 January 2019                         |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b>                   |            |          |             | on 08 January 2019                         |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                                    |            |          |             | Safety Patrol V1 on 11 January 2019        |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018</b> |            |          |             |  |                    |                             |                          |                    |                      |
| SW82332070-241   | 42m        | 43m      | CARRIAGEWAY | Pothole<br>(POTH)                          | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                      |
| SW82332070-250   | 284m       | 285m     | CATCHPIT    | Other (OTHR)                               | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                      |
| SW82332070-252   | 426m       | 436m     | CARRIAGEWAY | Bituminous<br>surfacing<br>fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                      |

| Defect Reference   | Start m | End m | Item Type     | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                             |
|--|---------|-------|---------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|--|
| SW82332070-239   | 28m     | 29m   | CARRIAGEWAY   | Pothole (POTH)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-254   | 521m    | 523m  | CARRIAGEWAY   | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-256   | 631m    | 632m  | CARRIAGEWAY   | Pothole (POTH)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-245   | 118m    | 119m  | CARRIAGEWAY   | Pothole (POTH)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-246   | 150m    | 200m  | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-242   | 60m     | 61m   | CARRIAGEWAY   | Pothole (POTH)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-249   | 254m    | 264m  | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-238   | 18m     | 19m   | CARRIAGEWAY   | Pothole (POTH)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-253   | 509m    | 609m  | FILTER_DRAIN  | Weed growth (WEED)                   | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-255   | 542m    | 543m  | CARRIAGEWAY   | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-247   | 206m    | 306m  | FILTER_DRAIN  | Weed growth (WEED)                   | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-248   | 240m    | 241m  | TRAFFIC_SIGNS | Dirty sign (DIRT)                    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-240   | 40m     | 41m   | CARRIAGEWAY   | Pothole (POTH)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-244   | 110m    | 111m  | TREE          | Overhanging/overgrown (OVER)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-251   | 344m    | 364m  | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 January 2019</b>  |         |       |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 January 2019</b>  |         |       |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 January 2019</b>  |         |       |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 January 2019</b>  |         |       |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 January 2019</b>  |         |       |               |                                      |                 |                          |                       |                 |  |
| SW82428594-236291668   | 14m     | 15m   | CARRIAGEWAY   | Pothole (POTH)                       | CAT 1           | 26/02/2019               | Completed Defects     | 31/01/2019      | A77 NB SC AT EAST LODGE JCT SOUTH OF SPITTALHILL |
| SW82428594-236291670   | 14m     | 15m   | CARRIAGEWAY   | Pothole (POTH)                       | CAT 1           | 26/02/2019               | Completed Defects     | 31/01/2019      | A77 NB CW CENTRE LINE OUTSIDE EAST LODGE JCT     |
| SW82428594-236291669   | 19m     | 20m   | CARRIAGEWAY   | Pothole (POTH)                       | CAT 1           | 26/02/2019               | Completed Defects     | 31/01/2019      | A77 NB CW ON CENTRE LINE OUTSIDE EAST LODGE JCT  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 February 2019</b> |         |       |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 February 2019</b> |         |       |               |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |       |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 February 2019</b> |         |       |               |                                      |                 |                          |                       |                 |  |

| Defect Reference   | Start m | End m | Item Type   | Item Detail    | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                      |
|--|---------|-------|-------------|----------------|-----------------|--------------------------|-------------------|-----------------|---|
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 February 2019</b> |         |       |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 February 2019</b> |         |       |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 February 2019</b> |         |       |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 February 2019</b> |         |       |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 February 2019</b> |         |       |             |                |                 |                          |                   |                 |   |
| SW82435554-236335871   | 4m      | 6m    | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 27/02/2019               | Completed Defects | 26/02/2019      | A77 N/B 580M PRIOR TO SPITALHILL OFF SLIP |
| SW82435554-236335872   | 4m      | 6m    | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 27/02/2019               | Completed Defects | 26/02/2019      | A77 N/B 570M PRIOR TO SPITALHILL OFF SLIP |
| SW82435554-236335875   | 50m     | 52m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 27/02/2019               | Completed Defects | 26/02/2019      | A77 N/B 480M PRIOR TO SPITALHILL OFF SLIP |
| SW82435554-236335874   | 44m     | 46m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 27/02/2019               | Completed Defects | 26/02/2019      | A77 N/B 500M PRIOR TO SPITALHILL OFF SLIP |
| SW82435554-236335870   | 3m      | 5m    | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 27/02/2019               | Completed Defects | 26/02/2019      | A77 N/B 590M PRIOR TO SPITALHILL OFF SLIP |
| SW82435554-236335873   | 18m     | 20m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 27/02/2019               | Completed Defects | 26/02/2019      | A77N/B 560M PRIOR TO SPITALHILL OFF SLIP  |

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 March 2019**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 05 March 2019**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 March 2019**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 12 March 2019**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 March 2019**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 19 March 2019**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 March 2019**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 26 March 2019**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2019**

*No defects recorded*

**11650/90 : WITH: SPITALHILL SLIP RD TO EAST AYRSHIRE BOUNDARY**

**Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018**



| Defect Reference   | Start<br>m | End<br>m | Item Type | Item Detail  | Defect<br>Category | Required<br>Completion Date | Current Status       | Completion<br>Date | Location Description                       |
|--|------------|----------|-----------|--------------|--------------------|-----------------------------|----------------------|--------------------|--|
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 February 2018</b> |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018</b> |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 February 2018</b> |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018</b> |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 February 2018</b> |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018</b> |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 February 2018</b> |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018</b>    |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 March 2018</b>    |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018</b>    |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 March 2018</b>    |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018</b>    |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 March 2018</b>    |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018</b>    |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 March 2018</b>    |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2018</b>    |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 April 2018</b>    |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 April 2018</b>    |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 April 2018</b>    |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 April 2018</b>    |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 April 2018</b>    |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 April 2018</b>    |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 April 2018</b>    |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 April 2018</b>    |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 01 May 2018</b>      |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 May 2018</b>      |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 May 2018</b>      |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 May 2018</b>      |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 May 2018</b>      |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| SW82350359-235785071   | 531m       | 532m     | GULLY     | Other (OTHR) | CAT 1              | 19/05/2018                  | Completed<br>Defects | 18/05/2018         | A77 NB AT END OF<br>SPITTLEHILL ROUNDABOUT |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 May 2018</b>      |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 May 2018</b>      |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |

| Defect Reference  | Start<br>m              | End<br>m                 | Item Type     | Item Detail             | Defect<br>Category | Required<br>Completion Date | Current Status           | Completion<br>Date | Location Description                   |
|---|-------------------------|--------------------------|---------------|-------------------------|--------------------|-----------------------------|--------------------------|--------------------|--|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 May 2018</b>       |                         |                          |               |                         |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |                         |                          |               |                         |                    |                             |                          |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 June 2018</b>      |                         |                          |               |                         |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |                         |                          |               |                         |                    |                             |                          |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 June 2018</b>      |                         |                          |               |                         |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |                         |                          |               |                         |                    |                             |                          |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 June 2018</b>      |                         |                          |               |                         |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |                         |                          |               |                         |                    |                             |                          |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 June 2018</b>      |                         |                          |               |                         |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |                         |                          |               |                         |                    |                             |                          |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 June 2018</b>      |                         |                          |               |                         |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |                         |                          |               |                         |                    |                             |                          |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 June 2018</b>      |                         |                          |               |                         |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |                         |                          |               |                         |                    |                             |                          |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 June 2018</b>      |                         |                          |               |                         |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |                         |                          |               |                         |                    |                             |                          |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 June 2018</b>      |                         |                          |               |                         |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |                         |                          |               |                         |                    |                             |                          |                    |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018</b>        |                         |                          |               |                         |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |                         |                          |               |                         |                    |                             |                          |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 June 2018</b>      |                         |                          |               |                         |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |                         |                          |               |                         |                    |                             |                          |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 July 2018</b>      |                         |                          |               |                         |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |                         |                          |               |                         |                    |                             |                          |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 July 2018</b>      |                         |                          |               |                         |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |                         |                          |               |                         |                    |                             |                          |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 July 2018</b>      |                         |                          |               |                         |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |                         |                          |               |                         |                    |                             |                          |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 July 2018</b>      |                         |                          |               |                         |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |                         |                          |               |                         |                    |                             |                          |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 July 2018</b>      |                         |                          |               |                         |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |                         |                          |               |                         |                    |                             |                          |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 July 2018</b>      |                         |                          |               |                         |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |                         |                          |               |                         |                    |                             |                          |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 July 2018</b>      |                         |                          |               |                         |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |                         |                          |               |                         |                    |                             |                          |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 July 2018</b>      |                         |                          |               |                         |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |                         |                          |               |                         |                    |                             |                          |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 July 2018</b>      |                         |                          |               |                         |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |                         |                          |               |                         |                    |                             |                          |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 03 August 2018</b>    |                         |                          |               |                         |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |                         |                          |               |                         |                    |                             |                          |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 August 2018</b>    |                         |                          |               |                         |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |                         |                          |               |                         |                    |                             |                          |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 10 August 2018</b>    |                         |                          |               |                         |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |                         |                          |               |                         |                    |                             |                          |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 14 August 2018</b>    |                         |                          |               |                         |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |                         |                          |               |                         |                    |                             |                          |                    |  |
| <b>Safety Patrol of A77 Ayr North</b>                                       | <b>Safety Patrol V1</b> | <b>on 17 August 2018</b> |               |                         |                    |                             |                          |                    |  |
| SW80-394500-235964832   | 720m                    | 720m                     | TRAFFIC_SIGNS | Obscured sign<br>(OBSG) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         | A77 N/B VERGE NORTH OF<br>INCHGOTTRICK |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 21 August 2018</b>    |                         |                          |               |                         |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |                         |                          |               |                         |                    |                             |                          |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 24 August 2018</b>    |                         |                          |               |                         |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |                         |                          |               |                         |                    |                             |                          |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 28 August 2018</b>    |                         |                          |               |                         |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |                         |                          |               |                         |                    |                             |                          |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 31 August 2018</b>    |                         |                          |               |                         |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |                         |                          |               |                         |                    |                             |                          |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 September 2018</b> |                         |                          |               |                         |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |                         |                          |               |                         |                    |                             |                          |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 ( Awaiting Return )</b>  |                         |                          |               |                         |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |                         |                          |               |                         |                    |                             |                          |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 September 2018</b> |                         |                          |               |                         |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |                         |                          |               |                         |                    |                             |                          |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 14 September 2018</b> |                         |                          |               |                         |                    |                             |                          |                    |  |

| Defect Reference  | Start<br>m | End<br>m | Item Type | Item Detail | Defect<br>Category | Required<br>Completion Date | Current Status | Completion<br>Date | Location Description |
|---|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 September 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 September 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 25 September 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 September 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 October 2018</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 October 2018</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 October 2018</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 October 2018</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 October 2018</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 October 2018</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 October 2018</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 October 2018</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 October 2018</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 November 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 November 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 November 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 November 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 November 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 November 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 November 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 November 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 30 November 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 December 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 07 December 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 December 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 14 December 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 December 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 December 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 December 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 December 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 December 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 January 2019</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 January 2019</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |

| Defect Reference | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|------------------|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|
|------------------|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|

**Safety Inspection of A76 & A77 Ayr North V1 on 08 January 2019**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 January 2019**

*No defects recorded*

**Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018**

|                |      |      |             |                                      |       |            |                       |            |  |
|----------------|------|------|-------------|--------------------------------------|-------|------------|-----------------------|------------|--|
| SW82332070-445 | 130m | 130m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 |  |
|----------------|------|------|-------------|--------------------------------------|-------|------------|-----------------------|------------|--|

|                |      |      |                    |                                   |       |            |                       |            |  |
|----------------|------|------|--------------------|-----------------------------------|-------|------------|-----------------------|------------|--|
| SW82332070-439 | 382m | 482m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 |  |
|----------------|------|------|--------------------|-----------------------------------|-------|------------|-----------------------|------------|--|

**Safety Inspection of A76 & A77 Ayr North V1 on 15 January 2019**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 January 2019**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 22 January 2019**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 January 2019**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 29 January 2019**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 February 2019**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 05 February 2019**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 February 2019**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 12 February 2019**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 February 2019**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 19 February 2019**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 February 2019**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 26 February 2019**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 March 2019**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 05 March 2019**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 March 2019**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 12 March 2019**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 March 2019**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 19 March 2019**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 March 2019**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 26 March 2019**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2019**

*No defects recorded*

**11653/04 : WITH: EAST AYRSHIRE BDY TO 300M N OF WHATRIGGS BR**

**Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018**

*No defects recorded*

| Defect Reference   | Start m | End m  | Item Type   | Item Detail    | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description   |
|--|---------|--------|-------------|----------------|-----------------|--------------------------|-------------------|-----------------|--|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 January 2018</b>  |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018</b>  |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 January 2018</b>  |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018</b>  |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 January 2018</b>  |         |        |             |                |                 |                          |                   |                 |  |
| SW82318102-235531997   | 2,273m  | 2,473m | CARRIAGEWAY | Pothole (POTH) | CAT 2           | 01/01/9999               | Completed Defects | 10/09/2018      | A77 NB CW, TREESWOOD OB  |
| SW82318102-235531998   | 2,440m  | 2,640m | CARRIAGEWAY | Pothole (POTH) | CAT 2           | 01/01/9999               | Completed Defects | 10/09/2018      | A77 NB CW, NTH OF TREESWOOD OB   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| SW82318553-235533635   | 2,778m  | 2,780m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 02/03/2018               | Completed Defects | 16/02/2018      | A77 NB CW, ON CL, AT END OF LAYBY STH OF WHATRIGGS OB                    |
| SW82318553-235533634   | 2,733m  | 2,735m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 02/03/2018               | Completed Defects | 16/02/2018      | A77 NB CW, ON CL, 50M PRIOR TO LAYBY STH OF BELLFIELD                    |
| SW82318553-235533631   | 3,007m  | 3,010m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 02/03/2018               | Completed Defects | 16/02/2018      | A77 ON CL, MULTIPLE POTHOLES, 300M STH OF WHATRIGGS OB, STH OF BELLFIELD |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 February 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| SW82319109-235534722   | 2,179m  | 2,181m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 09/03/2018               | Completed Defects | 16/02/2018      | A77 NB CL, 200M NTH OF TREESWOOD OB                                      |
| SW82319109-235534729   | 1,912m  | 1,915m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 09/03/2018               | Completed Defects | 21/02/2018      | A77 NB CW, LANE 2, 300M STH OF TREESWOOD OB                              |
| SW82319109-235534725   | 2,805m  | 2,807m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 09/03/2018               | Completed Defects | 16/02/2018      | A77 NB CW, LANE 1, OPPOSITE LAST LAYBY PRIOR TO WHATRIGGS OB             |
| SW82319109-235534726   | 2,860m  | 2,870m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 09/03/2018               | Completed Defects | 16/02/2018      | A77 NB CW, 100M STH OF WHATRIGGS OB                                      |
| SW82319109-235534724   | 2,584m  | 2,588m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 09/03/2018               | Completed Defects | 16/02/2018      | A77 NB CW, 300M STH OF LAYBY PRIOR TO WHATRIGGS OB                       |
| SW82319109-235534723   | 2,546m  | 2,548m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 09/03/2018               | Completed Defects | 16/02/2018      | A77 NB CL, 400M NTH OF TREESWOOD OB                                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 February 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 February 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| SW82321390-235546236   | 2,966m  | 2,970m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 20/03/2018               | Completed Defects | 22/02/2018      | A7 N/B ON CENTRE LINE AT NORTH BOUND END OF LAYBY BEFORE BELLFIELD       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 February 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018</b>    |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 March 2018</b>    |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018</b>    |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 March 2018</b>    |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |

| Defect Reference  | Start m | End m  | Item Type     | Item Detail                   | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description  |
|---|---------|--------|---------------|-------------------------------|-----------------|--------------------------|-------------------|-----------------|---|
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018</b> |         |        |               |                               |                 |                          |                   |                 |   |
| SW82328364-235586136  | 3,023m  | 3,024m | CARRIAGEWAY   | Pothole (POTH)                | CAT 1           | 13/04/2018               | Completed Defects | 16/03/2018      | A77 NB CW, ON CL, AT END OF LAYBY STH OF WHATRIGGS            |
| SW82328364-235586135  | 2,544m  | 2,545m | CARRIAGEWAY   | Pothole (POTH)                | CAT 1           | 13/04/2018               | Completed Defects | 16/03/2018      | A77 NB CW, LANE 2, 200M STH OF NB LAYBY STH WHATRIGGS OB      |
| SW82328364-235586137  | 3,102m  | 3,103m | CARRIAGEWAY   | Pothole (POTH)                | CAT 1           | 13/04/2018               | Completed Defects | 16/03/2018      | A77 NB CW, ON CL, 200M STH OF WHATRIGGS OB                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 March 2018</b> |         |        |               |                               |                 |                          |                   |                 |   |
| No defects recorded   |         |        |               |                               |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018</b> |         |        |               |                               |                 |                          |                   |                 |   |
| SW82330424-235608134  | 3,117m  | 3,118m | CARRIAGEWAY   | Pothole (POTH)                | CAT 1           | 20/04/2018               | Completed Defects | 24/03/2018      | A77 NB CW, ON CL, 300M STH OF WHATRIGGS OB                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 March 2018</b> |         |        |               |                               |                 |                          |                   |                 |   |
| No defects recorded   |         |        |               |                               |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2018</b> |         |        |               |                               |                 |                          |                   |                 |   |
| No defects recorded   |         |        |               |                               |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 April 2018</b> |         |        |               |                               |                 |                          |                   |                 |   |
| SW82334242-235618389  | 3,328m  | 3,428m | CARRIAGEWAY   | Other (OTHR)                  | CAT 1           | 01/05/2018               | Completed Defects | 25/04/2018      | A77 N/B ON CENTRE LINE FROM TRESWOOD HEAD OVERBRIDGE TO LAYBY |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 April 2018</b> |         |        |               |                               |                 |                          |                   |                 |   |
| SW82335189-235618850  | 1,649m  | 0m     | CARRIAGEWAY   | Pothole VIAFIX (POTV)         | CAT 1           | 07/04/2018               | Completed Defects | 06/04/2018      | A77 N/B NORTH OF CRAIGY OVERBRIDGE                            |
| SW82335189-235618851  | 2,086m  | 0m     | CARRIAGEWAY   | Pothole (POTH)                | CAT 1           | 04/05/2018               | Completed Defects | 24/04/2018      | A77 N/B 100M PRIOR TO TREESWOOD OVERBRIDGE                    |
| SW82335189-235618852  | 2,226m  | 0m     | CARRIAGEWAY   | Pothole (POTH)                | CAT 1           | 04/05/2018               | Completed Defects | 25/04/2018      | A77 N/B AT START OF TREESWOOD BRIDGE                          |
| SW82335189-235618855  | 2,362m  | 0m     | CARRIAGEWAY   | Pothole (POTH)                | CAT 1           | 04/05/2018               | Completed Defects | 25/04/2018      | A77 N/B 100M AFTER TREESWOOD BRIDGE                           |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 April 2018</b> |         |        |               |                               |                 |                          |                   |                 |   |
| No defects recorded   |         |        |               |                               |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 April 2018</b> |         |        |               |                               |                 |                          |                   |                 |   |
| No defects recorded   |         |        |               |                               |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 April 2018</b> |         |        |               |                               |                 |                          |                   |                 |   |
| No defects recorded   |         |        |               |                               |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 April 2018</b> |         |        |               |                               |                 |                          |                   |                 |   |
| No defects recorded   |         |        |               |                               |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 April 2018</b> |         |        |               |                               |                 |                          |                   |                 |   |
| No defects recorded   |         |        |               |                               |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 April 2018</b> |         |        |               |                               |                 |                          |                   |                 |   |
| No defects recorded   |         |        |               |                               |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 01 May 2018</b>   |         |        |               |                               |                 |                          |                   |                 |   |
| No defects recorded   |         |        |               |                               |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 May 2018</b>   |         |        |               |                               |                 |                          |                   |                 |   |
| No defects recorded   |         |        |               |                               |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 May 2018</b>   |         |        |               |                               |                 |                          |                   |                 |   |
| No defects recorded   |         |        |               |                               |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 May 2018</b>   |         |        |               |                               |                 |                          |                   |                 |   |
| SW82347347-235785070  | 3,519m  | 3,520m | REMOVE_ANIMAL | Carcass of dead animal (DEAD) | CAT 1           | 08/06/2018               | Completed Defects | 11/05/2018      | A77 NB CW, LANE 1, 200M STH OF BELLFIELD NB OFFSLIP           |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 May 2018</b>   |         |        |               |                               |                 |                          |                   |                 |   |
| No defects recorded   |         |        |               |                               |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 May 2018</b>   |         |        |               |                               |                 |                          |                   |                 |   |
| No defects recorded   |         |        |               |                               |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 May 2018</b>   |         |        |               |                               |                 |                          |                   |                 |   |
| No defects recorded   |         |        |               |                               |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 May 2018</b>   |         |        |               |                               |                 |                          |                   |                 |   |
| No defects recorded   |         |        |               |                               |                 |                          |                   |                 |   |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                                  |
|--|---------|--------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|---|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 May 2018</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 June 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 June 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 June 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 June 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 June 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 June 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| SW82366110-235861181   | 3,117m  | 3,118m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 17/07/2018               | Completed Defects | 11/07/2018      | A77 NB CW CL APROX 200M SOUTH OF TRESWOOD             |
| SW82366110-235861183   | 3,131m  | 3,132m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 17/07/2018               | Completed Defects | 11/07/2018      | A77 NB CW CL 185 M SOUTH OF TRESWOOD                  |
| SW82366110-235861184   | 3,137m  | 3,138m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 17/07/2018               | Completed Defects | 11/07/2018      | A77 NB CW CL 180M SOUH OF TRESWOOD                    |
| SW82366110-235861185   | 3,142m  | 3,143m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 17/07/2018               | Completed Defects | 11/07/2018      | A77 NB CW CL 175M SOUTH OF TRESWOOD                   |
| SW82366110-235861182   | 3,126m  | 2,127m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 17/07/2018               | Completed Defects | 11/07/2018      | A77 NB CW EDGELINE APROX 190M SOUTH OF TRESWOOD       |
| SW82366110-235861189   | 3,194m  | 3,195m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 17/07/2018               | Completed Defects | 17/07/2018      | A77 NB CW CL 80M SOUTH OF TRESWOOD                    |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 June 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 June 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018</b>   |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 June 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| SW80-370953-235874268  | 2,112m  | 2,113m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 27/07/2018               | Completed Defects | 30/06/2018      | A77 NB CW 200M PRIOR TO TRESWOOD OVERBRIDGE           |
| SW80-370953-235874267  | 2,058m  | 2,059m | CARRIAGEWAY | Pothole (POTH)        | CAT 2           | 01/01/9999               | Completed Defects | 10/09/2018      | A77 NB CW 300M PRIOR TO TRESWOOD OVERBRIDGE           |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 July 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| SW82373024-235892349   | 2,583m  | 2,584m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 31/07/2018               | Completed Defects | 04/07/2018      | A77 NB CW 290M PRIOR TO LAYBY AT WHATRIGGS OVERBRIDGE |
| SW82373024-235892347   | 2,574m  | 2,575m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 31/07/2018               | Completed Defects | 04/07/2018      | A77 NB CW 300M PRIOR TO LAYBY AT WHATRIGGS OVERBRIDGE |
| SW82373024-235892348   | 2,576m  | 2,577m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 31/07/2018               | Completed Defects | 04/07/2018      | A77 NB CW 295M PRIOR TO LAYBY AT WHATRIGGS OVERBRIDGE |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 July 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 July 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 July 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 July 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 July 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 July 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 July 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |

| Defect Reference  | Start m | End m  | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description  |
|---|---------|--------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|---|
| SW82384352-235917902  | 3,418m  | 3,468m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 24/08/2018               | Completed Defects | 22/08/2018      | A77 NB CW CL 150M PRIOR TO BELLFIELD INTERCHANGE                                |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 July 2018</b>      |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 03 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| SW80-387712-235930167   | 2,770m  | 2,771m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 31/08/2018               | Completed Defects | 04/08/2018      | A77 NB CW 20M PRIOR TO TREESWOOD LAYBY  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 10 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 14 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| SW80-393014-235952309   | 1,968m  | 1,969m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 11/09/2018               | Completed Defects | 15/08/2018      | A77 NB CW 475M PRIOR TO TREESWOOD   |
| SW80-393014-235952311   | 2,049m  | 2,050m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 11/09/2018               | Completed Defects | 15/08/2018      | A77 NB CW 450M PRIOR TO TREESWOOD   |
| SW80-393014-235952308   | 1,898m  | 1,899m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 11/09/2018               | Completed Defects | 15/08/2018      | A77 NB CW 500M PRIOR TO TREESWOOD OVERBRIDGE                                    |
| SW80-393014-235952310   | 1,975m  | 1,976m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 11/09/2018               | Completed Defects | 15/08/2018      | A77 NB CW 470M PRIOR TO TREESWOOD   |
| SW80-393014-235952312   | 2,053m  | 2,054m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 11/09/2018               | Completed Defects | 15/08/2018      | A77 NB CW 445M PRIOR TO TREESWOOD   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 17 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| SW80-394500-235964833   | 2,383m  | 2,885m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 14/09/2018               | Completed Defects | 17/08/2018      | A77 S/B ON CENTRE LINE 100M PRIOR TO TREESWOOD RD OVERBRIDGE SOUTH OF BELLFIELD |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 21 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 24 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 28 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 31 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 September 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 ( Awaiting Return )</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 September 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 14 September 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 September 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 September 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 25 September 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 September 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 October 2018</b>   |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 October 2018</b>   |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 October 2018</b>   |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 October 2018</b>   |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 October 2018</b>   |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |   |



| Defect Reference   | Start<br>m | End<br>m | Item Type   | Item Detail                          | Defect<br>Category | Required<br>Completion Date | Current Status        | Completion<br>Date | Location Description |
|--|------------|----------|-------------|--------------------------------------|--------------------|-----------------------------|-----------------------|--------------------|----------------------|
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 October 2018</b>  |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 October 2018</b>  |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 October 2018</b>  |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 October 2018</b>  |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 November 2018</b> |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 November 2018</b> |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 November 2018</b> |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 November 2018</b> |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 November 2018</b> |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 November 2018</b> |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 November 2018</b> |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 November 2018</b> |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 30 November 2018</b> |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 December 2018</b> |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 07 December 2018</b> |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 December 2018</b> |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 14 December 2018</b> |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 December 2018</b> |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 December 2018</b> |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 December 2018</b> |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 December 2018</b> |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 December 2018</b> |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 January 2019</b>  |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 January 2019</b>  |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 January 2019</b>  |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 January 2019</b>  |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018</b>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| SW82332070-378   | 3,203m     | 1m       | KERB        | Damaged (DAMG)                       | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-261   | 1,012m     | 1,032m   | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-415   | 1,574m     | 1,674m   | ROAD_STUDS  | Missing (MISS)                       | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-417   | 1,584m     | 1,684m   | CARRIAGEWAY | Pothole (POTH)                       | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |

| Defect Reference | Start m | End m  | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|--------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82332070-414   | 1,572m  | 1,572m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-265   | 486m    | 506m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-272   | 3,325m  | 3,326m | TRAFFIC_SIGNS      | Physical condition of post (COPT)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-262   | 55m     | 76m    | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-268   | 1,449m  | 1,450m | TRAFFIC_SIGNS      | Physical condition of post (COPT)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-259   | 942m    | 943m   | CARRIAGEWAY        | Pothole (POTH)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-267   | 1,157m  | 1,158m | CARRIAGEWAY        | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-413   | 1,585m  | 1,585m | KERB               | Damaged (DAMG)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-260   | 945m    | 955m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-416   | 1,594m  | 1,694m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-423   | 1,175m  | 1,175m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-422   | 1,396m  | 100m   | ROAD_STUDS         | Missing (MISS)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-377   | 3,316m  | 3,316m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-381   | 2,942m  | 2,952m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-263   | 203m    | 208m   | CARRIAGEWAY        | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-257   | 729m    | 759m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-273   | 3,321m  | 3,322m | TRAFFIC_SIGNS      | Dirty sign (DIRT)                    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |

**Safety Inspection of A76 & A77 Ayr North V1 on 15 January 2019**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 January 2019**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 22 January 2019**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 January 2019**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 29 January 2019**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 February 2019**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 05 February 2019**

| Defect Reference   | Start m | End m  | Item Type           | Item Detail              | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                              |
|--|---------|--------|---------------------|--------------------------|-----------------|--------------------------|-------------------|-----------------|---|
| SW82429329-236310614   | 2,750m  | 2,751m | CARRIAGEWAY         | Failed repair (RFAL)     | CAT 1           | 05/03/2019               | Completed Defects | 20/02/2019      | A77 SB CW, 300M NTH OF SB LAYBY AT TREESWOOD OB   |
| SW82429329-236310601   | 413m    | 414m   | CARRIAGEWAY         | Detritus / Refuse (DETR) | CAT 1           | 05/03/2019               | Completed Defects | 05/02/2019      | A77 NB LANE 2, 400M NTH OF EAST AYRSHIRE BOUNDARY |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 February 2019</b> |         |        |                     |                          |                 |                          |                   |                 |   |
| No defects recorded  |         |        |                     |                          |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 February 2019</b> |         |        |                     |                          |                 |                          |                   |                 |   |
| No defects recorded  |         |        |                     |                          |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 February 2019</b> |         |        |                     |                          |                 |                          |                   |                 |   |
| No defects recorded  |         |        |                     |                          |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 February 2019</b> |         |        |                     |                          |                 |                          |                   |                 |   |
| SW82432260-236330732   | 3,038m  | 3,038m | FENCES_AND_BARRIERS | Accident damage (ACCD)   | CAT 1           | 19/03/2019               | Completed Defects | 19/02/2019      | A77 N/B 200MTRS BEFORE WATRIGGS OVERBRIDGE        |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 February 2019</b> |         |        |                     |                          |                 |                          |                   |                 |   |
| SW82433749-236325481   | 1,647m  | 1,647m | CARRIAGEWAY         | Pothole VIAFIX (POTV)    | CAT 1           | 23/02/2019               | Completed Defects | 22/02/2019      | A77 S/B 650MTRS PASS TREESWOOD OVER BRIDGE        |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 February 2019</b> |         |        |                     |                          |                 |                          |                   |                 |   |
| No defects recorded  |         |        |                     |                          |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 March 2019</b>    |         |        |                     |                          |                 |                          |                   |                 |   |
| No defects recorded  |         |        |                     |                          |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 March 2019</b>    |         |        |                     |                          |                 |                          |                   |                 |   |
| No defects recorded  |         |        |                     |                          |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 March 2019</b>    |         |        |                     |                          |                 |                          |                   |                 |   |
| No defects recorded  |         |        |                     |                          |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 March 2019</b>    |         |        |                     |                          |                 |                          |                   |                 |   |
| No defects recorded  |         |        |                     |                          |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 March 2019</b>    |         |        |                     |                          |                 |                          |                   |                 |   |
| No defects recorded  |         |        |                     |                          |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 March 2019</b>    |         |        |                     |                          |                 |                          |                   |                 |   |
| SW82451334-236467201   | 1,461m  | 1,461m | FENCES_AND_BARRIERS | Accident damage (ACCD)   | CAT 1           | 16/04/2019               | Completed Defects | 20/04/2019      | A77 N/B 50MTRS BEFORE CRAIGIE OVERBRIDGE          |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 March 2019</b>    |         |        |                     |                          |                 |                          |                   |                 |   |
| No defects recorded  |         |        |                     |                          |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 March 2019</b>    |         |        |                     |                          |                 |                          |                   |                 |   |
| No defects recorded  |         |        |                     |                          |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2019</b>    |         |        |                     |                          |                 |                          |                   |                 |   |
| No defects recorded  |         |        |                     |                          |                 |                          |                   |                 |   |
| <b>11656/03 : WITH: 300M N WHATRIGGS BR TO OFF SLIP TO A76/A71</b>         |         |        |                     |                          |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 January 2018</b>  |         |        |                     |                          |                 |                          |                   |                 |   |
| No defects recorded  |         |        |                     |                          |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018</b>  |         |        |                     |                          |                 |                          |                   |                 |   |
| No defects recorded  |         |        |                     |                          |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 January 2018</b>  |         |        |                     |                          |                 |                          |                   |                 |   |
| No defects recorded  |         |        |                     |                          |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018</b>  |         |        |                     |                          |                 |                          |                   |                 |   |
| No defects recorded  |         |        |                     |                          |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 January 2018</b>  |         |        |                     |                          |                 |                          |                   |                 |   |
| No defects recorded  |         |        |                     |                          |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018</b>  |         |        |                     |                          |                 |                          |                   |                 |   |
| No defects recorded  |         |        |                     |                          |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 January 2018</b>  |         |        |                     |                          |                 |                          |                   |                 |   |
| No defects recorded  |         |        |                     |                          |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018</b>  |         |        |                     |                          |                 |                          |                   |                 |   |
| No defects recorded  |         |        |                     |                          |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 January 2018</b>  |         |        |                     |                          |                 |                          |                   |                 |   |
| No defects recorded  |         |        |                     |                          |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018</b> |         |        |                     |                          |                 |                          |                   |                 |   |
| No defects recorded  |         |        |                     |                          |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 February 2018</b> |         |        |                     |                          |                 |                          |                   |                 |   |
| No defects recorded  |         |        |                     |                          |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018</b> |         |        |                     |                          |                 |                          |                   |                 |   |

| Defect Reference     | Start m | End m | Item Type   | Item Detail    | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                        |
|----------------------|---------|-------|-------------|----------------|-----------------|--------------------------|-------------------|-----------------|---|
| SW82319109-235534727 | 78m     | 80m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 09/03/2018               | Completed Defects | 22/02/2018      | A77 ON CL, 150M STH OF BELLFIELD NB OFFSLIP |
| SW82319109-235534728 | 175m    | 185m  | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 09/03/2018               | Completed Defects | 22/02/2018      | A77 NB CW, AT BELLFIELD NB OFFSLIP          |

**Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 27 March 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 03 April 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 April 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 10 April 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 April 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 17 April 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 April 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 24 April 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 April 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 01 May 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 May 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 08 May 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 May 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 15 May 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 May 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 22 May 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 May 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 29 May 2018**

*No defects recorded*

| Defect Reference     | Start m | End m | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                         |
|----------------------|---------|-------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|--|
| SW82355166-235815745 | 97m     | 98m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 26/06/2018               | Completed Defects | 30/05/2018      | A77 NB CW 40M PRIOR TO BELLFIELD ONTERCHANGE |
| SW82355166-235815744 | 56m     | 57m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 26/06/2018               | Completed Defects | 30/05/2018      | A77 NB CW 45M PRIOR TO BELLFIELD INTERCHANGE |

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 June 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 05 June 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 June 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 12 June 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 June 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 19 June 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 June 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 26 June 2018**

*No defects recorded*

**Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 June 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 03 July 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 July 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 10 July 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 July 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 17 July 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 July 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 24 July 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 July 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 31 July 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 03 August 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 07 August 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 10 August 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 14 August 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 17 August 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 21 August 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 24 August 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 28 August 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 31 August 2018**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 04 September 2018**

*No defects recorded*

**Safety Patrol of A77 Ayr North Safety Patrol V1 ( Awaiting Return )**

*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 11 September 2018**

| Defect Reference                                       | Start<br>m | End<br>m | Item Type | Item Detail                                  | Defect<br>Category | Required<br>Completion Date | Current Status | Completion<br>Date | Location Description |
|--|------------|----------|-----------|--|--------------------|-----------------------------|----------------|--------------------|----------------------|
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | <b>Safety Patrol V1 on 14 September 2018</b> |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | <b>on 18 September 2018</b>                  |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | <b>Safety Patrol V1 on 21 September 2018</b> |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | <b>on 25 September 2018</b>                  |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | <b>Safety Patrol V1 on 28 September 2018</b> |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | <b>on 02 October 2018</b>                    |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | <b>Safety Patrol V1 on 05 October 2018</b>   |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | <b>on 09 October 2018</b>                    |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | <b>Safety Patrol V1 on 12 October 2018</b>   |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | <b>on 16 October 2018</b>                    |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | <b>Safety Patrol V1 on 19 October 2018</b>   |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | <b>on 23 October 2018</b>                    |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | <b>Safety Patrol V1 on 26 October 2018</b>   |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | <b>on 30 October 2018</b>                    |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | <b>Safety Patrol V1 on 02 November 2018</b>  |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | <b>on 06 November 2018</b>                   |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | <b>Safety Patrol V1 on 09 November 2018</b>  |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | <b>on 13 November 2018</b>                   |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | <b>Safety Patrol V1 on 16 November 2018</b>  |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | <b>on 20 November 2018</b>                   |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | <b>Safety Patrol V1 on 23 November 2018</b>  |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | <b>on 27 November 2018</b>                   |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | <b>Safety Patrol V1 on 30 November 2018</b>  |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | <b>on 04 December 2018</b>                   |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | <b>Safety Patrol V1 on 07 December 2018</b>  |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | <b>on 11 December 2018</b>                   |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | <b>Safety Patrol V1 on 14 December 2018</b>  |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | <b>on 18 December 2018</b>                   |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | <b>Safety Patrol V1 on 21 December 2018</b>  |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | <b>on 24 December 2018</b>                   |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | <b>Safety Patrol V1 on 28 December 2018</b>  |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | <b>on 31 December 2018</b>                   |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | <b>Safety Patrol V1 on 04 January 2019</b>   |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |  |                    |                             |                |                    |                      |

| Defect Reference   | Start m | End m | Item Type     | Item Detail       | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description   |
|--|---------|-------|---------------|-------------------|-----------------|--------------------------|-----------------------|-----------------|--|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 January 2019</b>  |         |       |               |                   |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 January 2019</b>  |         |       |               |                   |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                   |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 January 2019</b>  |         |       |               |                   |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                   |                 |                          |                       |                 |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018</b>   |         |       |               |                   |                 |                          |                       |                 |  |
| SW82332070-373   | 194m    | 0m    | TRAFFIC_SIGNS | Dirty sign (DIRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 January 2019</b>  |         |       |               |                   |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                   |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 January 2019</b>  |         |       |               |                   |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 January 2019</b>  |         |       |               |                   |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                   |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 January 2019</b>  |         |       |               |                   |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 January 2019</b>  |         |       |               |                   |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                   |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 February 2019</b> |         |       |               |                   |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 February 2019</b> |         |       |               |                   |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                   |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 February 2019</b> |         |       |               |                   |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 February 2019</b> |         |       |               |                   |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                   |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 February 2019</b> |         |       |               |                   |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 February 2019</b> |         |       |               |                   |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                   |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 February 2019</b> |         |       |               |                   |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 February 2019</b> |         |       |               |                   |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                   |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 March 2019</b>    |         |       |               |                   |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 March 2019</b>    |         |       |               |                   |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                   |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 March 2019</b>    |         |       |               |                   |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 March 2019</b>    |         |       |               |                   |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                   |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 March 2019</b>    |         |       |               |                   |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 March 2019</b>    |         |       |               |                   |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                   |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 March 2019</b>    |         |       |               |                   |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 March 2019</b>    |         |       |               |                   |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                   |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2019</b>    |         |       |               |                   |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                   |                 |                          |                       |                 |  |
| <b>11656/05 : WITH: OFF SLIP TO A76/A71 TO ON SLIP FROM A76/A71</b>        |         |       |               |                   |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 January 2018</b>  |         |       |               |                   |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                   |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018</b>  |         |       |               |                   |                 |                          |                       |                 |  |
| SW82317357-235513861   | 657m    | 658m  | CARRIAGEWAY   | Pothole (POTH)    | CAT 1           | 02/02/2018               | Completed Defects     | 09/02/2018      | A77 N/B LANE1 ON BRIDGE DECK BETWEEN OF SLIP AND ON SLIP BELFIELD INTECHANGE |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 January 2018</b>  |         |       |               |                   |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                   |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018</b>  |         |       |               |                   |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                   |                 |                          |                       |                 |  |

| Defect Reference   | Start<br>m | End<br>m | Item Type   | Item Detail       | Defect<br>Category | Required<br>Completion Date | Current Status       | Completion<br>Date | Location Description  |
|--|------------|----------|-------------|-------------------|--------------------|-----------------------------|----------------------|--------------------|---|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 January 2018</b>  |            |          |             |                   |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018</b>  |            |          |             |                   |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 January 2018</b>  |            |          |             |                   |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018</b>  |            |          |             |                   |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 January 2018</b>  |            |          |             |                   |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018</b> |            |          |             |                   |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 February 2018</b> |            |          |             |                   |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018</b> |            |          |             |                   |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 February 2018</b> |            |          |             |                   |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018</b> |            |          |             |                   |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 February 2018</b> |            |          |             |                   |                    |                             |                      |                    |   |
| SW82321390-235546237   | 654m       | 656m     | CARRIAGEWAY | Pothole<br>(POTH) | CAT 1              | 20/03/2018                  | Completed<br>Defects | 21/02/2018         | A77 N/B LANE1 ON BRIDGE<br>DECK BETWEEN OFF AND ON<br>SLIP BELLFIELD<br>INTERCHANGE |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018</b> |            |          |             |                   |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 February 2018</b> |            |          |             |                   |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018</b>    |            |          |             |                   |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 March 2018</b>    |            |          |             |                   |                    |                             |                      |                    |   |
| SW82325502-235553036   | 665m       | 666m     | CARRIAGEWAY | Pothole<br>(POTH) | CAT 1              | 03/04/2018                  | Completed<br>Defects | 07/03/2018         | A77 NB CW, LANE 1, BRIDGE<br>JOINT UNDER BELLFIELD<br>INTERCHANGE                   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018</b>    |            |          |             |                   |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 March 2018</b>    |            |          |             |                   |                    |                             |                      |                    |   |
| SW82327521-235576662   | 367m       | 368m     | CARRIAGEWAY | Pothole<br>(POTH) | CAT 1              | 10/04/2018                  | Completed<br>Defects | 14/03/2018         | A77 NB CW, ON CL,<br>BELLFIELD MAIN DRAG  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018</b>    |            |          |             |                   |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 March 2018</b>    |            |          |             |                   |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018</b>    |            |          |             |                   |                    |                             |                      |                    |   |
| SW82330424-235608135   | 187m       | 188m     | CARRIAGEWAY | Pothole<br>(POTH) | CAT 1              | 20/04/2018                  | Completed<br>Defects | 24/03/2018         | A77 NB CW, AT BELLFIELD NB<br>OFFSLIP, MAIN DRAG                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 March 2018</b>    |            |          |             |                   |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2018</b>    |            |          |             |                   |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 April 2018</b>    |            |          |             |                   |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 April 2018</b>    |            |          |             |                   |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 April 2018</b>    |            |          |             |                   |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 April 2018</b>    |            |          |             |                   |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 April 2018</b>    |            |          |             |                   |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 April 2018</b>    |            |          |             |                   |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 April 2018</b>    |            |          |             |                   |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                      |                    |   |



| Defect Reference   | Start m | End m | Item Type   | Item Detail    | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                                |
|--|---------|-------|-------------|----------------|-----------------|--------------------------|-------------------|-----------------|---|
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 April 2018</b>  |         |       |             |                |                 |                          |                   |                 |   |
| SW82341494-235545592   | 58m     | 0m    | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 25/05/2018               | Completed Defects | 28/04/2018      | A77 NB MAIN C/WAY AT BELLFIELD OFFSLIP LANE 1 OS WT |
| SW82341494-235545591   | 29m     | 0m    | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 25/05/2018               | Completed Defects | 28/04/2018      | A77 NB MAIN C/WAY AT BELLFIELD OFFSLIP LANE 1 OS WT |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 01 May 2018</b>    |         |       |             |                |                 |                          |                   |                 |   |
| No defects recorded  |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 May 2018</b>    |         |       |             |                |                 |                          |                   |                 |   |
| No defects recorded  |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 May 2018</b>    |         |       |             |                |                 |                          |                   |                 |   |
| No defects recorded  |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 May 2018</b>    |         |       |             |                |                 |                          |                   |                 |   |
| No defects recorded  |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 May 2018</b>    |         |       |             |                |                 |                          |                   |                 |   |
| No defects recorded  |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 May 2018</b>    |         |       |             |                |                 |                          |                   |                 |   |
| No defects recorded  |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 May 2018</b>    |         |       |             |                |                 |                          |                   |                 |   |
| No defects recorded  |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 May 2018</b>    |         |       |             |                |                 |                          |                   |                 |   |
| No defects recorded  |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 May 2018</b>    |         |       |             |                |                 |                          |                   |                 |   |
| No defects recorded  |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 June 2018</b>   |         |       |             |                |                 |                          |                   |                 |   |
| No defects recorded  |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 June 2018</b>   |         |       |             |                |                 |                          |                   |                 |   |
| No defects recorded  |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 June 2018</b>   |         |       |             |                |                 |                          |                   |                 |   |
| No defects recorded  |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 June 2018</b>   |         |       |             |                |                 |                          |                   |                 |   |
| No defects recorded  |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 June 2018</b>   |         |       |             |                |                 |                          |                   |                 |   |
| No defects recorded  |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 June 2018</b>   |         |       |             |                |                 |                          |                   |                 |   |
| No defects recorded  |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 June 2018</b>   |         |       |             |                |                 |                          |                   |                 |   |
| No defects recorded  |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 June 2018</b>   |         |       |             |                |                 |                          |                   |                 |   |
| No defects recorded  |         |       |             |                |                 |                          |                   |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018</b>     |         |       |             |                |                 |                          |                   |                 |   |
| No defects recorded  |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 June 2018</b>   |         |       |             |                |                 |                          |                   |                 |   |
| No defects recorded  |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 July 2018</b>   |         |       |             |                |                 |                          |                   |                 |   |
| No defects recorded  |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 July 2018</b>   |         |       |             |                |                 |                          |                   |                 |   |
| No defects recorded  |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 July 2018</b>   |         |       |             |                |                 |                          |                   |                 |   |
| No defects recorded  |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 July 2018</b>   |         |       |             |                |                 |                          |                   |                 |   |
| No defects recorded  |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 July 2018</b>   |         |       |             |                |                 |                          |                   |                 |   |
| No defects recorded  |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 July 2018</b>   |         |       |             |                |                 |                          |                   |                 |   |
| No defects recorded  |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 July 2018</b>   |         |       |             |                |                 |                          |                   |                 |   |
| No defects recorded  |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 July 2018</b>   |         |       |             |                |                 |                          |                   |                 |   |
| No defects recorded  |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 July 2018</b>   |         |       |             |                |                 |                          |                   |                 |   |
| No defects recorded  |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 03 August 2018</b> |         |       |             |                |                 |                          |                   |                 |   |
| No defects recorded  |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 August 2018</b> |         |       |             |                |                 |                          |                   |                 |   |
| No defects recorded  |         |       |             |                |                 |                          |                   |                 |   |

| Defect Reference  | Start<br>m | End<br>m | Item Type   | Item Detail                   | Defect<br>Category | Required<br>Completion Date | Current Status    | Completion<br>Date | Location Description  |
|---|------------|----------|-------------|-------------------------------|--------------------|-----------------------------|-------------------|--------------------|---|
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 10 August 2018</b>    |            |          |             |                               |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |             |                               |                    |                             |                   |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 14 August 2018</b>    |            |          |             |                               |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |             |                               |                    |                             |                   |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 17 August 2018</b>    |            |          |             |                               |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |             |                               |                    |                             |                   |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 21 August 2018</b>    |            |          |             |                               |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |             |                               |                    |                             |                   |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 24 August 2018</b>    |            |          |             |                               |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |             |                               |                    |                             |                   |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 28 August 2018</b>    |            |          |             |                               |                    |                             |                   |                    |   |
| SW80-399552-235979791   | 383m       | 384m     | CARRIAGEWAY | Debris in traffic Lane (DBTL) | CAT 1              | 29/08/2018                  | Completed Defects | 28/08/2018         | A77 S/B LANE1 BETWEEN OFF AND ON SLIP BELLFIELD INTERCHANGE |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 31 August 2018</b>    |            |          |             |                               |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |             |                               |                    |                             |                   |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 September 2018</b> |            |          |             |                               |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |             |                               |                    |                             |                   |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 ( Awaiting Return )</b>  |            |          |             |                               |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |             |                               |                    |                             |                   |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 September 2018</b> |            |          |             |                               |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |             |                               |                    |                             |                   |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 14 September 2018</b> |            |          |             |                               |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |             |                               |                    |                             |                   |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 September 2018</b> |            |          |             |                               |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |             |                               |                    |                             |                   |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 September 2018</b> |            |          |             |                               |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |             |                               |                    |                             |                   |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 25 September 2018</b> |            |          |             |                               |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |             |                               |                    |                             |                   |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 September 2018</b> |            |          |             |                               |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |             |                               |                    |                             |                   |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 October 2018</b>   |            |          |             |                               |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |             |                               |                    |                             |                   |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 October 2018</b>   |            |          |             |                               |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |             |                               |                    |                             |                   |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 October 2018</b>   |            |          |             |                               |                    |                             |                   |                    |   |
| SW82419282-236112151  | 863m       | 863m     | GULLY       | Blockage (BLOK)               | CAT 1              | 10/10/2018                  | Completed Defects | 09/10/2018         | A77 NB CW BELLFIELD INTERCHANGE ON SLIP                     |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 October 2018</b>   |            |          |             |                               |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |             |                               |                    |                             |                   |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 October 2018</b>   |            |          |             |                               |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |             |                               |                    |                             |                   |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 October 2018</b>   |            |          |             |                               |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |             |                               |                    |                             |                   |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 October 2018</b>   |            |          |             |                               |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |             |                               |                    |                             |                   |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 October 2018</b>   |            |          |             |                               |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |             |                               |                    |                             |                   |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 October 2018</b>   |            |          |             |                               |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |             |                               |                    |                             |                   |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 November 2018</b>  |            |          |             |                               |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |             |                               |                    |                             |                   |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 November 2018</b>  |            |          |             |                               |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |             |                               |                    |                             |                   |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 November 2018</b>  |            |          |             |                               |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |             |                               |                    |                             |                   |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 November 2018</b>  |            |          |             |                               |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |             |                               |                    |                             |                   |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 November 2018</b>  |            |          |             |                               |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |             |                               |                    |                             |                   |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 November 2018</b>  |            |          |             |                               |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |             |                               |                    |                             |                   |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 November 2018</b>  |            |          |             |                               |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |             |                               |                    |                             |                   |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 November 2018</b>  |            |          |             |                               |                    |                             |                   |                    |   |

| Defect Reference   | Start m | End m | Item Type     | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description   |
|--|---------|-------|---------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|--|
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 30 November 2018</b> |         |       |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 December 2018</b> |         |       |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 07 December 2018</b> |         |       |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 December 2018</b> |         |       |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 14 December 2018</b> |         |       |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 December 2018</b> |         |       |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 December 2018</b> |         |       |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 December 2018</b> |         |       |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 December 2018</b> |         |       |               |                                      |                 |                          |                       |                 |  |
| SW82427673-236270231   | 351m    | 353m  | CARRIAGEWAY   | Pothole (POTH)                       | CAT 1           | 25/01/2019               | Completed Defects     | 29/12/2018      | A77 NB CW BELLFIELD INTERCHANGE MAIN DRAG ON CENTRE LINE 30M NORTH OF FIRST OVERBRIDGE |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 December 2018</b> |         |       |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 January 2019</b>  |         |       |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 January 2019</b>  |         |       |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 January 2019</b>  |         |       |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 January 2019</b>  |         |       |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018</b>   |         |       |               |                                      |                 |                          |                       |                 |  |
| SW82332070-161   | 274m    | 350m  | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-159   | 182m    | 183m  | TRAFFIC_SIGNS | Dirty sign (DIRT)                    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 January 2019</b>  |         |       |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 January 2019</b>  |         |       |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 January 2019</b>  |         |       |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 January 2019</b>  |         |       |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 January 2019</b>  |         |       |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 February 2019</b> |         |       |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 February 2019</b> |         |       |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 February 2019</b> |         |       |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 February 2019</b> |         |       |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 February 2019</b> |         |       |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 February 2019</b> |         |       |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 February 2019</b> |         |       |               |                                      |                 |                          |                       |                 |  |
| SW82433749-236325475   | 878m    | 878m  | CARRIAGEWAY   | Pothole VIAFIX (POTV)                | CAT 1           | 23/02/2019               | Completed Defects     | 22/02/2019      | A77 S/B LANE 2 MAIN C/W @ BELLFEILD OFFSLIP  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 February 2019</b> |         |       |               |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                      |                 |                          |                       |                 |  |

| Defect Reference                                       | Start m | End m | Item Type | Item Detail                       | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|--|---------|-------|-----------|-----------------------------------|-----------------|--------------------------|----------------|-----------------|----------------------|
| <b>Safety Patrol of A77 Ayr North</b>                  |         |       |           | Safety Patrol V1 on 01 March 2019 |                 |                          |                |                 |                      |
| <i>No defects recorded</i>                             |         |       |           |                                   |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |         |       |           | on 05 March 2019                  |                 |                          |                |                 |                      |
| <i>No defects recorded</i>                             |         |       |           |                                   |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |         |       |           | Safety Patrol V1 on 08 March 2019 |                 |                          |                |                 |                      |
| <i>No defects recorded</i>                             |         |       |           |                                   |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |         |       |           | on 12 March 2019                  |                 |                          |                |                 |                      |
| <i>No defects recorded</i>                             |         |       |           |                                   |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |         |       |           | Safety Patrol V1 on 15 March 2019 |                 |                          |                |                 |                      |
| <i>No defects recorded</i>                             |         |       |           |                                   |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |         |       |           | on 19 March 2019                  |                 |                          |                |                 |                      |
| <i>No defects recorded</i>                             |         |       |           |                                   |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |         |       |           | Safety Patrol V1 on 22 March 2019 |                 |                          |                |                 |                      |
| <i>No defects recorded</i>                             |         |       |           |                                   |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |         |       |           | on 26 March 2019                  |                 |                          |                |                 |                      |
| <i>No defects recorded</i>                             |         |       |           |                                   |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |         |       |           | Safety Patrol V1 on 29 March 2019 |                 |                          |                |                 |                      |
| <i>No defects recorded</i>                             |         |       |           |                                   |                 |                          |                |                 |                      |

**11656/20 : HURLFORD INTERCHANGE ROUNDABOUT**

|  |  |  |  |                                      |  |  |  |  |  |
|--|--|--|--|--------------------------------------|--|--|--|--|--|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |  |  |  | on 02 January 2018                   |  |  |  |  |  |
| <i>No defects recorded</i>                             |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Patrol of A77 Ayr North</b>                  |  |  |  | Safety Patrol V1 on 05 January 2018  |  |  |  |  |  |
| <i>No defects recorded</i>                             |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |  |  |  | on 09 January 2018                   |  |  |  |  |  |
| <i>No defects recorded</i>                             |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Patrol of A77 Ayr North</b>                  |  |  |  | Safety Patrol V1 on 12 January 2018  |  |  |  |  |  |
| <i>No defects recorded</i>                             |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |  |  |  | on 16 January 2018                   |  |  |  |  |  |
| <i>No defects recorded</i>                             |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Patrol of A77 Ayr North</b>                  |  |  |  | Safety Patrol V1 on 19 January 2018  |  |  |  |  |  |
| <i>No defects recorded</i>                             |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |  |  |  | on 23 January 2018                   |  |  |  |  |  |
| <i>No defects recorded</i>                             |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Patrol of A77 Ayr North</b>                  |  |  |  | Safety Patrol V1 on 26 January 2018  |  |  |  |  |  |
| <i>No defects recorded</i>                             |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |  |  |  | on 30 January 2018                   |  |  |  |  |  |
| <i>No defects recorded</i>                             |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Patrol of A77 Ayr North</b>                  |  |  |  | Safety Patrol V1 on 02 February 2018 |  |  |  |  |  |
| <i>No defects recorded</i>                             |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |  |  |  | on 06 February 2018                  |  |  |  |  |  |
| <i>No defects recorded</i>                             |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Patrol of A77 Ayr North</b>                  |  |  |  | Safety Patrol V1 on 09 February 2018 |  |  |  |  |  |
| <i>No defects recorded</i>                             |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |  |  |  | on 13 February 2018                  |  |  |  |  |  |
| <i>No defects recorded</i>                             |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Patrol of A77 Ayr North</b>                  |  |  |  | Safety Patrol V1 on 16 February 2018 |  |  |  |  |  |
| <i>No defects recorded</i>                             |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |  |  |  | on 20 February 2018                  |  |  |  |  |  |
| <i>No defects recorded</i>                             |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Patrol of A77 Ayr North</b>                  |  |  |  | Safety Patrol V1 on 23 February 2018 |  |  |  |  |  |
| <i>No defects recorded</i>                             |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |  |  |  | on 27 February 2018                  |  |  |  |  |  |
| <i>No defects recorded</i>                             |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Patrol of A77 Ayr North</b>                  |  |  |  | Safety Patrol V1 on 02 March 2018    |  |  |  |  |  |
| <i>No defects recorded</i>                             |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |  |  |  | on 06 March 2018                     |  |  |  |  |  |
| <i>No defects recorded</i>                             |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Patrol of A77 Ayr North</b>                  |  |  |  | Safety Patrol V1 on 09 March 2018    |  |  |  |  |  |
| <i>No defects recorded</i>                             |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |  |  |  | on 13 March 2018                     |  |  |  |  |  |
| <i>No defects recorded</i>                             |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Patrol of A77 Ayr North</b>                  |  |  |  | Safety Patrol V1 on 16 March 2018    |  |  |  |  |  |
| <i>No defects recorded</i>                             |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |  |  |  | on 20 March 2018                     |  |  |  |  |  |
| <i>No defects recorded</i>                             |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Patrol of A77 Ayr North</b>                  |  |  |  | Safety Patrol V1 on 23 March 2018    |  |  |  |  |  |

| Defect Reference  | Start<br>m | End<br>m | Item Type | Item Detail | Defect<br>Category | Required<br>Completion Date | Current Status | Completion<br>Date | Location Description |
|---|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 March 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 April 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 April 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 April 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 April 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 April 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 April 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 April 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 April 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 01 May 2018</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 May 2018</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 May 2018</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 May 2018</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 May 2018</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 May 2018</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 May 2018</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 May 2018</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 May 2018</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 June 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 June 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 June 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 June 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 June 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 June 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 June 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 June 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 June 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 July 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 July 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 July 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 July 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |

| Defect Reference  | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|---|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 July 2018</b><br><i>No defects recorded</i>      |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 July 2018</b><br><i>No defects recorded</i>      |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 July 2018</b><br><i>No defects recorded</i>      |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 July 2018</b><br><i>No defects recorded</i>      |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 July 2018</b><br><i>No defects recorded</i>      |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 03 August 2018</b><br><i>No defects recorded</i>    |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 August 2018</b><br><i>No defects recorded</i>    |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 10 August 2018</b><br><i>No defects recorded</i>    |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 14 August 2018</b><br><i>No defects recorded</i>    |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 17 August 2018</b><br><i>No defects recorded</i>    |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 21 August 2018</b><br><i>No defects recorded</i>    |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 24 August 2018</b><br><i>No defects recorded</i>    |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 28 August 2018</b><br><i>No defects recorded</i>    |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 31 August 2018</b><br><i>No defects recorded</i>    |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 September 2018</b><br><i>No defects recorded</i> |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 September 2018</b><br><i>No defects recorded</i> |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 14 September 2018</b><br><i>No defects recorded</i> |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 September 2018</b><br><i>No defects recorded</i> |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 September 2018</b><br><i>No defects recorded</i> |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 25 September 2018</b><br><i>No defects recorded</i> |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 September 2018</b><br><i>No defects recorded</i> |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 October 2018</b><br><i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 October 2018</b><br><i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 October 2018</b><br><i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 October 2018</b><br><i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 October 2018</b><br><i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 October 2018</b><br><i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 October 2018</b><br><i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 October 2018</b><br><i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 October 2018</b><br><i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 November 2018</b><br><i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 November 2018</b><br><i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 November 2018</b><br><i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 November 2018</b><br><i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |

| Defect Reference   | Start<br>m | End<br>m | Item Type   | Item Detail       | Defect<br>Category | Required<br>Completion Date | Current Status           | Completion<br>Date | Location Description |
|--|------------|----------|-------------|-------------------|--------------------|-----------------------------|--------------------------|--------------------|----------------------|
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 16 November 2018 |            |          |             |                   |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 20 November 2018 |            |          |             |                   |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 23 November 2018 |            |          |             |                   |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 27 November 2018 |            |          |             |                   |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 30 November 2018 |            |          |             |                   |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 04 December 2018 |            |          |             |                   |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 07 December 2018 |            |          |             |                   |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 11 December 2018 |            |          |             |                   |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 14 December 2018 |            |          |             |                   |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 18 December 2018 |            |          |             |                   |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 21 December 2018 |            |          |             |                   |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 24 December 2018 |            |          |             |                   |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 28 December 2018 |            |          |             |                   |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 31 December 2018 |            |          |             |                   |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 04 January 2019  |            |          |             |                   |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 07 January 2019  |            |          |             |                   |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 08 January 2019  |            |          |             |                   |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 11 January 2019  |            |          |             |                   |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                          |                    |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det</b> on 17 November 2018   |            |          |             |                   |                    |                             |                          |                    |                      |
| SW82332070-282   | 397m       | 398m     | CARRIAGEWAY | Pothole<br>(POTH) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 15 January 2019  |            |          |             |                   |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 18 January 2019  |            |          |             |                   |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 22 January 2019  |            |          |             |                   |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 25 January 2019  |            |          |             |                   |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 29 January 2019  |            |          |             |                   |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 01 February 2019 |            |          |             |                   |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 05 February 2019 |            |          |             |                   |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 08 February 2019 |            |          |             |                   |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 12 February 2019 |            |          |             |                   |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 15 February 2019 |            |          |             |                   |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 19 February 2019 |            |          |             |                   |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 22 February 2019 |            |          |             |                   |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 26 February 2019 |            |          |             |                   |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                   |                    |                             |                          |                    |                      |

| <b>Defect Reference</b>  | <b>Start<br/>m</b> | <b>End<br/>m</b> | <b>Item Type</b> | <b>Item Detail</b>  | <b>Defect<br/>Category</b> | <b>Required<br/>Completion Date</b> | <b>Current Status</b> | <b>Completion<br/>Date</b> | <b>Location Description</b> |
|--|--------------------|------------------|------------------|---------------------|----------------------------|-------------------------------------|-----------------------|----------------------------|-----------------------------|
| Safety Patrol of A77 Ayr North                                       |                    |                  | Safety Patrol V1 | on 01 March 2019    |                            |                                     |                       |                            |                             |
| No defects recorded  |                    |                  |                  |                     |                            |                                     |                       |                            |                             |
| Safety Inspection of A76 & A77 Ayr North V1                          |                    |                  | Safety Patrol V1 | on 05 March 2019    |                            |                                     |                       |                            |                             |
| No defects recorded  |                    |                  |                  |                     |                            |                                     |                       |                            |                             |
| Safety Patrol of A77 Ayr North                                       |                    |                  | Safety Patrol V1 | on 08 March 2019    |                            |                                     |                       |                            |                             |
| No defects recorded  |                    |                  |                  |                     |                            |                                     |                       |                            |                             |
| Safety Inspection of A76 & A77 Ayr North V1                          |                    |                  | Safety Patrol V1 | on 12 March 2019    |                            |                                     |                       |                            |                             |
| No defects recorded  |                    |                  |                  |                     |                            |                                     |                       |                            |                             |
| Safety Patrol of A77 Ayr North                                       |                    |                  | Safety Patrol V1 | on 15 March 2019    |                            |                                     |                       |                            |                             |
| No defects recorded  |                    |                  |                  |                     |                            |                                     |                       |                            |                             |
| Safety Inspection of A76 & A77 Ayr North V1                          |                    |                  | Safety Patrol V1 | on 19 March 2019    |                            |                                     |                       |                            |                             |
| No defects recorded  |                    |                  |                  |                     |                            |                                     |                       |                            |                             |
| Safety Patrol of A77 Ayr North                                       |                    |                  | Safety Patrol V1 | on 22 March 2019    |                            |                                     |                       |                            |                             |
| No defects recorded  |                    |                  |                  |                     |                            |                                     |                       |                            |                             |
| Safety Inspection of A76 & A77 Ayr North V1                          |                    |                  | Safety Patrol V1 | on 26 March 2019    |                            |                                     |                       |                            |                             |
| No defects recorded  |                    |                  |                  |                     |                            |                                     |                       |                            |                             |
| Safety Patrol of A77 Ayr North                                       |                    |                  | Safety Patrol V1 | on 29 March 2019    |                            |                                     |                       |                            |                             |
| No defects recorded  |                    |                  |                  |                     |                            |                                     |                       |                            |                             |
| <b>11656/12 : AGAINST: OFF SLIP A76/A71 TO 300M N WHATRIGGS BRID</b> |                    |                  |                  |                     |                            |                                     |                       |                            |                             |
| Safety Inspection of A76 & A77 Ayr North V1                          |                    |                  | Safety Patrol V1 | on 02 January 2018  |                            |                                     |                       |                            |                             |
| No defects recorded  |                    |                  |                  |                     |                            |                                     |                       |                            |                             |
| Safety Patrol of A77 Ayr North                                       |                    |                  | Safety Patrol V1 | on 05 January 2018  |                            |                                     |                       |                            |                             |
| No defects recorded  |                    |                  |                  |                     |                            |                                     |                       |                            |                             |
| Safety Inspection of A76 & A77 Ayr North V1                          |                    |                  | Safety Patrol V1 | on 09 January 2018  |                            |                                     |                       |                            |                             |
| No defects recorded  |                    |                  |                  |                     |                            |                                     |                       |                            |                             |
| Safety Patrol of A77 Ayr North                                       |                    |                  | Safety Patrol V1 | on 12 January 2018  |                            |                                     |                       |                            |                             |
| No defects recorded  |                    |                  |                  |                     |                            |                                     |                       |                            |                             |
| Safety Inspection of A76 & A77 Ayr North V1                          |                    |                  | Safety Patrol V1 | on 16 January 2018  |                            |                                     |                       |                            |                             |
| No defects recorded  |                    |                  |                  |                     |                            |                                     |                       |                            |                             |
| Safety Patrol of A77 Ayr North                                       |                    |                  | Safety Patrol V1 | on 19 January 2018  |                            |                                     |                       |                            |                             |
| No defects recorded  |                    |                  |                  |                     |                            |                                     |                       |                            |                             |
| Safety Inspection of A76 & A77 Ayr North V1                          |                    |                  | Safety Patrol V1 | on 23 January 2018  |                            |                                     |                       |                            |                             |
| No defects recorded  |                    |                  |                  |                     |                            |                                     |                       |                            |                             |
| Safety Patrol of A77 Ayr North                                       |                    |                  | Safety Patrol V1 | on 26 January 2018  |                            |                                     |                       |                            |                             |
| No defects recorded  |                    |                  |                  |                     |                            |                                     |                       |                            |                             |
| Safety Inspection of A76 & A77 Ayr North V1                          |                    |                  | Safety Patrol V1 | on 30 January 2018  |                            |                                     |                       |                            |                             |
| No defects recorded  |                    |                  |                  |                     |                            |                                     |                       |                            |                             |
| Safety Patrol of A77 Ayr North                                       |                    |                  | Safety Patrol V1 | on 02 February 2018 |                            |                                     |                       |                            |                             |
| No defects recorded  |                    |                  |                  |                     |                            |                                     |                       |                            |                             |
| Safety Inspection of A76 & A77 Ayr North V1                          |                    |                  | Safety Patrol V1 | on 06 February 2018 |                            |                                     |                       |                            |                             |
| No defects recorded  |                    |                  |                  |                     |                            |                                     |                       |                            |                             |
| Safety Patrol of A77 Ayr North                                       |                    |                  | Safety Patrol V1 | on 09 February 2018 |                            |                                     |                       |                            |                             |
| No defects recorded  |                    |                  |                  |                     |                            |                                     |                       |                            |                             |
| Safety Inspection of A76 & A77 Ayr North V1                          |                    |                  | Safety Patrol V1 | on 13 February 2018 |                            |                                     |                       |                            |                             |
| No defects recorded  |                    |                  |                  |                     |                            |                                     |                       |                            |                             |
| Safety Patrol of A77 Ayr North                                       |                    |                  | Safety Patrol V1 | on 16 February 2018 |                            |                                     |                       |                            |                             |
| No defects recorded  |                    |                  |                  |                     |                            |                                     |                       |                            |                             |
| Safety Inspection of A76 & A77 Ayr North V1                          |                    |                  | Safety Patrol V1 | on 20 February 2018 |                            |                                     |                       |                            |                             |
| No defects recorded  |                    |                  |                  |                     |                            |                                     |                       |                            |                             |
| Safety Patrol of A77 Ayr North                                       |                    |                  | Safety Patrol V1 | on 23 February 2018 |                            |                                     |                       |                            |                             |
| No defects recorded  |                    |                  |                  |                     |                            |                                     |                       |                            |                             |
| Safety Inspection of A76 & A77 Ayr North V1                          |                    |                  | Safety Patrol V1 | on 27 February 2018 |                            |                                     |                       |                            |                             |
| No defects recorded  |                    |                  |                  |                     |                            |                                     |                       |                            |                             |
| Safety Patrol of A77 Ayr North                                       |                    |                  | Safety Patrol V1 | on 02 March 2018    |                            |                                     |                       |                            |                             |
| No defects recorded  |                    |                  |                  |                     |                            |                                     |                       |                            |                             |
| Safety Inspection of A76 & A77 Ayr North V1                          |                    |                  | Safety Patrol V1 | on 06 March 2018    |                            |                                     |                       |                            |                             |
| No defects recorded  |                    |                  |                  |                     |                            |                                     |                       |                            |                             |
| Safety Patrol of A77 Ayr North                                       |                    |                  | Safety Patrol V1 | on 09 March 2018    |                            |                                     |                       |                            |                             |
| No defects recorded  |                    |                  |                  |                     |                            |                                     |                       |                            |                             |
| Safety Inspection of A76 & A77 Ayr North V1                          |                    |                  | Safety Patrol V1 | on 13 March 2018    |                            |                                     |                       |                            |                             |
| No defects recorded  |                    |                  |                  |                     |                            |                                     |                       |                            |                             |
| Safety Patrol of A77 Ayr North                                       |                    |                  | Safety Patrol V1 | on 16 March 2018    |                            |                                     |                       |                            |                             |
| No defects recorded  |                    |                  |                  |                     |                            |                                     |                       |                            |                             |
| Safety Inspection of A76 & A77 Ayr North V1                          |                    |                  | Safety Patrol V1 | on 20 March 2018    |                            |                                     |                       |                            |                             |
| No defects recorded  |                    |                  |                  |                     |                            |                                     |                       |                            |                             |
| Safety Patrol of A77 Ayr North                                       |                    |                  | Safety Patrol V1 | on 23 March 2018    |                            |                                     |                       |                            |                             |



| Defect Reference | Start<br>m | End<br>m | Item Type | Item Detail | Defect<br>Category | Required<br>Completion Date | Current Status | Completion<br>Date | Location Description |
|------------------|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|
|------------------|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 27 March 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 03 April 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 April 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 10 April 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 April 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 17 April 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 April 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 24 April 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 April 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 01 May 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 May 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 08 May 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 May 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 15 May 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 May 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 22 May 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 May 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 29 May 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 June 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 05 June 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 June 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 12 June 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 June 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 19 June 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 June 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 26 June 2018**

No defects recorded

**Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 June 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 03 July 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 July 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 10 July 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 July 2018**

No defects recorded



| Defect Reference  | Start<br>m | End<br>m | Item Type | Item Detail | Defect<br>Category | Required<br>Completion Date | Current Status | Completion<br>Date | Location Description |
|---|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 July 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 July 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 July 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 July 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 July 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 03 August 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 August 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 10 August 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 14 August 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 17 August 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 21 August 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 24 August 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 28 August 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 31 August 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 September 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 ( Awaiting Return )</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 September 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 14 September 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 September 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 September 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 25 September 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 September 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 October 2018</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 October 2018</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 October 2018</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 October 2018</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 October 2018</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 October 2018</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 October 2018</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 October 2018</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 October 2018</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 November 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 November 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 November 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |

| Defect Reference   | Start<br>m | End<br>m | Item Type   | Item Detail                                | Defect<br>Category | Required<br>Completion Date | Current Status           | Completion<br>Date | Location Description |
|--|------------|----------|-------------|--|--------------------|-----------------------------|--------------------------|--------------------|----------------------|
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 November 2018</b> |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 November 2018</b> |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 November 2018</b> |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 November 2018</b> |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 November 2018</b> |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 30 November 2018</b> |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 December 2018</b> |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 07 December 2018</b> |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 December 2018</b> |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 14 December 2018</b> |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 December 2018</b> |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 December 2018</b> |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 December 2018</b> |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 December 2018</b> |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 December 2018</b> |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 January 2019</b>  |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 January 2019</b>  |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 January 2019</b>  |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 January 2019</b>  |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018</b>   |            |          |             |  |                    |                             |                          |                    |                      |
| SW82332070-274   | 650m       | 750m     | CARRIAGEWAY | Bituminous<br>surfacing<br>fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                      |
| SW82332070-275   | 474m       | 475m     | CARRIAGEWAY | Pothole<br>(POTH)                          | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 January 2019</b>  |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 January 2019</b>  |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 January 2019</b>  |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 January 2019</b>  |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 January 2019</b>  |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 February 2019</b> |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 February 2019</b> |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 February 2019</b> |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 February 2019</b> |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 February 2019</b> |            |          |             |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 February 2019</b> |            |          |             |  |                    |                             |                          |                    |                      |

| Defect Reference   | Start m | End m  | Item Type    | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description   |
|--|---------|--------|--------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|--|
| <i>No defects recorded</i>   |         |        |              |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 February 2019</b> |         |        |              |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |              |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 February 2019</b> |         |        |              |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |              |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 March 2019</b>    |         |        |              |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |              |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 March 2019</b>    |         |        |              |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |              |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 March 2019</b>    |         |        |              |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |              |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 March 2019</b>    |         |        |              |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |              |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 March 2019</b>    |         |        |              |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |              |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 March 2019</b>    |         |        |              |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |              |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 March 2019</b>    |         |        |              |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |              |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 March 2019</b>    |         |        |              |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |              |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2019</b>    |         |        |              |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |              |                                      |                 |                          |                       |                 |  |
| <b>11653/06 : AGAINST: 300M N OF WHATRIGGS BR TO E. AYRSHIRE BDY</b>       |         |        |              |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 January 2018</b>  |         |        |              |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |              |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018</b>  |         |        |              |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |              |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 January 2018</b>  |         |        |              |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |              |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018</b>  |         |        |              |                                      |                 |                          |                       |                 |  |
| <i>No defects recorded</i>   |         |        |              |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 January 2018</b>  |         |        |              |                                      |                 |                          |                       |                 |  |
| SW82317632-235520467   | 2,811m  | 2,844m | SAFETY_FENCE | Accident damage (ACCD)               | CAT 1           | 13/02/2018               | Completed Defects     | 02/02/2018      | INCHGOTRICK A77 CENTRE RESERVE                                   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018</b>  |         |        |              |                                      |                 |                          |                       |                 |  |
| SW82317695-235522279   | 1,966m  | 2,000m | CARRIAGEWAY  | Pothole (POTH)                       | CAT 1           | 16/02/2018               | Completed Defects     | 01/02/2018      | A77 SB CW, 4 POTHOLES FROM LAYBY STH OF TREESWOOD OB TO 250M STH |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 January 2018</b>  |         |        |              |                                      |                 |                          |                       |                 |  |
| SW82317767-235529085   | 847m    | 850m   | CARRIAGEWAY  | Pothole (POTH)                       | CAT 1           | 20/02/2018               | Completed Defects     | 02/02/2018      | A77 SB CW, LANE 1, 50M STH OF BELLFIELD INT                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 15 September 2017</b>  |         |        |              |                                      |                 |                          |                       |                 |  |
| SW82256027-218   | 1,834m  | 1,914m | CARRIAGEWAY  | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 E. AYRSHIRE BDY TO WHATRIGGS                                   |
| SW82256027-313   | 2,350m  | 2,450m | CARRIAGEWAY  | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 WHATRIGGS OB TO SPITTALHILL ON SLIP                            |
| SW82256027-315   | 2,545m  | 2,625m | CARRIAGEWAY  | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 WHATRIGGS OB TO SPITTALHILL ON SLIP                            |
| SW82256027-302   | 1,086m  | 1,090m | CARRIAGEWAY  | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 WHATRIGGS OB TO SPITTALHILL ON SLIP                            |
| SW82256027-309   | 2,035m  | 2,115m | CARRIAGEWAY  | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 WHATRIGGS OB TO SPITTALHILL ON SLIP                            |
| SW82256027-305   | 1,509m  | 1,589m | CARRIAGEWAY  | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 WHATRIGGS OB TO SPITTALHILL ON SLIP                            |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description  |
|--|---------|--------|-------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| SW82256027-306   | 1,646m  | 1,726m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 WHATRIGGS OB TO SPITTALHILL ON SLIP                                     |
| SW82256027-301   | 1,024m  | 1,104m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 WHATRIGGS OB TO SPITTALHILL ON SLIP                                     |
| SW82256027-303   | 1,239m  | 1,319m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 WHATRIGGS OB TO SPITTALHILL ON SLIP                                     |
| SW82256027-310   | 2,042m  | 2,122m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 WHATRIGGS OB TO SPITTALHILL ON SLIP                                     |
| SW82256027-312   | 2,258m  | 2,338m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 WHATRIGGS OB TO SPITTALHILL ON SLIP                                     |
| SW82256027-314   | 2,352m  | 1,432m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 WHATRIGGS OB TO SPITTALHILL ON SLIP                                     |
| SW82256027-316   | 2,858m  | 2,938m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 WHATRIGGS OB TO SPITTALHILL ON SLIP                                     |
| SW82256027-300   | 751m    | 831m   | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 WHATRIGGS OB TO SPITTALHILL ON SLIP                                     |
| SW82256027-311   | 2,137m  | 2,217m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 WHATRIGGS OB TO SPITTALHILL ON SLIP                                     |
| SW82256027-304   | 1,364m  | 1,444m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 WHATRIGGS OB TO SPITTALHILL ON SLIP                                     |
| SW82256027-307   | 1,699m  | 1,779m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 WHATRIGGS OB TO SPITTALHILL ON SLIP                                     |
| SW82256027-308   | 1,811m  | 1,891m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 WHATRIGGS OB TO SPITTALHILL ON SLIP                                     |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 January 2018</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018</b> |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 February 2018</b> |         |        |             |                                      |                 |                          |                       |                 |   |
| SW82318894-235534935   | 1,928m  | 1,930m | CARRIAGEWAY | Pothole (POTH)                       | CAT 1           | 06/03/2018               | Completed Defects     | 07/02/2018      | A77 NB CW, LANE 1, AT LAYBY PRIOR TO TREESWOOD OB                         |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018</b> |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 February 2018</b> |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018</b> |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 February 2018</b> |         |        |             |                                      |                 |                          |                       |                 |   |
| SW82321390-235546244   | 775m    | 777m   | CARRIAGEWAY | Pothole (POTH)                       | CAT 1           | 20/03/2018               | Completed Defects     | 21/02/2018      | A77 S/B LANE 1 25M SOUTH OF FIRST LAYBY SOUTH OF BELLFIELD INTERCHAGE     |
| SW82321390-235546243   | 741m    | 742m   | CARRIAGEWAY | Pothole (POTH)                       | CAT 1           | 20/03/2018               | Completed Defects     | 21/02/2018      | A7 S/B LANE1 5M SOUTH OF ENDOF FIRST LAYBY SOUTH OF BELLFIELD INTERCHANGE |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018</b> |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 February 2018</b> |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018</b>    |         |        |             |                                      |                 |                          |                       |                 |   |

| Defect Reference  | Start m | End m  | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                                  |
|---|---------|--------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|---|
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 March 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| SW82326369-235553180  | 1,646m  | 1,647m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 06/04/2018               | Completed Defects | 10/03/2018      | A77 SB CW, LANE 1, OPPOSITE TREESWOOD SB LAYBY        |
| SW82326369-235553182  | 1,838m  | 1,839m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 06/04/2018               | Completed Defects | 10/03/2018      | A77 SB CW, LANE 1, OPPOSITE TREESWOOD SB LAYBY        |
| SW82326369-235553183  | 1,912m  | 1,913m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 06/04/2018               | Completed Defects | 10/03/2018      | A77 SB CW, 50M STH OF TREESWOOD SB LAYBY              |
| SW82326369-235553179  | 1,527m  | 1,528m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 06/04/2018               | Completed Defects | 10/03/2018      | A77 SB CW, LANE 1, 50M NTH OF TREESWOOD SB LAYBY      |
| SW82326369-235553184  | 2,128m  | 2,129m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 06/04/2018               | Completed Defects | 10/03/2018      | A77 SB CW, LANE 1, 200M STH OF TREESWOOD SB LAYBY     |
| SW82326369-235553181  | 1,748m  | 1,749m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 06/04/2018               | Completed Defects | 10/03/2018      | A77 SB CW, LANE 1, OPPOSITE TREESWOOD SB LAYBY        |
| SW82326369-235553178  | 1,425m  | 1,426m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 06/04/2018               | Completed Defects | 10/03/2018      | A77 SB CW, LANE 1, 100M NTH OF TREESWOOD SB LAYBY     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 March 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| SW82327521-235576660  | 1,396m  | 1,398m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 10/04/2018               | Completed Defects | 14/03/2018      | A77 SB CW, LANE 1, 100M STH TREESWOOD OB AND AT LAYBY |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 March 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| SW82330424-235608133  | 1,782m  | 1,784m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 20/04/2018               | Completed Defects | 24/03/2018      | A77 NB CW, LANE 1, AT LAYBY STH OF TREESWOOD OB       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 March 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 April 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 April 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| SW82335189-235618853  | 1,305m  | 0m     | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 04/05/2018               | Completed Defects | 25/04/2018      | A77 N/B 5M AFTER TREESWOOD BRIDGE                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 April 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 April 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 April 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 April 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| SW82339168-235634095  | 768m    | 768m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 21/04/2018               | Completed Defects | 20/04/2018      | M77 S/B FIRST LAYBY BY BELLFIELD                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 April 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| SW82340437-235634100  | 1,828m  | 1,828m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 25/04/2018               | Completed Defects | 24/04/2018      | M77 S/B @2ND LAYBY PASS BELLFIELD R/A                 |
| SW82340437-235634099  | 664m    | 664m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 25/04/2018               | Completed Defects | 24/04/2018      | M77 S/B @ FIRST LAYBY AFORE BELLFIELD R/A             |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 April 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 01 May 2018</b>   |         |        |             |                       |                 |                          |                   |                 |   |

| Defect Reference   | Start m | End m  | Item Type     | Item Detail                       | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description  |
|--|---------|--------|---------------|-----------------------------------|-----------------|--------------------------|-------------------|-----------------|---|
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 May 2018</b>  |         |        |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 May 2018</b>  |         |        |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 May 2018</b>  |         |        |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 May 2018</b>  |         |        |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 May 2018</b>  |         |        |               |                                   |                 |                          |                   |                 |   |
| SW82350359-235785074   | 1,511m  | 1,512m | CARRIAGEWAY   | Pothole VIAFIX (POTV)             | CAT 1           | 19/05/2018               | Completed Defects | 18/05/2018      | A77 SB LANE 1 200M SOUT PF TREESWOOD HEAD OVEBRIDGE                           |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 May 2018</b>  |         |        |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 May 2018</b>  |         |        |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 May 2018</b>  |         |        |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 June 2018</b> |         |        |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 June 2018</b> |         |        |               |                                   |                 |                          |                   |                 |   |
| SW82358718-235826945   | 360m    | 361m   | CARRIAGEWAY   | Pothole (POTH)                    | CAT 1           | 03/07/2018               | Completed Defects | 06/06/2018      | A77 NB CW 600M STH OF BELLFIELD INTERCHANGE CL                                |
| SW82358718-235826946   | 374m    | 375m   | CARRIAGEWAY   | Pothole (POTH)                    | CAT 1           | 03/07/2018               | Completed Defects | 06/06/2018      | A77 NB 620M STH OF BELLFIELD INTECHANGE CL                                    |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 June 2018</b> |         |        |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 June 2018</b> |         |        |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 June 2018</b> |         |        |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 June 2018</b> |         |        |               |                                   |                 |                          |                   |                 |   |
| SW82366110-235861186   | 369m    | 370m   | CARRIAGEWAY   | Pothole VIAFIX (POTV)             | CAT 1           | 17/07/2018               | Completed Defects | 11/07/2018      | A77 NB CW CL 100M SOUTH OF TREESWOOD  |
| SW82366110-235861188   | 363m    | 364m   | CARRIAGEWAY   | Pothole VIAFIX (POTV)             | CAT 1           | 17/07/2018               | Completed Defects | 17/07/2018      | A77 NB CW CL 90M SOUTH OF TREESWOOD   |
| SW82366110-235861187   | 363m    | 364m   | CARRIAGEWAY   | Pothole VIAFIX (POTV)             | CAT 1           | 17/07/2018               | Completed Defects | 17/07/2018      | A77 NB CW CL 95M SOUTH OF TREESWOOD   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 June 2018</b> |         |        |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 June 2018</b> |         |        |               |                                   |                 |                          |                   |                 |   |
| SW82369551-235867689   | 1,514m  | 1,515m | CARRIAGEWAY   | Failed repair (RFAL)              | CAT 1           | 24/07/2018               | Completed Defects | 27/06/2018      | A77 SB 100M PRIOR TO LAYBY AT TREESWOOD OVERBRIDGE                            |
| SW82369551-235867687   | 3,497m  | 3,498m | TRAFFIC_SIGNS | Physical condition of post (COPT) | CAT 1           | 24/07/2018               | Completed Defects | 26/06/2018      | A77 NB CW 100M AFTER INCHGOTRICH OVERBRIDGE                                   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018</b>   |         |        |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 June 2018</b> |         |        |               |                                   |                 |                          |                   |                 |   |
| SW80-370953-235874269  | 652m    | 653m   | CARRIAGEWAY   | Pothole (POTH)                    | CAT 1           | 27/07/2018               | Completed Defects | 30/06/2018      | A77 NB CW LAYBY PRIOR TO WHATRIGGS OVERBRIDGE                                 |
| SW80-370953-235874272  | 844m    | 845m   | CARRIAGEWAY   | Pothole (POTH)                    | CAT 1           | 27/07/2018               | Completed Defects | 30/06/2018      | A77 SB CW 20M PRIOR TO SCOTLAND TRANSERV SIGN BETWEEN BELLFIELD AND TREESWOOD |
| SW80-370953-235874270  | 649m    | 650m   | CARRIAGEWAY   | Pothole (POTH)                    | CAT 1           | 27/07/2018               | Completed Defects | 30/06/2018      | A77 NB CW LAYBY PRIOR TO WHATRIGGS OVERBRIDGE                                 |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 July 2018</b> |         |        |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |        |               |                                   |                 |                          |                   |                 |   |

| Defect Reference  | Start m | End m  | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description   |
|---|---------|--------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|--|
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 July 2018</b>      |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 July 2018</b>      |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 July 2018</b>      |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 July 2018</b>      |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 July 2018</b>      |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 July 2018</b>      |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 July 2018</b>      |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 July 2018</b>      |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 03 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |  |
| SW80-389720-235948035   | 676m    | 677m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 04/09/2018               | Completed Defects | 07/08/2018      | A77 SB CW LAYBY 500M AFTER BELLFIELD ON SLIP   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 10 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |  |
| SW80-391133-235930167   | 653m    | 654m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 07/09/2018               | Completed Defects | 10/08/2018      | A77 SB CW 1ST LAYBY AFTER BELLFIELD ONSLIP   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 14 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 17 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |  |
| SW80-394500-235964835   | 1,765m  | 1,766m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 14/09/2018               | Completed Defects | 17/08/2018      | A77 S/B LANE 1 AT SECOND LAYBY SOUTH OF BELLFIELD                                    |
| SW80-394500-235964837   | 2,053m  | 2,054m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 14/09/2018               | Completed Defects | 17/08/2018      | A77 S/B LANE1 AT CRAIGIE ROAD BRIDGE SOUTH OF BELLFIELD INTERCHANGE                  |
| SW80-394500-235964834   | 1,760m  | 1,760m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 14/09/2018               | Completed Defects | 17/08/2018      | A77 S/B LANE 1 AT SECOND LAYBY SOUTH OF BELLFIELD                                    |
| SW80-394500-235964836   | 2,052m  | 2,053m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 14/09/2018               | Completed Defects | 17/08/2018      | A77S/B C/W AT CRAIGIE ROAD BRIDGE SOUTH OF BELLFIELD                                 |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 21 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 24 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 28 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 31 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 September 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| SW80-402975-236036446   | 1,827m  | 1,828m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 05/09/2018               | Completed Defects | 04/09/2018      | POTHOLES IN CARRIAGEWAY A77 S/B LANE 1 S/B TREESWOODHEAD OVERBRIDGE S/B OF BELLFIELD |
| SW80-402975-236036445   | 1,812m  | 1,813m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 05/09/2018               | Completed Defects | 04/09/2018      | A77 SOUTHBOUND LANE 1 400M SOUTH OF TREESWOODHEAD OVERBRIDGE SOUTH OF BELLFIELD      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 ( Awaiting Return )</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 September 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| SW82406268-236054646  | 1,699m  | 1,700m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 12/09/2018               | Completed Defects | 11/09/2018      | A77 S/B LAYBY 500M SOUTH OF TREESWOODHEAD OVERBRIDGE                                 |



| Defect Reference  | Start m | End m  | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description   |
|---|---------|--------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|--|
| SW82406268-236054647  | 1,710m  | 1,711m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 12/09/2018               | Completed Defects | 11/09/2018      | A77 S/B LAYBY 500M SOUTH TREESWOODHEAD ROAD OVERBRIDGE   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 14 September 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| SW82407615-236055840  | 774m    | 777m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 12/10/2018               | Completed Defects | 10/10/2018      | A77 SB 30M SOUTH OF FIRST LAYBY SOUTH OF BELLFIELD INTERCHANGE                                 |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 September 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| SW82409417-236071475  | 2,327m  | 2,328m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 16/10/2018               | Completed Defects | 19/09/2018      | A77 SB CENTRE LINE 300M SOUTH OF CRAIGIEMROAD BRIDGE SOUTH OF BELLFIELD INTERCHANGE KILMARNOCK |
| SW82409417-236071474  | 1,647m  | 1,648m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 19/09/2018               | Completed Defects | 18/09/2018      | A77 SB LANE 1 AT SECOND LAYBY SOUTH OF BELLFIELD INTERCHANGE                                   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 September 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 25 September 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 September 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 October 2018</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 October 2018</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| SW82417436-236071194  | 1,857m  | 1,859m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 02/11/2018               | Completed Defects | 01/11/2018      | A77 SB CW 50M PAST THE SECOND LAYBY SOUTH OF BELLFIELD INTERCHANGE ON CENTRE LINE              |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 October 2018</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 October 2018</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 October 2018</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| SW82422516-236143038  | 1,745m  | 1,746m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 13/11/2018               | Completed Defects | 16/10/2018      | A77 S/B ON CENTER LINE OPPOSITE LAYBY 300M SOUTH OF TREESWOOD HEAD OVERBRIDGE                  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 October 2018</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 October 2018</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 October 2018</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 October 2018</b>   |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 November 2018</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 November 2018</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| SW82426411-236211486  | 1,516m  | 1,520m | CARRIAGEWAY | Failed repair (RFAL)  | CAT 1           | 04/12/2018               | Completed Defects | 07/11/2018      | A77 S/B LANE100m PRIOR TO LSYBY SOUTH OF TRESWOOD HEAD ROAD OVERBRIDGE                         |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 November 2018</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 November 2018</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 November 2018</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 November 2018</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 November 2018</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| SW82426775-236232766  | 1,695m  | 1,697m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 21/12/2018               | Completed Defects | 24/11/2018      | A77 SB CW AT SECOND LAYBY SOUTH OF BELLFIELD   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 November 2018</b>  |         |        |             |                       |                 |                          |                   |                 |  |

| Defect Reference   | Start m | End m  | Item Type     | Item Detail               | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description  |
|--|---------|--------|---------------|---------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| <i>No defects recorded</i>   |         |        |               |                           |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 30 November 2018</b> |         |        |               |                           |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                           |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 December 2018</b> |         |        |               |                           |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                           |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 07 December 2018</b> |         |        |               |                           |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                           |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 December 2018</b> |         |        |               |                           |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                           |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 14 December 2018</b> |         |        |               |                           |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                           |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 December 2018</b> |         |        |               |                           |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                           |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 December 2018</b> |         |        |               |                           |                 |                          |                       |                 |   |
| SW82427545-236266526   | 838m    | 839m   | CARRIAGEWAY   | Pothole (POTH)            | CAT 1           | 18/01/2019               | Completed Defects     | 21/12/2018      | A77 SB CW, LANE 1, 200M NTH OF TREESWOOD OB   |
| SW82427545-236266527   | 849m    | 850m   | CARRIAGEWAY   | Pothole (POTH)            | CAT 1           | 18/01/2019               | Completed Defects     | 21/12/2018      | A77 SB CW, LANE 1, 200M NTH OF TREESWOOD OB   |
| SW82427545-236266528   | 840m    | 841m   | CARRIAGEWAY   | Pothole (POTH)            | CAT 1           | 18/01/2019               | Completed Defects     | 21/12/2018      | A77 SB CW, LANE 1, 200M NTH OF TREESWOOD OB   |
| SW82427545-236266525   | 835m    | 834m   | CARRIAGEWAY   | Pothole (POTH)            | CAT 1           | 18/01/2019               | Completed Defects     | 21/12/2018      | A77 SB CW, LANE 1, 200M NTH OF TREESWOOD OB   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 December 2018</b> |         |        |               |                           |                 |                          |                       |                 |   |
| SW80-427602-236270239  | 3,521m  | 3,522m | TRAFFIC_SIGNS | Pointing wrong way (RWAY) | CAT 1           | 25/12/2018               | Completed Defects     | 24/12/2018      | A77 SB CW 50M BEFORE SOUTH AYRSHIRE BOUNDARY  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 December 2018</b> |         |        |               |                           |                 |                          |                       |                 |   |
| SW82427673-236270234   | 1,663m  | 1,664m | CARRIAGEWAY   | Pothole (POTH)            | CAT 1           | 25/01/2019               | Completed Defects     | 29/12/2018      | A77 SB CW AT LAYBY SOUTH OF TREESWOODHEAD OVERBRIDGE SOUTH OF BELLFIELD                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 December 2018</b> |         |        |               |                           |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                           |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 January 2019</b>  |         |        |               |                           |                 |                          |                       |                 |   |
| SW82427910-236270617   | 1,544m  | 1,545m | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1           | 01/02/2019               | Completed Defects     | 05/01/2019      | A77 S/B LANE 1 60M PRIOR TO SECOND LAYBY SOUTH OF BELLFIELD INTERCHANGE KILLMARNOCK         |
| SW82427910-236270618   | 1,508m  | 1,509m | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1           | 01/02/2019               | Completed Defects     | 05/01/2019      | A77 S/BLANE 1 120MPRIOR TOSECOND LAYBY SOUTH OFBELLFIELDINTERCHANGE                         |
| SW82427910-236270616   | 1,214m  | 1,216m | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1           | 01/02/2019               | Completed Defects     | 05/01/2019      | A77 S/B ON CENTE LINE 100M PRIOR TO TREESWOOD HEAD OVEBRIDGE SOUTH OF BELLFIELD INTERCHANGE |
| SW82427910-236270619   | 1,514m  | 1,515m | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1           | 01/02/2019               | Completed Defects     | 05/01/2019      | A77 S/B LANE1 118M PRIOR TO SECOND LAYBY SOUTH OF BELLFIED INTERCHANGE                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 January 2019</b>  |         |        |               |                           |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                           |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 January 2019</b>  |         |        |               |                           |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                           |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 January 2019</b>  |         |        |               |                           |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |               |                           |                 |                          |                       |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018</b>   |         |        |               |                           |                 |                          |                       |                 |   |
| SW82332070-379   | 344m    | 344m   | TRAFFIC_SIGNS | Dirty sign (DIRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332070-394   | 1,175m  | 1,175m | KERB          | Damaged (DAMG)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |

| Defect Reference | Start m | End m  | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|--------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82332070-406   | 1,658m  | 1,658m | CARRIAGEWAY        | Pothole (POTH)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-420   | 2,144m  | 2,144m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-435   | 3,479m  | 1m     | TRAFFIC_SIGNS      | Dirty sign (DIRT)                    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-395   | 1,152m  | 1,152m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-397   | 1,196m  | 1,196m | KERB               | Damaged (DAMG)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-264   | 3,479m  | 3,480m | TRAFFIC_SIGNS      | Physical condition of post (COPT)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-271   | 198m    | 199m   | TRAFFIC_SIGNS      | Physical condition of post (COPT)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-383   | 641m    | 641m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-390   | 886m    | 886m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-392   | 906m    | 906m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-424   | 2,374m  | 2,384m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-426   | 2,384m  | 2,384m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-431   | 3,051m  | 3,051m | KERB               | Damaged (DAMG)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-433   | 3,250m  | 3,270m | ROAD_STUDS         | Missing (MISS)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-399   | 1,358m  | 1,358m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-401   | 1,350m  | 1,350m | CARRIAGEWAY        | Pothole (POTH)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-258   | 2,697m  | 2,727m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-270   | 1,953m  | 1,954m | CARRIAGEWAY        | Pothole (POTH)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-375   | 192m    | 192m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-382   | 603m    | 603m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-389   | 890m    | 899m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |

| Defect Reference | Start m | End m  | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|--------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82332070-410   | 1,777m  | 1,777m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-434   | 3,266m  | 3,266m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-402   | 1,385m  | 1,385m | ROAD_STUDS         | Missing (MISS)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-266   | 2,433m  | 2,434m | CARRIAGEWAY        | Pothole (POTH)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-427   | 2,711m  | 2,811m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-430   | 2,832m  | 2,832m | CARRIAGEWAY        | Pothole (POTH)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-385   | 721m    | 721m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-386   | 724m    | 724m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-412   | 1,699m  | 1,699m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-407   | 1,642m  | 1,662m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-409   | 1,687m  | 1,787m | ROAD_STUDS         | Missing (MISS)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-393   | 941m    | 20m    | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-405   | 1,395m  | 1,395m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-419   | 2,133m  | 2,133m | TRAFFIC_SIGNS      | Dirty sign (DIRT)                    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-421   | 2,135m  | 2,135m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-376   | 191m    | 191m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-396   | 1,077m  | 1,077m | CARRIAGEWAY        | Pothole (POTH)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | POTHOLE              |
| SW82332070-398   | 1,357m  | 1,357m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-418   | 2,016m  | 2,056m | ROAD_STUDS         | Missing (MISS)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-425   | 2,384m  | 2,394m | ROAD_STUDS         | Missing (MISS)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |

| Defect Reference   | Start m | End m  | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                         |
|--|---------|--------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|--|
| SW82332070-432   | 3,252m  | 3,252m | KERB               | Damaged (DAMG)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-380   | 384m    | 384m   | CARRIAGEWAY        | Pothole (POTH)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-384   | 711m    | 711m   | KERB               | Damaged (DAMG)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-391   | 869m    | 869m   | KERB               | Damaged (DAMG)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-408   | 1,654m  | 1,654m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-400   | 1,358m  | 1,358m | ROAD_STUDS         | Missing (MISS)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-374   | 177m    | 177m   | TRAFFIC_SIGNS      | Dirty sign (DIRT)                    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-269   | 2,043m  | 2,083m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-403   | 1,264m  | 1,264m | KERB               | Damaged (DAMG)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-404   | 1,371m  | 1,391m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-387   | 701m    | 701m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-388   | 762m    | 762m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-411   | 1,654m  | 1,654m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-428   | 2,765m  | 2,765m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-429   | 2,839m  | 2,859m | ROAD_STUDS         | Missing (MISS)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 January 2019</b>  |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 January 2019</b>  |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 January 2019</b>  |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 January 2019</b>  |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 January 2019</b>  |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 February 2019</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW82428977-236305204   | 1,529m  | 1,530m | CARRIAGEWAY        | Pothole (POTH)                       | CAT 1           | 01/03/2019               | Completed Defects     | 01/02/2019      | POTHOLE IN CW                                |
| SW82428977-236305201   | 2,059m  | 2,060m | MANHOLE            | Cracked or broken (IBCK)             | CAT 1           | 01/03/2019               | Completed Defects     | 28/02/2019      | A77 NB CW AT CRAIGIE ROAD OVERBRIDGE         |
| SW82428977-236305203   | 1,376m  | 1,377m | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 02/02/2019               | Completed Defects     | 01/02/2019      | A77 SB CW 50M AFTER TREESWOODHEAD OVERBRIDGE |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description  |
|--|---------|--------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|---|
| SW82428977-236305205   | 1,854m  | 1,855m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 01/03/2019               | Completed Defects | 01/02/2019      | A77 SB CW 10M AFTER LAYBY SOUTH OF TREESWOODHEAD OVERBRIDGE |
| SW82428977-236305202   | 1,428m  | 1,429m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 01/03/2019               | Completed Defects | 01/02/2019      | A77 SB CW 50M AFTER TREESWODHEAD OVERBRIDGE                 |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 February 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| SW82429329-236310617   | 1,390m  | 1,391m | CARRIAGEWAY | Failed repair (RFAL)  | CAT 1           | 05/03/2019               | Completed Defects | 20/02/2019      | A77 SB CW LANE 1, 100M NTH OF LAYBY TREESWOOD               |
| SW82429329-236310616   | 855m    | 856m   | CARRIAGEWAY | Failed repair (RFAL)  | CAT 1           | 05/03/2019               | Completed Defects | 20/02/2019      | A77 SB CW LANE 1 280M NTH OF LAYBY TREESWOOD OB             |
| SW82429329-236310615   | 827m    | 828m   | CARRIAGEWAY | Failed repair (RFAL)  | CAT 1           | 05/03/2019               | Completed Defects | 20/02/2019      | A77 SB CW, LANE 1, 280M NTH OF LAYBY TREESWOOD OB           |
| SW82429329-236310618   | 1,460m  | 1,461m | CARRIAGEWAY | Failed repair (RFAL)  | CAT 1           | 05/03/2019               | Completed Defects | 20/02/2019      | A77 SB CW, LANE 1, 80M NTH OF LAYBY TREESWOOD               |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 February 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 February 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| SW82429845-236328227   | 771m    | 775m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 13/02/2019               | Completed Defects | 13/02/2019      | A77 S/B AT END OF LAY BY AFTER BELLFIELD                    |
| SW82429845-236328230   | 834m    | 835m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 13/02/2019               | Completed Defects | 13/02/2019      | A77 S/B 80M AFTER LAY BY AFTER BELLFIELD                    |
| SW82429845-236328235   | 1,467m  | 1,468m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 13/02/2019               | Completed Defects | 13/02/2019      | A77 S/B 100M PRIOR TO SECOND LAY BY AFTER BELLFIELD         |
| SW82429845-236328233   | 847m    | 848m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 13/02/2019               | Completed Defects | 13/02/2019      | A77 S/B 105M AFTER LAY BY AFTER BELLFIELD                   |
| SW82429845-236328231   | 834m    | 836m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 13/02/2019               | Completed Defects | 13/02/2019      | A77 S/B 90M AFTER LAY BY AFTER BELLFIELD                    |
| SW82429845-236328234   | 775m    | 779m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 13/02/2019               | Completed Defects | 13/02/2019      | A77 S/B 20M AFTER LAY BY AFTER BELLFIELD                    |
| SW82429845-236328226   | 770m    | 771m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 13/02/2019               | Completed Defects | 13/02/2019      | A77 S/B AT END OF LAY BY AFTER BELLFIELD                    |
| SW82429845-236328229   | 823m    | 825m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 13/02/2019               | Completed Defects | 13/02/2019      | A77 S/B 70M AFTER LAY BY AFTER BELLFIELD                    |
| SW82429845-236328232   | 847m    | 848m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 13/02/2019               | Completed Defects | 13/02/2019      | A77 S/B 100M AFTER LAY BY AFTER BELLFIELD                   |
| SW82429845-236328236   | 1,637m  | 1,638m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 13/02/2019               | Completed Defects | 13/02/2019      | A77 S/B AT STAT OF SECOND LAY BY AFTER BELLFIELD            |
| SW82429845-236328237   | 1,690m  | 1,692m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 13/02/2019               | Completed Defects | 13/02/2019      | A77 S/B MIDDLE OF SECOND BLAY BY AFTER BELLFIELD            |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 February 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| No defects recorded  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 February 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| SW82432260-236330744   | 1,518m  | 1,518m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 20/02/2019               | Completed Defects | 19/02/2019      | M77 S/B WHATRIGGS BRIDGE TO LAYBY                           |
| SW82432260-236330743   | 1,466m  | 1,466m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 20/02/2019               | Completed Defects | 19/02/2019      | M77 S/B WHATRIGGS BRIDGE TO LAYBY                           |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 February 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| SW82433749-236325465   | 119m    | 119m   | CARRIAGEWAY | Litter Grade C (LITC) | 3RD PTY         | 23/02/2019               | Completed Defects | 14/05/2019      | A77 N/B WHATRIGGS OVERBRIDGE TO BELLFEILD OFF SLIP          |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description  |
|--|---------|--------|-------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| SW82433749-236325478   | 1,521m  | 1,521m | CARRIAGEWAY | Pothole (POTH)                       | CAT 1           | 22/03/2019               | Completed Defects     | 20/03/2019      | A77 S/B TREESWOOD OVERBRIDGE TO LAYBY 100MTRS BEFORE LAYBY        |
| SW82433749-236325479   | 1,543m  | 1,543m | CARRIAGEWAY | Pothole (POTH)                       | CAT 1           | 22/03/2019               | Completed Defects     | 20/03/2019      | A77 S/B TREESWOOD OVERBRIDGE TO LAYBY 50MTRS BEFORE LAYBY O/S/W/T |
| SW82433749-236325480   | 1,860m  | 1,860m | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 23/02/2019               | Completed Defects     | 22/02/2019      | A77 S/B 600MTR PASS TREESWOOD OVERBRIDGE                          |
| SW82433749-236325476   | 1,547m  | 1,547m | CARRIAGEWAY | Pothole (POTH)                       | CAT 1           | 22/03/2019               | Completed Defects     | 20/03/2019      | A77 S/B @100MRS BEFORE LAYBY @ TREESWOOD OVERBRIDGE TO LAYBY      |
| SW82433749-236325477   | 1,516m  | 1,516m | CARRIAGEWAY | Pothole (POTH)                       | CAT 1           | 22/03/2019               | Completed Defects     | 20/03/2019      | A77 S/B TREESWOOD OVERBRIDGE TO LAYBY 100MTRS BEFORE LAYBY        |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 February 2019</b> |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 March 2019</b>    |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 March 2019</b>    |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 March 2019</b>    |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 March 2019</b>    |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 March 2019</b>    |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 March 2019</b>    |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 March 2019</b>    |         |        |             |                                      |                 |                          |                       |                 |   |
| SW82454084-236489756   | 1,175m  | 1,175m | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 23/03/2019               | Completed Defects     | 23/03/2019      | A77 S/B BELLFEILD PASS FIRST LAYBY @ 1/4 MILE PARKING SIGN        |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 March 2019</b>    |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2019</b>    |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>11650/91 : AGAINST: EAST AYRSHIRE BDY TO SPITALHILL SLIP ROAD</b>       |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 January 2018</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 January 2018</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 January 2018</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 January 2018</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 15 September 2017</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| SW82256027-318   | 228m    | 308m   | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 WHATRIGGS OB TO SPITTALHILL ON SLIP                             |
| SW82256027-322   | 835m    | 915m   | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 WHATRIGGS OB TO SPITTALHILL ON SLIP                             |

| Defect Reference | Start m | End m | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                  |
|------------------|---------|-------|-------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|---------------------------------------|
| SW82256027-320   | 479m    | 559m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 WHATRIGGS OB TO SPITTALHILL ON SLIP |
| SW82256027-319   | 345m    | 425m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 WHATRIGGS OB TO SPITTALHILL ON SLIP |
| SW82256027-321   | 663m    | 743m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 WHATRIGGS OB TO SPITTALHILL ON SLIP |
| SW82256027-317   | 221m    | 301m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 WHATRIGGS OB TO SPITTALHILL ON SLIP |

**Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 27 March 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 03 April 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 April 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 10 April 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 April 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 17 April 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 April 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 24 April 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 April 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 01 May 2018**

No defects recorded



| Defect Reference   | Start<br>m | End<br>m | Item Type | Item Detail  | Defect<br>Category | Required<br>Completion Date | Current Status       | Completion<br>Date | Location Description                             |
|--|------------|----------|-----------|--------------|--------------------|-----------------------------|----------------------|--------------------|--|
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 04 May 2018    |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 08 May 2018    |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 11 May 2018    |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 15 May 2018    |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 18 May 2018    |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 22 May 2018    |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 25 May 2018    |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 29 May 2018    |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 01 June 2018   |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 05 June 2018   |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 08 June 2018   |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 12 June 2018   |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 15 June 2018   |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 19 June 2018   |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 22 June 2018   |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 26 June 2018   |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det</b> on 20 June 2018     |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 29 June 2018   |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 03 July 2018   |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 06 July 2018   |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 10 July 2018   |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 13 July 2018   |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 17 July 2018   |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 20 July 2018   |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 24 July 2018   |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 27 July 2018   |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 31 July 2018   |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 03 August 2018 |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 07 August 2018 |            |          |           |              |                    |                             |                      |                    |  |
| SW80-389720-235948036  | 49m        | 50m      | GULLY     | Other (OTHR) | CAT 1              | 04/09/2018                  | Completed<br>Defects | 07/08/2018         | A77 SB CW 50M PRIOR TO<br>INCHGOTRICH OVERBRIDGE |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 10 August 2018 |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 14 August 2018 |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 17 August 2018 |            |          |           |              |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |              |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 21 August 2018 |            |          |           |              |                    |                             |                      |                    |  |

| Defect Reference  | Start<br>m | End<br>m | Item Type | Item Detail | Defect<br>Category | Required<br>Completion Date | Current Status | Completion<br>Date | Location Description |
|---|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 24 August 2018    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 28 August 2018    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 31 August 2018    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 04 September 2018 |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 ( Awaiting Return )  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 11 September 2018 |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 14 September 2018 |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 18 September 2018 |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 21 September 2018 |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 25 September 2018 |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 28 September 2018 |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 02 October 2018   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 05 October 2018   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 09 October 2018   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 12 October 2018   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 16 October 2018   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 19 October 2018   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 23 October 2018   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 26 October 2018   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 30 October 2018   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 02 November 2018  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 06 November 2018  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 09 November 2018  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 13 November 2018  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 16 November 2018  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 20 November 2018  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 23 November 2018  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 27 November 2018  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 30 November 2018  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 04 December 2018  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 07 December 2018  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> on 11 December 2018  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 14 December 2018  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |

| Defect Reference   | Start m | End m | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|--|---------|-------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 December 2018</b> |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 December 2018</b> |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 December 2018</b> |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 December 2018</b> |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 December 2018</b> |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 January 2019</b>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 January 2019</b>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 January 2019</b>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 January 2019</b>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018</b>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| SW82332070-443   | 732m    | 732m  | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-436   | 400m    | 400m  | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-438   | 453m    | 473m  | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-440   | 600m    | 1m    | KERB               | Damaged (DAMG)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-442   | 702m    | 702m  | ROAD_STUDS         | Missing (MISS)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-444   | 780m    | 800m  | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-441   | 788m    | 788m  | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-437   | 410m    | 410m  | KERB               | Damaged (DAMG)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 January 2019</b>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 January 2019</b>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 January 2019</b>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 January 2019</b>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 January 2019</b>  |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 February 2019</b> |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 February 2019</b> |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 February 2019</b> |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 February 2019</b> |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 February 2019</b> |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 February 2019</b> |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |

| Defect Reference   | Start m | End m | Item Type | Item Detail                          | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|--|---------|-------|-----------|--------------------------------------|-----------------|--------------------------|----------------|-----------------|----------------------|
| <b>Safety Patrol of A77 Ayr North</b>                                      |         |       |           |                                      |                 |                          |                |                 |                      |
|  |         |       |           | Safety Patrol V1 on 22 February 2019 |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |                                      |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 February 2019</b> |         |       |           |                                      |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |                                      |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North</b>                                      |         |       |           |                                      |                 |                          |                |                 |                      |
|  |         |       |           | Safety Patrol V1 on 01 March 2019    |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |                                      |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 March 2019</b>    |         |       |           |                                      |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |                                      |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North</b>                                      |         |       |           |                                      |                 |                          |                |                 |                      |
|  |         |       |           | Safety Patrol V1 on 08 March 2019    |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |                                      |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 March 2019</b>    |         |       |           |                                      |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |                                      |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North</b>                                      |         |       |           |                                      |                 |                          |                |                 |                      |
|  |         |       |           | Safety Patrol V1 on 15 March 2019    |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |                                      |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 March 2019</b>    |         |       |           |                                      |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |                                      |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North</b>                                      |         |       |           |                                      |                 |                          |                |                 |                      |
|  |         |       |           | Safety Patrol V1 on 22 March 2019    |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |                                      |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 March 2019</b>    |         |       |           |                                      |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |                                      |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North</b>                                      |         |       |           |                                      |                 |                          |                |                 |                      |
|  |         |       |           | Safety Patrol V1 on 29 March 2019    |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |                                      |                 |                          |                |                 |                      |

**11650/81 : AGAINST: SPITALHILL SLIP ROAD TO EAST LODGE**

|  |  |  |  |                                      |  |  |  |  |  |
|--|--|--|--|--------------------------------------|--|--|--|--|--|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 January 2018</b>  |  |  |  |                                      |  |  |  |  |  |
| No defects recorded  |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Patrol of A77 Ayr North</b>                                      |  |  |  |                                      |  |  |  |  |  |
|  |  |  |  | Safety Patrol V1 on 05 January 2018  |  |  |  |  |  |
| No defects recorded  |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 January 2018</b>  |  |  |  |                                      |  |  |  |  |  |
| No defects recorded  |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Patrol of A77 Ayr North</b>                                      |  |  |  |                                      |  |  |  |  |  |
|  |  |  |  | Safety Patrol V1 on 12 January 2018  |  |  |  |  |  |
| No defects recorded  |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 January 2018</b>  |  |  |  |                                      |  |  |  |  |  |
| No defects recorded  |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Patrol of A77 Ayr North</b>                                      |  |  |  |                                      |  |  |  |  |  |
|  |  |  |  | Safety Patrol V1 on 19 January 2018  |  |  |  |  |  |
| No defects recorded  |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 January 2018</b>  |  |  |  |                                      |  |  |  |  |  |
| No defects recorded  |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Patrol of A77 Ayr North</b>                                      |  |  |  |                                      |  |  |  |  |  |
|  |  |  |  | Safety Patrol V1 on 26 January 2018  |  |  |  |  |  |
| No defects recorded  |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 January 2018</b>  |  |  |  |                                      |  |  |  |  |  |
| No defects recorded  |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Patrol of A77 Ayr North</b>                                      |  |  |  |                                      |  |  |  |  |  |
|  |  |  |  | Safety Patrol V1 on 02 February 2018 |  |  |  |  |  |
| No defects recorded  |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 February 2018</b> |  |  |  |                                      |  |  |  |  |  |
| No defects recorded  |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Patrol of A77 Ayr North</b>                                      |  |  |  |                                      |  |  |  |  |  |
|  |  |  |  | Safety Patrol V1 on 09 February 2018 |  |  |  |  |  |
| No defects recorded  |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 February 2018</b> |  |  |  |                                      |  |  |  |  |  |
| No defects recorded  |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Patrol of A77 Ayr North</b>                                      |  |  |  |                                      |  |  |  |  |  |
|  |  |  |  | Safety Patrol V1 on 16 February 2018 |  |  |  |  |  |
| No defects recorded  |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 February 2018</b> |  |  |  |                                      |  |  |  |  |  |
| No defects recorded  |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Patrol of A77 Ayr North</b>                                      |  |  |  |                                      |  |  |  |  |  |
|  |  |  |  | Safety Patrol V1 on 23 February 2018 |  |  |  |  |  |
| No defects recorded  |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 February 2018</b> |  |  |  |                                      |  |  |  |  |  |
| No defects recorded  |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Patrol of A77 Ayr North</b>                                      |  |  |  |                                      |  |  |  |  |  |
|  |  |  |  | Safety Patrol V1 on 02 March 2018    |  |  |  |  |  |
| No defects recorded  |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 March 2018</b>    |  |  |  |                                      |  |  |  |  |  |
| No defects recorded  |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Patrol of A77 Ayr North</b>                                      |  |  |  |                                      |  |  |  |  |  |
|  |  |  |  | Safety Patrol V1 on 09 March 2018    |  |  |  |  |  |
| No defects recorded  |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 March 2018</b>    |  |  |  |                                      |  |  |  |  |  |
| No defects recorded  |  |  |  |                                      |  |  |  |  |  |
| <b>Safety Patrol of A77 Ayr North</b>                                      |  |  |  |                                      |  |  |  |  |  |
|  |  |  |  | Safety Patrol V1 on 16 March 2018    |  |  |  |  |  |



| Defect Reference  | Start m | End m | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                  |
|---|---------|-------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|---------------------------------------|
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 March 2018</b> |         |       |             |                       |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018</b> |         |       |             |                       |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 March 2018</b> |         |       |             |                       |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2018</b> |         |       |             |                       |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 April 2018</b> |         |       |             |                       |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 April 2018</b> |         |       |             |                       |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| SW82336341-235634094  | 51m     | 0m    | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 11/04/2018               | Completed Defects | 10/04/2018      | A76 S/B AT JEAN ARMOUR DRIVE MAUCLINE |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 April 2018</b> |         |       |             |                       |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 April 2018</b> |         |       |             |                       |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 April 2018</b> |         |       |             |                       |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 April 2018</b> |         |       |             |                       |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 April 2018</b> |         |       |             |                       |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 01 May 2018</b>   |         |       |             |                       |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 May 2018</b>   |         |       |             |                       |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 May 2018</b>   |         |       |             |                       |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 May 2018</b>   |         |       |             |                       |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 May 2018</b>   |         |       |             |                       |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 May 2018</b>   |         |       |             |                       |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 May 2018</b>   |         |       |             |                       |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 May 2018</b>   |         |       |             |                       |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 May 2018</b>   |         |       |             |                       |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 June 2018</b>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 June 2018</b>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 June 2018</b>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 June 2018</b>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 June 2018</b>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 June 2018</b>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 June 2018</b>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 June 2018</b>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018</b>    |         |       |             |                       |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 June 2018</b>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 July 2018</b>  |         |       |             |                       |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                       |

| Defect Reference                                       | Start<br>m | End<br>m | Item Type | Item Detail                           | Defect<br>Category | Required<br>Completion Date | Current Status | Completion<br>Date | Location Description |
|--|------------|----------|-----------|---------------------------------------|--------------------|-----------------------------|----------------|--------------------|----------------------|
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | Safety Patrol V1 on 06 July 2018      |                    |                             |                |                    |                      |
|  |            |          |           | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | on 10 July 2018                       |                    |                             |                |                    |                      |
|  |            |          |           | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | Safety Patrol V1 on 13 July 2018      |                    |                             |                |                    |                      |
|  |            |          |           | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | on 17 July 2018                       |                    |                             |                |                    |                      |
|  |            |          |           | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | Safety Patrol V1 on 20 July 2018      |                    |                             |                |                    |                      |
|  |            |          |           | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | on 24 July 2018                       |                    |                             |                |                    |                      |
|  |            |          |           | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | Safety Patrol V1 on 27 July 2018      |                    |                             |                |                    |                      |
|  |            |          |           | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | on 31 July 2018                       |                    |                             |                |                    |                      |
|  |            |          |           | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | Safety Patrol V1 on 03 August 2018    |                    |                             |                |                    |                      |
|  |            |          |           | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | on 07 August 2018                     |                    |                             |                |                    |                      |
|  |            |          |           | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | Safety Patrol V1 on 10 August 2018    |                    |                             |                |                    |                      |
|  |            |          |           | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | on 14 August 2018                     |                    |                             |                |                    |                      |
|  |            |          |           | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | Safety Patrol V1 on 17 August 2018    |                    |                             |                |                    |                      |
|  |            |          |           | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | on 21 August 2018                     |                    |                             |                |                    |                      |
|  |            |          |           | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | Safety Patrol V1 on 24 August 2018    |                    |                             |                |                    |                      |
|  |            |          |           | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | on 28 August 2018                     |                    |                             |                |                    |                      |
|  |            |          |           | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | Safety Patrol V1 on 31 August 2018    |                    |                             |                |                    |                      |
|  |            |          |           | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | on 04 September 2018                  |                    |                             |                |                    |                      |
|  |            |          |           | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | Safety Patrol V1 ( Awaiting Return )  |                    |                             |                |                    |                      |
|  |            |          |           | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | on 11 September 2018                  |                    |                             |                |                    |                      |
|  |            |          |           | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | Safety Patrol V1 on 14 September 2018 |                    |                             |                |                    |                      |
|  |            |          |           | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | on 18 September 2018                  |                    |                             |                |                    |                      |
|  |            |          |           | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | Safety Patrol V1 on 21 September 2018 |                    |                             |                |                    |                      |
|  |            |          |           | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | on 25 September 2018                  |                    |                             |                |                    |                      |
|  |            |          |           | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | Safety Patrol V1 on 28 September 2018 |                    |                             |                |                    |                      |
|  |            |          |           | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | on 02 October 2018                    |                    |                             |                |                    |                      |
|  |            |          |           | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | Safety Patrol V1 on 05 October 2018   |                    |                             |                |                    |                      |
|  |            |          |           | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | on 09 October 2018                    |                    |                             |                |                    |                      |
|  |            |          |           | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | Safety Patrol V1 on 12 October 2018   |                    |                             |                |                    |                      |
|  |            |          |           | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | on 16 October 2018                    |                    |                             |                |                    |                      |
|  |            |          |           | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | Safety Patrol V1 on 19 October 2018   |                    |                             |                |                    |                      |
|  |            |          |           | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | on 23 October 2018                    |                    |                             |                |                    |                      |
|  |            |          |           | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | Safety Patrol V1 on 26 October 2018   |                    |                             |                |                    |                      |
|  |            |          |           | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | on 30 October 2018                    |                    |                             |                |                    |                      |

| Defect Reference   | Start<br>m | End<br>m | Item Type             | Item Detail                          | Defect<br>Category | Required<br>Completion Date | Current Status        | Completion<br>Date | Location Description |
|--|------------|----------|-----------------------|--------------------------------------|--------------------|-----------------------------|-----------------------|--------------------|----------------------|
| <i>No defects recorded</i>   |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 November 2018</b> |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 November 2018</b> |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 November 2018</b> |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 November 2018</b> |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 November 2018</b> |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 November 2018</b> |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 November 2018</b> |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 November 2018</b> |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 30 November 2018</b> |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 December 2018</b> |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 07 December 2018</b> |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 December 2018</b> |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 14 December 2018</b> |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 December 2018</b> |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 December 2018</b> |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 December 2018</b> |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 December 2018</b> |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 December 2018</b> |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 January 2019</b>  |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 January 2019</b>  |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 January 2019</b>  |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 January 2019</b>  |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |                       |                                      |                    |                             |                       |                    |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018</b>   |            |          |                       |                                      |                    |                             |                       |                    |                      |
| SW82332070-448   | 42m        | 42m      | KERB                  | Damaged (DAMG)                       | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-450   | 309m       | 329m     | ROAD_STUDS            | Missing (MISS)                       | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-451   | 82m        | 82m      | CARRIAGEWAY           | Bituminous surfacing fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-449   | 206m       | 206m     | CARRIAGEWAY           | Bituminous surfacing fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         | FRETTING             |
| SW82332070-243   | 289m       | 329m     | ROAD_MARKINGS_HATCHED | Wear (for example erosion) (WEAR)    | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-446   | 3m         | 103m     | ROAD_MARKINGS_LONG    | Wear (for example erosion) (WEAR)    | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description   |
|--|---------|--------|-------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|--|
| SW82332070-447   | 70m     | 35m    | ROAD_STUDS  | Missing (MISS)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-452   | 227m    | 227m   | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 January 2019</b>  |         |        |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 January 2019</b>  |         |        |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 January 2019</b>  |         |        |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 January 2019</b>  |         |        |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 January 2019</b>  |         |        |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 February 2019</b> |         |        |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 February 2019</b> |         |        |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 February 2019</b> |         |        |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 February 2019</b> |         |        |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 February 2019</b> |         |        |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 February 2019</b> |         |        |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 February 2019</b> |         |        |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 February 2019</b> |         |        |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 March 2019</b>    |         |        |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 March 2019</b>    |         |        |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 March 2019</b>    |         |        |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 March 2019</b>    |         |        |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 March 2019</b>    |         |        |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 March 2019</b>    |         |        |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 March 2019</b>    |         |        |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 March 2019</b>    |         |        |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2019</b>    |         |        |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>11650/41 : AGAINST: EAST LODGE TO SYMINGTON SB</b>                      |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 January 2018</b>  |         |        |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018</b>  |         |        |             |                                      |                 |                          |                       |                 |  |
| SW82317357-235513859   | 2,457m  | 2,457m | CARRIAGEWAY | Pothole (POTH)                       | CAT 1           | 02/02/2018               | Completed Defects     | 31/01/2018      | A77 N/B LANE1 AND CENTRELINE 40M NORTH OF COTAGESNORTH OFSYMINGTON ON SLIP |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 January 2018</b>  |         |        |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018</b>  |         |        |             |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 January 2018</b>  |         |        |             |                                      |                 |                          |                       |                 |  |
| SW82317632-235520464   | 2,456m  | 2,457m | CARRIAGEWAY | Pothole (POTH)                       | CAT 1           | 13/02/2018               | Completed Defects     | 31/01/2018      | LANE 1 200meters north of the symington nb on slip at cottages             |



| Defect Reference   | Start<br>m | End<br>m | Item Type   | Item Detail              | Defect<br>Category | Required<br>Completion Date | Current Status       | Completion<br>Date | Location Description  |
|--|------------|----------|-------------|--------------------------|--------------------|-----------------------------|----------------------|--------------------|---|
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018</b>  |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 January 2018</b>  |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018</b>  |            |          |             |                          |                    |                             |                      |                    |   |
| SW82317812-235529552   | 878m       | 880m     | CARRIAGEWAY | Pothole<br>(POTH)        | CAT 1              | 23/02/2018                  | Completed<br>Defects | 09/02/2018         | A77 NB CW, AT BOG END<br>TOLL NB ON SLIP  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 January 2018</b>  |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018</b> |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 February 2018</b> |            |          |             |                          |                    |                             |                      |                    |   |
| SW82318894-235534933   | 2,590m     | 2,590m   | CARRIAGEWAY | Pothole<br>(POTH)        | CAT 1              | 06/03/2018                  | Completed<br>Defects | 07/02/2018         | A77 NB CW, LANE 1, 100M<br>NTH OF SYMINGTON ONSLIP                              |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018</b> |            |          |             |                          |                    |                             |                      |                    |   |
| SW82319109-235534716   | 2,447m     | 2,450m   | CARRIAGEWAY | Pothole<br>(POTH)        | CAT 1              | 09/03/2018                  | Completed<br>Defects | 09/02/2018         | A77 NB CW, ON CL, 300M NTH<br>OF SYMINGTON NB ONSLIP                            |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 February 2018</b> |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018</b> |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 February 2018</b> |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018</b> |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 February 2018</b> |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018</b>    |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 March 2018</b>    |            |          |             |                          |                    |                             |                      |                    |   |
| SW82325502-235553035   | 2,463m     | 2,863m   | CARRIAGEWAY | Pothole<br>(POTH)        | CAT 1              | 03/04/2018                  | Completed<br>Defects | 07/03/2018         | A77 NB CW, ON CL, 500M NTH<br>OF SYMINGTON ONSLIP, TO<br>200M STH HALFWAY HOUSE |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018</b>    |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 March 2018</b>    |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018</b>    |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 March 2018</b>    |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018</b>    |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 March 2018</b>    |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2018</b>    |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 April 2018</b>    |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 April 2018</b>    |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 April 2018</b>    |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 April 2018</b>    |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 April 2018</b>    |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 April 2018</b>    |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 April 2018</b>    |            |          |             |                          |                    |                             |                      |                    |   |
| SW82340437-235634095   | 2,067m     | 2,067m   | CARRIAGEWAY | Pothole VIAFIX<br>(POTV) | CAT 1              | 25/04/2018                  | Completed<br>Defects | 24/04/2018         | M77 N/B @ LAMP POST<br>GG5711 @ LAND FOR SALE<br>SIGN                           |

| Defect Reference  | Start m | End m  | Item Type       | Item Detail                   | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description  |
|---|---------|--------|-----------------|-------------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| SW82340437-235634094  | 2,184m  | 2,184m | CARRIAGEWAY     | Pothole VIAFIX (POTV)         | CAT 1           | 25/04/2018               | Completed Defects     | 24/04/2018      | M77 N/B @LAMP POST<br>GG5709 @ HOUSE NO 15  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 April 2018</b><br>No defects recorded<br><b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 01 May 2018</b><br>No defects recorded<br><b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 May 2018</b><br>No defects recorded<br><b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 May 2018</b><br>No defects recorded<br><b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 May 2018</b>   |         |        |                 |                               |                 |                          |                       |                 |   |
| SW82347347-235785071  | 104m    | 106m   | CARRIAGEWAY     | Debris in traffic Lane (DBTL) | CAT 1           | 08/06/2018               | Completed Defects     | 11/05/2018      | A77 SB CW, AT BUS STOP<br>PRIOR TO 50MPH<br>RESTRICTION ZONE STH OF<br>KILMARNOCK |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 May 2018</b>   |         |        |                 |                               |                 |                          |                       |                 |   |
| SW82348955-235802353  | 469m    | 470m   | GULLY           | Other (OTHR)                  | CAT 1           | 16/05/2018               | Completed Defects     | 15/05/2018      | A77 SB 300M PRIOR TO<br>BOGEND TOLL   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 May 2018</b>   |         |        |                 |                               |                 |                          |                       |                 |   |
| SW82350359-235785070  | 796m    | 797m   | GULLY           | Other (OTHR)                  | CAT 1           | 19/05/2018               | Completed Defects     | 18/05/2018      | A77 SB AT START OF SLIP<br>BOGEND TOLL  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 May 2018</b><br>No defects recorded<br><b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 May 2018</b><br>No defects recorded<br><b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 May 2018</b><br>No defects recorded<br><b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 June 2018</b><br>No defects recorded<br><b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 June 2018</b><br>No defects recorded<br><b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 June 2018</b><br>No defects recorded<br><b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 June 2018</b><br>No defects recorded<br><b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 June 2018</b><br>No defects recorded<br><b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 June 2018</b> |         |        |                 |                               |                 |                          |                       |                 |   |
| SW82366110-235861180  | 1,410m  | 1,411m | CENTRAL_RESERVE | Debris in traffic Lane (DBTL) | CAT 1           | 20/06/2018               | Completed Defects     | 19/06/2018      | A77 NB CW CENTRE<br>RESERVE OPPOSITE SPICE<br>ROUTE                               |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 June 2018</b><br>No defects recorded<br><b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 June 2018</b><br>No defects recorded<br><b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018</b>  |         |        |                 |                               |                 |                          |                       |                 |   |
| SW86-357205-1   | 1,421m  | 1,431m | WOODLAND        | Invasive species (INVS)       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 June 2018</b><br>No defects recorded<br><b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 July 2018</b><br>No defects recorded<br><b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 July 2018</b><br>No defects recorded<br><b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 July 2018</b><br>No defects recorded<br><b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 July 2018</b>  |         |        |                 |                               |                 |                          |                       |                 |   |
| SW82377861-235874035  | 692m    | 693m   | GULLY           | Collapsed (COLP)              | CAT 1           | 10/08/2018               | Completed Defects     | 13/07/2018      | A77 SB CW, AT NTH END OG<br>BOGEND TOLL SB OFFSLIP                                |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 July 2018</b><br>No defects recorded<br><b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 July 2018</b>   |         |        |                 |                               |                 |                          |                       |                 |   |

| Defect Reference  | Start m | End m  | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                            |
|---|---------|--------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|---|
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 July 2018</b>      |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 July 2018</b>      |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 July 2018</b>      |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 03 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 10 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 14 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 17 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 21 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| SW80-396340-235971031   | 894m    | 2,890m | CARRIAGEWAY | Litter Grade D (LITD) | 3RD PTY         | 22/08/2018               | Completed Defects | 14/09/2018      | A77 ON CENTRE RES FROM BOGEND TOLL TO SYMINGTON |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 24 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 28 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 31 August 2018</b>    |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 September 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 ( Awaiting Return )</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| SW80-404397-236051812   | 474m    | 475m   | GULLY       | Other (OTHR)          | CAT 1           | 08/09/2018               | Completed Defects | 07/09/2018      | A77 N/B LANE 1 500M NORTH OF BOGEND TOLL        |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 September 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 14 September 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 September 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 September 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 25 September 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 September 2018</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 October 2018</b>   |         |        |             |                       |                 |                          |                   |                 |   |
| SW82416069-236108732  | 786m    | 786m   | GULLY       | Other (OTHR)          | CAT 1           | 03/10/2018               | Completed Defects | 02/10/2018      | A77 SB CW BOGEND TOLL OFF SLIP                  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 October 2018</b>   |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 October 2018</b>   |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 October 2018</b>   |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 October 2018</b>   |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 October 2018</b>   |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 October 2018</b>   |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 October 2018</b>   |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 October 2018</b>   |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 November 2018</b>  |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |

| Defect Reference   | Start<br>m | End<br>m | Item Type              | Item Detail                                | Defect<br>Category | Required<br>Completion Date | Current Status           | Completion<br>Date | Location Description  |
|--|------------|----------|------------------------|--|--------------------|-----------------------------|--------------------------|--------------------|---|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 November 2018</b><br><i>No defects recorded</i> |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 November 2018</b><br><i>No defects recorded</i> |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 November 2018</b><br><i>No defects recorded</i> |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 November 2018</b><br><i>No defects recorded</i> |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 November 2018</b>                               |            |          |                        |  |                    |                             |                          |                    |   |
| SW82426735-236231056   | 373m       | 375m     | CARRIAGEWAY            | Pothole<br>(POTH)                          | CAT 1              | 18/12/2018                  | Completed<br>Defects     | 21/11/2018         | A77 NB CW AT NATIONAL<br>SPEED LIMIT SIGN 150M<br>NORTH OF BOGEND TOLL ON<br>SLIP |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 November 2018</b><br><i>No defects recorded</i> |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 November 2018</b><br><i>No defects recorded</i> |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 30 November 2018</b><br><i>No defects recorded</i> |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 December 2018</b><br><i>No defects recorded</i> |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 07 December 2018</b>                               |            |          |                        |  |                    |                             |                          |                    |   |
| SW82427232-236257452   | 477m       | 477m     | GULLY                  | Other (OTHR)                               | CAT 1              | 04/01/2019                  | Completed<br>Defects     | 07/12/2018         | A77 NB CW, 300M STH OF<br>EAST LODGE  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 December 2018</b><br><i>No defects recorded</i> |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 14 December 2018</b><br><i>No defects recorded</i> |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018</b>                                 |            |          |                        |  |                    |                             |                          |                    |   |
| SW82332070-214   | 345m       | 355m     | CARRIAGEWAY            | Bituminous<br>surfacing<br>fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |   |
| SW82332070-231   | 66m        | 67m      | CARRIAGEWAY            | Pothole<br>(POTH)                          | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |   |
| SW82332070-213   | 352m       | 353m     | CARRIAGEWAY            | Pothole<br>(POTH)                          | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |   |
| SW82332070-135   | 805m       | 807m     | CARRIAGEWAY            | Localised<br>cracking<br>(LOCK)            | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |   |
| SW82332070-455   | 279m       | 279m     | CARRIAGEWAY            | Bituminous<br>surfacing<br>fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |   |
| SW82332070-226   | 163m       | 164m     | CARRIAGEWAY            | Pothole<br>(POTH)                          | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |   |
| SW82332070-222   | 246m       | 247m     | MANHOLE                | Other (OTHR)                               | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |   |
| SW82332070-221   | 245m       | 265m     | CARRIAGEWAY            | Bituminous<br>surfacing<br>fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |   |
| SW82332070-456   | 284m       | 294m     | ROAD_MARKINGS<br>_LONG | Wear (for<br>example<br>erosion)<br>(WEAR) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |   |
| SW82332070-134   | 717m       | 817m     | CARRIAGEWAY            | Bituminous<br>surfacing<br>fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |   |
| SW82332070-136   | 1,081m     | 1,091m   | CARRIAGEWAY            | Bituminous<br>surfacing<br>fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |   |

| Defect Reference | Start<br>m | End<br>m | Item Type          | Item Detail                                  | Defect<br>Category | Required<br>Completion Date | Current Status        | Completion<br>Date | Location Description |
|------------------|------------|----------|--------------------|--|--------------------|-----------------------------|-----------------------|--------------------|----------------------|
| SW82332070-105   | 1,535m     | 1,545m   | FOOTWAY            | Bituminous surfacing - local cracking (BLCK) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-130   | 201m       | 301m     | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)         | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-132   | 417m       | 517m     | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)         | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-215   | 338m       | 339m     | CARRIAGEWAY        | Pothole (POTH)                               | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-229   | 120m       | 140m     | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)         | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-230   | 113m       | 114m     | CARRIAGEWAY        | Pothole (POTH)                               | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-223   | 213m       | 214m     | CARRIAGEWAY        | Pothole (POTH)                               | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-137   | 1,656m     | 1,666m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)         | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-454   | 54m        | 54m      | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)         | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-211   | 361m       | 461m     | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)            | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-220   | 259m       | 289m     | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)         | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-133   | 534m       | 535m     | CARRIAGEWAY        | Localised cracking (LOCK)                    | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-106   | 1,413m     | 1,513m   | FOOTWAY            | Overgrown by vegetation (OVGV)               | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-112   | 348m       | 448m     | CARRIAGEWAY        | Deep spalling at joints (DSPL)               | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-232   | 56m        | 57m      | MANHOLE            | Other (OTHR)                                 | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-212   | 366m       | 367m     | GULLY              | Other (OTHR)                                 | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-227   | 150m       | 151m     | TRAFFIC_SIGNS      | Damaged (DAMG)                               | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-453   | 1m         | 1m       | ROAD_STUDS         | Missing (MISS)                               | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-225   | 178m       | 180m     | CARRIAGEWAY        | Pothole (POTH)                               | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-131   | 361m       | 363m     | CARRIAGEWAY        | Localised cracking (LOCK)                    | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-108   | 824m       | 826m     | CARRIAGEWAY        | Localised cracking (LOCK)                    | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |

| Defect Reference   | Start m | End m | Item Type   | Item Detail               | Defect Category | Required Completion Date | Current Status               | Completion Date | Location Description                                       |
|--|---------|-------|-------------|---------------------------|-----------------|--------------------------|------------------------------|-----------------|--|
| SW82332070-111   | 481m    | 581m  | CARRIAGEWAY | Localised cracking (LOCK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action        | 01/01/9999      |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 December 2018</b> |         |       |             |                           |                 |                          |                              |                 |  |
| SW82427481-236264537   | 727m    | 729m  | CARRIAGEWAY | Pothole (POTH)            | CAT 1           | 15/01/2019               | Completed Defects            | 18/12/2018      | A77 NB CW AT END OF BOGEND TOLL ON SLIP                    |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 December 2018</b> |         |       |             |                           |                 |                          |                              |                 |  |
| No defects recorded  |         |       |             |                           |                 |                          |                              |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 December 2018</b> |         |       |             |                           |                 |                          |                              |                 |  |
| No defects recorded  |         |       |             |                           |                 |                          |                              |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 December 2018</b> |         |       |             |                           |                 |                          |                              |                 |  |
| No defects recorded  |         |       |             |                           |                 |                          |                              |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 December 2018</b> |         |       |             |                           |                 |                          |                              |                 |  |
| No defects recorded  |         |       |             |                           |                 |                          |                              |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 January 2019</b>  |         |       |             |                           |                 |                          |                              |                 |  |
| No defects recorded  |         |       |             |                           |                 |                          |                              |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 January 2019</b>  |         |       |             |                           |                 |                          |                              |                 |  |
| No defects recorded  |         |       |             |                           |                 |                          |                              |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 January 2019</b>  |         |       |             |                           |                 |                          |                              |                 |  |
| No defects recorded  |         |       |             |                           |                 |                          |                              |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 January 2019</b>  |         |       |             |                           |                 |                          |                              |                 |  |
| No defects recorded  |         |       |             |                           |                 |                          |                              |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 January 2019</b>  |         |       |             |                           |                 |                          |                              |                 |  |
| No defects recorded  |         |       |             |                           |                 |                          |                              |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 January 2019</b>  |         |       |             |                           |                 |                          |                              |                 |  |
| No defects recorded  |         |       |             |                           |                 |                          |                              |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 January 2019</b>  |         |       |             |                           |                 |                          |                              |                 |  |
| No defects recorded  |         |       |             |                           |                 |                          |                              |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 January 2019</b>  |         |       |             |                           |                 |                          |                              |                 |  |
| No defects recorded  |         |       |             |                           |                 |                          |                              |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 January 2019</b>  |         |       |             |                           |                 |                          |                              |                 |  |
| SW82428594-236291667   | 331m    | 333m  | CARRIAGEWAY | Pothole (POTH)            | CAT 1           | 26/02/2019               | Completed Defects            | 31/01/2019      | A77 NB CW ON CENTRE LINE 200M SOUTH OF EAST LODGE          |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 February 2019</b> |         |       |             |                           |                 |                          |                              |                 |  |
| No defects recorded  |         |       |             |                           |                 |                          |                              |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 February 2019</b> |         |       |             |                           |                 |                          |                              |                 |  |
| No defects recorded  |         |       |             |                           |                 |                          |                              |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 February 2019</b> |         |       |             |                           |                 |                          |                              |                 |  |
| SW82429570-236325469   | 799m    | 800m  | CARRIAGEWAY | Pothole VIAFIX (POTV)     | CAT 1           | 08/03/2019               | Completed Defects            | 08/02/2019      | A77 SB CW, LANE 1, AT BOGEND TOLL OFFSLIP                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 February 2019</b> |         |       |             |                           |                 |                          |                              |                 |  |
| No defects recorded  |         |       |             |                           |                 |                          |                              |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 February 2019</b> |         |       |             |                           |                 |                          |                              |                 |  |
| No defects recorded  |         |       |             |                           |                 |                          |                              |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 February 2019</b> |         |       |             |                           |                 |                          |                              |                 |  |
| No defects recorded  |         |       |             |                           |                 |                          |                              |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 February 2019</b> |         |       |             |                           |                 |                          |                              |                 |  |
| SW82433749-236325464   | 817m    | 817m  | CARRIAGEWAY | Litter Grade C (LITC)     | 3RD PTY         | 23/02/2019               | Awaiting CCMS Permanent Date | 01/01/9999      | Litter on verge  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 February 2019</b> |         |       |             |                           |                 |                          |                              |                 |  |
| SW82435554-236335868   | 335m    | 337m  | CARRIAGEWAY | Pothole (POTH)            | CAT 1           | 27/02/2019               | Completed Defects            | 26/02/2019      | A77 N/B 45M PRIOR TO KILMARNOCK 1/2 MILE SIGN              |
| SW82435554-236335865   | 455m    | 456m  | CARRIAGEWAY | Pothole (POTH)            | CAT 1           | 27/02/2019               | Completed Defects            | 26/02/2019      | A77 N/B 30M PRIOR TO NATIONAL SPEED LIMIT SIGN BOGEND TOLL |
| SW82435554-236335867   | 345m    | 347m  | CARRIAGEWAY | Pothole (POTH)            | CAT 1           | 27/02/2019               | Completed Defects            | 26/02/2019      | A77 N/B 50M PRIOR TO 1/2 MILE KILMARNOCK SIGN              |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 March 2019</b>    |         |       |             |                           |                 |                          |                              |                 |  |
| No defects recorded  |         |       |             |                           |                 |                          |                              |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 March 2019</b>    |         |       |             |                           |                 |                          |                              |                 |  |
| No defects recorded  |         |       |             |                           |                 |                          |                              |                 |  |

| Defect Reference  | Start<br>m | End<br>m | Item Type   | Item Detail    | Defect<br>Category | Required<br>Completion Date | Current Status    | Completion<br>Date | Location Description                              |
|---|------------|----------|-------------|----------------|--------------------|-----------------------------|-------------------|--------------------|---|
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 March 2019</b>                                   |            |          |             |                |                    |                             |                   |                    |   |
| No defects recorded   |            |          |             |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 March 2019</b>                                   |            |          |             |                |                    |                             |                   |                    |   |
| No defects recorded   |            |          |             |                |                    |                             |                   |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 March 2019</b>                                   |            |          |             |                |                    |                             |                   |                    |   |
| No defects recorded   |            |          |             |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 March 2019</b>                                   |            |          |             |                |                    |                             |                   |                    |   |
| No defects recorded   |            |          |             |                |                    |                             |                   |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 March 2019</b>                                   |            |          |             |                |                    |                             |                   |                    |   |
| No defects recorded   |            |          |             |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 March 2019</b>                                   |            |          |             |                |                    |                             |                   |                    |   |
| No defects recorded   |            |          |             |                |                    |                             |                   |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2019</b>                                   |            |          |             |                |                    |                             |                   |                    |   |
| No defects recorded   |            |          |             |                |                    |                             |                   |                    |   |
| <b>11650/09 : AGAINST: SYMINGTON SB TO DUTCH HOUSE RBT</b>  |            |          |             |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 January 2018</b>                                 |            |          |             |                |                    |                             |                   |                    |   |
| SW82317274-235513678  | 511m       | 514m     | CARRIAGEWAY | Pothole (POTH) | CAT 1              | 30/01/2018                  | Completed Defects | 02/02/2018         | A7 S/B ON CENTRE LINE OPPOSITE JCT HANSEL VILLAGE |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018</b>                                 |            |          |             |                |                    |                             |                   |                    |   |
| No defects recorded   |            |          |             |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 January 2018</b>                                 |            |          |             |                |                    |                             |                   |                    |   |
| SW82317440-235515661  | 643m       | 644m     | CARRIAGEWAY | Pothole (POTH) | CAT 1              | 06/02/2018                  | Completed Defects | 01/02/2018         | A77 SB CW, LANE 2, OUTSIDE HANSEL VILLAGE         |
| <b>Detailed Inspections - Category A Footways of A77 Hansel Village CATA Footways on 09 January 2018</b>  |            |          |             |                |                    |                             |                   |                    |   |
| No defects recorded   |            |          |             |                |                    |                             |                   |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018</b>                                 |            |          |             |                |                    |                             |                   |                    |   |
| No defects recorded   |            |          |             |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 January 2018</b>                                 |            |          |             |                |                    |                             |                   |                    |   |
| SW82317632-235520463  | 2,364m     | 2,365m   | CARRIAGEWAY | Pothole (POTH) | CAT 1              | 13/02/2018                  | Completed Defects | 31/01/2018         | 300 M NORTH OF DUTCHHOUSE RBT LANE 1              |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018</b>                                 |            |          |             |                |                    |                             |                   |                    |   |
| No defects recorded   |            |          |             |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 January 2018</b>                                 |            |          |             |                |                    |                             |                   |                    |   |
| No defects recorded   |            |          |             |                |                    |                             |                   |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018</b>                                 |            |          |             |                |                    |                             |                   |                    |   |
| No defects recorded   |            |          |             |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 January 2018</b>                                 |            |          |             |                |                    |                             |                   |                    |   |
| No defects recorded   |            |          |             |                |                    |                             |                   |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018</b>                                |            |          |             |                |                    |                             |                   |                    |   |
| No defects recorded   |            |          |             |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 February 2018</b>                                |            |          |             |                |                    |                             |                   |                    |   |
| No defects recorded   |            |          |             |                |                    |                             |                   |                    |   |
| <b>Detailed Inspections - Category A Footways of A77 Hansel Village CATA Footways on 06 February 2018</b> |            |          |             |                |                    |                             |                   |                    |   |
| No defects recorded   |            |          |             |                |                    |                             |                   |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018</b>                                |            |          |             |                |                    |                             |                   |                    |   |
| No defects recorded   |            |          |             |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 February 2018</b>                                |            |          |             |                |                    |                             |                   |                    |   |
| SW82319390-235542962  | 2,103m     | 2,104m   | CARRIAGEWAY | Pothole (POTH) | CAT 1              | 13/03/2018                  | Completed Defects | 13/02/2018         | A77 SB CW LANE 1, 500M NTH OF DUTCH HOUSE RBT     |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018</b>                                |            |          |             |                |                    |                             |                   |                    |   |
| No defects recorded   |            |          |             |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 February 2018</b>                                |            |          |             |                |                    |                             |                   |                    |   |
| No defects recorded   |            |          |             |                |                    |                             |                   |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018</b>                                |            |          |             |                |                    |                             |                   |                    |   |
| No defects recorded   |            |          |             |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 February 2018</b>                                |            |          |             |                |                    |                             |                   |                    |   |
| No defects recorded   |            |          |             |                |                    |                             |                   |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018</b>                                   |            |          |             |                |                    |                             |                   |                    |   |
| No defects recorded   |            |          |             |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 March 2018</b>                                   |            |          |             |                |                    |                             |                   |                    |   |
| No defects recorded   |            |          |             |                |                    |                             |                   |                    |   |
| <b>Detailed Inspections - Category A Footways of A77 Hansel Village CATA Footways on 06 March 2018</b>    |            |          |             |                |                    |                             |                   |                    |   |

| Defect Reference   | Start m | End m | Item Type   | Item Detail    | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description         |
|--|---------|-------|-------------|----------------|-----------------|--------------------------|-------------------|-----------------|------------------------------|
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |                              |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 09 March 2018                                |         |       |             |                |                 |                          |                   |                 |                              |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |                              |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 March 2018</b>                                |         |       |             |                |                 |                          |                   |                 |                              |
| SW82327521-235576666   | 608m    | 610m  | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 10/04/2018               | Completed Defects | 14/03/2018      | A77 SB CW, AT HANSEL VILLAGE |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 16 March 2018                                |         |       |             |                |                 |                          |                   |                 |                              |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |                              |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 March 2018</b>                                |         |       |             |                |                 |                          |                   |                 |                              |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |                              |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 23 March 2018                                |         |       |             |                |                 |                          |                   |                 |                              |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |                              |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 March 2018</b>                                |         |       |             |                |                 |                          |                   |                 |                              |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |                              |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 29 March 2018                                |         |       |             |                |                 |                          |                   |                 |                              |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |                              |
| <b>Detailed Inspections - Category A Footways of A77 Hansel Village CATA Footways on 03 April 2018</b> |         |       |             |                |                 |                          |                   |                 |                              |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |                              |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 April 2018</b>                                |         |       |             |                |                 |                          |                   |                 |                              |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |                              |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 06 April 2018                                |         |       |             |                |                 |                          |                   |                 |                              |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |                              |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 April 2018</b>                                |         |       |             |                |                 |                          |                   |                 |                              |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |                              |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 13 April 2018                                |         |       |             |                |                 |                          |                   |                 |                              |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |                              |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 April 2018</b>                                |         |       |             |                |                 |                          |                   |                 |                              |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |                              |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 20 April 2018                                |         |       |             |                |                 |                          |                   |                 |                              |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |                              |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 April 2018</b>                                |         |       |             |                |                 |                          |                   |                 |                              |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |                              |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 27 April 2018                                |         |       |             |                |                 |                          |                   |                 |                              |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |                              |
| <b>Detailed Inspections - Category A Footways of A77 Hansel Village CATA Footways on 01 May 2018</b>   |         |       |             |                |                 |                          |                   |                 |                              |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |                              |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 01 May 2018</b>                                  |         |       |             |                |                 |                          |                   |                 |                              |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |                              |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 04 May 2018                                  |         |       |             |                |                 |                          |                   |                 |                              |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |                              |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 May 2018</b>                                  |         |       |             |                |                 |                          |                   |                 |                              |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |                              |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 11 May 2018                                  |         |       |             |                |                 |                          |                   |                 |                              |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |                              |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 May 2018</b>                                  |         |       |             |                |                 |                          |                   |                 |                              |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |                              |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 18 May 2018                                  |         |       |             |                |                 |                          |                   |                 |                              |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |                              |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 May 2018</b>                                  |         |       |             |                |                 |                          |                   |                 |                              |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |                              |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 25 May 2018                                  |         |       |             |                |                 |                          |                   |                 |                              |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |                              |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 May 2018</b>                                  |         |       |             |                |                 |                          |                   |                 |                              |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |                              |
| <b>Detailed Inspections - Category A Footways of A77 Hansel Village CATA Footways on 01 June 2018</b>  |         |       |             |                |                 |                          |                   |                 |                              |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |                              |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 01 June 2018                                 |         |       |             |                |                 |                          |                   |                 |                              |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |                              |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 June 2018</b>                                 |         |       |             |                |                 |                          |                   |                 |                              |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |                              |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 08 June 2018                                 |         |       |             |                |                 |                          |                   |                 |                              |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |                              |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 June 2018</b>                                 |         |       |             |                |                 |                          |                   |                 |                              |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |                              |
| <b>Safety Patrol of A77 Ayr North</b> Safety Patrol V1 on 15 June 2018                                 |         |       |             |                |                 |                          |                   |                 |                              |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |                              |



| Defect Reference  | Start m | End m  | Item Type | Item Detail                                  | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description  |
|---|---------|--------|-----------|--|-----------------|--------------------------|-----------------------|-----------------|---|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 June 2018</b>                                |         |        |           |  |                 |                          |                       |                 |   |
| No defects recorded   |         |        |           |  |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 June 2018</b>                                |         |        |           |  |                 |                          |                       |                 |   |
| SW80-367730-235862803   | 1,589m  | 1,590m | GULLY     | Cracked or broken (IBCK)                     | CAT 1           | 20/07/2018               | Completed Defects     | 29/06/2018      | A77 SB CW 25M PRIOR TO LAST BUS STOP BEFORE DUTCH HOUSE RBT |
| <b>Detailed Inspections - Category A Footways of A77 Hansel Village CATA Footways on 26 June 2018</b> |         |        |           |  |                 |                          |                       |                 |   |
| SW82368225-1  | 2,209m  | 2,409m | FOOTWAY   | Overgrown by vegetation (OVGV)               | CAT 1           | 24/07/2018               | Completed Defects     | 05/07/2018      | A77 NB CW 500M NORTH OF DUTCH HOUSE RBT                     |
| SW82368225-3  | 2,017m  | 2,018m | FOOTWAY   | Overgrown by vegetation (OVGV)               | CAT 1           | 24/07/2018               | Completed Defects     | 26/06/2018      | A77 NB CW 25M AFTER HILLHOUSE JCT                           |
| SW82368225-7  | 753m    | 763m   | FOOTWAY   | Overgrown by vegetation (OVGV)               | CAT 1           | 24/07/2018               | Completed Defects     | 26/06/2018      | A77 SB CW 10M AFTER HANSEL VILLAGE BUS STOP                 |
| SW82368225-2  | 2,103m  | 2,104m | FOOTWAY   | Overgrown by vegetation (OVGV)               | CAT 1           | 24/07/2018               | Completed Defects     | 26/06/2018      | A77 NB CW 25M PRIOR TO HILLHOUSE JCT                        |
| SW82368225-5  | 1,108m  | 1,109m | FOOTWAY   | Overgrown by vegetation (OVGV)               | CAT 1           | 24/07/2018               | Completed Defects     | 26/06/2018      | A77 NB CW 780M PRIOR TO HANSEL VILLAGE FOOTBRIDGE           |
| SW82368225-8  | 771m    | 801m   | FOOTWAY   | Overgrown by vegetation (OVGV)               | CAT 1           | 24/07/2018               | Completed Defects     | 26/06/2018      | A77 SB CW 25M AFTER HANSEL VILLAGE BUS STOP                 |
| SW82368225-9  | 1,581m  | 1,591m | FOOTWAY   | Overgrown by vegetation (OVGV)               | CAT 1           | 24/07/2018               | Completed Defects     | 26/06/2018      | A77 SB CW 25M PRIOR TO LAST BUS STOP BEFORE DUTCH HOUSE RBT |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 June 2018</b>                                |         |        |           |  |                 |                          |                       |                 |   |
| No defects recorded   |         |        |           |  |                 |                          |                       |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018</b>                                  |         |        |           |  |                 |                          |                       |                 |   |
| No defects recorded   |         |        |           |  |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 June 2018</b>                                |         |        |           |  |                 |                          |                       |                 |   |
| No defects recorded   |         |        |           |  |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 July 2018</b>                                |         |        |           |  |                 |                          |                       |                 |   |
| No defects recorded   |         |        |           |  |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 July 2018</b>                                |         |        |           |  |                 |                          |                       |                 |   |
| No defects recorded   |         |        |           |  |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 July 2018</b>                                |         |        |           |  |                 |                          |                       |                 |   |
| SW82376428-235909718  | 1,094m  | 1,095m | FOOTWAY   | Other (OTHR)                                 | 3RD PTY         | 07/08/2018               | Completed Defects     | 28/08/2018      | A77 ON FOOTWAY JUST OF SB CW 250M AFTER HANSEL VILLAGE      |
| SW82376428-235909727  | 1,088m  | 1,098m | FOOTWAY   | Bituminous surfacing - local cracking (BLCK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | A77 SB CW 250M AFTER HANSEL VILLAGE                         |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 July 2018</b>                                |         |        |           |  |                 |                          |                       |                 |   |
| SW82377861-235874034  | 2,323m  | 2,324m | GULLY     | Collapsed (COLP)                             | CAT 1           | 10/08/2018               | Completed Defects     | 07/08/2018      | A77 SB CW, 310M NTH OF DUTCH HOUSE RBT                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 July 2018</b>                                |         |        |           |  |                 |                          |                       |                 |   |
| No defects recorded   |         |        |           |  |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 July 2018</b>                                |         |        |           |  |                 |                          |                       |                 |   |
| SW82381111-235914467  | 561m    | 562m   | GULLY     | Cracked or broken (IBCK)                     | CAT 1           | 17/08/2018               | Completed Defects     | 17/08/2018      | A77 NB CW 100M AFTER HANSEL VILLAGE FOOTWAY                 |
| <b>Detailed Inspections - Category A Footways of A77 Hansel Village CATA Footways on 24 July 2018</b> |         |        |           |  |                 |                          |                       |                 |   |
| No defects recorded   |         |        |           |  |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 July 2018</b>                                |         |        |           |  |                 |                          |                       |                 |   |
| No defects recorded   |         |        |           |  |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 July 2018</b>                                |         |        |           |  |                 |                          |                       |                 |   |
| SW82384352-235917903  | 1,201m  | 1,202m | GULLY     | Blockage (BLOK)                              | CAT 1           | 24/08/2018               | Completed Defects     | 07/08/2018      | A77 SB CW 200M AFTER LADYKIRK JCT                           |

| Defect Reference   | Start<br>m | End<br>m | Item Type      | Item Detail                          | Defect<br>Category | Required<br>Completion Date | Current Status           | Completion<br>Date | Location Description   |
|--|------------|----------|----------------|--------------------------------------|--------------------|-----------------------------|--------------------------|--------------------|--|
| SW82384352-235917905   | 2,653m     | 2,654m   | GULLY          | Other (OTHR)                         | CAT 1              | 24/08/2018                  | Completed<br>Defects     | 27/07/2018         | A77 DUTCH HOUSE RBT  |
| SW82384352-235917904   | 1,961m     | 1,962m   | GULLY          | Blockage<br>(BLOK)                   | CAT 1              | 24/08/2018                  | Completed<br>Defects     | 07/08/2018         | A77 SB CW OUTSIDE<br>ROSEMONT RIDING SCHOOL                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 July 2018</b>                                     |            |          |                |                                      |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                |                                      |                    |                             |                          |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 03 August 2018</b>                                   |            |          |                |                                      |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                |                                      |                    |                             |                          |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 August 2018</b>                                   |            |          |                |                                      |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                |                                      |                    |                             |                          |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 10 August 2018</b>                                   |            |          |                |                                      |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                |                                      |                    |                             |                          |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 14 August 2018</b>                                   |            |          |                |                                      |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                |                                      |                    |                             |                          |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 17 August 2018</b>                                   |            |          |                |                                      |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                |                                      |                    |                             |                          |                    |  |
| <b>Detailed Inspections - Category A Footways of A77 Hansel Village CATA Footways on 21 August 2018</b>    |            |          |                |                                      |                    |                             |                          |                    |  |
| SW80-394975-1  | 1,066m     | 1,166m   | CYCLE_FACILITY | Other (OTHR)                         | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         | A77 S/B AT SLIP ROAD<br>SOUTH OF HANSEL VILLAGE              |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 21 August 2018</b>                                   |            |          |                |                                      |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                |                                      |                    |                             |                          |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 24 August 2018</b>                                   |            |          |                |                                      |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                |                                      |                    |                             |                          |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 28 August 2018</b>                                   |            |          |                |                                      |                    |                             |                          |                    |  |
| SW80-399552-235979798  | 573m       | 580m     | CARRIAGEWAY    | Other (OTHR)                         | CAT 1              | 25/09/2018                  | Completed<br>Defects     | 28/08/2018         | A77 S/B ON CENTRE LINE<br>20M SOUTH OF JCT HANSEL<br>VILLAGE |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 31 August 2018</b>                                   |            |          |                |                                      |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                |                                      |                    |                             |                          |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 September 2018</b>                                |            |          |                |                                      |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                |                                      |                    |                             |                          |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 ( Awaiting Return )</b>                                 |            |          |                |                                      |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                |                                      |                    |                             |                          |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 September 2018</b>                                |            |          |                |                                      |                    |                             |                          |                    |  |
| SW82406268-236054636   | 1,104m     | 1,104m   | GULLY          | Other (OTHR)                         | CAT 1              | 12/09/2018                  | Completed<br>Defects     | 11/09/2018         | A77 N/B 800M NORTH OF<br>DUTCHHOUSE RBT                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 14 September 2018</b>                                |            |          |                |                                      |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                |                                      |                    |                             |                          |                    |  |
| <b>Detailed Inspections - Category A Footways of A77 Hansel Village CATA Footways on 18 September 2018</b> |            |          |                |                                      |                    |                             |                          |                    |  |
| SW82408073-1   | 740m       | 755m     | FOOTWAY        | Overgrown by<br>vegetation<br>(OVGV) | CAT 1              | 19/09/2018                  | Completed<br>Defects     | 18/09/2018         | A77 SB JUST OUTSIDE<br>HANSEL VILLAGE                        |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 September 2018</b>                                |            |          |                |                                      |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                |                                      |                    |                             |                          |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 September 2018</b>                                |            |          |                |                                      |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                |                                      |                    |                             |                          |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 25 September 2018</b>                                |            |          |                |                                      |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                |                                      |                    |                             |                          |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 September 2018</b>                                |            |          |                |                                      |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                |                                      |                    |                             |                          |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 October 2018</b>                                  |            |          |                |                                      |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                |                                      |                    |                             |                          |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 October 2018</b>                                  |            |          |                |                                      |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                |                                      |                    |                             |                          |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 October 2018</b>                                  |            |          |                |                                      |                    |                             |                          |                    |  |
| SW82419282-236112150   | 206m       | 206m     | GULLY          | Other (OTHR)                         | CAT 1              | 10/10/2018                  | Completed<br>Defects     | 09/10/2018         | A77 NB CW 200M PRIOR TO<br>SYMINGTON OFF SLIP                |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 October 2018</b>                                  |            |          |                |                                      |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                |                                      |                    |                             |                          |                    |  |
| <b>Detailed Inspections - Category A Footways of A77 Hansel Village CATA Footways on 16 October 2018</b>   |            |          |                |                                      |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                |                                      |                    |                             |                          |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 October 2018</b>                                  |            |          |                |                                      |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                |                                      |                    |                             |                          |                    |  |

| Defect Reference  | Start m | End m  | Item Type   | Item Detail                                  | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description  |
|---|---------|--------|-------------|--|-----------------|--------------------------|-----------------------|-----------------|---|
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 October 2018</b>                                 |         |        |             |  |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |        |             |  |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 October 2018</b>                                 |         |        |             |  |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |        |             |  |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 October 2018</b>                                 |         |        |             |  |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |        |             |  |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 October 2018</b>                                 |         |        |             |  |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |        |             |  |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 November 2018</b>                                |         |        |             |  |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |        |             |  |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 November 2018</b>                                |         |        |             |  |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |        |             |  |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 November 2018</b>                                |         |        |             |  |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |        |             |  |                 |                          |                       |                 |   |
| <b>Detailed Inspections - Category A Footways of A77 Hansel Village CATA Footways on 09 November 2018</b> |         |        |             |  |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |        |             |  |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 November 2018</b>                                |         |        |             |  |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |        |             |  |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 November 2018</b>                                |         |        |             |  |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |        |             |  |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 November 2018</b>                                |         |        |             |  |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |        |             |  |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 November 2018</b>                                |         |        |             |  |                 |                          |                       |                 |   |
| SW82426775-236232767  | 735m    | 737m   | CARRIAGEWAY | Pothole (POTH)                               | CAT 1           | 21/12/2018               | Completed Defects     | 24/11/2018      | A77 SB CW ON THE INSIDE LANE OUTSIDE ENTRANCE TO HANSEL VILLAGE |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 November 2018</b>                                |         |        |             |  |                 |                          |                       |                 |   |
| SW82426853-236234056  | 537m    | 538m   | CARRIAGEWAY | Pothole (POTH)                               | CAT 1           | 25/12/2018               | Completed Defects     | 28/11/2018      | A77 SB CW ON INSIDE LANE AT ENTRANCE TO HANSEL VILLAGE          |
| SW82426853-236234058  | 533m    | 534m   | CARRIAGEWAY | Pothole (POTH)                               | CAT 1           | 25/12/2018               | Completed Defects     | 28/11/2018      | A77 SB CW AT OVERBRIDGE 25M FROM HANSEL VILLAGE ENTRANCE        |
| SW82426853-236234057  | 549m    | 550m   | CARRIAGEWAY | Pothole (POTH)                               | CAT 1           | 25/12/2018               | Completed Defects     | 28/11/2018      | A77 SB CW ON INSIDE LANE AT ENTRANCE TO HANSEL VILLAGE          |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 30 November 2018</b>                                |         |        |             |  |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |        |             |  |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 December 2018</b>                                |         |        |             |  |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |        |             |  |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 07 December 2018</b>                                |         |        |             |  |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |        |             |  |                 |                          |                       |                 |   |
| <b>Detailed Inspections - Category A Footways of A77 Hansel Village CATA Footways on 11 December 2018</b> |         |        |             |  |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |        |             |  |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 December 2018</b>                                |         |        |             |  |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |        |             |  |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 14 December 2018</b>                                |         |        |             |  |                 |                          |                       |                 |   |
| SW82427393-236262789  | 1,882m  | 1,882m | GULLY       | Other (OTHR)                                 | CAT 1           | 15/12/2018               | Completed Defects     | 14/12/2018      | A77 S/B 500M SOUTH OF HANSEL VILLAGE                            |
| SW82427393-236262788  | 536m    | 537m   | CARRIAGEWAY | Pothole VIAFIX (POTV)                        | CAT 1           | 11/01/2019               | Completed Defects     | 14/12/2018      | A77 S/B LANE 2 20M SOUTH OF JCT HANSEL VILLAGE                  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018</b>                                  |         |        |             |  |                 |                          |                       |                 |   |
| SW82332070-87   | 970m    | 975m   | FOOTWAY     | Bituminous surfacing - local cracking (BLCK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332070-116  | 1,816m  | 1,916m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332070-85   | 1,082m  | 1,083m | CARRIAGEWAY | Localised cracking (LOCK)                    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |

| Defect Reference | Start m | End m  | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|--------|-------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82332070-113   | 198m    | 298m   | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-84    | 1,104m  | 1,204m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-140   | 688m    | 698m   | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-141   | 893m    | 903m   | CARRIAGEWAY | Opening of longitudinal joint (OLJT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-77    | 1,887m  | 1,997m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-115   | 867m    | 937m   | CARRIAGEWAY | Deep spalling at joints (DSPL)       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-81    | 1,225m  | 1,335m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-86    | 998m    | 1,088m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-99    | 428m    | 438m   | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-101   | 233m    | 333m   | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-90    | 902m    | 802m   | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-114   | 475m    | 575m   | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-142   | 2,356m  | 2,406m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-117   | 2,079m  | 2,179m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-138   | 363m    | 393m   | CARRIAGEWAY | Opening of longitudinal joint (OLJT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-139   | 688m    | 698m   | CARRIAGEWAY | Opening of longitudinal joint (OLJT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-79    | 1,453m  | 1,653m | FOOTWAY     | Excessive muck (MUCK)                | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |

**Safety Inspection of A76 & A77 Ayr North V1 on 18 December 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 December 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 24 December 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 December 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 31 December 2018**

No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 January 2019**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 07 January 2019**

No defects recorded

| Defect Reference  | Start<br>m | End<br>m | Item Type   | Item Detail                                      | Defect<br>Category | Required<br>Completion Date | Current Status          | Completion<br>Date | Location Description  |
|---|------------|----------|-------------|--|--------------------|-----------------------------|-------------------------|--------------------|---|
| <b>Detailed Inspections - Category A Footways of A77 Hansel Village CATA Footways on 08 January 2019</b>  |            |          |             |  |                    |                             |                         |                    |   |
| SW82427925-1  | 1,085m     | 1,185m   | FOOTWAY     | Other (OTHR)                                     | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action   | 01/01/9999         | A77 SOUTH OF LADY KIRK JCT  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 January 2019</b>                                 |            |          |             |  |                    |                             |                         |                    |   |
| No defects recorded   |            |          |             |  |                    |                             |                         |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 January 2019</b>                                 |            |          |             |  |                    |                             |                         |                    |   |
| No defects recorded   |            |          |             |  |                    |                             |                         |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 January 2019</b>                                 |            |          |             |  |                    |                             |                         |                    |   |
| SW82428194-236279608  | 651m       | 655m     | CARRIAGEWAY | Pothole (POTH)                                   | CAT 1              | 12/02/2019                  | Completed Defects       | 16/01/2019         | A77 UNDERNEATH HANSELVILLAGE FOOTBRIDGE SB CW ON CENTRE LINE                  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 January 2019</b>                                 |            |          |             |  |                    |                             |                         |                    |   |
| No defects recorded   |            |          |             |  |                    |                             |                         |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 January 2019</b>                                 |            |          |             |  |                    |                             |                         |                    |   |
| No defects recorded   |            |          |             |  |                    |                             |                         |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 January 2019</b>                                 |            |          |             |  |                    |                             |                         |                    |   |
| SW82428408-236287021  | 1,195m     | 1,196m   | CARRIAGEWAY | Pothole (POTH)                                   | CAT 1              | 22/02/2019                  | Completed Defects       | 26/01/2019         | A77 N/B LANE 1 10M NORTH OF 2ND AVERAGE SPEED CAMERA NORTH OF DUTCH HOUSE RBT |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 January 2019</b>                                 |            |          |             |  |                    |                             |                         |                    |   |
| SW82428594-236291664  | 1,214m     | 1,215m   | CARRIAGEWAY | Pothole (POTH)                                   | CAT 1              | 26/02/2019                  | Completed Defects       | 30/01/2019         | A77 NB CW 500M SOUTH OF HANSEL OVERBRIDGE                                     |
| SW82428594-236291691  | 541m       | 546m     | CARRIAGEWAY | Pothole (POTH)                                   | CAT 1              | 26/02/2019                  | Completed Defects       | 30/01/2019         | A77 SB CW CENTRE LINE 15M SOUTH OF HANSEL VILLAGE                             |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 February 2019</b>                                |            |          |             |  |                    |                             |                         |                    |   |
| No defects recorded   |            |          |             |  |                    |                             |                         |                    |   |
| <b>Detailed Inspections - Category A Footways of A77 Hansel Village CATA Footways on 04 February 2019</b> |            |          |             |  |                    |                             |                         |                    |   |
| No defects recorded   |            |          |             |  |                    |                             |                         |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 February 2019</b>                                |            |          |             |  |                    |                             |                         |                    |   |
| SW82429329-236310599  | 1,229m     | 1,230m   | CARRIAGEWAY | Other (OTHR)                                     | 3RD PTY            | 05/03/2019                  | Awaiting CCMS Temp Date | 01/01/9999         | A77 NB FOOTWAY, 1200M NTH OF DUTCHHOUSE                                       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 February 2019</b>                                |            |          |             |  |                    |                             |                         |                    |   |
| No defects recorded   |            |          |             |  |                    |                             |                         |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 February 2019</b>                                |            |          |             |  |                    |                             |                         |                    |   |
| SW82429845-236328223  | 896m       | 897m     | CARRIAGEWAY | Pothole VIAFIX (POTV)                            | CAT 1              | 13/02/2019                  | Completed Defects       | 12/02/2019         | A77 N/B 200M PRIOR TO HANSEL VILLAGE  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 February 2019</b>                                |            |          |             |  |                    |                             |                         |                    |   |
| No defects recorded   |            |          |             |  |                    |                             |                         |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 February 2019</b>                                |            |          |             |  |                    |                             |                         |                    |   |
| No defects recorded   |            |          |             |  |                    |                             |                         |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 February 2019</b>                                |            |          |             |  |                    |                             |                         |                    |   |
| No defects recorded   |            |          |             |  |                    |                             |                         |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 February 2019</b>                                |            |          |             |  |                    |                             |                         |                    |   |
| No defects recorded   |            |          |             |  |                    |                             |                         |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 March 2019</b>                                   |            |          |             |  |                    |                             |                         |                    |   |
| No defects recorded   |            |          |             |  |                    |                             |                         |                    |   |
| <b>Detailed Inspections - Category A Footways of A77 Hansel Village CATA Footways on 05 March 2019</b>    |            |          |             |  |                    |                             |                         |                    |   |
| SW82437829-3  | 1,697m     | 1,697m   | FOOTWAY     | Bituminous surfacing fretting (BFRT)             | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action   | 01/01/9999         |   |
| SW82437829-7  | 1,098m     | 1,098m   | FOOTWAY     | Bituminous surfacing - extensive cracking (BECK) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action   | 01/01/9999         | A77 S/B HANSEL ONSLIP   |
| SW82437829-6  | 1,085m     | 1,085m   | FOOTWAY     | Bituminous surfacing - extensive cracking (BECK) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action   | 01/01/9999         | A77 S/B @ HANSEL GG55206  |

| Defect Reference | Start<br>m | End<br>m | Item Type | Item Detail | Defect<br>Category | Required<br>Completion Date | Current Status | Completion<br>Date | Location Description |
|------------------|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|
|------------------|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|

Safety Inspection of A76 & A77 Ayr North V1 on 05 March 2019

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 March 2019

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 12 March 2019

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 March 2019

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 19 March 2019

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 March 2019

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 26 March 2019

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2019

No defects recorded

11650/86 : WITH: SPITTALHILL SL.RD N/BD-K&L DIST BDY

Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018

No defects recorded

Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 27 March 2018

| Defect Reference  | Start m | End m | Item Type     | Item Detail                   | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description   |
|---|---------|-------|---------------|-------------------------------|-----------------|--------------------------|-----------------------|-----------------|--|
| <i>No defects recorded</i>  |         |       |               |                               |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2018</b> |         |       |               |                               |                 |                          |                       |                 |  |
| <i>No defects recorded</i>  |         |       |               |                               |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 April 2018</b> |         |       |               |                               |                 |                          |                       |                 |  |
| <i>No defects recorded</i>  |         |       |               |                               |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 April 2018</b> |         |       |               |                               |                 |                          |                       |                 |  |
| <i>No defects recorded</i>  |         |       |               |                               |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 April 2018</b> |         |       |               |                               |                 |                          |                       |                 |  |
| <i>No defects recorded</i>  |         |       |               |                               |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 April 2018</b> |         |       |               |                               |                 |                          |                       |                 |  |
| <i>No defects recorded</i>  |         |       |               |                               |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 April 2018</b> |         |       |               |                               |                 |                          |                       |                 |  |
| <i>No defects recorded</i>  |         |       |               |                               |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 April 2018</b> |         |       |               |                               |                 |                          |                       |                 |  |
| <i>No defects recorded</i>  |         |       |               |                               |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 April 2018</b> |         |       |               |                               |                 |                          |                       |                 |  |
| <i>No defects recorded</i>  |         |       |               |                               |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 April 2018</b> |         |       |               |                               |                 |                          |                       |                 |  |
| <i>No defects recorded</i>  |         |       |               |                               |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 01 May 2018</b>   |         |       |               |                               |                 |                          |                       |                 |  |
| <i>No defects recorded</i>  |         |       |               |                               |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 May 2018</b>   |         |       |               |                               |                 |                          |                       |                 |  |
| <i>No defects recorded</i>  |         |       |               |                               |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 May 2018</b>   |         |       |               |                               |                 |                          |                       |                 |  |
| <i>No defects recorded</i>  |         |       |               |                               |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 May 2018</b>   |         |       |               |                               |                 |                          |                       |                 |  |
| SW82347347-235785069  | 392m    | 393m  | REMOVE_ANIMAL | Carcass of dead animal (DEAD) | CAT 1           | 08/06/2018               | Completed Defects     | 11/05/2018      | A77 NB CW, LANE 1, FIRST LAYBY NTH OF SPITTALHILL NB OFFSLIP |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 May 2018</b>   |         |       |               |                               |                 |                          |                       |                 |  |
| <i>No defects recorded</i>  |         |       |               |                               |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 May 2018</b>   |         |       |               |                               |                 |                          |                       |                 |  |
| <i>No defects recorded</i>  |         |       |               |                               |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 May 2018</b>   |         |       |               |                               |                 |                          |                       |                 |  |
| <i>No defects recorded</i>  |         |       |               |                               |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 May 2018</b>   |         |       |               |                               |                 |                          |                       |                 |  |
| <i>No defects recorded</i>  |         |       |               |                               |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 May 2018</b>   |         |       |               |                               |                 |                          |                       |                 |  |
| <i>No defects recorded</i>  |         |       |               |                               |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 June 2018</b>  |         |       |               |                               |                 |                          |                       |                 |  |
| <i>No defects recorded</i>  |         |       |               |                               |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 June 2018</b>  |         |       |               |                               |                 |                          |                       |                 |  |
| <i>No defects recorded</i>  |         |       |               |                               |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 June 2018</b>  |         |       |               |                               |                 |                          |                       |                 |  |
| <i>No defects recorded</i>  |         |       |               |                               |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 June 2018</b>  |         |       |               |                               |                 |                          |                       |                 |  |
| <i>No defects recorded</i>  |         |       |               |                               |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 June 2018</b>  |         |       |               |                               |                 |                          |                       |                 |  |
| SW80-364233-235859302   | 305m    | 305m  | CARRIAGEWAY   | Litter Grade D (LITD)         | 3RD PTY         | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | A77 NB SPITTAHILL OFFSLIP                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 June 2018</b>  |         |       |               |                               |                 |                          |                       |                 |  |
| <i>No defects recorded</i>  |         |       |               |                               |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 June 2018</b>  |         |       |               |                               |                 |                          |                       |                 |  |
| <i>No defects recorded</i>  |         |       |               |                               |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 June 2018</b>  |         |       |               |                               |                 |                          |                       |                 |  |
| <i>No defects recorded</i>  |         |       |               |                               |                 |                          |                       |                 |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018</b>    |         |       |               |                               |                 |                          |                       |                 |  |
| <i>No defects recorded</i>  |         |       |               |                               |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 June 2018</b>  |         |       |               |                               |                 |                          |                       |                 |  |
| <i>No defects recorded</i>  |         |       |               |                               |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 July 2018</b>  |         |       |               |                               |                 |                          |                       |                 |  |
| <i>No defects recorded</i>  |         |       |               |                               |                 |                          |                       |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 July 2018</b>  |         |       |               |                               |                 |                          |                       |                 |  |
| <i>No defects recorded</i>  |         |       |               |                               |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 July 2018</b>  |         |       |               |                               |                 |                          |                       |                 |  |
| <i>No defects recorded</i>  |         |       |               |                               |                 |                          |                       |                 |  |

| Defect Reference                         | Start m | End m | Item Type        | Item Detail                           | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|--|---------|-------|------------------|---------------------------------------|-----------------|--------------------------|----------------|-----------------|----------------------|
| Safety Patrol of A77 Ayr North           |         |       | Safety Patrol V1 | Safety Patrol V1 on 13 July 2018      |                 |                          |                |                 |                      |
| <i>No defects recorded</i>               |         |       |                  |                                       |                 |                          |                |                 |                      |
| Safety Inspection of A76 & A77 Ayr North |         |       | V1               | Safety Patrol V1 on 17 July 2018      |                 |                          |                |                 |                      |
| <i>No defects recorded</i>               |         |       |                  |                                       |                 |                          |                |                 |                      |
| Safety Patrol of A77 Ayr North           |         |       | Safety Patrol V1 | Safety Patrol V1 on 20 July 2018      |                 |                          |                |                 |                      |
| <i>No defects recorded</i>               |         |       |                  |                                       |                 |                          |                |                 |                      |
| Safety Inspection of A76 & A77 Ayr North |         |       | V1               | Safety Patrol V1 on 24 July 2018      |                 |                          |                |                 |                      |
| <i>No defects recorded</i>               |         |       |                  |                                       |                 |                          |                |                 |                      |
| Safety Patrol of A77 Ayr North           |         |       | Safety Patrol V1 | Safety Patrol V1 on 27 July 2018      |                 |                          |                |                 |                      |
| <i>No defects recorded</i>               |         |       |                  |                                       |                 |                          |                |                 |                      |
| Safety Inspection of A76 & A77 Ayr North |         |       | V1               | Safety Patrol V1 on 31 July 2018      |                 |                          |                |                 |                      |
| <i>No defects recorded</i>               |         |       |                  |                                       |                 |                          |                |                 |                      |
| Safety Patrol of A77 Ayr North           |         |       | Safety Patrol V1 | Safety Patrol V1 on 03 August 2018    |                 |                          |                |                 |                      |
| <i>No defects recorded</i>               |         |       |                  |                                       |                 |                          |                |                 |                      |
| Safety Inspection of A76 & A77 Ayr North |         |       | V1               | Safety Patrol V1 on 07 August 2018    |                 |                          |                |                 |                      |
| <i>No defects recorded</i>               |         |       |                  |                                       |                 |                          |                |                 |                      |
| Safety Patrol of A77 Ayr North           |         |       | Safety Patrol V1 | Safety Patrol V1 on 10 August 2018    |                 |                          |                |                 |                      |
| <i>No defects recorded</i>               |         |       |                  |                                       |                 |                          |                |                 |                      |
| Safety Inspection of A76 & A77 Ayr North |         |       | V1               | Safety Patrol V1 on 14 August 2018    |                 |                          |                |                 |                      |
| <i>No defects recorded</i>               |         |       |                  |                                       |                 |                          |                |                 |                      |
| Safety Patrol of A77 Ayr North           |         |       | Safety Patrol V1 | Safety Patrol V1 on 17 August 2018    |                 |                          |                |                 |                      |
| <i>No defects recorded</i>               |         |       |                  |                                       |                 |                          |                |                 |                      |
| Safety Inspection of A76 & A77 Ayr North |         |       | V1               | Safety Patrol V1 on 21 August 2018    |                 |                          |                |                 |                      |
| <i>No defects recorded</i>               |         |       |                  |                                       |                 |                          |                |                 |                      |
| Safety Patrol of A77 Ayr North           |         |       | Safety Patrol V1 | Safety Patrol V1 on 24 August 2018    |                 |                          |                |                 |                      |
| <i>No defects recorded</i>               |         |       |                  |                                       |                 |                          |                |                 |                      |
| Safety Inspection of A76 & A77 Ayr North |         |       | V1               | Safety Patrol V1 on 28 August 2018    |                 |                          |                |                 |                      |
| <i>No defects recorded</i>               |         |       |                  |                                       |                 |                          |                |                 |                      |
| Safety Patrol of A77 Ayr North           |         |       | Safety Patrol V1 | Safety Patrol V1 on 31 August 2018    |                 |                          |                |                 |                      |
| <i>No defects recorded</i>               |         |       |                  |                                       |                 |                          |                |                 |                      |
| Safety Inspection of A76 & A77 Ayr North |         |       | V1               | Safety Patrol V1 on 04 September 2018 |                 |                          |                |                 |                      |
| <i>No defects recorded</i>               |         |       |                  |                                       |                 |                          |                |                 |                      |
| Safety Inspection of A76 & A77 Ayr North |         |       | V1               | Safety Patrol V1 on 11 September 2018 |                 |                          |                |                 |                      |
| <i>No defects recorded</i>               |         |       |                  |                                       |                 |                          |                |                 |                      |
| Safety Patrol of A77 Ayr North           |         |       | Safety Patrol V1 | Safety Patrol V1 on 14 September 2018 |                 |                          |                |                 |                      |
| <i>No defects recorded</i>               |         |       |                  |                                       |                 |                          |                |                 |                      |
| Safety Inspection of A76 & A77 Ayr North |         |       | V1               | Safety Patrol V1 on 18 September 2018 |                 |                          |                |                 |                      |
| <i>No defects recorded</i>               |         |       |                  |                                       |                 |                          |                |                 |                      |
| Safety Patrol of A77 Ayr North           |         |       | Safety Patrol V1 | Safety Patrol V1 on 21 September 2018 |                 |                          |                |                 |                      |
| <i>No defects recorded</i>               |         |       |                  |                                       |                 |                          |                |                 |                      |
| Safety Inspection of A76 & A77 Ayr North |         |       | V1               | Safety Patrol V1 on 25 September 2018 |                 |                          |                |                 |                      |
| <i>No defects recorded</i>               |         |       |                  |                                       |                 |                          |                |                 |                      |
| Safety Patrol of A77 Ayr North           |         |       | Safety Patrol V1 | Safety Patrol V1 on 28 September 2018 |                 |                          |                |                 |                      |
| <i>No defects recorded</i>               |         |       |                  |                                       |                 |                          |                |                 |                      |
| Safety Inspection of A76 & A77 Ayr North |         |       | V1               | Safety Patrol V1 on 02 October 2018   |                 |                          |                |                 |                      |
| <i>No defects recorded</i>               |         |       |                  |                                       |                 |                          |                |                 |                      |
| Safety Patrol of A77 Ayr North           |         |       | Safety Patrol V1 | Safety Patrol V1 on 05 October 2018   |                 |                          |                |                 |                      |
| <i>No defects recorded</i>               |         |       |                  |                                       |                 |                          |                |                 |                      |
| Safety Inspection of A76 & A77 Ayr North |         |       | V1               | Safety Patrol V1 on 09 October 2018   |                 |                          |                |                 |                      |
| <i>No defects recorded</i>               |         |       |                  |                                       |                 |                          |                |                 |                      |
| Safety Patrol of A77 Ayr North           |         |       | Safety Patrol V1 | Safety Patrol V1 on 12 October 2018   |                 |                          |                |                 |                      |
| <i>No defects recorded</i>               |         |       |                  |                                       |                 |                          |                |                 |                      |
| Safety Inspection of A76 & A77 Ayr North |         |       | V1               | Safety Patrol V1 on 16 October 2018   |                 |                          |                |                 |                      |
| <i>No defects recorded</i>               |         |       |                  |                                       |                 |                          |                |                 |                      |
| Safety Patrol of A77 Ayr North           |         |       | Safety Patrol V1 | Safety Patrol V1 on 19 October 2018   |                 |                          |                |                 |                      |
| <i>No defects recorded</i>               |         |       |                  |                                       |                 |                          |                |                 |                      |
| Safety Inspection of A76 & A77 Ayr North |         |       | V1               | Safety Patrol V1 on 23 October 2018   |                 |                          |                |                 |                      |
| <i>No defects recorded</i>               |         |       |                  |                                       |                 |                          |                |                 |                      |
| Safety Patrol of A77 Ayr North           |         |       | Safety Patrol V1 | Safety Patrol V1 on 26 October 2018   |                 |                          |                |                 |                      |
| <i>No defects recorded</i>               |         |       |                  |                                       |                 |                          |                |                 |                      |
| Safety Inspection of A76 & A77 Ayr North |         |       | V1               | Safety Patrol V1 on 30 October 2018   |                 |                          |                |                 |                      |
| <i>No defects recorded</i>               |         |       |                  |                                       |                 |                          |                |                 |                      |
| Safety Patrol of A77 Ayr North           |         |       | Safety Patrol V1 | Safety Patrol V1 on 02 November 2018  |                 |                          |                |                 |                      |
| <i>No defects recorded</i>               |         |       |                  |                                       |                 |                          |                |                 |                      |
| Safety Inspection of A76 & A77 Ayr North |         |       | V1               | Safety Patrol V1 on 06 November 2018  |                 |                          |                |                 |                      |
| <i>No defects recorded</i>               |         |       |                  |                                       |                 |                          |                |                 |                      |
| Safety Patrol of A77 Ayr North           |         |       | Safety Patrol V1 | Safety Patrol V1 on 09 November 2018  |                 |                          |                |                 |                      |



| Defect Reference | Start<br>m | End<br>m | Item Type | Item Detail | Defect<br>Category | Required<br>Completion Date | Current Status | Completion<br>Date | Location Description |
|------------------|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|
|------------------|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|

*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 13 November 2018**

*No defects recorded*  
**Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 November 2018**

*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 20 November 2018**

*No defects recorded*  
**Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 November 2018**

*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 27 November 2018**

*No defects recorded*  
**Safety Patrol of A77 Ayr North Safety Patrol V1 on 30 November 2018**

*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 04 December 2018**

*No defects recorded*  
**Safety Patrol of A77 Ayr North Safety Patrol V1 on 07 December 2018**

*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 11 December 2018**

*No defects recorded*  
**Safety Patrol of A77 Ayr North Safety Patrol V1 on 14 December 2018**

*No defects recorded*  
**Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018**

|                |      |      |               |                          |       |            |                       |            |  |
|----------------|------|------|---------------|--------------------------|-------|------------|-----------------------|------------|--|
| SW82332070-121 | 581m | 581m | TRAFFIC_SIGNS | Surface corrosion (SFCO) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 |  |
|----------------|------|------|---------------|--------------------------|-------|------------|-----------------------|------------|--|

|                |      |      |             |                           |       |            |                       |            |  |
|----------------|------|------|-------------|---------------------------|-------|------------|-----------------------|------------|--|
| SW82332070-119 | 640m | 645m | CARRIAGEWAY | Localised cracking (LOCK) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 |  |
|----------------|------|------|-------------|---------------------------|-------|------------|-----------------------|------------|--|

|                |      |      |             |                                      |       |            |                       |            |  |
|----------------|------|------|-------------|--------------------------------------|-------|------------|-----------------------|------------|--|
| SW82332070-118 | 666m | 696m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 |  |
|----------------|------|------|-------------|--------------------------------------|-------|------------|-----------------------|------------|--|

|                |      |      |               |                          |       |            |                       |            |  |
|----------------|------|------|---------------|--------------------------|-------|------------|-----------------------|------------|--|
| SW82332070-120 | 603m | 603m | TRAFFIC_SIGNS | Surface corrosion (SFCO) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 |  |
|----------------|------|------|---------------|--------------------------|-------|------------|-----------------------|------------|--|

*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 18 December 2018**

*No defects recorded*  
**Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 December 2018**

*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 24 December 2018**

*No defects recorded*  
**Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 December 2018**

*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 31 December 2018**

*No defects recorded*  
**Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 January 2019**

*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 07 January 2019**

*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 08 January 2019**

*No defects recorded*  
**Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 January 2019**

*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 15 January 2019**

*No defects recorded*  
**Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 January 2019**

*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 22 January 2019**

*No defects recorded*  
**Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 January 2019**

*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 29 January 2019**

*No defects recorded*  
**Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 February 2019**

*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 05 February 2019**

*No defects recorded*  
**Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 February 2019**

*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 05 February 2019**

*No defects recorded*  
**Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 February 2019**



| Defect Reference  | Start m | End m | Item Type   | Item Detail    | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                       |
|---|---------|-------|-------------|----------------|-----------------|--------------------------|-------------------|-----------------|--|
| <i>No defects recorded</i>  |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 March 2018</b> |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018</b> |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 March 2018</b> |         |       |             |                |                 |                          |                   |                 |  |
| SW82327521-235576665  | 680m    | 681m  | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 10/04/2018               | Completed Defects | 14/03/2018      | A77 SPITTALHILL SB ONSLIP, 200M NTH JOIN   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018</b> |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 March 2018</b> |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018</b> |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 March 2018</b> |         |       |             |                |                 |                          |                   |                 |  |
| SW82331491-235609015  | 62m     | 63m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 24/04/2018               | Completed Defects | 27/03/2018      | A77 SB SPITTALHILL ONSLIP AT START OF SLIP |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2018</b> |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 April 2018</b> |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 April 2018</b> |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 April 2018</b> |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 April 2018</b> |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 April 2018</b> |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 April 2018</b> |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 April 2018</b> |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 April 2018</b> |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 01 May 2018</b>   |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 May 2018</b>   |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 May 2018</b>   |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 May 2018</b>   |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 May 2018</b>   |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 May 2018</b>   |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 May 2018</b>   |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 May 2018</b>   |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 May 2018</b>   |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 June 2018</b>  |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 June 2018</b>  |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 June 2018</b>  |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 June 2018</b>  |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 June 2018</b>  |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 June 2018</b>  |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>  |         |       |             |                |                 |                          |                   |                 |  |

| Defect Reference  | Start m | End m | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description             |
|---|---------|-------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|----------------------------------|
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 June 2018</b>      |         |       |             |                       |                 |                          |                   |                 |                                  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 June 2018</b>      |         |       |             |                       |                 |                          |                   |                 |                                  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018</b>        |         |       |             |                       |                 |                          |                   |                 |                                  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 June 2018</b>      |         |       |             |                       |                 |                          |                   |                 |                                  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 July 2018</b>      |         |       |             |                       |                 |                          |                   |                 |                                  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 July 2018</b>      |         |       |             |                       |                 |                          |                   |                 |                                  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 July 2018</b>      |         |       |             |                       |                 |                          |                   |                 |                                  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 July 2018</b>      |         |       |             |                       |                 |                          |                   |                 |                                  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 July 2018</b>      |         |       |             |                       |                 |                          |                   |                 |                                  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 July 2018</b>      |         |       |             |                       |                 |                          |                   |                 |                                  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 July 2018</b>      |         |       |             |                       |                 |                          |                   |                 |                                  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 July 2018</b>      |         |       |             |                       |                 |                          |                   |                 |                                  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 July 2018</b>      |         |       |             |                       |                 |                          |                   |                 |                                  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 03 August 2018</b>    |         |       |             |                       |                 |                          |                   |                 |                                  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 August 2018</b>    |         |       |             |                       |                 |                          |                   |                 |                                  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 10 August 2018</b>    |         |       |             |                       |                 |                          |                   |                 |                                  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 14 August 2018</b>    |         |       |             |                       |                 |                          |                   |                 |                                  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 17 August 2018</b>    |         |       |             |                       |                 |                          |                   |                 |                                  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 21 August 2018</b>    |         |       |             |                       |                 |                          |                   |                 |                                  |
| SW80-396340-235971030   | 14m     | 970m  | CARRIAGEWAY | Litter Grade D (LITD) | 3RD PTY         | 22/08/2018               | Completed Defects | 14/05/2019      | A77 S/B ON SLIP FROM SPITTALHILL |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 24 August 2018</b>    |         |       |             |                       |                 |                          |                   |                 |                                  |
| SW80-397735-235979791   | 200m    | 201m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 21/09/2018               | Completed Defects | 24/08/2018      | A77 SB ONSLIP SPITTALHILL        |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 28 August 2018</b>    |         |       |             |                       |                 |                          |                   |                 |                                  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 31 August 2018</b>    |         |       |             |                       |                 |                          |                   |                 |                                  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 September 2018</b> |         |       |             |                       |                 |                          |                   |                 |                                  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 ( Awaiting Return )</b>  |         |       |             |                       |                 |                          |                   |                 |                                  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 September 2018</b> |         |       |             |                       |                 |                          |                   |                 |                                  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 14 September 2018</b> |         |       |             |                       |                 |                          |                   |                 |                                  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 September 2018</b> |         |       |             |                       |                 |                          |                   |                 |                                  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 September 2018</b> |         |       |             |                       |                 |                          |                   |                 |                                  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 25 September 2018</b> |         |       |             |                       |                 |                          |                   |                 |                                  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 September 2018</b> |         |       |             |                       |                 |                          |                   |                 |                                  |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 October 2018</b>   |         |       |             |                       |                 |                          |                   |                 |                                  |
| SW82416069-236108725  | 43m     | 43m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 03/10/2018               | Completed Defects | 02/10/2018      | A77 SPITTALHILL ON SLIP          |

| Defect Reference   | Start<br>m | End<br>m | Item Type   | Item Detail   | Defect<br>Category | Required<br>Completion Date | Current Status           | Completion<br>Date | Location Description    |
|--|------------|----------|-------------|---|--------------------|-----------------------------|--------------------------|--------------------|-------------------------|
| SW82416069-236108726   | 36m        | 37m      | CARRIAGEWAY | Pothole VIAFIX<br>(POTV)                            | CAT 1              | 03/10/2018                  | Completed<br>Defects     | 02/10/2018         | A77 SPITTALHILL ON SLIP |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 October 2018</b>  |            |          |             |   |                    |                             |                          |                    |                         |
| <i>No defects recorded</i>   |            |          |             |   |                    |                             |                          |                    |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 October 2018</b>  |            |          |             |   |                    |                             |                          |                    |                         |
| <i>No defects recorded</i>   |            |          |             |   |                    |                             |                          |                    |                         |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 October 2018</b>  |            |          |             |   |                    |                             |                          |                    |                         |
| <i>No defects recorded</i>   |            |          |             |   |                    |                             |                          |                    |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 October 2018</b>  |            |          |             |   |                    |                             |                          |                    |                         |
| <i>No defects recorded</i>   |            |          |             |   |                    |                             |                          |                    |                         |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 October 2018</b>  |            |          |             |   |                    |                             |                          |                    |                         |
| <i>No defects recorded</i>   |            |          |             |   |                    |                             |                          |                    |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 October 2018</b>  |            |          |             |   |                    |                             |                          |                    |                         |
| <i>No defects recorded</i>   |            |          |             |   |                    |                             |                          |                    |                         |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 October 2018</b>  |            |          |             |   |                    |                             |                          |                    |                         |
| <i>No defects recorded</i>   |            |          |             |   |                    |                             |                          |                    |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 October 2018</b>  |            |          |             |   |                    |                             |                          |                    |                         |
| <i>No defects recorded</i>   |            |          |             |   |                    |                             |                          |                    |                         |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 November 2018</b> |            |          |             |   |                    |                             |                          |                    |                         |
| <i>No defects recorded</i>   |            |          |             |   |                    |                             |                          |                    |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 November 2018</b> |            |          |             |   |                    |                             |                          |                    |                         |
| <i>No defects recorded</i>   |            |          |             |   |                    |                             |                          |                    |                         |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 November 2018</b> |            |          |             |   |                    |                             |                          |                    |                         |
| <i>No defects recorded</i>   |            |          |             |   |                    |                             |                          |                    |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 November 2018</b> |            |          |             |   |                    |                             |                          |                    |                         |
| <i>No defects recorded</i>   |            |          |             |   |                    |                             |                          |                    |                         |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 November 2018</b> |            |          |             |   |                    |                             |                          |                    |                         |
| <i>No defects recorded</i>   |            |          |             |   |                    |                             |                          |                    |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 November 2018</b> |            |          |             |   |                    |                             |                          |                    |                         |
| <i>No defects recorded</i>   |            |          |             |   |                    |                             |                          |                    |                         |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 November 2018</b> |            |          |             |   |                    |                             |                          |                    |                         |
| <i>No defects recorded</i>   |            |          |             |   |                    |                             |                          |                    |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 November 2018</b> |            |          |             |   |                    |                             |                          |                    |                         |
| <i>No defects recorded</i>   |            |          |             |   |                    |                             |                          |                    |                         |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 30 November 2018</b> |            |          |             |   |                    |                             |                          |                    |                         |
| SW82426931-236232766   | 123m       | 124m     | CARRIAGEWAY | Pothole VIAFIX<br>(POTV)                            | CAT 1              | 01/12/2018                  | Completed<br>Defects     | 30/11/2018         | A77 SPITTALHILL ON SLIP |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 December 2018</b> |            |          |             |   |                    |                             |                          |                    |                         |
| <i>No defects recorded</i>   |            |          |             |   |                    |                             |                          |                    |                         |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 07 December 2018</b> |            |          |             |   |                    |                             |                          |                    |                         |
| <i>No defects recorded</i>   |            |          |             |   |                    |                             |                          |                    |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 December 2018</b> |            |          |             |   |                    |                             |                          |                    |                         |
| <i>No defects recorded</i>   |            |          |             |   |                    |                             |                          |                    |                         |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 14 December 2018</b> |            |          |             |   |                    |                             |                          |                    |                         |
| <i>No defects recorded</i>   |            |          |             |   |                    |                             |                          |                    |                         |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018</b>   |            |          |             |   |                    |                             |                          |                    |                         |
| SW82332070-129   | 487m       | 587m     | CARRIAGEWAY | Bituminous<br>surfacing<br>fretting (BFRT)          | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                         |
| SW82332070-125   | 117m       | 119m     | CARRIAGEWAY | Patch - loss of<br>material<br>(fretting)<br>(PLMT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                         |
| SW82332070-127   | 201m       | 205m     | CARRIAGEWAY | Localised<br>cracking<br>(LOCK)                     | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                         |
| SW82332070-126   | 122m       | 124m     | CARRIAGEWAY | Localised<br>cracking<br>(LOCK)                     | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                         |
| SW82332070-122   | 57m        | 107m     | CARRIAGEWAY | Opening of<br>longitudinal<br>joint (OLJT)          | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                         |

| Defect Reference   | Start<br>m | End<br>m | Item Type     | Item Detail                                | Defect<br>Category | Required<br>Completion Date | Current Status           | Completion<br>Date | Location Description       |
|--|------------|----------|---------------|--|--------------------|-----------------------------|--------------------------|--------------------|----------------------------|
| SW82332070-123   | 62m        | 112m     | CARRIAGEWAY   | Bituminous<br>surfacing<br>fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                            |
| SW82332070-124   | 73m        | 73m      | TRAFFIC_SIGNS | Physical<br>condition of<br>post (COPT)    | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                            |
| SW82332070-128   | 265m       | 365m     | CARRIAGEWAY   | Bituminous<br>surfacing<br>fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                            |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 December 2018</b> |            |          |               |  |                    |                             |                          |                    |                            |
| No defects recorded  |            |          |               |  |                    |                             |                          |                    |                            |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 December 2018</b> |            |          |               |  |                    |                             |                          |                    |                            |
| No defects recorded  |            |          |               |  |                    |                             |                          |                    |                            |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 December 2018</b> |            |          |               |  |                    |                             |                          |                    |                            |
| No defects recorded  |            |          |               |  |                    |                             |                          |                    |                            |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 December 2018</b> |            |          |               |  |                    |                             |                          |                    |                            |
| No defects recorded  |            |          |               |  |                    |                             |                          |                    |                            |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 December 2018</b> |            |          |               |  |                    |                             |                          |                    |                            |
| No defects recorded  |            |          |               |  |                    |                             |                          |                    |                            |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 January 2019</b>  |            |          |               |  |                    |                             |                          |                    |                            |
| No defects recorded  |            |          |               |  |                    |                             |                          |                    |                            |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 January 2019</b>  |            |          |               |  |                    |                             |                          |                    |                            |
| No defects recorded  |            |          |               |  |                    |                             |                          |                    |                            |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 January 2019</b>  |            |          |               |  |                    |                             |                          |                    |                            |
| No defects recorded  |            |          |               |  |                    |                             |                          |                    |                            |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 January 2019</b>  |            |          |               |  |                    |                             |                          |                    |                            |
| No defects recorded  |            |          |               |  |                    |                             |                          |                    |                            |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 January 2019</b>  |            |          |               |  |                    |                             |                          |                    |                            |
| No defects recorded  |            |          |               |  |                    |                             |                          |                    |                            |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 January 2019</b>  |            |          |               |  |                    |                             |                          |                    |                            |
| No defects recorded  |            |          |               |  |                    |                             |                          |                    |                            |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 January 2019</b>  |            |          |               |  |                    |                             |                          |                    |                            |
| No defects recorded  |            |          |               |  |                    |                             |                          |                    |                            |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 January 2019</b>  |            |          |               |  |                    |                             |                          |                    |                            |
| No defects recorded  |            |          |               |  |                    |                             |                          |                    |                            |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 January 2019</b>  |            |          |               |  |                    |                             |                          |                    |                            |
| No defects recorded  |            |          |               |  |                    |                             |                          |                    |                            |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 February 2019</b> |            |          |               |  |                    |                             |                          |                    |                            |
| No defects recorded  |            |          |               |  |                    |                             |                          |                    |                            |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 February 2019</b> |            |          |               |  |                    |                             |                          |                    |                            |
| No defects recorded  |            |          |               |  |                    |                             |                          |                    |                            |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 February 2019</b> |            |          |               |  |                    |                             |                          |                    |                            |
| No defects recorded  |            |          |               |  |                    |                             |                          |                    |                            |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 February 2019</b> |            |          |               |  |                    |                             |                          |                    |                            |
| No defects recorded  |            |          |               |  |                    |                             |                          |                    |                            |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 February 2019</b> |            |          |               |  |                    |                             |                          |                    |                            |
| No defects recorded  |            |          |               |  |                    |                             |                          |                    |                            |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 February 2019</b> |            |          |               |  |                    |                             |                          |                    |                            |
| No defects recorded  |            |          |               |  |                    |                             |                          |                    |                            |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 February 2019</b> |            |          |               |  |                    |                             |                          |                    |                            |
| No defects recorded  |            |          |               |  |                    |                             |                          |                    |                            |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 February 2019</b> |            |          |               |  |                    |                             |                          |                    |                            |
| SW82435554-236335879   | 415m       | 615m     | CARRIAGEWAY   | Debris in hard<br>shoulder<br>(DBHS)       | 3RD PTY            | 27/02/2019                  | Completed<br>Defects     | 14/05/2019         | A77 S/B SPITALHILL ON SLIP |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 March 2019</b>    |            |          |               |  |                    |                             |                          |                    |                            |
| No defects recorded  |            |          |               |  |                    |                             |                          |                    |                            |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 March 2019</b>    |            |          |               |  |                    |                             |                          |                    |                            |
| No defects recorded  |            |          |               |  |                    |                             |                          |                    |                            |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 March 2019</b>    |            |          |               |  |                    |                             |                          |                    |                            |
| No defects recorded  |            |          |               |  |                    |                             |                          |                    |                            |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 March 2019</b>    |            |          |               |  |                    |                             |                          |                    |                            |
| No defects recorded  |            |          |               |  |                    |                             |                          |                    |                            |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 March 2019</b>    |            |          |               |  |                    |                             |                          |                    |                            |
| No defects recorded  |            |          |               |  |                    |                             |                          |                    |                            |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 March 2019</b>    |            |          |               |  |                    |                             |                          |                    |                            |

| Defect Reference   | Start<br>m | End<br>m | Item Type   | Item Detail   | Defect<br>Category | Required<br>Completion Date | Current Status       | Completion<br>Date | Location Description                       |
|--|------------|----------|-------------|---|--------------------|-----------------------------|----------------------|--------------------|--|
| <i>No defects recorded</i>   |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North</b><br>SW82454084-236489748  | 59m        | 59m      | CARRIAGEWAY | Safety Patrol V1 on 22 March 2019<br><i>Pothole VIAFIX (POTV)</i> | CAT 1              | 23/03/2019                  | Completed<br>Defects | 22/03/2019         | A77 S/B ONSLIP FROM SPITALHILL             |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 March 2019</b><br><i>No defects recorded</i>    |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North</b><br><i>No defects recorded</i>                                      |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Patrol V1 on 29 March 2019</b><br><i>No defects recorded</i>                                   |            |          |             |   |                    |                             |                      |                    |  |
| <b>11656/04 : WITH: N/B SLIP RD EXIT-HURLFORD INTERCHANGE</b>  |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 January 2018</b><br><i>No defects recorded</i>  |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North</b><br><i>No defects recorded</i>                                      |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Patrol V1 on 05 January 2018</b><br><i>No defects recorded</i>                                 |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 January 2018</b><br><i>No defects recorded</i>  |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North</b><br><i>No defects recorded</i>                                      |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Patrol V1 on 12 January 2018</b><br><i>No defects recorded</i>                                 |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 January 2018</b><br><i>No defects recorded</i>  |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North</b><br><i>No defects recorded</i>                                      |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Patrol V1 on 19 January 2018</b><br><i>No defects recorded</i>                                 |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 January 2018</b><br><i>No defects recorded</i>  |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North</b><br><i>No defects recorded</i>                                      |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Patrol V1 on 26 January 2018</b><br><i>No defects recorded</i>                                 |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 January 2018</b><br><i>No defects recorded</i>  |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North</b><br>SW82318553-235533632  | 11m        | 12m      | CARRIAGEWAY | Safety Patrol V1 on 02 February 2018<br><i>Pothole (POTH)</i>     | CAT 1              | 02/03/2018                  | Completed<br>Defects | 02/02/2018         | A77 NB CW, ON BELLFIELD NB OFFSLIP         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 February 2018</b><br><i>No defects recorded</i> |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North</b><br><i>No defects recorded</i>                                      |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Patrol V1 on 09 February 2018</b><br><i>No defects recorded</i>                                |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 February 2018</b><br><i>No defects recorded</i> |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North</b><br><i>No defects recorded</i>                                      |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Patrol V1 on 16 February 2018</b><br><i>No defects recorded</i>                                |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 February 2018</b><br><i>No defects recorded</i> |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North</b><br><i>No defects recorded</i>                                      |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Patrol V1 on 23 February 2018</b><br><i>No defects recorded</i>                                |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 February 2018</b><br>SW82323374-235550823       | 7m         | 3m       | CARRIAGEWAY | <i>Pothole (POTH)</i>   | CAT 1              | 27/03/2018                  | Completed<br>Defects | 28/02/2018         | A77 NB CW, START OF BELLFIELD OFFSLIP      |
| SW82323374-235550824   | 16m        | 17m      | CARRIAGEWAY | <i>Pothole (POTH)</i>   | CAT 1              | 27/03/2018                  | Completed<br>Defects | 28/02/2018         | A77 NB CW, LANE 1, AT BELLFIELD NB OFFSLIP |
| <b>Safety Patrol of A77 Ayr North</b><br><i>No defects recorded</i>                                      |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Patrol V1 on 02 March 2018</b><br><i>No defects recorded</i>                                   |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 March 2018</b><br><i>No defects recorded</i>    |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North</b><br><i>No defects recorded</i>                                      |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Patrol V1 on 09 March 2018</b><br><i>No defects recorded</i>                                   |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 March 2018</b><br><i>No defects recorded</i>    |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North</b><br><i>No defects recorded</i>                                      |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Patrol V1 on 16 March 2018</b><br><i>No defects recorded</i>                                   |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 March 2018</b><br><i>No defects recorded</i>    |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North</b><br><i>No defects recorded</i>                                      |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Patrol V1 on 23 March 2018</b><br><i>No defects recorded</i>                                   |            |          |             |   |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 March 2018</b>                                  |            |          |             |   |                    |                             |                      |                    |  |

| Defect Reference                                       | Start<br>m | End<br>m | Item Type | Item Detail                       | Defect<br>Category | Required<br>Completion Date | Current Status | Completion<br>Date | Location Description |
|--|------------|----------|-----------|-----------------------------------|--------------------|-----------------------------|----------------|--------------------|----------------------|
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | Safety Patrol V1 on 29 March 2018 |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | on 03 April 2018                  |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | Safety Patrol V1 on 06 April 2018 |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | on 10 April 2018                  |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | Safety Patrol V1 on 13 April 2018 |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | on 17 April 2018                  |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | Safety Patrol V1 on 20 April 2018 |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | on 24 April 2018                  |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | Safety Patrol V1 on 27 April 2018 |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | on 01 May 2018                    |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | Safety Patrol V1 on 04 May 2018   |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | on 08 May 2018                    |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | Safety Patrol V1 on 11 May 2018   |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | on 15 May 2018                    |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | Safety Patrol V1 on 18 May 2018   |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | on 22 May 2018                    |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | Safety Patrol V1 on 25 May 2018   |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | on 29 May 2018                    |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | Safety Patrol V1 on 01 June 2018  |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | on 05 June 2018                   |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | Safety Patrol V1 on 08 June 2018  |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | on 12 June 2018                   |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | Safety Patrol V1 on 15 June 2018  |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | on 19 June 2018                   |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | Safety Patrol V1 on 22 June 2018  |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | on 26 June 2018                   |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det</b>   |            |          |           | on 20 June 2018                   |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | Safety Patrol V1 on 29 June 2018  |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | on 03 July 2018                   |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | Safety Patrol V1 on 06 July 2018  |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | on 10 July 2018                   |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          |           | Safety Patrol V1 on 13 July 2018  |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |           | on 17 July 2018                   |                    |                             |                |                    |                      |
| <i>No defects recorded</i>                             |            |          |           |                                   |                    |                             |                |                    |                      |



| Defect Reference                                       | Start<br>m | End<br>m | Item Type        | Item Detail                           | Defect<br>Category | Required<br>Completion Date | Current Status | Completion<br>Date | Location Description |
|--|------------|----------|------------------|---------------------------------------|--------------------|-----------------------------|----------------|--------------------|----------------------|
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          | Safety Patrol V1 | Safety Patrol V1 on 20 July 2018      |                    |                             |                |                    |                      |
|  |            |          |                  | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |                  | Safety Patrol V1 on 24 July 2018      |                    |                             |                |                    |                      |
|  |            |          |                  | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          | Safety Patrol V1 | Safety Patrol V1 on 27 July 2018      |                    |                             |                |                    |                      |
|  |            |          |                  | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |                  | Safety Patrol V1 on 31 July 2018      |                    |                             |                |                    |                      |
|  |            |          |                  | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          | Safety Patrol V1 | Safety Patrol V1 on 03 August 2018    |                    |                             |                |                    |                      |
|  |            |          |                  | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |                  | Safety Patrol V1 on 07 August 2018    |                    |                             |                |                    |                      |
|  |            |          |                  | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          | Safety Patrol V1 | Safety Patrol V1 on 10 August 2018    |                    |                             |                |                    |                      |
|  |            |          |                  | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |                  | Safety Patrol V1 on 14 August 2018    |                    |                             |                |                    |                      |
|  |            |          |                  | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          | Safety Patrol V1 | Safety Patrol V1 on 17 August 2018    |                    |                             |                |                    |                      |
|  |            |          |                  | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |                  | Safety Patrol V1 on 21 August 2018    |                    |                             |                |                    |                      |
|  |            |          |                  | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          | Safety Patrol V1 | Safety Patrol V1 on 24 August 2018    |                    |                             |                |                    |                      |
|  |            |          |                  | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |                  | Safety Patrol V1 on 28 August 2018    |                    |                             |                |                    |                      |
|  |            |          |                  | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          | Safety Patrol V1 | Safety Patrol V1 on 31 August 2018    |                    |                             |                |                    |                      |
|  |            |          |                  | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |                  | Safety Patrol V1 on 04 September 2018 |                    |                             |                |                    |                      |
|  |            |          |                  | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |                  | Safety Patrol V1 on 11 September 2018 |                    |                             |                |                    |                      |
|  |            |          |                  | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          | Safety Patrol V1 | Safety Patrol V1 on 14 September 2018 |                    |                             |                |                    |                      |
|  |            |          |                  | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |                  | Safety Patrol V1 on 18 September 2018 |                    |                             |                |                    |                      |
|  |            |          |                  | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          | Safety Patrol V1 | Safety Patrol V1 on 21 September 2018 |                    |                             |                |                    |                      |
|  |            |          |                  | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |                  | Safety Patrol V1 on 25 September 2018 |                    |                             |                |                    |                      |
|  |            |          |                  | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          | Safety Patrol V1 | Safety Patrol V1 on 28 September 2018 |                    |                             |                |                    |                      |
|  |            |          |                  | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |                  | Safety Patrol V1 on 02 October 2018   |                    |                             |                |                    |                      |
|  |            |          |                  | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          | Safety Patrol V1 | Safety Patrol V1 on 05 October 2018   |                    |                             |                |                    |                      |
|  |            |          |                  | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |                  | Safety Patrol V1 on 09 October 2018   |                    |                             |                |                    |                      |
|  |            |          |                  | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          | Safety Patrol V1 | Safety Patrol V1 on 12 October 2018   |                    |                             |                |                    |                      |
|  |            |          |                  | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |                  | Safety Patrol V1 on 16 October 2018   |                    |                             |                |                    |                      |
|  |            |          |                  | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          | Safety Patrol V1 | Safety Patrol V1 on 19 October 2018   |                    |                             |                |                    |                      |
|  |            |          |                  | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |                  | Safety Patrol V1 on 23 October 2018   |                    |                             |                |                    |                      |
|  |            |          |                  | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          | Safety Patrol V1 | Safety Patrol V1 on 26 October 2018   |                    |                             |                |                    |                      |
|  |            |          |                  | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |                  | Safety Patrol V1 on 30 October 2018   |                    |                             |                |                    |                      |
|  |            |          |                  | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          | Safety Patrol V1 | Safety Patrol V1 on 02 November 2018  |                    |                             |                |                    |                      |
|  |            |          |                  | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |                  | Safety Patrol V1 on 06 November 2018  |                    |                             |                |                    |                      |
|  |            |          |                  | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          | Safety Patrol V1 | Safety Patrol V1 on 09 November 2018  |                    |                             |                |                    |                      |
|  |            |          |                  | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1</b> |            |          |                  | Safety Patrol V1 on 13 November 2018  |                    |                             |                |                    |                      |
|  |            |          |                  | No defects recorded                   |                    |                             |                |                    |                      |
| <b>Safety Patrol of A77 Ayr North</b>                  |            |          | Safety Patrol V1 | Safety Patrol V1 on 16 November 2018  |                    |                             |                |                    |                      |

| Defect Reference   | Start<br>m | End<br>m | Item Type   | Item Detail                                | Defect<br>Category | Required<br>Completion Date | Current Status           | Completion<br>Date | Location Description                      |
|--|------------|----------|-------------|--|--------------------|-----------------------------|--------------------------|--------------------|---|
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 November 2018</b> |            |          |             |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 November 2018</b> |            |          |             |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 November 2018</b> |            |          |             |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 30 November 2018</b> |            |          |             |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 December 2018</b> |            |          |             |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 07 December 2018</b> |            |          |             |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 December 2018</b> |            |          |             |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 14 December 2018</b> |            |          |             |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 December 2018</b> |            |          |             |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 December 2018</b> |            |          |             |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 December 2018</b> |            |          |             |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 December 2018</b> |            |          |             |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 December 2018</b> |            |          |             |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 January 2019</b>  |            |          |             |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 January 2019</b>  |            |          |             |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 January 2019</b>  |            |          |             |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 January 2019</b>  |            |          |             |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018</b>   |            |          |             |  |                    |                             |                          |                    |   |
| SW82332070-158   | 137m       | 237m     | CARRIAGEWAY | Bituminous<br>surfacing<br>fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |   |
| SW82332070-160   | 240m       | 350m     | CARRIAGEWAY | Single crack<br>(CRCK)                     | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 January 2019</b>  |            |          |             |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 January 2019</b>  |            |          |             |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 January 2019</b>  |            |          |             |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 January 2019</b>  |            |          |             |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 January 2019</b>  |            |          |             |  |                    |                             |                          |                    |   |
| SW82428594-236291671   | 152m       | 167m     | GULLY       | Blockage<br>(BLOK)                         | CAT 1              | 26/02/2019                  | Completed<br>Defects     | 29/01/2019         | A77 NB BELLFIELD OFF SLIP                 |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 February 2019</b> |            |          |             |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 February 2019</b> |            |          |             |  |                    |                             |                          |                    |   |
| SW82429329-236310602   | 230m       | 231m     | CARRIAGEWAY | Pothole VIAFIX<br>(POTV)                   | CAT 1              | 05/03/2019                  | Completed<br>Defects     | 06/02/2019         | A77 NB CW, UNDER<br>BELLFIELD INTERCHANGE |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 February 2019</b> |            |          |             |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 February 2019</b> |            |          |             |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 February 2019</b> |            |          |             |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |             |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 February 2019</b> |            |          |             |  |                    |                             |                          |                    |   |

| Defect Reference   | Start<br>m                                   | End<br>m | Item Type   | Item Detail              | Defect<br>Category | Required<br>Completion Date | Current Status       | Completion<br>Date | Location Description                |
|--|--|----------|-------------|--------------------------|--------------------|-----------------------------|----------------------|--------------------|-------------------------------------|
| <i>No defects recorded</i>   |  |          |             |                          |                    |                             |                      |                    |                                     |
| <b>Safety Patrol of A77 Ayr North</b><br>SW82433749-236325466              | Safety Patrol V1 on 22 February 2019<br>224m | 224m     | CARRIAGEWAY | Litter Grade C<br>(LITC) | 3RD PTY            | 23/02/2019                  | Completed<br>Defects | 14/05/2019         | A77 N/B OFFSLIP TO<br>BELLFEILD R/A |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 February 2019</b> |  |          |             |                          |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |  |          |             |                          |                    |                             |                      |                    |                                     |
| <b>Safety Patrol of A77 Ayr North</b>                                      | Safety Patrol V1 on 01 March 2019            |          |             |                          |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |  |          |             |                          |                    |                             |                      |                    |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 March 2019</b>    |  |          |             |                          |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |  |          |             |                          |                    |                             |                      |                    |                                     |
| <b>Safety Patrol of A77 Ayr North</b>                                      | Safety Patrol V1 on 08 March 2019            |          |             |                          |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |  |          |             |                          |                    |                             |                      |                    |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 March 2019</b>    |  |          |             |                          |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |  |          |             |                          |                    |                             |                      |                    |                                     |
| <b>Safety Patrol of A77 Ayr North</b>                                      | Safety Patrol V1 on 15 March 2019            |          |             |                          |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |  |          |             |                          |                    |                             |                      |                    |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 March 2019</b>    |  |          |             |                          |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |  |          |             |                          |                    |                             |                      |                    |                                     |
| <b>Safety Patrol of A77 Ayr North</b>                                      | Safety Patrol V1 on 22 March 2019            |          |             |                          |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |  |          |             |                          |                    |                             |                      |                    |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 March 2019</b>    |  |          |             |                          |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |  |          |             |                          |                    |                             |                      |                    |                                     |
| <b>Safety Patrol of A77 Ayr North</b>                                      | Safety Patrol V1 on 29 March 2019            |          |             |                          |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |  |          |             |                          |                    |                             |                      |                    |                                     |
| <b>11656/11 : AGAINST: HURLFORD INTERCHANGE-JCT OF S/B TR.ROAD</b>         |  |          |             |                          |                    |                             |                      |                    |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 January 2018</b>  |  |          |             |                          |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |  |          |             |                          |                    |                             |                      |                    |                                     |
| <b>Safety Patrol of A77 Ayr North</b>                                      | Safety Patrol V1 on 05 January 2018          |          |             |                          |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |  |          |             |                          |                    |                             |                      |                    |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 January 2018</b>  |  |          |             |                          |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |  |          |             |                          |                    |                             |                      |                    |                                     |
| <b>Safety Patrol of A77 Ayr North</b>                                      | Safety Patrol V1 on 12 January 2018          |          |             |                          |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |  |          |             |                          |                    |                             |                      |                    |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 January 2018</b>  |  |          |             |                          |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |  |          |             |                          |                    |                             |                      |                    |                                     |
| <b>Safety Patrol of A77 Ayr North</b>                                      | Safety Patrol V1 on 19 January 2018          |          |             |                          |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |  |          |             |                          |                    |                             |                      |                    |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 January 2018</b>  |  |          |             |                          |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |  |          |             |                          |                    |                             |                      |                    |                                     |
| <b>Safety Patrol of A77 Ayr North</b>                                      | Safety Patrol V1 on 26 January 2018          |          |             |                          |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |  |          |             |                          |                    |                             |                      |                    |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 January 2018</b>  |  |          |             |                          |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |  |          |             |                          |                    |                             |                      |                    |                                     |
| <b>Safety Patrol of A77 Ayr North</b>                                      | Safety Patrol V1 on 02 February 2018         |          |             |                          |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |  |          |             |                          |                    |                             |                      |                    |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 February 2018</b> |  |          |             |                          |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |  |          |             |                          |                    |                             |                      |                    |                                     |
| <b>Safety Patrol of A77 Ayr North</b>                                      | Safety Patrol V1 on 09 February 2018         |          |             |                          |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |  |          |             |                          |                    |                             |                      |                    |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 February 2018</b> |  |          |             |                          |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |  |          |             |                          |                    |                             |                      |                    |                                     |
| <b>Safety Patrol of A77 Ayr North</b>                                      | Safety Patrol V1 on 16 February 2018         |          |             |                          |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |  |          |             |                          |                    |                             |                      |                    |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 February 2018</b> |  |          |             |                          |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |  |          |             |                          |                    |                             |                      |                    |                                     |
| <b>Safety Patrol of A77 Ayr North</b>                                      | Safety Patrol V1 on 23 February 2018         |          |             |                          |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |  |          |             |                          |                    |                             |                      |                    |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 February 2018</b> |  |          |             |                          |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |  |          |             |                          |                    |                             |                      |                    |                                     |
| <b>Safety Patrol of A77 Ayr North</b>                                      | Safety Patrol V1 on 02 March 2018            |          |             |                          |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |  |          |             |                          |                    |                             |                      |                    |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 March 2018</b>    |  |          |             |                          |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |  |          |             |                          |                    |                             |                      |                    |                                     |
| <b>Safety Patrol of A77 Ayr North</b>                                      | Safety Patrol V1 on 09 March 2018            |          |             |                          |                    |                             |                      |                    |                                     |
| <i>No defects recorded</i>   |  |          |             |                          |                    |                             |                      |                    |                                     |

| Defect Reference  | Start<br>m | End<br>m | Item Type   | Item Detail              | Defect<br>Category | Required<br>Completion Date | Current Status       | Completion<br>Date | Location Description                               |
|---|------------|----------|-------------|--------------------------|--------------------|-----------------------------|----------------------|--------------------|--|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 March 2018</b> |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018</b> |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 March 2018</b> |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018</b> |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 March 2018</b> |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2018</b> |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 April 2018</b> |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 April 2018</b> |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 April 2018</b> |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 April 2018</b> |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 April 2018</b> |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 April 2018</b> |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 April 2018</b> |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 April 2018</b> |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 01 May 2018</b>   |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 May 2018</b>   |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 May 2018</b>   |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 May 2018</b>   |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 May 2018</b>   |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 May 2018</b>   |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 May 2018</b>   |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 May 2018</b>   |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 May 2018</b>   |            |          |             |                          |                    |                             |                      |                    |  |
| SW82355166-235815743  | 487m       | 488m     | CARRIAGEWAY | Pothole VIAFIX<br>(POTV) | CAT 1              | 26/06/2018                  | Completed<br>Defects | 30/05/2018         | A77 NB CW CL 50M PRIOR TO<br>BELLFIELD INTERCHANGE |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 June 2018</b>  |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 June 2018</b>  |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 June 2018</b>  |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 June 2018</b>  |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 June 2018</b>  |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 June 2018</b>  |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 June 2018</b>  |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 June 2018</b>  |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018</b>    |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 June 2018</b>  |            |          |             |                          |                    |                             |                      |                    |  |

| Defect Reference   | Start<br>m | End<br>m | Item Type      | Item Detail    | Defect<br>Category | Required<br>Completion Date | Current Status    | Completion<br>Date | Location Description                         |
|--|------------|----------|----------------|----------------|--------------------|-----------------------------|-------------------|--------------------|--|
| No defects recorded  |            |          |                |                |                    |                             |                   |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 03 July 2018          |            |          |                |                |                    |                             |                   |                    |  |
| No defects recorded  |            |          |                |                |                    |                             |                   |                    |  |
| Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 July 2018      |            |          |                |                |                    |                             |                   |                    |  |
| No defects recorded  |            |          |                |                |                    |                             |                   |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 10 July 2018          |            |          |                |                |                    |                             |                   |                    |  |
| No defects recorded  |            |          |                |                |                    |                             |                   |                    |  |
| Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 July 2018      |            |          |                |                |                    |                             |                   |                    |  |
| No defects recorded  |            |          |                |                |                    |                             |                   |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 17 July 2018          |            |          |                |                |                    |                             |                   |                    |  |
| No defects recorded  |            |          |                |                |                    |                             |                   |                    |  |
| Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 July 2018      |            |          |                |                |                    |                             |                   |                    |  |
| No defects recorded  |            |          |                |                |                    |                             |                   |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 24 July 2018          |            |          |                |                |                    |                             |                   |                    |  |
| No defects recorded  |            |          |                |                |                    |                             |                   |                    |  |
| Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 July 2018      |            |          |                |                |                    |                             |                   |                    |  |
| No defects recorded  |            |          |                |                |                    |                             |                   |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 31 July 2018          |            |          |                |                |                    |                             |                   |                    |  |
| No defects recorded  |            |          |                |                |                    |                             |                   |                    |  |
| Safety Patrol of A77 Ayr North Safety Patrol V1 on 03 August 2018    |            |          |                |                |                    |                             |                   |                    |  |
| No defects recorded  |            |          |                |                |                    |                             |                   |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 07 August 2018        |            |          |                |                |                    |                             |                   |                    |  |
| No defects recorded  |            |          |                |                |                    |                             |                   |                    |  |
| Safety Patrol of A77 Ayr North Safety Patrol V1 on 10 August 2018    |            |          |                |                |                    |                             |                   |                    |  |
| No defects recorded  |            |          |                |                |                    |                             |                   |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 14 August 2018        |            |          |                |                |                    |                             |                   |                    |  |
| No defects recorded  |            |          |                |                |                    |                             |                   |                    |  |
| Safety Patrol of A77 Ayr North Safety Patrol V1 on 17 August 2018    |            |          |                |                |                    |                             |                   |                    |  |
| No defects recorded  |            |          |                |                |                    |                             |                   |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 21 August 2018        |            |          |                |                |                    |                             |                   |                    |  |
| No defects recorded  |            |          |                |                |                    |                             |                   |                    |  |
| Safety Patrol of A77 Ayr North Safety Patrol V1 on 24 August 2018    |            |          |                |                |                    |                             |                   |                    |  |
| No defects recorded  |            |          |                |                |                    |                             |                   |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 28 August 2018        |            |          |                |                |                    |                             |                   |                    |  |
| No defects recorded  |            |          |                |                |                    |                             |                   |                    |  |
| Safety Patrol of A77 Ayr North Safety Patrol V1 on 31 August 2018    |            |          |                |                |                    |                             |                   |                    |  |
| No defects recorded  |            |          |                |                |                    |                             |                   |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 04 September 2018     |            |          |                |                |                    |                             |                   |                    |  |
| No defects recorded  |            |          |                |                |                    |                             |                   |                    |  |
| Safety Patrol of A77 Ayr North Safety Patrol V1 ( Awaiting Return )  |            |          |                |                |                    |                             |                   |                    |  |
| No defects recorded  |            |          |                |                |                    |                             |                   |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 11 September 2018     |            |          |                |                |                    |                             |                   |                    |  |
| SW82406268-236054645   | 52m        | 52m      | LIGHTING_POINT | Damaged (DAMG) | CAT 1              | 09/10/2018                  | Completed Defects | 17/10/2018         | A77 S/B TOP OF ON SLIP BELLFIELD INTERCHANGE |
| Safety Patrol of A77 Ayr North Safety Patrol V1 on 14 September 2018 |            |          |                |                |                    |                             |                   |                    |  |
| No defects recorded  |            |          |                |                |                    |                             |                   |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 18 September 2018     |            |          |                |                |                    |                             |                   |                    |  |
| No defects recorded  |            |          |                |                |                    |                             |                   |                    |  |
| Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 September 2018 |            |          |                |                |                    |                             |                   |                    |  |
| No defects recorded  |            |          |                |                |                    |                             |                   |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 25 September 2018     |            |          |                |                |                    |                             |                   |                    |  |
| No defects recorded  |            |          |                |                |                    |                             |                   |                    |  |
| Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 September 2018 |            |          |                |                |                    |                             |                   |                    |  |
| No defects recorded  |            |          |                |                |                    |                             |                   |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 02 October 2018       |            |          |                |                |                    |                             |                   |                    |  |
| No defects recorded  |            |          |                |                |                    |                             |                   |                    |  |
| Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 October 2018   |            |          |                |                |                    |                             |                   |                    |  |
| No defects recorded  |            |          |                |                |                    |                             |                   |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 09 October 2018       |            |          |                |                |                    |                             |                   |                    |  |
| No defects recorded  |            |          |                |                |                    |                             |                   |                    |  |
| Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 October 2018   |            |          |                |                |                    |                             |                   |                    |  |
| No defects recorded  |            |          |                |                |                    |                             |                   |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 16 October 2018       |            |          |                |                |                    |                             |                   |                    |  |
| No defects recorded  |            |          |                |                |                    |                             |                   |                    |  |
| Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 October 2018   |            |          |                |                |                    |                             |                   |                    |  |
| No defects recorded  |            |          |                |                |                    |                             |                   |                    |  |



| Defect Reference   | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|--|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 October 2018</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 October 2018</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 October 2018</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 November 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 November 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 November 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 November 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 November 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 November 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 November 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 November 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 30 November 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 December 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 07 December 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 December 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 14 December 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 December 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 December 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 December 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 December 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 December 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 January 2019</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 January 2019</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 January 2019</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 January 2019</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018</b>   |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 January 2019</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 January 2019</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 January 2019</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 January 2019</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 January 2019</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 February 2019</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 February 2019</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 February 2019</b> |         |       |           |             |                 |                          |                |                 |                      |

| Defect Reference | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|------------------|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|
|------------------|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 12 February 2019**  
No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 February 2019**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 19 February 2019**  
No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 February 2019**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 26 February 2019**  
No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 March 2019**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 05 March 2019**  
No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 March 2019**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 12 March 2019**  
No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 March 2019**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 19 March 2019**  
No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 March 2019**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 26 March 2019**  
No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2019**  
No defects recorded

**11656/17 : WITH: HURLFORD INTERCHANGE-JCT OF N/B TR.ROAD**

**Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018**  
No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018**  
No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018**  
No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018**  
No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018**  
No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018**  
No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018**  
No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018**  
No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018**  
No defects recorded

**Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018**  
No defects recorded

| Defect Reference  | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|---|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 March 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 March 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 March 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 March 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 April 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 April 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 April 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 April 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 April 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 April 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 April 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 April 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 01 May 2018</b>   |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 May 2018</b>   |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 May 2018</b>   |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 May 2018</b>   |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 May 2018</b>   |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 May 2018</b>   |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 May 2018</b>   |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 May 2018</b>   |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 May 2018</b>   |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 June 2018</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 June 2018</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 June 2018</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 June 2018</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 June 2018</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 June 2018</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 June 2018</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 June 2018</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018</b>    |         |       |           |             |                 |                          |                |                 |                      |



| Defect Reference  | Start m | End m | Item Type | Item Detail     | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                  |
|---|---------|-------|-----------|-----------------|-----------------|--------------------------|-------------------|-----------------|---------------------------------------|
| <i>No defects recorded</i>  |         |       |           |                 |                 |                          |                   |                 |                                       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 June 2018</b>                              |         |       |           |                 |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |           |                 |                 |                          |                   |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 July 2018</b>                              |         |       |           |                 |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |           |                 |                 |                          |                   |                 |                                       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 06 July 2018</b>                              |         |       |           |                 |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |           |                 |                 |                          |                   |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 July 2018</b>                              |         |       |           |                 |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |           |                 |                 |                          |                   |                 |                                       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 July 2018</b>                              |         |       |           |                 |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |           |                 |                 |                          |                   |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 July 2018</b>                              |         |       |           |                 |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |           |                 |                 |                          |                   |                 |                                       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 July 2018</b>                              |         |       |           |                 |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |           |                 |                 |                          |                   |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 July 2018</b>                              |         |       |           |                 |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |           |                 |                 |                          |                   |                 |                                       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 July 2018</b>                              |         |       |           |                 |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |           |                 |                 |                          |                   |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 July 2018</b>                              |         |       |           |                 |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |           |                 |                 |                          |                   |                 |                                       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 03 August 2018</b>                            |         |       |           |                 |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |           |                 |                 |                          |                   |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 August 2018</b>                            |         |       |           |                 |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |           |                 |                 |                          |                   |                 |                                       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 10 August 2018</b>                            |         |       |           |                 |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |           |                 |                 |                          |                   |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 14 August 2018</b>                            |         |       |           |                 |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |           |                 |                 |                          |                   |                 |                                       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 17 August 2018</b>                            |         |       |           |                 |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |           |                 |                 |                          |                   |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 21 August 2018</b>                            |         |       |           |                 |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |           |                 |                 |                          |                   |                 |                                       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 24 August 2018</b>                            |         |       |           |                 |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |           |                 |                 |                          |                   |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 28 August 2018</b>                            |         |       |           |                 |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |           |                 |                 |                          |                   |                 |                                       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 31 August 2018</b>                            |         |       |           |                 |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |           |                 |                 |                          |                   |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 September 2018</b>                         |         |       |           |                 |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |           |                 |                 |                          |                   |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 September 2018</b><br>SW82406268-236054638 | 512m    | 512m  | GULLY     | Blockage (BLOK) | CAT 1           | 12/09/2018               | Completed Defects | 11/09/2018      | N/B ON SLIP FROM BELLFIELD INTERCANGE |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 14 September 2018</b>                         |         |       |           |                 |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |           |                 |                 |                          |                   |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 September 2018</b>                         |         |       |           |                 |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |           |                 |                 |                          |                   |                 |                                       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 September 2018</b>                         |         |       |           |                 |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |           |                 |                 |                          |                   |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 25 September 2018</b>                         |         |       |           |                 |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |           |                 |                 |                          |                   |                 |                                       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 September 2018</b>                         |         |       |           |                 |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |           |                 |                 |                          |                   |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 October 2018</b>                           |         |       |           |                 |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |           |                 |                 |                          |                   |                 |                                       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 October 2018</b>                           |         |       |           |                 |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |           |                 |                 |                          |                   |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 October 2018</b>                           |         |       |           |                 |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |           |                 |                 |                          |                   |                 |                                       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 October 2018</b>                           |         |       |           |                 |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |           |                 |                 |                          |                   |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 October 2018</b>                           |         |       |           |                 |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |           |                 |                 |                          |                   |                 |                                       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 October 2018</b>                           |         |       |           |                 |                 |                          |                   |                 |                                       |
| <i>No defects recorded</i>  |         |       |           |                 |                 |                          |                   |                 |                                       |

| Defect Reference   | Start m | End m | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description  |
|--|---------|-------|-------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 October 2018</b>  |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 October 2018</b>  |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 October 2018</b>  |         |       |             |                                      |                 |                          |                       |                 |   |
| SW82426035-236177506   | 336m    | 337m  | CARRIAGEWAY | Pothole (POTH)                       | CAT 1           | 27/11/2018               | Completed Defects     | 22/11/2018      | A77 NB CW OUTSIDE LANE<br>100M AFTER BELLFIELD<br>INTERCHANGE OFF SLIP ON<br>MAIN CARRIAGEWAY |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 November 2018</b> |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 November 2018</b> |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 November 2018</b> |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 November 2018</b> |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 November 2018</b> |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 November 2018</b> |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 November 2018</b> |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 November 2018</b> |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 30 November 2018</b> |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 December 2018</b> |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 07 December 2018</b> |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 December 2018</b> |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 14 December 2018</b> |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 December 2018</b> |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 December 2018</b> |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 December 2018</b> |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 December 2018</b> |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 December 2018</b> |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 January 2019</b>  |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 January 2019</b>  |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 January 2019</b>  |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 January 2019</b>  |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018</b>   |         |       |             |                                      |                 |                          |                       |                 |   |
| SW82332070-367   | 463m    | 468m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332070-276   | 145m    | 245m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 January 2019</b>  |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 January 2019</b>  |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 January 2019</b>  |         |       |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 January 2019</b>  |         |       |             |                                      |                 |                          |                       |                 |   |

| Defect Reference   | Start m | End m | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                              |
|--|---------|-------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|---|
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 January 2019</b>  |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |   |
| SW82433749-236325473   | 448m    | 448m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 23/02/2019               | Completed Defects | 22/02/2019      | A77 S/B LANE 2 @ BELLFEILD OFFSLIP @ SERVICE SIGN |
| SW82433749-236325467   | 133m    | 133m  | CARRIAGEWAY | Litter Grade C (LITC) | 3RD PTY         | 23/02/2019               | Completed Defects | 14/05/2019      | A77 N/B BELLFEILD ON SLIP                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>11620/10 : B734 KIRKPATRICK STREET ROUNDABOUT</b>                       |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>            |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>            |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>            |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>            |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b>           |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b>           |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b>           |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b>           |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>              |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>              |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>              |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>   |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>              |         |       |             |                       |                 |                          |                   |                 |   |

| Defect Reference | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|------------------|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|
|------------------|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|

*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 29 March 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 05 April 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 12 April 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 19 April 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 26 April 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 03 May 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 10 May 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 17 May 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 24 May 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 31 May 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 07 June 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 14 June 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 21 June 2018**  
*No defects recorded*  
**Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 28 June 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 05 July 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 12 July 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 19 July 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 26 July 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 02 August 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 09 August 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 16 August 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 23 August 2018**  
*No defects recorded*  
**Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 30 August 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 06 September 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 13 September 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 20 September 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 27 September 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 04 October 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 11 October 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 18 October 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 25 October 2018**  
*No defects recorded*

| Defect Reference | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|------------------|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|
|------------------|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|

**Safety Inspection of A77 Ayr South V1 on 01 November 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 08 November 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 15 November 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 22 November 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 29 November 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 06 December 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 13 December 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 20 December 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 27 December 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 03 January 2019**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 10 January 2019**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 17 January 2019**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 24 January 2019**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 31 January 2019**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 07 February 2019**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 14 February 2019**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 21 February 2019**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 28 February 2019**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 07 March 2019**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 14 March 2019**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 21 March 2019**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 28 March 2019**  
*No defects recorded*

**11620/12 : B734 KIRKPATRICK STREET RBT TO YOUNG STREET**

**Safety Inspection of A77 Ayr South V1 on 04 January 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 11 January 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 18 January 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 25 January 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 01 February 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 08 February 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 15 February 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 22 February 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 01 March 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 08 March 2018**  
*No defects recorded*

**Safety Inspection of A77 Ayr South V1 on 15 March 2018**  
*No defects recorded*



| Defect Reference  | Start m | End m | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                         |
|---|---------|-------|-------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|--|
| SW82328086-235590028  | 25m     | 26m   | CARRIAGEWAY | Pothole (POTH)                       | CAT 1           | 12/04/2018               | Completed Defects     | 15/03/2018      | A77 NB CW, GIRVAN 50M NTH OF MINI RBT        |
| Safety Inspection of A77 Ayr South V1 on 22 March 2018<br><i>No defects recorded</i>        |         |       |             |                                      |                 |                          |                       |                 |  |
| Safety Inspection of A77 Ayr South V1 on 29 March 2018<br><i>No defects recorded</i>        |         |       |             |                                      |                 |                          |                       |                 |  |
| Safety Inspection of A77 Ayr South V1 on 05 April 2018<br><i>No defects recorded</i>        |         |       |             |                                      |                 |                          |                       |                 |  |
| Safety Inspection of A77 Ayr South V1 on 12 April 2018<br><i>No defects recorded</i>        |         |       |             |                                      |                 |                          |                       |                 |  |
| Safety Inspection of A77 Ayr South V1 on 19 April 2018<br><i>No defects recorded</i>        |         |       |             |                                      |                 |                          |                       |                 |  |
| Safety Inspection of A77 Ayr South V1 on 26 April 2018<br><i>No defects recorded</i>        |         |       |             |                                      |                 |                          |                       |                 |  |
| Safety Inspection of A77 Ayr South V1 on 03 May 2018<br><i>No defects recorded</i>          |         |       |             |                                      |                 |                          |                       |                 |  |
| Safety Inspection of A77 Ayr South V1 on 10 May 2018<br><i>No defects recorded</i>          |         |       |             |                                      |                 |                          |                       |                 |  |
| Safety Inspection of A77 Ayr South V1 on 17 May 2018<br><i>No defects recorded</i>          |         |       |             |                                      |                 |                          |                       |                 |  |
| SW82352984-235812706  | 92m     | 93m   | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 21/06/2018               | Completed Defects     | 24/05/2018      | NB CW OPPOSITE NUMBER 9 KILPATRICK ST GIRVAN |
| Safety Inspection of A77 Ayr South V1 on 31 May 2018<br><i>No defects recorded</i>          |         |       |             |                                      |                 |                          |                       |                 |  |
| Safety Inspection of A77 Ayr South V1 on 07 June 2018<br><i>No defects recorded</i>         |         |       |             |                                      |                 |                          |                       |                 |  |
| Safety Inspection of A77 Ayr South V1 on 14 June 2018<br><i>No defects recorded</i>         |         |       |             |                                      |                 |                          |                       |                 |  |
| Safety Inspection of A77 Ayr South V1 on 21 June 2018<br><i>No defects recorded</i>         |         |       |             |                                      |                 |                          |                       |                 |  |
| Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018<br><i>No defects recorded</i> |         |       |             |                                      |                 |                          |                       |                 |  |
| Safety Inspection of A77 Ayr South V1 on 28 June 2018<br><i>No defects recorded</i>         |         |       |             |                                      |                 |                          |                       |                 |  |
| Safety Inspection of A77 Ayr South V1 on 05 July 2018<br><i>No defects recorded</i>         |         |       |             |                                      |                 |                          |                       |                 |  |
| Safety Inspection of A77 Ayr South V1 on 12 July 2018<br><i>No defects recorded</i>         |         |       |             |                                      |                 |                          |                       |                 |  |
| Safety Inspection of A77 Ayr South V1 on 19 July 2018<br><i>No defects recorded</i>         |         |       |             |                                      |                 |                          |                       |                 |  |
| Safety Inspection of A77 Ayr South V1 on 26 July 2018<br><i>No defects recorded</i>         |         |       |             |                                      |                 |                          |                       |                 |  |
| Safety Inspection of A77 Ayr South V1 on 02 August 2018<br><i>No defects recorded</i>       |         |       |             |                                      |                 |                          |                       |                 |  |
| Safety Inspection of A77 Ayr South V1 on 09 August 2018<br><i>No defects recorded</i>       |         |       |             |                                      |                 |                          |                       |                 |  |
| Safety Inspection of A77 Ayr South V1 on 16 August 2018<br><i>No defects recorded</i>       |         |       |             |                                      |                 |                          |                       |                 |  |
| Safety Inspection of A77 Ayr South V1 on 23 August 2018<br><i>No defects recorded</i>       |         |       |             |                                      |                 |                          |                       |                 |  |
| Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018                               |         |       |             |                                      |                 |                          |                       |                 |  |
| SW82332071-528  | 59m     | 75m   | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| Safety Inspection of A77 Ayr South V1 on 30 August 2018<br><i>No defects recorded</i>       |         |       |             |                                      |                 |                          |                       |                 |  |
| Safety Inspection of A77 Ayr South V1 on 06 September 2018<br><i>No defects recorded</i>    |         |       |             |                                      |                 |                          |                       |                 |  |
| Safety Inspection of A77 Ayr South V1 on 13 September 2018<br><i>No defects recorded</i>    |         |       |             |                                      |                 |                          |                       |                 |  |
| Safety Inspection of A77 Ayr South V1 on 20 September 2018<br><i>No defects recorded</i>    |         |       |             |                                      |                 |                          |                       |                 |  |
| Safety Inspection of A77 Ayr South V1 on 27 September 2018<br><i>No defects recorded</i>    |         |       |             |                                      |                 |                          |                       |                 |  |

| Defect Reference   | Start<br>m | End<br>m | Item Type   | Item Detail              | Defect<br>Category | Required<br>Completion Date | Current Status       | Completion<br>Date | Location Description                            |
|--|------------|----------|-------------|--------------------------|--------------------|-----------------------------|----------------------|--------------------|---|
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>  |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>  |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>  |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>  |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b> |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b> |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b> |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b> |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b> |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b> |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b> |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b> |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b> |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>  |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>  |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>  |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>  |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>  |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b> |            |          |             |                          |                    |                             |                      |                    |   |
| SW82429489-236310405   | 86m        | 87m      | CARRIAGEWAY | Pothole VIAFIX<br>(POTV) | CAT 1              | 07/03/2019                  | Completed<br>Defects | 08/02/2019         | A77 ON CL, KIRKPATRICK<br>STREET, OUTSIDE NO.11 |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b> |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b> |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b> |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>    |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>    |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>    |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>    |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>11620/13 : YOUNG STREET TO DUNCAN STREET</b>                  |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>  |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>  |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>  |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>  |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b> |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b> |            |          |             |                          |                    |                             |                      |                    |   |

| Defect Reference   | Start m | End m | Item Type   | Item Detail    | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                   |
|--|---------|-------|-------------|----------------|-----------------|--------------------------|-------------------|-----------------|--|
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b>     |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b>     |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>        |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>        |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>        |         |       |             |                |                 |                          |                   |                 |  |
| SW82328086-235590030   | 360m    | 361m  | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 12/04/2018               | Completed Defects | 15/03/2018      | A77 NB CW, 20M PRIOR PARK GIRVAN BEACH |
| SW82328086-235590029   | 149m    | 152m  | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 12/04/2018               | Completed Defects | 15/03/2018      | A77 NB CW, AT YOUNG STREET JCT, GIRVAN |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>        |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>        |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>        |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>        |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>        |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>        |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>          |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>          |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |         |       |             |                |                 |                          |                   |                 |  |



| Defect Reference  | Start m | End m | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description  |
|---|---------|-------|-------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| SW82332071-530  | 427m    | 447m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-529  | 60m     | 100m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>    |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b> |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b> |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b> |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b> |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>   |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>   |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>   |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>   |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>  |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>  |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>  |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b>  |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b>  |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b>  |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b>  |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b>  |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b>  |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>   |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>   |         |       |             |                                      |                 |                          |                       |                 |   |
| SW82428044-236270552  | 155m    | 156m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 11/01/2019               | Completed Defects     | 10/01/2019      | A77 SB CW ON CORNER OF GEORGE STRT ON HENRIETTA STREET GIRVAN   |
| SW82428044-236270551  | 143m    | 144m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 11/01/2019               | Completed Defects     | 10/01/2019      | A77 NB CW CORNER OF GEORGE STREET AND HENRIETTA STREET GIRVAN   |
| SW82428044-236270553  | 162m    | 163m  | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 11/01/2019               | Completed Defects     | 10/01/2019      | A77 SB CW AT CORNER OF GEORGE STREET ON HENRIETTA STREET GIRVAN |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>   |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>   |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>   |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b>  |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b>  |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b>  |         |       |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |       |             |                                      |                 |                          |                       |                 |   |

| Defect Reference   | Start m | End m | Item Type   | Item Detail    | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description   |
|--|---------|-------|-------------|----------------|-----------------|--------------------------|-------------------|-----------------|--|
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b>     |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>        |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>        |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>        |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>        |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>11620/26 : DUNCAN STREET TO HENRIETTA STREET RBT</b>              |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>      |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>      |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>      |         |       |             |                |                 |                          |                   |                 |  |
| SW82317666-235521319   | 365m    | 366m  | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 15/02/2018               | Completed Defects | 04/02/2018      | A77 NB CW, AT CENTER ISLAND PRIOR TO HENRIETTA STREET MINI RBT, GIRVAN |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>      |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b>     |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b>     |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b>     |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b>     |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>        |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>        |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>        |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>        |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>        |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>        |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>        |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>        |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>        |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>          |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>          |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |         |       |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |             |                |                 |                          |                   |                 |  |

| Defect Reference   | Start<br>m | End<br>m | Item Type | Item Detail        | Defect<br>Category | Required<br>Completion Date | Current Status       | Completion<br>Date | Location Description   |
|--|------------|----------|-----------|--------------------|--------------------|-----------------------------|----------------------|--------------------|--|
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |            |          |           |                    |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |                    |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |            |          |           |                    |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |                    |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |            |          |           |                    |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |                    |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |            |          |           |                    |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |                    |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |            |          |           |                    |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |                    |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |            |          |           |                    |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |                    |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |            |          |           |                    |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |                    |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |            |          |           |                    |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |                    |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |            |          |           |                    |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |                    |                    |                             |                      |                    |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |            |          |           |                    |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |                    |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>       |            |          |           |                    |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |                    |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b>    |            |          |           |                    |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |                    |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b>    |            |          |           |                    |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |                    |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b>    |            |          |           |                    |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |                    |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b>    |            |          |           |                    |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |                    |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>      |            |          |           |                    |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |                    |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>      |            |          |           |                    |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |                    |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>      |            |          |           |                    |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |                    |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>      |            |          |           |                    |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |                    |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>     |            |          |           |                    |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |                    |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>     |            |          |           |                    |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |                    |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>     |            |          |           |                    |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |                    |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b>     |            |          |           |                    |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |                    |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b>     |            |          |           |                    |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |                    |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b>     |            |          |           |                    |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |                    |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b>     |            |          |           |                    |                    |                             |                      |                    |  |
| SW82427366-236262612   | 206m       | 207m     | GULLY     | Blockage<br>(BLOK) | CAT 1              | 10/01/2019                  | Completed<br>Defects | 13/12/2018         | A77 NB FW, AT NEW PED<br>CROSSING HENRIETTA<br>STREET GIRVAN |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b>     |            |          |           |                    |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |                    |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b>     |            |          |           |                    |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |                    |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>      |            |          |           |                    |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |                    |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>      |            |          |           |                    |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |                    |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>      |            |          |           |                    |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |                    |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>      |            |          |           |                    |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |           |                    |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>      |            |          |           |                    |                    |                             |                      |                    |  |

| Defect Reference | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|------------------|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|
|------------------|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|

*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 07 February 2019**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 14 February 2019**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 21 February 2019**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 28 February 2019**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 07 March 2019**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 14 March 2019**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 21 March 2019**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 28 March 2019**  
*No defects recorded*

**11620/33 : HENRIETTA STREET ROUNDABOUT**

**Safety Inspection of A77 Ayr South V1 on 04 January 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 11 January 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 18 January 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 25 January 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 01 February 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 08 February 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 15 February 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 22 February 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 01 March 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 08 March 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 15 March 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 22 March 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 29 March 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 05 April 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 12 April 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 19 April 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 26 April 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 03 May 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 10 May 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 17 May 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 24 May 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 31 May 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 07 June 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 14 June 2018**  
*No defects recorded*

| Defect Reference   | Start<br>m | End<br>m | Item Type | Item Detail | Defect<br>Category | Required<br>Completion Date | Current Status | Completion<br>Date | Location Description |
|--|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b><br><i>No defects recorded</i>         |            |          |           |             |                    |                             |                |                    |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b><br><i>No defects recorded</i> |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b><br><i>No defects recorded</i>         |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b><br><i>No defects recorded</i>         |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b><br><i>No defects recorded</i>         |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b><br><i>No defects recorded</i>         |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b><br><i>No defects recorded</i>         |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b><br><i>No defects recorded</i>       |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b><br><i>No defects recorded</i>       |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b><br><i>No defects recorded</i>       |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b><br><i>No defects recorded</i>       |            |          |           |             |                    |                             |                |                    |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b><br><i>No defects recorded</i> |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b><br><i>No defects recorded</i>       |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b><br><i>No defects recorded</i>    |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b><br><i>No defects recorded</i>    |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b><br><i>No defects recorded</i>    |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b><br><i>No defects recorded</i>    |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b><br><i>No defects recorded</i>      |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b><br><i>No defects recorded</i>      |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b><br><i>No defects recorded</i>      |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b><br><i>No defects recorded</i>      |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b><br><i>No defects recorded</i>     |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b><br><i>No defects recorded</i>     |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b><br><i>No defects recorded</i>     |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b><br><i>No defects recorded</i>     |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b><br><i>No defects recorded</i>     |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b><br><i>No defects recorded</i>     |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b><br><i>No defects recorded</i>     |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b><br><i>No defects recorded</i>     |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b><br><i>No defects recorded</i>     |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b><br><i>No defects recorded</i>      |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b><br><i>No defects recorded</i>      |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b><br><i>No defects recorded</i>      |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>                                    |            |          |           |             |                    |                             |                |                    |                      |

| Defect Reference   | Start m | End m | Item Type   | Item Detail    | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                                    |
|--|---------|-------|-------------|----------------|-----------------|--------------------------|-------------------|-----------------|---|
| <i>No defects recorded</i>                                       |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>  |         |       |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b> |         |       |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b> |         |       |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b> |         |       |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b> |         |       |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>    |         |       |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>    |         |       |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>    |         |       |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>    |         |       |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                |                 |                          |                   |                 |   |
| <b>11620/34 : HENRIETTA STREET RBT TO STUMPY CORNER</b>          |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>  |         |       |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>  |         |       |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>  |         |       |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>  |         |       |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b> |         |       |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b> |         |       |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b> |         |       |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b> |         |       |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>    |         |       |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>    |         |       |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>    |         |       |             |                |                 |                          |                   |                 |   |
| SW82328086-235590031   | 15m     | 20m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 12/04/2018               | Completed Defects | 15/03/2018      | A77 NB CW, BETWEEN HENRIETTA MINI RBT AND STUMPY CORNER |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>    |         |       |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>    |         |       |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>    |         |       |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>    |         |       |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>    |         |       |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>    |         |       |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>      |         |       |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>      |         |       |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>      |         |       |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>      |         |       |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>      |         |       |             |                |                 |                          |                   |                 |   |

| Defect Reference | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|------------------|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|
|------------------|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|

*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 07 June 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 14 June 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 21 June 2018**  
*No defects recorded*  
**Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 28 June 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 05 July 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 12 July 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 19 July 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 26 July 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 02 August 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 09 August 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 16 August 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 23 August 2018**  
*No defects recorded*

**Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018**

|                |      |      |                    |                                      |       |            |                       |            |  |
|----------------|------|------|--------------------|--------------------------------------|-------|------------|-----------------------|------------|--|
| SW82332071-532 | 29m  | 109m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 |  |
| SW82332071-533 | 94m  | 174m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 |  |
| SW82332071-536 | 118m | 198m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 |  |
| SW82332071-534 | 59m  | 140m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 |  |
| SW82332071-535 | 70m  | 71m  | TRAFFIC_SIGNS      | Physical condition of post (COPT)    | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 |  |
| SW82332071-531 | 11m  | 111m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 |  |

**Safety Inspection of A77 Ayr South V1 on 30 August 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 06 September 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 13 September 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 20 September 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 27 September 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 04 October 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 11 October 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 18 October 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 25 October 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 01 November 2018**

| Defect Reference  | Start m | End m | Item Type     | Item Detail  | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description   |
|---|---------|-------|---------------|--------------|-----------------|--------------------------|-------------------|-----------------|--|
| <i>No defects recorded</i>  |         |       |               |              |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b><br>SW82426441-236211989                                      | 5m      | 5m    | TRAFFIC_SIGNS | Other (OTHR) | CAT 1           | 06/12/2018               | Completed Defects | 08/11/2018      | A77 CENTRAL ISLAND<br>OUTSIDE HARBOUR BAR<br>HENRIETTA STREET GIRVAN |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b><br><i>No defects recorded</i>                                |         |       |               |              |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b><br><i>No defects recorded</i>                                |         |       |               |              |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b><br><i>No defects recorded</i>                                |         |       |               |              |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b><br><i>No defects recorded</i>                                |         |       |               |              |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b><br><i>No defects recorded</i>                                |         |       |               |              |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b><br><i>No defects recorded</i>                                |         |       |               |              |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b><br><i>No defects recorded</i>                                |         |       |               |              |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b><br><i>No defects recorded</i>                                 |         |       |               |              |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b><br><i>No defects recorded</i>                                 |         |       |               |              |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b><br><i>No defects recorded</i>                                 |         |       |               |              |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b><br><i>No defects recorded</i>                                 |         |       |               |              |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b><br><i>No defects recorded</i>                                 |         |       |               |              |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b><br><i>No defects recorded</i>                                |         |       |               |              |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b><br><i>No defects recorded</i>                                |         |       |               |              |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b><br><i>No defects recorded</i>                                |         |       |               |              |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b><br><i>No defects recorded</i>                                |         |       |               |              |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b><br><i>No defects recorded</i>                                   |         |       |               |              |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b><br><i>No defects recorded</i>                                   |         |       |               |              |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b><br><i>No defects recorded</i>                                   |         |       |               |              |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b><br><i>No defects recorded</i>                                   |         |       |               |              |                 |                          |                   |                 |  |
| <b>11620/37 : Against: STUMPY CORNER TO WESLEY ROAD</b>   |         |       |               |              |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b><br><i>No defects recorded</i>                                 |         |       |               |              |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b><br><i>No defects recorded</i>                                 |         |       |               |              |                 |                          |                   |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Girvan Footways V1 on 18 January 2018</b><br><i>No defects recorded</i>  |         |       |               |              |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b><br><i>No defects recorded</i>                                 |         |       |               |              |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b><br><i>No defects recorded</i>                                 |         |       |               |              |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b><br><i>No defects recorded</i>                                |         |       |               |              |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b><br><i>No defects recorded</i>                                |         |       |               |              |                 |                          |                   |                 |  |
| <b>Detailed Inspections - Category A Footways of A77 Girvan Footways V1 on 15 February 2018</b><br><i>No defects recorded</i> |         |       |               |              |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b><br><i>No defects recorded</i>                                |         |       |               |              |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b>  |         |       |               |              |                 |                          |                   |                 |  |



| Defect Reference  | Start m | End m | Item Type     | Item Detail    | Defect Category | Required Completion Date | Current Status               | Completion Date | Location Description                                      |
|---|---------|-------|---------------|----------------|-----------------|--------------------------|------------------------------|-----------------|---|
| <i>No defects recorded</i>  |         |       |               |                |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>                                 |         |       |               |                |                 |                          |                              |                 |   |
| <i>No defects recorded</i>  |         |       |               |                |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>                                 |         |       |               |                |                 |                          |                              |                 |   |
| <i>No defects recorded</i>  |         |       |               |                |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>                                 |         |       |               |                |                 |                          |                              |                 |   |
| <i>No defects recorded</i>  |         |       |               |                |                 |                          |                              |                 |   |
| <b>Detailed Inspections - Category A Footways of A77 Girvan Footways V1 on 16 March 2018</b>  |         |       |               |                |                 |                          |                              |                 |   |
| SW82327807-1  | 266m    | 306m  | FOOTWAY       | Other (OTHR)   | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action        | 01/01/9999      | GIRVAN FOOTWAY BOTH SIDES FOR 40M WITH 7 1M AREAS OF DIPS |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>                                 |         |       |               |                |                 |                          |                              |                 |   |
| <i>No defects recorded</i>  |         |       |               |                |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>                                 |         |       |               |                |                 |                          |                              |                 |   |
| <i>No defects recorded</i>  |         |       |               |                |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>                                 |         |       |               |                |                 |                          |                              |                 |   |
| <i>No defects recorded</i>  |         |       |               |                |                 |                          |                              |                 |   |
| <b>Detailed Inspections - Category A Footways of A77 Girvan Footways V1 on 12 April 2018</b>  |         |       |               |                |                 |                          |                              |                 |   |
| <i>No defects recorded</i>  |         |       |               |                |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>                                 |         |       |               |                |                 |                          |                              |                 |   |
| <i>No defects recorded</i>  |         |       |               |                |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>                                 |         |       |               |                |                 |                          |                              |                 |   |
| <i>No defects recorded</i>  |         |       |               |                |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>                                 |         |       |               |                |                 |                          |                              |                 |   |
| <i>No defects recorded</i>  |         |       |               |                |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>                                   |         |       |               |                |                 |                          |                              |                 |   |
| <i>No defects recorded</i>  |         |       |               |                |                 |                          |                              |                 |   |
| <b>Detailed Inspections - Category A Footways of A77 Girvan Footways V1 on 10 May 2018</b>    |         |       |               |                |                 |                          |                              |                 |   |
| <i>No defects recorded</i>  |         |       |               |                |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>                                   |         |       |               |                |                 |                          |                              |                 |   |
| <i>No defects recorded</i>  |         |       |               |                |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>                                   |         |       |               |                |                 |                          |                              |                 |   |
| <i>No defects recorded</i>  |         |       |               |                |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>                                   |         |       |               |                |                 |                          |                              |                 |   |
| <i>No defects recorded</i>  |         |       |               |                |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>                                   |         |       |               |                |                 |                          |                              |                 |   |
| <i>No defects recorded</i>  |         |       |               |                |                 |                          |                              |                 |   |
| <b>Detailed Inspections - Category A Footways of A77 Girvan Footways V1 on 07 June 2018</b>   |         |       |               |                |                 |                          |                              |                 |   |
| <i>No defects recorded</i>  |         |       |               |                |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>                                  |         |       |               |                |                 |                          |                              |                 |   |
| <i>No defects recorded</i>  |         |       |               |                |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>                                  |         |       |               |                |                 |                          |                              |                 |   |
| <i>No defects recorded</i>  |         |       |               |                |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>                                  |         |       |               |                |                 |                          |                              |                 |   |
| <i>No defects recorded</i>  |         |       |               |                |                 |                          |                              |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b>                          |         |       |               |                |                 |                          |                              |                 |   |
| <i>No defects recorded</i>  |         |       |               |                |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>                                  |         |       |               |                |                 |                          |                              |                 |   |
| <i>No defects recorded</i>  |         |       |               |                |                 |                          |                              |                 |   |
| <b>Detailed Inspections - Category A Footways of A77 Girvan Footways V1 on 05 July 2018</b>   |         |       |               |                |                 |                          |                              |                 |   |
| <i>No defects recorded</i>  |         |       |               |                |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>                                  |         |       |               |                |                 |                          |                              |                 |   |
| <i>No defects recorded</i>  |         |       |               |                |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>                                  |         |       |               |                |                 |                          |                              |                 |   |
| <i>No defects recorded</i>  |         |       |               |                |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>                                  |         |       |               |                |                 |                          |                              |                 |   |
| <i>No defects recorded</i>  |         |       |               |                |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>                                  |         |       |               |                |                 |                          |                              |                 |   |
| <i>No defects recorded</i>  |         |       |               |                |                 |                          |                              |                 |   |
| <b>Detailed Inspections - Category A Footways of A77 Girvan Footways V1 on 02 August 2018</b> |         |       |               |                |                 |                          |                              |                 |   |
| <i>No defects recorded</i>  |         |       |               |                |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>                                |         |       |               |                |                 |                          |                              |                 |   |
| <i>No defects recorded</i>  |         |       |               |                |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>                                |         |       |               |                |                 |                          |                              |                 |   |
| SW80-390684-235944666   | 314m    | 314m  | TRAFFIC_SIGNS | Damaged (DAMG) | CAT 1           | 06/09/2018               | Awaiting CCMS Permanent Date | 01/01/9999      | A77 SB CW DALRYMPLE ST GIRVAN OPOSITE LADBROKES           |

| Defect Reference   | Start<br>m | End<br>m | Item Type   | Item Detail                          | Defect<br>Category | Required<br>Completion Date | Current Status          | Completion<br>Date | Location Description                         |
|--|------------|----------|-------------|--------------------------------------|--------------------|-----------------------------|-------------------------|--------------------|--|
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>                                   |            |          |             |                                      |                    |                             |                         |                    |  |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                         |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>                                   |            |          |             |                                      |                    |                             |                         |                    |  |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                         |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>                                   |            |          |             |                                      |                    |                             |                         |                    |  |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                         |                    |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b>                             |            |          |             |                                      |                    |                             |                         |                    |  |
| SW82332071-537   | 47m        | 49m      | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action   | 01/01/9999         |  |
| SW82332071-538   | 159m       | 160m     | CARRIAGEWAY | Cracking around ironwork (CKIR)      | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action   | 01/01/9999         |  |
| <b>Detailed Inspections - Category A Footways of A77 Girvan Footways V1 on 31 August 2018</b>    |            |          |             |                                      |                    |                             |                         |                    |  |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                         |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b>                                |            |          |             |                                      |                    |                             |                         |                    |  |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                         |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b>                                |            |          |             |                                      |                    |                             |                         |                    |  |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                         |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b>                                |            |          |             |                                      |                    |                             |                         |                    |  |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                         |                    |  |
| <b>Detailed Inspections - Category A Footways of A77 Girvan Footways V1 on 24 September 2018</b> |            |          |             |                                      |                    |                             |                         |                    |  |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                         |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b>                                |            |          |             |                                      |                    |                             |                         |                    |  |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                         |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>                                  |            |          |             |                                      |                    |                             |                         |                    |  |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                         |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>                                  |            |          |             |                                      |                    |                             |                         |                    |  |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                         |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>                                  |            |          |             |                                      |                    |                             |                         |                    |  |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                         |                    |  |
| <b>Detailed Inspections - Category A Footways of A77 Girvan Footways V1 on 25 October 2018</b>   |            |          |             |                                      |                    |                             |                         |                    |  |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                         |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>                                  |            |          |             |                                      |                    |                             |                         |                    |  |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                         |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>                                 |            |          |             |                                      |                    |                             |                         |                    |  |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                         |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>                                 |            |          |             |                                      |                    |                             |                         |                    |  |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                         |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>                                 |            |          |             |                                      |                    |                             |                         |                    |  |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                         |                    |  |
| <b>Detailed Inspections - Category A Footways of A77 Girvan Footways V1 on 22 November 2018</b>  |            |          |             |                                      |                    |                             |                         |                    |  |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                         |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b>                                 |            |          |             |                                      |                    |                             |                         |                    |  |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                         |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b>                                 |            |          |             |                                      |                    |                             |                         |                    |  |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                         |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b>                                 |            |          |             |                                      |                    |                             |                         |                    |  |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                         |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b>                                 |            |          |             |                                      |                    |                             |                         |                    |  |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                         |                    |  |
| <b>Detailed Inspections - Category A Footways of A77 Girvan Footways V1 on 20 December 2018</b>  |            |          |             |                                      |                    |                             |                         |                    |  |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                         |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b>                                 |            |          |             |                                      |                    |                             |                         |                    |  |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                         |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b>                                 |            |          |             |                                      |                    |                             |                         |                    |  |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                         |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>                                  |            |          |             |                                      |                    |                             |                         |                    |  |
| SW82427890-236270554   | 49m        | 49m      | GULLY       | Other (OTHR)                         | 3RD PTY            | 31/01/2019                  | Awaiting CCMS Temp Date | 01/01/9999         | A77 SB CW, GIRVIN MAIN STREET OUTSIDE GREGGS |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>                                  |            |          |             |                                      |                    |                             |                         |                    |  |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                         |                    |  |
| <b>Detailed Inspections - Category A Footways of A77 Girvan Footways V1 on 17 January 2019</b>   |            |          |             |                                      |                    |                             |                         |                    |  |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                         |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>                                  |            |          |             |                                      |                    |                             |                         |                    |  |

| Defect Reference | Start<br>m | End<br>m | Item Type | Item Detail | Defect<br>Category | Required<br>Completion Date | Current Status | Completion<br>Date | Location Description |
|------------------|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|
|------------------|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|

No defects recorded  
**Safety Inspection of A77 Ayr South V1 on 24 January 2019**

No defects recorded  
**Safety Inspection of A77 Ayr South V1 on 31 January 2019**

No defects recorded  
**Safety Inspection of A77 Ayr South V1 on 07 February 2019**

No defects recorded  
**Safety Inspection of A77 Ayr South V1 on 14 February 2019**

No defects recorded  
**Detailed Inspections - Category A Footways of A77 Girvan Footways V1 on 15 February 2019**

No defects recorded  
**Safety Inspection of A77 Ayr South V1 on 21 February 2019**

No defects recorded  
**Safety Inspection of A77 Ayr South V1 on 28 February 2019**

No defects recorded  
**Safety Inspection of A77 Ayr South V1 on 07 March 2019**

No defects recorded  
**Safety Inspection of A77 Ayr South V1 on 14 March 2019**

No defects recorded  
**Detailed Inspections - Category A Footways of A77 Girvan Footways V1 on 15 March 2019**

No defects recorded  
**Safety Inspection of A77 Ayr South V1 on 21 March 2019**

No defects recorded  
**Safety Inspection of A77 Ayr South V1 on 28 March 2019**

**11620/49 : DUFF STREET TO KIRKPATRICK STREET RBT**

**Safety Inspection of A77 Ayr South V1 on 04 January 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 11 January 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 18 January 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 25 January 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 01 February 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 08 February 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 15 February 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 22 February 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 01 March 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 08 March 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 15 March 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 22 March 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 29 March 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 05 April 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 12 April 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 19 April 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 26 April 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 03 May 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 10 May 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 17 May 2018**  
No defects recorded

| Defect Reference   | Start<br>m | End<br>m | Item Type              | Item Detail                                | Defect<br>Category | Required<br>Completion Date | Current Status           | Completion<br>Date | Location Description |
|--|------------|----------|------------------------|--|--------------------|-----------------------------|--------------------------|--------------------|----------------------|
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>       |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |            |          |                        |  |                    |                             |                          |                    |                      |
| SW82332071-541   | 162m       | 200m     | CARRIAGEWAY            | Bituminous<br>surfacing<br>fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                      |
| SW82332071-543   | 364m       | 400m     | CARRIAGEWAY            | Bituminous<br>surfacing<br>fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                      |
| SW82332071-542   | 239m       | 339m     | ROAD_MARKINGS<br>_LONG | Wear (for<br>example<br>erosion)<br>(WEAR) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b>    |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b>    |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b>    |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b>    |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>      |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>      |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>      |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>      |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>     |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>     |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>     |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b>     |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |

| Defect Reference   | Start<br>m | End<br>m | Item Type     | Item Detail                       | Defect<br>Category | Required<br>Completion Date | Current Status    | Completion<br>Date | Location Description                                   |
|--|------------|----------|---------------|-----------------------------------|--------------------|-----------------------------|-------------------|--------------------|--|
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <i>No defects recorded</i>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <i>No defects recorded</i>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <i>No defects recorded</i>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <i>No defects recorded</i>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b>   |            |          |               |                                   |                    |                             |                   |                    |  |
| SW82427658-236270447   | 24m        | 25m      | TRAFFIC_SIGNS | Physical condition of post (COPT) | CAT 1              | 24/01/2019                  | Completed Defects | 27/12/2018         | A77 SB OUTSIDE AGE CONCERN GIRVAN AT DUFF STREET JCT   |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>    |            |          |               |                                   |                    |                             |                   |                    |  |
| <i>No defects recorded</i>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>    |            |          |               |                                   |                    |                             |                   |                    |  |
| <i>No defects recorded</i>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>    |            |          |               |                                   |                    |                             |                   |                    |  |
| <i>No defects recorded</i>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>    |            |          |               |                                   |                    |                             |                   |                    |  |
| <i>No defects recorded</i>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>    |            |          |               |                                   |                    |                             |                   |                    |  |
| <i>No defects recorded</i>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <i>No defects recorded</i>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <i>No defects recorded</i>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <i>No defects recorded</i>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <i>No defects recorded</i>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>      |            |          |               |                                   |                    |                             |                   |                    |  |
| <i>No defects recorded</i>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>      |            |          |               |                                   |                    |                             |                   |                    |  |
| <i>No defects recorded</i>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>      |            |          |               |                                   |                    |                             |                   |                    |  |
| <i>No defects recorded</i>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>      |            |          |               |                                   |                    |                             |                   |                    |  |
| <i>No defects recorded</i>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <b>11617/73 : ARDMILLAN CASTLE TO A714 SHALLOCHPARK ROUNDABOUT</b> |            |          |               |                                   |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>    |            |          |               |                                   |                    |                             |                   |                    |  |
| <i>No defects recorded</i>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>    |            |          |               |                                   |                    |                             |                   |                    |  |
| <i>No defects recorded</i>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>    |            |          |               |                                   |                    |                             |                   |                    |  |
| <i>No defects recorded</i>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>    |            |          |               |                                   |                    |                             |                   |                    |  |
| <i>No defects recorded</i>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <i>No defects recorded</i>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <i>No defects recorded</i>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <i>No defects recorded</i>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <i>No defects recorded</i>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>      |            |          |               |                                   |                    |                             |                   |                    |  |
| SW82323945-235550796   | 1,647m     | 1,648m   | CARRIAGEWAY   | Pothole (POTH)                    | CAT 1              | 29/03/2018                  | Completed Defects | 01/03/2018         | A77 SB CW, 1500M STH OF SHALLOWPARK RBT, STH OF GIRVAN |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>      |            |          |               |                                   |                    |                             |                   |                    |  |
| <i>No defects recorded</i>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>      |            |          |               |                                   |                    |                             |                   |                    |  |
| <i>No defects recorded</i>   |            |          |               |                                   |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>      |            |          |               |                                   |                    |                             |                   |                    |  |
| <i>No defects recorded</i>   |            |          |               |                                   |                    |                             |                   |                    |  |

| Defect Reference   | Start<br>m | End<br>m | Item Type      | Item Detail                                | Defect<br>Category | Required<br>Completion Date | Current Status                  | Completion<br>Date | Location Description   |
|--|------------|----------|----------------|--|--------------------|-----------------------------|---------------------------------|--------------------|--|
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>        |            |          |                |  |                    |                             |                                 |                    |  |
| <i>No defects recorded</i>   |            |          |                |  |                    |                             |                                 |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>        |            |          |                |  |                    |                             |                                 |                    |  |
| <i>No defects recorded</i>   |            |          |                |  |                    |                             |                                 |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>        |            |          |                |  |                    |                             |                                 |                    |  |
| <i>No defects recorded</i>   |            |          |                |  |                    |                             |                                 |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>        |            |          |                |  |                    |                             |                                 |                    |  |
| <i>No defects recorded</i>   |            |          |                |  |                    |                             |                                 |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>        |            |          |                |  |                    |                             |                                 |                    |  |
| <i>No defects recorded</i>   |            |          |                |  |                    |                             |                                 |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>          |            |          |                |  |                    |                             |                                 |                    |  |
| <i>No defects recorded</i>   |            |          |                |  |                    |                             |                                 |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>          |            |          |                |  |                    |                             |                                 |                    |  |
| <i>No defects recorded</i>   |            |          |                |  |                    |                             |                                 |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |            |          |                |  |                    |                             |                                 |                    |  |
| <i>No defects recorded</i>   |            |          |                |  |                    |                             |                                 |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |            |          |                |  |                    |                             |                                 |                    |  |
| <i>No defects recorded</i>   |            |          |                |  |                    |                             |                                 |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |            |          |                |  |                    |                             |                                 |                    |  |
| <i>No defects recorded</i>   |            |          |                |  |                    |                             |                                 |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |            |          |                |  |                    |                             |                                 |                    |  |
| <i>No defects recorded</i>   |            |          |                |  |                    |                             |                                 |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |            |          |                |  |                    |                             |                                 |                    |  |
| <i>No defects recorded</i>   |            |          |                |  |                    |                             |                                 |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |            |          |                |  |                    |                             |                                 |                    |  |
| <i>No defects recorded</i>   |            |          |                |  |                    |                             |                                 |                    |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |            |          |                |  |                    |                             |                                 |                    |  |
| <i>No defects recorded</i>   |            |          |                |  |                    |                             |                                 |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |            |          |                |  |                    |                             |                                 |                    |  |
| <i>No defects recorded</i>   |            |          |                |  |                    |                             |                                 |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |            |          |                |  |                    |                             |                                 |                    |  |
| <i>No defects recorded</i>   |            |          |                |  |                    |                             |                                 |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |            |          |                |  |                    |                             |                                 |                    |  |
| <i>No defects recorded</i>   |            |          |                |  |                    |                             |                                 |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |            |          |                |  |                    |                             |                                 |                    |  |
| <i>No defects recorded</i>   |            |          |                |  |                    |                             |                                 |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |            |          |                |  |                    |                             |                                 |                    |  |
| <i>No defects recorded</i>   |            |          |                |  |                    |                             |                                 |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |            |          |                |  |                    |                             |                                 |                    |  |
| <i>No defects recorded</i>   |            |          |                |  |                    |                             |                                 |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |            |          |                |  |                    |                             |                                 |                    |  |
| <i>No defects recorded</i>   |            |          |                |  |                    |                             |                                 |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |            |          |                |  |                    |                             |                                 |                    |  |
| SW80-394061-235954867  | 797m       | 950m     | FOOTWAY        | Overgrown by<br>vegetation<br>(OVGV)       | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action        | 01/01/9999         | A77 N/B VERGE NORTH OF<br>WOODLANDS FARM NORTH<br>OF GIRVAN    |
| SW80-394061-235954866  | 126m       | 476m     | WOODLAND       | Overhanging/ov<br>ergrown<br>(OVER)        | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action        | 01/01/9999         | A77 N/B FOR 350M SOUTH OF<br>WOODLANDS FARM SOUTH<br>OF GIRVAN |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |            |          |                |  |                    |                             |                                 |                    |  |
| SW80-397303-235954869  | 788m       | 920m     | CYCLE_FACILITY | Other (OTHR)                               | 3RD PTY            | 24/08/2018                  | Awaiting CCMS<br>Permanent Date | 23/08/2018         | A77N/B VERGE NORTH OF<br>WOODSIDE FARM SOUTH OF<br>GIRVAN      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |            |          |                |  |                    |                             |                                 |                    |  |
| SW82332071-516   | 665m       | 745m     | CARRIAGEWAY    | Bituminous<br>surfacing<br>fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action        | 01/01/9999         |  |
| SW82332071-517   | 739m       | 819m     | CARRIAGEWAY    | Bituminous<br>surfacing<br>fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action        | 01/01/9999         |  |
| SW82332071-513   | 324m       | 404m     | CARRIAGEWAY    | Bituminous<br>surfacing<br>fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action        | 01/01/9999         |  |
| SW82332071-520   | 1,124m     | 1,129m   | CARRIAGEWAY    | Bituminous<br>surfacing<br>fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action        | 01/01/9999         |  |

| Defect Reference | Start m | End m  | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|--------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82332071-524   | 1,437m  | 1,467m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-526   | 1,645m  | 1,725m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-518   | 763m    | 843m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-519   | 815m    | 915m   | FOOTWAY            | Other (OTHR)                         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-511   | 18m     | 118m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Completed Defects     | 28/02/2019      |                      |
| SW82332071-515   | 683m    | 763m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-522   | 1,176m  | 1,256m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-512   | 44m     | 94m    | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-514   | 580m    | 680m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Completed Defects     | 28/02/2019      |                      |
| SW82332071-521   | 1,101m  | 1,105m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-523   | 1,238m  | 1,338m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Completed Defects     | 28/02/2019      |                      |
| SW82332071-525   | 0m      | 100m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Completed Defects     | 28/02/2019      |                      |
| SW82332071-527   | 2,370m  | 2,470m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Completed Defects     | 28/02/2019      |                      |

**Safety Inspection of A77 Ayr South V1 on 30 August 2018**

No defects recorded

**Safety Inspection of A77 Ayr South V1 on 06 September 2018**

No defects recorded

**Safety Inspection of A77 Ayr South V1 on 13 September 2018**

No defects recorded

**Safety Inspection of A77 Ayr South V1 on 20 September 2018**

No defects recorded

**Safety Inspection of A77 Ayr South V1 on 27 September 2018**

|                       |      |      |       |                              |       |            |                   |            |  |
|-----------------------|------|------|-------|------------------------------|-------|------------|-------------------|------------|--|
| SW80-413634-236087130 | 416m | 417m | SHRUB | Overhanging/overgrown (OVER) | CAT 1 | 28/09/2018 | Completed Defects | 27/09/2018 | A77 NB CW 300M NORTH OF ARDMILLAN CARAVAN PARK |
|-----------------------|------|------|-------|------------------------------|-------|------------|-------------------|------------|--|

**Safety Inspection of A77 Ayr South V1 on 04 October 2018**

No defects recorded

**Safety Inspection of A77 Ayr South V1 on 11 October 2018**

No defects recorded

**Safety Inspection of A77 Ayr South V1 on 18 October 2018**

No defects recorded

**Safety Inspection of A77 Ayr South V1 on 25 October 2018**

No defects recorded

**Safety Inspection of A77 Ayr South V1 on 01 November 2018**

| Defect Reference  | Start<br>m | End<br>m | Item Type     | Item Detail               | Defect<br>Category | Required<br>Completion Date | Current Status    | Completion<br>Date | Location Description                                  |
|---|------------|----------|---------------|---------------------------|--------------------|-----------------------------|-------------------|--------------------|---|
| No defects recorded   |            |          |               |                           |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>          |            |          |               |                           |                    |                             |                   |                    |   |
| No defects recorded   |            |          |               |                           |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>          |            |          |               |                           |                    |                             |                   |                    |   |
| No defects recorded   |            |          |               |                           |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b>          |            |          |               |                           |                    |                             |                   |                    |   |
| No defects recorded   |            |          |               |                           |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b>          |            |          |               |                           |                    |                             |                   |                    |   |
| No defects recorded   |            |          |               |                           |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b>          |            |          |               |                           |                    |                             |                   |                    |   |
| No defects recorded   |            |          |               |                           |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b>          |            |          |               |                           |                    |                             |                   |                    |   |
| SW82427366-236262611  | 1,492m     | 1,493m   | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1              | 10/01/2019                  | Completed Defects | 13/12/2018         | A77 ON CWL, STH OF GIRVAN, 410M STH OF CARE HOME      |
| SW82427366-236262610  | 1,487m     | 1,488m   | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1              | 10/01/2019                  | Completed Defects | 13/12/2018         | A77 STH OF GIRVAN, 400M STH OF CARE HOME              |
| SW82427366-236262609  | 1,186m     | 1,187m   | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1              | 10/01/2019                  | Completed Defects | 13/12/2018         | A77 SB CW, ON BRIDGE DECK STH OF GIRVAN               |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b>          |            |          |               |                           |                    |                             |                   |                    |   |
| SW82427527-236264606  | 1,091m     | 1,091m   | TRAFFIC_SIGNS | Pointing wrong way (RWAY) | CAT 1              | 21/12/2018                  | Completed Defects | 20/12/2018         | A77 SB CW 250M NORTH OF WOODLAND RESTERAUNT           |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b>          |            |          |               |                           |                    |                             |                   |                    |   |
| SW82427658-236270448  | 1,073m     | 1,074m   | TRAFFIC_SIGNS | Other (OTHR)              | CAT 1              | 28/12/2018                  | Completed Defects | 27/12/2018         | A77 NB CW SOUTH OF WOODLAND HOTEL                     |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>           |            |          |               |                           |                    |                             |                   |                    |   |
| No defects recorded   |            |          |               |                           |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>           |            |          |               |                           |                    |                             |                   |                    |   |
| No defects recorded   |            |          |               |                           |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>           |            |          |               |                           |                    |                             |                   |                    |   |
| No defects recorded   |            |          |               |                           |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>           |            |          |               |                           |                    |                             |                   |                    |   |
| No defects recorded   |            |          |               |                           |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>           |            |          |               |                           |                    |                             |                   |                    |   |
| No defects recorded   |            |          |               |                           |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b>          |            |          |               |                           |                    |                             |                   |                    |   |
| SW82429489-236310404  | 1,632m     | 1,633m   | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1              | 07/03/2019                  | Completed Defects | 07/02/2019         | A77 SB CW, 100M STH OF RETIREMENT HOME, STH OF GIRVAN |
| SW82429489-236310403  | 1,091m     | 1,092m   | TRAFFIC_SIGNS | Missing (MISS)            | CAT 1              | 07/03/2019                  | Completed Defects | 01/03/2019         | A77 NB VERGE, 400M STH OF ARDWELL FARM STH OF GIRVAN  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b>          |            |          |               |                           |                    |                             |                   |                    |   |
| No defects recorded   |            |          |               |                           |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b>          |            |          |               |                           |                    |                             |                   |                    |   |
| No defects recorded   |            |          |               |                           |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b>          |            |          |               |                           |                    |                             |                   |                    |   |
| No defects recorded   |            |          |               |                           |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>             |            |          |               |                           |                    |                             |                   |                    |   |
| No defects recorded   |            |          |               |                           |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>             |            |          |               |                           |                    |                             |                   |                    |   |
| No defects recorded   |            |          |               |                           |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>             |            |          |               |                           |                    |                             |                   |                    |   |
| No defects recorded   |            |          |               |                           |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>             |            |          |               |                           |                    |                             |                   |                    |   |
| No defects recorded   |            |          |               |                           |                    |                             |                   |                    |   |
| <b>11656/22 : WITH: ON SLIP FROM A76/A71 TO M77 DBFO BOUNDARY</b>         |            |          |               |                           |                    |                             |                   |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 January 2018</b> |            |          |               |                           |                    |                             |                   |                    |   |
| No defects recorded   |            |          |               |                           |                    |                             |                   |                    |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 January 2018</b> |            |          |               |                           |                    |                             |                   |                    |   |
| No defects recorded   |            |          |               |                           |                    |                             |                   |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 January 2018</b> |            |          |               |                           |                    |                             |                   |                    |   |



| Defect Reference   | Start m | End m  | Item Type   | Item Detail    | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                               |
|--|---------|--------|-------------|----------------|-----------------|--------------------------|-------------------|-----------------|--|
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 January 2018</b>  |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 January 2018</b>  |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 January 2018</b>  |         |        |             |                |                 |                          |                   |                 |  |
| SW82317695-235522277   | 1,543m  | 1,544m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 16/02/2018               | Completed Defects | 09/02/2018      | A77 SB CW, LANE 2 500M STH OF GRASSYARDS ONSLIP SB |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 January 2018</b>  |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 January 2018</b>  |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 January 2018</b>  |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 February 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| SW82318553-235533633   | 264m    | 266m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 02/03/2018               | Completed Defects | 22/02/2018      | A77 NB CW, LANE 1, 300M NTH OF BELLFIELD NB ONSLIP |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 February 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 February 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 February 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 February 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 February 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 February 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 February 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 March 2018</b>    |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 March 2018</b>    |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 March 2018</b>    |         |        |             |                |                 |                          |                   |                 |  |
| SW82326369-23553169  | 669m    | 700m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 06/04/2018               | Completed Defects | 10/03/2018      | A77 NB LAYBY, 1ST LAYBY NTH OF BELLFIELD INT       |
| SW82326369-23553168  | 648m    | 649m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 06/04/2018               | Completed Defects | 10/03/2018      | A77 NB LAYBY, 1ST LAYBY NTH OF BELLFIELD INT       |
| SW82326369-23553166  | 644m    | 645m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 06/04/2018               | Completed Defects | 10/03/2018      | A77 NB CW, 1ST LAYBY AFTER BELLFIELD               |
| SW82326369-23553167  | 656m    | 657m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 06/04/2018               | Completed Defects | 10/03/2018      | A77 NB LAYBY, 1ST LAYBY NTH OF BELLFIELD INT       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 March 2018</b>    |         |        |             |                |                 |                          |                   |                 |  |
| SW82327521-235576663   | 1,422m  | 1,423m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 10/04/2018               | Completed Defects | 14/03/2018      | A77 NB CW, 500M STH OF GRASSYARDS, LANE 2          |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 March 2018</b>    |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 March 2018</b>    |         |        |             |                |                 |                          |                   |                 |  |
| SW82329522-235601242   | 3,196m  | 3,197m | GULLY       | Other (OTHR)   | CAT 1           | 17/04/2018               | Completed Defects | 21/03/2018      | A77 NB CW, ON CENTER, 500M STH OF MIEKLEWOOD       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 March 2018</b>    |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 March 2018</b>    |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2018</b>    |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 April 2018</b>    |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |

| Defect Reference   | Start m   | End m  | Item Type     | Item Detail                       | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description   |
|--|---|--------|---------------|-----------------------------------|-----------------|--------------------------|-------------------|-----------------|--|
| <b>Safety Patrol of A77 Ayr North</b><br>SW82335189-235618856                                  | <b>Safety Patrol V1 on 06 April 2018</b><br>446m  |        | CARRIAGEWAY   | Pothole VIAFIX (POTV)             | CAT 1           | 07/04/2018               | Completed Defects | 06/04/2018      | A77 S/B 400M PRIOR TO BELLFIELD OFF SLIP                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 April 2018</b><br>No defects recorded |   |        |               |                                   |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North</b><br>No defects recorded                                   |   |        |               |                                   |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 April 2018</b><br>No defects recorded |   |        |               |                                   |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North</b><br>No defects recorded                                   |   |        |               |                                   |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 April 2018</b><br>No defects recorded |   |        |               |                                   |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North</b><br>No defects recorded                                   |   |        |               |                                   |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 01 May 2018</b><br>No defects recorded   |   |        |               |                                   |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North</b><br>No defects recorded                                   |   |        |               |                                   |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 May 2018</b><br>No defects recorded   |   |        |               |                                   |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North</b><br>SW82347347-235785072                                  | <b>Safety Patrol V1 on 11 May 2018</b><br>473m    | 474m   | CARRIAGEWAY   | Pothole VIAFIX (POTV)             | CAT 1           | 08/06/2018               | Completed Defects | 11/05/2018      | A77 SB CW, LANE 1, 50M STH OF RAIL BRIDGE NTH OF BELLFIELD     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 May 2018</b><br>No defects recorded   |   |        |               |                                   |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North</b><br>No defects recorded                                   |   |        |               |                                   |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 May 2018</b><br>No defects recorded   |   |        |               |                                   |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North</b><br>No defects recorded                                   |   |        |               |                                   |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 May 2018</b><br>SW82355166-235815738  | 107m  | 108m   | CARRIAGEWAY   | Pothole VIAFIX (POTV)             | CAT 1           | 26/06/2018               | Completed Defects | 30/05/2018      | A77 END OF BELLFIELD ONSLIP                                    |
| <b>Safety Patrol of A77 Ayr North</b><br>No defects recorded                                   |   |        |               |                                   |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 June 2018</b><br>No defects recorded  |   |        |               |                                   |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North</b><br>No defects recorded                                   |   |        |               |                                   |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 June 2018</b><br>No defects recorded  |   |        |               |                                   |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North</b><br>No defects recorded                                   |   |        |               |                                   |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 June 2018</b><br>SW82366110-235861193 | 1,583m  | 1,584m | CARRIAGEWAY   | Pothole VIAFIX (POTV)             | CAT 1           | 17/07/2018               | Completed Defects | 10/07/2018      | A77 SB CW CL 305M SOUTH OF GRASSYARDS                          |
| <b>Safety Patrol of A77 Ayr North</b><br>SW80-367730-235862802                                 | <b>Safety Patrol V1 on 22 June 2018</b><br>1,286m | 1,287m | CARRIAGEWAY   | Pothole (POTH)                    | CAT 1           | 20/07/2018               | Completed Defects | 22/06/2018      | A77 NB CW 25M PRIOR TO THE 2ND NEW GRASSYARDS INTERCHANGE SIGN |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 June 2018</b><br>SW82369551-235867688 | 3,372m  | 3,373m | TRAFFIC_SIGNS | Physical condition of post (COPT) | CAT 1           | 24/07/2018               | Completed Defects | 01/08/2018      | A77 NB CW LAYBY AT MEIKLEWOOD                                  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018</b><br>No defects recorded    |   |        |               |                                   |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North</b><br>No defects recorded                                   |   |        |               |                                   |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 July 2018</b><br>No defects recorded  |   |        |               |                                   |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North</b><br>No defects recorded                                   |   |        |               |                                   |                 |                          |                   |                 |  |

| Defect Reference  | Start m | End m  | Item Type    | Item Detail            | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                                  |
|---|---------|--------|--------------|------------------------|-----------------|--------------------------|-------------------|-----------------|---|
| SW82374590-235874260  | 2,532m  | 2,533m | CARRIAGEWAY  | Pothole (POTH)         | CAT 1           | 03/08/2018               | Completed Defects | 07/07/2018      | A77 NB CW AT GRASSYARDS ON SLIP                       |
| SW82374590-235874259  | 2,539m  | 2,540m | CARRIAGEWAY  | Pothole (POTH)         | CAT 1           | 03/08/2018               | Completed Defects | 07/07/2018      | A77 NB CW AT GRASSYARDS ONSLIP                        |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 July 2018</b><br><i>No defects recorded</i>      |         |        |              |                        |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 13 July 2018</b>                                    |         |        |              |                        |                 |                          |                   |                 |   |
| SW82377861-235874037  | 2,653m  | 2,654m | GULLY        | Collapsed (COLP)       | CAT 1           | 10/08/2018               | Completed Defects | 13/07/2018      | A77 NB CW, ON MAIN CW, AT GRASSYARDS NB ONSLIP        |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 July 2018</b><br><i>No defects recorded</i>      |         |        |              |                        |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 20 July 2018</b>                                    |         |        |              |                        |                 |                          |                   |                 |   |
| SW82381111-235914466  | 1,557m  | 1,558m | CARRIAGEWAY  | Pothole (POTH)         | CAT 1           | 17/08/2018               | Completed Defects | 21/07/2018      | A77 SB CW 325M AFTER GRASSYARDS ON SLIP               |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 July 2018</b><br><i>No defects recorded</i>      |         |        |              |                        |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 27 July 2018</b><br><i>No defects recorded</i>      |         |        |              |                        |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 July 2018</b><br><i>No defects recorded</i>      |         |        |              |                        |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 03 August 2018</b><br><i>No defects recorded</i>    |         |        |              |                        |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 August 2018</b><br><i>No defects recorded</i>    |         |        |              |                        |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 10 August 2018</b><br><i>No defects recorded</i>    |         |        |              |                        |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 14 August 2018</b><br><i>No defects recorded</i>    |         |        |              |                        |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 17 August 2018</b><br><i>No defects recorded</i>    |         |        |              |                        |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 21 August 2018</b><br><i>No defects recorded</i>    |         |        |              |                        |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 24 August 2018</b><br><i>No defects recorded</i>    |         |        |              |                        |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 28 August 2018</b><br><i>No defects recorded</i>    |         |        |              |                        |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 31 August 2018</b><br><i>No defects recorded</i>    |         |        |              |                        |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 September 2018</b><br><i>No defects recorded</i> |         |        |              |                        |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 ( Awaiting Return )</b><br><i>No defects recorded</i>  |         |        |              |                        |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 September 2018</b><br><i>No defects recorded</i> |         |        |              |                        |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 14 September 2018</b>                               |         |        |              |                        |                 |                          |                   |                 |   |
| SW82407615-236055839  | 706m    | 707m   | CARRIAGEWAY  | Pothole VIAFIX (POTV)  | CAT 1           | 15/09/2018               | Completed Defects | 14/09/2018      | A77 N/B FIRST LAYBY NORTH OF BELLFIELD INTERCHANGE    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 September 2018</b>                               |         |        |              |                        |                 |                          |                   |                 |   |
| SW82409417-236071476  | 453m    | 503m   | SAFETY_FENCE | Accident damage (ACCD) | CAT 1           | 16/10/2018               | Completed Defects | 18/09/2018      | UNDERNEATH RAIL BRIDGE NORTH OF BELLFIELD INTERCHANGE |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 September 2018</b><br><i>No defects recorded</i> |         |        |              |                        |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 25 September 2018</b><br><i>No defects recorded</i> |         |        |              |                        |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 September 2018</b><br><i>No defects recorded</i> |         |        |              |                        |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 October 2018</b><br><i>No defects recorded</i>   |         |        |              |                        |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 05 October 2018</b><br><i>No defects recorded</i>   |         |        |              |                        |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 October 2018</b><br><i>No defects recorded</i>   |         |        |              |                        |                 |                          |                   |                 |   |

| Defect Reference   | Start m | End m  | Item Type           | Item Detail            | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description   |
|--|---------|--------|---------------------|------------------------|-----------------|--------------------------|-------------------|-----------------|--|
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 12 October 2018</b>  |         |        |                     |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                     |                        |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 October 2018</b>  |         |        |                     |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                     |                        |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 19 October 2018</b>  |         |        |                     |                        |                 |                          |                   |                 |  |
| SW82423922-236143039   | 1,668m  | 1,668m | CARRIAGEWAY         | Pothole VIAFIX (POTV)  | CAT 1           | 16/11/2018               | Completed Defects | 20/10/2018      | A77 SB CW, LANE 2, 200M STH OF GRASSYARDS ON SLIP                |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 October 2018</b>  |         |        |                     |                        |                 |                          |                   |                 |  |
| SW82425739-236166554   | 1,766m  | 1,766m | TRAFFIC_SIGNS       | Damaged (DAMG)         | CAT 1           | 20/11/2018               | Completed Defects | 28/12/2018      | A77 SB CW 100M AFTER GRASSYARDS SB ON SLIP                       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 26 October 2018</b>  |         |        |                     |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                     |                        |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 October 2018</b>  |         |        |                     |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                     |                        |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 02 November 2018</b> |         |        |                     |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                     |                        |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 November 2018</b> |         |        |                     |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                     |                        |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 09 November 2018</b> |         |        |                     |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                     |                        |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 November 2018</b> |         |        |                     |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                     |                        |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 16 November 2018</b> |         |        |                     |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                     |                        |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 November 2018</b> |         |        |                     |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                     |                        |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 23 November 2018</b> |         |        |                     |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                     |                        |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 November 2018</b> |         |        |                     |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                     |                        |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 30 November 2018</b> |         |        |                     |                        |                 |                          |                   |                 |  |
| SW82426931-236232767   | 117m    | 118m   | CARRIAGEWAY         | Pothole (POTH)         | CAT 1           | 28/12/2018               | Completed Defects | 01/12/2018      | A77 NB CW 100M AFTER BELLFIELD ON SLIP                           |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 December 2018</b> |         |        |                     |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                     |                        |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 07 December 2018</b> |         |        |                     |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                     |                        |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 December 2018</b> |         |        |                     |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                     |                        |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 14 December 2018</b> |         |        |                     |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                     |                        |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 December 2018</b> |         |        |                     |                        |                 |                          |                   |                 |  |
| SW82427481-236264538   | 262m    | 282m   | FENCES_AND_BARRIERS | Accident damage (ACCD) | CAT 1           | 15/01/2019               | Completed Defects | 18/12/2018      | A77 50M BEFORE HURLFORD ROAD OVER NORTH OF BELLFIELD INTERCHANGE |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 21 December 2018</b> |         |        |                     |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                     |                        |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 December 2018</b> |         |        |                     |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                     |                        |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 28 December 2018</b> |         |        |                     |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                     |                        |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 December 2018</b> |         |        |                     |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                     |                        |                 |                          |                   |                 |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 04 January 2019</b>  |         |        |                     |                        |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |                     |                        |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 January 2019</b>  |         |        |                     |                        |                 |                          |                   |                 |  |
| SW82427982-236271071   | 101m    | 102m   | CARRIAGEWAY         | Pothole VIAFIX (POTV)  | CAT 1           | 04/02/2019               | Completed Defects | 07/01/2019      | A77 NB CW, LANE 1, 120M NTH OF BELLFIELD INTERCHANGE             |
| SW82427982-236271069   | 121m    | 122m   | CARRIAGEWAY         | Pothole VIAFIX (POTV)  | CAT 1           | 04/02/2019               | Completed Defects | 07/01/2019      | A77 NBCW, LANE 1, 20M NTH OF BELLFIELD INTERCHANGE               |

| Defect Reference  | Start m | End m  | Item Type     | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                                |
|---|---------|--------|---------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| SW82427982-236271070  | 109m    | 110m   | CARRIAGEWAY   | Pothole VIAFIX (POTV)                | CAT 1           | 04/02/2019               | Completed Defects     | 07/01/2019      | A77 NB CW, ON CL, 100M NTH OF BELLFIELD INTERCHANGE |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 January 2019</b> |         |        |               |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 11 January 2019</b> |         |        |               |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 January 2019</b> |         |        |               |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 18 January 2019</b> |         |        |               |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 January 2019</b> |         |        |               |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 25 January 2019</b> |         |        |               |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |               |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018</b>  |         |        |               |                                      |                 |                          |                       |                 |   |
| SW82332070-277  | 306m    | 307m   | CARRIAGEWAY   | Pothole (POTH)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332070-287  | 1,656m  | 1,656m | TRAFFIC_SIGNS | Dirty sign (DIRT)                    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332070-301  | 3,400m  | 0m     | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332070-298  | 3,031m  | 0m     | CARRIAGEWAY   | Missing (MISS)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332070-347  | 1,146m  | 1,150m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332070-297  | 2,928m  | 0m     | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332070-281  | 179m    | 180m   | TRAFFIC_SIGNS | Dirty sign (DIRT)                    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332070-285  | 1,371m  | 1,376m | CARRIAGEWAY   | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332070-332  | 1,663m  | 1,663m | CARRIAGEWAY   | Pothole (POTH)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332070-294  | 10m     | 10m    | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332070-304  | 3,599m  | 0m     | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332070-286  | 1,404m  | 1,405m | CARRIAGEWAY   | Pothole (POTH)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332070-278  | 447m    | 487m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332070-333  | 1,646m  | 1,656m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332070-348  | 1,126m  | 1,156m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332070-280  | 229m    | 230m   | TRAFFIC_SIGNS | Physical condition of post (COPT)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332070-335  | 1,578m  | 1,579m | CARRIAGEWAY   | Pothole (POTH)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |

| Defect Reference   | Start<br>m | End<br>m | Item Type     | Item Detail                          | Defect<br>Category | Required<br>Completion Date | Current Status        | Completion<br>Date | Location Description                               |
|--|------------|----------|---------------|--------------------------------------|--------------------|-----------------------------|-----------------------|--------------------|--|
| SW82332070-346   | 1,160m     | 1,170m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |  |
| SW82332070-279   | 0m         | 1m       | TRAFFIC_SIGNS | Physical condition of post (COPT)    | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |  |
| SW82332070-300   | 3,389m     | 0m       | CARRIAGEWAY   | Surface crazing (SRCZ)               | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |  |
| SW82332070-336   | 1,569m     | 1,579m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |  |
| SW82332070-305   | 3,722m     | 0m       | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |  |
| SW82332070-306   | 3,812m     | 0m       | TRAFFIC_SIGNS | Surface corrosion (SFCO)             | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |  |
| SW82332070-283   | 897m       | 997m     | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 January 2019</b>  |            |          |               |                                      |                    |                             |                       |                    |  |
| No defects recorded  |            |          |               |                                      |                    |                             |                       |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 February 2019</b> |            |          |               |                                      |                    |                             |                       |                    |  |
| No defects recorded  |            |          |               |                                      |                    |                             |                       |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 February 2019</b> |            |          |               |                                      |                    |                             |                       |                    |  |
| SW82429329-236310603   | 114m       | 115m     | CARRIAGEWAY   | Pothole VIAFIX (POTV)                | CAT 1              | 05/03/2019                  | Completed Defects     | 21/02/2019         | A77 NB CW, 110M NTH OF BELLFIELD NB ONSLIP         |
| SW82429329-236310605   | 253m       | 254m     | CARRIAGEWAY   | Failed repair (RFAL)                 | CAT 1              | 05/03/2019                  | Completed Defects     | 21/02/2019         | A77 NB CW, LANE 1, 250M NTH OF BELLFIELD NB ONSLIP |
| SW82429329-236310606   | 241m       | 242m     | CARRIAGEWAY   | Failed repair (RFAL)                 | CAT 1              | 05/03/2019                  | Completed Defects     | 21/02/2019         | A77 NB CW, LANE 1, 250M NTH OF BELLFIELD NB ONSLIP |
| SW82429329-236310604   | 200m       | 201m     | CARRIAGEWAY   | Pothole VIAFIX (POTV)                | CAT 1              | 05/03/2019                  | Completed Defects     | 21/02/2019         | A77 NB CW, LANE 1 200M NTH OF BELLFIELD NO ONSLIP  |
| SW82429329-236310607   | 3,834m     | 3,834m   | CARRIAGEWAY   | Other (OTHR)                         | CAT 1              | 05/03/2019                  | Completed Defects     | 06/02/2019         | A77 NB CW LANE 1 AT MIEKLEWOOD BDARY               |
| SW82429329-236310608   | 3,633m     | 3,634m   | CARRIAGEWAY   | Pothole VIAFIX (POTV)                | CAT 1              | 05/03/2019                  | Completed Defects     | 06/02/2019         | A77 SB CW, 1/2MILE NTH OF GRASSYARDS OFFSLIP       |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 February 2019</b> |            |          |               |                                      |                    |                             |                       |                    |  |
| No defects recorded  |            |          |               |                                      |                    |                             |                       |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 February 2019</b> |            |          |               |                                      |                    |                             |                       |                    |  |
| SW82429845-236328225   | 273m       | 275m     | CARRIAGEWAY   | Pothole (POTH)                       | CAT 1              | 13/02/2019                  | Completed Defects     | 13/02/2019         | A77 N/B 100M AFTER BELLFIELD ON SLP                |
| SW82429845-236328224   | 271m       | 273m     | CARRIAGEWAY   | Pothole (POTH)                       | CAT 1              | 13/02/2019                  | Completed Defects     | 13/02/2019         | A77 N/B 100M AFTER BELLFIELD ON SLIP               |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 February 2019</b> |            |          |               |                                      |                    |                             |                       |                    |  |
| No defects recorded  |            |          |               |                                      |                    |                             |                       |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 February 2019</b> |            |          |               |                                      |                    |                             |                       |                    |  |
| No defects recorded  |            |          |               |                                      |                    |                             |                       |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 February 2019</b> |            |          |               |                                      |                    |                             |                       |                    |  |
| SW82433749-236325468   | 285m       | 285m     | CARRIAGEWAY   | Litter Grade C (LITC)                | 3RD PTY            | 23/02/2019                  | Completed Defects     | 14/05/2019         | A77 BELLFEILD TO GRASSYARDS                        |
| SW82433749-236325469   | 2,132m     | 2,132m   | CARRIAGEWAY   | Litter Grade C (LITC)                | 3RD PTY            | 23/02/2019                  | Completed Defects     | 14/05/2019         | A77 N/B OFFSLIP TO GRASSYARDS                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 February 2019</b> |            |          |               |                                      |                    |                             |                       |                    |  |
| No defects recorded  |            |          |               |                                      |                    |                             |                       |                    |  |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 01 March 2019</b>    |            |          |               |                                      |                    |                             |                       |                    |  |

| Defect Reference  | Start m | End m  | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                          |
|---|---------|--------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|---|
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 March 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 08 March 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 March 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 15 March 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| SW82448180-236461589  | 1,226m  | 1,227m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 16/03/2019               | Completed Defects | 15/03/2019      | A77 N/B 1/3 MILE PRIOR TO GRASSYARDS OFF SLIP |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 March 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 22 March 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 March 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |
| <b>Safety Patrol of A77 Ayr North Safety Patrol V1 on 29 March 2019</b> |         |        |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                       |                 |                          |                   |                 |   |

#### 11626/04 : A719 JCT TO STH END TURNBERRY CLIMBING LANE

|  |      |      |             |                       |       |            |                   |            |  |
|--|------|------|-------------|-----------------------|-------|------------|-------------------|------------|--|
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>  |      |      |             |                       |       |            |                   |            |  |
| <i>No defects recorded</i>                                       |      |      |             |                       |       |            |                   |            |  |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>  |      |      |             |                       |       |            |                   |            |  |
| SW82317471-235518223   | 523m | 524m | CARRIAGEWAY | Pothole (POTH)        | CAT 1 | 08/02/2018 | Completed Defects | 05/03/2018 | A77 NB CW, 100M NTH OF TRUMP TURNBERRY ENTRANCE, TURNBERRY |
| SW82317471-235518225   | 168m | 168m | CARRIAGEWAY | Pothole (POTH)        | CAT 1 | 08/02/2018 | Completed Defects | 05/03/2018 | A77 NB CW, 100M STH DALQUATT LAYBY, STH OF KIRKOSWALD      |
| SW82317471-235518226   | 227m | 229m | CARRIAGEWAY | Pothole (POTH)        | CAT 1 | 08/02/2018 | Completed Defects | 05/03/2018 | A77 NB CW, OPP DALQUATT LAYBY, STH OF KIRKOSWALD           |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>  |      |      |             |                       |       |            |                   |            |  |
| <i>No defects recorded</i>                                       |      |      |             |                       |       |            |                   |            |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>  |      |      |             |                       |       |            |                   |            |  |
| <i>No defects recorded</i>                                       |      |      |             |                       |       |            |                   |            |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b> |      |      |             |                       |       |            |                   |            |  |
| <i>No defects recorded</i>                                       |      |      |             |                       |       |            |                   |            |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b> |      |      |             |                       |       |            |                   |            |  |
| <i>No defects recorded</i>                                       |      |      |             |                       |       |            |                   |            |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b> |      |      |             |                       |       |            |                   |            |  |
| SW82319984-235544959   | 461m | 462m | CARRIAGEWAY | Pothole (POTH)        | CAT 1 | 15/03/2018 | Completed Defects | 15/02/2018 | A77 SB CW, OPP TRUMP TURNBERRY DELIVERY ENTRANCE           |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b> |      |      |             |                       |       |            |                   |            |  |
| <i>No defects recorded</i>                                       |      |      |             |                       |       |            |                   |            |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>    |      |      |             |                       |       |            |                   |            |  |
| <i>No defects recorded</i>                                       |      |      |             |                       |       |            |                   |            |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>    |      |      |             |                       |       |            |                   |            |  |
| <i>No defects recorded</i>                                       |      |      |             |                       |       |            |                   |            |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>    |      |      |             |                       |       |            |                   |            |  |
| <i>No defects recorded</i>                                       |      |      |             |                       |       |            |                   |            |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>    |      |      |             |                       |       |            |                   |            |  |
| SW82330474-235608116   | 309m | 310m | CARRIAGEWAY | Pothole (POTH)        | CAT 1 | 19/04/2018 | Completed Defects | 22/03/2018 | A77 SB CW, 20M STH OF TURNBERRY LODGE                      |
| SW82330474-235608117   | 264m | 265m | CARRIAGEWAY | Pothole (POTH)        | CAT 1 | 19/04/2018 | Completed Defects | 22/03/2018 | A77 ON CL, 40M STH OF TURNBERRY LODGE                      |
| SW82330474-235608115   | 333m | 334m | CARRIAGEWAY | Pothole (POTH)        | CAT 1 | 19/04/2018 | Completed Defects | 22/03/2018 | A77 SB CW, 20M NTH OF TURNBERRY LODGE                      |
| SW82330474-235608118   | 389m | 390m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1 | 19/04/2018 | Completed Defects | 22/03/2018 | A77 SB CW, 30M STH OF TRUMP TURNBERRY DELIVERY ENTRANCE    |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>    |      |      |             |                       |       |            |                   |            |  |

| Defect Reference   | Start<br>m | End<br>m | Item Type   | Item Detail           | Defect<br>Category | Required<br>Completion Date | Current Status               | Completion<br>Date | Location Description                         |
|--|------------|----------|-------------|-----------------------|--------------------|-----------------------------|------------------------------|--------------------|--|
| <i>No defects recorded</i>   |            |          |             |                       |                    |                             |                              |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>        |            |          |             |                       |                    |                             |                              |                    |  |
| <i>No defects recorded</i>   |            |          |             |                       |                    |                             |                              |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>        |            |          |             |                       |                    |                             |                              |                    |  |
| <i>No defects recorded</i>   |            |          |             |                       |                    |                             |                              |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>        |            |          |             |                       |                    |                             |                              |                    |  |
| <i>No defects recorded</i>   |            |          |             |                       |                    |                             |                              |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>        |            |          |             |                       |                    |                             |                              |                    |  |
| <i>No defects recorded</i>   |            |          |             |                       |                    |                             |                              |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>          |            |          |             |                       |                    |                             |                              |                    |  |
| <i>No defects recorded</i>   |            |          |             |                       |                    |                             |                              |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>          |            |          |             |                       |                    |                             |                              |                    |  |
| SW82346930-235712682   | 376m       | 377m     | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1              | 07/06/2018                  | Completed Defects            | 10/05/2018         | A77 SB CW OPPOSITE MILTON WYND TURNBURY      |
| SW82346930-235712683   | 220m       | 221m     | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1              | 07/06/2018                  | Completed Defects            | 10/05/2018         | A77 CL 40M SOUTH OF TURBURYLODGE             |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |            |          |             |                       |                    |                             |                              |                    |  |
| SW82349855-235793435   | 459m       | 460m     | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1              | 14/06/2018                  | Completed Defects            | 17/05/2018         | A78 NB CW TRUMP DELIVERY ENTRANCE TURNBURY   |
| SW82349855-235793436   | 462m       | 463m     | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1              | 14/06/2018                  | Completed Defects            | 17/05/2018         | A77 CL TRUMP DELIVERY ENTRANCE TURNBURY      |
| SW82349855-235793434   | 461m       | 462m     | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1              | 14/06/2018                  | Completed Defects            | 17/05/2018         | A78 CL TRUMP DELIVERY ENTRANCE TURNBURY      |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |            |          |             |                       |                    |                             |                              |                    |  |
| <i>No defects recorded</i>   |            |          |             |                       |                    |                             |                              |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |            |          |             |                       |                    |                             |                              |                    |  |
| <i>No defects recorded</i>   |            |          |             |                       |                    |                             |                              |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |            |          |             |                       |                    |                             |                              |                    |  |
| <i>No defects recorded</i>   |            |          |             |                       |                    |                             |                              |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |            |          |             |                       |                    |                             |                              |                    |  |
| <i>No defects recorded</i>   |            |          |             |                       |                    |                             |                              |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |            |          |             |                       |                    |                             |                              |                    |  |
| SW80-367289-235862780  | 459m       | 460m     | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1              | 19/07/2018                  | Completed Defects            | 21/06/2018         | A77 SB CW CL OUTSIDE TRUMP DELIVERY ENTRANCE |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |            |          |             |                       |                    |                             |                              |                    |  |
| <i>No defects recorded</i>   |            |          |             |                       |                    |                             |                              |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |            |          |             |                       |                    |                             |                              |                    |  |
| <i>No defects recorded</i>   |            |          |             |                       |                    |                             |                              |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |            |          |             |                       |                    |                             |                              |                    |  |
| <i>No defects recorded</i>   |            |          |             |                       |                    |                             |                              |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |            |          |             |                       |                    |                             |                              |                    |  |
| SW82377424-235909970   | 252m       | 253m     | CARRIAGEWAY | Pothole (POTH)        | CAT 1              | 09/08/2018                  | Completed Defects            | 12/07/2018         | A77 ON CL, OPP TURNBERRY LODGE, TURNBERRY    |
| SW82377424-235909971   | 252m       | 253m     | CARRIAGEWAY | Pothole (POTH)        | CAT 1              | 09/08/2018                  | Completed Defects            | 12/07/2018         | A77 ON CL, OPP TURNBERRY LODGE, TURNBERRY    |
| SW82377424-235909969   | 236m       | 238m     | CARRIAGEWAY | Pothole (POTH)        | CAT 1              | 09/08/2018                  | Completed Defects            | 12/07/2018         | A77 ON CL, OPPOSITE TURNBURY LODGE, TURNBURY |
| SW82377424-235909972   | 252m       | 253m     | GULLY       | Blockage (BLOK)       | CAT 1              | 09/08/2018                  | Completed Defects            | 24/07/2018         | A77 SB CW, OPP TURNBURY LODGE, TURNBURY      |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |            |          |             |                       |                    |                             |                              |                    |  |
| <i>No defects recorded</i>   |            |          |             |                       |                    |                             |                              |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |            |          |             |                       |                    |                             |                              |                    |  |
| SW82383889-235917498   | 545m       | 545m     | ROAD_STUDS  | Missing (MISS)        | CAT 1              | 23/08/2018                  | Awaiting CCMS Permanent Date | 01/01/9999         | A77 CL 200M AFTER TURNBURY STH GATEWAY       |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |            |          |             |                       |                    |                             |                              |                    |  |
| <i>No defects recorded</i>   |            |          |             |                       |                    |                             |                              |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |            |          |             |                       |                    |                             |                              |                    |  |



| Defect Reference   | Start m | End m | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|--|---------|-------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>       |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b>    |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b>    |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b>    |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b>    |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>      |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>      |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |         |       |                    |                                      |                 |                          |                       |                 |                      |
| SW82332071-636   | 428m    | 508m  | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-633   | 210m    | 290m  | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-635   | 339m    | 439m  | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-632   | 10m     | 90m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-637   | 547m    | 627m  | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-634   | 325m    | 395m  | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>      |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>      |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>     |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>     |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>     |         |       |                    |                                      |                 |                          |                       |                 |                      |
| SW82426587-236223181   | 126m    | 127m  | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 16/11/2018               | Completed Defects     | 15/11/2018      | A77 NB CW TURNBERRY  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b>     |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b>     |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b>     |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b>     |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b>     |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b>     |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>      |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |                    |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>      |         |       |                    |                                      |                 |                          |                       |                 |                      |

| Defect Reference  | Start m | End m | Item Type      | Item Detail            | Defect Category | Required Completion Date | Current Status               | Completion Date | Location Description                                    |
|---|---------|-------|----------------|------------------------|-----------------|--------------------------|------------------------------|-----------------|---|
| SW82428044-236270556  | 337m    | 338m  | CARRIAGEWAY    | Pothole VIAFIX (POTV)  | CAT 1           | 11/01/2019               | Completed Defects            | 10/01/2019      | A77 NB CW SOUTH OF TURNBUERRY NORTH GATEWAY             |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b><br>No defects recorded  |         |       |                |                        |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b><br>No defects recorded  |         |       |                |                        |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b><br>No defects recorded  |         |       |                |                        |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b>                        |         |       |                |                        |                 |                          |                              |                 |   |
| SW82429489-236310412  | 302m    | 303m  | CARRIAGEWAY    | Pothole VIAFIX (POTV)  | CAT 1           | 07/03/2019               | Completed Defects            | 08/02/2019      | A77 TURNBERRY SB, OPPOSITE LODGE                        |
| SW82429489-236310410  | 267m    | 269m  | CARRIAGEWAY    | Pothole VIAFIX (POTV)  | CAT 1           | 07/03/2019               | Completed Defects            | 08/02/2019      | A77 TURNBERRY CL, OPPOSITE LODGE                        |
| SW82429489-236310411  | 278m    | 279m  | CARRIAGEWAY    | Pothole VIAFIX (POTV)  | CAT 1           | 07/03/2019               | Completed Defects            | 08/02/2019      | A77 TURNBERRY CL, OPPOSITE LODGE                        |
| SW82429489-236310413  | 326m    | 327m  | CARRIAGEWAY    | Pothole VIAFIX (POTV)  | CAT 1           | 08/02/2019               | Completed Defects            | 08/02/2019      | A77 TURNBERRY ON CL, OPPOSITE LODGE                     |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b><br>No defects recorded |         |       |                |                        |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b>                        |         |       |                |                        |                 |                          |                              |                 |   |
| SW82433243-236330730  | 323m    | 323m  | CARRIAGEWAY    | Pothole VIAFIX (POTV)  | CAT 1           | 22/02/2019               | Completed Defects            | 21/02/2019      | A77 S/B @ TURRYBERRY LODGE                              |
| SW82433243-236330731  | 323m    | 323m  | CARRIAGEWAY    | Pothole VIAFIX (POTV)  | CAT 1           | 22/02/2019               | Completed Defects            | 21/02/2019      | A77 S/B @ TURNBERRY LODGE                               |
| SW82433243-236330727  | 282m    | 282m  | BOLLARDS       | Accident damage (ACCD) | CAT 1           | 21/03/2019               | Completed Defects            | 13/03/2019      | A77 N/B JT TURNBERRY LODGE @ TELEPHONE EXCHANGE         |
| SW82433243-236330729  | 262m    | 262m  | BOLLARDS       | Accident damage (ACCD) | CAT 1           | 21/03/2019               | Completed Defects            | 13/03/2019      | A77 N/B @ ENTRY TO TURNBERRY LODGE @ TELEPHONE EXCHANGE |
| SW82433243-236330728  | 297m    | 297m  | LIGHTING_POINT | Accident damage (ACCD) | CAT 1           | 21/03/2019               | Awaiting CCMS Permanent Date | 01/01/9999      | A77 N/B @ ENTRY TO TURNBERRY LODGE                      |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b><br>No defects recorded |         |       |                |                        |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b><br>No defects recorded    |         |       |                |                        |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b><br>No defects recorded    |         |       |                |                        |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b><br>No defects recorded    |         |       |                |                        |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b><br>No defects recorded    |         |       |                |                        |                 |                          |                              |                 |   |
| <b>11626/06 : TURNBERRY CLIMBING LANE</b>   |         |       |                |                        |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b><br>No defects recorded  |         |       |                |                        |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b><br>No defects recorded  |         |       |                |                        |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b><br>No defects recorded  |         |       |                |                        |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b><br>No defects recorded  |         |       |                |                        |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b><br>No defects recorded |         |       |                |                        |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b><br>No defects recorded |         |       |                |                        |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b><br>No defects recorded |         |       |                |                        |                 |                          |                              |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b>                        |         |       |                |                        |                 |                          |                              |                 |   |

| Defect Reference  | Start m | End m | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                             |
|---|---------|-------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|--|
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |
| Safety Inspection of A77 Ayr South V1 on 01 March 2018        |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |
| Safety Inspection of A77 Ayr South V1 on 08 March 2018        |         |       |             |                       |                 |                          |                   |                 |  |
| SW82326075-235554301  | 725m    | 728m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 05/04/2018               | Completed Defects | 08/03/2018      | A77 AT LAYBY TOP OF TURNBERRY HILL, ON STH EXIT  |
| Safety Inspection of A77 Ayr South V1 on 15 March 2018        |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |
| Safety Inspection of A77 Ayr South V1 on 22 March 2018        |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |
| Safety Inspection of A77 Ayr South V1 on 29 March 2018        |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |
| Safety Inspection of A77 Ayr South V1 on 05 April 2018        |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |
| Safety Inspection of A77 Ayr South V1 on 12 April 2018        |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |
| Safety Inspection of A77 Ayr South V1 on 19 April 2018        |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |
| Safety Inspection of A77 Ayr South V1 on 26 April 2018        |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |
| Safety Inspection of A77 Ayr South V1 on 03 May 2018          |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |
| Safety Inspection of A77 Ayr South V1 on 10 May 2018          |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |
| Safety Inspection of A77 Ayr South V1 on 17 May 2018          |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |
| Safety Inspection of A77 Ayr South V1 on 24 May 2018          |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |
| Safety Inspection of A77 Ayr South V1 on 31 May 2018          |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |
| Safety Inspection of A77 Ayr South V1 on 07 June 2018         |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |
| Safety Inspection of A77 Ayr South V1 on 14 June 2018         |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |
| Safety Inspection of A77 Ayr South V1 on 21 June 2018         |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |
| Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018 |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |
| Safety Inspection of A77 Ayr South V1 on 28 June 2018         |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |
| Safety Inspection of A77 Ayr South V1 on 05 July 2018         |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |
| Safety Inspection of A77 Ayr South V1 on 12 July 2018         |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |
| Safety Inspection of A77 Ayr South V1 on 19 July 2018         |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |
| Safety Inspection of A77 Ayr South V1 on 26 July 2018         |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |
| Safety Inspection of A77 Ayr South V1 on 02 August 2018       |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |
| Safety Inspection of A77 Ayr South V1 on 09 August 2018       |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |
| Safety Inspection of A77 Ayr South V1 on 16 August 2018       |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |
| Safety Inspection of A77 Ayr South V1 on 23 August 2018       |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |
| Safety Inspection of A77 Ayr South V1 on 30 August 2018       |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |
| Safety Inspection of A77 Ayr South V1 on 06 September 2018    |         |       |             |                       |                 |                          |                   |                 |  |
| SW80-403929-235984881   | 435m    | 436m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 07/09/2018               | Completed Defects | 06/09/2018      | A77 S/B C/W 450M NORTH OF TURBERRY NORTH GATEWAY |
| Safety Inspection of A77 Ayr South V1 on 13 September 2018    |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |
| Safety Inspection of A77 Ayr South V1 on 20 September 2018    |         |       |             |                       |                 |                          |                   |                 |  |
| No defects recorded   |         |       |             |                       |                 |                          |                   |                 |  |

| Defect Reference   | Start<br>m | End<br>m | Item Type     | Item Detail                       | Defect<br>Category | Required<br>Completion Date | Current Status          | Completion<br>Date | Location Description                                 |
|--|------------|----------|---------------|-----------------------------------|--------------------|-----------------------------|-------------------------|--------------------|--|
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b>    |            |          |               |                                   |                    |                             |                         |                    |  |
| No defects recorded  |            |          |               |                                   |                    |                             |                         |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>      |            |          |               |                                   |                    |                             |                         |                    |  |
| No defects recorded  |            |          |               |                                   |                    |                             |                         |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>      |            |          |               |                                   |                    |                             |                         |                    |  |
| No defects recorded  |            |          |               |                                   |                    |                             |                         |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>      |            |          |               |                                   |                    |                             |                         |                    |  |
| SW82423458-236136743   | 190m       | 191m     | CARRIAGEWAY   | Pothole VIAFIX (POTV)             | CAT 1              | 15/11/2018                  | Completed Defects       | 18/10/2018         | A77 SB CW, 300M NTH OF TURNBERRY NTH GATEWAY         |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |            |          |               |                                   |                    |                             |                         |                    |  |
| SW82332071-695   | 200m       | 201m     | TRAFFIC_SIGNS | Physical condition of post (COPT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action   | 01/01/9999         |  |
| SW82332071-697   | 306m       | 307m     | TRAFFIC_SIGNS | Physical condition of post (COPT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action   | 01/01/9999         |  |
| SW82332071-699   | 628m       | 629m     | TRAFFIC_SIGNS | Physical condition of post (COPT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action   | 01/01/9999         |  |
| SW82332071-701   | 692m       | 892m     | FILTER_DRAIN  | Silted (SILT)                     | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action   | 01/01/9999         |  |
| SW82332071-698   | 592m       | 593m     | TRAFFIC_SIGNS | Physical condition of post (COPT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action   | 01/01/9999         |  |
| SW82332071-702   | 702m       | 902m     | FILTER_DRAIN  | Weed growth (WEED)                | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action   | 01/01/9999         |  |
| SW82332071-694   | 204m       | 205m     | TRAFFIC_SIGNS | Physical condition of post (COPT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action   | 01/01/9999         |  |
| SW82332071-696   | 299m       | 300m     | TRAFFIC_SIGNS | Physical condition of post (COPT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action   | 01/01/9999         |  |
| SW82332071-693   | 132m       | 133m     | TRAFFIC_SIGNS | Physical condition of post (COPT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action   | 01/01/9999         |  |
| SW82332071-700   | 626m       | 627m     | TRAFFIC_SIGNS | Physical condition of post (COPT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action   | 01/01/9999         |  |
| SW82332071-703   | 944m       | 1,141m   | FILTER_DRAIN  | Weed growth (WEED)                | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action   | 01/01/9999         |  |
| SW82332071-704   | 953m       | 1,153m   | FILTER_DRAIN  | Weed growth (WEED)                | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action   | 01/01/9999         |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>      |            |          |               |                                   |                    |                             |                         |                    |  |
| No defects recorded  |            |          |               |                                   |                    |                             |                         |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>     |            |          |               |                                   |                    |                             |                         |                    |  |
| No defects recorded  |            |          |               |                                   |                    |                             |                         |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>     |            |          |               |                                   |                    |                             |                         |                    |  |
| No defects recorded  |            |          |               |                                   |                    |                             |                         |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>     |            |          |               |                                   |                    |                             |                         |                    |  |
| No defects recorded  |            |          |               |                                   |                    |                             |                         |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b>     |            |          |               |                                   |                    |                             |                         |                    |  |
| No defects recorded  |            |          |               |                                   |                    |                             |                         |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b>     |            |          |               |                                   |                    |                             |                         |                    |  |
| SW82426917-236234292   | 821m       | 841m     | CARRIAGEWAY   | Other (OTHR)                      | 3RD PTY            | 27/12/2018                  | Awaiting CCMS Temp Date | 01/01/9999         | A77 SB CW AT LAYBY AT TOP OF HILL NORTH OF TURNBERRY |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b>     |            |          |               |                                   |                    |                             |                         |                    |  |
| No defects recorded  |            |          |               |                                   |                    |                             |                         |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b>     |            |          |               |                                   |                    |                             |                         |                    |  |
| No defects recorded  |            |          |               |                                   |                    |                             |                         |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b>     |            |          |               |                                   |                    |                             |                         |                    |  |
| No defects recorded  |            |          |               |                                   |                    |                             |                         |                    |  |

| Defect Reference   | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|--|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b> |         |       |           |             |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>  |         |       |           |             |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>  |         |       |           |             |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>  |         |       |           |             |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>  |         |       |           |             |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>  |         |       |           |             |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b> |         |       |           |             |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b> |         |       |           |             |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b> |         |       |           |             |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b> |         |       |           |             |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>    |         |       |           |             |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>    |         |       |           |             |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>    |         |       |           |             |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>    |         |       |           |             |                 |                          |                |                 |                      |
| No defects recorded  |         |       |           |             |                 |                          |                |                 |                      |

**11626/16 : NTH END TURNBERRY CLIMBING LANE TO HIGH PARK**

|  |      |      |             |                   |       |            |                   |            |  |
|--|------|------|-------------|-------------------|-------|------------|-------------------|------------|--|
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>  |      |      |             |                   |       |            |                   |            |  |
| SW82317326-235513693   | 613m | 616m | CARRIAGEWAY | Pothole<br>(POTH) | CAT 1 | 01/02/2018 | Completed Defects | 26/02/2018 | JST SOUTH ON SIB CIW<br>FROM ENTRANCE TO<br>DALQUHAT FARM    |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>  |      |      |             |                   |       |            |                   |            |  |
| No defects recorded  |      |      |             |                   |       |            |                   |            |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>  |      |      |             |                   |       |            |                   |            |  |
| No defects recorded  |      |      |             |                   |       |            |                   |            |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>  |      |      |             |                   |       |            |                   |            |  |
| No defects recorded  |      |      |             |                   |       |            |                   |            |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b> |      |      |             |                   |       |            |                   |            |  |
| No defects recorded  |      |      |             |                   |       |            |                   |            |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b> |      |      |             |                   |       |            |                   |            |  |
| No defects recorded  |      |      |             |                   |       |            |                   |            |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b> |      |      |             |                   |       |            |                   |            |  |
| No defects recorded  |      |      |             |                   |       |            |                   |            |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b> |      |      |             |                   |       |            |                   |            |  |
| SW82321955-235548223   | 599m | 56m  | CARRIAGEWAY | Pothole<br>(POTH) | CAT 1 | 22/03/2018 | Completed Defects | 26/02/2018 | A77 AT BALLOCHNEIL FARM<br>JUST SOUTH OF DALQUHAT<br>SIB CIW |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>    |      |      |             |                   |       |            |                   |            |  |
| No defects recorded  |      |      |             |                   |       |            |                   |            |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>    |      |      |             |                   |       |            |                   |            |  |
| No defects recorded  |      |      |             |                   |       |            |                   |            |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>    |      |      |             |                   |       |            |                   |            |  |
| No defects recorded  |      |      |             |                   |       |            |                   |            |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>    |      |      |             |                   |       |            |                   |            |  |
| No defects recorded  |      |      |             |                   |       |            |                   |            |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>    |      |      |             |                   |       |            |                   |            |  |
| No defects recorded  |      |      |             |                   |       |            |                   |            |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>    |      |      |             |                   |       |            |                   |            |  |
| No defects recorded  |      |      |             |                   |       |            |                   |            |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>    |      |      |             |                   |       |            |                   |            |  |
| No defects recorded  |      |      |             |                   |       |            |                   |            |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>    |      |      |             |                   |       |            |                   |            |  |
| No defects recorded  |      |      |             |                   |       |            |                   |            |  |

| Defect Reference  | Start m | End m | Item Type     | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                                      |
|---|---------|-------|---------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| Safety Inspection of A77 Ayr South V1 on 26 April 2018<br><i>No defects recorded</i>        |         |       |               |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A77 Ayr South V1 on 03 May 2018<br><i>No defects recorded</i>          |         |       |               |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A77 Ayr South V1 on 10 May 2018<br><i>No defects recorded</i>          |         |       |               |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A77 Ayr South V1 on 17 May 2018<br><i>No defects recorded</i>          |         |       |               |                                      |                 |                          |                       |                 |   |
| SW82352984-235812707  | 637m    | 645m  | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | A77 S/B AT JCT BALLOCHNEIL FARM SOUTH OF KIRKOSWALD       |
| Safety Inspection of A77 Ayr South V1 on 31 May 2018<br><i>No defects recorded</i>          |         |       |               |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A77 Ayr South V1 on 07 June 2018<br><i>No defects recorded</i>         |         |       |               |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A77 Ayr South V1 on 14 June 2018<br><i>No defects recorded</i>         |         |       |               |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A77 Ayr South V1 on 21 June 2018<br><i>No defects recorded</i>         |         |       |               |                                      |                 |                          |                       |                 |   |
| Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018<br><i>No defects recorded</i> |         |       |               |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A77 Ayr South V1 on 28 June 2018<br><i>No defects recorded</i>         |         |       |               |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A77 Ayr South V1 on 05 July 2018<br><i>No defects recorded</i>         |         |       |               |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A77 Ayr South V1 on 12 July 2018<br><i>No defects recorded</i>         |         |       |               |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A77 Ayr South V1 on 19 July 2018<br><i>No defects recorded</i>         |         |       |               |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A77 Ayr South V1 on 26 July 2018<br><i>No defects recorded</i>         |         |       |               |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A77 Ayr South V1 on 02 August 2018<br><i>No defects recorded</i>       |         |       |               |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A77 Ayr South V1 on 09 August 2018<br><i>No defects recorded</i>       |         |       |               |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A77 Ayr South V1 on 16 August 2018<br><i>No defects recorded</i>       |         |       |               |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A77 Ayr South V1 on 23 August 2018<br><i>No defects recorded</i>       |         |       |               |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A77 Ayr South V1 on 30 August 2018<br><i>No defects recorded</i>       |         |       |               |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A77 Ayr South V1 on 06 September 2018<br><i>No defects recorded</i>    |         |       |               |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A77 Ayr South V1 on 13 September 2018<br><i>No defects recorded</i>    |         |       |               |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A77 Ayr South V1 on 20 September 2018<br><i>No defects recorded</i>    |         |       |               |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A77 Ayr South V1 on 27 September 2018<br><i>No defects recorded</i>    |         |       |               |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A77 Ayr South V1 on 04 October 2018<br><i>No defects recorded</i>      |         |       |               |                                      |                 |                          |                       |                 |   |
| SW82420227-236118420  | 608m    | 609m  | CARRIAGEWAY   | Pothole VIAFIX (POTV)                | CAT 1           | 12/10/2018               | Completed Defects     | 11/10/2018      | A77 SB CW AT DALQUAT                                      |
| SW82423458-236136744  | 599m    | 600m  | CARRIAGEWAY   | Pothole VIAFIX (POTV)                | CAT 1           | 15/11/2018               | Completed Defects     | 18/10/2018      | A77 SB CW, OPPOSITE BALLOCHNEIL COTTAGE STH OF KIRKOSWALD |
| SW82332071-707  | 539m    | 619m  | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-705  | 1m      | 2m    | TRAFFIC_SIGNS | Physical condition of post (COPT)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |

| Defect Reference  | Start<br>m | End<br>m | Item Type     | Item Detail                          | Defect<br>Category | Required<br>Completion Date | Current Status        | Completion<br>Date | Location Description            |
|---|------------|----------|---------------|--------------------------------------|--------------------|-----------------------------|-----------------------|--------------------|---------------------------------|
| SW82332071-706  | 8m         | 9m       | TRAFFIC_SIGNS | Physical condition of post (COPT)    | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                                 |
| SW82332071-708  | 562m       | 642m     | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                                 |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>           |            |          |               |                                      |                    |                             |                       |                    |                                 |
| No defects recorded   |            |          |               |                                      |                    |                             |                       |                    |                                 |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>          |            |          |               |                                      |                    |                             |                       |                    |                                 |
| No defects recorded   |            |          |               |                                      |                    |                             |                       |                    |                                 |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>          |            |          |               |                                      |                    |                             |                       |                    |                                 |
| SW82426441-236211990  | 597m       | 600m     | CARRIAGEWAY   | Pothole (POTH)                       | CAT 1              | 06/12/2018                  | Completed Defects     | 23/11/2018         | A77 SB CW OPPOSITE DALQUAT FARM |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>          |            |          |               |                                      |                    |                             |                       |                    |                                 |
| No defects recorded   |            |          |               |                                      |                    |                             |                       |                    |                                 |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b>          |            |          |               |                                      |                    |                             |                       |                    |                                 |
| No defects recorded   |            |          |               |                                      |                    |                             |                       |                    |                                 |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b>          |            |          |               |                                      |                    |                             |                       |                    |                                 |
| No defects recorded   |            |          |               |                                      |                    |                             |                       |                    |                                 |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b>          |            |          |               |                                      |                    |                             |                       |                    |                                 |
| No defects recorded   |            |          |               |                                      |                    |                             |                       |                    |                                 |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b>          |            |          |               |                                      |                    |                             |                       |                    |                                 |
| No defects recorded   |            |          |               |                                      |                    |                             |                       |                    |                                 |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b>          |            |          |               |                                      |                    |                             |                       |                    |                                 |
| No defects recorded   |            |          |               |                                      |                    |                             |                       |                    |                                 |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b>          |            |          |               |                                      |                    |                             |                       |                    |                                 |
| No defects recorded   |            |          |               |                                      |                    |                             |                       |                    |                                 |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>           |            |          |               |                                      |                    |                             |                       |                    |                                 |
| No defects recorded   |            |          |               |                                      |                    |                             |                       |                    |                                 |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>           |            |          |               |                                      |                    |                             |                       |                    |                                 |
| No defects recorded   |            |          |               |                                      |                    |                             |                       |                    |                                 |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>           |            |          |               |                                      |                    |                             |                       |                    |                                 |
| No defects recorded   |            |          |               |                                      |                    |                             |                       |                    |                                 |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>           |            |          |               |                                      |                    |                             |                       |                    |                                 |
| No defects recorded   |            |          |               |                                      |                    |                             |                       |                    |                                 |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>           |            |          |               |                                      |                    |                             |                       |                    |                                 |
| SW82428625-236291422  | 613m       | 614m     | CARRIAGEWAY   | Pothole VIAFIX (POTV)                | CAT 1              | 01/02/2019                  | Completed Defects     | 31/01/2019         | A77 NB CW AT DALQUAT FARM       |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b>          |            |          |               |                                      |                    |                             |                       |                    |                                 |
| No defects recorded   |            |          |               |                                      |                    |                             |                       |                    |                                 |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b>          |            |          |               |                                      |                    |                             |                       |                    |                                 |
| No defects recorded   |            |          |               |                                      |                    |                             |                       |                    |                                 |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b>          |            |          |               |                                      |                    |                             |                       |                    |                                 |
| No defects recorded   |            |          |               |                                      |                    |                             |                       |                    |                                 |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b>          |            |          |               |                                      |                    |                             |                       |                    |                                 |
| No defects recorded   |            |          |               |                                      |                    |                             |                       |                    |                                 |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>             |            |          |               |                                      |                    |                             |                       |                    |                                 |
| No defects recorded   |            |          |               |                                      |                    |                             |                       |                    |                                 |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>             |            |          |               |                                      |                    |                             |                       |                    |                                 |
| No defects recorded   |            |          |               |                                      |                    |                             |                       |                    |                                 |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>             |            |          |               |                                      |                    |                             |                       |                    |                                 |
| No defects recorded   |            |          |               |                                      |                    |                             |                       |                    |                                 |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>             |            |          |               |                                      |                    |                             |                       |                    |                                 |
| No defects recorded   |            |          |               |                                      |                    |                             |                       |                    |                                 |
| <b>11644/07 : WITH: WHITLETTS ROUNDABOUT TO SANDYFORD TOLL RBT</b>        |            |          |               |                                      |                    |                             |                       |                    |                                 |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 January 2018</b> |            |          |               |                                      |                    |                             |                       |                    |                                 |
| No defects recorded   |            |          |               |                                      |                    |                             |                       |                    |                                 |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 January 2018</b> |            |          |               |                                      |                    |                             |                       |                    |                                 |
| No defects recorded   |            |          |               |                                      |                    |                             |                       |                    |                                 |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 January 2018</b> |            |          |               |                                      |                    |                             |                       |                    |                                 |
| No defects recorded   |            |          |               |                                      |                    |                             |                       |                    |                                 |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 January 2018</b> |            |          |               |                                      |                    |                             |                       |                    |                                 |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail    | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                         |
|--|---------|--------|-------------|----------------|-----------------|--------------------------|-------------------|-----------------|--|
| SW82317767-235529087   | 2,196m  | 2,198m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 20/02/2018               | Completed Defects | 23/01/2018      | A77 SB CW, 660M STH OF DUTCHHOUSE RBT        |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 January 2018</b>  |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 February 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 February 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 February 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 February 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 March 2018</b>    |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 March 2018</b>    |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 March 2018</b>    |         |        |             |                |                 |                          |                   |                 |  |
| SW82329522-235601244   | 2,193m  | 2,195m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 17/04/2018               | Completed Defects | 20/03/2018      | A77 SB CW, LANE 1, 500M NTH OF SANDYFORD RBT |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 March 2018</b>    |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 April 2018</b>    |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 April 2018</b>    |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 April 2018</b>    |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 April 2018</b>    |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 01 May 2018</b>      |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 May 2018</b>      |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 May 2018</b>      |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 May 2018</b>      |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 May 2018</b>      |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 June 2018</b>     |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 June 2018</b>     |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 June 2018</b>     |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 June 2018</b>     |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018</b>       |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 July 2018</b>     |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 July 2018</b>     |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 July 2018</b>     |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 July 2018</b>     |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 July 2018</b>     |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 August 2018</b>   |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 14 August 2018</b>   |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 21 August 2018</b>   |         |        |             |                |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |        |             |                |                 |                          |                   |                 |  |



| Defect Reference  | Start<br>m | End<br>m | Item Type     | Item Detail                          | Defect<br>Category | Required<br>Completion Date | Current Status        | Completion<br>Date | Location Description                    |
|---|------------|----------|---------------|--------------------------------------|--------------------|-----------------------------|-----------------------|--------------------|---|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 28 August 2018</b>    |            |          |               |                                      |                    |                             |                       |                    |   |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 September 2018</b> |            |          |               |                                      |                    |                             |                       |                    |   |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 September 2018</b> |            |          |               |                                      |                    |                             |                       |                    |   |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 September 2018</b> |            |          |               |                                      |                    |                             |                       |                    |   |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 25 September 2018</b> |            |          |               |                                      |                    |                             |                       |                    |   |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 October 2018</b>   |            |          |               |                                      |                    |                             |                       |                    |   |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 October 2018</b>   |            |          |               |                                      |                    |                             |                       |                    |   |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 October 2018</b>   |            |          |               |                                      |                    |                             |                       |                    |   |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 October 2018</b>   |            |          |               |                                      |                    |                             |                       |                    |   |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 October 2018</b>   |            |          |               |                                      |                    |                             |                       |                    |   |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 November 2018</b>  |            |          |               |                                      |                    |                             |                       |                    |   |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 November 2018</b>  |            |          |               |                                      |                    |                             |                       |                    |   |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 November 2018</b>  |            |          |               |                                      |                    |                             |                       |                    |   |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 November 2018</b>  |            |          |               |                                      |                    |                             |                       |                    |   |
| SW82426853-236234064  | 354m       | 355m     | TRAFFIC_SIGNS | Pointing wrong way (RWAY)            | CAT 1              | 28/11/2018                  | Completed Defects     | 27/11/2018         | A77 CENTRAL RES 350M FROMCWHITLETTS RBT |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 December 2018</b>  |            |          |               |                                      |                    |                             |                       |                    |   |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 December 2018</b>  |            |          |               |                                      |                    |                             |                       |                    |   |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 December 2018</b>  |            |          |               |                                      |                    |                             |                       |                    |   |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 December 2018</b>  |            |          |               |                                      |                    |                             |                       |                    |   |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 December 2018</b>  |            |          |               |                                      |                    |                             |                       |                    |   |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 January 2019</b>   |            |          |               |                                      |                    |                             |                       |                    |   |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 January 2019</b>   |            |          |               |                                      |                    |                             |                       |                    |   |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 January 2019</b>   |            |          |               |                                      |                    |                             |                       |                    |   |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018</b>    |            |          |               |                                      |                    |                             |                       |                    |   |
| SW82332070-174  | 882m       | 981m     | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |   |
| SW82332070-176  | 1,015m     | 1,115m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |   |
| SW82332070-191  | 2,413m     | 2,513m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |   |
| SW82332070-193  | 2,459m     | 2,460m   | TRAFFIC_SIGNS | Physical condition of post (COPT)    | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |   |
| SW82332070-178  | 1,267m     | 1,300m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |   |
| SW82332070-180  | 1,351m     | 1,361m   | CARRIAGEWAY   | Opening of longitudinal joint (OLJT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |   |

| Defect Reference | Start m | End m  | Item Type     | Item Detail                                  | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|--------|---------------|--|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82332070-187   | 1,870m  | 1,875m | CARRIAGEWAY   | Localised cracking (LOCK)                    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-189   | 2,250m  | 2,251m | TRAFFIC_SIGNS | Physical condition of post (COPT)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-172   | 748m    | 798m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-179   | 1,332m  | 1,382m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-186   | 1,743m  | 1,745m | CARRIAGEWAY   | Localised cracking (LOCK)                    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-165   | 414m    | 424m   | FOOTWAY       | Bituminous surfacing - local cracking (BLCK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-168   | 525m    | 525m   | TRAFFIC_SIGNS | Physical condition of post (COPT)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-182   | 1,427m  | 1,467m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-183   | 1,458m  | 1,500m | CARRIAGEWAY   | Localised cracking (LOCK)                    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-162   | 225m    | 325m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-164   | 366m    | 369m   | CARRIAGEWAY   | Localised cracking (LOCK)                    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-169   | 575m    | 575m   | TRAFFIC_SIGNS | Physical condition of post (COPT)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-171   | 730m    | 731m   | TRAFFIC_SIGNS | Physical condition of post (COPT)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-194   | 2,550m  | 2,551m | TRAFFIC_SIGNS | Physical condition of post (COPT)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-196   | 2,700m  | 2,720m | CARRIAGEWAY   | Localised cracking (LOCK)                    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-173   | 861m    | 863m   | CARRIAGEWAY   | Single crack (CRCK)                          | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-175   | 950m    | 951m   | TRAFFIC_SIGNS | Physical condition of post (COPT)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-177   | 1,169m  | 1,169m | TRAFFIC_SIGNS | Physical condition of post (COPT)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-190   | 2,302m  | 2,302m | TRAFFIC_SIGNS | Physical condition of post (COPT)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-192   | 2,451m  | 2,451m | TRAFFIC_SIGNS | Physical condition of post (COPT)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-163   | 254m    | 354m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |

| Defect Reference   | Start m | End m  | Item Type     | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                |
|--|---------|--------|---------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|-------------------------------------|
| SW82332070-170   | 663m    | 664m   | TRAFFIC_SIGNS | Physical condition of post (COPT)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                     |
| SW82332070-181   | 1,402m  | 1,412m | CARRIAGEWAY   | Opening of longitudinal joint (OLJT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                     |
| SW82332070-188   | 2,110m  | 2,112m | CARRIAGEWAY   | Pothole (POTH)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                     |
| SW82332070-195   | 2,649m  | 2,650m | TRAFFIC_SIGNS | Physical condition of post (COPT)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                     |
| SW82332070-166   | 430m    | 431m   | CARRIAGEWAY   | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                     |
| SW82332070-167   | 486m    | 487m   | TRAFFIC_SIGNS | Physical condition of post (COPT)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                     |
| SW82332070-184   | 1,499m  | 1,510m | CARRIAGEWAY   | Opening of longitudinal joint (OLJT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                     |
| SW82332070-185   | 1,585m  | 1,595m | CARRIAGEWAY   | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 January 2019</b>  |         |        |               |                                      |                 |                          |                       |                 |                                     |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 January 2019</b>  |         |        |               |                                      |                 |                          |                       |                 |                                     |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 February 2019</b> |         |        |               |                                      |                 |                          |                       |                 |                                     |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 February 2019</b> |         |        |               |                                      |                 |                          |                       |                 |                                     |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 February 2019</b> |         |        |               |                                      |                 |                          |                       |                 |                                     |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 February 2019</b> |         |        |               |                                      |                 |                          |                       |                 |                                     |
| SW82435554-236335880   | 1,365m  | 1,370m | CARRIAGEWAY   | Pothole (POTH)                       | CAT 1           | 27/02/2019               | Completed Defects     | 26/02/2019      | A77 N/B AT ENTRANCE TO JST SERVICES |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 March 2019</b>    |         |        |               |                                      |                 |                          |                       |                 |                                     |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 March 2019</b>    |         |        |               |                                      |                 |                          |                       |                 |                                     |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 March 2019</b>    |         |        |               |                                      |                 |                          |                       |                 |                                     |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 March 2019</b>    |         |        |               |                                      |                 |                          |                       |                 |                                     |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                                     |
| <b>11644/90 : SANDYFORD TOLL ROUNDABOUT</b>                                |         |        |               |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 January 2018</b>  |         |        |               |                                      |                 |                          |                       |                 |                                     |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 January 2018</b>  |         |        |               |                                      |                 |                          |                       |                 |                                     |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 January 2018</b>  |         |        |               |                                      |                 |                          |                       |                 |                                     |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 January 2018</b>  |         |        |               |                                      |                 |                          |                       |                 |                                     |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 January 2018</b>  |         |        |               |                                      |                 |                          |                       |                 |                                     |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 February 2018</b> |         |        |               |                                      |                 |                          |                       |                 |                                     |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 February 2018</b> |         |        |               |                                      |                 |                          |                       |                 |                                     |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 February 2018</b> |         |        |               |                                      |                 |                          |                       |                 |                                     |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                                     |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 February 2018</b> |         |        |               |                                      |                 |                          |                       |                 |                                     |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                                     |

| Defect Reference  | Start<br>m | End<br>m | Item Type | Item Detail | Defect<br>Category | Required<br>Completion Date | Current Status | Completion<br>Date | Location Description |
|---|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 March 2018</b>     |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 March 2018</b>     |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 March 2018</b>     |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 March 2018</b>     |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 April 2018</b>     |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 April 2018</b>     |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 April 2018</b>     |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 April 2018</b>     |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 01 May 2018</b>       |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 May 2018</b>       |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 May 2018</b>       |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 May 2018</b>       |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 May 2018</b>       |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 June 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 June 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 June 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 June 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018</b>        |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 July 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 July 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 July 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 July 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 July 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 August 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 14 August 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 21 August 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 28 August 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 September 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 September 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 September 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 25 September 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 October 2018</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 October 2018</b>   |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>  |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 October 2018</b>   |            |          |           |             |                    |                             |                |                    |                      |

| Defect Reference  | Start m | End m  | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                                    |
|---|---------|--------|-------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A76 & A77 Ayr North V1 on 23 October 2018    |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A76 & A77 Ayr North V1 on 30 October 2018    |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A76 & A77 Ayr North V1 on 06 November 2018   |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A76 & A77 Ayr North V1 on 13 November 2018   |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018 |         |        |             |                                      |                 |                          |                       |                 |   |
| SW82332070-75   | 52m     | 72m    | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332070-73   | 8m      | 88m    | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332070-74   | 91m     | 171m   | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| Safety Inspection of A76 & A77 Ayr North V1 on 20 November 2018   |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A76 & A77 Ayr North V1 on 27 November 2018   |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A76 & A77 Ayr North V1 on 04 December 2018   |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A76 & A77 Ayr North V1 on 11 December 2018   |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A76 & A77 Ayr North V1 on 18 December 2018   |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A76 & A77 Ayr North V1 on 24 December 2018   |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A76 & A77 Ayr North V1 on 31 December 2018   |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A76 & A77 Ayr North V1 on 07 January 2019    |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A76 & A77 Ayr North V1 on 08 January 2019    |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A76 & A77 Ayr North V1 on 15 January 2019    |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A76 & A77 Ayr North V1 on 22 January 2019    |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A76 & A77 Ayr North V1 on 29 January 2019    |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A76 & A77 Ayr North V1 on 05 February 2019   |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A76 & A77 Ayr North V1 on 12 February 2019   |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A76 & A77 Ayr North V1 on 19 February 2019   |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A76 & A77 Ayr North V1 on 26 February 2019   |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A76 & A77 Ayr North V1 on 05 March 2019      |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A76 & A77 Ayr North V1 on 12 March 2019      |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A76 & A77 Ayr North V1 on 19 March 2019      |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A76 & A77 Ayr North V1 on 26 March 2019      |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>11647/07 : WITH: SANDYFORD TOLL R/BOUT to Dutch House Rbt</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018    |         |        |             |                                      |                 |                          |                       |                 |   |
| SW82317274-235513676  | 1,247m  | 1,250m | CARRIAGEWAY | Pothole (POTH)                       | CAT 1           | 30/01/2018               | Completed Defects     | 29/01/2018      | A77 N/B 500M NORTH OF OVERBRIDGE NORTH OF SANDYFORD RBT |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail    | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description   |
|--|---------|--------|-------------|----------------|-----------------|--------------------------|-------------------|-----------------|--|
| SW82317274-235513675   | 1,165m  | 1,169m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 30/01/2018               | Completed Defects | 09/02/2018      | N/B ON CENTRE LINE 400M NORTH OF OVER BRIDGE NORTH OF SANDY FORD RBT   |
| SW82317274-235513677   | 1,447m  | 1,449m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 30/01/2018               | Completed Defects | 30/01/2018      | A77 N/B ON CENTRE LINE 600M NORTH OF OVERBRIDGE NORTH OF SANDYFORD RBT |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 January 2018</b>  |         |        |             |                |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 January 2018</b>  |         |        |             |                |                 |                          |                   |                 |  |
| SW82317632-235520462   | 468m    | 469m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 13/02/2018               | Completed Defects | 29/01/2018      | LANE 2 500 M NORTH OF SANDYFORD RBT NORTHBOUND CARRIAGEWAY             |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 January 2018</b>  |         |        |             |                |                 |                          |                   |                 |  |
| SW82317767-235529069   | 3,223m  | 3,224m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 20/02/2018               | Completed Defects | 09/02/2018      | A77 NB CW, LANE 2, 150M STH OF DUTCHHOUSE RBT                          |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 January 2018</b>  |         |        |             |                |                 |                          |                   |                 |  |
| SW82318102-235532002   | 744m    | 755m   | CARRIAGEWAY | Pothole (POTH) | CAT 2           | 01/01/9999               | Completed Defects | 22/09/2018      | A77 NB CW, LANE 1, 750M NTH SANDYFORD                                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 February 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| SW82318894-235534930   | 396m    | 2,184m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 06/03/2018               | Completed Defects | 06/02/2018      | A77 NB CW, BETWEEN SANDYFORD AND DUTCH HOUSE RBT                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 February 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| SW82319390-235542964   | 3,342m  | 3,343m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 13/03/2018               | Completed Defects | 13/02/2018      | A77 NB CW, LANE 2, 150M STH OF DUTCH HOUSE RBT                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 February 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 February 2018</b> |         |        |             |                |                 |                          |                   |                 |  |
| SW82323374-235550827   | 2,101m  | 2,102m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 27/03/2018               | Completed Defects | 28/02/2018      | A77 NB CW, LANE 1, ON BRIDGE DECK, 2000M NTH OF SANDYFORD RBT          |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 March 2018</b>    |         |        |             |                |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 March 2018</b>    |         |        |             |                |                 |                          |                   |                 |  |
| No defects recorded  |         |        |             |                |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 March 2018</b>    |         |        |             |                |                 |                          |                   |                 |  |
| SW82329522-235601239   | 442m    | 446m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 17/04/2018               | Completed Defects | 20/03/2018      | A77 NB CW, 100-400M NTH OF SANDYFORD RBT                               |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 March 2018</b>    |         |        |             |                |                 |                          |                   |                 |  |
| SW82331491-235609003   | 501m    | 502m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 24/04/2018               | Completed Defects | 27/03/2018      | A77 NB CL, 450M NTH OF SANDYFORD                                       |
| SW82331491-235609005   | 810m    | 811m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 24/04/2018               | Completed Defects | 27/03/2018      | A77 NB CW, 800M NTH OF SANDYFORD RBT                                   |
| SW82331491-235609012   | 1,513m  | 1,514m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 24/04/2018               | Completed Defects | 28/03/2018      | A77 NB CW, 1500M NTH OF SANDYFORD                                      |
| SW82331491-235608999   | 316m    | 317m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 24/04/2018               | Completed Defects | 27/03/2018      | A77 NB CL, 300M NTH OF SANDYFORD                                       |
| SW82331491-235609001   | 424m    | 423m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 24/04/2018               | Completed Defects | 27/03/2018      | A77 NB CL, 360M NTH OF SANDYFORD RBT                                   |
| SW82331491-235609004   | 570m    | 571m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 24/04/2018               | Completed Defects | 27/03/2018      | A77 NB CW, 570M NTH OF SANDYFORD                                       |
| SW82331491-235609007   | 984m    | 988m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 24/04/2018               | Completed Defects | 27/03/2018      | A77 NB CW, 950M NTH OF SANDYFORD                                       |

| Defect Reference  | Start m | End m  | Item Type   | Item Detail    | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description  |
|---|---------|--------|-------------|----------------|-----------------|--------------------------|-------------------|-----------------|---|
| SW82331491-235609008  | 1,054m  | 1,058m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 24/04/2018               | Completed Defects | 27/03/2018      | A77 1000M NTH OF SANDYFORD                                      |
| SW82331491-235609011  | 1,447m  | 1,448m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 24/04/2018               | Completed Defects | 28/03/2018      | A77 NB CW, 1400M NTH OF SANDYFORD                               |
| SW82331491-235609006  | 913m    | 915m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 24/04/2018               | Completed Defects | 27/03/2018      | A77 NB CW, 900M NTH OF SANDYFORD                                |
| SW82331491-235609009  | 1,290m  | 1,291m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 24/04/2018               | Completed Defects | 28/03/2018      | A77 NB CW, 1300M NTH OF SANDYFORD                               |
| SW82331491-235609010  | 1,390m  | 1,391m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 24/04/2018               | Completed Defects | 28/03/2018      | A77 NB CW, 1360M NTH OF SANDYFORD                               |
| SW82331491-235609000  | 362m    | 363m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 24/04/2018               | Completed Defects | 27/03/2018      | A77 NB CL, 320M NTH OF SANDYFORD                                |
| SW82331491-235609002  | 431m    | 432m   | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 24/04/2018               | Completed Defects | 27/03/2018      | A77 NB CL, 380M NTH OF SANDYFORD                                |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 April 2018</b> |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 April 2018</b> |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 April 2018</b> |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 April 2018</b> |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 01 May 2018</b>   |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 May 2018</b>   |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 May 2018</b>   |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 May 2018</b>   |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 May 2018</b>   |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 June 2018</b>  |         |        |             |                |                 |                          |                   |                 |   |
| SW82358718-235826953  | 2,680m  | 2,681m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 03/07/2018               | Completed Defects | 06/06/2018      | A77 NB CW 800M SOUTH OF DUTCH HOUSE RBT CL                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 June 2018</b>  |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 June 2018</b>  |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 June 2018</b>  |         |        |             |                |                 |                          |                   |                 |   |
| SW82369551-235867685  | 2,677m  | 2,678m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 24/07/2018               | Completed Defects | 27/06/2018      | A77 NB CW CL 600M SOUTH OF DUTCH HOUSE RBT                      |
| SW82369551-235867686  | 2,731m  | 2,732m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 24/07/2018               | Completed Defects | 27/06/2018      | A77 NB CW CL 550M PRIOR TO DUTCH HOUSE RBT                      |
| SW82369551-235867683  | 3,362m  | 3,363m | CARRIAGEWAY | Pothole (POTH) | CAT 1           | 24/07/2018               | Completed Defects | 27/06/2018      | A77 NB CW LANE 2 100M COUNTDOWN MARKER PRIOR TO DUTCH HOUSE RBT |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018</b>    |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 July 2018</b>  |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 July 2018</b>  |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 July 2018</b>  |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 July 2018</b>  |         |        |             |                |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |        |             |                |                 |                          |                   |                 |   |

| Defect Reference  | Start<br>m | End<br>m | Item Type     | Item Detail                                | Defect<br>Category | Required<br>Completion Date | Current Status           | Completion<br>Date | Location Description  |
|---|------------|----------|---------------|--|--------------------|-----------------------------|--------------------------|--------------------|---|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 July 2018</b>      |            |          |               |  |                    |                             |                          |                    |   |
| No defects recorded   |            |          |               |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 August 2018</b>    |            |          |               |  |                    |                             |                          |                    |   |
| No defects recorded   |            |          |               |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 14 August 2018</b>    |            |          |               |  |                    |                             |                          |                    |   |
| SW80-393014-235952314   | 2,057m     | 2,058m   | GULLY         | Blockage<br>(BLOK)                         | CAT 1              | 11/09/2018                  | Completed<br>Defects     | 17/08/2018         | A77 SB CW AT THE<br>UNDERBRIDGE BETWEEN<br>DUTCH HOUSE AND<br>SANDYFORD |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 21 August 2018</b>    |            |          |               |  |                    |                             |                          |                    |   |
| No defects recorded   |            |          |               |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 28 August 2018</b>    |            |          |               |  |                    |                             |                          |                    |   |
| No defects recorded   |            |          |               |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 September 2018</b> |            |          |               |  |                    |                             |                          |                    |   |
| No defects recorded   |            |          |               |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 September 2018</b> |            |          |               |  |                    |                             |                          |                    |   |
| No defects recorded   |            |          |               |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 September 2018</b> |            |          |               |  |                    |                             |                          |                    |   |
| No defects recorded   |            |          |               |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 25 September 2018</b> |            |          |               |  |                    |                             |                          |                    |   |
| No defects recorded   |            |          |               |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 October 2018</b>   |            |          |               |  |                    |                             |                          |                    |   |
| No defects recorded   |            |          |               |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 October 2018</b>   |            |          |               |  |                    |                             |                          |                    |   |
| No defects recorded   |            |          |               |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 October 2018</b>   |            |          |               |  |                    |                             |                          |                    |   |
| No defects recorded   |            |          |               |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 October 2018</b>   |            |          |               |  |                    |                             |                          |                    |   |
| No defects recorded   |            |          |               |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 October 2018</b>   |            |          |               |  |                    |                             |                          |                    |   |
| No defects recorded   |            |          |               |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 November 2018</b>  |            |          |               |  |                    |                             |                          |                    |   |
| No defects recorded   |            |          |               |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 November 2018</b>  |            |          |               |  |                    |                             |                          |                    |   |
| No defects recorded   |            |          |               |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 November 2018</b>  |            |          |               |  |                    |                             |                          |                    |   |
| No defects recorded   |            |          |               |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 November 2018</b>  |            |          |               |  |                    |                             |                          |                    |   |
| No defects recorded   |            |          |               |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 December 2018</b>  |            |          |               |  |                    |                             |                          |                    |   |
| No defects recorded   |            |          |               |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 December 2018</b>  |            |          |               |  |                    |                             |                          |                    |   |
| No defects recorded   |            |          |               |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 December 2018</b>  |            |          |               |  |                    |                             |                          |                    |   |
| No defects recorded   |            |          |               |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 December 2018</b>  |            |          |               |  |                    |                             |                          |                    |   |
| No defects recorded   |            |          |               |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 December 2018</b>  |            |          |               |  |                    |                             |                          |                    |   |
| No defects recorded   |            |          |               |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 January 2019</b>   |            |          |               |  |                    |                             |                          |                    |   |
| SW82427982-236271067  | 3,333m     | 3,334m   | CARRIAGEWAY   | Pothole VIAFIX<br>(POTV)                   | CAT 1              | 04/02/2019                  | Completed<br>Defects     | 08/01/2019         | A77 NB CW, LANE 2, 150M<br>STH OF DUTCH HOUSE RBT                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 January 2019</b>   |            |          |               |  |                    |                             |                          |                    |   |
| No defects recorded   |            |          |               |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 January 2019</b>   |            |          |               |  |                    |                             |                          |                    |   |
| No defects recorded   |            |          |               |  |                    |                             |                          |                    |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018</b>    |            |          |               |  |                    |                             |                          |                    |   |
| SW82332070-197  | 197m       | 198m     | TRAFFIC_SIGNS | Physical<br>condition of<br>post (COPT)    | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |   |
| SW82332070-198  | 3,301m     | 3,401m   | CARRIAGEWAY   | Bituminous<br>surfacing<br>fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 January 2019</b>   |            |          |               |  |                    |                             |                          |                    |   |
| No defects recorded   |            |          |               |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 January 2019</b>   |            |          |               |  |                    |                             |                          |                    |   |



| Defect Reference | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|------------------|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|
|------------------|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 05 February 2019**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 12 February 2019**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 19 February 2019**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 26 February 2019**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 05 March 2019**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 12 March 2019**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 19 March 2019**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 26 March 2019**

No defects recorded

**11647/55 : AGAINST: DUTCH HOUSE RBT TO SANDYFORD TOLL RBT**

**Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018**

No defects recorded

**Detailed Inspection TEMPLATE of A77 Ayr N Det on 15 September 2017**

|                |        |        |              |                                      |       |            |                       |            |                                    |
|----------------|--------|--------|--------------|--------------------------------------|-------|------------|-----------------------|------------|------------------------------------|
| SW82256027-325 | 2,535m | 2,615m | CARRIAGEWAY  | Bituminous surfacing fretting (BFRT) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | 0 DUTCH HOUSE RBT TO SANDYFORD RBT |
| SW82256027-326 | 3,223m | 3,303m | CARRIAGEWAY  | Bituminous surfacing fretting (BFRT) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | 0 DUTCH HOUSE RBT TO SANDYFORD RBT |
| SW82256027-329 | 3,372m | 3,451m | CARRIAGEWAY  | Bituminous surfacing fretting (BFRT) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | 0 DUTCH HOUSE RBT TO SANDYFORD RBT |
| SW82256027-327 | 3,272m | 3,352m | CARRIAGEWAY  | Bituminous surfacing fretting (BFRT) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | 0 DUTCH HOUSE RBT TO SANDYFORD RBT |
| SW82256027-328 | 3,346m | 3,426m | CARRIAGEWAY  | Bituminous surfacing fretting (BFRT) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | 0 DUTCH HOUSE RBT TO SANDYFORD RBT |
| SW82256027-324 | 1,415m | 1,495m | CARRIAGEWAY  | Bituminous surfacing fretting (BFRT) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | 0 DUTCH HOUSE RBT TO SANDYFORD RBT |
| SW82256027-323 | 410m   | 490m   | CARRIAGEWAY  | Bituminous surfacing fretting (BFRT) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 | 0 DUTCH HOUSE RBT TO SANDYFORD RBT |
| SW82256027-330 | 3,399m | 3,499m | FILTER_DRAIN | Weed growth (WEED)                   | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 |                                    |

**Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018**

No defects recorded



| Defect Reference  | Start m | End m  | Item Type       | Item Detail                       | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description  |
|---|---------|--------|-----------------|-----------------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 March 2018</b>     |         |        |                 |                                   |                 |                          |                       |                 |   |
| No defects recorded   |         |        |                 |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 March 2018</b>     |         |        |                 |                                   |                 |                          |                       |                 |   |
| No defects recorded   |         |        |                 |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 April 2018</b>     |         |        |                 |                                   |                 |                          |                       |                 |   |
| No defects recorded   |         |        |                 |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 April 2018</b>     |         |        |                 |                                   |                 |                          |                       |                 |   |
| No defects recorded   |         |        |                 |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 April 2018</b>     |         |        |                 |                                   |                 |                          |                       |                 |   |
| No defects recorded   |         |        |                 |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 April 2018</b>     |         |        |                 |                                   |                 |                          |                       |                 |   |
| No defects recorded   |         |        |                 |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 01 May 2018</b>       |         |        |                 |                                   |                 |                          |                       |                 |   |
| No defects recorded   |         |        |                 |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 May 2018</b>       |         |        |                 |                                   |                 |                          |                       |                 |   |
| No defects recorded   |         |        |                 |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 May 2018</b>       |         |        |                 |                                   |                 |                          |                       |                 |   |
| No defects recorded   |         |        |                 |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 May 2018</b>       |         |        |                 |                                   |                 |                          |                       |                 |   |
| No defects recorded   |         |        |                 |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 May 2018</b>       |         |        |                 |                                   |                 |                          |                       |                 |   |
| No defects recorded   |         |        |                 |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 June 2018</b>      |         |        |                 |                                   |                 |                          |                       |                 |   |
| No defects recorded   |         |        |                 |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 June 2018</b>      |         |        |                 |                                   |                 |                          |                       |                 |   |
| No defects recorded   |         |        |                 |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 June 2018</b>      |         |        |                 |                                   |                 |                          |                       |                 |   |
| No defects recorded   |         |        |                 |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 June 2018</b>      |         |        |                 |                                   |                 |                          |                       |                 |   |
| SW82369551-235867684  | 276m    | 277m   | TRAFFIC_SIGNS   | Physical condition of post (COPT) | CAT 1           | 27/06/2018               | Completed Defects     | 26/06/2018      | A77 SB CW ATLAYBY SOUTH OF DUTCH HOUSE RBT                        |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018</b>        |         |        |                 |                                   |                 |                          |                       |                 |   |
| No defects recorded   |         |        |                 |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 July 2018</b>      |         |        |                 |                                   |                 |                          |                       |                 |   |
| No defects recorded   |         |        |                 |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 July 2018</b>      |         |        |                 |                                   |                 |                          |                       |                 |   |
| No defects recorded   |         |        |                 |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 July 2018</b>      |         |        |                 |                                   |                 |                          |                       |                 |   |
| No defects recorded   |         |        |                 |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 July 2018</b>      |         |        |                 |                                   |                 |                          |                       |                 |   |
| No defects recorded   |         |        |                 |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 July 2018</b>      |         |        |                 |                                   |                 |                          |                       |                 |   |
| No defects recorded   |         |        |                 |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 August 2018</b>    |         |        |                 |                                   |                 |                          |                       |                 |   |
| SW80-389720-235948043   | 1,058m  | 1,200m | CENTRAL_RESERVE | Overhanging/overgrown (OVER)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | A77 SB CW 500M AFTER DUTCHHOUSE RBT                               |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 14 August 2018</b>    |         |        |                 |                                   |                 |                          |                       |                 |   |
| SW80-393014-235952316   | 1,478m  | 1,479m | GULLY           | Blockage (BLOK)                   | CAT 1           | 11/09/2018               | Completed Defects     | 17/08/2018      | A77 SB CW 25M AFTER UNDERBRIDGE BETWEEN DUTCH HOUSE AND SANDYFORD |
| SW80-393014-235952315   | 1,418m  | 1,419m | GULLY           | Blockage (BLOK)                   | CAT 1           | 11/09/2018               | Completed Defects     | 17/08/2018      | A77 10M AFTER UNDERBRIDGE BETWEEN DUTCH HOUSE AND SANDYFORD       |
| SW80-393014-235952317   | 1,529m  | 1,530m | GULLY           | Blockage (BLOK)                   | CAT 1           | 11/09/2018               | Completed Defects     | 17/08/2018      | A77 SB CW 40M AFTER UNDERBRIDGE BETWEEN DUTCH HOUSE AND SANDYFORD |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 21 August 2018</b>    |         |        |                 |                                   |                 |                          |                       |                 |   |
| No defects recorded   |         |        |                 |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 28 August 2018</b>    |         |        |                 |                                   |                 |                          |                       |                 |   |
| No defects recorded   |         |        |                 |                                   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 September 2018</b> |         |        |                 |                                   |                 |                          |                       |                 |   |



| Defect Reference  | Start<br>m | End<br>m | Item Type     | Item Detail                             | Defect<br>Category | Required<br>Completion Date | Current Status           | Completion<br>Date | Location Description   |
|---|------------|----------|---------------|---|--------------------|-----------------------------|--------------------------|--------------------|--|
| <i>No defects recorded</i>  |            |          |               |   |                    |                             |                          |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 11 September 2018  |            |          |               |   |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |            |          |               |   |                    |                             |                          |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 18 September 2018  |            |          |               |   |                    |                             |                          |                    |  |
| SW82409417-236071472  | 1m         | 2m       | CARRIAGEWAY   | Pothole VIAFIX<br>(POTV)                | CAT 1              | 19/09/2018                  | Completed<br>Defects     | 18/09/2018         | A77 SB LANE AT FARM JCT<br>SOUTH OF SANDYFORD RBT                        |
| Safety Inspection of A76 & A77 Ayr North V1 on 25 September 2018  |            |          |               |   |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |            |          |               |   |                    |                             |                          |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 02 October 2018    |            |          |               |   |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |            |          |               |   |                    |                             |                          |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 09 October 2018    |            |          |               |   |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |            |          |               |   |                    |                             |                          |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 16 October 2018    |            |          |               |   |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |            |          |               |   |                    |                             |                          |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 23 October 2018    |            |          |               |   |                    |                             |                          |                    |  |
| SW82425739-236166556  | 289m       | 290m     | TRAFFIC_SIGNS | Pointing wrong<br>way (RWAY)            | CAT 1              | 24/10/2018                  | Completed<br>Defects     | 23/10/2018         | A77 SB CW AT LAYBY 100M<br>AFTER DUTCHHOUSE RBT                          |
| Safety Inspection of A76 & A77 Ayr North V1 on 30 October 2018    |            |          |               |   |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |            |          |               |   |                    |                             |                          |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 06 November 2018   |            |          |               |   |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |            |          |               |   |                    |                             |                          |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 13 November 2018   |            |          |               |   |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |            |          |               |   |                    |                             |                          |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 20 November 2018   |            |          |               |   |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |            |          |               |   |                    |                             |                          |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 27 November 2018   |            |          |               |   |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |            |          |               |   |                    |                             |                          |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 04 December 2018   |            |          |               |   |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |            |          |               |   |                    |                             |                          |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 11 December 2018   |            |          |               |   |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |            |          |               |   |                    |                             |                          |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 18 December 2018   |            |          |               |   |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |            |          |               |   |                    |                             |                          |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 24 December 2018   |            |          |               |   |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |            |          |               |   |                    |                             |                          |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 31 December 2018   |            |          |               |   |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |            |          |               |   |                    |                             |                          |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 07 January 2019    |            |          |               |   |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |            |          |               |   |                    |                             |                          |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 08 January 2019    |            |          |               |   |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |            |          |               |   |                    |                             |                          |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 15 January 2019    |            |          |               |   |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |            |          |               |   |                    |                             |                          |                    |  |
| Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018 |            |          |               |   |                    |                             |                          |                    |  |
| SW82332070-199  | 3,166m     | 3,167m   | TRAFFIC_SIGNS | Physical<br>condition of<br>post (COPT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 22 January 2019    |            |          |               |   |                    |                             |                          |                    |  |
| SW82428316-236286067  | 1,398m     | 1,399m   | MANHOLE       | Missing (MISS)                          | CAT 1              | 19/02/2019                  | Completed<br>Defects     | 23/01/2019         | A77 NB CW 1 MILE SOUTH OF<br>DUTCHHOUSE AT BARRIER<br>BEFORE UNDERBRIDGE |
| Safety Inspection of A76 & A77 Ayr North V1 on 29 January 2019    |            |          |               |   |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |            |          |               |   |                    |                             |                          |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 05 February 2019   |            |          |               |   |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |            |          |               |   |                    |                             |                          |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 12 February 2019   |            |          |               |   |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |            |          |               |   |                    |                             |                          |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 19 February 2019   |            |          |               |   |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |            |          |               |   |                    |                             |                          |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 26 February 2019   |            |          |               |   |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |            |          |               |   |                    |                             |                          |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 05 March 2019      |            |          |               |   |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |            |          |               |   |                    |                             |                          |                    |  |
| Safety Inspection of A76 & A77 Ayr North V1 on 12 March 2019      |            |          |               |   |                    |                             |                          |                    |  |
| <i>No defects recorded</i>  |            |          |               |   |                    |                             |                          |                    |  |

| Defect Reference  | Start<br>m | End<br>m | Item Type   | Item Detail           | Defect<br>Category | Required<br>Completion Date | Current Status    | Completion<br>Date | Location Description   |
|---|------------|----------|-------------|-----------------------|--------------------|-----------------------------|-------------------|--------------------|--|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 March 2019</b> |            |          |             |                       |                    |                             |                   |                    |  |
| No defects recorded   |            |          |             |                       |                    |                             |                   |                    |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 March 2019</b> |            |          |             |                       |                    |                             |                   |                    |  |
| No defects recorded   |            |          |             |                       |                    |                             |                   |                    |  |
| <b>11611/57 : JCT AT CARLOCK HOUSE TO JCT AT BALLOCHDOWAN</b>           |            |          |             |                       |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>         |            |          |             |                       |                    |                             |                   |                    |  |
| SW82317326-235513698  | 203m       | 205m     | CARRIAGEWAY | Pothole (POTH)        | CAT 1              | 01/02/2018                  | Completed Defects | 27/01/2018         | at top of carlock hill 150 meters north of carlock house onboth the nb and sbcws |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>         |            |          |             |                       |                    |                             |                   |                    |  |
| No defects recorded   |            |          |             |                       |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>         |            |          |             |                       |                    |                             |                   |                    |  |
| No defects recorded   |            |          |             |                       |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>         |            |          |             |                       |                    |                             |                   |                    |  |
| No defects recorded   |            |          |             |                       |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b>        |            |          |             |                       |                    |                             |                   |                    |  |
| No defects recorded   |            |          |             |                       |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b>        |            |          |             |                       |                    |                             |                   |                    |  |
| SW82319037-235539796  | 384m       | 390m     | CARRIAGEWAY | Pothole (POTH)        | CAT 1              | 08/03/2018                  | Completed Defects | 09/02/2018         | A77 NB CW, AT TOP OF CARLOCH HILL, 100M NTH OF CARLOCH HOUSE                     |
| SW82319037-235539797  | 41m        | 50m      | CARRIAGEWAY | Pothole (POTH)        | CAT 1              | 08/03/2018                  | Completed Defects | 09/02/2018         | A77 NB CW, OPPOSITE CARLOCH HOUSE, CARLOCH HILL                                  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b>        |            |          |             |                       |                    |                             |                   |                    |  |
| SW82319984-235544947  | 1,708m     | 1,709m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1              | 15/03/2018                  | Completed Defects | 15/02/2018         | A77 SB CW, 100M STH OF BALLOCHDOWAN JCT  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b>        |            |          |             |                       |                    |                             |                   |                    |  |
| No defects recorded   |            |          |             |                       |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>           |            |          |             |                       |                    |                             |                   |                    |  |
| No defects recorded   |            |          |             |                       |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>           |            |          |             |                       |                    |                             |                   |                    |  |
| SW82326075-235554322  | 293m       | 294m     | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1              | 05/04/2018                  | Completed Defects | 08/03/2018         | A77 NB CW, 100M NTH OF CARLOCH HOUSE   |
| SW82326075-235554323  | 324m       | 325m     | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1              | 05/04/2018                  | Completed Defects | 08/03/2018         | A77 ON CL, 110M NTH CARLOCH HOUSE  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>           |            |          |             |                       |                    |                             |                   |                    |  |
| SW82328086-235590011  | 486m       | 488m     | CARRIAGEWAY | Pothole (POTH)        | CAT 1              | 12/04/2018                  | Completed Defects | 16/03/2018         | A77 NB CW, ON STRAIGHT, 600M NTH OF CARLOCH HOUSE                                |
| SW82328086-235590012  | 1,380m     | 1,382m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1              | 12/04/2018                  | Completed Defects | 16/03/2018         | A77NB CW, ON STRAIGHTS, 800M NTH OF CARLOCH HOUSE                                |
| SW82328086-235590010  | 58m        | 60m      | CARRIAGEWAY | Pothole (POTH)        | CAT 1              | 12/04/2018                  | Completed Defects | 16/03/2018         | A77 BOTH CW, OUTSIDE CARLOCH HOUSE   |
| SW82328086-235590013  | 1,350m     | 1,352m   | CARRIAGEWAY | Pothole (POTH)        | CAT 1              | 12/04/2018                  | Completed Defects | 16/03/2018         | A77 SB CW, ON STRAIGHT, 800M NTH OF CARLOCH HOUSE                                |
| SW82328086-235590014  | 950m       | 955m     | CARRIAGEWAY | Pothole (POTH)        | CAT 1              | 12/04/2018                  | Completed Defects | 16/03/2018         | A77 SB CW, ON STRAIGHT, 700-500M NTH OF CARLOCH HOUSE                            |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>           |            |          |             |                       |                    |                             |                   |                    |  |
| No defects recorded   |            |          |             |                       |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>           |            |          |             |                       |                    |                             |                   |                    |  |
| No defects recorded   |            |          |             |                       |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>           |            |          |             |                       |                    |                             |                   |                    |  |
| No defects recorded   |            |          |             |                       |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>           |            |          |             |                       |                    |                             |                   |                    |  |
| No defects recorded   |            |          |             |                       |                    |                             |                   |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>           |            |          |             |                       |                    |                             |                   |                    |  |
| No defects recorded   |            |          |             |                       |                    |                             |                   |                    |  |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail              | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                              |
|--|---------|--------|-------------|--------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>        |         |        |             |                          |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                          |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>          |         |        |             |                          |                 |                          |                       |                 |   |
| SW82344114-235554289   | 529m    | 0m     | CARRIAGEWAY | Pothole VIAFIX (POTV)    | CAT 1           | 04/05/2018               | Completed Defects     | 03/05/2018      | A77 NB 800M PAST CARLOCK HOUSE LANE 1             |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>          |         |        |             |                          |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                          |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |         |        |             |                          |                 |                          |                       |                 |   |
| SW82349855-235793431   | 71m     | 171m   | CARRIAGEWAY | Detritus / Refuse (DETR) | 3RD PTY         | 18/05/2018               | Completed Defects     | 07/05/2019      | A77 SB VERGE, AT CARLOCK HOUSE, STH OF BALLANTRAE |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |         |        |             |                          |                 |                          |                       |                 |   |
| SW82352984-235812699   | 671m    | 672m   | CARRIAGEWAY | Pothole VIAFIX (POTV)    | CAT 1           | 21/06/2018               | Completed Defects     | 24/05/2018      | A77 SB CW 25M NORTH OF LAST JCT FOR CARLOCK HOUSE |
| SW82352984-235812701   | 1,389m  | 1,390m | CARRIAGEWAY | Pothole VIAFIX (POTV)    | CAT 1           | 21/06/2018               | Completed Defects     | 24/05/2018      | A77 NB CW 150 PRIOR TO MINAR JCT                  |
| SW82352984-235812697   | 620m    | 621m   | CARRIAGEWAY | Pothole VIAFIX (POTV)    | CAT 1           | 21/06/2018               | Completed Defects     | 24/05/2018      | A77 SB CW LAST JCT BEFORE CARLOCK HOUSE           |
| SW82352984-235812700   | 653m    | 654m   | MANHOLE     | Other (OTHR)             | CAT 1           | 21/06/2018               | Completed Defects     | 24/05/2018      | A77 SB CW 5M NORTH OF LAST JCT FOR CARLOCK HOUSE  |
| SW82352984-235812698   | 671m    | 672m   | CARRIAGEWAY | Pothole VIAFIX (POTV)    | CAT 1           | 21/06/2018               | Completed Defects     | 24/05/2018      | A77 SB CW 25M NORTH OF LAST JCT FOR CARLOCK HOUSE |
| SW82352984-235812702   | 1,382m  | 1,383m | CARRIAGEWAY | Pothole VIAFIX (POTV)    | CAT 1           | 21/06/2018               | Completed Defects     | 24/05/2018      | A77 NB CW 150M PRIOR TO MINAR JCT                 |
| SW82352984-235812696   | 620m    | 621m   | CARRIAGEWAY | Pothole VIAFIX (POTV)    | CAT 1           | 21/06/2018               | Completed Defects     | 24/05/2018      | A77 SB CW LAST JCT BEFORE CARLOCK HOUSE           |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |         |        |             |                          |                 |                          |                       |                 |   |
| SW82356191-235816773   | 300m    | 301m   | CARRIAGEWAY | Pothole VIAFIX (POTV)    | CAT 1           | 28/06/2018               | Completed Defects     | 31/05/2018      | A77 NB CW CARLOCK HILL ON HFS                     |
| SW82356191-235816774   | 773m    | 774m   | CARRIAGEWAY | Pothole VIAFIX (POTV)    | CAT 1           | 28/06/2018               | Completed Defects     | 31/05/2018      | A77 SB CW CARLOCK HOUSE                           |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |         |        |             |                          |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                          |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |         |        |             |                          |                 |                          |                       |                 |   |
| SW80-363687-235858064  | 749m    | 750m   | CARRIAGEWAY | Pothole (POTH)           | CAT 1           | 12/07/2018               | Completed Defects     | 14/06/2018      | A77 SB CW 125M SOUTH OF CARLOCK HILL JCT          |
| SW80-363687-235858063  | 536m    | 537m   | CARRIAGEWAY | Pothole (POTH)           | CAT 1           | 12/07/2018               | Completed Defects     | 14/06/2018      | A77 NB CW 100M PRIOR TO CARLOCK HILL JCT          |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |         |        |             |                          |                 |                          |                       |                 |   |
| SW80-367289-235862778  | 340m    | 341m   | CARRIAGEWAY | Pothole VIAFIX (POTV)    | CAT 1           | 19/07/2018               | Completed Defects     | 21/06/2018      | A77 NB CW MINAR JCT TOP OF CARLOCK HILL           |
| SW80-367289-235862779  | 1,488m  | 1,489m | CARRIAGEWAY | Pothole VIAFIX (POTV)    | CAT 1           | 19/07/2018               | Completed Defects     | 21/06/2018      | A77 SB CW 50M SOUTH OF MINAR JCT                  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |         |        |             |                          |                 |                          |                       |                 |   |
| SW86-357213-6  | 1,732m  | 1,780m | WOODLAND    | Invasive species (INVS)  | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW86-357213-7  | 173m    | 153m   | WOODLAND    | Invasive species (INVS)  | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW86-357213-9  | 42m     | 62m    | WOODLAND    | Invasive species (INVS)  | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |         |        |             |                          |                 |                          |                       |                 |   |

| Defect Reference   | Start m | End m  | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                                       |
|--|---------|--------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|--|
| SW80-370510-235861172  | 473m    | 474m   | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 26/07/2018               | Completed Defects     | 28/06/2018      | A78 SB CW 450M BEFORE CARLOCK HOUSE                        |
| SW80-370510-235861173  | 474m    | 475m   | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 26/07/2018               | Completed Defects     | 28/06/2018      | A78 SB CW 445M BEFORE CARLOCK HOUSE                        |
| SW80-370510-235861174  | 516m    | 517m   | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 26/07/2018               | Completed Defects     | 28/06/2018      | A78 SB CW 425M BEFORE CARLOCK HOUSE                        |
| SW80-370510-235861175  | 561m    | 562m   | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 26/07/2018               | Completed Defects     | 28/06/2018      | A78 SB CW 420M BEFORE CARLOCK HOUSE                        |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW82374127-235892362   | 1,481m  | 1,482m | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 02/08/2018               | Completed Defects     | 05/07/2018      | A77 SB CW 100M PRIOR TO 1ST LAYBY AT START OF CARLOCK HILL |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW82380667-235914373   | 831m    | 832m   | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 16/08/2018               | Completed Defects     | 19/07/2018      | A77 SB CW 500M PRIOR TO CARLOCK HOUSE                      |
| SW82380667-235914374   | 839m    | 840m   | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 16/08/2018               | Completed Defects     | 19/07/2018      | A77 SB CW 505M PRIOR TO CARLOCK HOUSE                      |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW82383889-235917511   | 922m    | 923m   | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 23/08/2018               | Completed Defects     | 26/07/2018      | A77 595 PRIOR TO CARLOCK HOUSE                             |
| SW82383889-235917509   | 947m    | 948m   | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 23/08/2018               | Completed Defects     | 26/07/2018      | A77 SB CW 599M PRIOR TO CARLOCK HOUSE                      |
| SW82383889-235917512   | 922m    | 923m   | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 23/08/2018               | Completed Defects     | 26/07/2018      | A77 SB CW 589M PRIOR TO CARLOCK HOUSE                      |
| SW82383889-235917513   | 917m    | 918m   | CARRIAGEWAY        | Pothole (POTH)                       | CAT 1           | 23/08/2018               | Completed Defects     | 08/08/2018      | A77 588 M PRIOR TO CARLOCK HOUSE                           |
| SW82383889-235917508   | 946m    | 947m   | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 23/08/2018               | Completed Defects     | 26/07/2018      | A77 SB CW 600 YARDS BEFORE CARLOCK HOUSE                   |
| SW82383889-235917510   | 922m    | 923m   | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 23/08/2018               | Completed Defects     | 26/07/2018      | A77 SB 590M PRIOR TO CARLOCK HOUSE                         |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW80-387291-235943990  | 917m    | 918m   | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 30/08/2018               | Completed Defects     | 02/08/2018      | A77 SB 600M PRIOR TO CARLOCK HOUSE                         |
| SW80-387291-235943988  | 1,453m  | 1,454m | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 30/08/2018               | Completed Defects     | 02/08/2018      | A77 SB CW JCT AT CARLOCK STRAIGHT                          |
| SW80-387291-235943989  | 1,456m  | 1,457m | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 30/08/2018               | Completed Defects     | 02/08/2018      | A77 SB CW JCT AT CARLOCK STRAIGHT                          |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW82332071-247   | 245m    | 300m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |  |
| SW82332071-249   | 274m    | 350m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-254   | 338m    | 400m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |  |
| SW82332071-256   | 365m    | 425m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |  |

| Defect Reference | Start m | End m  | Item Type          | Item Detail                                    | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|--------|--------------------|--|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82332071-284   | 757m    | 825m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-286   | 785m    | 825m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-293   | 881m    | 950m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-295   | 908m    | 975m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-313   | 1,184m  | 1,250m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-315   | 1,219m  | 1,275m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-322   | 1,421m  | 1,475m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-324   | 1,477m  | 1,525m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-240   | 108m    | 109m   | GULLY              | Other (OTHR)                                   | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-243   | 217m    | 275m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-245   | 232m    | 300m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-258   | 395m    | 450m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-260   | 418m    | 475m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-280   | 702m    | 750m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-282   | 730m    | 800m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-297   | 939m    | 940m   | TRAFFIC_SIGNS      | Surface corrosion (SFCO)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-299   | 967m    | 1,025m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-309   | 1,123m  | 1,200m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-311   | 1,155m  | 1,225m | SAFETY_FENCE       | Corroded - metal post (fence / barrier) (CMTP) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |

| Defect Reference | Start<br>m | End<br>m | Item Type              | Item Detail                                | Defect<br>Category | Required<br>Completion Date | Current Status           | Completion<br>Date | Location Description |
|------------------|------------|----------|------------------------|--|--------------------|-----------------------------|--------------------------|--------------------|----------------------|
| SW82332071-326   | 1,531m     | 1,575m   | CARRIAGEWAY            | Bituminous<br>surfacing<br>fretting (BFRT) | CAT 2              | 01/01/9999                  | Completed<br>Defects     | 13/11/2018         |                      |
| SW82332071-328   | 1,588m     | 1,650m   | ROAD_MARKINGS<br>_LONG | Wear (for<br>example<br>erosion)<br>(WEAR) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                      |
| SW82332071-238   | 75m        | 150m     | ROAD_MARKINGS<br>_LONG | Wear (for<br>example<br>erosion)<br>(WEAR) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                      |
| SW82332071-246   | 241m       | 350m     | CARRIAGEWAY            | Bituminous<br>surfacing<br>fretting (BFRT) | CAT 2              | 01/01/9999                  | Completed<br>Defects     | 13/11/2018         |                      |
| SW82332071-257   | 377m       | 450m     | ROAD_MARKINGS<br>_LONG | Wear (for<br>example<br>erosion)<br>(WEAR) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                      |
| SW82332071-264   | 473m       | 550m     | CARRIAGEWAY            | Bituminous<br>surfacing<br>fretting (BFRT) | CAT 2              | 01/01/9999                  | Completed<br>Defects     | 13/11/2018         |                      |
| SW82332071-271   | 575m       | 625m     | ROAD_MARKINGS<br>_LONG | Wear (for<br>example<br>erosion)<br>(WEAR) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                      |
| SW82332071-287   | 806m       | 850m     | CARRIAGEWAY            | Bituminous<br>surfacing<br>fretting (BFRT) | CAT 2              | 01/01/9999                  | Completed<br>Defects     | 13/11/2018         |                      |
| SW82332071-294   | 894m       | 950m     | ROAD_MARKINGS<br>_LONG | Wear (for<br>example<br>erosion)<br>(WEAR) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                      |
| SW82332071-301   | 997m       | 1,050m   | CARRIAGEWAY            | Bituminous<br>surfacing<br>fretting (BFRT) | CAT 2              | 01/01/9999                  | Completed<br>Defects     | 13/11/2018         |                      |
| SW82332071-307   | 1,091m     | 1,150m   | ROAD_MARKINGS<br>_LONG | Wear (for<br>example<br>erosion)<br>(WEAR) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                      |
| SW82332071-314   | 1,201m     | 1,275m   | CARRIAGEWAY            | Bituminous<br>surfacing<br>fretting (BFRT) | CAT 2              | 01/01/9999                  | Completed<br>Defects     | 13/11/2018         |                      |
| SW82332071-321   | 1,389m     | 1,425m   | CARRIAGEWAY            | Bituminous<br>surfacing<br>fretting (BFRT) | CAT 2              | 01/01/9999                  | Completed<br>Defects     | 13/11/2018         |                      |
| SW82332071-332   | 1,689m     | 1,725m   | ROAD_MARKINGS<br>_LONG | Wear (for<br>example<br>erosion)<br>(WEAR) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                      |
| SW82332071-236   | 35m        | 125m     | CARRIAGEWAY            | Bituminous<br>surfacing<br>fretting (BFRT) | CAT 2              | 01/01/9999                  | Completed<br>Defects     | 13/11/2018         |                      |
| SW82332071-250   | 286m       | 350m     | ROAD_MARKINGS<br>_LONG | Wear (for<br>example<br>erosion)<br>(WEAR) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                      |
| SW82332071-253   | 326m       | 400m     | CARRIAGEWAY            | Bituminous<br>surfacing<br>fretting (BFRT) | CAT 2              | 01/01/9999                  | Completed<br>Defects     | 13/11/2018         |                      |
| SW82332071-267   | 516m       | 600m     | CARRIAGEWAY            | Bituminous<br>surfacing<br>fretting (BFRT) | CAT 2              | 01/01/9999                  | Completed<br>Defects     | 13/11/2018         |                      |



| Defect Reference | Start m | End m  | Item Type          | Item Detail                                    | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|--------|--------------------|--|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82332071-268   | 528m    | 600m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-290   | 843m    | 900m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-291   | 852m    | 900m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-275   | 630m    | 675m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-303   | 1,026m  | 1,100m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-317   | 1,266m  | 1,325m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-318   | 1,295m  | 1,350m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-335   | 1,749m  | 1,850m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-336   | 1,768m  | 1,850m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-248   | 262m    | 350m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-255   | 354m    | 400m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-262   | 445m    | 455m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-266   | 501m    | 550m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-278   | 672m    | 750m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-285   | 775m    | 850m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-292   | 865m    | 900m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-296   | 923m    | 975m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-273   | 675m    | 0m     | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-305   | 1,057m  | 1,150m | SAFETY_FENCE       | Corroded - metal post (fence / barrier) (CMTP) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |

| Defect Reference | Start m | End m  | Item Type          | Item Detail                                    | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|--------|--------------------|--|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82332071-312   | 1,165m  | 1,200m | SAFETY_FENCE       | Corroded - metal post (fence / barrier) (CMTF) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-316   | 1,243m  | 1,300m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-323   | 1,450m  | 1,500m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-330   | 1,635m  | 1,700m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-251   | 300m    | 325m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-252   | 311m    | 350m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-269   | 543m    | 544m   | TRAFFIC_SIGNS      | Surface corrosion (SFCO)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-270   | 557m    | 625m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-288   | 815m    | 875m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-289   | 831m    | 90m    | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-276   | 646m    | 725m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-302   | 1,011m  | 1,100m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-319   | 1,327m  | 1,425m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-320   | 1,353m  | 1,425m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-333   | 1,716m  | 1,775m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-334   | 1,738m  | 1,800m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-241   | 135m    | 136m   | TRAFFIC_SIGNS      | Surface corrosion (SFCO)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-237   | 49m     | 50m    | TRAFFIC_SIGNS      | Surface corrosion (SFCO)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |

| Defect Reference | Start m | End m  | Item Type          | Item Detail                                    | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|--------|--------------------|--|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82332071-239   | 92m     | 150m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-263   | 459m    | 500m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-265   | 484m    | 550m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-277   | 658m    | 725m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-279   | 687m    | 725m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-272   | 588m    | 650m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-274   | 615m    | 675m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-304   | 1,042m  | 1,100m | SAFETY_FENCE       | Corroded - metal post (fence / barrier) (CMTP) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-306   | 1,072m  | 1,150m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-329   | 1,612m  | 1,613m | TRAFFIC_SIGNS      | Surface corrosion (SFCO)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-331   | 1,661m  | 1,700m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-235   | 15m     | 100m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-242   | 174m    | 275m   | FILTER_DRAIN       | Other (OTHR)                                   | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-244   | 223m    | 300m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-259   | 405m    | 450m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-261   | 431m    | 500m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |
| SW82332071-281   | 716m    | 800m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)              | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-283   | 741m    | 800m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)           | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |                      |

| Defect Reference  | Start m | End m  | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                       |
|---|---------|--------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|--|
| SW82332071-298  | 953m    | 1,000m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |  |
| SW82332071-300  | 981m    | 1,050m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-308  | 1,106m  | 1,150m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-310  | 1,139m  | 1,200m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |  |
| SW82332071-325  | 1,504m  | 1,505m | TRAFFIC_SIGNS      | Surface corrosion (SFCO)             | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332071-327  | 1,555m  | 1,600m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Completed Defects     | 13/11/2018      |  |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>    |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW80-390684-235944668   | 709m    | 710m   | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 06/09/2018               | Completed Defects     | 09/08/2018      | A77 SB CW 450M PRIOR TO CARLOCK HOUSE      |
| SW80-390684-235944670   | 596m    | 597m   | CARRIAGEWAY        | Pothole (POTH)                       | CAT 1           | 06/09/2018               | Completed Defects     | 09/08/2018      | A77 NB CW 345M CARLOCK HOUSE               |
| SW80-390684-235944667   | 790m    | 791m   | CARRIAGEWAY        | Pothole (POTH)                       | CAT 1           | 06/09/2018               | Completed Defects     | 09/08/2018      | A77 SB CW 500M PRIOR TO CARLOCK HOUSE      |
| SW80-390684-235944669   | 597m    | 598m   | CARRIAGEWAY        | Pothole (POTH)                       | CAT 1           | 06/09/2018               | Completed Defects     | 09/08/2018      | A77 SB CW 350M PRIOR TO CARLOCK HILL       |
| SW80-390684-235944671   | 591m    | 592m   | CARRIAGEWAY        | Pothole (POTH)                       | CAT 1           | 06/09/2018               | Completed Defects     | 09/08/2018      | A77 NB CW 340M CARLOCK HOUSE               |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>    |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>    |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>    |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW82407181-236053601  | 230m    | 231m   | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 14/09/2018               | Completed Defects     | 13/09/2018      | A77 S/B CW 100M PRIOR TO JCT CARLOCK HOUSE |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW82410364-236066535  | 380m    | 381m   | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 21/09/2018               | Completed Defects     | 20/09/2018      | A77 NB CW 300M NORTH OF JCT CARLOCK HOUSE  |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>   |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW82416981-236101748  | 865m    | 866m   | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 05/10/2018               | Completed Defects     | 04/10/2018      | A77 SB CW 200M PRIOR TO CARLOCK HILL       |
| SW82416981-236101749  | 868m    | 869m   | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 05/10/2018               | Completed Defects     | 04/10/2018      | A77 SB CW 205M PRIOR TO CARLOCK HILL       |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>   |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>   |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>   |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded   |         |        |                    |                                      |                 |                          |                       |                 |  |

| Defect Reference  | Start m | End m  | Item Type     | Item Detail            | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                                    |
|---|---------|--------|---------------|------------------------|-----------------|--------------------------|-------------------|-----------------|---|
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>                        |         |        |               |                        |                 |                          |                   |                 |   |
| SW82426212-236179760  | 1,793m  | 1,794m | CARRIAGEWAY   | Pothole VIAFIX (POTV)  | CAT 1           | 02/11/2018               | Completed Defects | 01/11/2018      | A77 SB CW 230M FROM AUCHENCROSH                         |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b><br>No defects recorded |         |        |               |                        |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b><br>No defects recorded |         |        |               |                        |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b><br>No defects recorded |         |        |               |                        |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b><br>No defects recorded |         |        |               |                        |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b><br>No defects recorded |         |        |               |                        |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b><br>No defects recorded |         |        |               |                        |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b><br>No defects recorded |         |        |               |                        |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b><br>No defects recorded |         |        |               |                        |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>                         |         |        |               |                        |                 |                          |                   |                 |   |
| SW82427890-236270546  | 702m    | 703m   | CARRIAGEWAY   | Pothole VIAFIX (POTV)  | CAT 1           | 31/01/2019               | Completed Defects | 03/01/2019      | A77 SB CW, 700M NTH OF CARLOCH HOUSE, STH OF BALLANTRAE |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>                         |         |        |               |                        |                 |                          |                   |                 |   |
| SW82428044-236270547  | 1,655m  | 1,656m | CARRIAGEWAY   | Pothole VIAFIX (POTV)  | CAT 1           | 11/01/2019               | Completed Defects | 10/01/2019      | A77 SB CW 1 MILE SOUTH OF AUCHENCROSH                   |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>                         |         |        |               |                        |                 |                          |                   |                 |   |
| SW82428228-236270551  | 969m    | 970m   | CARRIAGEWAY   | Pothole VIAFIX (POTV)  | CAT 1           | 18/01/2019               | Completed Defects | 17/01/2019      | A77 SB CW 800 YARDS NORTH OF CARLOCK HOUSE JCT          |
| SW82428228-236270552  | 950m    | 952m   | CARRIAGEWAY   | Pothole VIAFIX (POTV)  | CAT 1           | 18/01/2019               | Completed Defects | 17/01/2019      | A77 SB CW 805 YARDS NORTH OF CARLOCK HOUSE JCT          |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b><br>No defects recorded  |         |        |               |                        |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>                         |         |        |               |                        |                 |                          |                   |                 |   |
| SW82428625-236291428  | 838m    | 839m   | CARRIAGEWAY   | Pothole VIAFIX (POTV)  | CAT 1           | 01/02/2019               | Completed Defects | 31/01/2019      | A77 SB CW 500M NORTH OF CARLOCK HOUSE JCT               |
| SW82428625-236291427  | 420m    | 421m   | CARRIAGEWAY   | Pothole VIAFIX (POTV)  | CAT 1           | 01/02/2019               | Completed Defects | 31/01/2019      | A77 NB CW 200M NORTH OF CARLOCK HOUSE JCT               |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b><br>No defects recorded |         |        |               |                        |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b><br>No defects recorded |         |        |               |                        |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b><br>No defects recorded |         |        |               |                        |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b><br>No defects recorded |         |        |               |                        |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b><br>No defects recorded    |         |        |               |                        |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b><br>No defects recorded    |         |        |               |                        |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>                           |         |        |               |                        |                 |                          |                   |                 |   |
| SW82453127-236489175  | 152m    | 152m   | TRAFFIC_SIGNS | Accident damage (ACCD) | CAT 1           | 18/04/2019               | Completed Defects | 30/04/2019      | A77 N/B 200MTS PASS CARLOCK HOUSE                       |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b><br>No defects recorded    |         |        |               |                        |                 |                          |                   |                 |   |
| <b>11611/07 : SOUTH AYRSHIRE BOUNDARY TO HAGGSTONE CL SOUTH END</b>                     |         |        |               |                        |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b><br>No defects recorded  |         |        |               |                        |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>                         |         |        |               |                        |                 |                          |                   |                 |   |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                    |
|--|---------|--------|-------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>      |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>      |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b>     |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b>     |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b>     |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b>     |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>        |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>        |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>        |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>        |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>        |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>        |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>        |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| SW82338893-235633864   | 97m     | 97m    | CARRIAGEWAY | Pothole VIAFIX (POTV)                | CAT 1           | 20/04/2018               | Completed Defects     | 19/04/2018      | A77 N/B @ MARCHBURN COTTAGE ON BRIDGE   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>        |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>          |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>          |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |         |        |             |                                      |                 |                          |                       |                 |   |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| SW82380667-235914372   | 1,548m  | 1,549m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | A77 SB CW 600M PRIOR TO MARCHBURN LAYBY |
| SW82380667-235914371   | 1,554m  | 1,555m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | A77 NB CW 600M AFTEF MARCHBURN LAYBY    |
| No defects recorded  |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |         |        |             |                                      |                 |                          |                       |                 |   |

| Defect Reference | Start m | End m  | Item Type           | Item Detail                               | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|--------|---------------------|---|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82332071-5     | 289m    | 325m   | CARRIAGEWAY         | Miscellaneous surface Defects (MSRF)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-7     | 332m    | 375m   | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-22    | 719m    | 775m   | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-24    | 769m    | 800m   | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-39    | 1,102m  | 1,175m | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-41    | 1,145m  | 1,200m | FENCES_AND_BARRIERS | Corroded - metal (fence / barrier) (CMTF) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-56    | 1,505m  | 1,575m | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-58    | 1,556m  | 1,600m | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-14    | 493m    | 550m   | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-2     | 247m    | 300m   | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-18    | 624m    | 700m   | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-20    | 671m    | 750m   | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-43    | 1,195m  | 1,275m | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-45    | 1,241m  | 1,300m | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-52    | 1,411m  | 1,475m | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-54    | 1,460m  | 1,500m | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-4     | 266m    | 300m   | CARRIAGEWAY         | Miscellaneous surface Defects (MSRF)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-9     | 374m    | 425m   | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-31    | 924m    | 1,025m | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |

| Defect Reference | Start m | End m  | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|--------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82332071-32    | 945m    | 1,050m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-46    | 1,263m  | 1,300m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-49    | 1,339m  | 1,400m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-50    | 1,363m  | 1,400m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-12    | 441m    | 500m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-1     | 232m    | 275m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 17/08/2018               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-17    | 603m    | 675m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-28    | 861m    | 900m   | FILTER_DRAIN       | Weed growth (WEED)                   | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-35    | 1,017m  | 1,075m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-42    | 1,168m  | 1,225m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-53    | 1,435m  | 1,500m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-60    | 1,604m  | 1,675m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-15    | 510m    | 525m   | CARRIAGEWAY        | Missing (MISS)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-16    | 580m    | 650m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-30    | 904m    | 975m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-33    | 967m    | 1,075m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-47    | 1,294m  | 1,350m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-48    | 1,314m  | 1,400m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-10    | 393m    | 475m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |



| Defect Reference | Start<br>m | End<br>m | Item Type          | Item Detail                          | Defect<br>Category | Required<br>Completion Date | Current Status        | Completion<br>Date | Location Description |
|------------------|------------|----------|--------------------|--------------------------------------|--------------------|-----------------------------|-----------------------|--------------------|----------------------|
| SW82332071-3     | 249m       | 300m     | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332071-19    | 649m       | 750m     | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332071-26    | 813m       | 900m     | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332071-37    | 1,060m     | 1,125m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332071-44    | 1,218m     | 1,300m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332071-51    | 1,385m     | 1,425m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332071-62    | 1,654m     | 1,725m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332071-6     | 311m       | 350m     | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332071-8     | 353m       | 425m     | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332071-21    | 697m       | 775m     | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332071-23    | 745m       | 825m     | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332071-25    | 789m       | 850m     | FILTER_DRAIN       | Weed growth (WEED)                   | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332071-38    | 1,081m     | 1,150m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332071-40    | 1,122m     | 1,200m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332071-55    | 1,483m     | 1,550m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332071-57    | 1,531m     | 1,600m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332071-11    | 414m       | 475m     | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332071-13    | 475m       | 550m     | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |

| Defect Reference  | Start<br>m | End<br>m | Item Type          | Item Detail                                   | Defect<br>Category | Required<br>Completion Date | Current Status        | Completion<br>Date | Location Description   |
|---|------------|----------|--------------------|---|--------------------|-----------------------------|-----------------------|--------------------|--|
| SW82332071-27   | 838m       | 950m     | ROAD_MARKINGS_LONG | Wear (for example erosion)<br>(WEAR)          | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |  |
| SW82332071-29   | 882m       | 950m     | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)          | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |  |
| SW82332071-34   | 992m       | 1,075m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)          | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |  |
| SW82332071-36   | 1,037m     | 1,100m   | ROAD_MARKINGS_LONG | Wear (for example erosion)<br>(WEAR)          | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |  |
| SW82332071-59   | 1,578m     | 1,650m   | ROAD_MARKINGS_LONG | Wear (for example erosion)<br>(WEAR)          | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |  |
| SW82332071-61   | 1,624m     | 1,700m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT)          | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>      |            |          |                    |   |                    |                             |                       |                    |  |
| No defects recorded   |            |          |                    |   |                    |                             |                       |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>    |            |          |                    |   |                    |                             |                       |                    |  |
| No defects recorded   |            |          |                    |   |                    |                             |                       |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>    |            |          |                    |   |                    |                             |                       |                    |  |
| No defects recorded   |            |          |                    |   |                    |                             |                       |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>    |            |          |                    |   |                    |                             |                       |                    |  |
| SW80-394061-235954861   | 1,622m     | 1,623m   | CARRIAGEWAY        | Pothole VIAFIX (POTV)                         | CAT 1              | 17/08/2018                  | Completed Defects     | 16/08/2018         | A77 S/B C/W 750M SOUTH OF DRUMBRO KENNELS                        |
| SW80-394061-235954862   | 1,650m     | 1,730m   | CARRIAGEWAY        | Surface texture worn (SRTX)                   | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         | A77 600M NORTH OF MARCHBURN LAYBY NORTH OF CAIRNRYAN             |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>    |            |          |                    |   |                    |                             |                       |                    |  |
| No defects recorded   |            |          |                    |   |                    |                             |                       |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>    |            |          |                    |   |                    |                             |                       |                    |  |
| No defects recorded   |            |          |                    |   |                    |                             |                       |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b> |            |          |                    |   |                    |                             |                       |                    |  |
| SW80-403929-235984877   | 1,670m     | 1,671m   | CARRIAGEWAY        | Pothole VIAFIX (POTV)                         | CAT 1              | 07/09/2018                  | Completed Defects     | 06/09/2018         | A77 N/B C/W 1KM NORTH OF MARCHBURN LAYBY                         |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b> |            |          |                    |   |                    |                             |                       |                    |  |
| SW82407181-236053600  | 1,422m     | 1,423m   | CARRIAGEWAY        | Patch - loss of material (fretting)<br>(PLMT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         | A77 N/B C/W AT START HAGGINSTON CLIMBING LANE NORTH OF CAIRNRYAN |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b> |            |          |                    |   |                    |                             |                       |                    |  |
| No defects recorded   |            |          |                    |   |                    |                             |                       |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b> |            |          |                    |   |                    |                             |                       |                    |  |
| No defects recorded   |            |          |                    |   |                    |                             |                       |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>   |            |          |                    |   |                    |                             |                       |                    |  |
| No defects recorded   |            |          |                    |   |                    |                             |                       |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>   |            |          |                    |   |                    |                             |                       |                    |  |
| No defects recorded   |            |          |                    |   |                    |                             |                       |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>   |            |          |                    |   |                    |                             |                       |                    |  |
| No defects recorded   |            |          |                    |   |                    |                             |                       |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>   |            |          |                    |   |                    |                             |                       |                    |  |
| No defects recorded   |            |          |                    |   |                    |                             |                       |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>  |            |          |                    |   |                    |                             |                       |                    |  |
| No defects recorded   |            |          |                    |   |                    |                             |                       |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>  |            |          |                    |   |                    |                             |                       |                    |  |
| No defects recorded   |            |          |                    |   |                    |                             |                       |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>  |            |          |                    |   |                    |                             |                       |                    |  |
| No defects recorded   |            |          |                    |   |                    |                             |                       |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b>  |            |          |                    |   |                    |                             |                       |                    |  |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description   |
|--|---------|--------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|--|
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| SW82426917-236234294   | 207m    | 227m   | CARRIAGEWAY | Other (OTHR)          | 3RD PTY         | 27/12/2018               | Completed Defects | 07/05/2019      | A77 NB CW AT MARCHBURN LAYBY NORTH OF CAIRNRYAN                |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b> |         |        |             |                       |                 |                          |                   |                 |  |
| SW82427658-236270455   | 1,305m  | 1,306m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 28/12/2018               | Completed Defects | 27/12/2018      | A77 NB CW AT FINNARTS BAY JCT                                  |
| SW82427658-236270451   | 1,420m  | 1,422m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 28/12/2018               | Completed Defects | 27/12/2018      | A77 SB CW AT BOTTOM OF FINNARTS BAY HILL NORTH OF FINNARTS BAY |
| SW82427658-236270456   | 1,337m  | 1,338m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 28/12/2018               | Completed Defects | 27/12/2018      | A77 NB CW 10M NORTH OF FINNARTS BAY JCT                        |
| SW82427658-236270454   | 1,618m  | 1,619m | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 28/12/2018               | Completed Defects | 27/12/2018      | A77 SB CW AT BEND 50M NORTH OF FINNARTS BAY JCT                |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |        |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| SW82428228-236270553   | 1,435m  | 1,445m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 14/02/2019               | Completed Defects | 18/01/2019      | A77 NB CW 30M NORTH OF FINNARTS BAY                            |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>  |         |        |             |                       |                 |                          |                   |                 |  |
| SW82428351-236284308   | 1,455m  | 1,456m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 21/02/2019               | Completed Defects | 25/01/2019      | A77 NB CW, 208M NTH OF FINNARTS BAY, STH OF BALLANTRAE         |
| SW82428351-236284310   | 1,548m  | 1,549m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 21/02/2019               | Completed Defects | 25/01/2019      | A77 NB CW, 310M NTH OF FINNARTS BAY STH OF BALLANTRAE          |
| SW82428351-236284305   | 1,443m  | 1,444m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 21/02/2019               | Completed Defects | 25/01/2019      | A77 NB CW, 202M NTH OF FINNARTS BAY STH OF BALLANTRAE          |
| SW82428351-236284306   | 1,455m  | 1,456m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 21/02/2019               | Completed Defects | 25/01/2019      | A77 NB CW 204M NTH OF FINNARTS BAY STH OF BALLANTRAE           |
| SW82428351-236284312   | 1,590m  | 1,591m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 21/02/2019               | Completed Defects | 25/01/2019      | A77 410M NTH OF FINNARTS BAY STH OF BALLANTRAE                 |
| SW82428351-236284304   | 1,454m  | 1,455m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 21/02/2019               | Completed Defects | 25/01/2019      | A77 NB CW, 200M NTH OF FINARTS BAY, STH OF BALLANTRAE          |
| SW82428351-236284314   | 1,617m  | 1,618m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 21/02/2019               | Completed Defects | 25/01/2019      | A77 NB CW 440M NTH OF FINNARTS BAY, STH OF BALLANTRAE          |
| SW82428351-236284307   | 1,455m  | 1,456m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 21/02/2019               | Completed Defects | 25/01/2019      | A77 NB CW 206M NTH OF FINNARTS BAY STH OF BALLANTRAE           |
| SW82428351-236284309   | 1,542m  | 1,543m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 21/02/2019               | Completed Defects | 25/01/2019      | A77 NB CW, 300M NTH OF FINNARTS BAY, STH OF BALLANTRAE         |
| SW82428351-236284311   | 1,614m  | 1,615m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 21/02/2019               | Completed Defects | 25/01/2019      | A77 NB CW, 400M NTH OF FINNARTS BAY, STH OF BALLANTRAE         |
| SW82428351-236284313   | 1,598m  | 1,599m | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 21/02/2019               | Completed Defects | 25/01/2019      | A77 NB CW, 420M NTH OF FINNARTS BAY, STH OF BALLANTRAE         |



| Defect Reference   | Start<br>m | End<br>m | Item Type   | Item Detail              | Defect<br>Category | Required<br>Completion Date | Current Status       | Completion<br>Date | Location Description                          |
|--|------------|----------|-------------|--------------------------|--------------------|-----------------------------|----------------------|--------------------|---|
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>  |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b> |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b> |            |          |             |                          |                    |                             |                      |                    |   |
| SW82430228-236328523   | 363m       | 364m     | CARRIAGEWAY | Pothole<br>(POTH)        | CAT 1              | 14/03/2019                  | Completed<br>Defects | 01/03/2019         | A77 N/B MARCHBURN                             |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b> |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b> |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>    |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>    |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>    |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>    |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>11611/11 : HAGGSTONE CLIMBING LANE</b>                        |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>  |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>  |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>  |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>  |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b> |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b> |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b> |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b> |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>    |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>    |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>    |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>    |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>    |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>    |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>    |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>    |            |          |             |                          |                    |                             |                      |                    |   |
| SW82338893-235633865   | 904m       | 904m     | CARRIAGEWAY | Pothole VIAFIX<br>(POTV) | CAT 1              | 20/04/2018                  | Completed<br>Defects | 19/04/2018         | A77 N/B<br>HAGGSSTONECLIMBING<br>LANE N/S/W/T |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>    |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>      |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>      |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>      |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>      |            |          |             |                          |                    |                             |                      |                    |   |
| <i>No defects recorded</i>                                       |            |          |             |                          |                    |                             |                      |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>      |            |          |             |                          |                    |                             |                      |                    |   |

| Defect Reference   | Start m | End m  | Item Type           | Item Detail                               | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|--|---------|--------|---------------------|---|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| <i>No defects recorded</i>   |         |        |                     |   |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |         |        |                     |   |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |        |                     |   |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |         |        |                     |   |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |        |                     |   |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |         |        |                     |   |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |        |                     |   |                 |                          |                       |                 |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |         |        |                     |   |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |        |                     |   |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |         |        |                     |   |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |        |                     |   |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |         |        |                     |   |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |        |                     |   |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |         |        |                     |   |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |        |                     |   |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |         |        |                     |   |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |        |                     |   |                 |                          |                       |                 |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |         |        |                     |   |                 |                          |                       |                 |                      |
| SW82332071-68  | 136m    | 175m   | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-70  | 183m    | 225m   | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-93  | 928m    | 1,000m | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-72  | 244m    | 300m   | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-74  | 302m    | 402m   | FENCES_AND_BARRIERS | Corroded - metal (fence / barrier) (CMTF) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-89  | 783m    | 875m   | FENCES_AND_BARRIERS | Corroded - metal (fence / barrier) (CMTF) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-91  | 849m    | 950m   | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-69  | 157m    | 200m   | CARRIAGEWAY         | Missing (MISS)                            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-76  | 346m    | 450m   | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-87  | 711m    | 775m   | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-94  | 964m    | 1,025m | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-65  | 64m     | 125m   | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-66  | 87m     | 150m   | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-80  | 477m    | 550m   | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |

| Defect Reference | Start m | End m | Item Type           | Item Detail                               | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|-------|---------------------|---|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82332071-83    | 565m    | 625m  | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-67    | 111m    | 175m  | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-78    | 394m    | 400m  | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-85    | 635m    | 725m  | FENCES_AND_BARRIERS | Corroded - metal (fence / barrier) (CMTF) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-92    | 882m    | 950m  | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-63    | 6m      | 75m   | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-64    | 28m     | 100m  | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-81    | 510m    | 600m  | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-82    | 536m    | 625m  | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-95    | 684m    | 725m  | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-77    | 375m    | 475m  | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-79    | 431m    | 500m  | FENCES_AND_BARRIERS | Corroded - metal (fence / barrier) (CMTF) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-84    | 610m    | 700m  | FENCES_AND_BARRIERS | Corroded - metal (fence / barrier) (CMTF) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-86    | 678m    | 750m  | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-71    | 212m    | 300m  | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-73    | 275m    | 350m  | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-75    | 323m    | 425m  | FENCES_AND_BARRIERS | Corroded - metal (fence / barrier) (CMTF) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-88    | 741m    | 800m  | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-90    | 812m    | 900m  | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |

| Defect Reference  | Start<br>m | End<br>m | Item Type   | Item Detail              | Defect<br>Category | Required<br>Completion Date | Current Status       | Completion<br>Date | Location Description   |
|---|------------|----------|-------------|--------------------------|--------------------|-----------------------------|----------------------|--------------------|--|
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>      |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>    |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>    |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>    |            |          |             |                          |                    |                             |                      |                    |  |
| SW80-394061-235954860   | 359m       | 360m     | CARRIAGEWAY | Pothole VIAFIX<br>(POTV) | CAT 1              | 17/08/2018                  | Completed<br>Defects | 16/08/2018         | A77 S/B C/W 500M SOUTH OT<br>DRUMBRO KENELS                                |
| SW80-394061-235954859   | 364m       | 365m     | CARRIAGEWAY | Pothole VIAFIX<br>(POTV) | CAT 1              | 17/08/2018                  | Completed<br>Defects | 16/08/2018         | A77 S/B 500M SOUTH OF<br>DRUMBRO KENNELS                                   |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>    |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>    |            |          |             |                          |                    |                             |                      |                    |  |
| SW80-400497-235984888   | 209m       | 210m     | CARRIAGEWAY | Pothole VIAFIX<br>(POTV) | CAT 1              | 31/08/2018                  | Completed<br>Defects | 30/08/2018         | A77N/B IN LANE 2 900M<br>SOUTH OF DRUMBRO<br>KENNELS NORTH OF<br>CAIRNRYAN |
| SW80-400497-235984889   | 193m       | 194m     | CARRIAGEWAY | Pothole VIAFIX<br>(POTV) | CAT 1              | 31/08/2018                  | Completed<br>Defects | 30/08/2018         | A77 N/B 890M SOUTH OF<br>DRUMBRO KENNELS NORTH<br>OF CAIRNRYAN             |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b> |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b> |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b> |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b> |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>   |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>   |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>   |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>   |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>  |            |          |             |                          |                    |                             |                      |                    |  |
| SW82426212-236179757  | 280m       | 282m     | CARRIAGEWAY | Pothole VIAFIX<br>(POTV) | CAT 1              | 02/11/2018                  | Completed<br>Defects | 01/11/2018         | A77 NB CW CRAWLER LANE<br>NORTH OF MARCHBURN<br>LAYBY                      |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>  |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>  |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b>  |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b>  |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b>  |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b>  |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b>  |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b>  |            |          |             |                          |                    |                             |                      |                    |  |
| SW82427658-236270452  | 307m       | 308m     | CARRIAGEWAY | Pothole VIAFIX<br>(POTV) | CAT 1              | 28/12/2018                  | Completed<br>Defects | 27/12/2018         | A77 SB CW 450M NORTH OF<br>FINNARTS BAY                                    |
| SW82427658-236270453  | 310m       | 311m     | CARRIAGEWAY | Pothole VIAFIX<br>(POTV) | CAT 1              | 28/12/2018                  | Completed<br>Defects | 27/12/2018         | A77 SB CW 450M NORTH OF<br>FINNARTS BAY                                    |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>   |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>  |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>   |            |          |             |                          |                    |                             |                      |                    |  |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail              | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                                      |
|--|---------|--------|-------------|--------------------------|-----------------|--------------------------|-------------------|-----------------|---|
| <i>No defects recorded</i>                                       |         |        |             |                          |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>  |         |        |             |                          |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                          |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>  |         |        |             |                          |                 |                          |                   |                 |   |
| SW82428351-236284315   | 94m     | 95m    | VERGE       | Detritus / Refuse (DETR) | CAT 1           | 21/02/2019               | Completed Defects | 24/01/2019      | A77 NB VERGE, 500M NTH OF FINNARTS BAY, STH OF BALLANTRAE |
| SW82428351-236284316   | 104m    | 105m   | CARRIAGEWAY | Pothole (POTH)           | CAT 1           | 21/02/2019               | Completed Defects | 25/01/2019      | A77 500M NTH OF FINNARTS BAY STH OF BALLANTRAE            |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>  |         |        |             |                          |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                          |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b> |         |        |             |                          |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                          |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b> |         |        |             |                          |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                          |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b> |         |        |             |                          |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                          |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b> |         |        |             |                          |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                          |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>    |         |        |             |                          |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                          |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>    |         |        |             |                          |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                          |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>    |         |        |             |                          |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                          |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>    |         |        |             |                          |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                          |                 |                          |                   |                 |   |
| <b>11611/18 : HAGGSTONE CL NORTH END TO NORTH MARK BRIDGE</b>    |         |        |             |                          |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>  |         |        |             |                          |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                          |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>  |         |        |             |                          |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                          |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>  |         |        |             |                          |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                          |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>  |         |        |             |                          |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                          |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b> |         |        |             |                          |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                          |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b> |         |        |             |                          |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                          |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b> |         |        |             |                          |                 |                          |                   |                 |   |
| SW82319984-235544946   | 878m    | 879m   | CARRIAGEWAY | Pothole VIAFIX (POTV)    | CAT 1           | 15/03/2018               | Completed Defects | 15/02/2018      | A77 SB CW, 700M NTH OF DRUMBRO KENNELS                    |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b> |         |        |             |                          |                 |                          |                   |                 |   |
| SW82321955-235548236   | 690m    | 701m   | CARRIAGEWAY | Pothole (POTH)           | CAT 1           | 22/03/2018               | Completed Defects | 23/02/2018      | AT ENTRANCE TO NEW WIND FARM NORTH OF DUMBRO KENNELS      |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>    |         |        |             |                          |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |        |             |                          |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>    |         |        |             |                          |                 |                          |                   |                 |   |
| SW82326075-235554320   | 1,641m  | 1,841m | CARRIAGEWAY | Other (OTHR)             | CAT 2           | 01/01/9999               | Completed Defects | 30/03/2018      |   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>    |         |        |             |                          |                 |                          |                   |                 |   |
| SW82328086-235590007   | 350m    | 352m   | CARRIAGEWAY | Pothole (POTH)           | CAT 1           | 12/04/2018               | Completed Defects | 15/03/2018      | A77 SB CW, STH OF DRUMBRO KENNELS                         |
| SW82328086-235590006   | 588m    | 590m   | CARRIAGEWAY | Pothole (POTH)           | CAT 1           | 12/04/2018               | Completed Defects | 15/03/2018      | A77 SB CW, ON CL, DRUMBRO KENNELS                         |
| SW82328086-235590005   | 737m    | 737m   | CARRIAGEWAY | Pothole (POTH)           | CAT 1           | 12/04/2018               | Completed Defects | 15/03/2018      | A77 SB CW, DRUMBRO KENNELS                                |



| Defect Reference   | Start m | End m  | Item Type           | Item Detail                               | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                    |
|--|---------|--------|---------------------|---|-----------------|--------------------------|-----------------------|-----------------|---|
| SW82328086-235590004   | 478m    | 479m   | CARRIAGEWAY         | Pothole (POTH)                            | CAT 1           | 12/04/2018               | Completed Defects     | 15/03/2018      | A77 NB CW, OUTSIDE DRUMBRO KENNELS      |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>        |         |        |                     |   |                 |                          |                       |                 |   |
| No defects recorded  |         |        |                     |   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>        |         |        |                     |   |                 |                          |                       |                 |   |
| No defects recorded  |         |        |                     |   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>        |         |        |                     |   |                 |                          |                       |                 |   |
| SW82334882-235613707   | 616m    | 0m     | CARRIAGEWAY         | Pothole VIAFIX (POTV)                     | CAT 1           | 06/04/2018               | Completed Defects     | 05/04/2018      | A77 S/B AT DRUMBRO                      |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>        |         |        |                     |   |                 |                          |                       |                 |   |
| No defects recorded  |         |        |                     |   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>        |         |        |                     |   |                 |                          |                       |                 |   |
| SW82338893-235633866   | 372m    | 372m   | CARRIAGEWAY         | Pothole VIAFIX (POTV)                     | CAT 1           | 20/04/2018               | Completed Defects     | 19/04/2018      | M77 N/B HAGGSTONE CLIMBING LANE N/S/W/T |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>        |         |        |                     |   |                 |                          |                       |                 |   |
| No defects recorded  |         |        |                     |   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>          |         |        |                     |   |                 |                          |                       |                 |   |
| No defects recorded  |         |        |                     |   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>          |         |        |                     |   |                 |                          |                       |                 |   |
| No defects recorded  |         |        |                     |   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |         |        |                     |   |                 |                          |                       |                 |   |
| No defects recorded  |         |        |                     |   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |         |        |                     |   |                 |                          |                       |                 |   |
| No defects recorded  |         |        |                     |   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |         |        |                     |   |                 |                          |                       |                 |   |
| No defects recorded  |         |        |                     |   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |         |        |                     |   |                 |                          |                       |                 |   |
| No defects recorded  |         |        |                     |   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |         |        |                     |   |                 |                          |                       |                 |   |
| No defects recorded  |         |        |                     |   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |         |        |                     |   |                 |                          |                       |                 |   |
| No defects recorded  |         |        |                     |   |                 |                          |                       |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |         |        |                     |   |                 |                          |                       |                 |   |
| No defects recorded  |         |        |                     |   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |         |        |                     |   |                 |                          |                       |                 |   |
| No defects recorded  |         |        |                     |   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |         |        |                     |   |                 |                          |                       |                 |   |
| No defects recorded  |         |        |                     |   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |         |        |                     |   |                 |                          |                       |                 |   |
| No defects recorded  |         |        |                     |   |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |         |        |                     |   |                 |                          |                       |                 |   |
| No defects recorded  |         |        |                     |   |                 |                          |                       |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |         |        |                     |   |                 |                          |                       |                 |   |
| SW82332071-105   | 279m    | 375m   | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-107   | 331m    | 400m   | FENCES_AND_BARRIERS | Corroded - metal (fence / barrier) (CMTF) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-122   | 899m    | 1,000m | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-124   | 955m    | 1,055m | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332071-139   | 1,440m  | 1,500m | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |

| Defect Reference | Start m | End m  | Item Type           | Item Detail                               | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|--------|---------------------|---|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82332071-141   | 1,511m  | 1,600m | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-109   | 414m    | 500m   | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-111   | 498m    | 575m   | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-118   | 749m    | 825m   | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-120   | 824m    | 925m   | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-143   | 1,593m  | 1,675m | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-145   | 1,668m  | 1,725m | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-96    | 6m      | 75m    | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-113   | 576m    | 650m   | FENCES_AND_BARRIERS | Corroded - metal (fence / barrier) (CMTF) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-114   | 609m    | 700m   | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-131   | 1,183m  | 1,225m | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-132   | 1,216m  | 1,300m | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-149   | 1,803m  | 1,875m | FENCES_AND_BARRIERS | Corroded - metal (fence / barrier) (CMTF) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-150   | 1,834m  | 1,900m | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 27/08/2018               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-101   | 162m    | 250m   | FENCES_AND_BARRIERS | Corroded - metal (fence / barrier) (CMTF) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-99    | 98m     | 175m   | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-110   | 459m    | 500m   | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-117   | 825m    | 0m     | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |

| Defect Reference | Start m | End m  | Item Type           | Item Detail                               | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|--------|---------------------|---|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82332071-121   | 862m    | 950m   | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-128   | 1,089m  | 1,150m | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-135   | 1,300m  | 1,400m | FILTER_DRAIN        | Weed growth (WEED)                        | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-142   | 1,556m  | 1,625m | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-146   | 1,700m  | 1,775m | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-102   | 191m    | 250m   | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-103   | 225m    | 300m   | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-115   | 641m    | 750m   | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-116   | 696m    | 775m   | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-130   | 1,155m  | 1,250m | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-133   | 1,248m  | 1,300m | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-147   | 1,734m  | 1,825m | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-148   | 1,772m  | 1,825m | FENCES_AND_BARRIERS | Corroded - metal (fence / barrier) (CMTF) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-97    | 45m     | 100m   | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-112   | 540m    | 625m   | FENCES_AND_BARRIERS | Corroded - metal (fence / barrier) (CMTF) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-119   | 784m    | 850m   | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-126   | 1,021m  | 1,100m | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-137   | 1,368m  | 1,425m | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-144   | 1,627m  | 1,700m | FENCES_AND_BARRIERS | Corroded - metal (fence / barrier) (CMTF) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |

| Defect Reference | Start m | End m  | Item Type           | Item Detail                               | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|--------|---------------------|---|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82332071-106   | 306m    | 400m   | FENCES_AND_BARRIERS | Corroded - metal (fence / barrier) (CMTF) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-108   | 372m    | 425m   | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-123   | 931m    | 1,050m | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-125   | 988m    | 1,050m | FENCES_AND_BARRIERS | Corroded - metal (fence / barrier) (CMTF) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-138   | 1,405m  | 1,500m | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-140   | 1,469m  | 1,525m | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-100   | 128m    | 225m   | FENCES_AND_BARRIERS | Corroded - metal (fence / barrier) (CMTF) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-98    | 70m     | 150m   | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-104   | 250m    | 350m   | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-127   | 1,057m  | 1,150m | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-129   | 1,122m  | 1,225m | CARRIAGEWAY         | Bituminous surfacing fretting (BFRT)      | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-134   | 1,268m  | 1,325m | ROAD_MARKINGS_LONG  | Wear (for example erosion) (WEAR)         | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-136   | 1,333m  | 1,400m | FILTER_DRAIN        | Weed growth (WEED)                        | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |

**Safety Inspection of A77 Ayr South V1 on 26 July 2018**

No defects recorded

**Safety Inspection of A77 Ayr South V1 on 02 August 2018**

No defects recorded

**Safety Inspection of A77 Ayr South V1 on 09 August 2018**

No defects recorded

**Safety Inspection of A77 Ayr South V1 on 16 August 2018**

No defects recorded

**Safety Inspection of A77 Ayr South V1 on 23 August 2018**

No defects recorded

**Safety Inspection of A77 Ayr South V1 on 30 August 2018**

No defects recorded

**Safety Inspection of A77 Ayr South V1 on 06 September 2018**

No defects recorded

**Safety Inspection of A77 Ayr South V1 on 13 September 2018**

No defects recorded

**Safety Inspection of A77 Ayr South V1 on 20 September 2018**

No defects recorded

**Safety Inspection of A77 Ayr South V1 on 27 September 2018**

No defects recorded

**Safety Inspection of A77 Ayr South V1 on 04 October 2018**

No defects recorded

**Safety Inspection of A77 Ayr South V1 on 11 October 2018**

| Defect Reference   | Start m | End m | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                      |
|--|---------|-------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|---|
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>  |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>  |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b> |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b> |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b> |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b> |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b> |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b> |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b> |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b> |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b> |         |       |             |                       |                 |                          |                   |                 |   |
| SW82427658-236270449   | 312m    | 313m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 28/12/2018               | Completed Defects | 27/12/2018      | A77 SB CW AT TOP OF HILL AT FINNARTS BAY  |
| SW82427658-236270450   | 318m    | 319m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 28/12/2018               | Completed Defects | 27/12/2018      | A77 SB CW AT TOP OF HILL AT FINNARTS BAY  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>  |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>  |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>  |         |       |             |                       |                 |                          |                   |                 |   |
| SW82428228-236270554   | 72m     | 74m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 18/01/2019               | Completed Defects | 17/01/2019      | A77 NB CW 600 YARDS BEFORE DRUMBO KENNELS |
| SW82428228-236270555   | 110m    | 112m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 18/01/2019               | Completed Defects | 17/01/2019      | A77 NB CW 605 YARDS BEFORE DRUMBO KENNELS |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>  |         |       |             |                       |                 |                          |                   |                 |   |
| SW82428351-236284319   | 508m    | 509m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 21/02/2019               | Completed Defects | 24/01/2019      | A77 NB CW, OUTSIDE DRUMBRO KENNELS        |
| SW82428351-236284317   | 136m    | 137m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 21/02/2019               | Completed Defects | 25/01/2019      | A77 ON CL, 300M STH OF DRUMBRO KENNELS    |
| SW82428351-236284318   | 140m    | 141m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 21/02/2019               | Completed Defects | 25/01/2019      | A77 ON CL, 310M STH OF DRUMBRO KENNELS    |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>  |         |       |             |                       |                 |                          |                   |                 |   |
| SW82428625-236291426   | 382m    | 383m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 01/02/2019               | Completed Defects | 31/01/2019      | A77 NB CW 100M SOUTH OF DRUMBO KENNELS    |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |   |

| Defect Reference   | Start m | End m | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description  |
|--|---------|-------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|---|
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |   |
| <b>11612/06 : B7044 Jct to Start of climbing lane</b>            |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>  |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>  |         |       |             |                       |                 |                          |                   |                 |   |
| SW82317471-235518218   | 498m    | 499m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 08/02/2018               | Completed Defects | 08/02/2018      | A77 SB CW, 50M NTH OF BALLANTRAE MEDICAL PRACTICE, BALLANTRAE |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>  |         |       |             |                       |                 |                          |                   |                 |   |
| SW82317666-235521315   | 537m    | 540m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 15/02/2018               | Completed Defects | 08/02/2018      | A77 SB CW, OUTSIDE NO,16 MAIN ROAD BALLANTRAE                 |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>  |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b> |         |       |             |                       |                 |                          |                   |                 |   |
| SW82318129-235532269   | 742m    | 942m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 01/03/2018               | Completed Defects | 01/02/2018      | A77 BALLANTRAE  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b> |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b> |         |       |             |                       |                 |                          |                   |                 |   |
| SW82319984-235544951   | 400m    | 402m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 15/03/2018               | Completed Defects | 15/02/2018      | A77 SB CW, OPP SCOTMID, BALLANTRAE                            |
| SW82319984-235544950   | 468m    | 469m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 15/03/2018               | Completed Defects | 15/02/2018      | A77 SB CW, BALLANTRAE, OPP MEDICAL PRACTICE                   |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b> |         |       |             |                       |                 |                          |                   |                 |   |
| SW82321955-235548235   | 731m    | 732m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 22/03/2018               | Completed Defects | 22/02/2018      | POTHOLE LARGE   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>    |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>    |         |       |             |                       |                 |                          |                   |                 |   |
| SW82326075-235554309   | 500m    | 501m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 05/04/2018               | Completed Defects | 08/03/2018      | A77 SB CW, JCT SHORE ROAD, BALLANTRAE                         |
| SW82326075-235554310   | 390m    | 394m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 05/04/2018               | Completed Defects | 08/03/2018      | A77 NB CW, OUTSIDE SCOTMID, BALLANTRAE                        |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>    |         |       |             |                       |                 |                          |                   |                 |   |
| SW82328086-235590022   | 598m    | 600m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 12/04/2018               | Completed Defects | 15/03/2018      | A77 BOTH CW, OUTSIDE GARDEN CENTER BALLANTRAE                 |
| SW82328086-235590023   | 540m    | 545m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 12/04/2018               | Completed Defects | 15/03/2018      | A77 SB CW, OPP SHORE ROAD BALLANTRAE                          |
| SW82328086-235590024   | 467m    | 470m  | CARRIAGEWAY | Pothole (POTH)        | CAT 1           | 12/04/2018               | Completed Defects | 15/03/2018      | A77 SB CW, OUTSIDE MEDICAL PRACTICE BALLANTRAE                |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>    |         |       |             |                       |                 |                          |                   |                 |   |
| SW82330474-235608104   | 571m    | 572m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 19/04/2018               | Completed Defects | 22/03/2018      | A77 NB CW, 90M STH OF GARDEN CENTER, BALLANTRAE               |
| SW82330474-235608102   | 468m    | 469m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 19/04/2018               | Completed Defects | 22/03/2018      | A77 ON CL, BALLANTRAE, OUTSIDE MEDICAL PRACTICE               |
| SW82330474-235608103   | 604m    | 605m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 19/04/2018               | Completed Defects | 22/03/2018      | A77 NB CW, 100M STH OF GARDEN CENTER BALLANTRAE               |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>    |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>    |         |       |             |                       |                 |                          |                   |                 |   |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>    |         |       |             |                       |                 |                          |                   |                 |   |

| Defect Reference   | Start m | End m  | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                               |
|--|---------|--------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|--|
| SW82336916-235633865   | 764m    | 765m   | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 10/05/2018               | Completed Defects     | 12/04/2018      | A77 SB CW, BALLANTRAE NTH GATEWAY                  |
| SW82336916-235633866   | 754m    | 755m   | CARRIAGEWAY        | Pothole VIAFIX (POTV)                | CAT 1           | 10/05/2018               | Completed Defects     | 12/04/2018      | A77 SB CW, OPPOSITE GARDEN CENTER, BALLANTRAE      |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>        |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>        |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>          |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>          |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW82383889-235917505   | 777m    | 778m   | TRAFFIC_SIGNS      | Pointing wrong way (RWAY)            | CAT 1           | 23/08/2018               | Completed Defects     | 26/07/2018      | A77 CENTRAL ISLAND 200M AFTER BALLENTY STH GATEWAY |
| SW82383889-235917507   | 338m    | 339m   | FOOTWAY            | Other (OTHR)                         | CAT 1           | 23/08/2018               | Completed Defects     | 23/08/2018      | A77 SB CW OUTSIDE SHELLKNOWE GARAGE BALLENTY       |
| SW82383889-235917506   | 40m     | 41m    | TRAFFIC_SIGNS      | Pointing wrong way (RWAY)            | CAT 1           | 23/08/2018               | Completed Defects     | 26/07/2018      | A77 CENTER ISLAND 50M PRIOR TO RIVER STINCHAR      |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |         |        |                    |                                      |                 |                          |                       |                 |  |
| No defects recorded  |         |        |                    |                                      |                 |                          |                       |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW80-397303-235954865  | 32m     | 32m    | TRAFFIC_SIGNS      | Damaged (DAMG)                       | CAT 1           | 20/09/2018               | Completed Defects     | 20/09/2018      | A77 TRAFFIC ISLAND BALLANTRAE SOUTH GATEWAY        |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |         |        |                    |                                      |                 |                          |                       |                 |  |
| SW82332071-405   | 592m    | 672m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Completed Defects     | 07/12/2018      |  |
| SW82332071-392   | 151m    | 251m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Completed Defects     | 07/12/2018      |  |
| SW82332071-412   | 1,481m  | 1,681m | FILTER_DRAIN       | Weed growth (WEED)                   | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |

| Defect Reference | Start m | End m  | Item Type          | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|--------|--------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82332071-407   | 833m    | 845m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-409   | 1,060m  | 1,140m | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-396   | 270m    | 370m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Completed Defects     | 07/12/2018      |                      |
| SW82332071-403   | 587m    | 687m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Completed Defects     | 07/12/2018      |                      |
| SW82332071-399   | 369m    | 450m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Completed Defects     | 07/12/2018      |                      |
| SW82332071-400   | 457m    | 527m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Completed Defects     | 07/12/2018      |                      |
| SW82332071-394   | 142m    | 222m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Completed Defects     | 07/12/2018      |                      |
| SW82332071-410   | 1,142m  | 1,241m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-397   | 385m    | 485m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Completed Defects     | 07/12/2018      |                      |
| SW82332071-398   | 370m    | 450m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Completed Defects     | 07/12/2018      |                      |
| SW82332071-401   | 453m    | 523m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Completed Defects     | 07/12/2018      |                      |
| SW82332071-393   | 139m    | 219m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-395   | 321m    | 401m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Completed Defects     | 07/12/2018      |                      |
| SW82332071-402   | 492m    | 592m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Completed Defects     | 07/12/2018      |                      |
| SW82332071-404   | 553m    | 653m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Completed Defects     | 07/12/2018      |                      |
| SW82332071-408   | 850m    | 851m   | CARRIAGEWAY        | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332071-391   | 43m     | 143m   | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Completed Defects     | 07/12/2018      |                      |
| SW82332071-411   | 1,236m  | 1,336m | ROAD_MARKINGS_LONG | Wear (for example erosion) (WEAR)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |

Safety Inspection of A77 Ayr South V1 on 30 August 2018

No defects recorded

Safety Inspection of A77 Ayr South V1 on 06 September 2018



| Defect Reference  | Start<br>m | End<br>m | Item Type     | Item Detail               | Defect<br>Category | Required<br>Completion Date | Current Status    | Completion<br>Date | Location Description  |
|---|------------|----------|---------------|---------------------------|--------------------|-----------------------------|-------------------|--------------------|---|
| <i>No defects recorded</i>  |            |          |               |                           |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b> |            |          |               |                           |                    |                             |                   |                    |   |
| SW82407181-236053602  | 803m       | 804m     | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1              | 14/09/2018                  | Completed Defects | 13/09/2018         | A77 S/B CW AT TRAFFIC ISLAND OUTSIDE GARDEN CENTRE BALLANTRAE |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b> |            |          |               |                           |                    |                             |                   |                    |   |
| SW82410364-236066538  | 781m       | 782m     | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1              | 21/09/2018                  | Completed Defects | 20/09/2018         | A77 SB CW OPPOSITE GARDEN CENTRE BALLANTRAE                   |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b> |            |          |               |                           |                    |                             |                   |                    |   |
| SW80-413634-236087129   | 600m       | 601m     | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1              | 28/09/2018                  | Completed Defects | 27/09/2018         | A77 SB CW OPPOSITE BRICC HOUSE BALLANTRAE                     |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>   |            |          |               |                           |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |               |                           |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>   |            |          |               |                           |                    |                             |                   |                    |   |
| SW82420227-236118418  | 862m       | 863m     | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1              | 12/10/2018                  | Completed Defects | 11/10/2018         | A77 NB CW 100M BEFORE NORTH GATEWAY BALLANTRAE                |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>   |            |          |               |                           |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |               |                           |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>   |            |          |               |                           |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |               |                           |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>  |            |          |               |                           |                    |                             |                   |                    |   |
| SW82426212-236179763  | 1,741m     | 1,742m   | TRAFFIC_SIGNS | Other (OTHR)              | CAT 1              | 29/11/2018                  | Completed Defects | 22/11/2018         | A77 NB CW OPPOSITE BALIG FARM JCT                             |
| SW82426212-236179762  | 1,245m     | 1,246m   | TRAFFIC_SIGNS | Pointing wrong way (RWAY) | CAT 1              | 02/11/2018                  | Completed Defects | 01/11/2018         | A77 NB CW 200M NORTH OF BALLANTRAE                            |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>  |            |          |               |                           |                    |                             |                   |                    |   |
| SW82426441-236211987  | 1,223m     | 1,223m   | TRAFFIC_SIGNS | Pointing wrong way (RWAY) | CAT 1              | 09/11/2018                  | Completed Defects | 08/11/2018         | A78 NB CW 50M NORTH OF BALLANTRAE                             |
| SW82426441-236211986  | 762m       | 763m     | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1              | 09/11/2018                  | Completed Defects | 08/11/2018         | A77 SB CW OUTSIDE GARDEN CENTRE BALLANTRAE                    |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>  |            |          |               |                           |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |               |                           |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b>  |            |          |               |                           |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |               |                           |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b>  |            |          |               |                           |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |               |                           |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b>  |            |          |               |                           |                    |                             |                   |                    |   |
| SW80-427220-236234309   | 748m       | 749m     | TRAFFIC_SIGNS | Pointing wrong way (RWAY) | CAT 1              | 07/12/2018                  | Completed Defects | 06/12/2018         | A77 OUTSIDE GARDEN CENTRE BALLANTRAE                          |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b>  |            |          |               |                           |                    |                             |                   |                    |   |
| SW82427366-236262605  | 778m       | 779m     | CARRIAGEWAY   | Pothole (POTH)            | CAT 1              | 10/01/2019                  | Completed Defects | 13/12/2018         | A77 NB CW, BALLANTRAE NTH GATEWAY, OUTSIDE GARDEN CENTER      |
| SW82427366-236262604  | 767m       | 768m     | CARRIAGEWAY   | Pothole VIAFIX (POTV)     | CAT 1              | 10/01/2019                  | Completed Defects | 13/12/2018         | A77 SB CW, BALLANTRAE NTH GATEWAY, OUTSIDE GARDEN CENTRE      |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b>  |            |          |               |                           |                    |                             |                   |                    |   |
| SW82427527-236264602  | 1,219m     | 1,220m   | TRAFFIC_SIGNS | Pointing wrong way (RWAY) | CAT 1              | 21/12/2018                  | Completed Defects | 20/12/2018         | A77 NB CW 220M NORTH OF BALLANTRAE                            |
| SW82427527-236264600  | 748m       | 749m     | CARRIAGEWAY   | Pothole (POTH)            | CAT 1              | 17/01/2019                  | Completed Defects | 12/01/2019         | A77 SB CW OPPOSITE GARDEN CENTRE ENTRANCE BALLANTRAE          |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b>  |            |          |               |                           |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |               |                           |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>   |            |          |               |                           |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |               |                           |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>   |            |          |               |                           |                    |                             |                   |                    |   |
| <i>No defects recorded</i>  |            |          |               |                           |                    |                             |                   |                    |   |

| Defect Reference   | Start m | End m | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                           |
|--|---------|-------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|--|
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| SW82428625-236291425   | 394m    | 395m  | GULLY       | Blockage (BLOK)       | CAT 1           | 28/02/2019               | Completed Defects | 31/01/2019      | A77 NB CW OUTSIDE SCOTMID BALLANTRAE           |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b> |         |       |             |                       |                 |                          |                   |                 |  |
| SW82436659-236335203   | 779m    | 780m  | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 01/03/2019               | Completed Defects | 28/02/2019      | A77 S/B BALLANTRAE OPPCRAIGMAINS GARDEN CENTRE |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>11612/66 : Start to End of NB climbing lane</b>               |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>  |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b> |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b> |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b> |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b> |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>    |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>      |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>      |         |       |             |                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>                                       |         |       |             |                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>      |         |       |             |                       |                 |                          |                   |                 |  |

| Defect Reference   | Start<br>m | End<br>m | Item Type     | Item Detail    | Defect<br>Category | Required<br>Completion Date | Current Status    | Completion<br>Date | Location Description  |
|--|------------|----------|---------------|----------------|--------------------|-----------------------------|-------------------|--------------------|---|
| <i>No defects recorded</i>   |            |          |               |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |            |          |               |                |                    |                             |                   |                    |   |
| <i>No defects recorded</i>   |            |          |               |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |            |          |               |                |                    |                             |                   |                    |   |
| <i>No defects recorded</i>   |            |          |               |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |            |          |               |                |                    |                             |                   |                    |   |
| <i>No defects recorded</i>   |            |          |               |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |            |          |               |                |                    |                             |                   |                    |   |
| <i>No defects recorded</i>   |            |          |               |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |            |          |               |                |                    |                             |                   |                    |   |
| <i>No defects recorded</i>   |            |          |               |                |                    |                             |                   |                    |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |            |          |               |                |                    |                             |                   |                    |   |
| <i>No defects recorded</i>   |            |          |               |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |            |          |               |                |                    |                             |                   |                    |   |
| <i>No defects recorded</i>   |            |          |               |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |            |          |               |                |                    |                             |                   |                    |   |
| <i>No defects recorded</i>   |            |          |               |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |            |          |               |                |                    |                             |                   |                    |   |
| <i>No defects recorded</i>   |            |          |               |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |            |          |               |                |                    |                             |                   |                    |   |
| <i>No defects recorded</i>   |            |          |               |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |            |          |               |                |                    |                             |                   |                    |   |
| <i>No defects recorded</i>   |            |          |               |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |            |          |               |                |                    |                             |                   |                    |   |
| <i>No defects recorded</i>   |            |          |               |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |            |          |               |                |                    |                             |                   |                    |   |
| <i>No defects recorded</i>   |            |          |               |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |            |          |               |                |                    |                             |                   |                    |   |
| <i>No defects recorded</i>   |            |          |               |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |            |          |               |                |                    |                             |                   |                    |   |
| <i>No defects recorded</i>   |            |          |               |                |                    |                             |                   |                    |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |            |          |               |                |                    |                             |                   |                    |   |
| <i>No defects recorded</i>   |            |          |               |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>       |            |          |               |                |                    |                             |                   |                    |   |
| <i>No defects recorded</i>   |            |          |               |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b>    |            |          |               |                |                    |                             |                   |                    |   |
| <i>No defects recorded</i>   |            |          |               |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b>    |            |          |               |                |                    |                             |                   |                    |   |
| <i>No defects recorded</i>   |            |          |               |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b>    |            |          |               |                |                    |                             |                   |                    |   |
| <i>No defects recorded</i>   |            |          |               |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b>    |            |          |               |                |                    |                             |                   |                    |   |
| <i>No defects recorded</i>   |            |          |               |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>      |            |          |               |                |                    |                             |                   |                    |   |
| <i>No defects recorded</i>   |            |          |               |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>      |            |          |               |                |                    |                             |                   |                    |   |
| <i>No defects recorded</i>   |            |          |               |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>      |            |          |               |                |                    |                             |                   |                    |   |
| <i>No defects recorded</i>   |            |          |               |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>      |            |          |               |                |                    |                             |                   |                    |   |
| <i>No defects recorded</i>   |            |          |               |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>     |            |          |               |                |                    |                             |                   |                    |   |
| SW82426212-236179764   | 181m       | 182m     | TRAFFIC_SIGNS | Damaged (DAMG) | CAT 1              | 29/11/2018                  | Completed Defects | 19/12/2018         | A77 SB CW AT 300 YARDS TO<br>END OF CRAWLER LANE<br>SIGN NORTH OF<br>BALLANTRAE |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>     |            |          |               |                |                    |                             |                   |                    |   |
| <i>No defects recorded</i>   |            |          |               |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>     |            |          |               |                |                    |                             |                   |                    |   |
| <i>No defects recorded</i>   |            |          |               |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b>     |            |          |               |                |                    |                             |                   |                    |   |
| <i>No defects recorded</i>   |            |          |               |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b>     |            |          |               |                |                    |                             |                   |                    |   |
| <i>No defects recorded</i>   |            |          |               |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b>     |            |          |               |                |                    |                             |                   |                    |   |
| <i>No defects recorded</i>   |            |          |               |                |                    |                             |                   |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b>     |            |          |               |                |                    |                             |                   |                    |   |

| Defect Reference | Start<br>m | End<br>m | Item Type | Item Detail | Defect<br>Category | Required<br>Completion Date | Current Status | Completion<br>Date | Location Description |
|------------------|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|
|------------------|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|

*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 20 December 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 27 December 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 03 January 2019**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 10 January 2019**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 17 January 2019**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 24 January 2019**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 31 January 2019**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 07 February 2019**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 14 February 2019**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 21 February 2019**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 28 February 2019**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 07 March 2019**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 14 March 2019**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 21 March 2019**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 28 March 2019**  
*No defects recorded*

**11612/80 : End of NB climbing lane to B734 Jct**  
**Safety Inspection of A77 Ayr South V1 on 04 January 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 11 January 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 18 January 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 25 January 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 01 February 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 08 February 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 15 February 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 22 February 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 01 March 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 08 March 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 15 March 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 22 March 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 29 March 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 05 April 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 12 April 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 19 April 2018**  
*No defects recorded*  
**Safety Inspection of A77 Ayr South V1 on 26 April 2018**  
*No defects recorded*

| Defect Reference   | Start m | End m | Item Type              | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                      |
|--|---------|-------|------------------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>          |         |       |                        |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                        |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>          |         |       |                        |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                        |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |         |       |                        |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                        |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |         |       |                        |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                        |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |         |       |                        |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                        |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |         |       |                        |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                        |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |         |       |                        |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                        |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |         |       |                        |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                        |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |         |       |                        |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                        |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |         |       |                        |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                        |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |         |       |                        |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                        |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |         |       |                        |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                        |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |         |       |                        |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                        |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |         |       |                        |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                        |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |         |       |                        |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                        |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |         |       |                        |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                        |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |         |       |                        |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                        |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |         |       |                        |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                        |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |         |       |                        |                                      |                 |                          |                       |                 |   |
| SW82332071-413   | 268m    | 368m  | ROAD_MARKINGS<br>_LONG | Wear (for example erosion)<br>(WEAR) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>       |         |       |                        |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                        |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b>    |         |       |                        |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                        |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b>    |         |       |                        |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                        |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b>    |         |       |                        |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                        |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b>    |         |       |                        |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                        |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>      |         |       |                        |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                        |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>      |         |       |                        |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                        |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>      |         |       |                        |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                        |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>      |         |       |                        |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                        |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>     |         |       |                        |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                        |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>     |         |       |                        |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |       |                        |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>     |         |       |                        |                                      |                 |                          |                       |                 |   |
| SW82426587-236223179   | 378m    | 378m  | Culvert                | Free flow impeded<br>(FRFL)          | CAT 1           | 13/12/2018               | Completed Defects     | 15/11/2018      | A77 SB CW AT B734 JCT NORTH OF BALLANTRAE |

| Defect Reference | Start<br>m | End<br>m | Item Type | Item Detail | Defect<br>Category | Required<br>Completion Date | Current Status | Completion<br>Date | Location Description |
|------------------|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|
|------------------|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|

**Safety Inspection of A77 Ayr South V1 on 22 November 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 29 November 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 06 December 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 13 December 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 20 December 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 27 December 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 03 January 2019**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 10 January 2019**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 17 January 2019**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 24 January 2019**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 31 January 2019**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 07 February 2019**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 14 February 2019**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 21 February 2019**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 28 February 2019**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 07 March 2019**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 14 March 2019**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 21 March 2019**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 28 March 2019**  
No defects recorded

**11614/05 : B734 Jct to end of SB climbing lane**

**Safety Inspection of A77 Ayr South V1 on 04 January 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 11 January 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 18 January 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 25 January 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 01 February 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 08 February 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 15 February 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 22 February 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 01 March 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 08 March 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 15 March 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 22 March 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 29 March 2018**  
No defects recorded

**Safety Inspection of A77 Ayr South V1 on 05 April 2018**

| Defect Reference   | Start<br>m | End<br>m | Item Type              | Item Detail                                | Defect<br>Category | Required<br>Completion Date | Current Status           | Completion<br>Date | Location Description                     |
|--|------------|----------|------------------------|--|--------------------|-----------------------------|--------------------------|--------------------|--|
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>        |            |          |                        |  |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>        |            |          |                        |  |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>        |            |          |                        |  |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>          |            |          |                        |  |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>          |            |          |                        |  |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |            |          |                        |  |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |            |          |                        |  |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |            |          |                        |  |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |            |          |                        |  |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |            |          |                        |  |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |            |          |                        |  |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |            |          |                        |  |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |            |          |                        |  |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |            |          |                        |  |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |            |          |                        |  |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |            |          |                        |  |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |            |          |                        |  |                    |                             |                          |                    |  |
| SW82383889-235917504   | 224m       | 324m     | ROAD_MARKINGS<br>_LONG | Wear (for<br>example<br>erosion)<br>(WEAR) | CAT 1              | 23/08/2018                  | Completed<br>Defects     | 17/10/2018         | A77 SB CW 200M PRIOR TO<br>COLMONELL JCT |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |            |          |                        |  |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |            |          |                        |  |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |            |          |                        |  |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |            |          |                        |  |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |            |          |                        |  |                    |                             |                          |                    |  |
| SW82332071-406   | 0m         | 335m     | ROAD_MARKINGS<br>_LONG | Wear (for<br>example<br>erosion)<br>(WEAR) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |  |
| SW82332071-414   | 174m       | 274m     | ROAD_MARKINGS<br>_LONG | Wear (for<br>example<br>erosion)<br>(WEAR) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |  |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>       |            |          |                        |  |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b>    |            |          |                        |  |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b>    |            |          |                        |  |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b>    |            |          |                        |  |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b>    |            |          |                        |  |                    |                             |                          |                    |  |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>      |            |          |                        |  |                    |                             |                          |                    |  |

| Defect Reference  | Start m | End m | Item Type     | Item Detail               | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description              |
|---|---------|-------|---------------|---------------------------|-----------------|--------------------------|-------------------|-----------------|-----------------------------------|
| No defects recorded                                       |         |       |               |                           |                 |                          |                   |                 |                                   |
| Safety Inspection of A77 Ayr South V1 on 11 October 2018  |         |       |               |                           |                 |                          |                   |                 |                                   |
| No defects recorded                                       |         |       |               |                           |                 |                          |                   |                 |                                   |
| Safety Inspection of A77 Ayr South V1 on 18 October 2018  |         |       |               |                           |                 |                          |                   |                 |                                   |
| No defects recorded                                       |         |       |               |                           |                 |                          |                   |                 |                                   |
| Safety Inspection of A77 Ayr South V1 on 25 October 2018  |         |       |               |                           |                 |                          |                   |                 |                                   |
| No defects recorded                                       |         |       |               |                           |                 |                          |                   |                 |                                   |
| Safety Inspection of A77 Ayr South V1 on 01 November 2018 |         |       |               |                           |                 |                          |                   |                 |                                   |
| No defects recorded                                       |         |       |               |                           |                 |                          |                   |                 |                                   |
| Safety Inspection of A77 Ayr South V1 on 08 November 2018 |         |       |               |                           |                 |                          |                   |                 |                                   |
| No defects recorded                                       |         |       |               |                           |                 |                          |                   |                 |                                   |
| Safety Inspection of A77 Ayr South V1 on 15 November 2018 |         |       |               |                           |                 |                          |                   |                 |                                   |
| No defects recorded                                       |         |       |               |                           |                 |                          |                   |                 |                                   |
| Safety Inspection of A77 Ayr South V1 on 22 November 2018 |         |       |               |                           |                 |                          |                   |                 |                                   |
| No defects recorded                                       |         |       |               |                           |                 |                          |                   |                 |                                   |
| Safety Inspection of A77 Ayr South V1 on 29 November 2018 |         |       |               |                           |                 |                          |                   |                 |                                   |
| No defects recorded                                       |         |       |               |                           |                 |                          |                   |                 |                                   |
| Safety Inspection of A77 Ayr South V1 on 06 December 2018 |         |       |               |                           |                 |                          |                   |                 |                                   |
| No defects recorded                                       |         |       |               |                           |                 |                          |                   |                 |                                   |
| Safety Inspection of A77 Ayr South V1 on 13 December 2018 |         |       |               |                           |                 |                          |                   |                 |                                   |
| No defects recorded                                       |         |       |               |                           |                 |                          |                   |                 |                                   |
| SW82427527-236264603                                      | 242m    | 243m  | TRAFFIC_SIGNS | Pointing wrong way (RWAY) | CAT 1           | 21/12/2018               | Completed Defects | 20/12/2018      | A77 SB CW 200M AFTER BENNANE HILL |
| Safety Inspection of A77 Ayr South V1 on 27 December 2018 |         |       |               |                           |                 |                          |                   |                 |                                   |
| No defects recorded                                       |         |       |               |                           |                 |                          |                   |                 |                                   |
| Safety Inspection of A77 Ayr South V1 on 03 January 2019  |         |       |               |                           |                 |                          |                   |                 |                                   |
| No defects recorded                                       |         |       |               |                           |                 |                          |                   |                 |                                   |
| Safety Inspection of A77 Ayr South V1 on 10 January 2019  |         |       |               |                           |                 |                          |                   |                 |                                   |
| No defects recorded                                       |         |       |               |                           |                 |                          |                   |                 |                                   |
| Safety Inspection of A77 Ayr South V1 on 17 January 2019  |         |       |               |                           |                 |                          |                   |                 |                                   |
| No defects recorded                                       |         |       |               |                           |                 |                          |                   |                 |                                   |
| Safety Inspection of A77 Ayr South V1 on 24 January 2019  |         |       |               |                           |                 |                          |                   |                 |                                   |
| No defects recorded                                       |         |       |               |                           |                 |                          |                   |                 |                                   |
| Safety Inspection of A77 Ayr South V1 on 31 January 2019  |         |       |               |                           |                 |                          |                   |                 |                                   |
| No defects recorded                                       |         |       |               |                           |                 |                          |                   |                 |                                   |
| Safety Inspection of A77 Ayr South V1 on 07 February 2019 |         |       |               |                           |                 |                          |                   |                 |                                   |
| No defects recorded                                       |         |       |               |                           |                 |                          |                   |                 |                                   |
| Safety Inspection of A77 Ayr South V1 on 14 February 2019 |         |       |               |                           |                 |                          |                   |                 |                                   |
| No defects recorded                                       |         |       |               |                           |                 |                          |                   |                 |                                   |
| Safety Inspection of A77 Ayr South V1 on 21 February 2019 |         |       |               |                           |                 |                          |                   |                 |                                   |
| No defects recorded                                       |         |       |               |                           |                 |                          |                   |                 |                                   |
| Safety Inspection of A77 Ayr South V1 on 28 February 2019 |         |       |               |                           |                 |                          |                   |                 |                                   |
| No defects recorded                                       |         |       |               |                           |                 |                          |                   |                 |                                   |
| Safety Inspection of A77 Ayr South V1 on 07 March 2019    |         |       |               |                           |                 |                          |                   |                 |                                   |
| No defects recorded                                       |         |       |               |                           |                 |                          |                   |                 |                                   |
| Safety Inspection of A77 Ayr South V1 on 14 March 2019    |         |       |               |                           |                 |                          |                   |                 |                                   |
| No defects recorded                                       |         |       |               |                           |                 |                          |                   |                 |                                   |
| Safety Inspection of A77 Ayr South V1 on 21 March 2019    |         |       |               |                           |                 |                          |                   |                 |                                   |
| No defects recorded                                       |         |       |               |                           |                 |                          |                   |                 |                                   |
| Safety Inspection of A77 Ayr South V1 on 28 March 2019    |         |       |               |                           |                 |                          |                   |                 |                                   |
| No defects recorded                                       |         |       |               |                           |                 |                          |                   |                 |                                   |
| <b>11614/08 : End of SB climbing lane to Bennane Jct</b>  |         |       |               |                           |                 |                          |                   |                 |                                   |
| Safety Inspection of A77 Ayr South V1 on 04 January 2018  |         |       |               |                           |                 |                          |                   |                 |                                   |
| No defects recorded                                       |         |       |               |                           |                 |                          |                   |                 |                                   |
| Safety Inspection of A77 Ayr South V1 on 11 January 2018  |         |       |               |                           |                 |                          |                   |                 |                                   |
| No defects recorded                                       |         |       |               |                           |                 |                          |                   |                 |                                   |
| Safety Inspection of A77 Ayr South V1 on 18 January 2018  |         |       |               |                           |                 |                          |                   |                 |                                   |
| No defects recorded                                       |         |       |               |                           |                 |                          |                   |                 |                                   |
| Safety Inspection of A77 Ayr South V1 on 25 January 2018  |         |       |               |                           |                 |                          |                   |                 |                                   |
| No defects recorded                                       |         |       |               |                           |                 |                          |                   |                 |                                   |
| Safety Inspection of A77 Ayr South V1 on 01 February 2018 |         |       |               |                           |                 |                          |                   |                 |                                   |
| No defects recorded                                       |         |       |               |                           |                 |                          |                   |                 |                                   |
| Safety Inspection of A77 Ayr South V1 on 08 February 2018 |         |       |               |                           |                 |                          |                   |                 |                                   |
| No defects recorded                                       |         |       |               |                           |                 |                          |                   |                 |                                   |



| Defect Reference   | Start<br>m | End<br>m | Item Type              | Item Detail                                | Defect<br>Category | Required<br>Completion Date | Current Status           | Completion<br>Date | Location Description  |
|--|------------|----------|------------------------|--|--------------------|-----------------------------|--------------------------|--------------------|---|
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b>     |            |          |                        |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b>     |            |          |                        |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>        |            |          |                        |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>        |            |          |                        |  |                    |                             |                          |                    |   |
| SW82326075-235554308   | 282m       | 283m     | TRAFFIC_SIGNS          | Damaged<br>(DAMG)                          | CAT 1              | 05/04/2018                  | Completed<br>Defects     | 16/04/2018         | A77 SB VERGE, 200M FROM<br>END OF CLIMBING LANE<br>BALLANTRAE |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>        |            |          |                        |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>        |            |          |                        |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>        |            |          |                        |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>        |            |          |                        |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>        |            |          |                        |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>        |            |          |                        |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>        |            |          |                        |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>          |            |          |                        |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>          |            |          |                        |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |            |          |                        |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |            |          |                        |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |            |          |                        |  |                    |                             |                          |                    |   |
| SW82356191-235816776   | 301m       | 302m     | TRAFFIC_SIGNS          | Physical<br>condition of<br>post (COPT)    | CAT 1              | 28/06/2018                  | Completed<br>Defects     | 20/06/2018         | A77 SB VERGE BINNIAN HILL<br>NORTH OF BALLENTYRE              |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |            |          |                        |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |            |          |                        |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |            |          |                        |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |            |          |                        |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |            |          |                        |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |            |          |                        |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |            |          |                        |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |            |          |                        |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |            |          |                        |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |            |          |                        |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |            |          |                        |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |            |          |                        |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |            |          |                        |  |                    |                             |                          |                    |   |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |            |          |                        |  |                    |                             |                          |                    |   |
| SW82332071-415   | 21m        | 121m     | ROAD_MARKINGS<br>_LONG | Wear (for<br>example<br>erosion)<br>(WEAR) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |   |

| Defect Reference  | Start m | End m | Item Type     | Item Detail                       | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                                    |
|---|---------|-------|---------------|-----------------------------------|-----------------|--------------------------|-------------------|-----------------|---|
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>    |         |       |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b> |         |       |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b> |         |       |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b> |         |       |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b> |         |       |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>   |         |       |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>   |         |       |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>   |         |       |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>   |         |       |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                   |                 |                          |                   |                 |   |
| SW82427366-236262606  | 277m    | 278m  | TRAFFIC_SIGNS | Physical condition of post (COPT) | CAT 1           | 10/01/2019               | Completed Defects | 13/12/2018      | A77 SB VERGE, BOTTOM OF BENNANE HILL, NTH OF BALLANTRAE |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>   |         |       |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>   |         |       |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>   |         |       |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>   |         |       |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>   |         |       |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>     |         |       |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>     |         |       |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>     |         |       |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                   |                 |                          |                   |                 |   |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>     |         |       |               |                                   |                 |                          |                   |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                   |                 |                          |                   |                 |   |

11614/15 : Bennane Jct to Little Bennane Jct

| Defect Reference   | Start<br>m | End<br>m | Item Type   | Item Detail              | Defect<br>Category | Required<br>Completion Date | Current Status       | Completion<br>Date | Location Description                     |
|--|------------|----------|-------------|--------------------------|--------------------|-----------------------------|----------------------|--------------------|--|
| <b>Safety Inspection of A77 Ayr South V1 on 04 January 2018</b>      |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 11 January 2018</b>      |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 18 January 2018</b>      |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 25 January 2018</b>      |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 February 2018</b>     |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 February 2018</b>     |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 February 2018</b>     |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 February 2018</b>     |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 01 March 2018</b>        |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 08 March 2018</b>        |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 15 March 2018</b>        |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 22 March 2018</b>        |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 29 March 2018</b>        |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 April 2018</b>        |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 April 2018</b>        |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 April 2018</b>        |            |          |             |                          |                    |                             |                      |                    |  |
| SW82338893-235633867   | 981m       | 981m     | CARRIAGEWAY | Pothole VIAFIX<br>(POTV) | CAT 1              | 20/04/2018                  | Completed<br>Defects | 19/04/2018         | A77 N/B @ BENNANE LODGE<br>N/S/L O/S/W/T |
| <b>Safety Inspection of A77 Ayr South V1 on 26 April 2018</b>        |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 May 2018</b>          |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 May 2018</b>          |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 May 2018</b>          |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 24 May 2018</b>          |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 May 2018</b>          |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 June 2018</b>         |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 June 2018</b>         |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 June 2018</b>         |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 27 June 2018</b> |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 June 2018</b>         |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 05 July 2018</b>         |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 12 July 2018</b>         |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 19 July 2018</b>         |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 26 July 2018</b>         |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 02 August 2018</b>       |            |          |             |                          |                    |                             |                      |                    |  |
| <i>No defects recorded</i>   |            |          |             |                          |                    |                             |                      |                    |  |
| <b>Safety Inspection of A77 Ayr South V1 on 09 August 2018</b>       |            |          |             |                          |                    |                             |                      |                    |  |

| Defect Reference   | Start<br>m | End<br>m | Item Type              | Item Detail                                | Defect<br>Category | Required<br>Completion Date | Current Status           | Completion<br>Date | Location Description |
|--|------------|----------|------------------------|--|--------------------|-----------------------------|--------------------------|--------------------|----------------------|
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 16 August 2018</b>       |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 23 August 2018</b>       |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr S Det on 23 July 2018</b> |            |          |                        |  |                    |                             |                          |                    |                      |
| SW82332071-424   | 1,446m     | 1,546m   | ROAD_MARKINGS<br>_LONG | Wear (for<br>example<br>erosion)<br>(WEAR) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                      |
| SW82332071-417   | 254m       | 454m     | FILTER_DRAIN           | Weed growth<br>(WEED)                      | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                      |
| SW82332071-423   | 1,213m     | 1,293m   | CARRIAGEWAY            | Bituminous<br>surfacing<br>fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                      |
| SW82332071-420   | 607m       | 687m     | ROAD_MARKINGS<br>_LONG | Wear (for<br>example<br>erosion)<br>(WEAR) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                      |
| SW82332071-419   | 474m       | 554m     | CARRIAGEWAY            | Bituminous<br>surfacing<br>fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                      |
| SW82332071-421   | 868m       | 948m     | CARRIAGEWAY            | Bituminous<br>surfacing<br>fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                      |
| SW82332071-416   | 122m       | 202m     | CARRIAGEWAY            | Bituminous<br>surfacing<br>fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                      |
| SW82332071-418   | 354m       | 454m     | ROAD_MARKINGS<br>_LONG | Wear (for<br>example<br>erosion)<br>(WEAR) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                      |
| SW82332071-422   | 1,038m     | 1,138m   | ROAD_MARKINGS<br>_LONG | Wear (for<br>example<br>erosion)<br>(WEAR) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting<br>Action | 01/01/9999         |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 30 August 2018</b>       |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 06 September 2018</b>    |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 13 September 2018</b>    |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 20 September 2018</b>    |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 27 September 2018</b>    |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 04 October 2018</b>      |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 11 October 2018</b>      |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 18 October 2018</b>      |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 25 October 2018</b>      |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 01 November 2018</b>     |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 08 November 2018</b>     |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 15 November 2018</b>     |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 22 November 2018</b>     |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 29 November 2018</b>     |            |          |                        |  |                    |                             |                          |                    |                      |
| <i>No defects recorded</i>   |            |          |                        |  |                    |                             |                          |                    |                      |
| <b>Safety Inspection of A77 Ayr South V1 on 06 December 2018</b>     |            |          |                        |  |                    |                             |                          |                    |                      |

| Defect Reference   | Start m | End m | Item Type     | Item Detail                           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description                           |
|--|---------|-------|---------------|---------------------------------------|-----------------|--------------------------|-------------------|-----------------|--|
| <i>No defects recorded</i>   |         |       |               |                                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 13 December 2018</b>           |         |       |               |                                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 20 December 2018</b>           |         |       |               |                                       |                 |                          |                   |                 |  |
| SW82427527-236264604   | 197m    | 198m  | TRAFFIC_SIGNS | Physical condition of fittings (COFT) | CAT 1           | 21/12/2018               | Completed Defects | 20/12/2018      | A77 SB CW BENNANE HILL                         |
| <b>Safety Inspection of A77 Ayr South V1 on 27 December 2018</b>           |         |       |               |                                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 03 January 2019</b>            |         |       |               |                                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 10 January 2019</b>            |         |       |               |                                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 17 January 2019</b>            |         |       |               |                                       |                 |                          |                   |                 |  |
| SW82428228-236270549   | 987m    | 988m  | CARRIAGEWAY   | Pothole VIAFIX (POTV)                 | CAT 1           | 18/01/2019               | Completed Defects | 17/01/2019      | A77 NB CW 15M SOUTH OF MEIKLE BENNANE FARM JCT |
| SW82428228-236270550   | 987m    | 988m  | CARRIAGEWAY   | Pothole VIAFIX (POTV)                 | CAT 1           | 18/01/2019               | Completed Defects | 17/01/2019      | A77 NB CW 20M SOUTH MEIKLE BENNANE FARM JCT    |
| SW82428228-236270548   | 391m    | 392m  | GULLY         | Difference in level with road (IDLV)  | CAT 1           | 14/02/2019               | Completed Defects | 24/01/2019      | A77 SB CW LAYBY ON BENNANE HILL                |
| <b>Safety Inspection of A77 Ayr South V1 on 24 January 2019</b>            |         |       |               |                                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 31 January 2019</b>            |         |       |               |                                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 February 2019</b>           |         |       |               |                                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 February 2019</b>           |         |       |               |                                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 February 2019</b>           |         |       |               |                                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 February 2019</b>           |         |       |               |                                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 07 March 2019</b>              |         |       |               |                                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 14 March 2019</b>              |         |       |               |                                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 21 March 2019</b>              |         |       |               |                                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A77 Ayr South V1 on 28 March 2019</b>              |         |       |               |                                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                       |                 |                          |                   |                 |  |
| <b>11641/94 : Whitletts Roundabout</b>                                     |         |       |               |                                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 January 2018</b>  |         |       |               |                                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 January 2018</b>  |         |       |               |                                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 January 2018</b>  |         |       |               |                                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 January 2018</b>  |         |       |               |                                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 January 2018</b>  |         |       |               |                                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 February 2018</b> |         |       |               |                                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 February 2018</b> |         |       |               |                                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 February 2018</b> |         |       |               |                                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 February 2018</b> |         |       |               |                                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 March 2018</b>    |         |       |               |                                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                       |                 |                          |                   |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 March 2018</b>    |         |       |               |                                       |                 |                          |                   |                 |  |
| <i>No defects recorded</i>   |         |       |               |                                       |                 |                          |                   |                 |  |

| Defect Reference  | Start m | End m | Item Type   | Item Detail           | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description    |
|---|---------|-------|-------------|-----------------------|-----------------|--------------------------|-------------------|-----------------|-------------------------|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 March 2018</b>     |         |       |             |                       |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 March 2018</b>     |         |       |             |                       |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 April 2018</b>     |         |       |             |                       |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 April 2018</b>     |         |       |             |                       |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 April 2018</b>     |         |       |             |                       |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 April 2018</b>     |         |       |             |                       |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 01 May 2018</b>       |         |       |             |                       |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 May 2018</b>       |         |       |             |                       |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 May 2018</b>       |         |       |             |                       |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 May 2018</b>       |         |       |             |                       |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 May 2018</b>       |         |       |             |                       |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 June 2018</b>      |         |       |             |                       |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 June 2018</b>      |         |       |             |                       |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 June 2018</b>      |         |       |             |                       |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 June 2018</b>      |         |       |             |                       |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                         |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018</b>        |         |       |             |                       |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 July 2018</b>      |         |       |             |                       |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 July 2018</b>      |         |       |             |                       |                 |                          |                   |                 |                         |
| SW82376428-235909728  | 70m     | 71m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 07/08/2018               | Completed Defects | 10/07/2018      | A77 SB CW WHITLETTS RBT |
| SW82376428-235909729  | 82m     | 83m   | CARRIAGEWAY | Pothole VIAFIX (POTV) | CAT 1           | 07/08/2018               | Completed Defects | 10/07/2018      | A77 NB CW WHITLETTS RBT |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 July 2018</b>      |         |       |             |                       |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 July 2018</b>      |         |       |             |                       |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 July 2018</b>      |         |       |             |                       |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 August 2018</b>    |         |       |             |                       |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 14 August 2018</b>    |         |       |             |                       |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 21 August 2018</b>    |         |       |             |                       |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 28 August 2018</b>    |         |       |             |                       |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 September 2018</b> |         |       |             |                       |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 September 2018</b> |         |       |             |                       |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 September 2018</b> |         |       |             |                       |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 25 September 2018</b> |         |       |             |                       |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 October 2018</b>   |         |       |             |                       |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 October 2018</b>   |         |       |             |                       |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |             |                       |                 |                          |                   |                 |                         |

| Defect Reference   | Start<br>m | End<br>m | Item Type   | Item Detail                          | Defect<br>Category | Required<br>Completion Date | Current Status        | Completion<br>Date | Location Description |
|--|------------|----------|-------------|--------------------------------------|--------------------|-----------------------------|-----------------------|--------------------|----------------------|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 October 2018</b>  |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 October 2018</b>  |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 October 2018</b>  |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 November 2018</b> |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 November 2018</b> |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 November 2018</b> |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 November 2018</b> |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 December 2018</b> |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 December 2018</b> |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 December 2018</b> |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 December 2018</b> |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 December 2018</b> |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 January 2019</b>  |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 January 2019</b>  |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 January 2019</b>  |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 January 2019</b>  |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 January 2019</b>  |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 February 2019</b> |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 February 2019</b> |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 February 2019</b> |            |          |             |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018</b>   |            |          |             |                                      |                    |                             |                       |                    |                      |
| SW82332070-461   | 240m       | 290m     | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-463   | 75m        | 155m     | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-465   | 131m       | 141m     | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-460   | 209m       | 290m     | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-464   | 180m       | 190m     | CARRIAGEWAY | Localised cracking (LOCK)            | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-459   | 145m       | 225m     | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-462   | 13m        | 83m      | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-469   | 161m       | 161m     | GULLY       | Other (OTHR)                         | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 February 2019</b> |            |          |             |                                      |                    |                             |                       |                    |                      |

| Defect Reference | Start<br>m | End<br>m | Item Type | Item Detail | Defect<br>Category | Required<br>Completion Date | Current Status | Completion<br>Date | Location Description |
|------------------|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|
|------------------|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|

*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 05 March 2019**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 12 March 2019**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 19 March 2019**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 26 March 2019**  
*No defects recorded*

**11641/07 : Holmston Rbt to start of 3 lane**

**Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 27 March 2018**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 03 April 2018**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 10 April 2018**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 17 April 2018**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 24 April 2018**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 01 May 2018**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 08 May 2018**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 15 May 2018**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 22 May 2018**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 29 May 2018**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 05 June 2018**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 12 June 2018**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 19 June 2018**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 26 June 2018**  
*No defects recorded*  
**Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018**  
*No defects recorded*  
**Safety Inspection of A76 & A77 Ayr North V1 on 03 July 2018**  
*No defects recorded*





| Defect Reference  | Start m | End m  | Item Type     | Item Detail                                      | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description             |
|---|---------|--------|---------------|--|-----------------|--------------------------|-----------------------|-----------------|----------------------------------|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 July 2018</b>      |         |        |               |  |                 |                          |                       |                 |                                  |
| <i>No defects recorded</i>  |         |        |               |  |                 |                          |                       |                 |                                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 July 2018</b>      |         |        |               |  |                 |                          |                       |                 |                                  |
| <i>No defects recorded</i>  |         |        |               |  |                 |                          |                       |                 |                                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 July 2018</b>      |         |        |               |  |                 |                          |                       |                 |                                  |
| <i>No defects recorded</i>  |         |        |               |  |                 |                          |                       |                 |                                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 July 2018</b>      |         |        |               |  |                 |                          |                       |                 |                                  |
| <i>No defects recorded</i>  |         |        |               |  |                 |                          |                       |                 |                                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 August 2018</b>    |         |        |               |  |                 |                          |                       |                 |                                  |
| <i>No defects recorded</i>  |         |        |               |  |                 |                          |                       |                 |                                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 14 August 2018</b>    |         |        |               |  |                 |                          |                       |                 |                                  |
| SW80-393014-235952318   | 764m    | 765m   | CARRIAGEWAY   | Pothole VIAFIX (POTV)                            | CAT 1           | 11/09/2018               | Completed Defects     | 14/08/2018      | A77 SB CW 25M AFTER MAINHOLM JCT |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 21 August 2018</b>    |         |        |               |  |                 |                          |                       |                 |                                  |
| <i>No defects recorded</i>  |         |        |               |  |                 |                          |                       |                 |                                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 28 August 2018</b>    |         |        |               |  |                 |                          |                       |                 |                                  |
| <i>No defects recorded</i>  |         |        |               |  |                 |                          |                       |                 |                                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 September 2018</b> |         |        |               |  |                 |                          |                       |                 |                                  |
| <i>No defects recorded</i>  |         |        |               |  |                 |                          |                       |                 |                                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 September 2018</b> |         |        |               |  |                 |                          |                       |                 |                                  |
| <i>No defects recorded</i>  |         |        |               |  |                 |                          |                       |                 |                                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 September 2018</b> |         |        |               |  |                 |                          |                       |                 |                                  |
| <i>No defects recorded</i>  |         |        |               |  |                 |                          |                       |                 |                                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 25 September 2018</b> |         |        |               |  |                 |                          |                       |                 |                                  |
| <i>No defects recorded</i>  |         |        |               |  |                 |                          |                       |                 |                                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 October 2018</b>   |         |        |               |  |                 |                          |                       |                 |                                  |
| <i>No defects recorded</i>  |         |        |               |  |                 |                          |                       |                 |                                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 October 2018</b>   |         |        |               |  |                 |                          |                       |                 |                                  |
| <i>No defects recorded</i>  |         |        |               |  |                 |                          |                       |                 |                                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 October 2018</b>   |         |        |               |  |                 |                          |                       |                 |                                  |
| <i>No defects recorded</i>  |         |        |               |  |                 |                          |                       |                 |                                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 October 2018</b>   |         |        |               |  |                 |                          |                       |                 |                                  |
| <i>No defects recorded</i>  |         |        |               |  |                 |                          |                       |                 |                                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 October 2018</b>   |         |        |               |  |                 |                          |                       |                 |                                  |
| <i>No defects recorded</i>  |         |        |               |  |                 |                          |                       |                 |                                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 November 2018</b>  |         |        |               |  |                 |                          |                       |                 |                                  |
| <i>No defects recorded</i>  |         |        |               |  |                 |                          |                       |                 |                                  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 November 2018</b>  |         |        |               |  |                 |                          |                       |                 |                                  |
| <i>No defects recorded</i>  |         |        |               |  |                 |                          |                       |                 |                                  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018</b>    |         |        |               |  |                 |                          |                       |                 |                                  |
| SW82332070-34   | 75m     | 75m    | TRAFFIC_SIGNS | Physical condition of post (COPT)                | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                  |
| SW82332070-36   | 93m     | 193m   | CARRIAGEWAY   | Opening of longitudinal joint (OLJT)             | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                  |
| SW82332070-52   | 1,024m  | 1,034m | FOOTWAY       | Bituminous surfacing - extensive cracking (BECK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                  |
| SW82332070-54   | 1,081m  | 1,081m | TRAFFIC_SIGNS | Physical condition of post (COPT)                | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                  |
| SW82332070-32   | 36m     | 106m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)             | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                  |
| SW82332070-38   | 192m    | 292m   | CARRIAGEWAY   | Opening of longitudinal joint (OLJT)             | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                  |
| SW82332070-56   | 1,153m  | 1,163m | FOOTWAY       | Bituminous surfacing - extensive cracking (BECK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                  |

| Defect Reference | Start m | End m  | Item Type     | Item Detail                                      | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|------------------|---------|--------|---------------|--|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| SW82332070-58    | 1,248m  | 1,268m | FOOTWAY       | Bituminous surfacing - extensive cracking (BECK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-41    | 488m    | 498m   | FOOTWAY       | Bituminous surfacing - extensive cracking (BECK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-48    | 727m    | 737m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)             | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-59    | 1,556m  | 1,561m | CARRIAGEWAY   | Localised cracking (LOCK)                        | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-31    | 13m     | 17m    | FOOTWAY       | Bituminous surfacing - extensive cracking (BECK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-44    | 612m    | 622m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)             | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-45    | 670m    | 680m   | FOOTWAY       | Bituminous surfacing - extensive cracking (BECK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-62    | 1,875m  | 1,895m | FOOTWAY       | Bituminous surfacing - extensive cracking (BECK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-33    | 54m     | 55m    | TRAFFIC_SIGNS | Physical condition of post (COPT)                | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-39    | 266m    | 276m   | CARRIAGEWAY   | Localised cracking (LOCK)                        | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-50    | 933m    | 953m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)             | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-57    | 1,211m  | 1,221m | FOOTWAY       | Bituminous surfacing - extensive cracking (BECK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-30    | 11m     | 51m    | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)             | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-43    | 560m    | 570m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)             | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-46    | 675m    | 685m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)             | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-47    | 708m    | 728m   | CARRIAGEWAY   | Localised cracking (LOCK)                        | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-60    | 1,643m  | 1,743m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT)             | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail                                      | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                           |
|--|---------|--------|-------------|--|-----------------|--------------------------|-----------------------|-----------------|--|
| SW82332070-61  | 1,878m  | 1,898m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT)             | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-35  | 79m     | 179m   | CARRIAGEWAY | Bituminous surfacing fretting (BFRT)             | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-37  | 125m    | 225m   | CARRIAGEWAY | Opening of longitudinal joint (OLJT)             | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-53  | 1,055m  | 1,065m | CARRIAGEWAY | Localised cracking (LOCK)                        | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-55  | 1,103m  | 1,123m | FOOTWAY     | Bituminous surfacing - extensive cracking (BECK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-40  | 301m    | 381m   | CARRIAGEWAY | Opening of longitudinal joint (OLJT)             | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-42  | 543m    | 562m   | FOOTWAY     | Bituminous surfacing - extensive cracking (BECK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-49  | 823m    | 883m   | CARRIAGEWAY | Bituminous surfacing fretting (BFRT)             | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| SW82332070-51  | 943m    | 953m   | FOOTWAY     | Bituminous surfacing - extensive cracking (BECK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 November 2018</b> |         |        |             |  |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |  |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 November 2018</b> |         |        |             |  |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |  |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 December 2018</b> |         |        |             |  |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |  |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 December 2018</b> |         |        |             |  |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |  |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 December 2018</b> |         |        |             |  |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |  |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 December 2018</b> |         |        |             |  |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |  |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 December 2018</b> |         |        |             |  |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |  |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 January 2019</b>  |         |        |             |  |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |  |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 January 2019</b>  |         |        |             |  |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |  |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 January 2019</b>  |         |        |             |  |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |  |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 January 2019</b>  |         |        |             |  |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |  |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 January 2019</b>  |         |        |             |  |                 |                          |                       |                 |  |
| SW82428594-236291692   | 1,119m  | 1,120m | CARRIAGEWAY | Pothole (POTH)                                   | CAT 1           | 26/02/2019               | Completed Defects     | 31/01/2019      | A77 SB CW 30M BEFORE MAINHOLM SMALLHOLDIÑS JCT |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 February 2019</b> |         |        |             |  |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |  |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 February 2019</b> |         |        |             |  |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |  |                 |                          |                       |                 |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 February 2019</b> |         |        |             |  |                 |                          |                       |                 |  |
| No defects recorded  |         |        |             |  |                 |                          |                       |                 |  |

| Defect Reference   | Start<br>m | End<br>m | Item Type | Item Detail | Defect<br>Category | Required<br>Completion Date | Current Status | Completion<br>Date | Location Description |
|--|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 February 2019</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 March 2019</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 March 2019</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 March 2019</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 March 2019</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>11641/83 : Start of 3 Lane to Rbt approach</b>                          |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 January 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 January 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 January 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 January 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 January 2018</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 February 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 February 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 February 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 February 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 March 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 March 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 March 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 March 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 April 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 April 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 April 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 April 2018</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 01 May 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 May 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 May 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 May 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 May 2018</b>      |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 June 2018</b>     |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 June 2018</b>     |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 June 2018</b>     |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 June 2018</b>     |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018</b>       |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 July 2018</b>     |            |          |           |             |                    |                             |                |                    |                      |

| Defect Reference  | Start m | End m | Item Type   | Item Detail                                      | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|---|---------|-------|-------------|--|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| <i>No defects recorded</i>  |         |       |             |  |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 July 2018</b>      |         |       |             |  |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |             |  |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 July 2018</b>      |         |       |             |  |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |             |  |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 July 2018</b>      |         |       |             |  |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |             |  |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 July 2018</b>      |         |       |             |  |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |             |  |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 August 2018</b>    |         |       |             |  |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |             |  |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 14 August 2018</b>    |         |       |             |  |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |             |  |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 21 August 2018</b>    |         |       |             |  |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |             |  |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 28 August 2018</b>    |         |       |             |  |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |             |  |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 September 2018</b> |         |       |             |  |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |             |  |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 September 2018</b> |         |       |             |  |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |             |  |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 September 2018</b> |         |       |             |  |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |             |  |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 25 September 2018</b> |         |       |             |  |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |             |  |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 October 2018</b>   |         |       |             |  |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |             |  |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 October 2018</b>   |         |       |             |  |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |             |  |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 October 2018</b>   |         |       |             |  |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |             |  |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 October 2018</b>   |         |       |             |  |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |             |  |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 October 2018</b>   |         |       |             |  |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |             |  |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 November 2018</b>  |         |       |             |  |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |             |  |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 November 2018</b>  |         |       |             |  |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |             |  |                 |                          |                       |                 |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018</b>    |         |       |             |  |                 |                          |                       |                 |                      |
| SW82332070-64   | 107m    | 137m  | CARRIAGEWAY | Opening of longitudinal joint (OLJT)             | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-63   | 16m     | 66m   | FOOTWAY     | Bituminous surfacing - extensive cracking (BECK) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-66   | 173m    | 193m  | CARRIAGEWAY | Bituminous surfacing fretting (BFRT)             | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-65   | 116m    | 120m  | CARRIAGEWAY | Localised cracking (LOCK)                        | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 November 2018</b>  |         |       |             |  |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |             |  |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 November 2018</b>  |         |       |             |  |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |             |  |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 December 2018</b>  |         |       |             |  |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |             |  |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 December 2018</b>  |         |       |             |  |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |             |  |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 December 2018</b>  |         |       |             |  |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |             |  |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 December 2018</b>  |         |       |             |  |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>  |         |       |             |  |                 |                          |                       |                 |                      |

| Defect Reference   | Start<br>m | End<br>m | Item Type | Item Detail | Defect<br>Category | Required<br>Completion Date | Current Status | Completion<br>Date | Location Description |
|--|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 December 2018</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 January 2019</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 January 2019</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 January 2019</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 January 2019</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 January 2019</b>  |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 February 2019</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 February 2019</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 February 2019</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 February 2019</b> |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 March 2019</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 March 2019</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 March 2019</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 March 2019</b>    |            |          |           |             |                    |                             |                |                    |                      |
| <i>No defects recorded</i>   |            |          |           |             |                    |                             |                |                    |                      |

**11641/88 : With: NB Entry to Whitletts Rbt**

|  |  |  |  |  |  |  |  |  |  |
|--|--|--|--|--|--|--|--|--|--|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 January 2018</b>  |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 January 2018</b>  |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 January 2018</b>  |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 January 2018</b>  |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 January 2018</b>  |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 February 2018</b> |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 February 2018</b> |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 February 2018</b> |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 February 2018</b> |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 March 2018</b>    |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 March 2018</b>    |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 March 2018</b>    |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 March 2018</b>    |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 April 2018</b>    |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 April 2018</b>    |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 April 2018</b>    |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 April 2018</b>    |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 01 May 2018</b>      |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 May 2018</b>      |  |  |  |  |  |  |  |  |  |

| Defect Reference | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|------------------|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|
|------------------|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|

|   |
|---|
| <i>No defects recorded</i>  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 May 2018</b>       |
| <i>No defects recorded</i>  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 May 2018</b>       |
| <i>No defects recorded</i>  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 May 2018</b>       |
| <i>No defects recorded</i>  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 June 2018</b>      |
| <i>No defects recorded</i>  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 June 2018</b>      |
| <i>No defects recorded</i>  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 June 2018</b>      |
| <i>No defects recorded</i>  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 June 2018</b>      |
| <i>No defects recorded</i>  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018</b>        |
| <i>No defects recorded</i>  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 July 2018</b>      |
| <i>No defects recorded</i>  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 July 2018</b>      |
| <i>No defects recorded</i>  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 July 2018</b>      |
| <i>No defects recorded</i>  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 July 2018</b>      |
| <i>No defects recorded</i>  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 July 2018</b>      |
| <i>No defects recorded</i>  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 August 2018</b>    |
| <i>No defects recorded</i>  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 14 August 2018</b>    |
| <i>No defects recorded</i>  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 21 August 2018</b>    |
| <i>No defects recorded</i>  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 28 August 2018</b>    |
| <i>No defects recorded</i>  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 September 2018</b> |
| <i>No defects recorded</i>  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 September 2018</b> |
| <i>No defects recorded</i>  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 September 2018</b> |
| <i>No defects recorded</i>  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 25 September 2018</b> |
| <i>No defects recorded</i>  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 October 2018</b>   |
| <i>No defects recorded</i>  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 October 2018</b>   |
| <i>No defects recorded</i>  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 October 2018</b>   |
| <i>No defects recorded</i>  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 October 2018</b>   |
| <i>No defects recorded</i>  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 October 2018</b>   |
| <i>No defects recorded</i>  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 November 2018</b>  |
| <i>No defects recorded</i>  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 November 2018</b>  |
| <i>No defects recorded</i>  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 November 2018</b>  |
| <i>No defects recorded</i>  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 November 2018</b>  |
| <i>No defects recorded</i>  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 December 2018</b>  |
| <i>No defects recorded</i>  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 December 2018</b>  |
| <i>No defects recorded</i>  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 December 2018</b>  |
| <i>No defects recorded</i>  |

| Defect Reference   | Start m | End m | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|--|---------|-------|-------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 December 2018</b> |         |       |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 December 2018</b> |         |       |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 January 2019</b>  |         |       |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 January 2019</b>  |         |       |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 January 2019</b>  |         |       |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 January 2019</b>  |         |       |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 January 2019</b>  |         |       |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 February 2019</b> |         |       |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 February 2019</b> |         |       |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 February 2019</b> |         |       |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018</b>   |         |       |             |                                      |                 |                          |                       |                 |                      |
| SW82332070-468   | 18m     | 55m   | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-467   | 19m     | 55m   | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 February 2019</b> |         |       |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 March 2019</b>    |         |       |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 March 2019</b>    |         |       |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 March 2019</b>    |         |       |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 March 2019</b>    |         |       |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                      |
| <b>11641/89 : Against: SB Exit from Whitletts Rbt</b>                      |         |       |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 January 2018</b>  |         |       |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 January 2018</b>  |         |       |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 January 2018</b>  |         |       |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 January 2018</b>  |         |       |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 January 2018</b>  |         |       |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 February 2018</b> |         |       |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 February 2018</b> |         |       |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 February 2018</b> |         |       |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 February 2018</b> |         |       |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 March 2018</b>    |         |       |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 March 2018</b>    |         |       |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 March 2018</b>    |         |       |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 March 2018</b>    |         |       |             |                                      |                 |                          |                       |                 |                      |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 April 2018</b>    |         |       |             |                                      |                 |                          |                       |                 |                      |



| Defect Reference | Start<br>m | End<br>m | Item Type | Item Detail | Defect<br>Category | Required<br>Completion Date | Current Status | Completion<br>Date | Location Description |
|------------------|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|
|------------------|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|

|   |  |  |  |  |  |  |  |  |  |
|---|--|--|--|--|--|--|--|--|--|
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 April 2018</b>     |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 April 2018</b>     |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 April 2018</b>     |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 01 May 2018</b>       |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 May 2018</b>       |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 May 2018</b>       |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 May 2018</b>       |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 May 2018</b>       |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 June 2018</b>      |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 June 2018</b>      |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 June 2018</b>      |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 June 2018</b>      |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018</b>        |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 July 2018</b>      |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 July 2018</b>      |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 July 2018</b>      |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 July 2018</b>      |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 July 2018</b>      |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 August 2018</b>    |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 14 August 2018</b>    |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 21 August 2018</b>    |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 28 August 2018</b>    |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 September 2018</b> |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 September 2018</b> |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 September 2018</b> |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 25 September 2018</b> |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 October 2018</b>   |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 October 2018</b>   |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 October 2018</b>   |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 October 2018</b>   |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 October 2018</b>   |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 November 2018</b>  |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 November 2018</b>  |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>  |  |  |  |  |  |  |  |  |  |

| Defect Reference   | Start m | End m  | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description  |
|--|---------|--------|-------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 November 2018</b> |         |        |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 November 2018</b> |         |        |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 December 2018</b> |         |        |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 December 2018</b> |         |        |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 December 2018</b> |         |        |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 December 2018</b> |         |        |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 December 2018</b> |         |        |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 January 2019</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 January 2019</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 January 2019</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 January 2019</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 January 2019</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 February 2019</b> |         |        |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 February 2019</b> |         |        |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 February 2019</b> |         |        |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018</b>   |         |        |             |                                      |                 |                          |                       |                 |   |
| SW82332070-466   | 26m     | 66m    | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 February 2019</b> |         |        |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 March 2019</b>    |         |        |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 March 2019</b>    |         |        |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 March 2019</b>    |         |        |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 March 2019</b>    |         |        |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>11644/65 : Against: Sandyford Toll Rbt to start of 4 lane</b>           |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 January 2018</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 January 2018</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 January 2018</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>   |         |        |             |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 January 2018</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| SW82317767-235529088   | 874m    | 878m   | CARRIAGEWAY | Pothole (POTH)                       | CAT 1           | 20/02/2018               | Completed Defects     | 23/01/2018      | A77 SB CW, LANE 1, AT FARM ENTRY 800M STH OF DUTCHHOUSE RBT |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 15 September 2017</b>  |         |        |             |                                      |                 |                          |                       |                 |   |
| SW82256027-333   | 148m    | 228m   | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 SANDYFORD RBT TO WHITLETTS RBT                            |
| SW82256027-335   | 547m    | 627m   | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 SANDYFORD RBT TO WHITLETTS RBT                            |
| SW82256027-337   | 970m    | 1,050m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 SANDYFORD RBT TO WHITLETTS RBT                            |

| Defect Reference | Start m | End m  | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description             |
|------------------|---------|--------|-------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|----------------------------------|
| SW82256027-350   | 2,527m  | 2,607m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 SANDYFORD RBT TO WHITLETTS RBT |
| SW82256027-339   | 1,268m  | 1,348m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 SANDYFORD RBT TO WHITLETTS RBT |
| SW82256027-341   | 1,673m  | 1,753m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 SANDYFORD RBT TO WHITLETTS RBT |
| SW82256027-346   | 2,109m  | 2,189m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 SANDYFORD RBT TO WHITLETTS RBT |
| SW82256027-348   | 2,373m  | 2,453m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 SANDYFORD RBT TO WHITLETTS RBT |
| SW82256027-340   | 1,456m  | 1,536m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 SANDYFORD RBT TO WHITLETTS RBT |
| SW82256027-347   | 2,232m  | 2,312m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 SANDYFORD RBT TO WHITLETTS RBT |
| SW82256027-343   | 1,769m  | 1,849m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 SANDYFORD RBT TO WHITLETTS RBT |
| SW82256027-344   | 1,844m  | 1,924m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 SANDYFORD RBT TO WHITLETTS RBT |
| SW82256027-342   | 1,717m  | 1,817m | FOOTWAY     | Need for herbicide (HERB)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 SANDYFORD RBT TO WHITLETTS RBT |
| SW82256027-345   | 2,012m  | 2,092m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 SANDYFORD RBT TO WHITLETTS RBT |
| SW82256027-331   | 4m      | 84m    | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 SANDYFORD RBT TO WHITLETTS RBT |
| SW82256027-349   | 2,421m  | 2,401m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 SANDYFORD RBT TO WHITLETTS RBT |
| SW82256027-334   | 229m    | 309m   | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 SANDYFORD RBT TO WHITLETTS RBT |
| SW82256027-336   | 827m    | 907m   | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 SANDYFORD RBT TO WHITLETTS RBT |
| SW82256027-351   | 2,620m  | 2,660m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 SANDYFORD RBT TO WHITLETTS RBT |
| SW82256027-332   | 4m      | 84m    | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 SANDYFORD RBT TO WHITLETTS RBT |

**Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018**

|                      |      |      |             |                |       |            |                   |            |   |
|----------------------|------|------|-------------|----------------|-------|------------|-------------------|------------|---|
| SW82321390-235546245 | 853m | 855m | CARRIAGEWAY | Pothole (POTH) | CAT 1 | 20/03/2018 | Completed Defects | 21/02/2018 | A77 S/B LANE1 AT RAC PHONE BOX SOUTH OF SANDYFORD RBT |
|----------------------|------|------|-------------|----------------|-------|------------|-------------------|------------|---|

**Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018**

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018**

| Defect Reference | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|------------------|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|
|------------------|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 27 March 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 03 April 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 10 April 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 17 April 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 24 April 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 01 May 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 08 May 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 15 May 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 22 May 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 29 May 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 05 June 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 12 June 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 19 June 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 26 June 2018**  
No defects recorded

**Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018**

|               |      |      |          |                         |       |            |                       |            |  |
|---------------|------|------|----------|-------------------------|-------|------------|-----------------------|------------|--|
| SW86-357205-2 | 627m | 637m | WOODLAND | Invasive species (INVS) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 |  |
|---------------|------|------|----------|-------------------------|-------|------------|-----------------------|------------|--|

**Safety Inspection of A76 & A77 Ayr North V1 on 03 July 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 10 July 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 17 July 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 24 July 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 31 July 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 07 August 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 14 August 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 21 August 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 28 August 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 04 September 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 11 September 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 18 September 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 25 September 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 02 October 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 09 October 2018**  
No defects recorded

| Defect Reference   | Start m | End m  | Item Type     | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description               |
|--|---------|--------|---------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|------------------------------------|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 October 2018</b>  |         |        |               |                                      |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 October 2018</b>  |         |        |               |                                      |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 October 2018</b>  |         |        |               |                                      |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 November 2018</b> |         |        |               |                                      |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 November 2018</b> |         |        |               |                                      |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 November 2018</b> |         |        |               |                                      |                 |                          |                       |                 |                                    |
| SW82426735-236231060   | 864m    | 865m   | CARRIAGEWAY   | Pothole (POTH)                       | CAT 1           | 18/12/2018               | Completed Defects     | 20/11/2018      | A77 SB CW AT KIRKLANDHOME FARM JCT |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 November 2018</b> |         |        |               |                                      |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 December 2018</b> |         |        |               |                                      |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 December 2018</b> |         |        |               |                                      |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 December 2018</b> |         |        |               |                                      |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 December 2018</b> |         |        |               |                                      |                 |                          |                       |                 |                                    |
| SW80-427602-236270240  | 1,886m  | 1,887m | GULLY         | Other (OTHR)                         | CAT 1           | 25/12/2018               | Completed Defects     | 24/12/2018      | A77 SB CW OPPOSITE ST QUIVOX JCT   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 December 2018</b> |         |        |               |                                      |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 January 2019</b>  |         |        |               |                                      |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 January 2019</b>  |         |        |               |                                      |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 January 2019</b>  |         |        |               |                                      |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |                                    |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018</b>   |         |        |               |                                      |                 |                          |                       |                 |                                    |
| SW82332070-207   | 1,881m  | 1,882m | CARRIAGEWAY   | Pothole (POTH)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                    |
| SW82332070-203   | 1,158m  | 1,200m | FOOTWAY       | Excessive muck (MUCK)                | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                    |
| SW82332070-205   | 1,777m  | 1,877m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                    |
| SW82332070-206   | 1,809m  | 1,859m | CARRIAGEWAY   | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                    |
| SW82332070-202   | 1,158m  | 1,255m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                    |
| SW82332070-200   | 272m    | 372m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                    |
| SW82332070-201   | 969m    | 970m   | CARRIAGEWAY   | Pothole (POTH)                       | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                    |
| SW82332070-204   | 1,651m  | 1,652m | TRAFFIC_SIGNS | Dirty sign (DIRT)                    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                    |
| SW82332070-208   | 1,969m  | 1,971m | CARRIAGEWAY   | Localised cracking (LOCK)            | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 January 2019</b>  |         |        |               |                                      |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 January 2019</b>  |         |        |               |                                      |                 |                          |                       |                 |                                    |
| <i>No defects recorded</i>   |         |        |               |                                      |                 |                          |                       |                 |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 February 2019</b> |         |        |               |                                      |                 |                          |                       |                 |                                    |

| Defect Reference   | Start m | End m | Item Type   | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description                  |
|--|---------|-------|-------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|---------------------------------------|
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 February 2019</b> |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 February 2019</b> |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 February 2019</b> |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 March 2019</b>    |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 March 2019</b>    |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 March 2019</b>    |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 March 2019</b>    |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <b>11644/70 : Against: Start of 4 lane to Whitletts Rbt</b>                |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 January 2018</b>  |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 January 2018</b>  |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 January 2018</b>  |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 January 2018</b>  |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 15 September 2017</b>  |         |       |             |                                      |                 |                          |                       |                 |                                       |
| SW82256027-352   | 16m     | 86m   | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      | 0 SANDYFORD RBT TO WHITLETTS RBT      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 January 2018</b>  |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 February 2018</b> |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 February 2018</b> |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 February 2018</b> |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 February 2018</b> |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 March 2018</b>    |         |       |             |                                      |                 |                          |                       |                 |                                       |
| SW82325502-235553037   | 74m     | 75m   | CARRIAGEWAY | Pothole (POTH)                       | CAT 1           | 03/04/2018               | Completed Defects     | 07/03/2018      | A77 WHITLETTS RBT, SB ENTRANCE TO RBT |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 March 2018</b>    |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 March 2018</b>    |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 March 2018</b>    |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 April 2018</b>    |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 April 2018</b>    |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 April 2018</b>    |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 April 2018</b>    |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 01 May 2018</b>      |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 May 2018</b>      |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 May 2018</b>      |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 May 2018</b>      |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 May 2018</b>      |         |       |             |                                      |                 |                          |                       |                 |                                       |
| <i>No defects recorded</i>   |         |       |             |                                      |                 |                          |                       |                 |                                       |

| Defect Reference  | Start m | End m | Item Type | Item Detail                                      | Defect Category | Required Completion Date | Current Status    | Completion Date | Location Description    |
|---|---------|-------|-----------|--|-----------------|--------------------------|-------------------|-----------------|-------------------------|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 June 2018</b>      |         |       |           |  |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |           |  |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 June 2018</b>      |         |       |           |  |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |           |  |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 June 2018</b>      |         |       |           |  |                 |                          |                   |                 |                         |
| SW82366110-235861201  | 71m     | 72m   | FOOTWAY   | Bituminous surfacing - extensive cracking (BECK) | CAT 1           | 17/07/2018               | Completed Defects | 11/07/2018      | A77 SB CW WHITLETTS RBT |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 June 2018</b>      |         |       |           |  |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |           |  |                 |                          |                   |                 |                         |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018</b>        |         |       |           |  |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |           |  |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 July 2018</b>      |         |       |           |  |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |           |  |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 July 2018</b>      |         |       |           |  |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |           |  |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 July 2018</b>      |         |       |           |  |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |           |  |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 July 2018</b>      |         |       |           |  |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |           |  |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 July 2018</b>      |         |       |           |  |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |           |  |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 August 2018</b>    |         |       |           |  |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |           |  |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 14 August 2018</b>    |         |       |           |  |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |           |  |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 21 August 2018</b>    |         |       |           |  |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |           |  |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 28 August 2018</b>    |         |       |           |  |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |           |  |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 September 2018</b> |         |       |           |  |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |           |  |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 September 2018</b> |         |       |           |  |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |           |  |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 September 2018</b> |         |       |           |  |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |           |  |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 25 September 2018</b> |         |       |           |  |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |           |  |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 October 2018</b>   |         |       |           |  |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |           |  |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 October 2018</b>   |         |       |           |  |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |           |  |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 October 2018</b>   |         |       |           |  |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |           |  |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 October 2018</b>   |         |       |           |  |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |           |  |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 October 2018</b>   |         |       |           |  |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |           |  |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 November 2018</b>  |         |       |           |  |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |           |  |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 November 2018</b>  |         |       |           |  |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |           |  |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 November 2018</b>  |         |       |           |  |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |           |  |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 November 2018</b>  |         |       |           |  |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |           |  |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 December 2018</b>  |         |       |           |  |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |           |  |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 December 2018</b>  |         |       |           |  |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |           |  |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 December 2018</b>  |         |       |           |  |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |           |  |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 December 2018</b>  |         |       |           |  |                 |                          |                   |                 |                         |
| <i>No defects recorded</i>  |         |       |           |  |                 |                          |                   |                 |                         |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 December 2018</b>  |         |       |           |  |                 |                          |                   |                 |                         |

| Defect Reference | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|------------------|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|
|------------------|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|

No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 07 January 2019**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 08 January 2019**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 15 January 2019**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 22 January 2019**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 29 January 2019**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 05 February 2019**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 12 February 2019**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 19 February 2019**  
No defects recorded

**Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018**

|                |     |     |             |                                      |       |            |                       |            |  |
|----------------|-----|-----|-------------|--------------------------------------|-------|------------|-----------------------|------------|--|
| SW82332070-457 | 19m | 89m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 |  |
| SW82332070-458 | 69m | 82m | CARRIAGEWAY | Bituminous surfacing fretting (BFRT) | CAT 2 | 01/01/9999 | Cat 2 Awaiting Action | 01/01/9999 |  |

**Safety Inspection of A76 & A77 Ayr North V1 on 26 February 2019**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 05 March 2019**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 12 March 2019**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 19 March 2019**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 26 March 2019**  
No defects recorded

**11638/20 : Bankhead Rbt to End of Climbing Lane**

**Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 27 March 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 03 April 2018**  
No defects recorded

**Safety Inspection of A76 & A77 Ayr North V1 on 10 April 2018**  
No defects recorded



| Defect Reference  | Start<br>m | End<br>m | Item Type    | Item Detail  | Defect<br>Category | Required<br>Completion Date | Current Status       | Completion<br>Date | Location Description               |
|---|------------|----------|--------------|--|--------------------|-----------------------------|----------------------|--------------------|------------------------------------|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 April 2018</b>     |            |          |              |  |                    |                             |                      |                    |                                    |
| <i>No defects recorded</i>  |            |          |              |  |                    |                             |                      |                    |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 April 2018</b>     |            |          |              |  |                    |                             |                      |                    |                                    |
| <i>No defects recorded</i>  |            |          |              |  |                    |                             |                      |                    |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 01 May 2018</b>       |            |          |              |  |                    |                             |                      |                    |                                    |
| <i>No defects recorded</i>  |            |          |              |  |                    |                             |                      |                    |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 May 2018</b>       |            |          |              |  |                    |                             |                      |                    |                                    |
| <i>No defects recorded</i>  |            |          |              |  |                    |                             |                      |                    |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 May 2018</b>       |            |          |              |  |                    |                             |                      |                    |                                    |
| <i>No defects recorded</i>  |            |          |              |  |                    |                             |                      |                    |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 May 2018</b>       |            |          |              |  |                    |                             |                      |                    |                                    |
| <i>No defects recorded</i>  |            |          |              |  |                    |                             |                      |                    |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 May 2018</b>       |            |          |              |  |                    |                             |                      |                    |                                    |
| <i>No defects recorded</i>  |            |          |              |  |                    |                             |                      |                    |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 June 2018</b>      |            |          |              |  |                    |                             |                      |                    |                                    |
| <i>No defects recorded</i>  |            |          |              |  |                    |                             |                      |                    |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 June 2018</b>      |            |          |              |  |                    |                             |                      |                    |                                    |
| <i>No defects recorded</i>  |            |          |              |  |                    |                             |                      |                    |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 June 2018</b>      |            |          |              |  |                    |                             |                      |                    |                                    |
| <i>No defects recorded</i>  |            |          |              |  |                    |                             |                      |                    |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 June 2018</b>      |            |          |              |  |                    |                             |                      |                    |                                    |
| <i>No defects recorded</i>  |            |          |              |  |                    |                             |                      |                    |                                    |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018</b>        |            |          |              |  |                    |                             |                      |                    |                                    |
| <i>No defects recorded</i>  |            |          |              |  |                    |                             |                      |                    |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 July 2018</b>      |            |          |              |  |                    |                             |                      |                    |                                    |
| <i>No defects recorded</i>  |            |          |              |  |                    |                             |                      |                    |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 July 2018</b>      |            |          |              |  |                    |                             |                      |                    |                                    |
| <i>No defects recorded</i>  |            |          |              |  |                    |                             |                      |                    |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 July 2018</b>      |            |          |              |  |                    |                             |                      |                    |                                    |
| <i>No defects recorded</i>  |            |          |              |  |                    |                             |                      |                    |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 July 2018</b>      |            |          |              |  |                    |                             |                      |                    |                                    |
| <i>No defects recorded</i>  |            |          |              |  |                    |                             |                      |                    |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 July 2018</b>      |            |          |              |  |                    |                             |                      |                    |                                    |
| <i>No defects recorded</i>  |            |          |              |  |                    |                             |                      |                    |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 August 2018</b>    |            |          |              |  |                    |                             |                      |                    |                                    |
| <i>No defects recorded</i>  |            |          |              |  |                    |                             |                      |                    |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 14 August 2018</b>    |            |          |              |  |                    |                             |                      |                    |                                    |
| <i>No defects recorded</i>  |            |          |              |  |                    |                             |                      |                    |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 21 August 2018</b>    |            |          |              |  |                    |                             |                      |                    |                                    |
| SW80-396340-235971032   | 911m       | 915m     | SAFETY_FENCE | Damaged /<br>deformed -<br>fence / barrier<br>(DAMM) | CAT 1              | 18/09/2018                  | Completed<br>Defects | 14/09/2018         | A77 900M NORTH OF<br>BANKFIELD RBT |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 28 August 2018</b>    |            |          |              |  |                    |                             |                      |                    |                                    |
| <i>No defects recorded</i>  |            |          |              |  |                    |                             |                      |                    |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 September 2018</b> |            |          |              |  |                    |                             |                      |                    |                                    |
| <i>No defects recorded</i>  |            |          |              |  |                    |                             |                      |                    |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 September 2018</b> |            |          |              |  |                    |                             |                      |                    |                                    |
| <i>No defects recorded</i>  |            |          |              |  |                    |                             |                      |                    |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 September 2018</b> |            |          |              |  |                    |                             |                      |                    |                                    |
| <i>No defects recorded</i>  |            |          |              |  |                    |                             |                      |                    |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 25 September 2018</b> |            |          |              |  |                    |                             |                      |                    |                                    |
| <i>No defects recorded</i>  |            |          |              |  |                    |                             |                      |                    |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 October 2018</b>   |            |          |              |  |                    |                             |                      |                    |                                    |
| <i>No defects recorded</i>  |            |          |              |  |                    |                             |                      |                    |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 October 2018</b>   |            |          |              |  |                    |                             |                      |                    |                                    |
| <i>No defects recorded</i>  |            |          |              |  |                    |                             |                      |                    |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 October 2018</b>   |            |          |              |  |                    |                             |                      |                    |                                    |
| <i>No defects recorded</i>  |            |          |              |  |                    |                             |                      |                    |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 October 2018</b>   |            |          |              |  |                    |                             |                      |                    |                                    |
| <i>No defects recorded</i>  |            |          |              |  |                    |                             |                      |                    |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 October 2018</b>   |            |          |              |  |                    |                             |                      |                    |                                    |
| <i>No defects recorded</i>  |            |          |              |  |                    |                             |                      |                    |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 November 2018</b>  |            |          |              |  |                    |                             |                      |                    |                                    |
| <i>No defects recorded</i>  |            |          |              |  |                    |                             |                      |                    |                                    |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 November 2018</b>  |            |          |              |  |                    |                             |                      |                    |                                    |
| <i>No defects recorded</i>  |            |          |              |  |                    |                             |                      |                    |                                    |

| Defect Reference   | Start m | End m  | Item Type     | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description |
|--|---------|--------|---------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|----------------------|
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018</b>   |         |        |               |                                      |                 |                          |                       |                 |                      |
| SW82332070-10  | 254m    | 254m   | TRAFFIC_SIGNS | Physical condition of post (COPT)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-13  | 458m    | 458m   | TRAFFIC_SIGNS | Physical condition of post (COPT)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-6   | 8m      | 18m    | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-11  | 323m    | 343m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-12  | 354m    | 374m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-8   | 132m    | 152m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-7   | 101m    | 121m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-9   | 162m    | 182m   | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| SW82332070-14  | 1,030m  | 1,050m | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 November 2018</b> |         |        |               |                                      |                 |                          |                       |                 |                      |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 November 2018</b> |         |        |               |                                      |                 |                          |                       |                 |                      |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 December 2018</b> |         |        |               |                                      |                 |                          |                       |                 |                      |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 December 2018</b> |         |        |               |                                      |                 |                          |                       |                 |                      |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 December 2018</b> |         |        |               |                                      |                 |                          |                       |                 |                      |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 December 2018</b> |         |        |               |                                      |                 |                          |                       |                 |                      |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 December 2018</b> |         |        |               |                                      |                 |                          |                       |                 |                      |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 January 2019</b>  |         |        |               |                                      |                 |                          |                       |                 |                      |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 January 2019</b>  |         |        |               |                                      |                 |                          |                       |                 |                      |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 January 2019</b>  |         |        |               |                                      |                 |                          |                       |                 |                      |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 January 2019</b>  |         |        |               |                                      |                 |                          |                       |                 |                      |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 January 2019</b>  |         |        |               |                                      |                 |                          |                       |                 |                      |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 February 2019</b> |         |        |               |                                      |                 |                          |                       |                 |                      |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 February 2019</b> |         |        |               |                                      |                 |                          |                       |                 |                      |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 February 2019</b> |         |        |               |                                      |                 |                          |                       |                 |                      |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 February 2019</b> |         |        |               |                                      |                 |                          |                       |                 |                      |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 March 2019</b>    |         |        |               |                                      |                 |                          |                       |                 |                      |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 March 2019</b>    |         |        |               |                                      |                 |                          |                       |                 |                      |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 March 2019</b>    |         |        |               |                                      |                 |                          |                       |                 |                      |
| No defects recorded  |         |        |               |                                      |                 |                          |                       |                 |                      |

| Defect Reference | Start<br>m | End<br>m | Item Type | Item Detail | Defect<br>Category | Required<br>Completion Date | Current Status | Completion<br>Date | Location Description |
|------------------|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|
|------------------|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|

**Safety Inspection of A76 & A77 Ayr North V1 on 26 March 2019**  
*No defects recorded*

**11638/60 : End of Climbing Lane to Start of 4 Lane Single**

**Safety Inspection of A76 & A77 Ayr North V1 on 02 January 2018**  
*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 09 January 2018**  
*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 16 January 2018**  
*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 23 January 2018**  
*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 30 January 2018**  
*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 06 February 2018**  
*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 13 February 2018**  
*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 20 February 2018**  
*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 27 February 2018**  
*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 06 March 2018**  
*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 13 March 2018**  
*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 20 March 2018**  
*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 27 March 2018**  
*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 03 April 2018**  
*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 10 April 2018**  
*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 17 April 2018**  
*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 24 April 2018**  
*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 01 May 2018**  
*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 08 May 2018**  
*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 15 May 2018**  
*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 22 May 2018**  
*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 29 May 2018**  
*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 05 June 2018**  
*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 12 June 2018**  
*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 19 June 2018**  
*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 26 June 2018**  
*No defects recorded*

**Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018**  
*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 03 July 2018**  
*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 10 July 2018**  
*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 17 July 2018**  
*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 24 July 2018**  
*No defects recorded*

**Safety Inspection of A76 & A77 Ayr North V1 on 31 July 2018**

| Defect Reference  | Start m | End m | Item Type     | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description  |
|---|---------|-------|---------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|---|
| <i>No defects recorded</i>  |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 August 2018</b>    |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 14 August 2018</b>    |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 21 August 2018</b>    |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 28 August 2018</b>    |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 September 2018</b> |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 September 2018</b> |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 September 2018</b> |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 25 September 2018</b> |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 October 2018</b>   |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 October 2018</b>   |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 October 2018</b>   |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 October 2018</b>   |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 October 2018</b>   |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 November 2018</b>  |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 November 2018</b>  |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018</b>    |         |       |               |                                      |                 |                          |                       |                 |   |
| SW82332070-16   | 253m    | 254m  | TRAFFIC_SIGNS | Physical condition of post (COPT)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332070-18   | 280m    | 290m  | FILTER_DRAIN  | Weed growth (WEED)                   | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332070-20   | 366m    | 366m  | TRAFFIC_SIGNS | Physical condition of post (COPT)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332070-15   | 215m    | 215m  | TRAFFIC_SIGNS | Physical condition of post (COPT)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332070-17   | 266m    | 306m  | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| SW82332070-19   | 341m    | 441m  | CARRIAGEWAY   | Opening of longitudinal joint (OLJT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 November 2018</b>  |         |       |               |                                      |                 |                          |                       |                 |   |
| SW82426735-236231061  | 142m    | 143m  | TRAFFIC_SIGNS | Accident damage (ACCD)               | CAT 1           | 18/12/2018               | Completed Defects     | 20/11/2018      | A77 SB CW OPPOSITE LAYBY BETWEEN HOLMSTON RBT AND BANKFIELD RBT |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 November 2018</b>  |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 December 2018</b>  |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 December 2018</b>  |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 December 2018</b>  |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 December 2018</b>  |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                      |                 |                          |                       |                 |   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 December 2018</b>  |         |       |               |                                      |                 |                          |                       |                 |   |
| <i>No defects recorded</i>  |         |       |               |                                      |                 |                          |                       |                 |   |

| Defect Reference   | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|--|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 January 2019</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 January 2019</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 January 2019</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 January 2019</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 January 2019</b>  |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 February 2019</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 February 2019</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 February 2019</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 February 2019</b> |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 March 2019</b>    |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 March 2019</b>    |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 March 2019</b>    |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 March 2019</b>    |         |       |           |             |                 |                          |                |                 |                      |
| <i>No defects recorded</i>   |         |       |           |             |                 |                          |                |                 |                      |

**11638/80 : Start of Single 4-Lane to Holmston Roundabout**

|  |  |  |  |  |  |  |  |  |  |
|--|--|--|--|--|--|--|--|--|--|
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 January 2018</b>  |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 January 2018</b>  |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 January 2018</b>  |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 January 2018</b>  |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 January 2018</b>  |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 February 2018</b> |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 February 2018</b> |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 February 2018</b> |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 February 2018</b> |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 March 2018</b>    |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 March 2018</b>    |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 March 2018</b>    |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 March 2018</b>    |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 April 2018</b>    |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 April 2018</b>    |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 April 2018</b>    |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 April 2018</b>    |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 01 May 2018</b>      |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 May 2018</b>      |  |  |  |  |  |  |  |  |  |
| <i>No defects recorded</i>   |  |  |  |  |  |  |  |  |  |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 May 2018</b>      |  |  |  |  |  |  |  |  |  |

| Defect Reference  | Start<br>m | End<br>m | Item Type     | Item Detail                          | Defect<br>Category | Required<br>Completion Date | Current Status        | Completion<br>Date | Location Description |
|---|------------|----------|---------------|--------------------------------------|--------------------|-----------------------------|-----------------------|--------------------|----------------------|
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 May 2018</b>       |            |          |               |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 May 2018</b>       |            |          |               |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 June 2018</b>      |            |          |               |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 June 2018</b>      |            |          |               |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 June 2018</b>      |            |          |               |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 June 2018</b>      |            |          |               |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 20 June 2018</b>        |            |          |               |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 03 July 2018</b>      |            |          |               |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 10 July 2018</b>      |            |          |               |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 17 July 2018</b>      |            |          |               |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 July 2018</b>      |            |          |               |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 July 2018</b>      |            |          |               |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 August 2018</b>    |            |          |               |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 14 August 2018</b>    |            |          |               |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 21 August 2018</b>    |            |          |               |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 28 August 2018</b>    |            |          |               |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 September 2018</b> |            |          |               |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 September 2018</b> |            |          |               |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 September 2018</b> |            |          |               |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 25 September 2018</b> |            |          |               |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 02 October 2018</b>   |            |          |               |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 09 October 2018</b>   |            |          |               |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 16 October 2018</b>   |            |          |               |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 23 October 2018</b>   |            |          |               |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 30 October 2018</b>   |            |          |               |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 06 November 2018</b>  |            |          |               |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |                      |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 13 November 2018</b>  |            |          |               |                                      |                    |                             |                       |                    |                      |
| <i>No defects recorded</i>  |            |          |               |                                      |                    |                             |                       |                    |                      |
| <b>Detailed Inspection TEMPLATE of A77 Ayr N Det on 17 November 2018</b>    |            |          |               |                                      |                    |                             |                       |                    |                      |
| SW82332070-21   | 7m         | 47m      | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-23   | 85m        | 86m      | TRAFFIC_SIGNS | Physical condition of post (COPT)    | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |
| SW82332070-25   | 137m       | 157m     | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2              | 01/01/9999                  | Cat 2 Awaiting Action | 01/01/9999         |                      |

| Defect Reference   | Start m | End m | Item Type     | Item Detail                          | Defect Category | Required Completion Date | Current Status        | Completion Date | Location Description              |
|--|---------|-------|---------------|--------------------------------------|-----------------|--------------------------|-----------------------|-----------------|-----------------------------------|
| SW82332070-24  | 120m    | 140m  | CARRIAGEWAY   | Bituminous surfacing fretting (BFRT) | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                   |
| SW82332070-26  | 181m    | 191m  | CARRIAGEWAY   | Single crack (CRCK)                  | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                   |
| SW82332070-22  | 65m     | 65m   | TRAFFIC_SIGNS | Physical condition of post (COPT)    | CAT 2           | 01/01/9999               | Cat 2 Awaiting Action | 01/01/9999      |                                   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 20 November 2018</b> |         |       |               |                                      |                 |                          |                       |                 |                                   |
| SW82426735-236231062   | 51m     | 52m   | TRAFFIC_SIGNS | Exposed wiring (EXPW)                | CAT 1           | 18/12/2018               | Completed Defects     | 12/03/2019      | A77 SB CW 110M AFTER HOLMSTON RBT |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 27 November 2018</b> |         |       |               |                                      |                 |                          |                       |                 |                                   |
| No defects recorded  |         |       |               |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 04 December 2018</b> |         |       |               |                                      |                 |                          |                       |                 |                                   |
| No defects recorded  |         |       |               |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 11 December 2018</b> |         |       |               |                                      |                 |                          |                       |                 |                                   |
| No defects recorded  |         |       |               |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 18 December 2018</b> |         |       |               |                                      |                 |                          |                       |                 |                                   |
| No defects recorded  |         |       |               |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 24 December 2018</b> |         |       |               |                                      |                 |                          |                       |                 |                                   |
| No defects recorded  |         |       |               |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 31 December 2018</b> |         |       |               |                                      |                 |                          |                       |                 |                                   |
| No defects recorded  |         |       |               |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 07 January 2019</b>  |         |       |               |                                      |                 |                          |                       |                 |                                   |
| No defects recorded  |         |       |               |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 08 January 2019</b>  |         |       |               |                                      |                 |                          |                       |                 |                                   |
| No defects recorded  |         |       |               |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 15 January 2019</b>  |         |       |               |                                      |                 |                          |                       |                 |                                   |
| No defects recorded  |         |       |               |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 22 January 2019</b>  |         |       |               |                                      |                 |                          |                       |                 |                                   |
| No defects recorded  |         |       |               |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 29 January 2019</b>  |         |       |               |                                      |                 |                          |                       |                 |                                   |
| No defects recorded  |         |       |               |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 February 2019</b> |         |       |               |                                      |                 |                          |                       |                 |                                   |
| No defects recorded  |         |       |               |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 February 2019</b> |         |       |               |                                      |                 |                          |                       |                 |                                   |
| No defects recorded  |         |       |               |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 February 2019</b> |         |       |               |                                      |                 |                          |                       |                 |                                   |
| No defects recorded  |         |       |               |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 February 2019</b> |         |       |               |                                      |                 |                          |                       |                 |                                   |
| No defects recorded  |         |       |               |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 05 March 2019</b>    |         |       |               |                                      |                 |                          |                       |                 |                                   |
| No defects recorded  |         |       |               |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 12 March 2019</b>    |         |       |               |                                      |                 |                          |                       |                 |                                   |
| No defects recorded  |         |       |               |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 19 March 2019</b>    |         |       |               |                                      |                 |                          |                       |                 |                                   |
| No defects recorded  |         |       |               |                                      |                 |                          |                       |                 |                                   |
| <b>Safety Inspection of A76 &amp; A77 Ayr North V1 on 26 March 2019</b>    |         |       |               |                                      |                 |                          |                       |                 |                                   |
| No defects recorded  |         |       |               |                                      |                 |                          |                       |                 |                                   |