

Communication Logs:

Log Type

Details

Log Type:
Note

Description:
Nearside lane closure for CAT1 dark lamp repairs


Draft Media Release (optional):

A77 Symington to Bogend toll n/b

Roadwork Identifier: SW/2019/7615

Route:

 Start: A77 (55.54192°, -4.56510°)

 End: A77 (55.56121°, -4.54029°)

Direction:

Northbound

SRWR Reference Number:

2574339 2574321 2574317

Diversion:

No Diversion

Estimated Delay:

1 - Little or No Delay, 3 - Off Peak Hours

Works Periods:

| Work Start | Work End | Traffic Management |
|------------------|------------------|--------------------|
| 29/01/2019 09:30 | 29/01/2019 15:30 | Lane Closure |

Works Activities:

| Works Activity Type | Contractors | Statuses |
|---------------------|---|-------------------|
| Lighting Works | Scotland TranServ (Primary)  | 1 of 1 Completed. |

Communication Logs:

Log Type

Details

Log Type:
Note

Description:
Nearside lane closure for dark lamp repairs.

Draft Media Release (optional):

A77 Symington n/b off slip

Roadwork Identifier: SW/2019/7616

Route:

 Start: A77 (55.54354°, -4.56287°)

 End: A77 (55.54394°, -4.56297°)

Direction:
Northbound

SRWR Reference Number:
2574339 2574321 2574317

Diversion:
Continue N/B on A77 - Off A77 Bellfield off slip - Return A77 S/B follow signs

Estimated Delay:
1 - Little or No Delay, 3 - Off Peak Hours

Works Periods:

| Work Start | Work End | Traffic Management |
|------------------|------------------|--------------------|
| 29/01/2019 09:30 | 29/01/2019 15:30 | Road Closure |

Works Activities:

| Works Activity Type | Contractors | Statuses |
|---------------------|--|-------------------|
| Lighting Works | Scotland TransServ (Primary)  | 1 of 1 Completed. |

Communication Logs:



| Log Type | Details |
|----------|--|
| Note | Description: Progressive slip road closure for Lighting works |

Draft Media Release (optional):

A77 Symington n/b on slip

Roadwork Identifier: SW/2019/7617

Route:

-  **Start:** A77 (55.54424°, -4.56347°)
-  **End:** A77 (55.54397°, -4.56216°)

Direction:
Northbound

SRWR Reference Number:
2574339 2574321 2574317


Diversion:
Join A77 S/B - Continue A77 S/B - A77 Dutchhouse - Return A77 N/B follow directions

Estimated Delay:
1 - Little or No Delay, 3 - Off Peak Hours

Works Periods:

| Work Start | Work End | Traffic Management |
|------------------|------------------|--------------------|
| 29/01/2019 09:30 | 29/01/2019 15:30 | Road Closure |

Works Activities:

| Works Activity Type | Contractors | Statuses |
|--|---|-------------------|
| Lighting Works | Scotland TranServ (Primary)  | 1 of 1 Completed. |
| Communication Logs: | | |
| Log Type | Details | |
| Log Type: | Description: | |
| Note | Progressive slip road closure for cat1 lighting works | |
| Draft Media Release (optional): | | |

Roadwork: SW/2019/7918


Operating Company Contract:

South West Unit - Transerv

A77 Spitalhill to Bellfield

Roadwork Identifier: SW/2019/7918

Route:

 Start: A77 - E. Ayrshire Bdy to 300m N Whattriggs Br (55.57939°, -4.49255°)

 End: A77 - 300m N Whattriggs Br to Nb Slip Road Exit To A76/A71 (55.59248°, -4.47967°)

Direction:

Northbound

SRWR Reference Number:

2588732

Diversion:

No Diversion

Estimated Delay:

1 - Little or No Delay, 3 - Off Peak Hours

Works Periods:

| Work Start | Work End | Traffic Management |
|------------------|------------------|--------------------|
| 28/02/2019 09:30 | 28/02/2019 15:30 | Lane Closure |

Works Activities:

| Works Activity Type | Contractors | Statuses |
|------------------------|---|-------------------|
| Gully/ironwork repairs | Scotland TranServ (Primary)  | 1 of 1 Completed. |

Communication Logs:

| Log Type | Details |
|-------------------|--|
| Log Type: Note | Description: nearside lane closure on A77 northbound at Craigie Rd overbridge |

Draft Media Release (optional):

Roadwork: SW/2019/8334

Operating Company Contract:

South West Unit - Transerv

A77 Bellfield to Spittalhill

Roadwork Identifier: SW/2019/8334

Route:

 Start: A77 - Sb Slip Exit to Hurlford Int Rbt (55.59873°, -4.47521°)

 End: A77 - East Ayrshire Bdy to Spitalhill Slip Rd (55.57037°, -4.52434°)

Direction:

Southbound

SRWR Reference Number:

2602151

Diversion:

A71 - A78 - End

Estimated Delay:

1 - Little or No Delay, 3 - Off Peak Hours

Works Periods:

| Work Start | Work End | Traffic Management |
|------------------|------------------|--------------------|
| 19/03/2019 20:00 | 20/03/2019 06:00 | Road Closure |

Works Activities:

| Works Activity Type | Contractors | Statuses |
|----------------------|---|-------------------|
| Carriageway Patching | Scotland TranServ (Primary)  | 2 of 2 Completed. |

Communication Logs:

| Log Type | Details |
|-------------------|---|
| Log Type: Note | Description: total closure of A77 Bellfield to Spittalhill |

Draft Media Release (optional):

Roadworks: SW/2019/8550, SW/2019/8551, SW/2019/8556, SW/2019/8557 ... SW/2019/8591

Operating Company Contract:

South West Unit - Transerv

A77 Fenwick

Roadwork Identifier: SW/2019/8550

Route:

 **Start: M77** (55.66628°, -4.44540°)

 **End: M77** (55.66323°, -4.44690°)

Direction:

Southbound

SRWR Reference Number:

2605672

Diversion:

No Diversion

Estimated Delay:

1 - Little or No Delay, 3 - Off Peak Hours

Emergency Reason:

Late Programmed Works

Works Periods:

| Work Start | Work End | Traffic Management |
|------------------|------------------|--------------------------------|
| 23/03/2019 09:30 | 25/03/2019 05:00 | Portable Traffic Lights (TTLS) |

Works Activities:

| Works Activity Type | Contractors | Statuses |
|---------------------|--|-------------------|
| Traffic Loops | Amey (Primary)  Lochwynd (Secondary)  | 5 of 5 Completed. |

Communication Logs:

| Log Type | Details |
|----------|---------|
|----------|---------|


There are no communications logs to display.

Draft Media Release (optional):

A738 Kilwinning - Stevenston Road

Roadwork Identifier: SW/2019/8551

Route:

 **Start: A738** (55.64767°, -4.73097°)

 **End: A738** (55.64778°, -4.73087°)

Direction:

Eastbound

SRWR Reference Number:

2605610

Diversion:

No Diversion

Estimated Delay:

1 - Little or No Delay, 3 - Off Peak Hours

Emergency Reason:

Late Programmed Works

Works Periods:

| Work Start | Work End | Traffic Management |
|------------------|------------------|--------------------------------|
| 24/03/2019 09:30 | 27/03/2019 05:00 | Portable Traffic Lights (TTLS) |

Works Activities:

| Works Activity Type | Contractors | Statuses |
|---------------------|--|-------------------|
| Traffic Loops | Amey (Primary)  Lochwynd (Secondary)  | 9 of 9 Completed. |

Communication Logs:

| Log Type | Details |
|--|---------|
| There are no communications logs to display. | |

Draft Media Release (optional):

A738 Kilwinning - Stevenston Road

Roadwork Identifier: SW/2019/8556

Route:

 **Start:** A738 (55.65305°, -4.71510°)

 **End:** A738 (55.65297°, -4.71514°)

Direction:

Eastbound

SRWR Reference Number:

2605618

Diversion:

No Diversion

Estimated Delay:

1 - Little or No Delay, 3 - Off Peak Hours

Emergency Reason:

Late Programmed Works

Works Periods:

| Work Start | Work End | Traffic Management |
|------------|----------|--------------------|
|------------|----------|--------------------|

| Work Start | Work End | Traffic Management |
|------------------|------------------|--------------------------------|
| 24/03/2019 09:30 | 26/03/2019 05:00 | Portable Traffic Lights (TTLS) |

Works Activities:

| Works Activity Type | Contractors | Statuses |
|---------------------|--------------------|-------------------|
| Traffic Loops | Amey (Primary) | 6 of 6 Completed. |
| | Lochwynd (Primary) | |

Communication Logs:

| Log Type | Details |
|--|---------|
| There are no communications logs to display. | |

Draft Media Release (optional):

A78 Skelmorlie- 40m south of Shuma Court entrance

Roadwork Identifier: SW/2019/8557

Route:

- Start:** A78 (55.85660°, -4.88971°)
- End:** A78 (55.85672°, -4.88976°)

Direction:
Northbound

SRWR Reference Number:
2605728

Diversion:
No Diversion

Estimated Delay:
1 - Little or No Delay, 3 - Off Peak Hours

Emergency Reason:
Late Programmed Works

Works Periods:

| Work Start | Work End | Traffic Management |
|------------------|------------------|--------------------------------|
| 24/03/2019 09:30 | 26/03/2019 05:00 | Portable Traffic Lights (TTLS) |

Works Activities:

| Works Activity Type | Contractors | Statuses |
|---------------------|----------------------|-------------------|
| Traffic Loops | Amey (Primary) | 6 of 6 Completed. |
| | Lochwynd (Secondary) | |

Communication Logs:


| Log Type | Details |
|--|---------|
| There are no communications logs to display. | |

Draft Media Release (optional):

A77 south of Kilmarnock

Roadwork Identifier: SW/2019/8558

Route:

 **Start:** A77 - E. Ayrshire Bdy to 300m N Whattriggs Br (55.57894°, -4.49466°)

 **End:** A77 - E. Ayrshire Bdy to 300m N Whattriggs Br (55.57919°, -4.49380°)

Direction:

Northbound

SRWR Reference Number:

2605715

Diversion:

No Diversion

Estimated Delay:

1 - Little or No Delay, 3 - Off Peak Hours



Emergency Reason:

Late Programmed Works

Works Periods:

| Work Start | Work End | Traffic Management |
|------------------|------------------|----------------------|
| 26/03/2019 09:30 | 29/03/2019 05:00 | Mobile Lane Closures |

Works Activities:

| Works Activity Type | Contractors | Statuses |
|---------------------|--|-------------------|
| Traffic Loops | Amey (Primary)  Lochwynd (Secondary)  | 9 of 9 Completed. |

Communication Logs:

| Log Type | Details |
|----------|---------|
|----------|---------|

There are no communications logs to display.

Draft Media Release (optional):

A75 West of Gretna

Roadwork Identifier: SW/2019/8589

Route:

 **Start:** A75 (54.99749°, -3.08286°)

 **End:** A75 (54.99903°, -3.07712°)

Direction:

Eastbound

SRWR Reference Number:

2605602

Diversion:

No Diversion

Estimated Delay:

1 - Little or No Delay, 3 - Off Peak Hours

Emergency Reason:

Late Programmed Works

Works Periods:

| Work Start | Work End | Traffic Management |
|------------------|------------------|----------------------|
| 21/03/2019 19:00 | 22/03/2019 05:00 | Mobile Lane Closures |

Works Activities:

| Works Activity Type | Contractors | Statuses |
|---------------------|----------------------|-------------------|
| Traffic Loops | Amey (Primary) | 2 of 2 Completed. |
| | Lochwynd (Secondary) | |

Communication Logs:

| Log Type | Details |
|----------|---------|
|----------|---------|

There are no communications logs to display.

Draft Media Release (optional):

A701 North of B7020 Jct

Roadwork Identifier: SW/2019/8590

Route:

Start: A701 (55.28487°, -3.44476°)

End: A701 (55.28623°, -3.44525°)

Direction:

Northbound

SRWR Reference Number:

2605595

Diversion:

No Diversion

Estimated Delay:

1 - Little or No Delay, 3 - Off Peak Hours

Emergency Reason:

Late Programmed Works

Works Periods:

| Work Start | Work End | Traffic Management |
|------------------|------------------|--------------------------------|
| 21/03/2019 19:00 | 23/03/2019 05:00 | Portable Traffic Lights (TTLS) |

Works Activities:

| Works Activity Type | Contractors | Statuses |
|---------------------|-------------|----------|
|---------------------|-------------|----------|

| Works Activity Type | Contractors | Statuses |
|---------------------|----------------------|-------------------|
| Traffic Loops | Amey (Primary) | 4 of 4 Completed. |
| | Lochwynd (Secondary) | |

Communication Logs:

Log Type Details

There are no communications logs to display.

Draft Media Release (optional):

A75 North of A780 Rbt

Roadwork Identifier: SW/2019/8591

Route:

Start: A75 (55.06936°, -3.55721°)

End: A75 (55.06992°, -3.55740°)

Direction:
Northbound

SRWR Reference Number:
2605632

Diversion:
No Diversion

Estimated Delay:
1 - Little or No Delay, 3 - Off Peak Hours

Emergency Reason:
Late Programmed Works

Works Periods:

| Work Start | Work End | Traffic Management |
|------------------|------------------|--------------------------------|
| 21/03/2019 19:00 | 23/03/2019 05:00 | Portable Traffic Lights (TTLS) |

Works Activities:

| Works Activity Type | Contractors | Statuses |
|---------------------|----------------------|-------------------|
| Traffic Loops | Amey (Primary) | 4 of 4 Completed. |
| | Lochwynd (Secondary) | |

Communication Logs:

Log Type Details

There are no communications logs to display.

Draft Media Release (optional):

Roadworks: SW/2019/9343, SW/2019/9344


Operating Company Contract:

South West Unit - Transerv

A77 South of Bellfield

Roadwork Identifier: SW/2019/9343

Route:

 **Start:** A77 - 300m N Whatriggs Br to East Ayrshire Bdy (55.59144°, -4.47877°)

 **End:** A77 - 300m N Whatriggs Br to East Ayrshire Bdy (55.57603°, -4.50329°)

Direction:

Southbound

SRWR Reference Number:

2631060

Diversion:

No Diversion


Estimated Delay:

1 - Little or No Delay, 3 - Off Peak Hours

Works Periods:

| Work Start | Work End | Traffic Management |
|------------------|------------------|--------------------|
| 17/05/2019 20:00 | 18/05/2019 06:00 | Lane Closure |

Works Activities:

| Works Activity Type | Contractors | Statuses |
|---------------------|---|-------------------|
| Barrier Repair | Scotland TranServ (Primary)  | 2 of 2 Completed. |

Communication Logs:

| Log Type | Details |
|-------------------|---|
| Log Type: Note | Description: A77 900m South of Bellfield C/Res closure |

Draft Media Release (optional):

A77 South of Bellfield

Roadwork Identifier: SW/2019/9344

Route:

 **Start:** A77 (55.57254°, -4.51824°)

 **End:** A77 (55.59107°, -4.47917°)

Direction:

Northbound

SRWR Reference Number:

2631060

Diversion:

No Diversion


Estimated Delay:

1 - Little or No Delay, 3 - Off Peak Hours

Works Periods:

| Work Start | Work End | Traffic Management |
|------------------|------------------|--------------------|
| 17/05/2019 20:00 | 18/05/2019 06:00 | Lane Closure |

Works Activities:

| Works Activity Type | Contractors | Statuses |
|---------------------|---|-------------------|
| Barrier Repair | Scotland TranServ (Primary)  | 2 of 2 Completed. |

Communication Logs:

| Log Type | Details |
|----------|---------|
|----------|---------|

There are no communications logs to display.

Draft Media Release (optional):