

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/05/2017 and 30/05/2019, and defects raised outside of inspections on the same Section(s) during this period.

(Section Code is 17208/15)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
17208/15 : DUBH LIGHE BRIDGE TO GLENFINNAN SIGN									
Safety Inspection of A86 A830 Safety on 04 May 2017									
No defects recorded									
Safety Inspection of A86 A830 Safety on 11 May 2017									
No defects recorded									
Safety Inspection of A86 A830 Safety on 18 May 2017									
No defects recorded									
Safety Inspection of A86 A830 Safety on 25 May 2017									
No defects recorded									
Safety Inspection of A86 A830 Safety on 01 June 2017									
No defects recorded									
Safety Inspection of A86 A830 Safety on 08 June 2017									
No defects recorded									
Safety Inspection of A86 A830 Safety on 15 June 2017									
No defects recorded									
Safety Inspection of A86 A830 Safety on 22 June 2017									
NWG23-280285-235211658	1,621m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 2	20/07/2017	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
Safety Inspection of A86 A830 Safety on 29 June 2017									
No defects recorded									
Safety Inspection of A86 A830 Safety on 06 July 2017									
No defects recorded									
Safety Inspection of A86 A830 Safety on 13 July 2017									
No defects recorded									
Safety Inspection of A86 A830 Safety on 20 July 2017									
No defects recorded									
Safety Inspection of A86 A830 Safety on 27 July 2017									
No defects recorded									
Safety Inspection of A86 A830 Safety on 03 August 2017									
NWG16-282787-235292206	549m	593m	CARRIAGEWAY	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	GRAIGIEG BRIDGE
NWG16-282787-235292205	550m	550m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 1	31/08/2017	Completed Defects	11/08/2017	GRAIGIEG BRIDGE
Safety Inspection of A86 A830 Safety on 10 August 2017									
No defects recorded									
Safety Inspection of A86 A830 Safety on 17 August 2017									
No defects recorded									
Safety Inspection of A86 A830 Safety on 24 August 2017									
No defects recorded									
Safety Inspection of A86 A830 Safety on 31 August 2017									
NWG23-283871-235351499	533m	0m	DITCH	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	CRAIGIE DITCH
NWG23-283871-235351498	626m	0m	DITCH	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	CRAIGIE BRIDGE, WEST
Safety Inspection of A86 A830 Safety on 07 September 2017									
No defects recorded									
Safety Inspection of A86 A830 Safety on 14 September 2017									
No defects recorded									
Safety Inspection of A86 A830 Safety on 21 September 2017									
No defects recorded									
Safety Inspection of A86 A830 Safety on 28 September 2017									
No defects recorded									
Safety Inspection of A86 A830 Safety on 05 October 2017									
No defects recorded									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A86 A830 Safety on 12 October 2017									
NWG23-315304-235427429	1,834m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	13/10/2017	Awaiting CCMS Permanent Date	12/10/2017	W OF GLENFINNAN
Safety Inspection of A86 A830 Safety on 19 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 26 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 02 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 09 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 16 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 23 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 30 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 07 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 14 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 21 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 28 December 2017									
NWG23-317068-235513190	2,799m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/01/2018	Completed Defects	25/01/2018	GLENFINNAN
Safety Inspection of A86 A830 Safety on 04 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 11 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 18 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 25 January 2018									
NWG23-317731-235528828	1,428m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	26/01/2018	Completed Defects	25/01/2018	GLENFINNAN
Safety Inspection of A86 A830 Safety on 01 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 08 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 15 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 22 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 01 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 08 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 15 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 22 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 29 March 2018									
NWG23-330670-235608544	1,570m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	26/04/2018	Completed Defects	09/04/2018	EAST OF GLENFINNAN
Safety Inspection of A86 A830 Safety on 05 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 12 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 18 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 26 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 03 May 2018									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A86 A830 Safety on 10 May 2018									
NW34344798-235690388	1,636m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/05/2018	Completed Defects	10/05/2018	EAST OF GLENFINNAN
NW34344798-235690387	1,659m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 1	07/06/2018	Completed Defects	06/06/2018	EAST OF GLENFINNAN
NW34344798-235690389	1,623m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/05/2018	Completed Defects	10/05/2018	EAST OF GLENFINNAN
Safety Inspection of A86 A830 Safety on 17 May 2018									
NW34347684-235731409	1,420m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
Safety Inspection of A86 A830 Safety on 24 May 2018									
NW35350737-235800687	2,570m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	25/05/2018	Completed Defects	24/05/2018	CAIRN
Safety Inspection of A86 A830 Safety on 31 May 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 07 June 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 14 June 2018									
NW34360540-235830755	1,694m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	15/06/2018	Completed Defects	14/06/2018	EAST OF GLENFINNAN
NW34360540-235830756	1,701m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34360540-235830754	1,698m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	15/06/2018	Completed Defects	14/06/2018	EAST OF GLENFINNAN
NW34360540-235830757	1,710m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34360540-235830753	1,778m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
Safety Inspection of A86 A830 Safety on 20 June 2018									
NW34364648-235853320	873m	0m	TRAFFIC_SIGNS	Physical condition of fittings (COFT)	CAT 1	21/06/2018	Completed Defects	20/06/2018	EAST OF GLENFINNAN
NW34364648-235853310	1,232m	0m	TRAFFIC_SIGNS	Pointing wrong way (RWAY)	CAT 1	21/06/2018	Completed Defects	20/06/2018	EAST OF GLENFINNAN
Safety Inspection of A86 A830 Safety on 27 June 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 04 July 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 11 July 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 18 July 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 25 July 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 01 August 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 08 August 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 15 August 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 22 August 2018									
NW34394971-235970012	1,397m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	23/08/2018	Completed Defects	22/08/2018	1 MILE EAST OF GLENFINNAN

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW34394971-235969995	515m	0m	STRUCTURE	Graffiti - Offensive (OFFS)	CAT 1	19/09/2018	Completed Defects	22/08/2018	CRAIGIEBRIDGE
NW34394971-235970014	1,421m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	23/08/2018	Completed Defects	22/08/2018	1 MILE EAST OF GLENFINNAN
NW34394971-235970011	1,614m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 1	19/09/2018	Completed Defects	17/09/2018	1 MILE EAST OF GLENFINNAN
NW34394971-235970013	1,421m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	23/08/2018	Completed Defects	22/08/2018	1 MILE EAST OF GLENFINNAN
Safety Inspection of A86 A830 Safety on 29 August 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 05 September 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 12 September 2018									
NW34404869-236054215	1,984m	0m	MANHOLE	Collapsed (COLP)	3RD PTY	10/10/2018	Awaiting CCMS Temp Date	01/01/9999	EAST OF GLENFINNAN
NW34404869-236054214	1,622m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34404869-236054213	1,623m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	13/09/2018	Completed Defects	12/09/2018	EAST OF GLENFINNAN
NW34404869-236054218	1,784m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	CRAIGAG COTTAGE
Safety Inspection of A86 A830 Safety on 19 September 2018									
NW34408058-236060198	507m	0m	VERGE	Fly tipping/illegal dumping (FTIP)	3RD PTY	17/10/2018	Awaiting CCMS Temp Date	01/01/9999	CRAIGIEBRIDGE
NW34408058-236060197	873m	0m	TRAFFIC_SIGNS	Physical condition of fittings (COFT)	CAT 1	20/09/2018	Completed Defects	19/09/2018	CRAIGAG
Safety Inspection of A86 A830 Safety on 26 September 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 03 October 2018									
NW38414543-236101540	1,420m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/10/2018	Completed Defects	03/10/2018	CRAIGAG LODGE
Safety Inspection of A86 A830 Safety on 10 October 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 17 October 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 24 October 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 31 October 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 07 November 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 14 November 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 21 November 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 28 November 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 05 December 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 12 December 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 19 December 2018									
No defects recorded									
Safety Inspection of A830,A82 Safety inspection short on 21 December 2018									
No defects recorded									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A830,A82 Safety inspection short on 28 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 04 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 10 January 2019									
NW34428008-236271126	495m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 1	11/01/2019	Completed Defects	10/01/2019	CRAIGIEBRIDGE
NW34428008-236271124	1,428m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/01/2019	Completed Defects	10/01/2019	GLENFINNAN
NW34428008-236271121	1,607m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/01/2019	Completed Defects	10/01/2019	GLENFINNAN
NW34428008-236271125	1,419m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/01/2019	Completed Defects	10/01/2019	GLENFINNAN
Safety Inspection of A830,A82 Safety inspection short on 17 January 2019									
NW34428196-236276059	1,430m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/01/2019	Completed Defects	17/01/2019	GLENFINNAN
NW34428196-236276058	1,457m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/01/2019	Completed Defects	17/01/2019	GLENFINNAN
NW34428196-236276060	1,515m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/01/2019	Completed Defects	17/01/2019	GLENFINNAN
Safety Inspection of A830,A82 Safety inspection short on 24 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 31 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 07 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 14 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 20 February 2019									
NW34432281-236330981	1,664m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	21/02/2019	Completed Defects	20/02/2019	CRAIGAG LODGE
Safety Inspection of A830,A82 Safety inspection short on 27 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 06 March 2019									
NW34440020-236341781	1,657m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	07/03/2019	Completed Defects	06/03/2019	CRAIGAG LODGE
Safety Inspection of A830,A82 Safety inspection short on 13 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 20 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 27 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 03 April 2019									
NW35466196-236493950	1,627m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN E/B
NW35466196-236493943	1,712m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 1	01/05/2019	Completed Defects	22/04/2019	EAST OF GLENFINNAN E/B
NW35466196-236493946	1,686m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN E/B
NW35466196-236493948	1,660m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN E/B

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW35466196-236493944	1,696m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/05/2019	Completed Defects	22/04/2019	EAST OF GLENFINNAN E/B
NW35466196-236493945	1,703m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN E/B
NW35466196-236493947	1,660m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/05/2019	Completed Defects	22/04/2019	EAST OF GLENFINNAN W/B
NW35466196-236493949	1,622m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/05/2019	Completed Defects	22/04/2019	EAST OF GLENFINNAN W/B
Safety Inspection of A830,A82 Safety inspection short on 10 April 2019									
NW34474665-236531691	1,424m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/05/2019	Completed Defects	29/04/2019	EAST OF GLENFINNAN W/B
Safety Inspection of A830,A82 Safety inspection short on 17 April 2019									
No defects recorded									
Safety Inspection of A830,A82 Safety inspection short on 24 April 2019									
No defects recorded									
Safety Inspection of A830,A82 Safety inspection short on 01 May 2019									
No defects recorded									
Safety Inspection of A830,A82 Safety inspection short on 08 May 2019									
No defects recorded									
Safety Inspection of A830,A82 Safety inspection short on 15 May 2019									
No defects recorded									
Safety Inspection of A830,A82 Safety inspection short on 22 May 2019									
No defects recorded									
Safety Inspection of A830,A82 Safety inspection short on 29 May 2019									
NW34514366-236805978	1,695m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 1	26/06/2019	Awaiting CCMS Permanent Date	01/01/9999	EAST OF GLENFINNAN
NW34514366-236805981	1,420m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	26/06/2019	Awaiting CCMS Permanent Date	01/01/9999	EAST OF GLENFINNAN
NW34514366-236805982	1,258m	0m	VERGE	Dead, dying or damaged areas (DPDY)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34514366-236805974	1,594m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	26/06/2019	Awaiting CCMS Permanent Date	01/01/9999	EAST OF GLENFINNAN
NW34514366-236805976	1,713m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	26/06/2019	Awaiting CCMS Permanent Date	01/01/9999	EAST OF GLENFINNAN
NW34514366-236805980	1,503m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	30/05/2019	Completed Defects	29/05/2019	EAST OF GLENFINNAN
NW34514366-236805979	1,661m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	30/05/2019	Completed Defects	29/05/2019	EAST OF GLENFINNAN
NW34514366-236805977	1,705m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34514366-236805975	1,576m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	30/05/2019	Completed Defects	29/05/2019	EAST OF GLENFINNAN
NW34514366-236805973	1,604m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	26/06/2019	Awaiting CCMS Permanent Date	01/01/9999	EAST OF GLEN FINNAN