

# Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/01/2014 and 06/08/2019, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'WITH: WB ON SLIP JCT 10 TO WB OFF SLIP JCT 11',) Or

(Section is 'Against: EB on Slip Jct 11 to Jct 10 Off Slip',) Or

(Section is 'WITH: WB OFF SLIP JCT 11 TO WB ON SLIP JCT 11',) Or

(Section is 'AGAINST: JCT 11 EB OFF SLIP TO ENTRY SLIP',) Or

(Section is 'AGAINST: EB M8 JCT 12 OFF SLIP TO JCT 11 ON SLIP',) Or

(Section is 'WITH: WB JCT 11 ON SLIP TO JCT 12 OFF SLIP',) Or

(Section is 'AGAINST: EB JCT 14 OFF SLIP TO OFF SLIP TO M80',) Or

(Section is 'WITH: ON SLIP FROM M80 TO OFF SLIP JCT 14',) Or

(Section is 'WITH: WB M8 JCT 14 ON SLIP TO JCT 15 OFF SLIP',) Or

(Section is 'AGAINST: EB M8 JCT 15 ENTRY TO JCT 14 OFF SLIP',) Or

(Section is 'WITH: JCT 15 OFF SLIP TO M8 OBRIDGE',) Or

(Section is 'AGAINST: EB JCT 15 OFF SLIP TO ENTRY SLIP',) Or

(Section is 'With: EB On Slip to A803',) Or

(Section is 'AGAINST: EB JCT 15 OFF SLIP TO ENTRY SLIP',) Or

(Section is 'AGAINST: JCT 16 ON SLIP TO JCT 15 OFF SLIP',) Or

(Section is 'WITH: M8 OBRIDGE TO SLIP ON TO M8 WB',) Or

(Section is 'WITH: JCT 16 OFF SLIP TO CRAIGHALL RD',) Or

(Section is 'AGAINST: JCT 16 CRAIGHALL RD TO ENTRY M8 EB',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	---------	-------	-----------	-------------	-----------------	--------------------------	----------------	-----------------	----------------------

## 14210/29 : WITH: WB ON SLIP JCT 10 TO WB OFF SLIP JCT 11

Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014

Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014

Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014

Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014

Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014

Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014

SW8670461-64	222m	222m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-67	573m	573m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-61	170m	170m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-63	208m	208m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-68	606m	606m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	

SW8670461-70	767m	767m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8370461-129	964m	964m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 1	16/01/2015	Completed Defects	01/01/2016	
SW8370461-131	1,039m	1,039m	SAFETY_FENCE	Corroded - metal (fence / barrier)	CAT 1	16/01/2015	Completed Defects	01/01/2016	CLEARANCE FROM LC NOT TO SPEC
SW8370461-127	810m	810m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 1	12/02/2015	Completed Defects	01/01/2016	
SW8670461-62	189m	189m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-69	616m	616m	SAFETY_FENCE	Corroded - metal (fence / barrier)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-65	348m	384m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	11/12/2015	
SW8670461-66	386m	386m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	

**Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014**  
**Detailed Inspection TEMPLATE of M8E Detail SW on 21 May 2015**  
**Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015**  
**Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016**  
**Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016**

**Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016**

SW83-143364-123	232m	232m	SAFETY_FENCE	Corroded - metal (fence / barrier)	CAT 1	28/03/2017	Completed Defects	19/10/2017	M8 WB AT END OF 10 ON,AT GANTRY
SW83-143364-3	568m	568m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 W/B JCT 10 TO 11,ADJ EB GANTRY 04130,WB GANTRY HAS BEEN REMOVED
SW83-143364-124	459m	459m	SAFETY_FENCE	Corroded - metal (fence / barrier)	CAT 1	28/03/2017	Awaiting CCMS Permanent	01/01/9999	M8 WB 10 TO 11 AT M8 DIRECTIONAL SIGN
SW83-143364-2	351m	351m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB JCT 10 TO 11,BLUE M8 MILEAGE SIGN
SW83-143364-125	600m	600m	SAFETY_FENCE	Corroded - metal (fence / barrier)	CAT 1	28/03/2017	Awaiting CCMS Permanent	01/01/9999	M8 WB 10 TO 11 @ GANTRY 04130
SW83-143364-4	774m	774m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB JCT 10 TO 11,200 YDS MARKER FOR JCT 11
SW83-143364-1	171m	171m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB JCT 10 ON TO 1ST GANTRY

**Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017**  
**Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017**

**Detailed Inspection TEMPLATE of M8E Detail SW on 08 June 2018**  
**Detailed Inspection TEMPLATE of M8E Detail SW on 26 September 2018**  
**Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW ( Awaiting Return )**  
**Detailed Inspection TEMPLATE of M8E Detail SW on 07 June 2019**

**14215/05 : WITH: WB OFF SLIP JCT 11 TO WB ON SLIP JCT 11**

**Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014**  
**Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014**  
**Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014**

Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014  
 Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014

SW8670461-78	280m	280m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8370461-134	358m	358m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 1	16/01/2015	Completed Defects	01/01/2016	CLEARANCE FROM LC AND OVER BRIDGES NOT TO SPEC
SW8370461-137	669m	669m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 1	16/01/2015	Completed Defects	01/01/2016	CLEARANCE FRM ALL CL AND OVERBRIDGES AND GANTRY NOT TO SPEC
SW8370461-133	224m	224m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 1	16/01/2015	Completed Defects	01/01/2016	ALL LIGTNG COLUMNS NOT TO SPEC
SW8370461-136	516m	516m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 1	16/01/2015	Completed Defects	01/01/2016	CLEARANCE FRM ALL LC AND OVERBRIDGES NOT TO SPEC
SW8670461-76	350m	350m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	

Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 21 May 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016  
 Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016  
 Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016

SW83-143364-129	345m	345m	SAFETY_FENCE	Corroded - metal (fence / barrier)	CAT 1	28/03/2017	Awaiting CCMS Permanent	01/01/9999	AT OVERBRIDGE
SW83-143364-7	157m	157m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB JCT 11 OFF
SW83-143364-8	281m	281m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB JCT 11 OFF TO ON

Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 26 September 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 June 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 June 2019

**14215/06 : AGAINST:JCT 11 EB OFF SLIP TO ENTRY SLIP**

Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014  
 Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014

SW8670461-51	392m	292m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8370461-135	274m	274m	SAFETY_FENCE	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Archive	20/10/2015	
SW8370461-138	42m	42m	SAFETY_FENCE	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-50	194m	194m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	

Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015

Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016  
 Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016  
 Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016

SW83-143364-112	193m	193m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB BETWEEN 11 OFF AND ON
SW83-143364-113	379m	379m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB 11 ON

Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 26 September 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 June 2019

**14215/39 : WITH: WB JCT 11 ON SLIP TO JCT 12 OFF SLIP**

Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014

Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014

SW8670461-87	798m	798m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8370461-143	402m	402m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 1	16/01/2015	Completed Defects	01/01/2016	
SW8670461-85	687m	687m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8370461-146	769m	769m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 1	16/01/2015	Completed Defects	01/01/2016	
SW8670461-80	278m	278m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-84	666m	666m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-86	686m	686m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 1	10/12/2014	Completed Defects	02/02/2016	
SW8670461-88	864m	864m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-81	364m	364m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-82	435m	435m	SAFETY_FENCE	Loose bolt (LOSB)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-89	926m	926m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-79	155m	166m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-83	509m	509m	SAFETY_FENCE	Corroded - metal (fence / barrier)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8370461-142	385m	0m	SAFETY_FENCE	Other (OTHR)	CAT 1	16/01/2015	Completed Defects	01/01/2016	

Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014

Detailed Inspection TEMPLATE of M8E Detail SW on 21 May 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016

Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016  
 Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016

SW83-143364-11	168m	168m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB JCT 11 ON AT BOTTOM
SW83-143364-133	165m	165m	SAFETY_FENCE	Corroded - metal (fence / barrier)	CAT 1	29/03/2017	Awaiting CCMS Permanent	01/01/9999	
SW83-143364-10	158m	158m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB JCT 11 ON @ 1&1S
SW83-143364-12	183m	183m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB AT VERY BOTTOM OF JCT 11 ON N/S
SW83-143364-135	917m	917m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	AT GANTRY 04910
SW83-143364-13	806m	806m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB 400 YDS TO 12 OFF SLIP

Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 26 September 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 June 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 June 2019

**14215/40 : AGAINST: EB M8 JCT 12 OFF SLIP TO JCT 11 ON SLIP**

Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014

Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014  
 Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014

SW8370461-139	815m	815m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 1	16/01/2015	Completed Defects	01/01/2016	CLEARANCE FROM LC AND GANTRY NOT TO SPEC
SW8670461-42	819m	819m	SAFETY_FENCE	Corroded - concrete post (CCTP)	CAT 1	09/12/2014	Completed Defects	02/02/2016	
SW8370461-147	38m	38m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 1	16/01/2015	Completed Defects	01/01/2016	CLEARANCE FRM ALL LC AND GANTRYS AND OVERBRIDGES NOT TO SPEC
SW8370461-140	647m	647m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 1	16/01/2015	Completed Defects	01/01/2016	CLEARANCE FRM ALL LC GANTRY AND OVERBRIDGES OUT OF SPC
SW8670461-38	618m	618m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-40	681m	681m	SAFETY_FENCE	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8370461-144	343m	343m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 1	16/01/2015	Completed Defects	01/01/2016	
SW8670461-36	126m	126m	SAFETY_FENCE	Corroded - concrete post (CCTP)	CAT 1	09/12/2014	Completed Defects	02/02/2016	

SW8670461-39	662m	662m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 1	09/12/2014	Completed Defects	02/02/2016	
SW8370461-145	263m	263m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 1	16/01/2015	Completed Defects	01/01/2016	CLEARANCE NOT TO SPEC FROM ALL LC AND OVERBRIDGE
SW8670461-41	742m	742m	SAFETY_FENCE	Corroded - concrete fence (CCTF)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8370461-141	571m	571m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Archive	20/10/2015	
SW8670461-35	120m	120m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-37	184m	184m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	

Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014

Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015

Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016

Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016

Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016

SW83-143364-108	688m	688m	SAFETY_FENCE	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB 200YDS TO 11 OFF
SW83-143364-104	82m	82m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB 12 ON
SW83-143364-105	129m	129m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB 12 ON
SW83-143364-134	477m	477m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB 11 TO 12 AT SOS 668W
SW83-143364-103	113m	113m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB 12 ON
SW83-143364-106	157m	157m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB 12 ON
SW83-143364-107	609m	609m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB 330M TO 11 OFF

Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017

Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017

Detailed Inspection TEMPLATE of M8E Detail SW on 26 September 2018

Detailed Inspection TEMPLATE of M8E Detail SW on 08 June 2018

Detailed Inspection TEMPLATE of M8E Detail SW on 07 June 2019

14225/55 : WITH: ON SLIP FROM M80 TO OFF SLIP JCT 14

Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014

Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014

Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014

Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014

Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014

Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014

SW8370461-125	136m	136m	SAFETY_FENCE	Corroded - metal (fence / barrier)	CAT 2	08/01/2015	Cat 2 Archive	01/01/9999	
---------------	------	------	--------------	------------------------------------	-------	------------	---------------	------------	--

Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 21 May 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016  
 Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016

**Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016**

SW83-143364-24	0m	0m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	ON FROM M80 TO W/B M8
SW83-143364-25	179m	179m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB 1ST LAYBY AFTER M80 ON
SW83-143364-141	368m	368m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB FROM M80

Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 26 September 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 June 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 June 2019

**14225/56 : AGAINST: EB JCT 14 OFF SLIP TO OFF SLIP TO M80**

Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014  
 No defects recorded  
 Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014

No defects recorded

Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014

Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014

SW8370461-124	364m	364m	SAFETY_FENCE	Other (OTHR)	CAT 2	08/01/2015	Cat 2 Archive	01/01/9999	
---------------	------	------	--------------	--------------	-------	------------	---------------	------------	--

Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 21 May 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016  
 Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016

**Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016**

SW83-143364-84	664m	664m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB 14 OFF TO M80 ON
SW83-143364-83	515m	515m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB 14 TO M80 @ SOS 699E
SW83-143364-85	689m	689m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB HARD SHOULDER AT OVERBRIDGE BEFORE M80

Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 26 September 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 June 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 June 2019

**14230/05 : WITH: WB M8 JCT 14 ON SLIP TO JCT 15 OFF SLIP**

Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014  
 Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014

SW8370461-117	555m	555m	SAFETY_FENCE	Corroded - metal post (fence / barrier)	CAT 2	08/01/2015	Cat 2 Archive	01/01/9999	HOLES IN BEAM CODE RED CORRTION FULL LENGTH OF BEAM
---------------	------	------	--------------	---	-------	------------	---------------	------------	---

SW8370461-119	359m	359m	SAFETY_FENCE	(CMTP) Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
---------------	------	------	--------------	------------------------	-------	------------	---------------	------------	--

Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 21 May 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016  
 Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016

Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016

SW83-143364-144	346m	346m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	AT 2ND GANTRY
SW83-143364-145	419m	419m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 1	02/04/2017	Completed Defects	02/04/2017	M8 WB 14 TO 15 2ND GANTRY TO FOOTBRIDGE
SW83-143364-31	521m	521m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB START HIS @ 15 OFF

Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 26 September 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 June 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 June 2019

#### 14230/06 : AGAINST: EB M8 JCT 15 ENTRY TO JCT 14 OFF SLIP

Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014  
 Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014

SW8370461-121	401m	401m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 1	08/01/2015	Completed Defects	03/08/2015	
SW8370461-116	78m	78m	SAFETY_FENCE	Loose tension bolts (LTEN)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	GANTRY INCORRECT WORKNG WIDTH
SW8370461-122	470m	470m	SAFETY_FENCE	Corroded - metal (fence / barrier)	CAT 1	08/01/2015	Completed Defects	01/01/2016	
SW8370461-118	216m	216m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	HI MASS INCORRECT WORKNG WIDTH AND HI MASS
SW8370461-120	380m	380m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	

Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 21 May 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016  
 Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016  
 Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016  
 Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017

Detailed Inspection TEMPLATE of M8E Detail SW on 26 September 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 June 2018  
 Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW ( Awaiting Return )

SW86-334793-3	478m	478m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EB
SW86-334793-2	370m	370m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EB



SW86-334793-1	160m	160m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EB
---------------	------	------	--------------	-------------	-------	------------	-----------------------	------------	----

Detailed Inspection TEMPLATE of M8E Detail SW on 07 June 2019

**14235/05 : WITH: JCT 15 OFF SLIP TO M8 OBRIDGE**

Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014  
Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 21 May 2015

Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015  
Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016

Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016  
Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016  
Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017  
Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017  
Detailed Inspection TEMPLATE of M8E Detail SW on 26 September 2018  
Detailed Inspection TEMPLATE of M8E Detail SW on 08 June 2018  
Detailed Inspection TEMPLATE of M8E Detail SW on 07 June 2019

**14235/06 : AGAINST: EB JCT 15 OFF SLIP TO ENTRY SLIP**

Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014  
Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014

SW8370461-114	558m	558m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8370461-112	402m	402m	SAFETY_FENCE	Other (OTHR)	CAT 2	08/01/2015	Cat 2 Archive	01/01/9999	SURFACE MOUNTS WERE ON SLEAVES
SW8370461-113	428m	0m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8370461-115	620m	620m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	

Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 21 May 2015

Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015  
Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016  
Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016  
Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016  
Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017  
Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017  
Detailed Inspection TEMPLATE of M8E Detail SW on 26 September 2018  
Detailed Inspection TEMPLATE of M8E Detail SW on 08 June 2018  
Detailed Inspection TEMPLATE of M8E Detail SW on 07 June 2019

**14235/39 : WITH: M8 OBRIDGE TO SLIP ON TO M8 WB**

Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014  
Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 21 May 2015

Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015

Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016  
 Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016  
 Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016  
 Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 26 September 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 June 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 June 2019

**14235/82 : AGAINST: JCT 16 ON SLIP TO JCT 15 OFF SLIP**

Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014  
 Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 21 May 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016

Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016  
 Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016

SW83-143364-73	50m	50m	SAFETY_FENCE	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB ON JCT 16 ON SLIP
----------------	-----	-----	--------------	----------------	-------	------------	-----------------------	------------	-------------------------

SW83-143364-75	290m	290m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB JCT 16 LAYBY TO JCT 15 GANTRY
----------------	------	------	--------------	--------------	-------	------------	-----------------------	------------	-------------------------------------

Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 26 September 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 June 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 June 2019

**14240/05 : WITH: JCT 16 OFF SLIP TO CRAIGHALL RD**

Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014  
 Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 21 May 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016  
 Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016

Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016

SW83-143364-45	24m	24m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB JCT 16 OFF AT SOS 721W
----------------	-----	-----	--------------	--------------	-------	------------	-----------------------	------------	------------------------------

Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 26 September 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 June 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 June 2019

**14240/06 : AGAINST: JCT 16 CRAIGHALL RD TO ENTRY M8 EB**

Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014  
 Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014

Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 21 May 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016  
 Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016  
 Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016

SW83-143364-72	3m	3m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB LAYBY AT CANAL TO BRIDGE RAIL
----------------	----	----	--------------	--------------	-------	------------	-----------------------	------------	-------------------------------------

Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 26 September 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 June 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 June 2019

**14210/32 : Against: EB on Slip Jct 11 to Jct 10 Off Slip**

Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014

Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014

**Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014**

SW8370461-130	439m	439m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-52	16m	16m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-54	235m	235m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8370461-128	529m	529m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 1	16/01/2015	Completed Defects	01/01/2016	CLEARANCE FROM LC NT TO SPEC
SW8670461-56	258m	258m	SAFETY_FENCE	Corroded - metal (fence / barrier)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-58	819m	819m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-55	258m	258m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-53	37m	37m	SAFETY_FENCE	Corroded - metal (fence / barrier)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-59	826m	826m	SAFETY_FENCE	Corroded - metal (fence / barrier)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8370461-132	306m	306m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 1	16/01/2015	Completed Defects	01/01/2016	CLEARANCE FROM LC AND OVERBRIDGE NOT TO SPEC
SW8670461-57	817m	817m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-60	1,047m	1,047m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	

Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016

Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016

Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016

SW83-143364-140	202m	202m	SAFETY_FENCE	Corroded - metal (fence / barrier)	CAT 1	01/04/2017	Awaiting CCMS Permanent	01/01/9999	M8 EB GANTRY AT BOTTOM OF 11 ON
SW83-143364-114	67m	67m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB END OF 11 ON
SW83-143364-139	104m	104m	SAFETY_FENCE	Corroded - metal (fence / barrier)	CAT 1	01/04/2017	Awaiting CCMS Permanent	01/01/9999	M8 EB 11 ON AT OVERBRIDGE

Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017  
Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017

Detailed Inspection TEMPLATE of M8E Detail SW on 26 September 2018  
Detailed Inspection TEMPLATE of M8E Detail SW on 08 June 2018  
Detailed Inspection TEMPLATE of M8E Detail SW on 07 June 2019

**14235/32 : With: EB On Slip to A803**

Detailed Inspection TEMPLATE of M8E Detail SW on 07 June 2019

# Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/01/2014 and 06/08/2019, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'WITH: WB M8 OFF SLIP TO A81 UPASS',) Or

(Section is 'WITH: A81 UPASS TO JCT 18 OFF SLIP',) Or

(Section is 'AGAINST: EB JCT 18 ENTRY TO A81 UPASS',) Or

(Section is 'AGAINST: JCT 17 A81 UPASS TO CRAIGHALL RD UPASS',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

## 14240/44 : WITH: WB M8 OFF SLIP TO A81 UPASS

- Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014
- Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014
- Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014
- Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014
- Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014
- Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014
- Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014
- Detailed Inspection TEMPLATE of M8E Detail SW on 21 May 2015
- Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015
- Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016
- Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016
- Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016
- Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017
- Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017
- Detailed Inspection TEMPLATE of M8E Detail SW on 26 September 2018
- Detailed Inspection TEMPLATE of M8E Detail SW on 08 June 2018
- Detailed Inspection TEMPLATE of M8E Detail SW on 07 June 2019

## 14240/45 : AGAINST: JCT 17 A81 UPASS TO CRAIGHALL RD UPASS

- Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014
- Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014
- Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014
- Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014
- Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014
- Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014
- Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014
- Detailed Inspection TEMPLATE of M8E Detail SW on 21 May 2015
- Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015
- Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016
- Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016
- Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016

SW83-143364-70	321m	321m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	LAYBY AT CANAL M8 EB
SW83-143364-71	386m	386m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB LAYBY AT CANAL

- Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017
- Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017
- Detailed Inspection TEMPLATE of M8E Detail SW on 26 September 2018
- Detailed Inspection TEMPLATE of M8E Detail SW on 08 June 2018
- Detailed Inspection TEMPLATE of M8E Detail SW on 07 June 2019

## 14240/83 : WITH: A81 UPASS TO JCT 18 OFF SLIP

- Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014
- Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014
- Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014

Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014  
Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 21 May 2015  
Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015  
Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016  
Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016  
Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016  
Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017  
Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017  
Detailed Inspection TEMPLATE of M8E Detail SW on 26 September 2018  
Detailed Inspection TEMPLATE of M8E Detail SW on 08 June 2018  
Detailed Inspection TEMPLATE of M8E Detail SW on 07 June 2019

**14240/84 : AGAINST: EB JCT 18 ENTRY TO A81 UPASS**

Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014  
Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 21 May 2015  
Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015  
Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016  
Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016  
Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016  
Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017  
Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017  
Detailed Inspection TEMPLATE of M8E Detail SW on 26 September 2018  
Detailed Inspection TEMPLATE of M8E Detail SW on 08 June 2018  
Detailed Inspection TEMPLATE of M8E Detail SW on 07 June 2019

# Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/01/2014 and 06/08/2019, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'AGAINST: WOODLANDS RD OBR TO ON SLIP EB M8') Or

(Section is 'AGAINST: EB JCT 19 TO JCT 18') Or

(Section is 'WITH: JCT 18 TO JCT 19') Or

(Section is 'AGAINST: JCT 19 EB OFF SLIP TO ON SLIP') Or

(Section is 'WITH: JCT 19 WB OFF SLIP TO ON SLIP')

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

## 14245/26 : AGAINST: WOODLANDS RD OBR TO ON SLIP EB M8

Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014  
 Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 21 May 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016  
 Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016  
 Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016  
 Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 26 September 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 June 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 June 2019

## 14245/30 : WITH: JCT 18 TO JCT 19

Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014  
 Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014

SW8370461-153	697m	697m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	DIFFERENT TYPES OF POSTS
SW8370461-156	326m	26m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 1	19/01/2015	Completed Defects	01/01/2016	VERY POOR STATE

Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 21 May 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016  
 Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016  
 Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016  
 Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 26 September 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 June 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 June 2019

**14245/61 : AGAINST: EB JCT 19 TO JCT 18**

Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014  
 Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014

SW8370461-154	126m	126m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 1	19/01/2015	Completed Defects	01/01/2016
SW8370461-155	187m	187m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 1	19/01/2015	Completed Defects	01/01/2016

Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 21 May 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016  
 Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016  
 Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016  
 Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 26 September 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 June 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 June 2019

**14250/05 : WITH: JCT 19 WB OFF SLIP TO ON SLIP**

Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014  
 Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014

SW8370461-151	98m	98m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999
SW8370461-152	26m	26m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999

Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 21 May 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016  
 Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016  
 Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016  
 Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 26 September 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 June 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 June 2019

**14250/06 : AGAINST: JCT 19 EB OFF SLIP TO ON SLIP**

Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014  
 Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 21 May 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016  
 Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016



Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016  
Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017  
Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017  
Detailed Inspection TEMPLATE of M8E Detail SW on 26 September 2018  
Detailed Inspection TEMPLATE of M8E Detail SW on 08 June 2018  
Detailed Inspection TEMPLATE of M8E Detail SW on 07 June 2019

# Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/01/2014 and 06/08/2019, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'WITH: JCT 19 ON SLIP TO M8 EB Entry',) Or

(Section is 'WITH: ENTRY M8 WB TO JCT 20 OFF SLIP',) Or

(Section is 'WITH: JCT 20 SLIP OFF WB M8 TO JCT 22 M77 INT',) Or

(Section is 'AGAINST: JCT 22 M77 INT TO JCT 20',) Or

(Section is 'AGAINST: EB JCT 20 ON SLIP TO JCT 19 OFF SLIP',) Or

(Section is 'AGAINST: SLIP OFF TO A814 TOJCT 19 OFF SLIP',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

## 14250/57 : WITH: JCT 19 ON SLIP TO M8 EB Entry

Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014  
Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 21 May 2015  
Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015  
Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016  
Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016  
Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016  
Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017  
Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017  
Detailed Inspection TEMPLATE of M8E Detail SW on 26 September 2018  
Detailed Inspection TEMPLATE of M8E Detail SW on 08 June 2018  
Detailed Inspection TEMPLATE of M8E Detail SW on 07 June 2019

## 14250/58 : AGAINST: SLIP OFF TO A814 TOJCT 19 OFF SLIP

Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014  
Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 21 May 2015  
Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015  
Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016  
Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016  
Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016  
Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017  
Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017  
Detailed Inspection TEMPLATE of M8E Detail SW on 26 September 2018  
Detailed Inspection TEMPLATE of M8E Detail SW on 08 June 2018  
Detailed Inspection TEMPLATE of M8E Detail SW on 07 June 2019

## 14255/05 : WITH: ENTRY M8 WB TO JCT 20 OFF SLIP

Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014  
Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014

Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 21 May 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016  
 Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016  
 Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016  
 Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 June 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 26 September 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 June 2019

**14255/06 : AGAINST: EB JCT 20 ON SLIP TO JCT 19 OFF SLIP**

Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014  
 Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 21 May 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016  
 Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016  
 Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016  
 Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 June 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 26 September 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 June 2019

**14260/05 : WITH: JCT 20 SLIP OFF WB M8 TO JCT 22 M77 INT**

Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014  
 Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014

SW8670461-2	1,219m	1,219m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999
-------------	--------	--------	--------------	--------------	-------	------------	---------------	------------

Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014  
 Detailed Inspection TEMPLATE of M8E Detail SW on 21 May 2015  
 Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015  
*No defects recorded*  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016  
 Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016  
*No defects recorded*  
 Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016

SW83-143364-48	220m	220m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB END OF KINGSTON TO M77 SLIP
SW83-143364-50	627m	627m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB JCT 20 OFF TO M77 ON
SW83-143364-51	740m	740m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB JCT 20 TO 77 ON, BEAM SEPERATING SEC CWAY FROM M8
SW83-143364-49	254m	254m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB WEST STREET OFF TO M77

Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017  
 Detailed Inspection TEMPLATE of M8E Detail SW on 08 June 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 26 September 2018  
 Detailed Inspection TEMPLATE of M8E Detail SW on 07 June 2019

**14260/06 : AGAINST: JCT 22 M77 INT TO JCT 20**

**Detailed Inspection TEMPLATE of M8E Detail SW on 25 March 2014**  
**Detailed Inspection TEMPLATE of M8E Detail SW on 20 May 2014**  
**Detailed Inspection TEMPLATE of M8E Detail SW on 22 July 2014**  
**Detailed Inspection TEMPLATE of M8E Detail SW on 20 August 2014**  
**Detailed Inspection TEMPLATE of M8E Detail SW on 12 September 2014**  
**Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014**

SW8670461-13	274m	274m	SAFETY_FENCE	Corroded - metal (fence / barrier)	CAT 1	08/12/2014	Awaiting CCMS Permanent	02/02/2016	
SW8670461-15	796m	796m	SAFETY_FENCE	Other (OTHR)	CAT 1	08/12/2014	Completed Defects	30/04/2018	M8 - 14260/06 - AGAINST: JCT 22 M77 INT TO JCT 20
SW8670461-9	164m	164m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-10	200m	200m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-12	300m	300m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-1	504m	504m	SAFETY_FENCE	Corroded - metal (fence / barrier)	CAT 1	05/12/2014	Completed Defects	30/04/2018	M8 - 14260/06 - AGAINST: JCT 22 M77 INT TO JCT 20
SW8670461-14	468m	468m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-16	959m	959m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-7	59m	59m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-8	134m	134m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-11	275m	275m	SAFETY_FENCE	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	

**Detailed Inspection TEMPLATE of M8E Detail SW on 13 November 2014**  
**Detailed Inspection TEMPLATE of M8E Detail SW on 21 May 2015**  
**Detailed Inspection TEMPLATE of M8E Detail SW on 09 October 2015**  
**Detailed Inspection TEMPLATE of M8E Detail SW on 08 July 2016**  
**Detailed Inspection TEMPLATE of M8E Detail SW on 16 September 2016**  
**Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016**

SW83-143364-68	517m	517m	SAFETY_FENCE	Corroded - metal (fence / barrier)	CAT 1	29/12/2016	Completed Defects	08/11/2017	M8 EB ADJ TO CRASH CUSHION AT KINNING PARK SLIP
SW83-143364-66	294m	294m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB 225 METRES AFTER GANTRY 07980
SW83-143364-64	198m	198m	SAFETY_FENCE	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB 130M AFTER GANTRY 07980
SW83-143364-67	308m	308m	SAFETY_FENCE	Corroded - metal (fence / barrier)	CAT 1	29/12/2016	Completed Defects	19/10/2017	M8 EB 235 M AFTER GANTRY 07980
SW83-143364-65	276m	276m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB 210M AFTER GANTRY 07980
SW83-143364-69	521m	521m	SAFETY_FENCE	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB MAIN C\WAY,ADJ TO CUSHION ON OFF SLIP FOR KINNING PARK

Detailed Inspection TEMPLATE of M8E Detail SW on 26 May 2017  
Detailed Inspection TEMPLATE of M8E Detail SW on 07 September 2017  
Detailed Inspection TEMPLATE of M8E Detail SW on 08 June 2018

Detailed Inspection TEMPLATE of M8E Detail SW on 26 September 2018  
Detailed Inspection TEMPLATE of M8E Detail SW on 07 June 2019

# Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/01/2014 and 06/08/2019, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'WITH: JCT 20 SLIP OFF WB M8 TO JCT 22 M77 INT',) Or

(Section is 'AGAINST: JCT 22 M77 INT TO JCT 20',) Or

(Section is 'WITH: JCT 22 WB OFF SLIP TO ON SLIP',) Or

(Section is 'AGAINST: JCT 22 EB OFF SLIP TO ON SLIP',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>14260/05 : WITH: JCT 20 SLIP OFF WB M8 TO JCT 22 M77 INT</b>									
<b>Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014</b>									
SW8670461-2	1,219m	1,219m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
<b>Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016</b>									
SW83-143364-48	220m	220m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB END OF KINGSTON TO M77 SLIP
SW83-143364-50	627m	627m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB JCT 20 OFF TO M77 ON
SW83-143364-51	740m	740m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB JCT 20 TO 77 ON, BEAM SEPERATING SEC CWAY FROM M8
SW83-143364-49	254m	254m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB WEST STREET OFF TO M77
<b>14260/06 : AGAINST: JCT 22 M77 INT TO JCT 20</b>									
<b>Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014</b>									
SW8670461-13	274m	274m	SAFETY_FENCE	Corroded - metal (fence / barrier)	CAT 1	08/12/2014	Awaiting CCMS Permanent	02/02/2016	
SW8670461-15	796m	796m	SAFETY_FENCE	Other (OTHR)	CAT 1	08/12/2014	Completed Defects	30/04/2018	M8 - 14260/06 - AGAINST: JCT 22 M77 INT TO JCT 20
SW8670461-9	164m	164m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-1	504m	504m	SAFETY_FENCE	Corroded - metal (fence / barrier)	CAT 1	05/12/2014	Completed Defects	30/04/2018	M8 - 14260/06 - AGAINST: JCT 22 M77 INT TO JCT 20
SW8670461-14	468m	468m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-16	959m	959m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-10	200m	200m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-12	300m	300m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-11	275m	275m	SAFETY_FENCE	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	

SW8670461-7	59m	59m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-8	134m	134m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
<b>Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016</b>									
SW83-143364-66	294m	294m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB 225 METRES AFTER GANTRY 07980
SW83-143364-68	517m	517m	SAFETY_FENCE	Corroded - metal (fence / barrier)	CAT 1	29/12/2016	Completed Defects	08/11/2017	M8 EB ADJ TO CRASH CUSHION AT KINNING PARK SLIP
SW83-143364-64	198m	198m	SAFETY_FENCE	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB 130M AFTER GANTRY 07980
SW83-143364-65	276m	276m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB 210M AFTER GANTRY 07980
SW83-143364-67	308m	308m	SAFETY_FENCE	Corroded - metal (fence / barrier)	CAT 1	29/12/2016	Completed Defects	19/10/2017	M8 EB 235 M AFTER GANTRY 07980
SW83-143364-69	521m	521m	SAFETY_FENCE	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB MAIN C/WAY, ADJ TO CUSHION ON OFF SLIP FOR KINNING PARK
SW83-143364-63	193m	193m	SAFETY_FENCE	Other (OTHR)	CAT 2	25/12/2016	Cat 2 Awaiting Action	01/01/9999	M8 WB M77 ON SEC C/WAY DIVIDER

#### 14265/05 : WITH: JCT 22 WB OFF SLIP TO ON SLIP

##### Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014

SW8670461-3	75m	75m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
-------------	-----	-----	--------------	--------------	-------	------------	---------------	------------	--

##### Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016

SW83-143364-53	455m	455m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 SEC C/WAY TO JCT 23
SW83-143364-52	160m	160m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB ADJ TO M77 ON

#### 14265/06 : AGAINST: JCT 22 EB OFF SLIP TO ON SLIP

##### Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014

SW8670461-6	427m	427m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-108	69m	69m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-104	131m	131m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	28/07/2015	
SW8670461-111	531m	531m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-109	141m	141m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-110	302m	302m	SAFETY_FENCE	Corroded - concrete fence (CCTF)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
<b>Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016</b>									
SW83-143364-152	566m	0m	SAFETY_FENCE	Corroded - metal (fence /	CAT 1	08/06/2017	Completed Defects	11/05/2017	M77 ONTO M8 O/S LANE TO M74

SW83-143364-62	510m	510m	SAFETY_FENCE	barrier) Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB ADJ TO M77 ON TO M8
----------------	------	------	--------------	--------------------------	-------	------------	--------------------------	------------	---------------------------



# Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/01/2014 and 06/08/2019, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'WITH: JCT 20 SLIP OFF WB M8 TO JCT 22 M77 INT',) Or

(Section is 'AGAINST: JCT 22 M77 INT TO JCT 20',) Or

(Section is 'WITH: JCT 22 WB OFF SLIP TO ON SLIP',) Or

(Section is 'AGAINST: JCT 22 EB OFF SLIP TO ON SLIP',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>14260/05 : WITH: JCT 20 SLIP OFF WB M8 TO JCT 22 M77 INT</b>									
<b>Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014</b>									
SW8670461-2	1,219m	1,219m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
<b>Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016</b>									
SW83-143364-48	220m	220m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB END OF KINGSTON TO M77 SLIP
SW83-143364-50	627m	627m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB JCT 20 OFF TO M77 ON
SW83-143364-51	740m	740m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB JCT 20 TO 77 ON, BEAM SEPERATING SEC CWAY FROM M8
SW83-143364-49	254m	254m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB WEST STREET OFF TO M77
<b>14260/06 : AGAINST: JCT 22 M77 INT TO JCT 20</b>									
<b>Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014</b>									
SW8670461-13	274m	274m	SAFETY_FENCE	Corroded - metal (fence / barrier)	CAT 1	08/12/2014	Awaiting CCMS Permanent	02/02/2016	
SW8670461-15	796m	796m	SAFETY_FENCE	Other (OTHR)	CAT 1	08/12/2014	Completed Defects	30/04/2018	M8 - 14260/06 - AGAINST: JCT 22 M77 INT TO JCT 20
SW8670461-9	164m	164m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-1	504m	504m	SAFETY_FENCE	Corroded - metal (fence / barrier)	CAT 1	05/12/2014	Completed Defects	30/04/2018	M8 - 14260/06 - AGAINST: JCT 22 M77 INT TO JCT 20
SW8670461-14	468m	468m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-16	959m	959m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-10	200m	200m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-12	300m	300m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-11	275m	275m	SAFETY_FENCE	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	

SW8670461-7	59m	59m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-8	134m	134m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
<b>Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016</b>									
SW83-143364-66	294m	294m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB 225 METRES AFTER GANTRY 07980
SW83-143364-68	517m	517m	SAFETY_FENCE	Corroded - metal (fence / barrier)	CAT 1	29/12/2016	Completed Defects	08/11/2017	M8 EB ADJ TO CRASH CUSHION AT KINNING PARK SLIP
SW83-143364-64	198m	198m	SAFETY_FENCE	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB 130M AFTER GANTRY 07980
SW83-143364-65	276m	276m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB 210M AFTER GANTRY 07980
SW83-143364-67	308m	308m	SAFETY_FENCE	Corroded - metal (fence / barrier)	CAT 1	29/12/2016	Completed Defects	19/10/2017	M8 EB 235 M AFTER GANTRY 07980
SW83-143364-69	521m	521m	SAFETY_FENCE	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB MAIN C/WAY, ADJ TO CUSHION ON OFF SLIP FOR KINNING PARK
SW83-143364-63	193m	193m	SAFETY_FENCE	Other (OTHR)	CAT 2	25/12/2016	Cat 2 Awaiting Action	01/01/9999	M8 WB M77 ON SEC C/WAY DIVIDER

#### 14265/05 : WITH: JCT 22 WB OFF SLIP TO ON SLIP

##### Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014

SW8670461-3	75m	75m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
-------------	-----	-----	--------------	--------------	-------	------------	---------------	------------	--

##### Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016

SW83-143364-53	455m	455m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 SEC C/WAY TO JCT 23
SW83-143364-52	160m	160m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB ADJ TO M77 ON

#### 14265/06 : AGAINST: JCT 22 EB OFF SLIP TO ON SLIP

##### Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 06 November 2014

SW8670461-6	427m	427m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-108	69m	69m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-104	131m	131m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	28/07/2015	
SW8670461-111	531m	531m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-109	141m	141m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670461-110	302m	302m	SAFETY_FENCE	Corroded - concrete fence (CCTF)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
<b>Detailed Inspection - Vehicle Restraint Systems of M8E Detail SW on 21 December 2016</b>									
SW83-143364-152	566m	0m	SAFETY_FENCE	Corroded - metal (fence /	CAT 1	08/06/2017	Completed Defects	11/05/2017	M77 ONTO M8 O/S LANE TO M74

SW83-143364-62	510m	510m	SAFETY_FENCE	barrier) Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB ADJ TO M77 ON TO M8
----------------	------	------	--------------	--------------------------	-------	------------	--------------------------	------------	---------------------------

# Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/01/2014 and 06/08/2019, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'WITH: WB JCT 25 ON SLIP TO JCT 26 OFF SLIP',) Or

(Section is 'AGAINST: EB JCT 26 ENTRY SLIP TO JCT 25 OFF SLIP',) Or

(Section is 'AGAINST: SLIP TO H.INT TO MID POINT H.INT BRIDGES',) Or

(Section is 'AGAINST: FROM ARKLESTON ON TO HGTON SLIP OFF',) Or

(Section is 'WITH: SLIP FRM HGTN INTR -SLIP TO ARKLESTON',) Or

(Section is 'AGAINST: OFF M8 TO A741 ARKLESTON ROAD',) Or

(Section is 'WITH: RENFREW RD SLIP TO A741 RENFREW RD OBR',) Or

(Section is 'AGAINST: SLIP TO ARKLESTON TO SLIP FROM ARKLESTON',) Or

(Section is 'WITH: VIADUCT OVER WHITE CART RIVER WESTBOUND',) Or

(Section is 'AGAINST: AIRPORT INTERCHANGE BRIDGE EASTBOUND',) Or

(Section is 'WITH: END OF VIADUCT WBND TO SLIP RD TO APORT',) Or

(Section is 'AGAINST: SLIP FROM A737 INT TO SLIP OFF M8 EB',) Or

(Section is 'WITH: A937 WB ENTRY SLIP TO A937 INT OFF SLIP',) Or

(Section is 'AGAINST: MID POINT A737 BRIDGE TO SLIP FROM A737',) Or

(Section is 'AGAINST: SLIP OFF M8 EB TO MID POINT A737 BRIDGES',) Or

(Section is 'AGAINST: SLIP ON FROM CRAIGTON INT TO MID POINT BR',) Or

(Section is 'WITH: M8 WB FROM A737 INT TO CRAIGTON INT',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	---------	-------	-----------	-------------	-----------------	--------------------------	----------------	-----------------	----------------------

## 13713/10 : WITH: SLIP FRM HGTN INTR -SLIP TO ARKLESTON

Detailed Inspection TEMPLATE of M8 W Detail SW on 24 March 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 14 May 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 22 July 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 10 September 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 17 September 2014

Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 03 November 2014

SW8670460-95	713m	713m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
--------------	------	------	--------------	--------------	-------	------------	---------------	------------	--

SW8670460-94	291m	291m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
--------------	------	------	--------------	--------------	-------	------------	---------------	------------	--

SW8670460-96	1,474m	1,474m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
--------------	--------	--------	--------------	--------------	-------	------------	---------------	------------	--

Detailed Inspection TEMPLATE of M8 W Detail SW on 03 May 2015

Detailed Inspection TEMPLATE of M8 W Detail SW on 08 October 2015

Detailed Inspection TEMPLATE of M8 W Detail SW on 16 September 2016

Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 21 December 2016

SW83-143363-144	1,951m	1,951m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB FROM START OF 27 OFF TO END OF WB WHITECART, FLEX & DOUBLE
-----------------	--------	--------	--------------	-------------	-------	------------	-----------------------	------------	--

SW83-143363-95	1,857m	1,857m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting	01/01/9999	M8 WB APPROX 200 METRES
----------------	--------	--------	--------------	--------------	-------	------------	----------------	------------	-------------------------

Detailed Inspection TEMPLATE of M8 W Detail SW on 07 September 2017

Detailed Inspection TEMPLATE of M8 W Detail SW on 08 September 2017

Detailed Inspection TEMPLATE of M8 W Detail SW on 17 May 2016

Detailed Inspection TEMPLATE of M8 W Detail SW on 26 September 2018

Detailed Inspection TEMPLATE of M8 W Detail SW on 12 October 2018

Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW ( Awaiting Return )

### 13713/93 : WITH: RENFREW RD SLIP TO A741 RENFREW RD OBR

Detailed Inspection TEMPLATE of M8 W Detail SW on 24 March 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 14 May 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 22 July 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 10 September 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 17 September 2014

Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 03 November 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 03 May 2015

Detailed Inspection TEMPLATE of M8 W Detail SW on 08 October 2015

Detailed Inspection TEMPLATE of M8 W Detail SW on 16 September 2016

Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 21 December 2016

SW83-143363-145	255m	255m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB WHITECART VIADUCT,DOUBLE HEIGHT
-----------------	------	------	--------------	-------------	-------	------------	--------------------------	------------	--

Detailed Inspection TEMPLATE of M8 W Detail SW on 07 September 2017

Detailed Inspection TEMPLATE of M8 W Detail SW on 08 September 2017

Detailed Inspection TEMPLATE of M8 W Detail SW on 17 May 2016

Detailed Inspection TEMPLATE of M8 W Detail SW on 26 September 2018

Detailed Inspection TEMPLATE of M8 W Detail SW on 12 October 2018

Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW ( Awaiting Return )

SW86-334005-79	131m	131m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
----------------	------	------	--------------	-------------	-------	------------	--------------------------	------------	--

### 13714/23 : WITH: VIADUCT OVER WHITE CART RIVER WESTBOUND

Detailed Inspection TEMPLATE of M8 W Detail SW on 24 March 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 14 May 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 22 July 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 10 September 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 17 September 2014

Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 03 November 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 03 May 2015

Detailed Inspection TEMPLATE of M8 W Detail SW on 08 October 2015

Detailed Inspection TEMPLATE of M8 W Detail SW on 16 September 2016

Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 21 December 2016

Detailed Inspection TEMPLATE of M8 W Detail SW on 07 September 2017

Detailed Inspection TEMPLATE of M8 W Detail SW on 08 September 2017

Detailed Inspection TEMPLATE of M8 W Detail SW on 17 May 2016

Detailed Inspection TEMPLATE of M8 W Detail SW on 26 September 2018

Detailed Inspection TEMPLATE of M8 W Detail SW on 12 October 2018

### 13714/77 : WITH: END OF VIADUCT WBND TO SLIP RD TO APORT

Detailed Inspection TEMPLATE of M8 W Detail SW on 24 March 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 14 May 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 22 July 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 10 September 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 17 September 2014

Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 03 November 2014

SW8670460-184	100m	100m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
---------------	------	------	--------------	---	-------	------------	---------------	------------	--

Detailed Inspection TEMPLATE of M8 W Detail SW on 03 May 2015

Detailed Inspection TEMPLATE of M8 W Detail SW on 08 October 2015

Detailed Inspection TEMPLATE of M8 W Detail SW on 16 September 2016

No defects recorded

Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 21 December 2016

SW83-143363-139	312m	312m	SAFETY_FENCE	Damaged / deformed -	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB ADJ TO AIRPORT OFF SLIP
-----------------	------	------	--------------	-------------------------	-------	------------	--------------------------	------------	----------------------------------

				<i>fence / barrier (DAMM)</i>					
SW83-143363-142	144m	144m	SAFETY_FENCE	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB 25 METRES BEFORE AIRPORT SLIP

Detailed Inspection TEMPLATE of M8 W Detail SW on 07 September 2017

Detailed Inspection TEMPLATE of M8 W Detail SW on 08 September 2017

Detailed Inspection TEMPLATE of M8 W Detail SW on 17 May 2016

Detailed Inspection TEMPLATE of M8 W Detail SW on 26 September 2018

Detailed Inspection TEMPLATE of M8 W Detail SW on 12 October 2018

Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW ( Awaiting Return )

SW86-334005-78	154m	154m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting	01/01/9999	
----------------	------	------	--------------	-------------	-------	------------	----------------	------------	--

**13716/05 : WITH: A937 WB ENTRY SLIP TO A937 INT OFF SLIP**

Detailed Inspection TEMPLATE of M8 W Detail SW on 24 March 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 14 May 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 22 July 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 10 September 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 17 September 2014

Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 03 November 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 03 May 2015

Detailed Inspection TEMPLATE of M8 W Detail SW on 08 October 2015

Detailed Inspection TEMPLATE of M8 W Detail SW on 16 September 2016

Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 21 December 2016

Detailed Inspection TEMPLATE of M8 W Detail SW on 07 September 2017

Detailed Inspection TEMPLATE of M8 W Detail SW on 08 September 2017

Detailed Inspection TEMPLATE of M8 W Detail SW on 17 May 2016

Detailed Inspection TEMPLATE of M8 W Detail SW on 26 September 2018

Detailed Inspection TEMPLATE of M8 W Detail SW on 12 October 2018

Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW ( Awaiting Return )

SW86-334005-65	188m	188m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
----------------	------	------	--------------	-------------	-------	------------	-----------------------	------------	--

**13717/04 : WITH: M8 WB FROM A737 INT TO CRAIGTON INT**

Detailed Inspection TEMPLATE of M8 W Detail SW on 24 March 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 14 May 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 22 July 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 10 September 2014

SW3063345-499	4,359m	0m	FENCES_AND_BARRIERS	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	With: M8 WB From A737 Int to Craigton Int (J29 - J30)
---------------	--------	----	---------------------	---	-------	------------	---------------	------------	---

SW3063345-236	589m	718m	TRAFFIC_CONTROL_BARRIERS	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	27/05/2016	M8 WB From A737 INT TO CRAIGTON INT
---------------	------	------	--------------------------	--------------	-------	------------	---------------	------------	-------------------------------------

SW3063345-240	748m	749m	TRAFFIC_CONTROL_BARRIERS	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	M8 WB From A737 INT TO CRAIGTON INT
---------------	------	------	--------------------------	--------------	-------	------------	---------------	------------	-------------------------------------

SW3063345-221	409m	410m	TRAFFIC_CONTROL_BARRIERS	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	18/12/2015	M8 WB From A737 INT TO CRAIGTON INT
---------------	------	------	--------------------------	--------------	-------	------------	---------------	------------	-------------------------------------

SW3063345-225	458m	487m	TRAFFIC_CONTROL_BARRIERS	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	M8 WB From A737 INT TO CRAIGTON INT
---------------	------	------	--------------------------	--------------	-------	------------	---------------	------------	-------------------------------------

SW3063345-217	251m	252m	TRAFFIC_CONTROL_BARRIERS	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	M8 WB From A737 INT TO CRAIGTON INT
---------------	------	------	--------------------------	--------------	-------	------------	---------------	------------	-------------------------------------

SW3063345-238	676m	677m	TRAFFIC_CONTROL_BARRIERS	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	M8 WB From A737 INT TO CRAIGTON INT
---------------	------	------	--------------------------	--------------	-------	------------	---------------	------------	-------------------------------------

SW3063345-268	1,176m	1,177m	ROAD_STUDS	Missing "catseye" (MISC)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	M8 WB From A737 INT TO CRAIGTON INT
---------------	--------	--------	------------	--------------------------	-------	------------	---------------	------------	-------------------------------------

Detailed Inspection TEMPLATE of M8 W Detail SW on 17 September 2014

Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 03 November 2014

SW8670460-5	2,927m	2,927m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
-------------	--------	--------	--------------	--------------	-------	------------	---------------	------------	--

SW8670460-7	3,212m	3,212m	SAFETY_FENCE	Other (OTHR)	CAT 2	02/12/2014	Cat 2 Archive	01/01/9999
SW8670460-16	4,335m	4,335m	SAFETY_FENCE	Accident damage (ACCD)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999
SW8670460-18	4,705m	4,705m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999
SW8670460-63	1,409m	1,409m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	31/08/2015
SW8670460-12	3,924m	3,924m	SAFETY_FENCE	Corroded - metal (fence / barrier)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999
SW8670460-14	4,218m	4,218m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999
SW8670460-9	3,567m	3,567m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999
SW8670460-10	3,633m	3,633m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999
SW8670460-160	4,055m	4,055m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999
SW8670460-3	678m	678m	SAFETY_FENCE	Loose bolt (LOSB)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999
SW8670460-13	4,195m	4,195m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999
SW8670460-2	369m	369m	SAFETY_FENCE	Loose bolt (LOSB)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999
SW8670460-164	1,838m	1,838m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999
SW8670460-4	2,005m	2,005m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999
SW8670460-6	2,924m	2,924m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999
SW8670460-17	4,685m	4,685m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999
SW8670460-8	3,535m	3,535m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999
SW8670460-11	3,901m	3,901m	SAFETY_FENCE	Other (OTHR)	CAT 1	02/12/2014	Completed Defects	21/09/2015
SW8670460-15	4,295m	4,295m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999

**Detailed Inspection TEMPLATE of M8 W Detail SW on 03 May 2015**  
**Detailed Inspection TEMPLATE of M8 W Detail SW on 08 October 2015**  
**Detailed Inspection TEMPLATE of M8 W Detail SW on 16 September 2016**  
**Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 21 December 2016**

SW83-143363-32	1,992m	1,992m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB ST JAMES TO WEST FERRY
SW83-143363-34	2,076m	2,076m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB ST JAMES TO WEST FERRY

SW83-143363-28	238m	238m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB AFTER ST JAMES ON
SW83-143363-38	3,208m	3,208m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB ST JAMES TO WEST FERRY AT 1MILE SIGN
SW83-143363-36	2,342m	2,342m	SAFETY_FENCE	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB ST JAMES TO WEST FERRY
SW83-143363-30	1,021m	1,021m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB ST JAMES TO WEST FERRY
SW83-143363-42	4,307m	4,307m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB APPROX 500M TO M898
SW83-143363-29	626m	626m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB ST JAMES TO WEST FERRY
SW83-143363-39	3,535m	3,535m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB ST JAMES TO WEST FERRY @ VMS
SW83-143363-41	4,190m	4,190m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB 1/4 MILE FOR M898 @ OVERBRIDGE
SW83-143363-31	1,138m	1,138m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB ST JAMES TO WEST FERRY
SW83-143363-33	1,993m	1,993m	SAFETY_FENCE	Loose bolt (LOSB)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB ST JAMES TO WEST FERRY
SW83-143363-37	3,110m	3,110m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB ST JAMES TO WEST FERRY
SW83-143363-43	4,676m	4,676m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB 60 METRES TO M898 SLIP
SW83-143363-35	2,268m	2,268m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB ST JAMES TO WEST FERRY
SW83-143363-40	3,905m	3,905m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB 1/2 MILE SIGN FOR M898
<b>Detailed Inspection TEMPLATE of M8 W Detail SW on 07 September 2017</b>									
<b>Detailed Inspection TEMPLATE of M8 W Detail SW on 08 September 2017</b>									
SW77-257656-2	517m	517m	FENCES_AND_BARRIERS	Corroded - metal (fence / barrier)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
<b>Detailed Inspection TEMPLATE of M8 W Detail SW on 17 May 2016</b>									
<b>Detailed Inspection TEMPLATE of M8 W Detail SW on 26 September 2018</b>									
<b>Detailed Inspection TEMPLATE of M8 W Detail SW on 12 October 2018</b>									
<b>Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW ( Awaiting Return )</b>									
SW86-334005-5	3,198m	3,198m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW86-334005-7	3,890m	3,890m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW86-334005-1	160m	160m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB 29 TO 30
SW86-334005-4	3,113m	3,113m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW86-334005-8	4,200m	4,200m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	



SW86-334005-10	4,676m	4,676m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW86-334005-6	3,558m	3,558m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW86-334005-9	4,301m	4,301m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999

### 13717/50 : AGAINST:SLIP ON FROM CRAIGTON INT TO MID POINT BR

**Detailed Inspection TEMPLATE of M8 W Detail SW on 24 March 2014**  
**Detailed Inspection TEMPLATE of M8 W Detail SW on 14 May 2014**  
**Detailed Inspection TEMPLATE of M8 W Detail SW on 22 July 2014**  
**Detailed Inspection TEMPLATE of M8 W Detail SW on 10 September 2014**  
**Detailed Inspection TEMPLATE of M8 W Detail SW on 17 September 2014**  
**Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 03 November 2014**

SW8670460-61	3,265m	3,265m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-68	4,057m	4,057m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-168	3,816m	3,816m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-71	4,383m	4,383m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-72	4,438m	4,438m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-161	971m	971m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-162	1,290m	1,290m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-171	4,441m	4,441m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-172	4,608m	4,608m	SAFETY_FENCE	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-62	3,423m	3,423m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-64	3,664m	3,664m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-66	3,829m	3,829m	SAFETY_FENCE	Incorrect or no tension (metal fence) (NTEN)	CAT 2	01/01/9999	Cat 2 Archive	31/08/2015	
SW8670460-157	136m	136m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-165	3,306m	3,306m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	CLAMPLATE MISS OBB
SW8670460-167	3,744m	3,744m	SAFETY_FENCE	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-169	4,106m	4,106m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	OBB CORRODED ON THE INSIDE

SW8670460-60	2,901m	2,901m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	18/08/2015	
SW8670460-159	738m	738m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	TCB SHOWING SIGNS OF CORROSION OVER THE PAST 100 MTRS
SW8670460-59	2,897m	2,897m	SAFETY_FENCE	Loose bolt (LOSB)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-70	4,280m	4,280m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-163	1,452m	1,452m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-166	3,738m	3,738m	SAFETY_FENCE	Loose bolt (LOSB)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	BEAM LOW 400MM OVER 200MTRS
SW8670460-73	4,485m	4,485m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-74	4,519m	4,519m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-170	4,180m	4,180m	SAFETY_FENCE	Loose bolt (LOSB)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	FO1 MISS AT CROSSOVER
SW8670460-173	4,719m	4,719m	SAFETY_FENCE	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-67	3,895m	3,895m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-69	4,106m	4,106m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	08/06/2015	
SW8670460-65	3,712m	3,712m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-158	249m	249m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
<b>Detailed Inspection TEMPLATE of M8 W Detail SW on 03 May 2015</b>									
<b>Detailed Inspection TEMPLATE of M8 W Detail SW on 08 October 2015</b>									
<b>Detailed Inspection TEMPLATE of M8 W Detail SW on 16 September 2016</b>									
<b>Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 21 December 2016</b>									
SW83-143363-83	3,752m	3,752m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB @ ROYAL HOSPITAL SIGN
SW83-143363-87	4,291m	4,291m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB AT 2ND PAISLEY INFO SIGN
SW83-143363-88	4,376m	4,376m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB 2ND SIGN FOR ROYAL HOSPITAL
SW83-143363-84	3,902m	3,902m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB BEFORE GANTRY SHOWING AIRPORT
SW83-143363-86	4,151m	4,151m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB APPROX 600 METRES TO ST JAMES OFF
SW83-143363-85	4,063m	4,063m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB AT GANTRY PRIOR TO JCT 29
SW83-143363-81	3,580m	1m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB POLICE LAYBY BEFORE JCT 29
SW83-143363-82	3,668m	3,668m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB OBB @ PAISLEY INFORMATION SIGN

SW83-143363-89 4,482m 4,482m SAFETY\_FENCE Other (OTHR) CAT 2 01/01/9999 Cat 2 Awaiting Action 01/01/9999 M8 EB @ 200 YDS TO ST JAMES

Detailed Inspection TEMPLATE of M8 W Detail SW on 07 September 2017

Detailed Inspection TEMPLATE of M8 W Detail SW on 08 September 2017

SW77-257656-105 3,218m 3,225m FENCES\_AND\_BARRIERS Rotten - Wood fence (RWDF) CAT 2 01/01/9999 Cat 2 Awaiting Action 01/01/9999

Detailed Inspection TEMPLATE of M8 W Detail SW on 17 May 2016

Detailed Inspection TEMPLATE of M8 W Detail SW on 26 September 2018

Detailed Inspection TEMPLATE of M8 W Detail SW on 12 October 2018

Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW ( Awaiting Return )

SW86-334005-51 3,262m 3,262m SAFETY\_FENCE None (NONE) CAT 2 01/01/9999 Cat 2 Awaiting Action 01/01/9999

SW86-334005-57 4,188m 4,188m SAFETY\_FENCE None (NONE) CAT 2 01/01/9999 Cat 2 Awaiting Action 01/01/9999

SW86-334005-60 4,476m 4,476m SAFETY\_FENCE None (NONE) CAT 2 01/01/9999 Cat 2 Awaiting Action 01/01/9999

SW86-334005-50 2,629m 2,630m SAFETY\_FENCE None (NONE) CAT 2 01/01/9999 Cat 2 Awaiting Action 01/01/9999

SW86-334005-52 3,427m 3,427m SAFETY\_FENCE None (NONE) CAT 2 01/01/9999 Cat 2 Awaiting Action 01/01/9999

SW86-334005-49 695m 695m SAFETY\_FENCE None (NONE) CAT 2 01/01/9999 Cat 2 Awaiting Action 01/01/9999

SW86-334005-55 3,755m 3,755m SAFETY\_FENCE None (NONE) CAT 2 01/01/9999 Cat 2 Awaiting Action 01/01/9999

SW86-334005-58 4,296m 4,296m SAFETY\_FENCE None (NONE) CAT 2 01/01/9999 Cat 2 Awaiting Action 01/01/9999

SW86-334005-59 4,376m 4,376m SAFETY\_FENCE None (NONE) CAT 2 01/01/9999 Cat 2 Awaiting Action 01/01/9999

SW86-334005-54 3,668m 3,668m SAFETY\_FENCE None (NONE) CAT 2 01/01/9999 Cat 2 Awaiting Action 01/01/9999

SW86-334005-56 4,067m 4,067m SAFETY\_FENCE None (NONE) CAT 2 01/01/9999 Cat 2 Awaiting Action 01/01/9999

SW86-334005-53 3,569m 3,569m SAFETY\_FENCE None (NONE) CAT 2 01/01/9999 Cat 2 Awaiting Action 01/01/9999

### 13717/02 : AGAINST: SLIP OFF M8 EB TO MID POINT A737 BRIDGES

Detailed Inspection TEMPLATE of M8 W Detail SW on 24 March 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 14 May 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 22 July 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 10 September 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 17 September 2014

Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 03 November 2014

SW8670460-80 30m 30m SAFETY\_FENCE Other (OTHR) CAT 2 01/01/9999 Cat 2 Archive 01/01/9999

SW8670460-81 36m 36m SAFETY\_FENCE Other (OTHR) CAT 2 01/01/9999 Cat 2 Archive 01/01/9999

Detailed Inspection TEMPLATE of M8 W Detail SW on 03 May 2015

Detailed Inspection TEMPLATE of M8 W Detail SW on 08 October 2015

No defects recorded

Detailed Inspection TEMPLATE of M8 W Detail SW on 16 September 2016

Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 21 December 2016

Detailed Inspection TEMPLATE of M8 W Detail SW on 07 September 2017

Detailed Inspection TEMPLATE of M8 W Detail SW on 08 September 2017

Detailed Inspection TEMPLATE of M8 W Detail SW on 17 May 2016

Detailed Inspection TEMPLATE of M8 W Detail SW on 26 September 2018

**Detailed Inspection TEMPLATE of M8 W Detail SW on 12 October 2018**

**Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW ( Awaiting Return )**

SW86-334005-90	135m	135m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EB
SW86-334005-89	14m	14m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EB

**13716/56 : AGAINST:MID POINT A737 BRIDGE TO SLIP FROM A737**

**Detailed Inspection TEMPLATE of M8 W Detail SW on 24 March 2014**

**Detailed Inspection TEMPLATE of M8 W Detail SW on 14 May 2014**

**Detailed Inspection TEMPLATE of M8 W Detail SW on 22 July 2014**

**Detailed Inspection TEMPLATE of M8 W Detail SW on 10 September 2014**

**Detailed Inspection TEMPLATE of M8 W Detail SW on 17 September 2014**

**Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 03 November 2014**

SW8670460-85	238m	238m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-83	153m	153m	SAFETY_FENCE	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-82	112m	112m	SAFETY_FENCE	Other (OTHR)	CAT 2	03/12/2014	Cat 2 Archive	01/01/9999	

**Detailed Inspection TEMPLATE of M8 W Detail SW on 03 May 2015**

**Detailed Inspection TEMPLATE of M8 W Detail SW on 08 October 2015**

**Detailed Inspection TEMPLATE of M8 W Detail SW on 16 September 2016**

**Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 21 December 2016**

**Detailed Inspection TEMPLATE of M8 W Detail SW on 07 September 2017**

**Detailed Inspection TEMPLATE of M8 W Detail SW on 08 September 2017**

**Detailed Inspection TEMPLATE of M8 W Detail SW on 17 May 2016**

**Detailed Inspection TEMPLATE of M8 W Detail SW on 26 September 2018**

**Detailed Inspection TEMPLATE of M8 W Detail SW on 12 October 2018**

**Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW ( Awaiting Return )**

SW86-334005-69	79m	79m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW86-334005-68	3m	3m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	

**13716/06 : AGAINST: SLIP FROM A737 INT TO SLIP OFF M8 EB**

**Detailed Inspection TEMPLATE of M8 W Detail SW on 24 March 2014**

**Detailed Inspection TEMPLATE of M8 W Detail SW on 14 May 2014**

**Detailed Inspection TEMPLATE of M8 W Detail SW on 22 July 2014**

**Detailed Inspection TEMPLATE of M8 W Detail SW on 10 September 2014**

**Detailed Inspection TEMPLATE of M8 W Detail SW on 17 September 2014**

**Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 03 November 2014**

SW8670460-92	99m	99m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
--------------	-----	-----	--------------	--------------	-------	------------	---------------	------------	--

**Detailed Inspection TEMPLATE of M8 W Detail SW on 03 May 2015**

**Detailed Inspection TEMPLATE of M8 W Detail SW on 08 October 2015**

No defects recorded

**Detailed Inspection TEMPLATE of M8 W Detail SW on 16 September 2016**

**Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 21 December 2016**

SW83-143363-138	418m	418m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB ADJ TO SLIP FROM A737
SW83-143363-151	18m	18m	SAFETY_FENCE	Corroded - metal (fence / barrier)	CAT 1	06/06/2017	Completed Defects	09/05/2017	FROM J29 ALL THE WAY TO J28
SW83-143363-137	344m	344m	SAFETY_FENCE	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB ADJ TO SLIP FROM A737

SW83-143363-134	254m	254m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB ADJ TO A737 ON SLIP TO M8
SW83-143363-136	313m	313m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB ADJ TO A737 OFF SLIP TO M8,
SW83-143363-135	266m	266m	SAFETY_FENCE	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB CENTRE RES, 12 METRES AFTER WB GANTRY ADJ TO A737 ON

Detailed Inspection TEMPLATE of M8 W Detail SW on 07 September 2017

Detailed Inspection TEMPLATE of M8 W Detail SW on 08 September 2017

Detailed Inspection TEMPLATE of M8 W Detail SW on 17 May 2016

Detailed Inspection TEMPLATE of M8 W Detail SW on 26 September 2018

No defects recorded

Detailed Inspection TEMPLATE of M8 W Detail SW on 12 October 2018

Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW ( Awaiting Return )

### 13714/88 : AGAINST: AIRPORT INTERCHANGE BRIDGE EASTBOUND

Detailed Inspection TEMPLATE of M8 W Detail SW on 24 March 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 14 May 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 22 July 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 10 September 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 17 September 2014

Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 03 November 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 03 May 2015

Detailed Inspection TEMPLATE of M8 W Detail SW on 08 October 2015

Detailed Inspection TEMPLATE of M8 W Detail SW on 17 May 2016

Detailed Inspection TEMPLATE of M8 W Detail SW on 16 September 2016

Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 21 December 2016

SW83-143363-143	188m	188m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB APPROX 40 METRES BEFORE START OF WHITECART VIADUCT
-----------------	------	------	--------------	---	-------	------------	-----------------------	------------	--

SW83-143363-141	5m	5m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 EB&WB TCB SECTION ADJ TO AIRPORT SLIPS
-----------------	----	----	--------------	--------------	-------	------------	-----------------------	------------	---

Detailed Inspection TEMPLATE of M8 W Detail SW on 07 September 2017

Detailed Inspection TEMPLATE of M8 W Detail SW on 08 September 2017

Detailed Inspection TEMPLATE of M8 W Detail SW on 26 September 2018

Detailed Inspection TEMPLATE of M8 W Detail SW on 12 October 2018

### 13713/75 : AGAINST: SLIP TO ARKLESTON TO SLIP FROM ARKLESTON

Detailed Inspection TEMPLATE of M8 W Detail SW on 24 March 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 14 May 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 22 July 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 10 September 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 17 September 2014

Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 03 November 2014

SW8670460-109	102m	102m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
---------------	------	------	--------------	--------------	-------	------------	---------------	------------	--

SW8670460-108	89m	89m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	08/06/2015	
---------------	-----	-----	--------------	--------------	-------	------------	---------------	------------	--

Detailed Inspection TEMPLATE of M8 W Detail SW on 03 May 2015

Detailed Inspection TEMPLATE of M8 W Detail SW on 08 October 2015

Detailed Inspection TEMPLATE of M8 W Detail SW on 16 September 2016

Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 21 December 2016

SW83-143363-147	147m	147m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting	01/01/9999	M8 EB 27 OFF TO ON
-----------------	------	------	--------------	-------------	-------	------------	----------------	------------	--------------------

Detailed Inspection TEMPLATE of M8 W Detail SW on 07 September 2017

Detailed Inspection TEMPLATE of M8 W Detail SW on 08 September 2017

Detailed Inspection TEMPLATE of M8 W Detail SW on 17 May 2016

Detailed Inspection TEMPLATE of M8 W Detail SW on 26 September 2018

Detailed Inspection TEMPLATE of M8 W Detail SW on 12 October 2018

Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW ( Awaiting Return )

SW86-334005-82	105m	105m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
----------------	------	------	--------------	-------------	-------	------------	-----------------------	------------

### 13713/52 : AGAINST: FROM ARKLESTON ON TO HGTON SLIP OFF

Detailed Inspection TEMPLATE of M8 W Detail SW on 24 March 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 14 May 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 22 July 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 10 September 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 17 September 2014

Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 03 November 2014

SW8670460-111	885m	885m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999
---------------	------	------	--------------	--------------	-------	------------	---------------	------------

SW8670460-113	1,204m	1,204m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999
---------------	--------	--------	--------------	--------------	-------	------------	---------------	------------

SW8670460-115	1,775m	1,775m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999
---------------	--------	--------	--------------	--------------	-------	------------	---------------	------------

SW8670460-114	1,283m	1,283m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999
---------------	--------	--------	--------------	--------------	-------	------------	---------------	------------

SW8670460-106	528m	528m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999
---------------	------	------	--------------	--------------	-------	------------	---------------	------------

SW8670460-112	994m	994m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999
---------------	------	------	--------------	--------------	-------	------------	---------------	------------

SW8670460-105	130m	130m	SAFETY_FENCE	Accident damage (ACCD)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999
---------------	------	------	--------------	------------------------	-------	------------	---------------	------------

Detailed Inspection TEMPLATE of M8 W Detail SW on 03 May 2015

Detailed Inspection TEMPLATE of M8 W Detail SW on 08 October 2015

Detailed Inspection TEMPLATE of M8 W Detail SW on 16 September 2016

Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 21 December 2016

Detailed Inspection TEMPLATE of M8 W Detail SW on 07 September 2017

Detailed Inspection TEMPLATE of M8 W Detail SW on 08 September 2017

Detailed Inspection TEMPLATE of M8 W Detail SW on 26 September 2018

Detailed Inspection TEMPLATE of M8 W Detail SW on 12 October 2018

Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW ( Awaiting Return )

SW86-334005-47	1,766m	1,766m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
----------------	--------	--------	--------------	-------------	-------	------------	-----------------------	------------

SW86-334005-44	529m	529m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
----------------	------	------	--------------	-------------	-------	------------	-----------------------	------------

SW86-334005-43	117m	117m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
----------------	------	------	--------------	-------------	-------	------------	-----------------------	------------

SW86-334005-45	849m	849m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
----------------	------	------	--------------	-------------	-------	------------	-----------------------	------------

SW86-334005-46	1,195m	1,195m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
----------------	--------	--------	--------------	-------------	-------	------------	-----------------------	------------

### 13713/05 : AGAINST: SLIP TO H.INT TO MID POINT H.INT BRIDGES

Detailed Inspection TEMPLATE of M8 W Detail SW on 24 March 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 14 May 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 22 July 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 10 September 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 17 September 2014

Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 03 November 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 03 May 2015

Detailed Inspection TEMPLATE of M8 W Detail SW on 08 October 2015

Detailed Inspection TEMPLATE of M8 W Detail SW on 16 September 2016

**Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 21 December 2016**

SW83-143363-152	296m	296m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 1	06/06/2017	Completed Defects	09/10/2017	J26 BETWEEN SLIPS
-----------------	------	------	--------------	--	-------	------------	-------------------	------------	-------------------

Detailed Inspection TEMPLATE of M8 W Detail SW on 07 September 2017

Detailed Inspection TEMPLATE of M8 W Detail SW on 08 September 2017

Detailed Inspection TEMPLATE of M8 W Detail SW on 17 May 2016

Detailed Inspection TEMPLATE of M8 W Detail SW on 26 September 2018

Detailed Inspection TEMPLATE of M8 W Detail SW on 12 October 2018

**Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW ( Awaiting Return )**

SW86-334005-73	96m	96m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
----------------	-----	-----	--------------	-------------	-------	------------	-----------------------	------------	--

**13713/96 : AGAINST: OFF M8 TO A741 ARKLESTON ROAD**

Detailed Inspection TEMPLATE of M8 W Detail SW on 24 March 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 14 May 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 22 July 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 10 September 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 17 September 2014

**Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 03 November 2014**

SW8670460-107	175m	175m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
---------------	------	------	--------------	--------------	-------	------------	---------------	------------	--

Detailed Inspection TEMPLATE of M8 W Detail SW on 03 May 2015

Detailed Inspection TEMPLATE of M8 W Detail SW on 08 October 2015

Detailed Inspection TEMPLATE of M8 W Detail SW on 16 September 2016

Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 21 December 2016

Detailed Inspection TEMPLATE of M8 W Detail SW on 07 September 2017

Detailed Inspection TEMPLATE of M8 W Detail SW on 08 September 2017

Detailed Inspection TEMPLATE of M8 W Detail SW on 17 May 2016

Detailed Inspection TEMPLATE of M8 W Detail SW on 26 September 2018

Detailed Inspection TEMPLATE of M8 W Detail SW on 12 October 2018

**14280/46 : WITH: WB JCT 25 ON SLIP TO JCT 26 OFF SLIP**

Detailed Inspection TEMPLATE of M8 W Detail SW on 24 March 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 14 May 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 22 July 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 10 September 2014

Detailed Inspection TEMPLATE of M8 W Detail SW on 17 September 2014

**Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 03 November 2014**

SW8370460-149	626m	626m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
---------------	------	------	--------------	--------------	-------	------------	---------------	------------	--

SW8370460-147	224m	224m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
---------------	------	------	--------------	--------------	-------	------------	---------------	------------	--

SW8370460-145	152m	152m	SAFETY_FENCE	Missing (MISS)	CAT 1	11/12/2014	Completed Defects	02/02/2016	
---------------	------	------	--------------	----------------	-------	------------	-------------------	------------	--

SW8370460-150	640m	640m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
---------------	------	------	--------------	--------------	-------	------------	---------------	------------	--

SW8370460-146	152m	152m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
---------------	------	------	--------------	--------------	-------	------------	---------------	------------	--

SW8370460-148	284m	284m	SAFETY_FENCE	Corroded - metal (fence / barrier)	CAT 1	14/11/2014	Completed Defects	02/02/2016	
---------------	------	------	--------------	------------------------------------	-------	------------	-------------------	------------	--

Detailed Inspection TEMPLATE of M8 W Detail SW on 03 May 2015

Detailed Inspection TEMPLATE of M8 W Detail SW on 08 October 2015

Detailed Inspection TEMPLATE of M8 W Detail SW on 17 May 2016

Detailed Inspection TEMPLATE of M8 W Detail SW on 16 September 2016

**Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 21 December 2016**

SW83-143363-19	606m	606m	SAFETY_FENCE	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 25 TO 26 WB
----------------	------	------	--------------	----------------	-------	------------	-----------------------	------------	----------------

SW83-143363-22	858m	858m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB AT GANTRY FOR 25A
SW83-143363-150	57m	57m	SAFETY_FENCE	Corroded - metal (fence / barrier)	CAT 1	01/04/2017	Awaiting CCMS Permanent	01/01/9999	M8 WB 25 ON
SW83-143363-16	309m	309m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB 25 TO 26 AT WOOD STORAGE
SW83-143363-18	341m	341m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB 25 TO 26 @ WOOD STORE
SW83-143363-20	629m	629m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB 25 TO 26
SW83-143363-15	183m	183m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB 25 ON TO FIRST BRIDGE DECK
SW83-143363-17	327m	327m	SAFETY_FENCE	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB 25 TO 26 AT WOOD STORAGE
SW83-143363-21	660m	660m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 25 TO 26 WB AFTER GANTRY 01110

**Detailed Inspection TEMPLATE of M8 W Detail SW on 07 September 2017**  
**Detailed Inspection TEMPLATE of M8 W Detail SW on 08 September 2017**  
**Detailed Inspection TEMPLATE of M8 W Detail SW on 26 September 2018**  
**Detailed Inspection TEMPLATE of M8 W Detail SW on 12 October 2018**  
**Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW ( Awaiting Return )**

SW86-334005-38	0m	0m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
----------------	----	----	--------------	-------------	-------	------------	-----------------------	------------	--

#### 14280/47 : AGAINST: EB JCT 26 ENTRY SLIP TO JCT 25 OFF SLIP

**Detailed Inspection TEMPLATE of M8 W Detail SW on 24 March 2014**  
**Detailed Inspection TEMPLATE of M8 W Detail SW on 14 May 2014**  
**Detailed Inspection TEMPLATE of M8 W Detail SW on 22 July 2014**  
**Detailed Inspection TEMPLATE of M8 W Detail SW on 10 September 2014**  
**Detailed Inspection TEMPLATE of M8 W Detail SW on 17 September 2014**  
**Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 03 November 2014**

SW8670460-125	111m	0m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-132	1,142m	1,142m	SAFETY_FENCE	Corroded - concrete fence (CCTF)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-176	11m	11m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-131	924m	924m	SAFETY_FENCE	Corroded - concrete fence (CCTF)	CAT 2	01/01/9999	Cat 2 Archive	11/06/2015	
SW8670460-133	1,275m	1,275m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-134	1,340m	1,340m	SAFETY_FENCE	Accident damage (ACCD)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-130	886m	886m	SAFETY_FENCE	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	



- Detailed Inspection TEMPLATE of M8 W Detail SW on 03 May 2015
- Detailed Inspection TEMPLATE of M8 W Detail SW on 08 October 2015
- Detailed Inspection TEMPLATE of M8 W Detail SW on 17 May 2016
- Detailed Inspection TEMPLATE of M8 W Detail SW on 16 September 2016
- Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 21 December 2016
- Detailed Inspection TEMPLATE of M8 W Detail SW on 07 September 2017
- Detailed Inspection TEMPLATE of M8 W Detail SW on 08 September 2017
- Detailed Inspection TEMPLATE of M8 W Detail SW on 26 September 2018
- Detailed Inspection TEMPLATE of M8 W Detail SW on 12 October 2018
- Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW ( Awaiting Return )

SW86-334005-75	849m	850m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW86-334005-74	5m	5m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW86-334005-76	1,561m	1,561m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999

# Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/01/2014 and 06/08/2019, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'WITH: SLIP FROM M898 - WEST FERRY INTERCHANGE',) Or

(Section is 'AGAINST: SLIP WEST FERRY - SLIP TO ERSK BRIDGE',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>13719/06 : WITH: SLIP FROM M898 - WEST FERRY INTERCHANGE</b>									
Detailed Inspection TEMPLATE of M8 W Detail SW on 24 March 2014									
Detailed Inspection TEMPLATE of M8 W Detail SW on 14 May 2014									
Detailed Inspection TEMPLATE of M8 W Detail SW on 22 July 2014									
Detailed Inspection TEMPLATE of M8 W Detail SW on 10 September 2014									
Detailed Inspection TEMPLATE of M8 W Detail SW on 17 September 2014									
Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 03 November 2014									
SW8670460-22	423m	423m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-149	3,269m	3,269m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-25	1,252m	1,252m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-26	1,581m	1,581m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-21	367m	367m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Archive	14/05/2015	
SW8670460-23	723m	723m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-28	1,886m	1,886m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-30	3,077m	3,077m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-35	4,696m	4,698m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-24	754m	754m	SAFETY_FENCE	Corroded - metal post (fence / barrier) (CMTP)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-27	1,646m	1,646m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-33	4,189m	4,189m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-32	3,853m	3,853m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-29	2,445m	2,445m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	03/11/2015	
SW8670460-31	3,115m	3,115m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-34	4,222m	4,222m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	

SW8670460-150	1,612m	1,612m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
<b>Detailed Inspection TEMPLATE of M8 W Detail SW on 03 May 2015</b> <b>Detailed Inspection TEMPLATE of M8 W Detail SW on 08 October 2015</b> <b>Detailed Inspection TEMPLATE of M8 W Detail SW on 16 September 2016</b> <b>Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 21 December 2016</b>									
SW83-143363-54	3,859m	3,859m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB 1/2 MILE TO WEST FERRY
SW83-143363-47	722m	722m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB AT 10 MILE GREENOCK SIGN
SW83-143363-50	1,877m	1,877m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB 2ND CHANNEL DRAIN SECTION BEFORE WEST FERRY
SW83-143363-51	2,084m	2,084m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB 2ND CHANNEL DRAIN SECTION BEFORE WEST FERRY
SW83-143363-56	4,685m	4,685m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB AT JCT 31 BEFORE OFF SLIP
SW83-143363-52	2,488m	2,488m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB 3RD CHANNEL DRAIN BEFORE WEST FERRY
SW83-143363-48	775m	775m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB AT 10 MILE GREENOCK SIGN
SW83-143363-49	1,220m	1,220m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB AT CHANNEL DRAIN SECTION AFTER 10 MILE GREENOCK SIGN
SW83-143363-46	377m	377m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB AFTER M898 ON SLIP
SW83-143363-53	3,083m	3,083m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB 1 MILE TO WEST FERRY
SW83-143363-55	4,174m	4,174m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	M8 WB AFTER 1/2 MILE TO WEST FERRY @ INGLISTON COUNTRY CLUB SIGN
<b>Detailed Inspection TEMPLATE of M8 W Detail SW on 07 September 2017</b> <b>Detailed Inspection TEMPLATE of M8 W Detail SW on 08 September 2017</b> <b>Detailed Inspection TEMPLATE of M8 W Detail SW on 17 May 2016</b> <b>Detailed Inspection TEMPLATE of M8 W Detail SW on 26 September 2018</b> <b>Detailed Inspection TEMPLATE of M8 W Detail SW on 12 October 2018</b> <b>Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW ( Awaiting Return )</b>									
SW86-334005-20	3,842m	3,842m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW86-334005-16	1,247m	1,247m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW86-334005-17	1,903m	1,903m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW86-334005-19	3,078m	3,078m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW86-334005-21	4,195m	4,195m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW86-334005-18	2,452m	2,452m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW86-334005-14	379m	379m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	

SW86-334005-15	725m	725m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW86-334005-22	4,700m	4,700m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting	01/01/9999	
<b>13719/49 : AGAINST: SLIP WEST FERRY - SLIP TO ERSK BRIDGE</b>									
Detailed Inspection TEMPLATE of M8 W Detail SW on 24 March 2014									
Detailed Inspection TEMPLATE of M8 W Detail SW on 14 May 2014									
Detailed Inspection TEMPLATE of M8 W Detail SW on 22 July 2014									
Detailed Inspection TEMPLATE of M8 W Detail SW on 10 September 2014									
Detailed Inspection TEMPLATE of M8 W Detail SW on 17 September 2014									
Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 03 November 2014									
SW8670460-152	4,488m	4,488m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	OBB SHOWING SIGNS OFF CORROSION ON THE INSIDE OF BEAM
SW8670460-148	1,014m	1,014m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-45	40m	40m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	02/12/2015	
SW8670460-47	599m	599m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-50	2,542m	2,542m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-40	4,751m	4,751m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-41	4,830m	4,830m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-49	829m	829m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-55	4,310m	4,310m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-56	4,458m	4,458m	SAFETY_FENCE	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-52	3,234m	3,234m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-153	4,709m	4,709m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-46	308m	308m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-151	4,024m	4,024m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-39	4,715m	4,715m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-53	3,657m	3,657m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-48	704m	704m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-54	3,933m	3,933m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	
SW8670460-57	4,497m	4,497m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999	

SW8670460-51	2,661m	2,661m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Archive	01/01/9999
<b>Detailed Inspection TEMPLATE of M8 W Detail SW on 03 May 2015</b> <b>Detailed Inspection TEMPLATE of M8 W Detail SW on 08 October 2015</b> <b>Detailed Inspection TEMPLATE of M8 W Detail SW on 16 September 2016</b> <b>Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW on 21 December 2016</b> <b>Detailed Inspection TEMPLATE of M8 W Detail SW on 07 September 2017</b> <b>Detailed Inspection TEMPLATE of M8 W Detail SW on 08 September 2017</b> <b>Detailed Inspection TEMPLATE of M8 W Detail SW on 17 May 2016</b> <b>Detailed Inspection TEMPLATE of M8 W Detail SW on 26 September 2018</b> <b>Detailed Inspection TEMPLATE of M8 W Detail SW on 12 October 2018</b> <b>Detailed Inspection - Vehicle Restraint Systems of M8 W Detail SW ( Awaiting Return )</b>								
SW86-334005-28	2,537m	2,537m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW86-334005-29	2,665m	2,665m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW86-334005-32	4,484m	4,484m	SAFETY_FENCE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW86-334005-33	4,722m	4,722m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW86-334005-30	3,902m	3,902m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW86-334005-31	4,303m	4,303m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW86-334005-27	586m	586m	SAFETY_FENCE	None (NONE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999