



Defect Reference	Location Desc	Defect Date/Tim	Defect Category	Road	Section	XSP	Start Metres	End Metres	Item Category	Item Type	Item Detail	Permanent Repair Date	OI Reference	Repair	Job Status
D-SE18236270585	M8 Westbound Junction 2	27/12/2018 19:22:00	CATEGORY 1	M8	11306/06	Left Hard Shoulder	1264	1264	Litter and Refuse	CARRIAGEWAY	Debris in hard	25/12/2018 09:20:00	OI/18SE04482		Completed Defects
D-SE18236129710	M8 Westbound Junction 2 -	10/10/2018 22:36:39	CATEGORY 1	M8	11306/06	?	0	0	Litter and Refuse	CARRIAGEWAY	Debris in traffi	09/10/2018 08:05:00	OI/18SE03365		Completed Defects
D-SE18236270522	M8 WB J2 On slip hard shoulder	24/12/2018 19:23:56	CATEGORY 1	M8	11306/06	Left Hard Shoulder	405	405	Litter and Refuse	CARRIAGEWAY	Debris in hard	23/12/2018 10:50:00	OI/18SE04475		Completed Defects
D-SE19236965964	Verge, HS, & Central Res.	19/08/2018 19:54:46	CATEGORY 1	M8	11306/06	?	121	121	Litter and Refuse	CENTRAL RESERVE	Detritus / Refu	18/08/2019 08:50:00	OI/19SE02288		Completed Defects
SE47532246-236934378	M8 WB J2 ONSLIP L1 NSWT 80M PRIOR MP154	09/08/2019 09:14:00	CATEGORY 1	M8	11306/06	Left Permanent Lane 1	1513	1513	Carriageways	CARRIAGEWAY	Pothole (POTI)	21/08/2019 23:00:00	OI/19SE02183		Completed Defects
SE57427343-236282632	M8 WB JCT 2 ONSLIP OPP START OF HATCHING FOR MERGE FOR M8	11/12/2018 11:26:00	CATEGORY 1	M8	11306/06	Left Permanent Lane 1	1501	0	Carriageways	CARRIAGEWAY	Pothole (POTI)	09/01/2019 01:30:00	OI/18SE04276		Completed Defects
SE57427497-236264548	M8 WB JCT 2 ONSLIP AT LIGHTING COLUMN ABO808	18/12/2018 13:36:00	CATEGORY 1	M8	11306/06	Left Off Carriageway 2	1101	0	Covers, Gratings and Frames	MANHOLE	Cracked or br	04/02/2019 16:30:00	OI/18SE05821		Completed Defects
D-SE18236270592	M8 Westbound Junction 2	27/12/2018 23:42:03	CATEGORY 1	M8	11306/06	Left Hard Shoulder	1409	1409	Litter and Refuse	CARRIAGEWAY	Debris in hard	26/12/2018 07:10:00	OI/18SE04485		Completed Defects
SE47488566-236586626	M8 WB J2 ONSLIP UNDER 2ND BRIDGE L2 NSWT	19/04/2019 10:16:00	CATEGORY 1	M8	11306/06	Left Permanent Lane 2	962	0	Carriageways	CARRIAGEWAY	Pothole (POTI)	03/05/2019 02:30:00	OI/19SE00491		Completed Defects
D-SE19236916742	Hard Shoulder WB	21/07/2019 03:11:34	CATEGORY 1	M8	11306/06	?	856	856	Litter and Refuse	CARRIAGEWAY	Debris in hard	15/07/2019 11:20:00	OI/19SE01865		Completed Defects
D-SE19236906631	M8 WB J2 LANE 2	08/07/2019 23:02:48	CATEGORY 1	M8	11306/06	Left Permanent Lane 2	394	394	Dead Animals	REMOVE ANIMAL	Carcass of de	07/07/2019 17:10:00	OI/18SE01709		Completed Defects
D-SE19236342224	M8 WB J2 HARD SHOULDER	01/03/2019 02:30:21	CATEGORY 1	M8	11306/06	Left Hard Shoulder	1248	1248	Litter and Refuse	LAYBY	Debris in hard	27/02/2019 06:55:00	OI/18SE06338		Completed Defects
SE47493575-236588349	M8 WB J2 ONSLIP JUST AFTER SECOND BRIDGE	23/04/2019 09:25:00	CATEGORY 1	M8	11306/06	Left Off Carriageway 2	1028	0	Woodland Areas and Trees	TREE	Overhanging/r	14/05/2019 12:00:00	OI/19SE00571		Completed Defects
SE57427497-236264545	M8 WB J2 ONSLIP BETWEEN LIGHTING COLUMN ABO808 ABO812	18/12/2018 13:07:00	CATEGORY 1	M8	11306/06	Left Boundary Area	1222	0	Fences, Walls, Screens and Noise Barriers	FENCES_AND_BARRIERS	Damaged / de	04/02/2019 16:30:00	OI/18SE04398		Completed Defects
D-SE18236264623	M8 WB J2 (Onslip from Newbridge) Verge.	16/12/2018 21:06:53	CATEGORY 1	M8	11306/06	Left Boundary Area	1445	1445	Litter and Refuse	CARRIAGEWAY	Debris in hard	15/12/2018 09:05:00	OI/18SE04340		Completed Defects
SE47488566-236586627	M8 WB TOP OF J2 ONSLIP LANE 1	19/04/2019 10:23:00	CATEGORY 1	M8	11306/06	Left Permanent Lane 1	1498	0	Carriageways	CARRIAGEWAY	Pothole (POTI)	03/05/2019 03:30:00	OI/19SE00493		Completed Defects
SE57426421-236177482	M8 WB JCT ONSLIP LANE 1 250M PRIOR TO MERGE ONTO M8	06/11/2018 11:02:00	CATEGORY 1	M8	11306/06	Left Permanent Lane 1	1502	0	Carriageways	CARRIAGEWAY	Pothole (POTI)	08/11/2018 04:30:00	OI/18SE03773		Completed Defects
SE56425911-236166897	M8 WB JUST AFTER J2 OFFSLIP MP 14/1	23/10/2018 09:42:00	CATEGORY 1	M8	11306/06	Centre Line	234	0	Carriageways	CARRIAGEWAY	Pothole (POTI)	06/11/2018 05:30:00	OI/18SE03583		Completed Defects



Defect Reference	Location Desc	Defect Date/Tim	Defect Category	Road	Section	XSP	Start Metres	End Metres	Item Category	Item Type	Item Detail	Permanent Repair Date	Ol Reference	Repair Comments	Job Status
D-SE18236270585	M8 Westbound Junction 2	27/12/2018 19:22:00	CATEGORY 1	M8	11306/06	Left Hard Shoulder	1264	1264	Litter and Refuse	CARRIAGEWAY	Debris in hard	25/12/2018 09:20:00	OI/18SE04482	Completed Defects	
D-SE18236129710	M8 Westbound Junction 2 -	10/10/2018 22:36:39	CATEGORY 1	M8	11306/06	?	0	0	Litter and Refuse	CARRIAGEWAY	Debris in traffi	09/10/2018 08:05:00	OI/18SE03365	Completed Defects	
D-SE18236270522	M8 WB J2 On slip hard shoulder	24/12/2018 19:23:56	CATEGORY 1	M8	11306/06	Left Hard Shoulder	405	405	Litter and Refuse	CARRIAGEWAY	Debris in hard	23/12/2018 10:50:00	OI/18SE04475	Completed Defects	
D-SE19236965964	Verge, HS, & Central Res.	19/08/2019 19:54:48	CATEGORY 1	M8	11306/06	?	121	121	Litter and Refuse	CENTRAL_RESERVE	Detritus / Refu	18/08/2019 08:50:00	OI/19SE02288	Completed Defects	
SE47532246-236934376	M8 WB J2 ONSLIP L1 NSWT 80M PRIOR MP15/4	09/08/2019 09:14:00	CATEGORY 1	M8	11306/06	Left Permanent Lane 1	1513	1513	Carriageways	CARRIAGEWAY	Pothole (POTI	21/08/2019 23:00:00	OI/19SE02183	Completed Defects	
SE57427343-236262632	M8 W/B JCT 2 ONSLIP OPP START OF HATCHING FOR MERGE FOR M8	11/12/2018 11:26:00	CATEGORY 1	M8	11306/06	Left Permanent Lane 1	1501	0	Carriageways	CARRIAGEWAY	Pothole (POTI	09/01/2019 01:30:00	OI/18SE04276	Completed Defects	
SE57427497-236264546	M8 W/B JCT 2 ONSLIP AT LIGHTING COLUMN ABO808	18/12/2018 13:36:00	CATEGORY 1	M8	11306/06	Left Off Carriageway 2	1101	0	Covers, Gratings and Frames	MANHOLE	Cracked or br	04/02/2019 16:30:00	OI/18SE05821	Completed Defects	
D-SE18236270592	M8 Westbound Junction 2	27/12/2018 23:42:03	CATEGORY 1	M8	11306/06	Left Hard Shoulder	1409	1409	Litter and Refuse	CARRIAGEWAY	Debris in hard	26/12/2018 07:10:00	OI/18SE04485	Completed Defects	
SE47488566-236585626	M8 WB J2 ONSLIP UNDER 2ND BRIDGE L2 NSWT	19/04/2019 10:16:00	CATEGORY 1	M8	11306/06	Left Permanent Lane 2	962	0	Carriageways	CARRIAGEWAY	Pothole (POTI	03/05/2019 02:30:00	OI/19SE00491	Completed Defects	
D-SE19236916742	Hard Shoulder W/B	21/07/2019 03:11:34	CATEGORY 1	M8	11306/06	?	656	656	Litter and Refuse	CARRIAGEWAY	Debris in hard	15/07/2019 11:20:00	OI/19SE01865	Completed Defects	
D-SE19236906631	M8 W/B J2 LANE 2	08/07/2019 23:02:48	CATEGORY 1	M8	11306/06	Left Permanent Lane 2	394	394	Dead Animals	REMOVE_ANIMAL	Carcass of de	07/07/2019 17:10:00	OI/19SE01709	Completed Defects	
D-SE19236342224	M8 W/B J2 HARD SHOULDER	01/03/2019 02:30:21	CATEGORY 1	M8	11306/06	Left Hard Shoulder	1248	1248	Litter and Refuse	LAYBY	Debris in hard	27/02/2019 06:55:00	OI/18SE05338	Completed Defects	
SE47493575-236588349	M8 W/B J2 ONSLIP JUST AFTER SECOND BRIDGE	23/04/2019 09:25:00	CATEGORY 1	M8	11306/06	Left Off Carriageway 2	1028	0	Woodland Areas and Trees	TREE	Overhanging/c	14/05/2019 12:00:00	OI/19SE00571	Completed Defects	
SE57427497-236264545	M8 WB J2 ONSLIP BETWEEN LIGHTING COLUMN AB0808 AB0812	18/12/2018 13:07:00	CATEGORY 1	M8	11306/06	Left Boundary Area	1222	0	Fences, Walls, Screens and Noise Barriers	FENCES_AND_BARRIERS	Damaged / de	04/02/2019 16:30:00	OI/18SE04398	Completed Defects	
D-SE18236264623	M8 WB J2 (Onslip from Newbridge) Verge.	16/12/2018 21:06:53	CATEGORY 1	M8	11306/06	Left Boundary Area	1445	1445	Litter and Refuse	CARRIAGEWAY	Debris in hard	15/12/2018 09:05:00	OI/18SE04340	Completed Defects	
SE47488566-236585627	M8 WB TOP OF J2 ONSLIP LANE 1	19/04/2019 10:23:00	CATEGORY 1	M8	11306/06	Left Permanent Lane 1	1496	0	Carriageways	CARRIAGEWAY	Pothole (POTI	03/05/2019 03:30:00	OI/19SE00493	Completed Defects	
SE57426421-236177482	M8 W/B JCT ONSLIP LANE 1 250M PRIOR TO MERGE ONTO M8	06/11/2018 11:02:00	CATEGORY 1	M8	11306/06	Left Permanent Lane 1	1502	0	Carriageways	CARRIAGEWAY	Pothole (POTI	08/11/2018 04:30:00	OI/18SE03773	Completed Defects	
SE56425911-236166897	M8 WB JUST AFTER J2 OFFSLIP MP 14/1	23/10/2018 09:42:00	CATEGORY 1	M8	11306/06	Centre Line	234	0	Carriageways	CARRIAGEWAY	Pothole (POTI	06/11/2018 05:30:00	OI/18SE03583	Completed Defects	