

# Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 12/08/2018 and 09/05/2019, and defects raised outside of inspections on the same Section(s) during this period.

(Road is 'M8',)  
(Section Code is 11306/05) Or

(Section Code is 11306/06)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>11306/06 : AGAINST: WESTBOUND SLIP FROM NEWBRIDGE</b>									
Safety Inspection of Amey M8 Safety Inspection on 14 August 2018									
No defects recorded									
Safety Patrol of Amey M8 Safety Patrol on 17 August 2018									
No defects recorded									
Safety Inspection of Amey M8 Safety Inspection on 21 August 2018									
No defects recorded									
Safety Patrol of Amey M8 Safety Patrol on 24 August 2018									
No defects recorded									
Safety Inspection of Amey M8 Safety Inspection on 28 August 2018									
No defects recorded									
Safety Patrol of Amey M8 Safety Patrol on 31 August 2018									
No defects recorded									
Safety Inspection of Amey M8 Safety Inspection on 04 September 2018									
No defects recorded									
Safety Patrol of Amey M8 Safety Patrol on 07 September 2018									
No defects recorded									
Safety Inspection of Amey M8 Safety Inspection on 11 September 2018									
No defects recorded									
Safety Patrol of Amey M8 Safety Patrol on 14 September 2018									
No defects recorded									
Safety Inspection of Amey M8 Safety Inspection on 18 September 2018									
No defects recorded									
Safety Patrol of Amey M8 Safety Patrol on 21 September 2018									
No defects recorded									
Safety Inspection of Amey M8 Safety Inspection on 25 September 2018									
No defects recorded									
Safety Patrol of Amey M8 Safety Patrol on 28 September 2018									
No defects recorded									
Safety Inspection of Amey M8 Safety Inspection on 02 October 2018									
No defects recorded									
Safety Patrol of Amey M8 Safety Patrol on 05 October 2018									
No defects recorded									
Safety Inspection of Amey M8 Safety Inspection on 09 October 2018									
No defects recorded									
Safety Patrol of Amey M8 Safety Patrol on 12 October 2018									
No defects recorded									
Safety Inspection of Amey M8 Safety Inspection on 16 October 2018									
No defects recorded									
Safety Patrol of Amey M8 Safety Patrol on 19 October 2018									
No defects recorded									
Safety Inspection of Amey M8 Safety Inspection on 23 October 2018									
SE56425911-236166897	234m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/11/2018	Completed Defects	06/11/2018	M8 WB JUST AFTER J2 OFFSLIP MP 14/1
Safety Patrol of Amey M8 Safety Patrol on 26 October 2018									
No defects recorded									
Safety Inspection of Amey M8 Safety Inspection on 30 October 2018									
No defects recorded									
Safety Patrol of Amey M8 Safety Patrol on 02 November 2018									
No defects recorded									
Safety Inspection of Amey M8 Safety Inspection on 06 November 2018									
SE57426421-236177482	1,502m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	04/12/2018	Completed Defects	08/11/2018	M8 W/B JCT ONSLIP LANE 1 250M PRIOR TO MERGE ONTO M8

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>Safety Patrol of Amey M8 Safety Patrol on 09 November 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 13 November 2018</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 16 November 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 20 November 2018</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 23 November 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 27 November 2018</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 30 November 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 04 December 2018</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 07 December 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 11 December 2018</b>									
SE57427343-236262632	1,501m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/01/2019	Completed Defects	09/01/2019	M8 W/B JCT 2 ONSLIP OPP START OF HATCHING FOR MERGE FOR M8
<b>Safety Patrol of Amey M8 Safety Patrol on 14 December 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 18 December 2018</b>									
SE57427497-236264545	1,222m	0m	FENCES_AND_BA RRIERS	Damaged / deformed - fence / barrier (DAMM)	CAT 1	15/01/2019	Completed Defects	04/02/2019	M8 WB J2 ONSLIP BETWEEN LIGHTING COLUMN AB0808 AB0812
SE57427497-236264546	1,101m	0m	MANHOLE	Cracked or broken (IBCK)	CAT 1	15/01/2019	Completed Defects	04/02/2019	M8 W/B JCT 2 ONSLIP AT LIGHTING COLUMN ABO808
<b>Safety Patrol of Amey M8 Safety Patrol on 21 December 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 28 December 2018</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 28 December 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 01 January 2019</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 04 January 2019</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 08 January 2019</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 11 January 2019</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 15 January 2019</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 17 January 2019</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 22 January 2019</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 25 January 2019</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 29 January 2019</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 01 February 2019</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 05 February 2019</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 08 February 2019</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 12 February 2019</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 15 February 2019</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 19 February 2019</b>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 22 February 2019</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 26 February 2019</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 01 March 2019</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 05 March 2019</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 08 March 2019</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 12 March 2019</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 15 March 2019</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 19 March 2019</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 22 March 2019</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 26 March 2019</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 29 March 2019</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 02 April 2019</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 05 April 2019</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 09 April 2019</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 12 April 2019</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 16 April 2019</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 19 April 2019</b>									
SE47488566-236585626	962m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	17/05/2019	Completed Defects	03/05/2019	M8 WB J2 ONSLIP UNDER 2ND BRIDGE L2 NSWT
SE47488566-236585627	1,496m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	17/05/2019	Completed Defects	03/05/2019	M8 WB TOP OF J2 ONSLIP LANE 1
<b>Safety Inspection of Amey M8 Safety Inspection on 23 April 2019</b>									
SE47493575-236588349	1,028m	0m	TREE	Overhanging/ov ergrown (OVER)	CAT 1	21/05/2019	Completed Defects	14/05/2019	M8 W/B J2 ONSLIP JUST AFTER SECOND BRIDGE
<b>Safety Patrol of Amey M8 Safety Patrol on 26 April 2019</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 30 April 2019</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 03 May 2019</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 07 May 2019</b>									
<i>No defects recorded</i>									
<b>11306/05 : WITH: WESTBOUND SLIP TO NEWBRIDGE</b>									
<b>Safety Inspection of Amey M8 Safety Inspection on 14 August 2018</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 17 August 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 21 August 2018</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 24 August 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 28 August 2018</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 31 August 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 04 September 2018</b>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 07 September 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 11 September 2018</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 14 September 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 18 September 2018</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 21 September 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 25 September 2018</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 28 September 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 02 October 2018</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 05 October 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 09 October 2018</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 12 October 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 16 October 2018</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 19 October 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 23 October 2018</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 26 October 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 30 October 2018</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 02 November 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 06 November 2018</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 09 November 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 13 November 2018</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 16 November 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 20 November 2018</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 23 November 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 27 November 2018</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 30 November 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 04 December 2018</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 07 December 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 11 December 2018</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 14 December 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 18 December 2018</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 21 December 2018</b>									
<i>No defects recorded</i>									
<b>Safety Inspection of Amey M8 Safety Inspection on 28 December 2018</b>									
<i>No defects recorded</i>									
<b>Safety Patrol of Amey M8 Safety Patrol on 28 December 2018</b>									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>Safety Inspection of Amey M8</b>			Safety Inspection	Safety Inspection on 01 January 2019					
				<i>No defects recorded</i>					
<b>Safety Patrol of Amey M8</b>			Safety Patrol	Safety Patrol on 04 January 2019					
				<i>No defects recorded</i>					
<b>Safety Inspection of Amey M8</b>			Safety Inspection	Safety Inspection on 08 January 2019					
				<i>No defects recorded</i>					
<b>Safety Patrol of Amey M8</b>			Safety Patrol	Safety Patrol on 11 January 2019					
				<i>No defects recorded</i>					
<b>Safety Inspection of Amey M8</b>			Safety Inspection	Safety Inspection on 15 January 2019					
				<i>No defects recorded</i>					
<b>Safety Patrol of Amey M8</b>			Safety Patrol	Safety Patrol on 17 January 2019					
				<i>No defects recorded</i>					
<b>Safety Inspection of Amey M8</b>			Safety Inspection	Safety Inspection on 22 January 2019					
				<i>No defects recorded</i>					
<b>Safety Patrol of Amey M8</b>			Safety Patrol	Safety Patrol on 25 January 2019					
				<i>No defects recorded</i>					
<b>Safety Inspection of Amey M8</b>			Safety Inspection	Safety Inspection on 29 January 2019					
				<i>No defects recorded</i>					
<b>Safety Patrol of Amey M8</b>			Safety Patrol	Safety Patrol on 01 February 2019					
				<i>No defects recorded</i>					
<b>Safety Inspection of Amey M8</b>			Safety Inspection	Safety Inspection on 05 February 2019					
				<i>No defects recorded</i>					
<b>Safety Patrol of Amey M8</b>			Safety Patrol	Safety Patrol on 08 February 2019					
				<i>No defects recorded</i>					
<b>Safety Inspection of Amey M8</b>			Safety Inspection	Safety Inspection on 12 February 2019					
				<i>No defects recorded</i>					
<b>Safety Patrol of Amey M8</b>			Safety Patrol	Safety Patrol on 15 February 2019					
				<i>No defects recorded</i>					
<b>Safety Inspection of Amey M8</b>			Safety Inspection	Safety Inspection on 19 February 2019					
				<i>No defects recorded</i>					
<b>Safety Patrol of Amey M8</b>			Safety Patrol	Safety Patrol on 22 February 2019					
				<i>No defects recorded</i>					
<b>Safety Inspection of Amey M8</b>			Safety Inspection	Safety Inspection on 26 February 2019					
				<i>No defects recorded</i>					
<b>Safety Patrol of Amey M8</b>			Safety Patrol	Safety Patrol on 01 March 2019					
				<i>No defects recorded</i>					
<b>Safety Inspection of Amey M8</b>			Safety Inspection	Safety Inspection on 05 March 2019					
				<i>No defects recorded</i>					
<b>Safety Patrol of Amey M8</b>			Safety Patrol	Safety Patrol on 08 March 2019					
				<i>No defects recorded</i>					
<b>Safety Inspection of Amey M8</b>			Safety Inspection	Safety Inspection on 12 March 2019					
				<i>No defects recorded</i>					
<b>Safety Patrol of Amey M8</b>			Safety Patrol	Safety Patrol on 15 March 2019					
				<i>No defects recorded</i>					
<b>Safety Inspection of Amey M8</b>			Safety Inspection	Safety Inspection on 19 March 2019					
				<i>No defects recorded</i>					
<b>Safety Patrol of Amey M8</b>			Safety Patrol	Safety Patrol on 22 March 2019					
				<i>No defects recorded</i>					
<b>Safety Inspection of Amey M8</b>			Safety Inspection	Safety Inspection on 26 March 2019					
				<i>No defects recorded</i>					
<b>Safety Patrol of Amey M8</b>			Safety Patrol	Safety Patrol on 29 March 2019					
				<i>No defects recorded</i>					
<b>Safety Inspection of Amey M8</b>			Safety Inspection	Safety Inspection on 02 April 2019					
				<i>No defects recorded</i>					
<b>Safety Patrol of Amey M8</b>			Safety Patrol	Safety Patrol on 05 April 2019					
				<i>No defects recorded</i>					
<b>Safety Inspection of Amey M8</b>			Safety Inspection	Safety Inspection on 09 April 2019					
				<i>No defects recorded</i>					
<b>Safety Patrol of Amey M8</b>			Safety Patrol	Safety Patrol on 12 April 2019					
				<i>No defects recorded</i>					
<b>Safety Inspection of Amey M8</b>			Safety Inspection	Safety Inspection on 16 April 2019					
				<i>No defects recorded</i>					
<b>Safety Patrol of Amey M8</b>			Safety Patrol	Safety Patrol on 19 April 2019					
				<i>No defects recorded</i>					
<b>Safety Inspection of Amey M8</b>			Safety Inspection	Safety Inspection on 23 April 2019					
				<i>No defects recorded</i>					
<b>Safety Patrol of Amey M8</b>			Safety Patrol	Safety Patrol on 26 April 2019					

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

*No defects recorded*

**Safety Inspection of Amey M8 Safety Inspection on 30 April 2019**

*No defects recorded*

**Safety Patrol of Amey M8 Safety Patrol on 03 May 2019**

*No defects recorded*

**Safety Inspection of Amey M8 Safety Inspection on 07 May 2019**

*No defects recorded*

# Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 10/05/2019 and 08/08/2019, and defects raised outside of inspections on the same Section(s) during this period.

(Road is 'M8',)  
(Section Code is 11306/05) Or

(Section Code is 11306/06)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>11306/06 : AGAINST: WESTBOUND SLIP FROM NEWBRIDGE</b>									
Safety Patrol of Amey M8 Safety Patrol on 10 May 2019									
<i>No defects recorded</i>									
Safety Inspection of Amey M8 Safety Inspection on 14 May 2019									
<i>No defects recorded</i>									
Safety Patrol of Amey M8 Safety Patrol on 17 May 2019									
<i>No defects recorded</i>									
Safety Inspection of Amey M8 Safety Inspection on 21 May 2019									
<i>No defects recorded</i>									
Safety Patrol of Amey M8 Safety Patrol on 24 May 2019									
<i>No defects recorded</i>									
Safety Inspection of Amey M8 Safety Inspection on 28 May 2019									
<i>No defects recorded</i>									
Safety Patrol of Amey M8 Safety Patrol on 31 May 2019									
<i>No defects recorded</i>									
Safety Inspection of Amey M8 Safety Inspection on 04 June 2019									
<i>No defects recorded</i>									
Safety Patrol of Amey M8 Safety Patrol on 07 June 2019									
<i>No defects recorded</i>									
Safety Inspection of Amey M8 Safety Inspection on 11 June 2019									
<i>No defects recorded</i>									
Safety Patrol of Amey M8 Safety Patrol on 14 June 2019									
<i>No defects recorded</i>									
Safety Inspection of Amey M8 Safety Inspection on 18 June 2019									
<i>No defects recorded</i>									
Safety Patrol of Amey M8 Safety Patrol on 21 June 2019									
<i>No defects recorded</i>									
Safety Inspection of Amey M8 Safety Inspection on 25 June 2019									
<i>No defects recorded</i>									
Safety Patrol of Amey M8 Safety Patrol on 28 June 2019									
<i>No defects recorded</i>									
Safety Inspection of Amey M8 Safety Inspection on 02 July 2019									
<i>No defects recorded</i>									
Safety Patrol of Amey M8 Safety Patrol on 05 July 2019									
<i>No defects recorded</i>									
Safety Inspection of Amey M8 Safety Inspection on 09 July 2019									
<i>No defects recorded</i>									
Safety Patrol of Amey M8 Safety Patrol on 12 July 2019									
<i>No defects recorded</i>									
Safety Inspection of Amey M8 Safety Inspection on 16 July 2019									
<i>No defects recorded</i>									
Safety Patrol of Amey M8 Safety Patrol on 19 July 2019									
<i>No defects recorded</i>									
Safety Inspection of Amey M8 Safety Inspection on 23 July 2019									
<i>No defects recorded</i>									
Safety Patrol of Amey M8 Safety Patrol on 26 July 2019									
<i>No defects recorded</i>									
Safety Inspection of Amey M8 Safety Inspection on 30 July 2019									
<i>No defects recorded</i>									
Safety Patrol of Amey M8 Safety Patrol on 02 August 2019									
<i>No defects recorded</i>									
Safety Inspection of Amey M8 Safety Inspection on 06 August 2019									
<i>No defects recorded</i>									

## 11306/05 : WITH: WESTBOUND SLIP TO NEWBRIDGE

