

Drainage Strategy - Live Copy

Source	Related Ors	Ref. No.	Date first added to the Strategy	Route	Revised Ranking	Link / Section	Location	Description	Road Safety (40%)	Forthcoming Schemes (25%)	Frequency of Occurrence (25%)	Adjacent Land Impact (10%)	Overall Score	Progress to Date
									Score	Score	Score	Score		
Inspection		363	31/01/2017	M9	8	10309/87	M9 NB J4 Offslip	Low point on offslip flooding due to blocked gully reresulting in both lanes being affected	4	3	2	1	12.95	Monitor situation on inspections.A scheme to be raised to investigate carrier pipe
ASE246221		393	08/02/2019	M9	9	10350/50	M9 nb nth of Pirnhall jct 9 at Foot o Green		4	3	2	1	12.95	
Inspection		382	26/10/2017	M9	35		jct 2 NB prior to Pardovan overbridge	Removal of gullies and kerbs to be replaced with filter drainage	2	3	2	1	10.15	Design carried out by Consulting re crossfall of water when heavy rain

Drainage Strategy - Live Copy

Source	Related Ors	Ref. No.	Date first added to the Strategy	Route	Revised Ranking	Link / Section	Location	Description	Road Safety (40%)	Forthcoming Schemes (25%)	Frequency of Occurrence (25%)	Adjacent Land Impact (10%)	Overall Score	Progress to Date
									Score	Score	Score	Score		