

# Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 24/03/2019 and 21/04/2019, and defects raised outside of inspections on the same Section(s) during this period.

(Road is 'A82',)  
(Section Code is 10877/05) Or

(Section Code is 10877/25) Or

(Section Code is 10877/50)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

## 10877/05 : A87 JUNCTION INVERGARRY TO 300M N POWER STATI

Safety Inspection of A82,A87,A887 Safety inspection on 29 March 2019

No defects recorded

Safety Inspection of A82,A87,A887 Safety inspection on 05 April 2019

No defects recorded

Safety Inspection of A82,A87,A887 Safety inspection on 12 April 2019

No defects recorded

Safety Inspection of A82,A87,A887 Safety inspection on 19 April 2019

No defects recorded

## 10877/25 : 300M N POWER STA TO INVERNESS DIV BDY

Safety Inspection of A82,A87,A887 Safety inspection on 29 March 2019

No defects recorded

Safety Inspection of A82,A87,A887 Safety inspection on 05 April 2019

No defects recorded

Safety Inspection of A82,A87,A887 Safety inspection on 12 April 2019

No defects recorded

Safety Inspection of A82,A87,A887 Safety inspection on 19 April 2019

No defects recorded

## 10877/50 : INVERNESS DIV BDY TO 300M S 36ML M/S

Safety Inspection of A82,A87,A887 Safety inspection on 29 March 2019

No defects recorded

Safety Inspection of A82,A87,A887 Safety inspection on 05 April 2019

No defects recorded

Safety Inspection of A82,A87,A887 Safety inspection on 12 April 2019

No defects recorded

Safety Inspection of A82,A87,A887 Safety inspection on 19 April 2019

No defects recorded

# Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 24/03/2019 and 21/04/2019, and defects raised outside of inspections on the same Section(s) during this period.

(Road is 'A82',)  
 (Section Code is 10877/75) Or  
 (Section Code is 10877/90)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>10877/75 : 300M S 36ML M/S TO SPD RESTN SIGN FT AUG</b>									
Safety Inspection of A82,A87,A887 Safety inspection on 29 March 2019									
No defects recorded									
Safety Inspection of A82,A87,A887 Safety inspection on 05 April 2019									
NW125462124-236496777	2,501m	0m	TRAFFIC_SIGNS	Pointing wrong way (RWAY)	CAT 1	06/04/2019	Completed Defects	05/04/2019	SB AFT LOCHUANAGAN
Safety Inspection of A82,A87,A887 Safety inspection on 12 April 2019									
No defects recorded									
Safety Inspection of A82,A87,A887 Safety inspection on 19 April 2019									
NW125480265-236582765	3,698m	0m	TRAFFIC_SIGNS	Pointing wrong way (RWAY)	CAT 1	20/04/2019	Completed Defects	19/04/2019	SB AFT MILLFIELD
<b>10877/90 : SPD RESTN SIGN FT AUG TO B862 FOYERS JUNCTION</b>									
Safety Inspection of A82,A87,A887 Safety inspection on 29 March 2019									
No defects recorded									
Safety Inspection of A82,A87,A887 Safety inspection on 05 April 2019									
NW125462124-236496775	512m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	06/04/2019	Completed Defects	05/04/2019	SB FORT AUGUSTUS
NW125462124-236496776	517m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	06/04/2019	Completed Defects	05/04/2019	NB FT AUGUSTUS
Safety Inspection of A82,A87,A887 Safety inspection on 12 April 2019									
No defects recorded									
Safety Inspection of A82,A87,A887 Safety inspection on 19 April 2019									
No defects recorded									