

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/02/2019 and 30/06/2019, and defects raised outside of inspections on the same Section(s) during this period.

(Road is 'A9'.)
(Section Code is 10422/05) Or

(Section Code is 10422/50) Or

(Section Code is 10424/05) Or

(Section Code is 10424/50)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
10422/05 : WITH: AUCHTERARDER JCT TO ABBEY ROAD BRIDGE									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 04 February 2019									
No defects recorded									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 07 February 2019									
No defects recorded									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 11 February 2019									
No defects recorded									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 14 February 2019									
No defects recorded									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 18 February 2019									
No defects recorded									
NE130433218-236331723	287m	0m	FENCES_AND_BARRIERS	Rotten - Wood fence (RWDF)	CAT 1	21/03/2019	Completed Defects	27/02/2019	OPP LAST STREET LAMP AFTER AUCHTERARDER JCT NB
Safety Inspection of A9 & A90 Keir to Swallow Safety on 25 February 2019									
No defects recorded									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 28 February 2019									
No defects recorded									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 04 March 2019									
No defects recorded									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 07 March 2019									
No defects recorded									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 11 March 2019									
No defects recorded									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 14 March 2019									
No defects recorded									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 18 March 2019									
No defects recorded									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 21 March 2019									
No defects recorded									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 25 March 2019									
No defects recorded									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 28 March 2019									
No defects recorded									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 01 April 2019									
No defects recorded									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 04 April 2019									
No defects recorded									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 08 April 2019									
No defects recorded									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 11 April 2019									
No defects recorded									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 15 April 2019									
No defects recorded									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 18 April 2019									
No defects recorded									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 22 April 2019									
No defects recorded									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 25 April 2019									
No defects recorded									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A9 & A90 Keir to Swallow Safety on 29 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 02 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 06 May 2019									
NE130504822-236631337	2,417m	0m	GULLY	Broken (BROK)	CAT 1	03/06/2019	Completed Defects	14/05/2019	SOUTH OF SCOTISH WATER S/B
Safety Patrol of A9 & A90 Keir to Swallow Safety on 09 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 13 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 16 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 20 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 23 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 27 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 30 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 03 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 06 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 10 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 13 June 2019									
NE122523134-236836978	2,244m	0m	STRUCTURE	Graffiti - Offensive (OFFS)	CAT 1	11/07/2019	Completed Defects	08/07/2019	ABBAY ROAD UNDERPASS AUCHTERARDER
Safety Inspection of A9 & A90 Keir to Swallow Safety on 17 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 20 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 24 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 27 June 2019									
<i>No defects recorded</i>									
10424/05 : WITH: ABBEY ROAD BRIDGE TO A824 JCT ABERUTHVEN									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 04 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 07 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 11 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 14 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 18 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 21 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 25 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 28 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 04 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 07 March 2019									
NE130441630-236344535	532m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	04/04/2019	Completed Defects	28/03/2019	APP AUCHTERARDER WTP NB
Safety Inspection of A9 & A90 Keir to Swallow Safety on 11 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 14 March 2019									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 18 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 21 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 25 March 2019									
NE130455139-236490230	1,648m	0m	SAFETY_FENCE	Accident damage (ACCD)	CAT 1	22/04/2019	Completed Defects	09/04/2019	A9 NB AFTER LAYBY APPROACHING ABERUTHVEN
Safety Patrol of A9 & A90 Keir to Swallow Safety on 28 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 01 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 04 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 08 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 11 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 15 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 18 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 22 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 25 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 29 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 02 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 06 May 2019									
NE130504822-236631338	4,046m	4,046m	TRAFFIC_SIGNS	Missing (MISS)	CAT 1	03/06/2019	Completed Defects	14/05/2019	ABERUTHVEN JUNCTION NB
Safety Patrol of A9 & A90 Keir to Swallow Safety on 09 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 13 May 2019									
NE130506955-236670402	3,579m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	10/06/2019	Completed Defects	03/06/2019	WHITEMOSS XOVER DECELERATION LANE NB
NE130506955-236670403	3,564m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	03/06/2019	WHITEMOSS XOVER DECELERATION LANE NB
NE130506955-236670404	3,572m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHITEMOSS XOVER DECELERATION LANE NB
NE130506955-236670405	3,627m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	10/06/2019	Completed Defects	03/06/2019	WHITEMOSS XOVER DECELERATION LANE NB
NE130506955-236670406	3,624m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	03/06/2019	WHITEMOSS XOVER DECELERATION LANE NB
NE130506955-236670407	3,633m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	03/06/2019	WHITEMOSS XOVER DECELERATION LANE NB
Safety Patrol of A9 & A90 Keir to Swallow Safety on 16 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 20 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 23 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 27 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 30 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 03 June 2019									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 06 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 10 June 2019									
NE122522512-236836983	478m	0m	REMOVE_ANIMAL	Carcass of dead animal (DEAD)	CAT 1	08/07/2019	Completed Defects	10/06/2019	APP WTP AUCHTERARDER NB
Safety Patrol of A9 & A90 Keir to Swallow Safety on 13 June 2019									
NE122523134-236836980	1,401m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	11/07/2019	Completed Defects	05/07/2019	SHINAFOOT UNDERPASS NB
Safety Inspection of A9 & A90 Keir to Swallow Safety on 17 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 20 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 24 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 27 June 2019									
NE122529733-236872150	3,306m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/07/2019	Completed Defects	19/07/2019	APP WHITEMOSS XOVER NB
10424/50 : AGAINST: A824 JCT ABERUTHVEN TO ABBEY ROAD BRIDGE									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 04 February 2019									
NE130429060-236310531	3,077m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	05/02/2019	Completed Defects	04/02/2019	JUST AFTER SHINAFOOT UNDERPASS SB
Safety Patrol of A9 & A90 Keir to Swallow Safety on 07 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 11 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 14 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 18 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 21 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 25 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 28 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 04 March 2019									
NE130437886-236342096	422m	0m	TRAFFIC_SIGNS	Physical condition of fittings (COFT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WHITEMOSS JCT SB
Safety Patrol of A9 & A90 Keir to Swallow Safety on 07 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 11 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 14 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 18 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 21 March 2019									
NE130453066-236488914	610m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	18/04/2019	Completed Defects	09/04/2019	JUST AFTER WHITEMOSS JCT SB
Safety Inspection of A9 & A90 Keir to Swallow Safety on 25 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 28 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 01 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 04 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 08 April 2019									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of A9 & A90 Keir to Swallow Safety on 11 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 15 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 18 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 22 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 25 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 29 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 02 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 06 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 09 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 13 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 16 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 20 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 23 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 27 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 30 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 03 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 06 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 10 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 13 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 17 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 20 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 24 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 27 June 2019									
<i>No defects recorded</i>									

10422/50 : AGAINST: ABBEY ROAD BRIDGE TO AUCHTERARDER JCT

Safety Inspection of A9 & A90 Keir to Swallow Safety on 04 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 07 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 11 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 14 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 18 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 21 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 25 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 28 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 04 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 07 March 2019									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 11 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 14 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 18 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 21 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 25 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 28 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 01 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 04 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 08 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 11 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 15 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 18 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 22 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 25 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 29 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 02 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 06 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 09 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 13 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 16 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 20 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 23 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 27 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 30 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 03 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 06 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 10 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 13 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 17 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 20 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A9 & A90 Keir to Swallow Safety on 24 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A9 & A90 Keir to Swallow Safety on 27 June 2019									
<i>No defects recorded</i>									