

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/01/2017 and 08/01/2020, and defects raised outside of inspections on the same Section(s) during this period.

(Road is 'A830',)
(Section Code is 17208/15)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
17208/15 : DUBH LIGHE BRIDGE TO GLENFINNAN SIGN									
Night Safety Inspection 14 day - Signs and lighting of A830 Scout and Repair on 05 January 2017									
No defects recorded									
Safety Inspection of A86 A830 Safety on 05 January 2017									
No defects recorded									
Retro-reflectivity Inspection - Road Markings of A830 ECODYN on 05 January 2017									
No defects recorded									
Safety Inspection of A86 A830 Safety on 12 January 2017									
No defects recorded									
Night Safety Inspection 14 day - Signs and lighting of A830 Scout and Repair on 19 January 2017									
No defects recorded									
Safety Inspection of A86 A830 Safety on 19 January 2017									
No defects recorded									
Safety Inspection of A86 A830 Safety on 26 January 2017									
No defects recorded									
Night Safety Inspection 14 day - Signs and lighting of A830 Scout and Repair on 02 February 2017									
No defects recorded									
Safety Inspection of A86 A830 Safety on 02 February 2017									
No defects recorded									
Safety Inspection of A86 A830 Safety on 09 February 2017									
No defects recorded									
Detailed Inspection Spring - Drainage Structures of A86 A830 Safety on 10 February 2017									
NWG10240074-3	2,527m	0m	Culvert	Silted (SILT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF G/FINNAN
NWG10240074-4	2,070m	0m	Culvert	Roots present (ROOT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF G/FINBAN
NWG10240074-2	2,674m	0m	Culvert	Free flow impeded (FRFL)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF G/FINNAN
Night Safety Inspection 14 day - Signs and lighting of A830 Scout and Repair on 16 February 2017									
No defects recorded									
Safety Inspection of A86 A830 Safety on 16 February 2017									
No defects recorded									
Safety Inspection of A86 A830 Safety (Awaiting Return)									
No defects recorded									
Night Safety Inspection 14 day - Signs and lighting of A830 Scout and Repair on 02 March 2017									
No defects recorded									
Safety Inspection of A86 A830 Safety on 02 March 2017									
No defects recorded									
Safety Inspection of A86 A830 Safety on 09 March 2017									
No defects recorded									
Night Safety Inspection 14 day - Signs and lighting of A830 Scout and Repair on 16 March 2017									
No defects recorded									
Safety Inspection of A86 A830 Safety on 16 March 2017									
No defects recorded									
Detailed Inspection Spring - Trash screen, etc of A86 A830 Safety on 17 March 2017									
No defects recorded									
Reflective Conspicuity Inspection - Road Studs of A86 A830 Safety on 21 March 2017									
NWG30-248352-7	1,199m	0m	ROAD_STUDS	Missing reflector (MISR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	DUBH LIGHE BR - GLENFINNAN
Safety Inspection of A86 A830 Safety on 23 March 2017									
No defects recorded									
Night Safety Inspection 14 day - Signs and lighting of A830 Scout and Repair on 30 March 2017									
No defects recorded									
Safety Inspection of A86 A830 Safety on 30 March 2017									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 06 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 13 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 20 April 2017									
<i>No defects recorded</i>									
Night Safety Inspection 28 day - Signs and lighting of A830 Scout and Repair on 26 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 27 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 04 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 11 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 18 May 2017									
<i>No defects recorded</i>									
Night Safety Inspection 28 day - Signs and lighting of A830 Scout and Repair on 21 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 25 May 2017									
<i>No defects recorded</i>									
Night Safety Inspection 28 day - Signs and lighting of A830 Scout and Repair on 26 May 2016									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 01 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 08 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 15 June 2017									
<i>No defects recorded</i>									
Night Safety Inspection 28 day - Signs and lighting of A830 Scout and Repair on 18 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 22 June 2017									
NWG23-280285-235211658	1,621m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 2	20/07/2017	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
Safety Inspection of A86 A830 Safety on 29 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 06 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 13 July 2017									
<i>No defects recorded</i>									
Detailed Inspection - Snow Poles etc of A86 A830 Safety on 14 July 2017									
<i>No defects recorded</i>									
Night Safety Inspection 28 day - Signs and lighting of A830 Scout and Repair on 16 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 20 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 27 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 03 August 2017									
NWG16-282787-235292206	549m	593m	CARRIAGEWAY	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	GRAIGIEG BRIDGE
NWG16-282787-235292205	550m	550m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 1	31/08/2017	Completed Defects	11/08/2017	GRAIGIEG BRIDGE
Safety Inspection of A86 A830 Safety on 10 August 2017									
<i>No defects recorded</i>									
Night Safety Inspection 28 day - Signs and lighting of A830 Scout and Repair on 13 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 17 August 2017									
<i>No defects recorded</i>									
Detailed Inspection TEMPLATE of A830 CORPACH JCT TO A861 JUNCTION on 18 August 2017									
NWG23-253076-30	1,776m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF LODGE

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG23-253076-28	1,530m	0m	TREE	Obstructed sightline (OBSL)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	CRAIGAIG LODGE
NWG23-253076-34	2,371m	0m	TREE	Obstructed sightline (OBSL)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF MONUMENT
NWG23-253076-78	498m	0m	VERGE	Dead, dying or damaged areas (DPDY)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BOTH SIDES OF BRIDGE
NWG23-253076-37	2,761m	0m	VERGE	Dead, dying or damaged areas (DPDY)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF MONUMENT
NWG23-253076-76	2,718m	0m	VERGE	Dead, dying or damaged areas (DPDY)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	GLENFINNAN ESTATE
NWG23-253076-25	876m	0m	VERGE	Overhanging/overgrown (OVER)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BRIDGE
NWG23-253076-31	2,001m	0m	VERGE	Overhanging/overgrown (OVER)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF LODGE
NWG23-253076-29	1,661m	0m	VERGE	Overhanging/overgrown (OVER)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF LODGE
NWG23-253076-26	1,020m	0m	BOLLARDS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG
NWG23-253076-77	1,266m	0m	BOLLARDS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	CRAIGNAHA B&B
NWG23-253076-80	498m	0m	CARRIAGEWAY	Flooding (FLOD)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	CRAIGIE BRIDGE
NWG23-253076-75	2,488m	0m	CARRIAGEWAY	Miscellaneous surface Defects (MSRF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	GLENFINNAN ESTATE
NWG23-253076-36	2,625m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF MONUMENT
NWG23-253076-79	509m	0m	DITCH	Obstruction (OBST)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	CRAIGIE BRIDGE
NWG23-253076-24	107m	0m	DITCH	Silted (SILT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	CRAIGAG FORST
NWG23-253076-74	2,027m	0m	FILTER_DRAIN	Silted (SILT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	GLENFINNAN ESTATE
NWG23-253076-32	2,034m	0m	FILTER_DRAIN	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF LODGE
NWG23-253076-33	2,310m	0m	FILTER_DRAIN	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF MONUMENT
NWG23-253076-27	1,269m	0m	FILTER_DRAIN	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	CRAIGAIG LODGE
NWG23-253076-35	2,435m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF MONUMENT

Detailed Inspection - Covers, Gratings and Frames of A830 CORPACH JCT TO A861 JUNCTION

No defects recorded

Detailed Inspection - Vehicle Restraint Systems of A830 CORPACH JCT TO A861 JUNCTION

No defects recorded

Alternative Inspection - Road Markings of A830 CORPACH JCT TO A861 JUNCTION

No defects recorded

Annual Detailed Inspection - Carriageways of A830 CORPACH JCT TO A861 JUNCTION

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Annual Detailed Inspection - Drainage Grips of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspect - Inlet and Outlet - Wetland Areas of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection - All other Footways of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection - All signs of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection - Bulb and Wildflower Areas of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection - Ditches of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection - Fences, Walls, Screens etc of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection - Filter Drains and Soakaways of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection - Geotechnical Assets of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection - Headwalls, aprons and spillway of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection - Invasive Species of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection - Kerbs, Channels, Edgings of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection - Linear Drainage Systems of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection - Node Markers of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection - Pedestrian Restraint Systems of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection - Scrub, shrub and hedges of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection - Silt Depth - Wetland Areas of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection - Snow Poles etc of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection - Traffic Control Barriers of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection - Traffic Signals of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection - Woodland areas and Trees of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection Autumn - Drainage Structures of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection Autumn - Trash screen, etc of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection growing season - Grassed Areas of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 24 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 31 August 2017									
NWG23-283871-235351498	626m	0m	DITCH	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	CRAIGIE BRIDGE, WEST
NWG23-283871-235351499	533m	0m	DITCH	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	CRAIGIE DITCH
Safety Inspection of A86 A830 Safety on 07 September 2017									
<i>No defects recorded</i>									
Night Safety Inspection 28 day - Signs and lighting of A830 Scout and Repair on 10 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 14 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 21 September 2017									
<i>No defects recorded</i>									
Night Safety Inspection 14 day - Signs and lighting of A830 Scout and Repair on 25 September 2017									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 28 September 2017									
<i>No defects recorded</i>									
Reflective Conspicuity Inspection - Road Studs of A86 A830 Safety on 03 October 2017									
NWG10284891-22	2,864m	0m	ROAD_STUDS	Damaged stud (DAMS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	GLENFINNAN SIGN
NWG10284891-23	12m	0m	ROAD_STUDS	Damaged stud (DAMS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	DUBH LIGHE
Safety Inspection of A86 A830 Safety on 05 October 2017									
<i>No defects recorded</i>									
Night Safety Inspection 14 day - Signs and lighting of A830 Scout and Repair on 11 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 12 October 2017									
NWG23-315304-235427429	1,834m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	13/10/2017	Awaiting CCMS Permanent Date	12/10/2017	W OF GLENFINNAN
Safety Inspection of A86 A830 Safety on 19 October 2017									
<i>No defects recorded</i>									
Detailed Inspection Autumn - Trash screen, etc of A86 A830 Safety on 20 October 2017									
<i>No defects recorded</i>									
Detailed Inspection Autumn - Drainage Structures of A86 A830 Safety on 20 October 2017									
<i>No defects recorded</i>									
Night Safety Inspection 14 day - Signs and lighting of A830 Scout and Repair on 24 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 26 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 02 November 2017									
<i>No defects recorded</i>									
Night Safety Inspection 14 day - Signs and lighting of A830 Scout and Repair on 07 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 09 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 16 November 2017									
<i>No defects recorded</i>									
Night Safety Inspection 14 day - Signs and lighting of A830 Scout and Repair on 20 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 23 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 30 November 2017									
<i>No defects recorded</i>									
Night Safety Inspection 14 day - Signs and lighting of A830 Scout and Repair on 03 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 07 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 14 December 2017									
<i>No defects recorded</i>									
Night Safety Inspection 14 day - Signs and lighting of A830 Scout and Repair on 17 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 21 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 28 December 2017									
NWG23-317068-235513190	2,799m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/01/2018	Completed Defects	25/01/2018	GLENFINNAN
Night Safety Inspection 14 day - Signs and lighting of A830 Scout and Repair on 31 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 04 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 11 January 2018									
<i>No defects recorded</i>									
Night Safety Inspection 14 day - Signs and lighting of A830 Scout and Repair on 14 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 18 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 25 January 2018									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG23-317731-235528828	1,428m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	26/01/2018	Completed Defects	25/01/2018	GLENFINNAN
Night Safety Inspection 14 day - Signs and lighting of A830 Scout and Repair on 28 January 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 01 February 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 08 February 2018									
No defects recorded									
Night Safety Inspection 14 day - Signs and lighting of A830 Scout and Repair on 11 February 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 15 February 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 22 February 2018									
No defects recorded									
Night Safety Inspection 14 day - Signs and lighting of A830 Scout and Repair on 25 February 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 01 March 2018									
No defects recorded									
Reflective Conspicuity Inspection - Road Studs of A86 A830 Safety on 03 March 2018									
NWG23-324376-32	2,789m	0m	ROAD_STUDS	Damaged stud (DAMS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	GLENFINNAN
Safety Inspection of A86 A830 Safety on 08 March 2018									
No defects recorded									
Night Safety Inspection 14 day - Signs and lighting of A830 Scout and Repair on 11 March 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 15 March 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 22 March 2018									
No defects recorded									
Night Safety Inspection 14 day - Signs and lighting of A830 Scout and Repair on 25 March 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 29 March 2018									
NWG23-330670-235608544	1,570m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	26/04/2018	Completed Defects	09/04/2018	EAST OF GLENFINNAN
Retro-reflectivity Inspection - Road Markings of A830 ECODYN on 30 March 2018									
No defects recorded									
Specialist Inspection - Woodland Areas and Trees of NW TREE 5Y on 30 March 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 05 April 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 12 April 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 18 April 2018									
No defects recorded									
Night Safety Inspection 28 day - Signs and lighting of A830 Scout and Repair on 22 April 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 26 April 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 03 May 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 10 May 2018									
NW34344798-235690388	1,636m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/05/2018	Completed Defects	10/05/2018	EAST OF GLENFINNAN
NW34344798-235690389	1,623m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/05/2018	Completed Defects	10/05/2018	EAST OF GLENFINNAN
NW34344798-235690387	1,659m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 1	07/06/2018	Completed Defects	06/06/2018	EAST OF GLENFINNAN
Safety Inspection of A86 A830 Safety on 17 May 2018									
NW34347684-235731409	1,420m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
Night Safety Inspection 28 day - Signs and lighting of A830 Scout and Repair on 20 May 2018									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 24 May 2018									
NW35350737-235800687	2,570m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	25/05/2018	Completed Defects	24/05/2018	CAIRN
Safety Inspection of A86 A830 Safety on 31 May 2018									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 07 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 14 June 2018									
NW34360540-235830754	1,698m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	15/06/2018	Completed Defects	14/06/2018	EAST OF GLENFINNAN
NW34360540-235830755	1,694m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	15/06/2018	Completed Defects	14/06/2018	EAST OF GLENFINNAN
NW34360540-235830756	1,701m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34360540-235830757	1,710m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34360540-235830753	1,778m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
Night Safety Inspection 28 day - Signs and lighting of A830 Scout and Repair on 17 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 20 June 2018									
NW34364648-235853310	1,232m	0m	TRAFFIC_SIGNS	Pointing wrong way (RWAY)	CAT 1	21/06/2018	Completed Defects	20/06/2018	EAST OF GLENFINNAN
NW34364648-235853320	873m	0m	TRAFFIC_SIGNS	Physical condition of fittings (COFT)	CAT 1	21/06/2018	Completed Defects	20/06/2018	EAST OF GLENFINNAN
Safety Inspection of A86 A830 Safety on 27 June 2018									
<i>No defects recorded</i>									
Detailed Inspection - Snow Poles etc of A86 A830 Safety on 29 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 04 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 11 July 2018									
<i>No defects recorded</i>									
Night Safety Inspection 28 day - Signs and lighting of A830 Scout and Repair on 15 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 18 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 25 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 01 August 2018									
<i>No defects recorded</i>									
Detailed Inspection TEMPLATE of A830 CORPACH JCT TO A861 JUNCTION on 24 July 2018									
NW35328937-869	1,787m	0m	BOLLARDS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	GLENFINNAN EST.
NW35328937-864	1,315m	0m	BOLLARDS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	CRAIGAG LODGE
NW35328937-863	986m	0m	BOLLARDS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	N OF CRAIGIE BR
NW35328937-862	910m	0m	BOLLARDS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	N OF CRAIGIE BR.
NW35328937-866	1,559m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	GLENFINNAN EST.

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW35328937-858	179m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	NORTH OF DUBH LIGHE BRIDGE
NW35328937-861	906m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	N OF CRAIGIE BRIDGE
NW35328937-867	1,710m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	GLENFINNAN EST
NW35328937-865	1,427m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	CRAIGAG LODGE
NW35328937-872	2,714m	0m	FILTER_DRAIN	Filter material displaced (FMDS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	GLENFINNAN EST
NW35328937-871	1,986m	0m	MANHOLE	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	GLENFINNAN EST
NW35328937-859	907m	0m	ROAD_MARKINGS_HATCHED	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	CRAIGIE BRIDGE
NW35328937-860	907m	0m	ROAD_MARKINGS_HATCHED	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	CRAIGIE BRIDGE
NW35328937-868	1,785m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	GLENFINNAN EST
NW35328937-857	179m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	N OF LIBH DBH BD
NW35328937-870	1,784m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	GLENFINNAN EST

Detailed Inspection - Covers, Gratings and Frames of A830 CORPACH JCT TO A861 JUNCTION

No defects recorded

Detailed Inspection - Vehicle Restraint Systems of A830 CORPACH JCT TO A861 JUNCTION

No defects recorded

Alternative Inspection - Road Markings of A830 CORPACH JCT TO A861 JUNCTION

No defects recorded

Annual Detailed Inspection - Carriageways of A830 CORPACH JCT TO A861 JUNCTION

No defects recorded

Annual Detailed Inspection - Drainage Grips of A830 CORPACH JCT TO A861 JUNCTION

No defects recorded

Detailed Inspect - Inlet and Outlet - Wetland Areas of A830 CORPACH JCT TO A861 JUNCTION

No defects recorded

Detailed Inspection - All other Footways of A830 CORPACH JCT TO A861 JUNCTION

No defects recorded

Detailed Inspection - All signs of A830 CORPACH JCT TO A861 JUNCTION

No defects recorded

Detailed Inspection - Bulb and Wildflower Areas of A830 CORPACH JCT TO A861 JUNCTION

No defects recorded

Detailed Inspection - Ditches of A830 CORPACH JCT TO A861 JUNCTION

No defects recorded

Detailed Inspection - Fences, Walls, Screens etc of A830 CORPACH JCT TO A861 JUNCTION

No defects recorded

Detailed Inspection - Filter Drains and Soakaways of A830 CORPACH JCT TO A861 JUNCTION

No defects recorded

Detailed Inspection - Geotechnical Assets of A830 CORPACH JCT TO A861 JUNCTION

No defects recorded

Detailed Inspection - Headwalls, aprons and spillway of A830 CORPACH JCT TO A861 JUNCTION

No defects recorded

Detailed Inspection - Invasive Species of A830 CORPACH JCT TO A861 JUNCTION

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Detailed Inspection - Kerbs, Channels, Edgings of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection - Linear Drainage Systems of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection - Node Markers of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection - Pedestrian Restraint Systems of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection - Scrub, shrub and hedges of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection - Silt Depth - Wetland Areas of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection - Traffic Control Barriers of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection - Traffic Signals of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection - Woodland areas and Trees of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection Autumn - Drainage Structures of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection Autumn - Trash screen, etc of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection growing season - Grassed Areas of A830 CORPACH JCT TO A861 JUNCTION									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 08 August 2018									
<i>No defects recorded</i>									
Night Safety Inspection 28 day - Signs and lighting of A830 Scout and Repair on 12 August 2018									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 15 August 2018									
<i>No defects recorded</i>									
Detailed Inspection - Vehicle Restraint Systems of A830 CORPACH - MALLAIG BARRIER INSPECTION on 16 August 2018									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 22 August 2018									
NW34394971-235969995	515m	0m	STRUCTURE	Graffiti - Offensive (OFFS)	CAT 1	19/09/2018	Completed Defects	22/08/2018	CRAIGIEBRIDGE
NW34394971-235970012	1,397m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	23/08/2018	Completed Defects	22/08/2018	1 MILE EAST OF GLENFINNAN
NW34394971-235970013	1,421m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	23/08/2018	Completed Defects	22/08/2018	1 MILE EAST OF GLENFINNAN
NW34394971-235970014	1,421m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	23/08/2018	Completed Defects	22/08/2018	1 MILE EAST OF GLENFINNAN
NW34394971-235970011	1,614m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 1	19/09/2018	Completed Defects	17/09/2018	1 MILE EAST OF GLENFINNAN
Safety Inspection of A86 A830 Safety on 29 August 2018									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 05 September 2018									
<i>No defects recorded</i>									
Night Safety Inspection 28 day - Signs and lighting of A830 Scout and Repair on 09 September 2018									
<i>No defects recorded</i>									
Detailed Inspection - Traffic Signals of NW ALL ROUTES on 09 September 2018									
<i>No defects recorded</i>									
Detailed Inspection Items 1-12 - Traffic Signals of NW ALL ROUTES on 10 September 2018									
<i>No defects recorded</i>									
Detailed Inspections (labelling) - Traffic Signals of NW ALL ROUTES on 10 September 2018									
<i>No defects recorded</i>									
Annual Operational Review - Traffic Signals of NW ALL ROUTES on 10 September 2018									
<i>No defects recorded</i>									
Detailed Inspection TEMPLATE of A86 A830 Safety on 11 September 2018									
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 12 September 2018									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW34404869-236054213	1,623m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	13/09/2018	Completed Defects	12/09/2018	EAST OF GLENFINNAN
NW34404869-236054214	1,622m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34404869-236054215	1,984m	0m	MANHOLE	Collapsed (COLP)	3RD PTY	10/10/2018	Awaiting CCMS Temp Date	01/01/9999	EAST OF GLENFINNAN
NW34404869-236054218	1,784m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	CRAIGAG COTTAGE
Safety Inspection of A86 A830 Safety on 19 September 2018									
NW34408058-236060198	507m	0m	VERGE	Fly tipping/illegal dumping (FTIP)	3RD PTY	17/10/2018	Awaiting CCMS Temp Date	01/01/9999	CRAIGIEBRIDGE
NW34408058-236060197	873m	0m	TRAFFIC_SIGNS	Physical condition of fittings (COFT)	CAT 1	20/09/2018	Completed Defects	19/09/2018	CRAIGAG
Safety Inspection of A86 A830 Safety on 26 September 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 03 October 2018									
NW38414543-236101540	1,420m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/10/2018	Completed Defects	03/10/2018	CRAIGAG LODGE
Night Safety Inspection 14 day - Signs and lighting of A830 Scout and Repair on 07 October 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 10 October 2018									
No defects recorded									
Detailed Inspection Items 1-12 - Traffic Signals of NW ALL ROUTES on 12 October 2018									
No defects recorded									
Detailed Inspections (labelling) - Traffic Signals of NW ALL ROUTES on 07 October 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 17 October 2018									
No defects recorded									
Night Safety Inspection 14 day - Signs and lighting of A830 Scout and Repair on 21 October 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 24 October 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 31 October 2018									
No defects recorded									
Night Safety Inspection 14 day - Signs and lighting of A830 Scout and Repair on 04 November 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 07 November 2018									
No defects recorded									
Reflective Conspicuity Inspection - Road Studs of A830,A82 Linining, studs on 12 November 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 14 November 2018									
No defects recorded									
Night Safety Inspection 14 day - Signs and lighting of A830 Scout and Repair on 18 November 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 21 November 2018									
No defects recorded									
Detailed Inspection Items 1-12 - Traffic Signals of NW ALL ROUTES on 21 November 2018									
No defects recorded									
Detailed Inspections (labelling) - Traffic Signals of NW ALL ROUTES on 21 November 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 28 November 2018									
No defects recorded									
Night Safety Inspection 14 day - Signs and lighting of A830 Scout and Repair on 02 December 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 05 December 2018									
No defects recorded									
Safety Inspection of A86 A830 Safety on 12 December 2018									
No defects recorded									
Night Safety Inspection 14 day - Signs and lighting of A830 Scout and Repair on 16 December 2018									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of A86 A830 Safety on 19 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 21 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 28 December 2018									
<i>No defects recorded</i>									
Night Safety Inspection 14 day - Signs and lighting of A830 Scout and Repair on 30 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 04 January 2019									
<i>No defects recorded</i>									
Detailed Inspection - Network Referencing of Network Referencing A830 on 08 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 10 January 2019									
NW34428008-236271126	495m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 1	11/01/2019	Completed Defects	10/01/2019	CRAIGIEBRIDGE
NW34428008-236271121	1,607m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/01/2019	Completed Defects	10/01/2019	GLENFINNAN
NW34428008-236271124	1,428m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/01/2019	Completed Defects	10/01/2019	GLENFINNAN
NW34428008-236271125	1,419m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/01/2019	Completed Defects	10/01/2019	GLENFINNAN
Night Safety Inspection 14 day - Signs and lighting of A830 Scout and Repair on 13 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 17 January 2019									
NW34428196-236276058	1,457m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/01/2019	Completed Defects	17/01/2019	GLENFINNAN
NW34428196-236276059	1,430m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/01/2019	Completed Defects	17/01/2019	GLENFINNAN
NW34428196-236276060	1,515m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/01/2019	Completed Defects	17/01/2019	GLENFINNAN
Safety Inspection of A830,A82 Safety inspection short on 24 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 31 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 07 February 2019									
<i>No defects recorded</i>									
Detailed Inspection Spring - Drainage Structures of A86 A830 Safety (Awaiting Return)									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 14 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 20 February 2019									
NW34432281-236330981	1,664m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	21/02/2019	Completed Defects	20/02/2019	CRAIGAG LODGE
Detailed Inspection Spring - Trash screen, etc of A86 A830 Safety (Awaiting Return)									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 27 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 06 March 2019									
NW34440020-236341781	1,657m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	07/03/2019	Completed Defects	06/03/2019	CRAIGAG LODGE
Safety Inspection of A830,A82 Safety inspection short on 13 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 20 March 2019									
<i>No defects recorded</i>									
Reflective Conspicuity Inspection - Road Studs of A82.A830 ROAD STUDS on 26 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 27 March 2019									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A830,A82 Safety inspection short on 03 April 2019									
NW35466196-236493948	1,660m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN E/B
NW35466196-236493950	1,627m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN E/B
NW35466196-236493945	1,703m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN E/B
NW35466196-236493946	1,686m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN E/B
NW35466196-236493943	1,712m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 1	01/05/2019	Completed Defects	22/04/2019	EAST OF GLENFINNAN E/B
NW35466196-236493944	1,696m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/05/2019	Completed Defects	22/04/2019	EAST OF GLENFINNAN E/B
NW35466196-236493947	1,660m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/05/2019	Completed Defects	22/04/2019	EAST OF GLENFINNAN W/B
NW35466196-236493949	1,622m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/05/2019	Completed Defects	22/04/2019	EAST OF GLENFINNAN W/B
Safety Inspection of A830,A82 Safety inspection short on 10 April 2019									
NW34474665-236531691	1,424m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/05/2019	Awaiting CCMS Temp Date	01/01/9999	EAST OF GLENFINNAN W/B
Night Safety Inspection 28 day - Signs and lighting of A830 All on 16 April 2019									
No defects recorded									
Safety Inspection of A830,A82 Safety inspection short on 17 April 2019									
No defects recorded									
Safety Inspection of A830,A82 Safety inspection short on 24 April 2019									
No defects recorded									
Safety Inspection of A830,A82 Safety inspection short on 01 May 2019									
No defects recorded									
Safety Inspection of A830,A82 Safety inspection short on 08 May 2019									
No defects recorded									
Night Safety Inspection 28 day - Signs and lighting of ELEC NW R6 on 14 May 2019									
No defects recorded									
Detailed Inspection Items 1-12 - Traffic Signals of ELEC NW R6 on 14 May 2019									
No defects recorded									
Safety Inspection of A830,A82 Safety inspection short on 15 May 2019									
No defects recorded									
Safety Inspection of A830,A82 Safety inspection short on 22 May 2019									
No defects recorded									
Safety Inspection of A830,A82 Safety inspection short on 29 May 2019									
NW34514366-236805978	1,695m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 1	26/06/2019	Completed Defects	26/06/2019	EAST OF GLENFINNAN
NW34514366-236805982	1,258m	0m	VERGE	Dead, dying or damaged areas (DPDY)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34514366-236805975	1,576m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	30/05/2019	Completed Defects	29/05/2019	EAST OF GLENFINNAN
NW34514366-236805979	1,661m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	30/05/2019	Completed Defects	29/05/2019	EAST OF GLENFINNAN

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW34514366-236805980	1,503m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	30/05/2019	Completed Defects	29/05/2019	EAST OF GLENFINNAN
NW34514366-236805981	1,420m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	26/06/2019	Completed Defects	26/06/2019	EAST OF GLENFINNAN
NW34514366-236805976	1,713m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	26/06/2019	Completed Defects	26/06/2019	EAST OF GLENFINNAN
NW34514366-236805973	1,604m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	26/06/2019	Completed Defects	26/06/2019	EAST OF GLEN FINNAN
NW34514366-236805974	1,594m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	26/06/2019	Completed Defects	26/06/2019	EAST OF GLENFINNAN
NW34514366-236805977	1,705m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
Alternative Inspection - Road Markings of CORP 06 A830									
No defects recorded									
Annual Detailed Inspection - Carriageways of CORP 06 A830									
No defects recorded									
Annual Detailed Inspection - Drainage Grips of CORP 06 A830									
No defects recorded									
Detailed Inspection - All other Footways of CORP 06 A830									
No defects recorded									
Detailed Inspection - All signs of CORP 06 A830									
No defects recorded									
Detailed Inspection - Bulb and Wildflower Areas of CORP 06 A830									
No defects recorded									
Detailed Inspection - Covers, Gratings and Frames of CORP 06 A830									
No defects recorded									
Detailed Inspection - Ditches of CORP 06 A830									
No defects recorded									
Detailed Inspection - Fences, Walls, Screens etc of CORP 06 A830									
No defects recorded									
Detailed Inspection - Filter Drains and Soakaways of CORP 06 A830									
No defects recorded									
Detailed Inspection - Geotechnical Assets of CORP 06 A830									
No defects recorded									
Detailed Inspection - Invasive Species of CORP 06 A830									
No defects recorded									
Detailed Inspection - Kerbs, Channels, Edgings of CORP 06 A830									
No defects recorded									
Detailed Inspection - Linear Drainage Systems of CORP 06 A830									
No defects recorded									
Detailed Inspection - Node Markers of CORP 06 A830									
No defects recorded									
Detailed Inspection - Pedestrian Restraint Systems of CORP 06 A830									
No defects recorded									
Detailed Inspection - Scrub, shrub and hedges of CORP 06 A830									
No defects recorded									
Detailed Inspection - Woodland areas and Trees of CORP 06 A830									
No defects recorded									
Detailed Inspection growing season - Grassed Areas of CORP 06 A830									
No defects recorded									
Detailed Inspection TEMPLATE of CORP 06 A830 on 03 June 2019									
NW34510567-174	2,660m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-175	2,662m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-149	2,385m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW34510567-151	2,398m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-152	2,408m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-153	2,422m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-154	2,437m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-155	2,446m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-156	2,455m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-157	2,464m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-158	2,471m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-187	2,724m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-188	2,731m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-189	2,740m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-185	2,709m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW35510567-127	496m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. E/B
NW35510567-122	459m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. E/B
NW35510567-123	478m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. W/B
NW35510567-101	180m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. W/B
NW35510567-115	330m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. E/B
NW35510567-116	333m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. W/B
NW35510567-209	1,611m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-223	1,729m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN W/B
NW35510567-221	1,701m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN W/B
NW35510567-227	1,743m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN W/B
NW35510567-225	1,731m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN W/B

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW35510567-147	873m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-172	1,364m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW34510567-171	2,630m	0m	TRAFFIC_SIGNS	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-124	1,973m	0m	TRAFFIC_SIGNS	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-127	1,986m	0m	TRAFFIC_SIGNS	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-126	1,976m	0m	VERGE	Dead, dying or damaged areas (DPDY)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-129	2,042m	0m	VERGE	Dead, dying or damaged areas (DPDY)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-191	2,766m	0m	VERGE	Dead, dying or damaged areas (DPDY)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-135	2,140m	0m	PIPED_DRAINAGE	Broken (BROK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW35510567-90	53m	0m	BOLLARDS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF DROCHAID SGAINNIR E/B
NW35510567-93	69m	0m	BOLLARDS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF DROCHAID SGAINNIR E/B
NW35510567-94	115m	0m	BOLLARDS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. E/B
NW35510567-166	1,220m	0m	BOLLARDS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. E/B
NW35510567-96	143m	0m	BOLLARDS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. E/B
NW35510567-169	1,239m	0m	BOLLARDS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. E/B
NW35510567-180	1,415m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-186	1,461m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-196	1,501m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. E/B
NW35510567-197	1,515m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-199	1,531m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW35510567-202	1,563m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-207	1,601m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2				WEST OF CRAIGAG BR. W/B
NW35510567-210	1,624m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. E/B
NW35510567-211	1,624m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. E/B
NW35510567-213	1,655m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN W/B
NW35510567-219	1,698m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN E/B
NW35510567-220	1,700m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN E/B
NW34510567-198	2,866m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	GLENFINNAN
NW35510567-215	1,669m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN W/B
NW35510567-216	1,670m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN E/B
NW35510567-232	1,848m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN W/B
NW35510567-233	1,849m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN E/B
NW35510567-205	1,584m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-206	1,584m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. E/B
NW35510567-189	1,475m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-190	1,475m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. E/B
NW35510567-178	1,414m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. E/B
NW35510567-179	1,414m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. E/B
NW35510567-138	614m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. E/B

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW34510567-146	2,341m	0m	CARRIAGEWAY	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-163	2,522m	0m	Culvert	Standing water (STWT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-192	2,774m	0m	Culvert	Silted (SILT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-177	2,671m	0m	Culvert	Silted (SILT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-196	2,814m	0m	Culvert	Scour (SCOR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-183	2,711m	0m	FILTER_DRAIN	Silted (SILT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-166	2,568m	0m	GRIP	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-167	2,586m	0m	GRIP	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-194	2,801m	0m	GRIP	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW35510567-204	1,581m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-200	1,553m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-198	1,516m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-194	1,497m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-160	1,130m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. E/B
NW35510567-181	1,420m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-183	1,437m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-185	1,455m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-235	1,873m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN W/B
NW35510567-237	1,888m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN W/B
NW35510567-239	1,951m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN W/B
NW35510567-217	1,671m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN E/B
NW35510567-188	1,470m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-230	1,794m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN E/B

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW35510567-117	336m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. W/B
NW35510567-118	343m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. W/B
NW35510567-119	446m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. W/B
NW35510567-121	458m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. W/B
NW35510567-104	199m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. W/B
NW35510567-105	209m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. W/B
NW35510567-106	219m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. W/B
NW35510567-107	228m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. E/B
NW35510567-108	236m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. W/B
NW35510567-109	253m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. W/B
NW35510567-110	265m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. W/B
NW35510567-102	190m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. W/B
NW35510567-113	287m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. W/B
NW35510567-114	310m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. W/B
NW35510567-88	27m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF DROCHAID SGAINNIR W/B
NW35510567-91	53m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF DROCHAID SGAINNIR W/B
NW35510567-92	62m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF DROCHAID SGAINNIR W/B
NW35510567-143	782m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. E/B
NW35510567-144	800m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. E/B
NW35510567-145	872m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. E/B
NW35510567-95	120m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. W/B
NW35510567-153	1,019m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. E/B
NW35510567-156	1,062m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. E/B

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW35510567-163	1,161m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. E/B
NW35510567-174	1,371m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW34510567-164	2,544m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-165	2,564m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-144	2,290m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-150	2,385m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW35510567-165	1,183m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. E/B
NW35510567-97	154m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. W/B
NW34510567-195	2,813m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-138	2,220m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-142	2,272m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-134	2,138m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-125	1,972m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-145	2,313m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-147	2,344m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW35510567-184	1,442m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-191	1,480m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-192	1,481m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-201	1,554m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW35510567-208	1,601m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-214	1,658m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN W/B
NW35510567-212	1,636m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. E/B
NW35510567-241	1,971m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN W/B
NW34510567-190	2,732m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW35510567-170	1,284m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-234	1,863m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN W/B
NW35510567-136	594m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-129	500m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. E/B
NW35510567-130	512m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. W/B
NW35510567-120	452m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. W/B
NW35510567-142	687m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-175	1,397m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-176	1,400m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. /B
NW35510567-112	269m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. W/B
NW35510567-100	179m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. W/B

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW35510567-139	644m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. E/B
NW35510567-140	645m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-141	679m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. E/B
NW35510567-131	529m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. E/B
NW35510567-125	484m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. W/B
NW35510567-171	1,313m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. E/B
NW35510567-167	1,223m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-168	1,229m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-238	1,926m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN E/B
NW34510567-193	2,792m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-130	2,072m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-128	2,019m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW35510567-87	3m	0m	ROAD_STUDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF DROCHAID SGAINNIR W/B
NW35510567-134	574m	0m	ROAD_STUDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-203	1,562m	0m	ROAD_STUDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW34510567-143	2,275m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-184	2,710m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-173	2,649m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW35510567-158	1,078m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-154	1,036m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-148	927m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-149	971m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-89	41m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF DROCHAID SGAINNIR E/B
NW35510567-103	195m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. E/B
NW35510567-99	176m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. E/B
NW35510567-111	265m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. E/B
NW35510567-135	586m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-229	1,750m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN W/B
NW35510567-152	997m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-161	1,130m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW34510567-139	2,239m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-140	2,257m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-141	2,269m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-181	2,694m	0m	TRAFFIC_SIGNS	Physical condition of fittings (COFT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-176	2,664m	0m	TRAFFIC_SIGNS	Physical condition of fittings (COFT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW35510567-98	165m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. E/B
NW35510567-173	1,369m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-159	1,092m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-157	1,070m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-150	985m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW35510567-124	481m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. W/B
NW35510567-128	500m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. E/B
NW35510567-146	872m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-126	496m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CRAIGAG BR. E/B
NW35510567-132	566m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-133	566m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. E/B
NW35510567-137	598m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. E/B
NW35510567-240	1,968m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN W/B
NW35510567-228	1,748m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN W/B
NW35510567-224	1,729m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN W/B
NW35510567-226	1,732m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN W/B
NW35510567-231	1,843m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN E/B
NW35510567-218	1,695m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN W/B
NW35510567-222	1,708m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN W/B
NW35510567-236	1,879m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN E/B
NW35510567-195	1,504m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. E/B
NW35510567-193	1,491m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. E/B
NW35510567-187	1,465m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. E/B
NW35510567-182	1,431m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. E/B
NW35510567-162	1,135m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-155	1,047m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW35510567-151	986m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW35510567-177	1,399m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. E/B
NW34510567-182	2,698m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW35510567-164	1,164m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF CRAIGAG BR. W/B
NW34510567-197	2,837m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-178	2,677m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-179	2,683m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-180	2,693m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-186	2,715m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-148	2,375m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-136	2,149m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-137	2,222m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-168	2,606m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-169	2,614m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-170	2,623m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-172	2,638m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-159	2,489m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-160	2,499m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-161	2,512m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-162	2,528m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-131	2,113m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW34510567-132	2,115m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-133	2,124m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
NW34510567-123	1,971m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF GLENFINNAN
Safety Inspection of A830,A82 Safety inspection short on 05 June 2019									
<i>No defects recorded</i>									
Detailed Inspection - Snow Poles etc of A830,A82 Safety inspection short on 03 June 2019									
<i>No defects recorded</i>									
Night Safety Inspection 28 day - Signs and lighting of ELEC NW R6 on 11 June 2019									
<i>No defects recorded</i>									
Detailed Inspection Items 1-12 - Traffic Signals of ELEC NW R6 on 11 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 12 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 19 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 26 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 03 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 10 July 2019									
<i>No defects recorded</i>									
Night Safety Inspection 28 day - Signs and lighting of ELEC NW R6 on 10 July 2019									
<i>No defects recorded</i>									
Detailed Inspection Items 1-12 - Traffic Signals of ELEC NW R6 on 10 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 17 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 24 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 31 July 2019									
NW34531635-236920304	2,861m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 1	28/08/2019	Completed Defects	12/08/2019	GLENFINNAN
Safety Inspection of A830,A82 Safety inspection short on 07 August 2019									
<i>No defects recorded</i>									
Night Safety Inspection 28 day - Signs and lighting of ELEC NW R6 on 07 August 2019									
<i>No defects recorded</i>									
Detailed Inspection Items 1-12 - Traffic Signals of ELEC NW R6 on 07 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 14 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 21 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 28 August 2019									
<i>No defects recorded</i>									
Retro-reflectivity Inspection - Road Markings of A830 ECODYNE AUG 19 on 31 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 04 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 11 September 2019									
<i>No defects recorded</i>									
Night Safety Inspection 14 day - Signs and lighting of ELEC NW R6 on 17 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 18 September 2019									
<i>No defects recorded</i>									
Night Safety Inspection 28 day - Signs and lighting of ELEC NW R6 on 18 September 2019									
<i>No defects recorded</i>									
Detailed Inspection Items 1-12 - Traffic Signals of ELEC NW R6 on 18 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 25 September 2019									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Night Safety Inspection 14 day - Signs and lighting of ELEC NW R6 on 01 October 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 01 October 2019									
<i>No defects recorded</i>									
Detailed Inspection - All signs of A830 signs TR22 2019 on 03 October 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 08 October 2019									
<i>No defects recorded</i>									
Night Safety Inspection 14 day - Signs and lighting of ELEC NW R6 on 15 October 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 15 October 2019									
<i>No defects recorded</i>									
Detailed Inspection Items 1-12 - Traffic Signals of ELEC NW R6 on 15 October 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 22 October 2019									
<i>No defects recorded</i>									
Signplate replacement and visual performance - Signs of A83 A830 SIGN REFLECTIVITY on 23 October 2019									
<i>No defects recorded</i>									
Night Safety Inspection 14 day - Signs and lighting of ELEC NW R6 on 29 October 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 29 October 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 05 November 2019									
NWG25536243-237100385	1,136m	0m	BOLLARDS	Damaged (DAMG)	CAT 1	03/12/2019	Completed Defects	21/11/2019	NB BFR CRAIGAG LODGE
NWG25536243-237100384	909m	0m	ROAD_STUDS	Missing "catseye" (MISC)	CAT 1	03/12/2019	Awaiting CCMS Permanent Date	01/01/9999	NB AFT RAILWAY BR
Night Safety Inspection 14 day - Signs and lighting of ELEC NW R6 on 12 November 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 12 November 2019									
<i>No defects recorded</i>									
Detailed Inspection Items 1-12 - Traffic Signals of ELEC NW R6 on 12 November 2019									
<i>No defects recorded</i>									
Detailed Inspections (labelling) - Traffic Signals of ELEC NW R6 on 12 November 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 19 November 2019									
<i>No defects recorded</i>									
Night Safety Inspection 14 day - Signs and lighting of ELEC NW R6 on 26 November 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 26 November 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 03 December 2019									
<i>No defects recorded</i>									
Night Safety Inspection 14 day - Signs and lighting of ELEC NW R6 on 10 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 10 December 2019									
<i>No defects recorded</i>									
Detailed Inspection Items 1-12 - Traffic Signals of ELEC NW R6 on 10 December 2019									
<i>No defects recorded</i>									
Detailed Inspections (labelling) - Traffic Signals of ELEC NW R6 on 10 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 17 December 2019									
<i>No defects recorded</i>									
Night Safety Inspection 14 day - Signs and lighting of ELEC NW R6 on 24 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 24 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 31 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A830,A82 Safety inspection short on 07 January 2020									
<i>No defects recorded</i>									