

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/06/2014 and 30/06/2016, and defects raised outside of inspections on the same Section(s) during this period.

(Road is 'A7'.)
(Section Code is 11053/61)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
11053/61 : B7060 CADDONFOOT TO JUNCTION NETHERBARNES									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 20 August 2014									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 27 August 2014									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 03 September 2014									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 10 September 2014									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 17 September 2014									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 24 September 2014									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 01 October 2014									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 08 October 2014									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 15 October 2014									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 22 October 2014									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 29 October 2014									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 05 November 2014									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 12 November 2014									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 19 November 2014									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 26 November 2014									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 03 December 2014									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 10 December 2014									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 17 December 2014									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 24 December 2014									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 31 December 2014									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 07 January 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 14 January 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 21 January 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 28 January 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 04 February 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 11 February 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 18 February 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 25 February 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 04 March 2015									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 11 March 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 18 March 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 25 March 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 01 April 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 08 April 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 15 April 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 22 April 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 29 April 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 06 May 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 13 May 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 20 May 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 27 May 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 03 June 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 10 June 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 17 June 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 24 June 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 01 July 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 08 July 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 15 July 2015									
<i>No defects recorded</i>									
Detailed Inspection - Woodland areas and Trees of Amey A7 Detailed Inspection									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 22 July 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 29 July 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 05 August 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 12 August 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 19 August 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 26 August 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 02 September 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 09 September 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 16 September 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 23 September 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 30 September 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A68 A7 A6091 Safety Inspection on 07 October 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A7 6091 Safety inspection on 14 October 2015									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A7 6091 Safety inspection on 21 October 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A7 6091 Safety inspection on 28 October 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A7 6091 Safety inspection on 04 November 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A7 6091 Safety inspection on 11 November 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A7 6091 Safety inspection on 18 November 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A7 6091 Safety inspection on 25 November 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A7 6091 Safety inspection on 02 December 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A7 6091 Safety inspection on 09 December 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A7 6091 Safety inspection on 16 December 2015									
<i>No defects recorded</i>									
Safety Inspection of Amey A7 6091 Safety inspection on 23 December 2015									
SE59132509-1580543	968m	0m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 1	20/01/2016	Completed Defects	09/02/2016	A7 S/B VERGE BOLESIDE
Safety Inspection of Amey A7 6091 Safety inspection on 30 December 2015									
SE57132609-1616640	2,010m	0m	GULLY	Blockage (BLOK)	CAT 1	27/01/2016	Completed Defects	08/01/2016	A7 SB, GULLIES ON EDGE C/W, 500M APPROX SOUTH OF 40MPH SIGN
Safety Inspection of Amey A7 6091 Safety inspection on 06 January 2016									
<i>No defects recorded</i>									
Safety Inspection of Amey A7 6091 Safety inspection on 13 January 2016									
<i>No defects recorded</i>									
Safety Inspection of Amey A7 6091 Safety inspection on 20 January 2016									
<i>No defects recorded</i>									
Safety Inspection of Amey A7 6091 Safety inspection on 27 January 2016									
<i>No defects recorded</i>									
Safety Inspection of Amey A7 6091 Safety inspection on 03 February 2016									
<i>No defects recorded</i>									
Safety Inspection of Amey A7 6091 Safety inspection on 10 February 2016									
<i>No defects recorded</i>									
Safety Inspection of Amey A7 6091 Safety inspection on 17 February 2016									
<i>No defects recorded</i>									
Safety Inspection of Amey A7 6091 Safety inspection on 24 February 2016									
<i>No defects recorded</i>									
Safety Inspection of Amey A7 6091 Safety inspection on 02 March 2016									
<i>No defects recorded</i>									
Safety Inspection of Amey A7 6091 Safety inspection on 09 March 2016									
<i>No defects recorded</i>									
Safety Inspection of Amey A7 6091 Safety inspection on 16 March 2016									
<i>No defects recorded</i>									
Safety Inspection of Amey A7 6091 Safety inspection on 23 March 2016									
<i>No defects recorded</i>									
Safety Inspection of Amey A7 6091 Safety inspection on 30 March 2016									
<i>No defects recorded</i>									
Safety Inspection of Amey A7 6091 Safety inspection on 06 April 2016									
<i>No defects recorded</i>									
Safety Inspection of Amey A7 6091 Safety inspection on 13 April 2016									
<i>No defects recorded</i>									
Safety Inspection of Amey A7 6091 Safety inspection on 20 April 2016									
<i>No defects recorded</i>									
Safety Inspection of Amey A7 6091 Safety inspection on 27 April 2016									
<i>No defects recorded</i>									
Safety Inspection of Amey A7 6091 Safety inspection on 04 May 2016									
<i>No defects recorded</i>									
Safety Inspection of Amey A7 6091 Safety inspection on 11 May 2016									
<i>No defects recorded</i>									
Safety Inspection of Amey A7 6091 Safety inspection on 18 May 2016									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A7 6091			Safety inspection	Safety inspection on 25 May 2016					
				<i>No defects recorded</i>					
Safety Inspection of Amey A7 6091			Safety inspection	Safety inspection on 01 June 2016					
				<i>No defects recorded</i>					
Safety Inspection of Amey A7 6091			Safety inspection	Safety inspection on 08 June 2016					
				<i>No defects recorded</i>					
Safety Inspection of Amey A7 6091			Safety inspection	Safety inspection on 15 June 2016					
				<i>No defects recorded</i>					
Safety Inspection of Amey A7 6091			Safety inspection	Safety inspection on 22 June 2016					
				<i>No defects recorded</i>					
Safety Inspection of Amey A7 6091			Safety inspection	Safety inspection on 29 June 2016					
				<i>No defects recorded</i>					