

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 03/10/2018 and 03/10/2019, and defects raised outside of inspections on the same Section(s) during this period.

- (Road is 'A90',)
- (Section Code is 12150/05) Or
- (Section Code is 12150/06) Or
- (Section Code is 12150/40) Or
- (Section Code is 12150/41) Or
- (Section Code is 12150/79) Or
- (Section Code is 12150/86) Or
- (Section Code is 12155/00) Or
- (Section Code is 12155/09) Or
- (Section Code is 12155/19) Or
- (Section Code is 12155/35) Or
- (Section Code is 12155/51) Or
- (Section Code is 12155/61) Or
- (Section Code is 12160/00) Or
- (Section Code is 12160/22) Or
- (Section Code is 12160/44) Or
- (Section Code is 12160/63) Or
- (Section Code is 12170/00) Or
- (Section Code is 12170/15)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
12150/05 : WITH: SWALLOW ROUNDABOUT TO MYREKIRK ROAD RBT									
Safety Patrol of A90 Swallow to SCC on 05 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 09 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 12 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 16 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 19 October 2018									
NE7-423429-236145178	1,247m	1,247m	CARRIAGEWAY	Pothole (POTH)	CAT 1	16/11/2018	Completed Defects	31/10/2018	@ MYREKIRK RBT N/B
Safety Inspection of A90 & A972 South on 23 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 26 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 30 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 02 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 06 November 2018									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 09 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 13 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 16 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 20 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 23 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 27 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 30 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 04 December 2018									
NE7-426986-236234559	1,268m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/01/2019	Completed Defects	19/12/2018	@ MYREKIRK RBT N/B
Safety Patrol of A90 Swallow to SCC on 07 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 11 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 14 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 18 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 21 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 25 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 28 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 01 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 04 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 08 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 11 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 15 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 18 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 22 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 25 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 29 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 01 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 08 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 12 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 15 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 19 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 22 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 26 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 01 March 2019									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A90 & A972 South on 05 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 08 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 12 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 15 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 19 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 22 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 26 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 29 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 29 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 02 April 2019									
NE14-462086-236493345	1,275m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	30/04/2019	Completed Defects	23/04/2019	ON MYREKIRK RBT NB
Safety Patrol of A90 Swallow to SCC on 05 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 09 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 12 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 16 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 19 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 23 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 26 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 30 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 03 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 07 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 10 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 14 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 17 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 20 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 23 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 27 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 30 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 03 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 06 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 10 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 13 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 17 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 20 June 2019									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 24 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 27 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 01 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 04 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 08 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 11 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 15 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 18 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 22 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 25 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 29 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 01 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 05 August 2019									
NE14-531944-236922338	536m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/09/2019	Completed Defects	05/09/2019	@ BEEFEATER OFF SLIP KINGSWAY NB
NE14-531944-236922339	543m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/09/2019	Completed Defects	05/09/2019	@ BEEFEATER OFF SLIP KINGSWAY NB
NE14-531944-236922340	549m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/09/2019	Completed Defects	05/09/2019	@ BEEFEATER OFF SLIP KINGSWAY NB
NE14-531944-236922341	556m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/09/2019	Completed Defects	05/09/2019	@ BEEFEATER OFF SLIP KINGSWAY NB
NE14-531944-236922342	561m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/09/2019	Completed Defects	05/09/2019	@ BEEFEATER OFF SLIP KINGSWAY NB
NE14-531944-236922343	500m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	@ BEEFEATER OFF SLIP KINGSWAY NB
NE14-531944-236922344	586m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/09/2019	Completed Defects	05/09/2019	@ BEEFEATER OFF SLIP KINGSWAY NB
NE14-531944-236922345	599m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/09/2019	Completed Defects	05/09/2019	@ BEEFEATER OFF SLIP KINGSWAY NB
NE14-531944-236922346	608m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/09/2019	Completed Defects	05/09/2019	@ BEEFEATER OFF SLIP KINGSWAY NB
NE14-531944-236922347	607m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 1	02/09/2019	Completed Defects	05/09/2019	@ BEEFEATER OFF SLIP KINGSWAY NB
NE14-531944-236922348	602m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	@ BEEFEATER OFF SLIP KINGSWAY NB
Safety Patrol of A90 SAFETY PATROL on 08 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 12 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 15 August 2019									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A90 SAFETY INSPECTION on 19 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 22 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 26 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 29 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 02 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 05 September 2019									
NE14-533371-237002261	1,261m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	03/10/2019	Completed Defects	30/09/2019	@ MYREKIRK RBT N/B
Safety Inspection of A90 SAFETY INSPECTION on 09 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 12 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 16 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 19 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 23 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 26 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 30 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 03 October 2019									
<i>No defects recorded</i>									
12150/40 : WITH: MYREKIRK RD RBT TO OFF SLIP TO A923									
Safety Patrol of A90 Swallow to SCC on 05 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 09 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 12 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 16 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 19 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 23 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 26 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 30 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 02 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 06 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 09 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 13 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 16 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 20 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 23 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 27 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 30 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 04 December 2018									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 07 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 11 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 14 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 18 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 21 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 25 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 28 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 01 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 04 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 08 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 11 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 15 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 18 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 22 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 25 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 29 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 01 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 08 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 12 February 2019									
NE14-429636-236325558	1,322m	0m	GULLY	Missing (MISS)	CAT 1	12/03/2019	Completed Defects	21/02/2019	AFTER LIFF RD JCT N/B
Safety Patrol of A90 Swallow to SCC on 15 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 19 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 22 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 26 February 2019									
NE14-434361-236332475	376m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 1	26/03/2019	Completed Defects	12/03/2019	@ BALGARTHNO UNDERPASS N/B
Safety Patrol of A90 Swallow to SCC on 01 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 05 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 08 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 12 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 15 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 19 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 22 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 26 March 2019									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

No defects recorded
Safety Inspection of A90 & A972 South on 29 March 2019
No defects recorded
Safety Patrol of A90 Swallow to SCC on 29 March 2019
No defects recorded
Safety Inspection of A90 & A972 South on 02 April 2019
No defects recorded
Safety Patrol of A90 Swallow to SCC on 05 April 2019
No defects recorded
Safety Inspection of A90 & A972 South on 09 April 2019
No defects recorded
Safety Patrol of A90 Swallow to SCC on 12 April 2019
No defects recorded
Safety Inspection of A90 & A972 South on 16 April 2019
No defects recorded
Safety Patrol of A90 Swallow to SCC on 19 April 2019
No defects recorded
Safety Inspection of A90 & A972 South on 23 April 2019
No defects recorded
Safety Patrol of A90 Swallow to SCC on 26 April 2019
No defects recorded
Safety Inspection of A90 & A972 South on 30 April 2019
No defects recorded
Safety Patrol of A90 Swallow to SCC on 03 May 2019
No defects recorded
Safety Inspection of A90 & A972 South on 07 May 2019
No defects recorded
Safety Patrol of A90 Swallow to SCC on 10 May 2019
No defects recorded
Safety Inspection of A90 & A972 South on 14 May 2019
No defects recorded
Safety Patrol of A90 Swallow to SCC on 17 May 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 20 May 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 23 May 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 27 May 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 30 May 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 03 June 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 06 June 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 10 June 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 13 June 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 17 June 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 20 June 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 24 June 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 27 June 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 01 July 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 04 July 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 08 July 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 11 July 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 15 July 2019
No defects recorded

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of A90 SAFETY PATROL on 18 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 22 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 25 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 29 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 01 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 05 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 08 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 12 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 15 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 19 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 22 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 26 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 29 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 02 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 05 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 09 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 12 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 16 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 19 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 23 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 26 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 30 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 03 October 2019									
<i>No defects recorded</i>									

12150/79 : WITH: OFF SLIP TO A923 TO UNDER A923 ROUNDABOUT

Safety Patrol of A90 Swallow to SCC on 05 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 09 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 12 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 16 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 19 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 23 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 26 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 30 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 02 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 06 November 2018									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 09 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 13 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 16 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 20 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 23 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 27 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 30 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 04 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 07 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 11 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 14 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 18 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 21 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 25 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 28 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 01 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 04 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 08 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 11 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 15 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 18 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 22 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 25 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 29 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 01 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 08 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 12 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 15 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 19 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 22 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 26 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 01 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 05 March 2019									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of A90 Swallow to SCC on 08 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 12 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 15 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 19 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 22 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 26 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 29 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 29 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 02 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 05 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 09 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 12 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 16 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 19 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 23 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 26 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 30 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 03 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 07 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 10 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 14 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 17 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 20 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 23 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 27 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 30 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 03 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 06 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 10 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 13 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 17 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 20 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 24 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 27 June 2019									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 01 July 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 04 July 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 08 July 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 11 July 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 15 July 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 18 July 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 22 July 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 25 July 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 29 July 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 01 August 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 05 August 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 08 August 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 12 August 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 15 August 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 19 August 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 22 August 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 26 August 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 29 August 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 02 September 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 05 September 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 09 September 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 12 September 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 16 September 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 19 September 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 23 September 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 26 September 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 30 September 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 03 October 2019
No defects recorded

12155/00 : WITH: UNDER A923 RBT TO ON SLIP FROM A923

Safety Patrol of A90 Swallow to SCC on 05 October 2018
No defects recorded
Safety Inspection of A90 & A972 South on 09 October 2018
No defects recorded
Safety Patrol of A90 Swallow to SCC on 12 October 2018
No defects recorded
Safety Inspection of A90 & A972 South on 16 October 2018
No defects recorded

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of A90 Swallow to SCC on 19 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 23 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 26 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 30 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 02 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 06 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 09 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 13 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 16 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 20 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 23 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 27 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 30 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 04 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 07 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 11 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 14 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 18 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 21 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 25 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 28 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 01 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 04 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 08 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 11 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 15 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 18 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 22 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 25 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 29 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 01 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 08 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 12 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 15 February 2019									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

No defects recorded

Safety Inspection of A90 & A972 South on 19 February 2019
No defects recorded

Safety Patrol of A90 Swallow to SCC on 22 February 2019
No defects recorded

Safety Inspection of A90 & A972 South on 26 February 2019
No defects recorded

Safety Patrol of A90 Swallow to SCC on 01 March 2019
No defects recorded

Safety Inspection of A90 & A972 South on 05 March 2019
No defects recorded

Safety Patrol of A90 Swallow to SCC on 08 March 2019
No defects recorded

Safety Inspection of A90 & A972 South on 12 March 2019
No defects recorded

Safety Patrol of A90 Swallow to SCC on 15 March 2019
No defects recorded

Safety Inspection of A90 & A972 South on 19 March 2019
No defects recorded

Safety Patrol of A90 Swallow to SCC on 22 March 2019
No defects recorded

Safety Inspection of A90 & A972 South on 26 March 2019
No defects recorded

Safety Inspection of A90 & A972 South on 29 March 2019
No defects recorded

Safety Patrol of A90 Swallow to SCC on 29 March 2019
No defects recorded

Safety Inspection of A90 & A972 South on 02 April 2019
No defects recorded

Safety Patrol of A90 Swallow to SCC on 05 April 2019
No defects recorded

Safety Inspection of A90 & A972 South on 09 April 2019
No defects recorded

Safety Patrol of A90 Swallow to SCC on 12 April 2019
No defects recorded

Safety Inspection of A90 & A972 South on 16 April 2019
No defects recorded

Safety Patrol of A90 Swallow to SCC on 19 April 2019
No defects recorded

Safety Inspection of A90 & A972 South on 23 April 2019
No defects recorded

Safety Patrol of A90 Swallow to SCC on 26 April 2019
No defects recorded

Safety Inspection of A90 & A972 South on 30 April 2019
No defects recorded

Safety Patrol of A90 Swallow to SCC on 03 May 2019
No defects recorded

Safety Inspection of A90 & A972 South on 07 May 2019
No defects recorded

Safety Patrol of A90 Swallow to SCC on 10 May 2019
No defects recorded

Safety Inspection of A90 & A972 South on 14 May 2019
No defects recorded

Safety Patrol of A90 Swallow to SCC on 17 May 2019
No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 20 May 2019
No defects recorded

Safety Patrol of A90 SAFETY PATROL on 23 May 2019
No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 27 May 2019
No defects recorded

Safety Patrol of A90 SAFETY PATROL on 30 May 2019
No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 03 June 2019
No defects recorded

Safety Patrol of A90 SAFETY PATROL on 06 June 2019
No defects recorded

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A90 SAFETY INSPECTION on 10 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 13 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 17 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 20 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 24 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 27 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 01 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 04 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 08 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 11 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 15 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 18 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 22 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 25 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 29 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 01 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 05 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 08 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 12 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 15 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 19 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 22 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 26 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 29 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 02 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 05 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 09 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 12 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 16 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 19 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 23 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 26 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 30 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 03 October 2019									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

No defects recorded

12155/19 : WITH: ON SLIP FROM A923 TO OFF SLIP B960 CLEP RD

Safety Patrol of A90 Swallow to SCC on 05 October 2018

No defects recorded

Safety Inspection of A90 & A972 South on 09 October 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 12 October 2018

NE7-420205-236114939	467m	0m	GULLY	Missing (MISS)	CAT 1	09/11/2018	Completed Defects	26/10/2018	@ CLEP OFFSLIP N/B
----------------------	------	----	-------	----------------	-------	------------	-------------------	------------	--------------------

Safety Inspection of A90 & A972 South on 16 October 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 19 October 2018

No defects recorded

Safety Inspection of A90 & A972 South on 23 October 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 26 October 2018

No defects recorded

Safety Inspection of A90 & A972 South on 30 October 2018

NE7-425996-236179777	53m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Completed Defects	20/11/2018	ADJACENT TO PETER VARDY CAR STORE NB
----------------------	-----	----	-------------	--	-------	------------	-------------------	------------	--------------------------------------

NE7-425996-236179778	53m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Completed Defects	20/11/2018	ADJACENT TO PETER VARDY CAR STORE NB
----------------------	-----	----	-------------	--	-------	------------	-------------------	------------	--------------------------------------

Safety Patrol of A90 Swallow to SCC on 02 November 2018

No defects recorded

Safety Inspection of A90 & A972 South on 06 November 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 09 November 2018

No defects recorded

Safety Inspection of A90 & A972 South on 13 November 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 16 November 2018

No defects recorded

Safety Inspection of A90 & A972 South on 20 November 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 23 November 2018

No defects recorded

Safety Inspection of A90 & A972 South on 27 November 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 30 November 2018

No defects recorded

Safety Inspection of A90 & A972 South on 04 December 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 07 December 2018

No defects recorded

Safety Inspection of A90 & A972 South on 11 December 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 14 December 2018

No defects recorded

Safety Inspection of A90 & A972 South on 18 December 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 21 December 2018

No defects recorded

Safety Inspection of A90 & A972 South on 25 December 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 28 December 2018

No defects recorded

Safety Inspection of A90 & A972 South on 01 January 2019

No defects recorded

Safety Patrol of A90 Swallow to SCC on 04 January 2019

No defects recorded

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A90 & A972 South on 08 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 11 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 15 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 18 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 22 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 25 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 29 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 01 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 08 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 12 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 15 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 19 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 22 February 2019									
NE14-433220-236332469	53m	0m	GULLY	Missing (MISS)	CAT 1	22/03/2019	Completed Defects	12/03/2019	AFTER COUPAR ANGUS ONSLIP N/B
Safety Inspection of A90 & A972 South on 26 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 01 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 05 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 08 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 12 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 15 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 19 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 22 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 26 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 29 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 29 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 02 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 05 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 09 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 12 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 16 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 19 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 23 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 26 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 30 April 2019									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 03 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 07 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 10 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 14 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 17 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 20 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 23 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 27 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 30 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 03 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 06 June 2019									
NE14-518374-236809460	30m	0m	CARRIAGEWAY	Patch - difference in level (PDLV)	CAT 2	01/01/9999	Completed Defects	15/09/2019	OPPOSITE PETER VARDY CAR STORE NB
NE14-518374-236809461	41m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 1	04/07/2019	Completed Defects	26/06/2019	OPPOSITE PETER VARDY CAR STORE NB
Safety Inspection of A90 SAFETY INSPECTION on 10 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 13 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 17 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 20 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 24 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 27 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 01 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 04 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 08 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 11 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 15 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 18 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 22 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 25 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 29 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 01 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 05 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 08 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 12 August 2019									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of A90 SAFETY PATROL on 15 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 19 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 22 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 26 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 29 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 02 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 05 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 09 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 12 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 16 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 19 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 23 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 26 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 30 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 03 October 2019									
<i>No defects recorded</i>									

12155/51 : WITH: OFF SLIP B960 CLEP RD TO UNDER CLEP RD RBT

Safety Patrol of A90 Swallow to SCC on 05 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 09 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 12 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 16 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 19 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 23 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 26 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 30 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 02 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 06 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 09 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 13 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 16 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 20 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 23 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 27 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 30 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 04 December 2018									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 07 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 11 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 14 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 18 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 21 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 25 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 28 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 01 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 04 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 08 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 11 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 15 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 18 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 22 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 25 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 29 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 01 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 08 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 12 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 15 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 19 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 22 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 26 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 01 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 05 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 08 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 12 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 15 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 19 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 22 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 26 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 29 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 29 March 2019									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A90 & A972 South on 02 April 2019									
NE14-462086-236493348	144m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	30/04/2019	Completed Defects	26/04/2019	JUST BEFORE CLEP OVERBRIDGE NB
NE14-462086-236493349	148m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Completed Defects	26/04/2019	JUST BEFORE CLEP OVERBRIDGE NB
NE14-462086-236493350	96m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	15/09/2019	ADJACENT TO CLEP OFF SLIP NB
NE14-462086-236493351	130m	0m	CARRIAGEWAY	Patch - material cracking (PMCK)	CAT 2	01/01/9999	Completed Defects	26/04/2019	JUST BEFORE CLEP OVERBRIDGE NB
Safety Patrol of A90 Swallow to SCC on 05 April 2019									
No defects recorded									
Safety Inspection of A90 & A972 South on 09 April 2019									
No defects recorded									
Safety Patrol of A90 Swallow to SCC on 12 April 2019									
No defects recorded									
Safety Inspection of A90 & A972 South on 16 April 2019									
No defects recorded									
Safety Patrol of A90 Swallow to SCC on 19 April 2019									
NE14-487219-236584628	230m	0m	GULLY	Difference in component levels (ICLV)	CAT 1	17/05/2019	Completed Defects	10/05/2019	BEFORE CLEP OVERBRIDGE N/B
Safety Inspection of A90 & A972 South on 23 April 2019									
No defects recorded									
Safety Patrol of A90 Swallow to SCC on 26 April 2019									
No defects recorded									
Safety Inspection of A90 & A972 South on 30 April 2019									
No defects recorded									
Safety Patrol of A90 Swallow to SCC on 03 May 2019									
No defects recorded									
Safety Inspection of A90 & A972 South on 07 May 2019									
No defects recorded									
Safety Patrol of A90 Swallow to SCC on 10 May 2019									
No defects recorded									
Safety Inspection of A90 & A972 South on 14 May 2019									
No defects recorded									
Safety Patrol of A90 Swallow to SCC on 17 May 2019									
No defects recorded									
Safety Inspection of A90 SAFETY INSPECTION on 20 May 2019									
No defects recorded									
Safety Patrol of A90 SAFETY PATROL on 23 May 2019									
No defects recorded									
Safety Inspection of A90 SAFETY INSPECTION on 27 May 2019									
No defects recorded									
Safety Patrol of A90 SAFETY PATROL on 30 May 2019									
No defects recorded									
Safety Inspection of A90 SAFETY INSPECTION on 03 June 2019									
No defects recorded									
Safety Patrol of A90 SAFETY PATROL on 06 June 2019									
No defects recorded									
Safety Inspection of A90 SAFETY INSPECTION on 10 June 2019									
No defects recorded									
Safety Patrol of A90 SAFETY PATROL on 13 June 2019									
No defects recorded									
Safety Inspection of A90 SAFETY INSPECTION on 17 June 2019									
No defects recorded									
Safety Patrol of A90 SAFETY PATROL on 20 June 2019									
No defects recorded									
Safety Inspection of A90 SAFETY INSPECTION on 24 June 2019									
No defects recorded									
Safety Patrol of A90 SAFETY PATROL on 27 June 2019									
No defects recorded									
Safety Inspection of A90 SAFETY INSPECTION on 01 July 2019									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

No defects recorded
Safety Patrol of A90 SAFETY PATROL on 04 July 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 08 July 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 11 July 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 15 July 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 18 July 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 22 July 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 25 July 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 29 July 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 01 August 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 05 August 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 08 August 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 12 August 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 15 August 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 19 August 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 22 August 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 26 August 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 29 August 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 02 September 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 05 September 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 09 September 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 12 September 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 16 September 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 19 September 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 23 September 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 26 September 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 30 September 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 03 October 2019
No defects recorded

12160/00 : WITH: UNDER CLEP RD RBT TO ON SLIP FROM CLEP RD

Safety Patrol of A90 Swallow to SCC on 05 October 2018
No defects recorded
Safety Inspection of A90 & A972 South on 09 October 2018
No defects recorded
Safety Patrol of A90 Swallow to SCC on 12 October 2018
No defects recorded
Safety Inspection of A90 & A972 South on 16 October 2018
No defects recorded
Safety Patrol of A90 Swallow to SCC on 19 October 2018
No defects recorded

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A90 & A972 South on 23 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 26 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 30 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 02 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 06 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 09 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 13 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 16 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 20 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 23 November 2018									
NE7-426753-236232405	149m	0m	GULLY	Cracked or broken (IBCK)	CAT 1	21/12/2018	Completed Defects	05/12/2018	BFORE CLEP ON SLIP NB ACROSS FROM BURGER KING KINGSWAY
Safety Inspection of A90 & A972 South on 27 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 30 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 04 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 07 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 11 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 14 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 18 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 21 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 25 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 28 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 01 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 04 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 08 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 11 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 15 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 18 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 22 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 25 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 29 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 01 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 08 February 2019									
NE14-429475-236325556	254m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2019	Completed Defects	25/02/2019	@ BURGER KING N/B
Safety Inspection of A90 & A972 South on 12 February 2019									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 15 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 19 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 22 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 26 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 01 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 05 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 08 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 12 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 15 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 19 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 22 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 26 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 29 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 29 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 02 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 05 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 09 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 12 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 16 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 19 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 23 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 26 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 30 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 03 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 07 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 10 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 14 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 17 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 20 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 23 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 27 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 30 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 03 June 2019									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of A90 SAFETY PATROL on 06 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 10 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 13 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 17 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 20 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 24 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 27 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 01 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 04 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 08 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 11 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 15 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 18 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 22 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 25 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 29 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 01 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 05 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 08 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 12 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 15 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 19 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 22 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 26 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 29 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 02 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 05 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 09 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 12 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 16 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 19 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 23 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 26 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 30 September 2019									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

No defects recorded

Safety Patrol of A90 SAFETY PATROL on 03 October 2019

No defects recorded

12160/44 : WITH: ON SLIP FROM CLEP RD TO STRATHMARTINE RBT

Safety Patrol of A90 Swallow to SCC on 05 October 2018

No defects recorded

Safety Inspection of A90 & A972 South on 09 October 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 12 October 2018

No defects recorded

Safety Inspection of A90 & A972 South on 16 October 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 19 October 2018

No defects recorded

Safety Inspection of A90 & A972 South on 23 October 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 26 October 2018

No defects recorded

Safety Inspection of A90 & A972 South on 30 October 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 02 November 2018

No defects recorded

Safety Inspection of A90 & A972 South on 06 November 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 09 November 2018

No defects recorded

Safety Inspection of A90 & A972 South on 13 November 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 16 November 2018

No defects recorded

Safety Inspection of A90 & A972 South on 20 November 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 23 November 2018

No defects recorded

Safety Inspection of A90 & A972 South on 27 November 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 30 November 2018

No defects recorded

Safety Inspection of A90 & A972 South on 04 December 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 07 December 2018

No defects recorded

Safety Inspection of A90 & A972 South on 11 December 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 14 December 2018

No defects recorded

Safety Inspection of A90 & A972 South on 18 December 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 21 December 2018

No defects recorded

Safety Inspection of A90 & A972 South on 25 December 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 28 December 2018

No defects recorded

Safety Inspection of A90 & A972 South on 01 January 2019

No defects recorded

Safety Patrol of A90 Swallow to SCC on 04 January 2019

No defects recorded

Safety Inspection of A90 & A972 South on 08 January 2019

No defects recorded

Safety Patrol of A90 Swallow to SCC on 11 January 2019

No defects recorded

Safety Inspection of A90 & A972 South on 15 January 2019

No defects recorded

Safety Patrol of A90 Swallow to SCC on 18 January 2019

No defects recorded

No defects recorded

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A90 & A972 South on 22 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 25 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 29 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 01 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 08 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 12 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 15 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 19 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 22 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 26 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 01 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 05 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 08 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 12 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 15 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 19 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 22 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 26 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 29 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 29 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 02 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 05 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 09 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 12 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 16 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 19 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 23 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 26 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 30 April 2019									
NE14-498914-236614206	215m	0m	GULLY	Other (OTHR)	CAT 1	28/05/2019	Completed Defects	17/05/2019	@ BANK AV JUST BEFORE STRATHMARTIE RD RBT NB
NE14-498914-236614207	225m	0m	GULLY	Other (OTHR)	CAT 1	28/05/2019	Completed Defects	17/05/2019	@ BANK AV JUST BEFORE STRATHMARTINE RD RBT NB
Safety Patrol of A90 Swallow to SCC on 03 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 07 May 2019									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of A90 Swallow to SCC on 10 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 14 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 17 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 20 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 23 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 27 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 30 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 03 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 06 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 10 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 13 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 17 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 20 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 24 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 27 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 01 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 04 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 08 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 11 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 15 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 18 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 22 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 25 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 29 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 01 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 05 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 08 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 12 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 15 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 19 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 22 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 26 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 29 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 02 September 2019									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 05 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 09 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 12 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 16 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 19 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 23 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 26 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 30 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 03 October 2019									
<i>No defects recorded</i>									
12170/00 : WITH: STRATHMARTINE RD RBT TO OLD GLAMIS RD RBT									
Safety Patrol of A90 Swallow to SCC on 05 October 2018									
NE7-416956-236110946	119m	119m	MANHOLE	Rocking under load (IRLD)	CAT 1	02/11/2018	Completed Defects	12/10/2018	OUTSIDE 351 KINGSWAY NB AFTER STRATHMARTINE RD RBT
Safety Inspection of A90 & A972 South on 09 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 12 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 16 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 19 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 23 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 26 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 30 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 02 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 06 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 09 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 13 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 16 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 20 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 23 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 27 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 30 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 04 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 07 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 11 December 2018									
NE7-427256-236257569	2m	0m	MANHOLE	Missing (MISS)	CAT 2	01/01/9999	Completed Defects	16/01/2019	ON FOOTWAY @ BOTTOM OF STRATHMARTINE RD OVER BRIDGE NB
Safety Patrol of A90 Swallow to SCC on 14 December 2018									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

No defects recorded

Safety Inspection of A90 & A972 South on 18 December 2018
No defects recorded

Safety Patrol of A90 Swallow to SCC on 21 December 2018
No defects recorded

Safety Inspection of A90 & A972 South on 25 December 2018
No defects recorded

Safety Patrol of A90 Swallow to SCC on 28 December 2018
No defects recorded

Safety Inspection of A90 & A972 South on 01 January 2019
No defects recorded

Safety Patrol of A90 Swallow to SCC on 04 January 2019
No defects recorded

Safety Inspection of A90 & A972 South on 08 January 2019
No defects recorded

Safety Patrol of A90 Swallow to SCC on 11 January 2019
No defects recorded

Safety Inspection of A90 & A972 South on 15 January 2019
No defects recorded

Safety Patrol of A90 Swallow to SCC on 18 January 2019
No defects recorded

Safety Inspection of A90 & A972 South on 22 January 2019
No defects recorded

Safety Patrol of A90 Swallow to SCC on 25 January 2019
No defects recorded

Safety Inspection of A90 & A972 South on 29 January 2019
No defects recorded

Safety Patrol of A90 Swallow to SCC on 01 February 2019
No defects recorded

Safety Patrol of A90 Swallow to SCC on 08 February 2019
No defects recorded

Safety Inspection of A90 & A972 South on 12 February 2019
No defects recorded

Safety Patrol of A90 Swallow to SCC on 15 February 2019
No defects recorded

Safety Inspection of A90 & A972 South on 19 February 2019
No defects recorded

Safety Patrol of A90 Swallow to SCC on 22 February 2019
No defects recorded

Safety Inspection of A90 & A972 South on 26 February 2019
No defects recorded

Safety Patrol of A90 Swallow to SCC on 01 March 2019
No defects recorded

Safety Inspection of A90 & A972 South on 05 March 2019
No defects recorded

Safety Patrol of A90 Swallow to SCC on 08 March 2019
No defects recorded

Safety Inspection of A90 & A972 South on 12 March 2019
No defects recorded

Safety Patrol of A90 Swallow to SCC on 15 March 2019
No defects recorded

Safety Inspection of A90 & A972 South on 19 March 2019
No defects recorded

Safety Patrol of A90 Swallow to SCC on 22 March 2019
No defects recorded

Safety Inspection of A90 & A972 South on 26 March 2019
No defects recorded

Safety Inspection of A90 & A972 South on 29 March 2019
No defects recorded

Safety Patrol of A90 Swallow to SCC on 29 March 2019
No defects recorded

Safety Inspection of A90 & A972 South on 02 April 2019
No defects recorded

Safety Patrol of A90 Swallow to SCC on 05 April 2019
No defects recorded

Safety Inspection of A90 & A972 South on 09 April 2019
No defects recorded

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of A90 Swallow to SCC on 12 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 16 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 19 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 23 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 26 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 30 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 03 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 07 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 10 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 14 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 17 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 20 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 23 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 27 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 30 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 03 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 06 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 10 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 13 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 17 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 20 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 24 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 27 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 01 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 04 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 08 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 11 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 15 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 18 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 22 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 25 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 29 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 01 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 05 August 2019									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

No defects recorded
Safety Patrol of A90 SAFETY PATROL on 08 August 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 12 August 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 15 August 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 19 August 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 22 August 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 26 August 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 29 August 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 02 September 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 05 September 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 09 September 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 12 September 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 16 September 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 19 September 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 23 September 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 26 September 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 30 September 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 03 October 2019
No defects recorded

12170/15 : AGAINST: OLD GLAMIS RD RBT TO STRATHMARTINE RD RBT

Safety Patrol of A90 Swallow to SCC on 05 October 2018
No defects recorded
Safety Inspection of A90 & A972 South on 09 October 2018
No defects recorded
Safety Patrol of A90 Swallow to SCC on 12 October 2018
No defects recorded
Safety Inspection of A90 & A972 South on 16 October 2018
No defects recorded
Safety Patrol of A90 Swallow to SCC on 19 October 2018
No defects recorded
Safety Inspection of A90 & A972 South on 23 October 2018
No defects recorded
Safety Patrol of A90 Swallow to SCC on 26 October 2018
No defects recorded
Safety Inspection of A90 & A972 South on 30 October 2018
No defects recorded
Safety Patrol of A90 Swallow to SCC on 02 November 2018
No defects recorded
Safety Inspection of A90 & A972 South on 06 November 2018
No defects recorded
Safety Patrol of A90 Swallow to SCC on 09 November 2018
No defects recorded
Safety Inspection of A90 & A972 South on 13 November 2018
No defects recorded
Safety Patrol of A90 Swallow to SCC on 16 November 2018
No defects recorded
Safety Inspection of A90 & A972 South on 20 November 2018
No defects recorded
Safety Patrol of A90 Swallow to SCC on 23 November 2018
No defects recorded

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A90 & A972 South on 27 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 30 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 04 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 07 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 11 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 14 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 18 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 21 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 25 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 28 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 01 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 04 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 08 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 11 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 15 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 18 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 22 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 25 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 29 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 01 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 08 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 12 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 15 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 19 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 22 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 26 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 01 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 05 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 08 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 12 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 15 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 19 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 22 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 26 March 2019									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

No defects recorded
Safety Inspection of A90 & A972 South on 29 March 2019
No defects recorded
Safety Patrol of A90 Swallow to SCC on 29 March 2019
No defects recorded
Safety Inspection of A90 & A972 South on 02 April 2019
No defects recorded
Safety Patrol of A90 Swallow to SCC on 05 April 2019
No defects recorded
Safety Inspection of A90 & A972 South on 09 April 2019
No defects recorded
Safety Patrol of A90 Swallow to SCC on 12 April 2019
No defects recorded
Safety Inspection of A90 & A972 South on 16 April 2019
No defects recorded
Safety Patrol of A90 Swallow to SCC on 19 April 2019
No defects recorded
Safety Inspection of A90 & A972 South on 23 April 2019
No defects recorded
Safety Patrol of A90 Swallow to SCC on 26 April 2019
No defects recorded
Safety Inspection of A90 & A972 South on 30 April 2019
No defects recorded
Safety Patrol of A90 Swallow to SCC on 03 May 2019
No defects recorded
Safety Inspection of A90 & A972 South on 07 May 2019
No defects recorded
Safety Patrol of A90 Swallow to SCC on 10 May 2019
No defects recorded
Safety Inspection of A90 & A972 South on 14 May 2019
No defects recorded
Safety Patrol of A90 Swallow to SCC on 17 May 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 20 May 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 23 May 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 27 May 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 30 May 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 03 June 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 06 June 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 10 June 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 13 June 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 17 June 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 20 June 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 24 June 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 27 June 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 01 July 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 04 July 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 08 July 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 11 July 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 15 July 2019
No defects recorded

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of A90 SAFETY PATROL on 18 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 22 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 25 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 29 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 01 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 05 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 08 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 12 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 15 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 19 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 22 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 26 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 29 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 02 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 05 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 09 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 12 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 16 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 19 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 23 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 26 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 30 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 03 October 2019									
<i>No defects recorded</i>									

12160/63 : AGAINST: STRATHMARTINE RD RBT TO EXIT SLIP CLEP RD

Safety Patrol of A90 Swallow to SCC on 05 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 09 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 12 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 16 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 19 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 23 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 26 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 30 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 02 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 06 November 2018									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 09 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 13 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 16 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 20 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 23 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 27 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 30 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 04 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 07 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 11 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 14 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 18 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 21 December 2018									
NE7-427514-236266012	16m	0m	PEDESTRIAN_GU ARDRAIL	Accident damage (ACCD)	CAT 1	18/01/2019	Completed Defects	13/01/2019	JUST AFTER STRATHMARTINE RD RBT SB
Safety Inspection of A90 & A972 South on 25 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 28 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 01 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 04 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 08 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 11 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 15 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 18 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 22 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 25 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 29 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 01 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 08 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 12 February 2019									
NE14-429636-236325557	116m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/03/2019	Completed Defects	05/03/2019	@ MUIRFIELD GRESCENT S/B
Safety Patrol of A90 Swallow to SCC on 15 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 19 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 22 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 26 February 2019									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE14-434361-236332470	16m	0m	CARRIAGEWAY	Trench RI - loss of material (TLMT)	CAT 1	26/03/2019	Completed Defects	13/03/2019	ON EXIT FROM STRATHMARTINE RD RBT S/B
NE14-434361-236332471	7m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	ON EXIT FROM STRATHMARTINE RD RBT S/B
NE14-434361-236332472	64m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 1	26/03/2019	Completed Defects	13/03/2019	BEFORE MUIRFIELD CRESCENT S/B
NE14-434361-236332473	65m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BEFORE MUIRFIELD CRESCENT S/B
NE14-434361-236332474	75m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BEFORE MUIRFIELD CRESCENT S/B

Safety Patrol of A90 Swallow to SCC on 01 March 2019

No defects recorded

Safety Inspection of A90 & A972 South on 05 March 2019

No defects recorded

Safety Patrol of A90 Swallow to SCC on 08 March 2019

No defects recorded

Safety Inspection of A90 & A972 South on 12 March 2019

No defects recorded

Safety Patrol of A90 Swallow to SCC on 15 March 2019

No defects recorded

Safety Inspection of A90 & A972 South on 19 March 2019

NE14-449093-236463096	117m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	16/04/2019	Awaiting CCMS Temp Date	01/01/9999	JUST AFTER MUIRFIELD CRES SB
-----------------------	------	----	-------------	----------------	-------	------------	-------------------------	------------	------------------------------

NE14-449093-236463097	119m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST AFTER MUIRFIELD CRES SB
-----------------------	------	----	-------------	--------------------------------------	-------	------------	-----------------------	------------	------------------------------

Safety Patrol of A90 Swallow to SCC on 22 March 2019

No defects recorded

Safety Inspection of A90 & A972 South on 26 March 2019

No defects recorded

Safety Inspection of A90 & A972 South on 29 March 2019

No defects recorded

Safety Patrol of A90 Swallow to SCC on 29 March 2019

No defects recorded

Safety Inspection of A90 & A972 South on 02 April 2019

No defects recorded

Safety Patrol of A90 Swallow to SCC on 05 April 2019

No defects recorded

Safety Inspection of A90 & A972 South on 09 April 2019

No defects recorded

Safety Patrol of A90 Swallow to SCC on 12 April 2019

No defects recorded

Safety Inspection of A90 & A972 South on 16 April 2019

No defects recorded

Safety Patrol of A90 Swallow to SCC on 19 April 2019

No defects recorded

Safety Inspection of A90 & A972 South on 23 April 2019

No defects recorded

Safety Patrol of A90 Swallow to SCC on 26 April 2019

No defects recorded

Safety Inspection of A90 & A972 South on 30 April 2019

No defects recorded

Safety Patrol of A90 Swallow to SCC on 03 May 2019

No defects recorded

Safety Inspection of A90 & A972 South on 07 May 2019

No defects recorded

Safety Patrol of A90 Swallow to SCC on 10 May 2019

No defects recorded

Safety Inspection of A90 & A972 South on 14 May 2019

No defects recorded

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 17 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 20 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 23 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 27 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 30 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 03 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 06 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 10 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 13 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 17 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 20 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 24 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 27 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 01 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 04 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 08 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 11 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 15 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 18 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 22 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 25 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 29 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 01 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 05 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 08 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 12 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 15 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 19 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 22 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 26 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 29 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 02 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 05 September 2019									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE14-533371-237002257	112m	0m	GULLY	Rocking under load (IRLD)	CAT 1	03/10/2019	Completed Defects	26/09/2019	JUST AFTER MUIRFIELD CRESENT KINGSWAY S/B
Safety Inspection of A90 SAFETY INSPECTION on 09 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 12 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 16 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 19 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 23 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 26 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 30 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 03 October 2019									
<i>No defects recorded</i>									
12160/22 : AGAINST: EXIT SLIP CLEP RD RBT TO UNDER CLEP RD RB									
Safety Patrol of A90 Swallow to SCC on 05 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 09 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 12 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 16 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 19 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 23 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 26 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 30 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 02 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 06 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 09 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 13 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 16 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 20 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 23 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 27 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 30 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 04 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 07 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 11 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 14 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 18 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 21 December 2018									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A90 & A972 South on 25 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 28 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 01 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 04 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 08 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 11 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 15 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 18 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 22 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 25 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 29 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 01 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 08 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 12 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 15 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 19 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 22 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 26 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 01 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 05 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 08 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 12 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 15 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 19 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 22 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 26 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 29 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 29 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 02 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 05 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 09 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 12 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 16 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 19 April 2019									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

No defects recorded

Safety Inspection of A90 & A972 South on 23 April 2019
No defects recorded

Safety Patrol of A90 Swallow to SCC on 26 April 2019
No defects recorded

Safety Inspection of A90 & A972 South on 30 April 2019
No defects recorded

Safety Patrol of A90 Swallow to SCC on 03 May 2019
No defects recorded

Safety Inspection of A90 & A972 South on 07 May 2019
No defects recorded

Safety Patrol of A90 Swallow to SCC on 10 May 2019
No defects recorded

Safety Inspection of A90 & A972 South on 14 May 2019
No defects recorded

Safety Patrol of A90 Swallow to SCC on 17 May 2019
No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 20 May 2019
No defects recorded

Safety Patrol of A90 SAFETY PATROL on 23 May 2019
No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 27 May 2019
No defects recorded

Safety Patrol of A90 SAFETY PATROL on 30 May 2019
No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 03 June 2019
No defects recorded

Safety Patrol of A90 SAFETY PATROL on 06 June 2019
No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 10 June 2019
No defects recorded

Safety Patrol of A90 SAFETY PATROL on 13 June 2019
No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 17 June 2019
No defects recorded

Safety Patrol of A90 SAFETY PATROL on 20 June 2019
No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 24 June 2019
No defects recorded

Safety Patrol of A90 SAFETY PATROL on 27 June 2019
No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 01 July 2019
No defects recorded

Safety Patrol of A90 SAFETY PATROL on 04 July 2019
No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 08 July 2019
No defects recorded

Safety Patrol of A90 SAFETY PATROL on 11 July 2019
No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 15 July 2019
No defects recorded

Safety Patrol of A90 SAFETY PATROL on 18 July 2019
No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 22 July 2019
No defects recorded

Safety Patrol of A90 SAFETY PATROL on 25 July 2019
No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 29 July 2019
No defects recorded

Safety Patrol of A90 SAFETY PATROL on 01 August 2019
No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 05 August 2019
No defects recorded

Safety Patrol of A90 SAFETY PATROL on 08 August 2019
No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 12 August 2019
No defects recorded

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of A90 SAFETY PATROL on 15 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 19 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 22 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 26 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 29 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 02 September 2019									
NE14-533061-236989651	167m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	30/09/2019	Completed Defects	25/09/2019	@ BURGER KING S/B
NE14-533061-236989652	167m	0m	CARRIAGEWAY	Single crack (CRCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	@ BURGER KING S/B
Safety Patrol of A90 SAFETY PATROL on 05 September 2019									
NE14-533371-237002259	326m	0m	GULLY	Cracked or broken (IBCK)	CAT 1	03/10/2019	Completed Defects	26/09/2019	JUST BEFORE CLEP OVER BRIDGE S/B
NE14-533371-237002260	285m	0m	GULLY	Cracked or broken (IBCK)	CAT 1	03/10/2019	Completed Defects	26/09/2019	@ TOY R US CLEP OFF SLIP S/B
Safety Inspection of A90 SAFETY INSPECTION on 09 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 12 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 16 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 19 September 2019									
NE14-534035-237021764	42m	0m	GULLY	Cracked or broken (IBCK)	CAT 1	17/10/2019	Completed Defects	08/10/2019	JUST AFTER CHARLOTTE STREET JCT N/B
Safety Inspection of A90 SAFETY INSPECTION on 23 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 26 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 30 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 03 October 2019									
<i>No defects recorded</i>									

12155/61 : AGAINST: UNDER CLEP RD RBT TO ENTRY SLIP FROM CLEP

Safety Patrol of A90 Swallow to SCC on 05 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 09 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 12 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 16 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 19 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 23 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 26 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 30 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 02 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 06 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 09 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 13 November 2018									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 16 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 20 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 23 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 27 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 30 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 04 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 07 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 11 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 14 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 18 December 2018									
NE7-427409-236264131	212m	0m	CARRIAGEWAY	Patch - difference in level (PDLV)	CAT 1	15/01/2019	Completed Defects	08/01/2019	AFTER CLEP OVERBRIDGE S/B
Safety Patrol of A90 Swallow to SCC on 21 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 25 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 28 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 01 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 04 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 08 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 11 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 15 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 18 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 22 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 25 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 29 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 01 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 08 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 12 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 15 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 19 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 22 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 26 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 01 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 05 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 08 March 2019									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A90 & A972 South on 12 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 15 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 19 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 22 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 26 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 29 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 29 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 02 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 05 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 09 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 12 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 16 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 19 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 23 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 26 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 30 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 03 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 07 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 10 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 14 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 17 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 20 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 23 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 27 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 30 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 03 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 06 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 10 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 13 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 17 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 20 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 24 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 27 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 01 July 2019									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

No defects recorded
Safety Patrol of A90 SAFETY PATROL on 04 July 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 08 July 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 11 July 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 15 July 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 18 July 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 22 July 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 25 July 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 29 July 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 01 August 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 05 August 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 08 August 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 12 August 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 15 August 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 19 August 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 22 August 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 26 August 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 29 August 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 02 September 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 05 September 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 09 September 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 12 September 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 16 September 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 19 September 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 23 September 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 26 September 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 30 September 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 03 October 2019
No defects recorded

12155/35 : AGAINST: ENTRY SLIP CLEP RD RBT TO OFF SLIP A923

Safety Patrol of A90 Swallow to SCC on 05 October 2018
No defects recorded
Safety Inspection of A90 & A972 South on 09 October 2018
No defects recorded
Safety Patrol of A90 Swallow to SCC on 12 October 2018
No defects recorded
Safety Inspection of A90 & A972 South on 16 October 2018
No defects recorded
Safety Patrol of A90 Swallow to SCC on 19 October 2018
No defects recorded

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A90 & A972 South on 23 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 26 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 30 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 02 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 06 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 09 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 13 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 16 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 20 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 23 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 27 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 30 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 04 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 07 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 11 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 14 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 18 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 21 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 25 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 28 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 01 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 04 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 08 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 11 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 15 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 18 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 22 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 25 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 29 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 01 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 08 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 12 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 15 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 19 February 2019									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 22 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 26 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 01 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 05 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 08 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 12 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 15 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 19 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 22 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 26 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 29 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 29 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 02 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 05 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 09 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 12 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 16 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 19 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 23 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 26 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 30 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 03 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 07 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 10 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 14 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 17 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 20 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 23 May 2019									
<i>No defects recorded</i>									
NE14-512189-236804439	337m	0m	GULLY	Difference in level with road (IDLV)	CAT 1	28/05/2019	Completed Defects	27/05/2019	BEFORE CARSTORE S/B
Safety Patrol of A90 SAFETY PATROL on 30 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 03 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 06 June 2019									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A90 SAFETY INSPECTION on 10 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 13 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 17 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 20 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 24 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 27 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 01 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 04 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 08 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 11 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 15 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 18 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 22 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 25 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 29 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 01 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 05 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 08 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 12 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 15 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 19 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 22 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 26 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 29 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 02 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 05 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 09 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 12 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 16 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 19 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 23 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 26 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 30 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 03 October 2019									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	---------	-------	-----------	-------------	-----------------	--------------------------	----------------	-----------------	----------------------

No defects recorded

12155/09 : AGAINST: OFF SLIP TO A923 TO UNDER A923 ROUNDABOUT

Safety Patrol of A90 Swallow to SCC on 05 October 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 12 October 2018

No defects recorded

Safety Inspection of A90 & A972 South on 16 October 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 19 October 2018

No defects recorded

Safety Inspection of A90 & A972 South on 23 October 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 26 October 2018

No defects recorded

Safety Inspection of A90 & A972 South on 30 October 2018

No defects recorded

Safety Inspection of A90 & A972 South on 09 October 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 02 November 2018

No defects recorded

Safety Inspection of A90 & A972 South on 06 November 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 09 November 2018

No defects recorded

Safety Inspection of A90 & A972 South on 13 November 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 16 November 2018

No defects recorded

Safety Inspection of A90 & A972 South on 20 November 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 23 November 2018

No defects recorded

Safety Inspection of A90 & A972 South on 27 November 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 30 November 2018

No defects recorded

Safety Inspection of A90 & A972 South on 04 December 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 07 December 2018

No defects recorded

Safety Inspection of A90 & A972 South on 11 December 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 14 December 2018

No defects recorded

Safety Inspection of A90 & A972 South on 18 December 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 21 December 2018

No defects recorded

Safety Inspection of A90 & A972 South on 25 December 2018

No defects recorded

Safety Patrol of A90 Swallow to SCC on 28 December 2018

No defects recorded

Safety Inspection of A90 & A972 South on 01 January 2019

No defects recorded

Safety Patrol of A90 Swallow to SCC on 04 January 2019

No defects recorded

Safety Inspection of A90 & A972 South on 08 January 2019

No defects recorded

Safety Patrol of A90 Swallow to SCC on 11 January 2019

No defects recorded

Safety Inspection of A90 & A972 South on 15 January 2019

No defects recorded

Safety Patrol of A90 Swallow to SCC on 18 January 2019

No defects recorded

Safety Inspection of A90 & A972 South on 22 January 2019

No defects recorded

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of A90 Swallow to SCC on 25 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 29 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 01 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 08 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 12 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 15 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 19 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 22 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 26 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 01 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 05 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 08 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 12 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 15 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 19 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 22 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 26 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 29 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 29 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 02 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 05 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 09 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 12 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 16 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 19 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 23 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 26 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 30 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 03 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 07 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 10 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 14 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 17 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 20 May 2019									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 23 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 27 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 30 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 03 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 06 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 10 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 13 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 17 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 20 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 24 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 27 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 01 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 04 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 08 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 11 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 15 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 18 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 22 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 25 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 29 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 01 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 05 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 08 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 12 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 15 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 19 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 22 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 26 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 29 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 02 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 05 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 09 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 12 September 2019									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A90 SAFETY INSPECTION on 16 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 19 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 23 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 26 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 30 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 03 October 2019									
<i>No defects recorded</i>									
12150/86 : AGAINST: UNDER A923 RBT TO ENTRY SLIP FROM A923									
Safety Patrol of A90 Swallow to SCC on 05 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 09 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 12 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 16 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 19 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 23 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 26 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 30 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 02 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 06 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 09 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 13 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 16 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 20 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 23 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 27 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 30 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 04 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 07 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 11 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 14 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 18 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 21 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 25 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 28 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 01 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 04 January 2019									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 08 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 11 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 15 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 18 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 22 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 25 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 29 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 01 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 08 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 12 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 15 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 19 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 22 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 26 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 01 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 05 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 08 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 12 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 15 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 19 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 22 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 26 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 29 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 29 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 02 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 05 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 09 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 12 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 16 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 19 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 23 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 26 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 30 April 2019									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of A90 Swallow to SCC on 03 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 07 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 10 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 14 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 17 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 20 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 23 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 27 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 30 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 03 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 06 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 10 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 13 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 17 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 20 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 24 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 27 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 01 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 04 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 08 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 11 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 15 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 18 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 22 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 25 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 29 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 01 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 05 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 08 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 12 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 15 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 19 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 22 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 26 August 2019									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 29 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 02 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 05 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 09 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 12 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 16 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 19 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 23 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 26 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 30 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 03 October 2019									
<i>No defects recorded</i>									

12150/41 : AGAINST: ENTRY SLIP FROM A923 TO MYREKIRK RD RBT

Safety Patrol of A90 Swallow to SCC on 05 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 09 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 12 October 2018									
<i>No defects recorded</i>									
NE7-421178-236114939	1,782m	0m	MANHOLE	Rocking under load (IRLD)	CAT 1	13/11/2018	Completed Defects	31/10/2018	MYREKIRK RBT SB
Safety Patrol of A90 Swallow to SCC on 19 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 23 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 26 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 30 October 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 02 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 06 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 09 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 13 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 16 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 20 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 23 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 27 November 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 30 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 04 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 07 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 11 December 2018									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of A90 Swallow to SCC on 14 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 18 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 21 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 25 December 2018									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 28 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 01 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 04 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 08 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 11 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 15 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 18 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 22 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 25 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 29 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 01 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 08 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 12 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 15 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 19 February 2019									
NE14-430839-236330792	1,762m	0m	MANHOLE	Rocking under load (IRLD)	CAT 1	19/03/2019	Completed Defects	14/03/2019	JUST BEFORE MYREKIRK RBT SB
Safety Patrol of A90 Swallow to SCC on 22 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 26 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 01 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 05 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 08 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 12 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 15 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 19 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 22 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 26 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 29 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 29 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 02 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 05 April 2019									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 09 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 12 April 2019									
NE7-477205-236558601	322m	0m	CARRIAGEWAY	Single crack (CRCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	LINTON RD OFF SLIP SB
NE7-477205-236558602	323m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	LINTON RD OFF SLIP SB
NE7-477205-236558603	347m	0m	CARRIAGEWAY	Single crack (CRCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	LINTON RD OFF SLIP SB
NE7-477205-236558604	372m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	LINTON RD OFF SLIP SB
NE7-477205-236558605	380m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	LINTON RD OFF SLIP SB
NE7-477205-236558606	389m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	LINTON RD OFF SLIP SB
NE7-477205-236558607	390m	0m	CARRIAGEWAY	Single crack (CRCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	LINTON RD OFF SLIP SB
NE7-477205-236558608	390m	0m	CARRIAGEWAY	Miscellaneous surface Defects (MSRF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	PATCH 7M X 6M
NE7-477205-236558609	404m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	LIFF RD ON SLIP SB
NE7-477205-236558610	405m	0m	CARRIAGEWAY	Single crack (CRCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	LIFF RD ON SLIP SB
NE7-477205-236558611	405m	0m	CARRIAGEWAY	Single crack (CRCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
NE7-477205-236558612	407m	0m	CARRIAGEWAY	Single crack (CRCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
NE7-477205-236558613	418m	0m	CARRIAGEWAY	Single crack (CRCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	LIFF RD ON SLIP SB
NE7-477205-236558614	414m	0m	CARRIAGEWAY	Miscellaneous surface Defects (MSRF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	LIFF RD ON SLIP SB
Safety Inspection of A90 & A972 South on 16 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 19 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 23 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 26 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 30 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 03 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 07 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 10 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 14 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 17 May 2019									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A90 SAFETY INSPECTION on 20 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 23 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 27 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 30 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 03 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 06 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 10 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 13 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 17 June 2019									
NE14-527701-236853891	830m	0m	TRAFFIC_SIGNS	Obscured sign (OBSG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	ADJACENT TO SUBWAY S/B AFTER LIFF RD JCT
Safety Patrol of A90 SAFETY PATROL on 20 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 24 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 27 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 01 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 04 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 08 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 11 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 15 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 18 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 22 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 25 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 29 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 01 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 05 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 08 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 12 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 15 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 19 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 22 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 26 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 29 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 02 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 05 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 09 September 2019									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

No defects recorded
Safety Patrol of A90 SAFETY PATROL on 12 September 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 16 September 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 19 September 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 23 September 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 26 September 2019
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 30 September 2019
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 03 October 2019
No defects recorded

12150/06 : AGAINST: MYREKIRK ROAD RBT TO SWALLOW ROUNDABOUT

Safety Patrol of A90 Swallow to SCC on 05 October 2018
No defects recorded
Safety Inspection of A90 & A972 South on 09 October 2018
No defects recorded
Safety Patrol of A90 Swallow to SCC on 12 October 2018
No defects recorded
Safety Inspection of A90 & A972 South on 16 October 2018
No defects recorded
Safety Patrol of A90 Swallow to SCC on 19 October 2018
No defects recorded
Safety Inspection of A90 & A972 South on 23 October 2018
No defects recorded
Safety Patrol of A90 Swallow to SCC on 26 October 2018
No defects recorded
Safety Inspection of A90 & A972 South on 30 October 2018
No defects recorded
Safety Patrol of A90 Swallow to SCC on 02 November 2018
No defects recorded
Safety Inspection of A90 & A972 South on 06 November 2018
No defects recorded
Safety Patrol of A90 Swallow to SCC on 09 November 2018
No defects recorded
Safety Inspection of A90 & A972 South on 13 November 2018
No defects recorded
Safety Patrol of A90 Swallow to SCC on 16 November 2018
No defects recorded
Safety Inspection of A90 & A972 South on 20 November 2018
No defects recorded
Safety Patrol of A90 Swallow to SCC on 23 November 2018
No defects recorded
Safety Inspection of A90 & A972 South on 27 November 2018
No defects recorded
Safety Patrol of A90 Swallow to SCC on 30 November 2018
No defects recorded
Safety Inspection of A90 & A972 South on 04 December 2018
No defects recorded
Safety Patrol of A90 Swallow to SCC on 07 December 2018
No defects recorded
Safety Inspection of A90 & A972 South on 11 December 2018
No defects recorded
Safety Patrol of A90 Swallow to SCC on 14 December 2018
No defects recorded
Safety Inspection of A90 & A972 South on 18 December 2018
No defects recorded
Safety Patrol of A90 Swallow to SCC on 21 December 2018
No defects recorded
Safety Inspection of A90 & A972 South on 25 December 2018
No defects recorded
Safety Patrol of A90 Swallow to SCC on 28 December 2018
No defects recorded

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A90 & A972 South on 01 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 04 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 08 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 11 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 15 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 18 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 22 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 25 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 29 January 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 01 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 08 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 12 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 15 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 19 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 22 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 26 February 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 01 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 05 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 08 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 12 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 15 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 19 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 22 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 26 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 29 March 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 29 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 02 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 05 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 09 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 12 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 16 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 19 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 23 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 26 April 2019									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 30 April 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 03 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 07 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 10 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 & A972 South on 14 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 Swallow to SCC on 17 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 20 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 23 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 27 May 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 30 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 03 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 06 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 10 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 13 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 17 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 20 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 24 June 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 27 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 01 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 04 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 08 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 11 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 15 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 18 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 22 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 25 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 29 July 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 01 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 05 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 08 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 12 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 15 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 19 August 2019									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of A90 SAFETY PATROL on 22 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 26 August 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 29 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 02 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 05 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 09 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 12 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 16 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 19 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 23 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 26 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 30 September 2019									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 03 October 2019									
<i>No defects recorded</i>									