

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 26/11/2019 and 03/12/2019

(Road is 'M74',)

Job Reference	Defect Reference	Start m	End m	Item Type	Item Detail	Comments	Defect Cat	Required Completion Date	Current Status	Completion Date	Location Description
10793/11 : With: J3A slip on Jtn A721 to start 1 lane											
	Safety Inspection of M74 M73			Safety Inspection	on 26 November 2019						
	<i>No defects recorded</i>										
	Safety Patrol of M74 M73			Safety Patrol	on 29 November 2019						
	<i>No defects recorded</i>										
	Safety Inspection of M74 M73			Safety Inspection	on 03 December 2019						
	<i>No defects recorded</i>										
10793/12 : With: J3A slip on start 1 lane to end of slip											
	Safety Inspection of M74 M73			Safety Inspection	on 26 November 2019						
	<i>No defects recorded</i>										
	Safety Patrol of M74 M73			Safety Patrol	on 29 November 2019						
	<i>No defects recorded</i>										
	Safety Inspection of M74 M73			Safety Inspection	on 03 December 2019						
	<i>No defects recorded</i>										
10792/03 : With: J4 slip off to End Hard Shoulder											
	Safety Inspection of M74 M73			Safety Inspection	on 26 November 2019						
	<i>No defects recorded</i>										
	Safety Patrol of M74 M73			Safety Patrol	on 29 November 2019						
	<i>No defects recorded</i>										
	Safety Inspection of M74 M73			Safety Inspection	on 03 December 2019						
	<i>No defects recorded</i>										
10792/26 : With End of Hard Shoulder to end slip from M73											
	Safety Inspection of M74 M73			Safety Inspection	on 26 November 2019						
	<i>No defects recorded</i>										
	Safety Patrol of M74 M73			Safety Patrol	on 29 November 2019						
	<i>No defects recorded</i>										
	Safety Inspection of M74 M73			Safety Inspection	on 03 December 2019						
	<i>No defects recorded</i>										
10792/19 : With: J4 slip off from start to M73 NB split											
	Safety Inspection of M74 M73			Safety Inspection	on 26 November 2019						



Job Reference	Defect Reference	Start m	End m	Item Type	Item Detail	Comments	Defect Cat	Required Completion Date	Current Status	Completion Date	Location Description
---------------	------------------	---------	-------	-----------	-------------	----------	------------	--------------------------	----------------	-----------------	----------------------

No defects recorded
Safety Patrol of M74 M73 Safety Patrol on 29 November 2019
No defects recorded
Safety Inspection of M74 M73 Safety Inspection on 03 December 2019
No defects recorded

10792/08 : With: M74 J4 slip off to M73 J1 SB slip off
Safety Inspection of M74 M73 Safety Inspection on 26 November 2019
No defects recorded
Safety Patrol of M74 M73 Safety Patrol on 29 November 2019
No defects recorded
Safety Inspection of M74 M73 Safety Inspection on 03 December 2019
No defects recorded

10788/38 : Against: J1 slip on to Fallside Rd BO
Safety Inspection of M74 M73 Safety Inspection on 26 November 2019
No defects recorded
Safety Patrol of M74 M73 Safety Patrol on 29 November 2019
No defects recorded
Safety Inspection of M74 M73 Safety Inspection on 03 December 2019
No defects recorded

10793/02 : With: M73 J1 slip on to M8 DBFO Boundary
Safety Inspection of M74 M73 Safety Inspection on 26 November 2019
No defects recorded
Safety Patrol of M74 M73 Safety Patrol on 29 November 2019
No defects recorded
Safety Inspection of M74 M73 Safety Inspection on 03 December 2019
No defects recorded

10793/14 : With: J3A slip on start 1 lane to M8 DBFO Boundary
Safety Inspection of M74 M73 Safety Inspection on 26 November 2019
No defects recorded
Safety Patrol of M74 M73 Safety Patrol on 29 November 2019
No defects recorded
Safety Inspection of M74 M73 Safety Inspection on 03 December 2019
No defects recorded

10792/23 : With J4 slip off start to start 3 lanes
Safety Inspection of M74 M73 Safety Inspection on 26 November 2019
No defects recorded
Safety Patrol of M74 M73 Safety Patrol on 29 November 2019



Job Reference	Defect Reference	Start m	End m	Item Type	Item Detail	Comments	Defect Cat	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>											
Safety Inspection of M74 M73 Safety Inspection on 03 December 2019											
<i>No defects recorded</i>											
10788/66 : Against: M73 J1 3 lanes to Blantyre Farm Rd BO											
Safety Inspection of M74 M73 Safety Inspection on 26 November 2019											
<i>No defects recorded</i>											
Safety Patrol of M74 M73 Safety Patrol on 29 November 2019											
<i>No defects recorded</i>											
Safety Inspection of M74 M73 Safety Inspection on 03 December 2019											
<i>No defects recorded</i>											
10788/30 : Against: 3 lanes at Bothwell Services to 4 lanes											
Safety Inspection of M74 M73 Safety Inspection on 26 November 2019											
<i>No defects recorded</i>											
Safety Patrol of M74 M73 Safety Patrol on 29 November 2019											
<i>No defects recorded</i>											
Safety Inspection of M74 M73 Safety Inspection on 03 December 2019											
<i>No defects recorded</i>											
10788/29 : Against: Slip off to Bothwell Services											
Safety Inspection of M74 M73 Safety Inspection on 26 November 2019											
<i>No defects recorded</i>											
Safety Patrol of M74 M73 Safety Patrol on 29 November 2019											
M8-295955-136006	M8-295955-136006	55m	0m	CARRIAGEWAY	Pothole (POTH)	POTHOLE O/S WHEELTRACK	CAT 1	27/12/2019	Completed Work	29/11/2019	M74 S/B BOTHWELL SERVICES OFF SLIP
Safety Inspection of M74 M73 Safety Inspection on 03 December 2019											
<i>No defects recorded</i>											
10788/23 : Against: Slip on from Bothwell Services											
Safety Inspection of M74 M73 Safety Inspection on 26 November 2019											
<i>No defects recorded</i>											
Safety Patrol of M74 M73 Safety Patrol on 29 November 2019											
<i>No defects recorded</i>											
Safety Inspection of M74 M73 Safety Inspection on 03 December 2019											
<i>No defects recorded</i>											
10788/21 : Against: 4 lanes Bothwell services to J5 2 lanes											
Safety Inspection of M74 M73 Safety Inspection on 26 November 2019											
<i>No defects recorded</i>											
Safety Patrol of M74 M73 Safety Patrol on 29 November 2019											
<i>No defects recorded</i>											

Job Reference	Defect Reference	Start m	End m	Item Type	Item Detail	Comments	Defect Cat	Required Completion Date	Current Status	Completion Date	Location Description
---------------	------------------	---------	-------	-----------	-------------	----------	------------	--------------------------	----------------	-----------------	----------------------

Safety Inspection of M74 M73 Safety Inspection on 03 December 2019
No defects recorded

10788/15 : Against: J5 off 2 lanes to start 3 lanes

Safety Inspection of M74 M73 Safety Inspection on 26 November 2019
No defects recorded
Safety Patrol of M74 M73 Safety Patrol on 29 November 2019
No defects recorded
Safety Inspection of M74 M73 Safety Inspection on 03 December 2019
No defects recorded

10788/13 : Against: J5 off 3 lanes to Raith Rbt

Safety Inspection of M74 M73 Safety Inspection on 26 November 2019
No defects recorded
Safety Patrol of M74 M73 Safety Patrol on 29 November 2019
No defects recorded
Safety Inspection of M74 M73 Safety Inspection on 03 December 2019
No defects recorded

10788/16 : Against: J5 off 2 lanes to Raith Int BU

Safety Inspection of M74 M73 Safety Inspection on 26 November 2019
No defects recorded
Safety Patrol of M74 M73 Safety Patrol on 29 November 2019
No defects recorded
Safety Inspection of M74 M73 Safety Inspection on 03 December 2019
No defects recorded

10786/30 : Against: J5 on Raith Rbt to start 1 lane

Safety Inspection of M74 M73 Safety Inspection on 26 November 2019
No defects recorded
Safety Patrol of M74 M73 Safety Patrol on 29 November 2019
No defects recorded
Safety Inspection of M74 M73 Safety Inspection on 03 December 2019
No defects recorded

10786/27 : Against: J5 on 1 lane to start 4 lanes

Safety Inspection of M74 M73 Safety Inspection on 26 November 2019
No defects recorded
Safety Patrol of M74 M73 Safety Patrol on 29 November 2019
No defects recorded
Safety Inspection of M74 M73 Safety Inspection on 03 December 2019
No defects recorded



Job Reference	Defect Reference	Start m	End m	Item Type	Item Detail	Comments	Defect Cat	Required Completion Date	Current Status	Completion Date	Location Description
---------------	------------------	---------	-------	-----------	-------------	----------	------------	--------------------------	----------------	-----------------	----------------------

10786/21 : Against: J5 on 4 lanes to M8 DBFO Boundary

Safety Inspection of M74 M73 Safety Inspection on 26 November 2019

No defects recorded

Safety Patrol of M74 M73 Safety Patrol on 29 November 2019

No defects recorded

Safety Inspection of M74 M73 Safety Inspection on 03 December 2019

No defects recorded

10786/40 : Against: Raith Int BO to start 4 lanes

Safety Inspection of M74 M73 Safety Inspection on 26 November 2019

No defects recorded

Safety Patrol of M74 M73 Safety Patrol on 29 November 2019

No defects recorded

Safety Inspection of M74 M73 Safety Inspection on 03 December 2019

No defects recorded

10792/61 : Against: M8 DBFO Boundary to J4 off 1 lane

Safety Inspection of M74 M73 Safety Inspection on 26 November 2019

No defects recorded

Safety Patrol of M74 M73 Safety Patrol on 29 November 2019

No defects recorded

Safety Inspection of M74 M73 Safety Inspection on 03 December 2019

No defects recorded

10792/49 : Against: J3A off 1 lane to start 2 lanes

Safety Inspection of M74 M73 Safety Inspection on 26 November 2019

No defects recorded

Safety Patrol of M74 M73 Safety Patrol on 29 November 2019

No defects recorded

Safety Inspection of M74 M73 Safety Inspection on 03 December 2019

No defects recorded

10792/43 : Against: J3A off 2 lanes to Jtn A721

Safety Inspection of M74 M73 Safety Inspection on 26 November 2019

No defects recorded

Safety Patrol of M74 M73 Safety Patrol on 29 November 2019

No defects recorded

Safety Inspection of M74 M73 Safety Inspection on 03 December 2019

No defects recorded

10792/42 : Against: J4 off 2 lanes to start 3 lanes



Job Reference	Defect Reference	Start m	End m	Item Type	Item Detail	Comments	Defect Cat	Required Completion Date	Current Status	Completion Date	Location Description
	Safety Inspection of M74 M73				Safety Inspection on 26 November 2019						
					<i>No defects recorded</i>						
	Safety Patrol of M74 M73				Safety Patrol on 29 November 2019						
					<i>No defects recorded</i>						
	Safety Inspection of M74 M73				Safety Inspection on 03 December 2019						
					<i>No defects recorded</i>						
10792/39	: Against: J4 off 1 lane to start 2 lanes										
	Safety Inspection of M74 M73				Safety Inspection on 26 November 2019						
					<i>No defects recorded</i>						
	Safety Patrol of M74 M73				Safety Patrol on 29 November 2019						
					<i>No defects recorded</i>						
	Safety Inspection of M74 M73				Safety Inspection on 03 December 2019						
					<i>No defects recorded</i>						
10792/37	: Against: J3 off start of slip to start 2 lanes										
	Safety Inspection of M74 M73				Safety Inspection on 26 November 2019						
					<i>No defects recorded</i>						
	Safety Patrol of M74 M73				Safety Patrol on 29 November 2019						
					<i>No defects recorded</i>						
	Safety Inspection of M74 M73				Safety Inspection on 03 December 2019						
					<i>No defects recorded</i>						
10792/33	: Against: J3A on Slip Jtn A721 to start 1 lane										
	Safety Inspection of M74 M73				Safety Inspection on 26 November 2019						
					<i>No defects recorded</i>						
	Safety Patrol of M74 M73				Safety Patrol on 29 November 2019						
					<i>No defects recorded</i>						
	Safety Inspection of M74 M73				Safety Inspection on 03 December 2019						
					<i>No defects recorded</i>						
10792/31	: Against: J3A on slip 1 lane to end of slip										
	Safety Inspection of M74 M73				Safety Inspection on 26 November 2019						
					<i>No defects recorded</i>						
	Safety Patrol of M74 M73				Safety Patrol on 29 November 2019						
					<i>No defects recorded</i>						
	Safety Inspection of M74 M73				Safety Inspection on 03 December 2019						
					<i>No defects recorded</i>						
10792/27	: Against: J4 off 2 lanes to start 1 lane										
	Safety Inspection of M74 M73				Safety Inspection on 26 November 2019						
					<i>No defects recorded</i>						

Job Reference	Defect Reference	Start m	End m	Item Type	Item Detail	Comments	Defect Cat	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of M74 M73 Safety Patrol on 29 November 2019											
<i>No defects recorded</i>											
Safety Inspection of M74 M73 Safety Inspection on 03 December 2019											
<i>No defects recorded</i>											
10792/25 : Against: J4 off 1 lane to start 4 lanes											
Safety Inspection of M74 M73 Safety Inspection on 26 November 2019											
<i>No defects recorded</i>											
Safety Patrol of M74 M73 Safety Patrol on 29 November 2019											
<i>No defects recorded</i>											
Safety Inspection of M74 M73 Safety Inspection on 03 December 2019											
<i>No defects recorded</i>											
10786/20 : With: M8 DBFO Boundary to Raith Int BU											
Safety Inspection of M74 M73 Safety Inspection on 26 November 2019											
<i>No defects recorded</i>											
Safety Patrol of M74 M73 Safety Patrol on 29 November 2019											
<i>No defects recorded</i>											
Safety Inspection of M74 M73 Safety Inspection on 03 December 2019											
<i>No defects recorded</i>											
10786/23 : With: J5 off 2 lanes to start 3 lanes											
Safety Inspection of M74 M73 Safety Inspection on 26 November 2019											
<i>No defects recorded</i>											
Safety Patrol of M74 M73 Safety Patrol on 29 November 2019											
<i>No defects recorded</i>											
Safety Inspection of M74 M73 Safety Inspection on 03 December 2019											
<i>No defects recorded</i>											
10786/29 : With: J5 off 3 lanes to Raith Rbt											
Safety Inspection of M74 M73 Safety Inspection on 26 November 2019											
<i>No defects recorded</i>											
Safety Patrol of M74 M73 Safety Patrol on 29 November 2019											
<i>No defects recorded</i>											
Safety Inspection of M74 M73 Safety Inspection on 03 December 2019											
<i>No defects recorded</i>											
10788/01 : With: Raith Int BU to start 4 lanes											
Safety Inspection of M74 M73 Safety Inspection on 26 November 2019											
<i>No defects recorded</i>											
Safety Patrol of M74 M73 Safety Patrol on 29 November 2019											
<i>No defects recorded</i>											

Job Reference	Defect Reference	Start m	End m	Item Type	Item Detail	Comments	Defect Cat	Required Completion Date	Current Status	Completion Date	Location Description
---------------	------------------	---------	-------	-----------	-------------	----------	------------	--------------------------	----------------	-----------------	----------------------

Safety Inspection of M74 M73 Safety Inspection on 03 December 2019
No defects recorded

10788/10 : With: J5 on Raith Rbt to end of slip

Safety Inspection of M74 M73 Safety Inspection on 26 November 2019
No defects recorded

Safety Patrol of M74 M73 Safety Patrol on 29 November 2019
No defects recorded

Safety Inspection of M74 M73 Safety Inspection on 03 December 2019
No defects recorded

10788/25 : With: J5 on 4 lanes to Fallside Road BO

Safety Inspection of M74 M73 Safety Inspection on 26 November 2019
No defects recorded

Safety Patrol of M74 M73 Safety Patrol on 29 November 2019
No defects recorded

Safety Inspection of M74 M73 Safety Inspection on 03 December 2019
No defects recorded

10788/39 : With: Fallside Rd BO to Old Mill Rd BO

Safety Inspection of M74 M73 Safety Inspection on 26 November 2019
No defects recorded

Safety Patrol of M74 M73 Safety Patrol on 29 November 2019
No defects recorded

Safety Inspection of M74 M73 Safety Inspection on 03 December 2019
No defects recorded

10788/40 : With: Old Mill Rd BO to J4 off 2 lanes

Safety Inspection of M74 M73 Safety Inspection on 26 November 2019
No defects recorded

Safety Patrol of M74 M73 Safety Patrol on 29 November 2019
No defects recorded

Safety Inspection of M74 M73 Safety Inspection on 03 December 2019
No defects recorded

10792/24 : With: J3A slip off M73 J1 SB slip off to Jtn A721

Safety Inspection of M74 M73 Safety Inspection on 26 November 2019
No defects recorded

Safety Patrol of M74 M73 Safety Patrol on 29 November 2019
No defects recorded

Safety Inspection of M74 M73 Safety Inspection on 03 December 2019
No defects recorded



Job Reference	Defect Reference	Start m	End m	Item Type	Item Detail	Comments	Defect Cat	Required Completion Date	Current Status	Completion Date	Location Description
---------------	------------------	---------	-------	-----------	-------------	----------	------------	--------------------------	----------------	-----------------	----------------------

10788/28 : Against: Fallside Rd BO to start 3 lanes

Safety Inspection of M74 M73 Safety Inspection on 26 November 2019

No defects recorded

Safety Patrol of M74 M73 Safety Patrol on 29 November 2019

No defects recorded

Safety Inspection of M74 M73 Safety Inspection on 03 December 2019

No defects recorded

