

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/12/2019 and 13/02/2020, and defects raised outside of inspections on the same Section(s) during this period.

- (Road is 'A96',)
- (Section Code is 12685/92) Or
- (Section Code is 12685/90) Or
- (Section Code is 12685/85) Or
- (Section Code is 12685/55) Or
- (Section Code is 12685/50) Or
- (Section Code is 12685/40) Or
- (Section Code is 12685/35) Or
- (Section Code is 12685/30) Or
- (Section Code is 12685/25) Or
- (Section Code is 12685/20) Or
- (Section Code is 12685/15) Or
- (Section Code is 12685/10) Or
- (Section Code is 12685/05) Or
- (Section Code is 12680/60) Or
- (Section Code is 12680/50) Or
- (Section Code is 12680/10) Or
- (Section Code is 12675/80) Or
- (Section Code is 12675/60) Or
- (Section Code is 12675/05)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
12675/05 : X-RDS AT TRADESPARK TO DISTRICT BDY									
Safety Inspection of A95.A96 SAFETY INSPECTION on 05 December 2019									
No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 12 December 2019									
No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 19 December 2019									
NE131537592-237211521	2,429m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	20/12/2019	Completed Defects	19/12/2019	NB AFT DELNIES
NE131537592-237211522	2,429m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	20/12/2019	Completed Defects	19/12/2019	NB AFT DELNIES
NE131537592-237211523	2,410m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB AFT DELNIES
NE131537592-237211524	1,847m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	20/12/2019	Completed Defects	19/12/2019	NB BEF DELNIES

Safety Inspection of A95.A96 SAFETY INSPECTION on 26 December 2019

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 02 January 2020

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 09 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 16 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 23 January 2020									
NE131538585-237246006	539m	0m	TRAFFIC_SIGNS	Pointing wrong way (RWAY)	CAT 1	24/01/2020	Completed Defects	23/01/2020	SB BFR NAIRN
Safety Inspection of A95.A96 SAFETY INSPECTION on 30 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 06 February 2020									
NE131539044-237254290	2,254m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB BEF DELNIES JCT
NE131539044-237254285	2,424m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/03/2020	Awaiting CCMS Permanent Date	01/01/9999	NB AFT DELNIES JCT
NE131539044-237254286	2,439m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB AFT DELNIES JCT
NE131539044-237254287	2,851m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	07/02/2020	Completed Defects	06/02/2020	SB AFT WHITENESS JCT
NE131539044-237254288	2,258m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/03/2020	Awaiting CCMS Permanent Date	01/01/9999	SB BEF DELNIES JCT
NE131539044-237254289	2,258m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/03/2020	Awaiting CCMS Permanent Date	01/01/9999	SB BEF DELNIES JCT
Safety Inspection of A95.A96 SAFETY INSPECTION on 13 February 2020									
<i>No defects recorded</i>									
12675/60 : DISTRICT BOUNDARY TO JCT LOCHSIDE									
Safety Inspection of A95.A96 SAFETY INSPECTION on 05 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 12 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 19 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 26 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 02 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 09 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 16 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 23 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 30 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 06 February 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 13 February 2020									
<i>No defects recorded</i>									
12675/80 : JCT LOCHSIDE TO B9090 JCT TO CLEPHANTON									
Safety Inspection of A95.A96 SAFETY INSPECTION on 05 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 12 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 19 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 26 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 02 January 2020									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 09 January 2020									
No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 16 January 2020									
No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 23 January 2020									
No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 30 January 2020									
No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 06 February 2020									
No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 13 February 2020									
No defects recorded									
12685/05 : B9039 AIRPORT JUNCTION TO ALLANFEARN JUNCTION									
Safety Inspection of A95.A96 SAFETY INSPECTION on 05 December 2019									
No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 12 December 2019									
No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 19 December 2019									
NE131537592-237211517	2,559m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	20/12/2019	Completed Defects	19/12/2019	SB AFT ALTURLIE JCT
NE131537592-237211518	1,362m	0m	TRAFFIC_SIGNS	Accident damage (ACCD)	CAT 1	16/01/2020	Completed Defects	16/01/2020	NB BALLOCH JCT OFF SLIP
Safety Inspection of A95.A96 SAFETY INSPECTION on 26 December 2019									
No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 02 January 2020									
No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 09 January 2020									
No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 16 January 2020									
NE11-538371-237232725	2,157m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/02/2020	Completed Defects	12/02/2020	SB AFT NORBOARD
NE11-538371-237232726	2,157m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/02/2020	Completed Defects	12/02/2020	SB AFT NORBOARD
NE11-538371-237232727	2,151m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	17/01/2020	Cat 2 Awaiting Action	01/01/9999	SB AFT NORBOARD
NE11-538371-237232728	2,562m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/02/2020	Completed Defects	12/02/2020	NB BFR NORBOARD
NE11-538371-237232729	2,561m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB BFR NORBOARD
Safety Inspection of A95.A96 SAFETY INSPECTION on 23 January 2020									
NE131538585-237246005	1,128m	0m	TRAFFIC_SIGNS	Pointing wrong way (RWAY)	CAT 2		Cat 2 Awaiting Action		SB AFT BALLOCH JTN
Safety Inspection of A95.A96 SAFETY INSPECTION on 30 January 2020									
NE11538772-237249923	1,897m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/02/2020	Awaiting CCMS Permanent Date	01/01/9999	SB BFR BALLCH JTN
NE11538772-237249924	1,899m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/02/2020	Awaiting CCMS Permanent Date	01/01/9999	SB BFR BALLOCH JTN
NE11538772-237249925	1,899m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 2		Cat 2 Awaiting Action		SB BFR BALLOCH JTN
Safety Inspection of A95.A96 SAFETY INSPECTION on 06 February 2020									
NE131539044-237254284	2,470m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	07/02/2020	Completed Defects	06/02/2020	SB AFT ALLANFEARN JCT
Safety Inspection of A95.A96 SAFETY INSPECTION on 13 February 2020									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE11539389-237270899	2,565m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/03/2020	Awaiting CCMS Permanent Date	01/01/9999	SB AFT GOLLANFIELD
NE11539389-237270900	2,565m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB AFT GOLLANFIELD
NE11539389-237270901	2,524m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/03/2020	Awaiting CCMS Permanent Date	01/01/9999	SB AFT GOLLANFIELD
NE11539389-237270902	2,543m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB AFT GOLLANFIELD
NE11539389-237270903	2,516m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/03/2020	Awaiting CCMS Permanent Date	01/01/9999	SB AFT GOLLANFIELD
NE11539389-237270904	2,519m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB AFT GOLLANFIELD
NE11539389-237270905	2,465m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		SB AFT GOLLANFIELD
NE11539389-237270906	1,038m	0m	MANHOLE	Rocking under load (IRLD)	3RD PTY	12/03/2020	Awaiting CCMS Permanent Date	01/01/9999	SB AFT BALLOCH JTN

12685/85 : SEAFIELD ROUNDABOUT

Safety Inspection of A95.A96 SAFETY INSPECTION on 05 December 2019

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 12 December 2019

NE131537368-237205749	4m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	13/12/2019	Completed Defects	12/12/2019	NB SEAFIELD RBT
-----------------------	----	----	-------------	-----------------------	-------	------------	-------------------	------------	-----------------

Safety Inspection of A95.A96 SAFETY INSPECTION on 19 December 2019

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 26 December 2019

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 02 January 2020

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 09 January 2020

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 16 January 2020

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 23 January 2020

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 30 January 2020

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 06 February 2020

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 13 February 2020

No defects recorded

12685/90 : WITH:SEAFIELD ROUNDABOUT TO RAIGMORE INTERCHANGE

Safety Inspection of A95.A96 SAFETY INSPECTION on 05 December 2019

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 12 December 2019

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 19 December 2019

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 26 December 2019

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 02 January 2020

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 09 January 2020

NE11-538159-237222444	630m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	10/01/2020	Completed Defects	09/01/2020	NB BFR RAIGMORE INT
-----------------------	------	----	-------------	-----------------------	-------	------------	-------------------	------------	---------------------

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A95.A96 SAFETY INSPECTION on 16 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 23 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 30 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 06 February 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 13 February 2020									
<i>No defects recorded</i>									
12685/92 : AGAINST:RAIGMORE INTERCHANGE TO SEAFIELD RBT									
Safety Inspection of A95.A96 SAFETY INSPECTION on 05 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 12 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 19 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 26 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 02 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 09 January 2020									
NE11-538159-237222443	72m	0m	STRUCTURE	Damaged Parapets (DAMP)	CAT 2		Cat 2 Awaiting Action		SB AFT RAIGMORE INTERCHANGE
Safety Inspection of A95.A96 SAFETY INSPECTION on 16 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 23 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 30 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 06 February 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 13 February 2020									
<i>No defects recorded</i>									
12680/10 : JUNCTION B9006 TO CROY ROUNDABOUT									
Safety Inspection of A95.A96 SAFETY INSPECTION on 05 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 12 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 19 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 26 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 02 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 09 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 16 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 23 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 30 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 06 February 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 13 February 2020									
<i>No defects recorded</i>									
12680/50 : CROY ROUNDABOUT									
Safety Inspection of A95.A96 SAFETY INSPECTION on 05 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 12 December 2019									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 19 December 2019									
NE131537592-237211519	154m	0m	CARRIAGEWAY	Flooding (FLOD)	CAT 2		Cat 2 Awaiting Action		CROY RBT
NE131537592-237211520	166m	0m	GULLY	Silted (SILT)	CAT 2		Cat 2 Awaiting Action		CROY RBT

Safety Inspection of A95.A96 SAFETY INSPECTION on 26 December 2019

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 02 January 2020

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 09 January 2020

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 16 January 2020

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 23 January 2020

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 30 January 2020

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 06 February 2020

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 13 February 2020

No defects recorded

12680/60 : CROY ROUNDABOUT TO JUNCTION B9039 DALCROSS

Safety Inspection of A95.A96 SAFETY INSPECTION on 05 December 2019

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 12 December 2019

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 19 December 2019

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 26 December 2019

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 02 January 2020

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 09 January 2020

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 16 January 2020

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 23 January 2020

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 30 January 2020

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 06 February 2020

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 13 February 2020

No defects recorded

12685/10 : Allanfear Jct to Smithton Rbt

Safety Inspection of A95.A96 SAFETY INSPECTION on 05 December 2019

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 12 December 2019

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 19 December 2019

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 26 December 2019

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 02 January 2020

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 09 January 2020

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 16 January 2020

No defects recorded

Safety Inspection of A95.A96 SAFETY INSPECTION on 23 January 2020

No defects recorded

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A95.A96 SAFETY INSPECTION on 30 January 2020 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 06 February 2020 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 13 February 2020 No defects recorded									
12685/15 : With: Start of Divided Cway to Smithton Rbt									
Safety Inspection of A95.A96 SAFETY INSPECTION on 05 December 2019 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 12 December 2019 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 19 December 2019 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 26 December 2019 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 02 January 2020									
NE131537918-237221953	14m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	03/01/2020	Completed Defects	02/01/2020	NB BEFORE SMITHTON RBT
NE131537918-237221954	29m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	30/01/2020	Completed Defects	29/01/2020	NB BEFORE SMITHTON RBT
NE131537918-237221955	29m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		NB BEFORE SMITHTON RBT
Safety Inspection of A95.A96 SAFETY INSPECTION on 09 January 2020 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 16 January 2020 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 23 January 2020 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 30 January 2020 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 06 February 2020 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 13 February 2020 No defects recorded									
12685/20 : AGAINST: Smithton Rbt to End of Divided Cway									
Safety Inspection of A95.A96 SAFETY INSPECTION on 05 December 2019 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 12 December 2019 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 19 December 2019 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 26 December 2019 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 02 January 2020 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 09 January 2020 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 16 January 2020 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 23 January 2020 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 30 January 2020 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 06 February 2020 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 13 February 2020 No defects recorded									
12685/25 : Smithton Roundabout									
Safety Inspection of A95.A96 SAFETY INSPECTION on 05 December 2019 No defects recorded									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A95.A96 SAFETY INSPECTION on 12 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 19 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 26 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 02 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 09 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 16 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 23 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 30 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 06 February 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 13 February 2020									
<i>No defects recorded</i>									

12685/30 : With: Smithton Rbt to End of Divided Cway

Safety Inspection of A95.A96 SAFETY INSPECTION on 05 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 12 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 19 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 26 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 02 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 09 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 16 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 23 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 30 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 06 February 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 13 February 2020									
<i>No defects recorded</i>									

12685/35 : Against: Start of Divided Cway to Smithton Rbt

Safety Inspection of A95.A96 SAFETY INSPECTION on 05 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 12 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 19 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 26 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 02 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 09 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 16 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 23 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 30 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 06 February 2020									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A95.A96 SAFETY INSPECTION on 13 February 2020 No defects recorded									
12685/40 : Smithton Rbt to Seafield Rbt									
Safety Inspection of A95.A96 SAFETY INSPECTION on 05 December 2019 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 12 December 2019 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 19 December 2019 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 26 December 2019 No defects recorded									
NE131537746-237219949	297m	0m	TRAFFIC_SIGNS	Pointing wrong way (RWAY)	CAT 1	27/12/2019	Completed Defects	26/12/2019	SB BEFORE SMITHTON RBT
Safety Inspection of A95.A96 SAFETY INSPECTION on 02 January 2020 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 09 January 2020 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 16 January 2020 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 23 January 2020 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 30 January 2020 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 06 February 2020 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 13 February 2020 No defects recorded									
12685/50 : With: Start of Divided C/way to Seafield Rbt									
Safety Inspection of A95.A96 SAFETY INSPECTION on 05 December 2019 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 12 December 2019 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 19 December 2019 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 26 December 2019 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 02 January 2020 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 09 January 2020 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 16 January 2020 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 23 January 2020 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 30 January 2020 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 06 February 2020 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 13 February 2020 No defects recorded									
12685/55 : Against: Seafield Rbt to End of Divided Cway									
Safety Inspection of A95.A96 SAFETY INSPECTION on 05 December 2019 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 12 December 2019 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 19 December 2019 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 26 December 2019 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 02 January 2020 No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 09 January 2020 No defects recorded									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A95.A96 SAFETY INSPECTION on 16 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 23 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 30 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 06 February 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 13 February 2020									
<i>No defects recorded</i>									