

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/02/2017 and 03/03/2020, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'With Opp Westbound Off Slip to M8PPP Boundary',) Or

(Section is 'Against: M8PPP Boundary to Whistleberry Road',) Or

(Section is 'With: Craighead on Slip to Opp Westbound Off Slip',) Or

(Section is 'AGAINST: OFF SLIP TO ON SLIP WHISTLEBERRY RD',) Or

(Section is 'WITH: CRAIGHEAD OFF SLIP TO ON SLIP',) Or

(Section is 'WITH: GLASGOW RD ON SLIP TO CRAIGHEAD OFF SLIP',) Or

(Section is 'AGAINST:ON SLIP WBERRY RD TO OFF SLIP MAIN ST',) Or

(Section is 'WITH: MAIN ST ON SLIP TO GLASGOW RD ON SLIP',) Or

(Section is 'WITH: MAIN STREET OFF SLIP TO ON SLIP',) Or

(Section is 'AGAINST: OFF SLIP TO ON SLIP MAIN STREET',) Or

(Section is 'WITH: DOUGLAS RD ON SLIP TO MAIN ST OFF SLIP',) Or

(Section is 'AGAINST: OFF SLIP TO ON SLIP DOUGLAS ST',) Or

(Section is 'WITH: HAMILTON RD OFF SLIP TO DOUGLAS RD OFF SLIP',) Or

(Section is 'AGAINST: DOUGLAS ST TO CROSSBASKETS',) Or

(Section is 'WITH: WHIRLIES BYPASS TO HAMILTON ROAD OFF SLIP',) Or

(Section is 'AGAINST: CROSSBASKET TO WHIRLES BYPASS',) Or

(Section is 'WITH: THE WHIRLIES RBT TO WHIRLIES BYPASS',) Or

(Section is 'AGAINST: WHIRLIES BP TO SLIP TO CALDERWOOD RD',) Or

(Section is 'AGAINST: WHIRLIES RBT TO WHITEMOSS RBT (KINGSWAY)',) Or

(Section is 'WITH: WHITEMOSS RBT TO THE WHIRLIES RBT',) Or

(Section is 'AGAINST: WMOSS RBT TO BIRNIEHILL RBT (KINGSWAY)',) Or

(Section is 'WITH: BIRNIEHILL RBT TO WHITEMOSS RBT (KINGSWAY)',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	---------	-------	-----------	-------------	-----------------	--------------------------	----------------	-----------------	----------------------

15010/05 : WITH: BIRNIEHILL RBT TO WHITEMOSS RBT (KINGSWAY)

Safety Inspection of A725 & A726 Tannochside V1 on 06 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 April 2017

SW85-260143-235074801 548m 0m KERB CAT 1 08/05/2017 Completed Defects 04/05/2017 A725 AT WHITEMOSS RBT

Safety Inspection of A725 & A726 Tannochside V1 on 17 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 28 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 08 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 15 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 26 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 31 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 07 August 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 14 August 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 21 August 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 28 August 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 04 September 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 11 September 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 18 September 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 25 September 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 02 October 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 09 October 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 16 October 2017

No defects recorded

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 28 May 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 04 June 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 11 June 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 18 June 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 25 June 2018

SW85-369136-235853363	557m	557m	KERB	Damaged (DAMG)	CAT 1	23/07/2018	Completed Defects	03/08/2018	A725 BURNIEHILL TO WHITEMOSS R/A @WHITEMOSS
-----------------------	------	------	------	-------------------	-------	------------	----------------------	------------	---

Safety Inspection of A725 & A726 Tannochside V1 on 02 July 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 09 July 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 16 July 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 23 July 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 30 July 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 August 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 August 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 August 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 August 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 September 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 September 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 September 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 September 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 01 October 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 08 October 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 15 October 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 October 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 October 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 November 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 November 2018
No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 26 November 2018
No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 December 2018
No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 December 2018
No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 December 2018
No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 December 2018
No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 31 December 2018
No defects recorded

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 19 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 26 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 09 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 16 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 23 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 30 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 07 October 2019

SW85-535030-237037838	553m	553m	GULLY	Blockage (BLOK)	CAT 1	04/11/2019	Completed Defects	18/10/2019	A725 WB BETWEEN BHILL - WHITEMOSS
SW85-535030-237037839	402m	402m	GULLY	Blockage (BLOK)	CAT 1	04/11/2019	Completed Defects	18/10/2019	A725 WB BETWEEN BHILL - WHITEMOSS
SW85-535030-237037840	368m	368m	GULLY	Blockage (BLOK)	CAT 1	04/11/2019	Completed Defects	18/10/2019	A725 WB BETWEEN BHILL - WHITEMOSS
SW85-535030-237037841	326m	326m	GULLY	Blockage (BLOK)	CAT 1	04/11/2019	Completed Defects	18/10/2019	A725 WB BETWEEN BHILL - WHITEMOSS
SW85-535030-237037842	277m	277m	GULLY	Blockage (BLOK)	CAT 1	04/11/2019	Completed Defects	18/10/2019	A725 WB BETWEEN BHILL - WHITEMOSS

Safety Inspection of A725 & A726 Glasgow East V1 on 14 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 21 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 28 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 04 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 11 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 18 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 25 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 09 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 16 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 30 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 06 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 13 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 20 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 27 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 February 2020

SW85-539432-237270427	547m	547m	GULLY	Blockage (BLOK)	CAT 1	09/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 NB BETWEEN WHITEMOSS - BIRNIEHILL RBT
SW85-539432-237270428	516m	516m	GULLY	Blockage	CAT 1	09/03/2020	Awaiting CCMS	01/01/9999	A725 NB BETWEEN

(BLOK)

Permanent

WHITEMOSS - BIRNIEHILL RBT

Safety Inspection of A725 & A726 Glasgow East V1 on 17 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 February 2020

SW85-544128-237284468	278m	278m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/03/2020	Awaiting CCMS Permanent	25/02/2020	A726 NB BETWEEN BIRNIEHILL RBT -WHITEMOSS RBT
SW85-544128-237284471	215m	215m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	25/02/2020	Awaiting CCMS Permanent	01/01/9999	A725 NB BETWEEN BIRNIEHILL RBT - WHITEMOSS RBT

Safety Inspection of A725 & A726 Glasgow East V1 on 02 March 2020

No defects recorded

15010/06 : AGAINST: WMOSS RBT TO BIRNIEHILL RBT (KINGSWAY)

Safety Inspection of A725 & A726 Tannochside V1 on 06 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 28 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 08 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 15 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 June 2017

SW85-279773-235194744	41m	42m	CABINET	Other (OTHR)	CAT 1	10/07/2017	Completed Defects	12/06/2017	A725 BETWEEN WHITEMOSS & BIRNIEHILL RBTS (CABINET IN CENTRE RES JUST AFTER WHITEMOSS RBT)
SW85-279773-235194745	134m	134m	CARRIAGEWAY	Pothole (POTH)	CAT 1	10/07/2017	Completed Defects	06/07/2017	A725 WHITEMOSS TO BIRNIEHILL AT CABINET ON LEFT VERGE AT TRAFFIC LOOPS

Safety Inspection of A725 & A726 Tannochside V1 on 19 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 26 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 31 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 07 August 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 14 August 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 21 August 2017

SW85-283749-235321437	49m	0m	GULLY	Blockage (BLOK)	CAT 1	18/09/2017	Completed Defects	06/09/2017	A725 WB 49M PAST WHITEMOSS RBT LANE 1 NS WT
SW85-283749-235321438	53m	0m	GULLY	Blockage (BLOK)	CAT 1	18/09/2017	Completed Defects	06/09/2017	A725 WB 53M PAST WHITEMOSS RBT LANE 1 NS WT

Safety Inspection of A725 & A726 Tannochside V1 on 28 August 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 04 September 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 11 September 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 18 September 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 25 September 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 02 October 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 09 October 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 16 October 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 23 October 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 30 October 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 November 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 November 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 November 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 26 November 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 04 December 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 11 December 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 18 December 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 December 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 December 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 January 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 08 January 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 15 January 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 January 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 January 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 February 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 February 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 February 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 26 February 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 March 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 March 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 March 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 26 March 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 March 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 April 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 09 April 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 16 April 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 23 April 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 30 April 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 04 May 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 11 May 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 14 May 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 21 May 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 28 May 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 04 June 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 11 June 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 18 June 2018

SW85-365643-235853363 266m 266m CARRIAGEWAY

*Pothole VIAFIX
(POTV)*

CAT 1

19/06/2018

*Completed
Defects*

18/06/2018

*A725 WHITEMOSS TO
BIRNIEHILL R/A N/S/L*

Safety Inspection of A725 & A726 Tannochside V1 on 25 June 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 02 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 09 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 16 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 23 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 30 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 September 2018*No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 10 September 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 17 September 2018**

SW85-408949-236066475	42m	42m	GULLY	Blockage (BLOK)	CAT 1	18/09/2018	Completed Defects	18/09/2018	A725 WB 40M PAST WHITEMOSS RBT
SW85-408949-236066476	54m	54m	GULLY	Blockage (BLOK)	CAT 1	18/09/2018	Completed Defects	18/09/2018	A725 WB 40M PAST WHITEMOSS RBT

Safety Inspection of A725 & A726 Tannochside V1 on 24 September 2018*No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 01 October 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 08 October 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 15 October 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 22 October 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 29 October 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 05 November 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 12 November 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 19 November 2018***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 26 November 2018***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 03 December 2018***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 10 December 2018***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 17 December 2018***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 24 December 2018***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 31 December 2018***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 07 January 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 14 January 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 21 January 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 28 January 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 04 February 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 11 February 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 18 February 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 25 February 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 04 March 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 11 March 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 18 March 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 25 March 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 01 April 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 08 April 2019**

<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 15 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 18 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 26 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 29 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 03 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 10 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 13 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 20 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 27 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 03 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 10 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 17 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 24 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 01 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 08 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 15 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 22 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 29 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 05 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 12 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 19 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 26 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 02 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 09 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 16 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 23 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 30 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 07 October 2019									
SW85-535030-237037836	49m	49m	GULLY	Blockage (BLOK)	CAT 1	04/11/2019	Completed Defects	18/10/2019	A725 EB WHITEMOSS - BHILL
SW85-535030-237037837	47m	47m	GULLY	Blockage (BLOK)	CAT 1	04/11/2019	Completed Defects	18/10/2019	A725 EB WMOSS- BHILL
Safety Inspection of A725 & A726 Glasgow East V1 on 14 October 2019									
SW85-535241-237054114	464m	464m	GULLY	Blockage (BLOK)	CAT 1	11/11/2019	Completed Defects	26/10/2019	A725 WB 50M PRIOR TO BHILL RBT OS EDGE
Safety Inspection of A725 & A726 Glasgow East V1 on 21 October 2019									
<i>No defects recorded</i>									

Safety Inspection of A725 & A726 Glasgow East V1 on 28 October 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 04 November 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 11 November 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 18 November 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 25 November 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 02 December 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 09 December 2019**

SW85-537396-237210696	44m	44m	GULLY	Blockage (BLOK)	CAT 1	06/01/2020	Awaiting CCMS Permanent	01/01/9999	A725 WHITEMOSS TO BURNIEHILL R/A FIRST GULLY PASSED WHITEMOSS R/A
SW85-537396-237210697	50m	50m	GULLY	Blockage (BLOK)	CAT 1	06/01/2020	Awaiting CCMS Permanent	01/01/9999	A725 WHITEMOSS TO BURNIEHILL R/A SECOND GULLY PASSED WHITEMOSS

Safety Inspection of A725 & A726 Glasgow East V1 on 16 December 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 30 December 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 06 January 2020***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 13 January 2020**

SW85-538413-237239869	49m	49m	GULLY	Blockage (BLOK)	CAT 1	10/02/2020	Awaiting CCMS Permanent	01/01/9999	A725 WB BETWEEN WHITEMOSS-BIRNIEHILL RBTS
SW85-538413-237239870	52m	52m	GULLY	Blockage (BLOK)	CAT 1	10/02/2020	Awaiting CCMS Permanent	01/01/9999	A725 WB BETWEEN WMOSS RBT- BHILL RBT

Safety Inspection of A725 & A726 Glasgow East V1 on 20 January 2020*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 27 January 2020***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 03 February 2020***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 10 February 2020**

SW85-539432-237270418	554m	554m	GULLY	Blockage (BLOK)	CAT 1	09/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 NB BETWEEN BIRNIEHILL-WHITEMOSS RBT
SW85-539432-237270419	522m	522m	GULLY	Blockage (BLOK)	CAT 1	09/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 NB BETWEEN BIRNIEHILL-WHITEMOSS RBT
SW85-539432-237270420	496m	496m	GULLY	Blockage (BLOK)	CAT 1	09/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 NB BETWEEN BIRNIEHILL-WHITEMOSS RBT
SW85-539432-237270421	17m	17m	GULLY	Blockage (BLOK)	CAT 1	09/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 NB BETWEEN BIRNIEHILL-WHITEMOSS RBT
SW85-539432-237270422	49m	49m	GULLY	Blockage (BLOK)	CAT 1	09/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 NB BETWEEN BIRNIEHILL-WHITEMOSS RBT
SW85-539432-237270423	53m	53m	GULLY	Blockage (BLOK)	CAT 1	09/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 NB BETWEEN BIRNIEHILL-WHITEMOSS RBT
SW85-539432-237270424	124m	124m	GULLY	Blockage (BLOK)	CAT 1	09/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 NB BETWEEN BIRNIEHILL-WHITEMOSS RBT
SW85-539432-237270425	170m	170m	GULLY	Blockage (BLOK)	CAT 1	09/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 NB BETWEEN BIRNIEHILL-WHITEMOSS RBT
SW85-539432-237270426	197m	197m	GULLY	Blockage (BLOK)	CAT 1	09/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 NB BETWEEN BIRNIEHILL-WHITEMOSS RBT

Safety Inspection of A725 & A726 Glasgow East V1 on 17 February 2020*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 24 February 2020**

SW85-544128-237284467	290m	290m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	25/02/2020	Completed Defects	25/02/2020	A725 SB BETWEEN WHITEMOSS-BIRNIEHILL
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	--------------------------------------

Safety Inspection of A725 & A726 Glasgow East V1 on 02 March 2020

No defects recorded

15015/05 : WITH: WHITEMOSS RBT TO THE WHIRLIES RBT

Safety Inspection of A725 & A726 Tannochside V1 on 06 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 28 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 08 May 2017

SW85-269799-235096884	10m	0m	SAFETY_FENCE	Accident damage (ACCD)	CAT 1	05/06/2017	Completed Defects	09/06/2017	A725 EB 10M PAST WHITEMOSS RBT
-----------------------	-----	----	--------------	------------------------	-------	------------	-------------------	------------	--------------------------------

Safety Inspection of A725 & A726 Tannochside V1 on 15 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 26 June 2017

SW85-281644-235228843	528m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	24/07/2017	Completed Defects	04/07/2017	A725 EB AT LONDIS GARAGE TO WHIRLIES RBT LANE 1 NS WT
-----------------------	------	----	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Tannochside V1 on 03 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 31 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 07 August 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 14 August 2017*No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 21 August 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 28 August 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 04 September 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 11 September 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 18 September 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 25 September 2017**

SW85-314896-235384194	888m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/10/2017	Completed Defects	12/10/2017	A725 EB 450M PRIOR TO WHIRLIES RBT NS WT
-----------------------	------	----	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A725 & A726 Tannochside V1 on 02 October 2017

SW85-315101-235393065	998m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	30/10/2017	Completed Defects	12/10/2017	A725 EB 350M PRIOR TO WHIRLIES RBT LANE 1 NS WT
-----------------------	------	----	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Tannochside V1 on 09 October 2017*No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 16 October 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 23 October 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 30 October 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 06 November 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 13 November 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 20 November 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 26 November 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 04 December 2017**

SW85-316656-235485391	978m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/01/2018	Completed Defects	10/01/2018	A725 EB 400M PRIOR TO WHIRLIES RBT LANE 1 NS WT
-----------------------	------	----	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Tannochside V1 on 11 December 2017*No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 18 December 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 22 December 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 29 December 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 05 January 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 08 January 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 15 January 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 22 January 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 29 January 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 05 February 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 12 February 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 19 February 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 26 February 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 05 March 2018***No defects recorded*

Safety Inspection of A725 & A726 Tannochside V1 on 12 March 2018*No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 19 March 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 26 March 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 29 March 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 05 April 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 09 April 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 16 April 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 23 April 2018**

SW85-340105-235658757	850m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	24/04/2018	Completed Defects	18/05/2018	A725 EB EK EXPRESSWAY 500M PRIOR TO WHIRLIES RBT LANE 1 OS WT
-----------------------	------	----	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Tannochside V1 on 30 April 2018

SW85-342637-235669164	344m	344m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	01/05/2018	Completed Defects	30/04/2018	A725 BURNIEHILL R/A TO BP GARAGE @BUS STOP CENTRE LINE
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	--

Safety Inspection of A725 & A726 Tannochside V1 on 04 May 2018*No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 11 May 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 14 May 2018**

SW85-348580-235802000	641m	641m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	15/05/2018	Completed Defects	14/05/2018	A725 EB 80M PAST PETROL STATION
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	---------------------------------

SW85-348580-235802001	853m	855m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	15/05/2018	Completed Defects	14/05/2018	A725 EB 150M PRIOR O/BRIDGE
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	-----------------------------

SW85-348580-235802002	923m	925m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	15/05/2018	Completed Defects	14/05/2018	A725 EB 100M PRIOR O/BRIDGE
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	-----------------------------

SW85-348580-235802003	1,052m	1,053m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	01/01/9999	Completed Defects	14/05/2018	A725 EB @ O/BRIDGE KINGSWAY
-----------------------	--------	--------	-------------	-----------------------	-------	------------	-------------------	------------	-----------------------------

Safety Inspection of A725 & A726 Tannochside V1 on 21 May 2018*No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 28 May 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 04 June 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 11 June 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 18 June 2018**

SW85-365643-235853364	919m	919m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	19/06/2018	Completed Defects	18/06/2018	A725 WHITEMOSS TO WHIRLIES R/A ABOUT 200M BEFORE FOOTBRIDGE
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	---

SW85-365643-235853365	419m	419m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	19/06/2018	Completed Defects	18/06/2018	A725 WHITEMOSS TO WHIRLIES R/A @ BUS STOP
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Tannochside V1 on 25 June 2018*No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 02 July 2018**

SW85-372668-235871428	995m	995m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	03/07/2018	Completed Defects	02/07/2018	A725 WHITEMOSS TO WHIRLIES
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	----------------------------

SW85-372668-235871429	1,026m	1,026m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	03/07/2018	Completed Defects	02/07/2018	A725 WHITEMOSS TO WHIRLIES R/A
-----------------------	--------	--------	-------------	-----------------------	-------	------------	-------------------	------------	--------------------------------

Safety Inspection of A725 & A726 Tannochside V1 on 09 July 2018*No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 16 July 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 23 July 2018***No defects recorded*

Safety Inspection of A725 & A726 Tannochside V1 on 30 July 2018*No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 06 August 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 13 August 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 20 August 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 27 August 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 03 September 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 10 September 2018**

SW85-405761-236052248	992m	992m	GULLY	Cracked or broken (IBCK)	CAT 1	08/10/2018	Completed Defects	17/09/2018	A725 WHITEMOSS TO WHIRLIES 3 X LAMP POST BEFORE FOOTBRIDGE
-----------------------	------	------	-------	--------------------------	-------	------------	-------------------	------------	--

Safety Inspection of A725 & A726 Tannochside V1 on 17 September 2018*No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 24 September 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 01 October 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 08 October 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 15 October 2018**

SW85-422048-236141660	991m	991m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/10/2018	Awaiting CCMS Permanent	15/10/2018	A725 BTWEEN WHITEMOSS ROUNDABOUT TO WHIRLIES ROUNDABOUT
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------------	------------	---

SW85-422048-236141661	43m	43m	GULLY	Other (OTHR)	CAT 1	16/10/2018	Completed Defects	15/10/2018	A725 BETWEEN WHITEMOSS & WHIRLIES R/ABOUT JUST OFF WHITEMOSS R/ABOUT
-----------------------	-----	-----	-------	--------------	-------	------------	-------------------	------------	--

SW85-422048-236141662	762m	762m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/10/2018	Awaiting CCMS Permanent	15/10/2018	A725 EB BTWN WHITEMOSS RBT & WHIRLIES RBT
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------------	------------	---

Safety Inspection of A725 & A726 Tannochside V1 on 22 October 2018

SW85-425292-236143465	579m	579m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	23/10/2018	Completed Defects	22/10/2018	A725 WHITEMOSS TO WHIRLIES O/S/L O/S/WT
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Tannochside V1 on 29 October 2018*No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 05 November 2018**

SW85-426396-236186632	968m	968m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	06/11/2018	Completed Defects	05/11/2018	A725 BETWEEN WHITEMOSS RBT TO WHIRLIES RBT
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	--

Safety Inspection of A725 & A726 Tannochside V1 on 12 November 2018*No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 19 November 2018**

SW85-426714-236228415	969m	969m	GULLY	Blockage (BLOK)	CAT 1	20/11/2018	Completed Defects	19/11/2018	A725 BETWEEN WHIRLIES & WHITEMOSS RBT 50M BEFORE OVERBRIDGE @ RECENTLY PATCHED POTHOLE SURROUNDING GULLY
-----------------------	------	------	-------	-----------------	-------	------------	-------------------	------------	--

Safety Inspection of A725 & A726 Glasgow East V1 on 26 November 2018*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 03 December 2018***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 10 December 2018***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 17 December 2018**

SW85-427465-236262867	658m	658m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/12/2018	Completed Defects	18/12/2018	A725 NB FROM WHITEMOSS RBT TO WHIRLIES RBT CENTRE OF LANE 1, 50M AFTER FUEL STATION @ 50MPH SIGN
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	--

Safety Inspection of A725 & A726 Glasgow East V1 on 24 December 2018*No defects recorded*

Safety Inspection of A725 & A726 Glasgow East V1 on 31 December 2018*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 07 January 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 14 January 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 21 January 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 28 January 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 04 February 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 11 February 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 18 February 2019**

SW85-431758-236328618	766m	766m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	19/02/2019	Completed Defects	18/02/2019	A725 FROM WHITEMOSS TO WHIRLIES RBT
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	-------------------------------------

Safety Inspection of A725 & A726 Glasgow East V1 on 25 February 2019

SW85-434998-236328625	926m	926m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	26/02/2019	Completed Defects	25/02/2019	A725 FROM WHITEMOSS RBT TO WHIRLIES RBT
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	---

SW85-434998-236328626	932m	932m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	26/02/2019	Completed Defects	25/02/2019	A725 BTWN WHITEMOSS & WHIRLIES RBT
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	------------------------------------

Safety Inspection of A725 & A726 Glasgow East V1 on 04 March 2019

SW85-439166-236336878	418m	418m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/04/2019	Completed Defects	22/03/2019	A725 BETWEEN WHITEMOSS RBT & WHIRLIES RBT, AT END OF BUS STOP
-----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Glasgow East V1 on 11 March 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 18 March 2019**

SW85-450767-236466923	1,003m	1,003m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/04/2019	Completed Defects	06/04/2019	A725 NB BETWEEN WHITEMOSS RBT & WHIRLIES RBT, 50M PRIOR TO FOOTBRIDGE
-----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Glasgow East V1 on 25 March 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 01 April 2019**

SW85-464326-236487668	752m	752m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	02/04/2019	Completed Defects	01/04/2019	A725 EB AT LONDIS EXIT
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	------------------------

Safety Inspection of A725 & A726 Glasgow East V1 on 08 April 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 15 April 2019**

SW85-482556-236569454	375m	375m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/04/2019	Completed Defects	16/04/2019	A725 NB WHITEMOSS RBT TO WHIRLIES RBT, IN CENTRE LINE, 50M PRIOR TO BP GARAGE
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	---

SW85-482556-236569455	656m	656m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/04/2019	Completed Defects	16/04/2019	A725 NB WHITEMOSS RBT TO WHIRLIES RBT, IN CENTRE LINE, 20M AFTER BP GARAGE
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	--

SW85-482556-236569456	813m	813m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/04/2019	Completed Defects	16/04/2019	A725 NB WHITEMOSS RBT TO WHIRLIES RBT, IN CENTRE LINE @ 50MPH SIGN @ 150M PRIOR TO OVERBRIDGE
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	---

SW85-482556-236569457	819m	819m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/04/2019	Completed Defects	16/04/2019	A725 NB WHITEMOSS RBT TO WHIRLIES RBT, IN LANE 2 @ 50MPH SIGN @ 150M PRIOR TO OVERBRIDGE
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	--

SW85-482556-236569458	819m	819m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/04/2019	Completed Defects	16/04/2019	A725 NB WHITEMOSS RBT TO WHIRLIES RBT, IN LANE 2 @ 50MPH SIGN @ 150M PRIOR TO OVERBRIDGE
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	--

SW85-482556-236569459	913m	913m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/04/2019	Completed Defects	16/04/2019	A725 NB WHITEMOSS RBT TO WHIRLIES RBT, IN NSL @ 100M PRIOR TO OVERBRIDGE
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	--

SW85-482556-236569452	57m	57m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/04/2019	Completed Defects	16/04/2019	A725 NB BETWEEN WHITEMOSS & WHIRLIES RBT, 20M AFTER WHITEMOSS
-----------------------	-----	-----	-------------	--------------------------	-------	------------	----------------------	------------	---

Safety Inspection of A725 & A726 Glasgow East V1 on 18 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 26 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 29 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 13 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 20 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 27 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 June 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 June 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 June 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 June 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 01 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 08 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 15 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 22 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 29 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 05 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 12 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 19 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 26 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 09 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 16 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 23 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 30 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 07 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 14 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 21 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 28 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 04 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 11 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 18 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 25 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 09 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 16 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 30 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 06 January 2020

SW85-538200-237222048	694m	694m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 1	03/02/2020	Completed Defects	24/01/2020	A725 WHIRLIES RBT - WHITEMOSS RBT, @ 50MPH SIGN CENTRE RES
SW85-538200-237222049	689m	689m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 1	03/02/2020	Completed Defects	24/01/2020	A725 WHIRLIES RBT - WHITEMOSS RBT, @ 50MPH SIGN
SW85-538200-237222050	768m	768m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 1	03/02/2020	Completed Defects	24/01/2020	A725 WHIRLIES RBT - WHITEMOSS RBT, @ 50MPH SIGN

Safety Inspection of A725 & A726 Glasgow East V1 on 13 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 20 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 27 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 March 2020

No defects recorded

15015/06 : AGAINST: WHIRLIES RBT TO WHITEMOSS RBT (KINGSWAY)

Safety Inspection of A725 & A726 Tannochside V1 on 06 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 28 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 May 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 08 May 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 15 May 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 22 May 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 29 May 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 05 June 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 12 June 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 19 June 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 26 June 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 03 July 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 10 July 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 17 July 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 24 July 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 31 July 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 07 August 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 14 August 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 21 August 2017

SW85-283749-235321434	458m	0m	TREE	Dead tree (DTRE)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A725 NB WHIRLIES RBT - WHITEMOSS RBT
-----------------------	------	----	------	---------------------	-------	------------	--------------------------	------------	---

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 28 August 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 04 September 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 11 September 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 18 September 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 25 September 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 02 October 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 09 October 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 16 October 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 23 October 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 30 October 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 06 November 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 13 November 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 20 November 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 26 November 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 04 December 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 11 December 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 18 December 2017

<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 22 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 29 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 05 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 08 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 15 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 22 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 29 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 05 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 12 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 19 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 26 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 05 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 12 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 19 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 26 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 29 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 05 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 09 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 16 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 23 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 30 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 04 May 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 11 May 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 14 May 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 21 May 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 28 May 2018									
SW85-354701-235705989	1,345m	1,345m	ROAD_MARKINGS _LONG	Wear (for example erosion) (WEAR)	CAT 1	25/06/2018	Completed Defects	16/07/2018	A725 WHITEMOSS R/ABOUT
SW85-354701-235705992	883m	883m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	25/06/2018	Completed Defects	17/06/2018	A725 WHITEMOSS TO WHIRLIES @LONDIS PETROL STATION ENTRY AND EXIT ROADS
Safety Inspection of A725 & A726 Tannochside V1 on 04 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 11 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 18 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 25 June 2018									

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 02 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 09 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 16 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 23 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 30 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 August 2018

SW85-392547-235950818	1,334m	1,334m	KERB	Damaged (DAMG)	CAT 1	10/09/2018	Completed Defects	10/11/2018	M725 @WHITEMOSS R/ABOUT FROM WHIRLIES
-----------------------	--------	--------	------	----------------	-------	------------	-------------------	------------	---------------------------------------

Safety Inspection of A725 & A726 Tannochside V1 on 20 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 August 2018

SW85-399086-235988019	948m	948m	GULLY	Blockage (BLOK)	CAT 1	24/09/2018	Completed Defects	02/10/2018	A725 WHIRLIES R/A TO WHITEMOSS R/A @ BARRHEAD TRAVEL
-----------------------	------	------	-------	-----------------	-------	------------	-------------------	------------	--

Safety Inspection of A725 & A726 Tannochside V1 on 03 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 01 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 08 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 15 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 October 2018

SW85-426018-236179786	1,337m		GULLY	Difference in level with road (IDLV)			Completed Defects	09/11/2018	A725 LANE 1 ON WHITEMOSS RBT FROM WHIRLIES RBT
-----------------------	--------	--	-------	--------------------------------------	--	--	-------------------	------------	--

Safety Inspection of A725 & A726 Tannochside V1 on 05 November 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 November 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 November 2018

SW85-426714-236228414	392m		CARRIAGEWAY	Pothole VIAFIX (POTV)			Completed Defects	19/11/2018	A725 BETWEEN WHITEMOSS RBT & WHIRLIES RBT
-----------------------	------	--	-------------	-----------------------	--	--	-------------------	------------	---

Safety Inspection of A725 & A726 Glasgow East V1 on 26 November 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 December 2018

SW85-427598-236262866	332m		CARRIAGEWAY	Pothole VIAFIX (POTV)			Completed Defects	24/12/2018	A725 EB BETWEEN WHIRLIES RBT & WHITEMOSS RBT 50M BEFORE OVERBRIDGE
-----------------------	------	--	-------------	-----------------------	--	--	-------------------	------------	--

Safety Inspection of A725 & A726 Glasgow East V1 on 31 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 07 January 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 14 January 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 21 January 2019**

SW85-428297-236283778	1,329m	1,329m	CARRIAGEWAY	Pothole (POTH)	CAT 1	18/02/2019	Completed Defects	21/01/2019	A725 @ WHITEMOSS RBT FROM WHIRLIES RBT
-----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A725 & A726 Glasgow East V1 on 28 January 2019

SW85-428544-236286476	396m	396m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/02/2019	Completed Defects	08/02/2019	A725 TO WHIRLIES RBT
-----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	----------------------

SW85-428544-236286477	339m	339m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/02/2019	Completed Defects	08/02/2019	A724 TO WHIRLIES 50M PRIOR TO OVERBRIDGE
-----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A725 & A726 Glasgow East V1 on 04 February 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 11 February 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 18 February 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 25 February 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 04 March 2019**

SW85-439166-236336877	44m	44m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/04/2019	Completed Defects	21/03/2019	A725 BETWEEN WHIRLIES RBT & WHITEMOSS RBT, PRIOR TO BUS STOP, 15M AFTER WHIRLIES RBT
-----------------------	-----	-----	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A725 & A726 Glasgow East V1 on 11 March 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 18 March 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 25 March 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 01 April 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 08 April 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 15 April 2019**

SW85-482556-236569453	224m	224m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/04/2019	Completed Defects	16/04/2019	A725 NB WHITEMOSS RBT TO WHIRLIES RBT, IN CENTRE LINE, 20M PRIOR TO OVERBRIDGE
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	--

Safety Inspection of A725 & A726 Glasgow East V1 on 18 April 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 26 April 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 29 April 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 03 May 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 10 May 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 13 May 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 20 May 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 27 May 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 03 June 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 10 June 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 17 June 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 24 June 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 01 July 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 08 July 2019**

<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 15 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 22 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 29 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 05 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 12 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 19 August 2019									
SW85-532712-236963102	400m	400m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 1	16/09/2019	Completed Defects	20/08/2019	A725 WB BETWEEN WHIRLIES RBT - WHITEMOSS RBT
Safety Inspection of A725 & A726 Glasgow East V1 on 26 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 02 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 09 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 16 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 23 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 30 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 07 October 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 14 October 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 21 October 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 28 October 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 04 November 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 11 November 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 18 November 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 25 November 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 02 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 09 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 16 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 30 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 06 January 2020									
SW85-538200-237222047	1,248m	1,248m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 1	03/02/2020	Completed Defects	22/01/2020	A725, BTWN WHIRLIES RBT- WHITEMOSS RBT. START OF CYCLE TRACK PRIOR TO W/MOSS RBT
Safety Inspection of A725 & A726 Glasgow East V1 on 13 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 20 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 27 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 03 February 2020									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 10 February 2020									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 17 February 2020									
<i>No defects recorded</i>									

Safety Inspection of A725 & A726 Glasgow East V1 on 24 February 2020

SW85-544128-237284469	14m	14m	GULLY	Difference in level with road (IDLV)	CAT 1	23/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 NB BETWEEN WHIRLIES RBT-WHITEMOSS RBT
-----------------------	-----	-----	-------	--------------------------------------	-------	------------	-------------------------	------------	--

Safety Inspection of A725 & A726 Glasgow East V1 on 02 March 2020

No defects recorded

15020/05 : WITH: THE WHIRLIES RBT TO WHIRLIES BYPASS**Safety Inspection of A725 & A726 Tannochside V1 on 06 February 2017**

SW77242809-235034692	487m	487m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/03/2017	Completed Defects	28/02/2017	A725 SB CROSSBASKETS - KINGSWAY,
----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	----------------------------------

Safety Inspection of A725 & A726 Tannochside V1 on 13 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 April 2017

SW85-260143-235074803	53m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	FRETTING
-----------------------	-----	----	-------------	--------------------------------------	-------	------------	-----------------------	------------	----------

Safety Inspection of A725 & A726 Tannochside V1 on 17 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 28 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 08 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 15 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 May 2017

SW85-275782-235160628	458m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/06/2017	Completed Defects	24/06/2017	A725 SB 10M PRIOR TO OVERBRIDGE AT WHIRLIES BYPASS
-----------------------	------	----	-------------	----------------	-------	------------	-------------------	------------	--

SW85-275782-235160629	473m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/06/2017	Completed Defects	24/06/2017	A725 SB PRIOR TO OVERBRIDGE AT WHIRLIES BYPASS
-----------------------	------	----	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A725 & A726 Tannochside V1 on 29 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 26 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 July 2017

SW85-282503-235265798	310m	0m	TRAFFIC_SIGNS	Physical	CAT 1	14/08/2017	Awaiting CCMS	01/01/9999	A725 EB WHIRLIES AT HSS
-----------------------	------	----	---------------	----------	-------	------------	---------------	------------	-------------------------

				condition of post (COPT)		Temp Date		HIRE	
Safety Inspection of A725 & A726 Tannochside V1 on 24 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 31 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 07 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 14 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 21 August 2017									
SW85-283749-235321435	994m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	18/09/2017	Completed Defects	11/09/2017	A725 EB WHIRLIES BYPASS
Safety Inspection of A725 & A726 Tannochside V1 on 28 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 04 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 11 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 18 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 25 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 02 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 09 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 16 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 23 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 30 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 06 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 13 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 20 November 2017									
SW85-316344-235473149	254m	254m	CARRIAGEWAY	Pothole (POTH)	CAT 1	18/12/2017	Completed Defects	01/12/2017	A725 NB AT T/LIGHTS WHIRLIES BY PASS
SW85-316344-235473150	252m	252m	CARRIAGEWAY	Pothole (POTH)	CAT 1	18/12/2017	Completed Defects	01/12/2017	A725 NB AT T/LIGHTS WHIRLIES BY PASS
Safety Inspection of A725 & A726 Tannochside V1 on 26 November 2017									
SW85-316447-235476809	0m	1m	TRAFFIC_SIGNS	Accident damage (ACCD)	CAT 1	25/12/2017	Completed Defects	28/12/2017	A725 EXIT FROM WHIRLIES RBT
Safety Inspection of A725 & A726 Tannochside V1 on 04 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 11 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 18 December 2017									
SW85-316977-235495391	478m	478m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/01/2018	Completed Defects	10/01/2018	A725 @ A749 TO KINGWAY R/A N/S/L BEFORE FRANKIE AND BENNYS
Safety Inspection of A725 & A726 Tannochside V1 on 22 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 29 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 05 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 08 January 2018									
SW85-317422-235515697	254m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/02/2018	Completed Defects	07/02/2018	A725 EB WHIRLIES BYPASS AT PED CROSSING LANE 2 OS WT

Safety Inspection of A725 & A726 Tannochside V1 on 15 January 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 January 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 January 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 February 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 February 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 February 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 26 February 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 March 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 March 2018

SW85-327259-235553270	607m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	13/03/2018	Completed Defects	12/03/2018	A725 EB WHIRLIES BYPASS
-----------------------	------	----	-------------	-----------------------	-------	------------	-------------------	------------	-------------------------

Safety Inspection of A725 & A726 Tannochside V1 on 19 March 2018

SW85-329250-235581725	283m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	20/03/2018	Completed Defects	19/03/2018	A725 EB WHIRLIES BYPASS AT HSS HIRE
-----------------------	------	----	-------------	-----------------------	-------	------------	-------------------	------------	-------------------------------------

Safety Inspection of A725 & A726 Tannochside V1 on 26 March 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 March 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 April 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 09 April 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 16 April 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 23 April 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 30 April 2018

SW85-342637-235669160	899m	899m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	01/05/2018	Completed Defects	30/04/2018	A 725 KINGATES R/A TO WHIRLIES BYPASS N/S/L
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Tannochside V1 on 04 May 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 11 May 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 14 May 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 21 May 2018

SW85-351720-235705988	484m	484m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	22/05/2018	Completed Defects	21/05/2018	A725 TO KINGWAY R/A @BEND
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	---------------------------

Safety Inspection of A725 & A726 Tannochside V1 on 28 May 2018

SW85-354701-235705986	78m	78m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	29/05/2018	Completed Defects	28/05/2018	A725 WHIRLIES TO WHIRLIES BYPASS @ BUS STOP
-----------------------	-----	-----	-------------	-----------------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Tannochside V1 on 04 June 2018

SW85-358160-235819044	184m	184m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	05/06/2018	Completed Defects	04/06/2018	A725 WHIRLIES R/A TO BYPASS
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	-----------------------------

Safety Inspection of A725 & A726 Tannochside V1 on 11 June 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 18 June 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 25 June 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 02 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 09 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 16 July 2018

SW85-379248-235909993	663m	663m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	17/07/2018	Completed Defects	16/07/2018	A725 WHIRLIES R/A TO WHIRLIES BYPASS
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	--------------------------------------

Safety Inspection of A725 & A726 Tannochside V1 on 23 July 2018

SW85-382484-235917042	690m	690m	TREE	Overhanging/o vergrown (OVER)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A725
-----------------------	------	------	------	-------------------------------	-------	------------	-----------------------	------------	------

Safety Inspection of A725 & A726 Tannochside V1 on 30 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 September 2018

SW85-402507-235991313	70m	70m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/09/2018	Completed Defects	03/09/2018	A725 WHIRLIES R/A TO HIRLIES BYPASS
-----------------------	-----	-----	-------------	-----------------------	-------	------------	-------------------	------------	-------------------------------------

SW85-402507-235991314	63m	63m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/09/2018	Completed Defects	03/09/2018	A725 WHIRLIES R/A TO WHIRLIES BYPASS
-----------------------	-----	-----	-------------	-----------------------	-------	------------	-------------------	------------	--------------------------------------

Safety Inspection of A725 & A726 Tannochside V1 on 10 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 01 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 08 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 15 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 October 2018

SW85-425292-236143466	85m	85m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	23/10/2018	Completed Defects	22/10/2018	A725 WHIRLIES RBT TO WHIRLIES BYPASS
-----------------------	-----	-----	-------------	-----------------------	-------	------------	-------------------	------------	--------------------------------------

Safety Inspection of A725 & A726 Tannochside V1 on 29 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 November 2018

SW85-426396-236186633	88m	88m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	06/11/2018	Completed Defects	05/11/2018	A725 WHIRLIES RBT TO WHIRLIES BYPASS
-----------------------	-----	-----	-------------	-----------------------	-------	------------	-------------------	------------	--------------------------------------

Safety Inspection of A725 & A726 Tannochside V1 on 12 November 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 November 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 26 November 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 31 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 07 January 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 14 January 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 21 January 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 28 January 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 04 February 2019**

SW85-429263-236292015	730m	730m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	05/02/2019	Completed Defects	04/02/2019	A725 ONSLIP FROM WHIRLIES RBT
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	-------------------------------

Safety Inspection of A725 & A726 Glasgow East V1 on 11 February 2019

SW85-429789-236315516	257m	257m	CARRIAGEWAY	Pothole (POTH)	CAT 1	11/03/2019	Completed Defects	05/03/2019	A725 WHIRLIES RBT TO WHIRLIES BYPASS @ PED CROSSING
-----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Glasgow East V1 on 18 February 2019

SW85-431758-236328619	637m	637m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	19/02/2019	Completed Defects	18/02/2019	A725 ONSLIP FROM WHIRLIES RBT TO WHIRLIES BYPASS CENTRE OF LANE
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Glasgow East V1 on 25 February 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 04 March 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 11 March 2019**

SW85-444815-236365170	487m	487m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	12/03/2019	Completed Defects	11/03/2019	A725 SB TO RBT @ MCDONALDS
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	----------------------------

Safety Inspection of A725 & A726 Glasgow East V1 on 18 March 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 25 March 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 01 April 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 08 April 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 15 April 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 18 April 2019**

SW85-487286-236569452	370m	370m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	19/04/2019	Completed Defects	19/04/2019	A725 EB FRM WHIRLIES RBT TO EXPRESSWAY
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	--

SW85-487286-236569453	437m	437m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	19/04/2019	Completed Defects	19/04/2019	A725 BTWN WHIRLIES RBT TO BYPASS
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	----------------------------------

SW85-487286-236569454	719m	719m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	19/04/2019	Completed Defects	19/04/2019	A725 BTWN WHIRLIES RBT > BYPASS
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	---------------------------------

SW85-487286-236569455	1,002m	1,002m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	19/04/2019	Completed Defects	19/04/2019	A725 BTWN WHIRLIES RBT & BYPASS
-----------------------	--------	--------	-------------	-----------------------	-------	------------	-------------------	------------	---------------------------------

Safety Inspection of A725 & A726 Glasgow East V1 on 26 April 2019

SW85-496955-236588320	397m	397m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 1	24/05/2019	Awaiting CCMS Permanent	01/01/9999	A725 WHIRLIES BYPASS WB @ JOINING FROM WHIRLIES RBT
-----------------------	------	------	--------------------	-----------------------------------	-------	------------	-------------------------	------------	---

Safety Inspection of A725 & A726 Glasgow East V1 on 29 April 2019

SW85-500796-236613308	180m	180m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	30/04/2019	Completed Defects	30/04/2019	A725 NB BETWEEN WHIRLIES RBT & PED XING
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Glasgow East V1 on 03 May 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 10 May 2019**

SW85-506485-236633008	6m	6m	GULLY	Blockage (BLOK)	CAT 1	07/06/2019	Completed Defects	21/05/2019	A725 WHIRLIES RBT
-----------------------	----	----	-------	-----------------	-------	------------	-------------------	------------	-------------------

Safety Inspection of A725 & A726 Glasgow East V1 on 13 May 2019

SW85-507967-236671094	171m	171m	GULLY	Difference in level with road (IDLV)	CAT 1	10/06/2019	Completed Defects	21/05/2019	A725 NB WHIRLIES RBT TO WHIRLIES BYPASS
-----------------------	------	------	-------	--------------------------------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Glasgow East V1 on 20 May 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 27 May 2019***No defects recorded*

Safety Inspection of A725 & A726 Glasgow East V1 on 03 June 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 10 June 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 17 June 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 24 June 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 01 July 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 08 July 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 15 July 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 22 July 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 29 July 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 05 August 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 12 August 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 19 August 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 26 August 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 02 September 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 09 September 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 16 September 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 23 September 2019**

SW85-534451-237024633	473m	473m	GULLY	Missing (MISS)	CAT 1	21/10/2019	Completed Defects	22/11/2019	A725 BETWEEN OFF TO WHIRLIES - KINGSWAY RBT
-----------------------	------	------	-------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Glasgow East V1 on 30 September 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 07 October 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 14 October 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 21 October 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 28 October 2019**

SW85-535935-237064517	528m	528m	STRUCTURE	Graffiti - Offensive (OFFS)	CAT 1	25/11/2019	Completed Defects	18/01/2020	A725 EB WHIRLIES RBT TO WHIRLIES BYPASS
-----------------------	------	------	-----------	-----------------------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Glasgow East V1 on 04 November 2019

SW85-536320-237072767	75m	75m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	05/11/2019	Awaiting CCMS Permanent	01/01/9999	A725 WHIRLIES RBT TO BYPASS@ BUS STOP
-----------------------	-----	-----	-------------	-----------------------	-------	------------	-------------------------	------------	---------------------------------------

SW85-536320-237072769	0m	0m	GULLY	Blockage (BLOK)	CAT 1	02/12/2019	Completed Defects	09/11/2019	A725 WHIRLIES RBT EXIT FOR WHIRLIES BYPASS
-----------------------	----	----	-------	-----------------	-------	------------	-------------------	------------	--

Safety Inspection of A725 & A726 Glasgow East V1 on 11 November 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 18 November 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 25 November 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 02 December 2019**

SW85-537189-237183951	489m	489m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	03/12/2019	Completed Defects	02/12/2019	A725 TO WHIRLIES BYPASS
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	-------------------------

Safety Inspection of A725 & A726 Glasgow East V1 on 09 December 2019*No defects recorded*

Safety Inspection of A725 & A726 Glasgow East V1 on 16 December 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 30 December 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 06 January 2020***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 13 January 2020***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 20 January 2020***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 27 January 2020***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 03 February 2020***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 10 February 2020***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 17 February 2020**

SW85-541139-237284286	383m	383m	CARRIAGEWAY	Pothole (POTH)	CAT 1	16/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 NB WHIRLIES RBT - WHIRLIES BYPASS
SW85-541139-237284287	554m	554m	CARRIAGEWAY	Pothole (POTH)	CAT 1	16/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 NB WHIRLIES RBT - WHIRLIES BYPASS
SW85-541139-237284288	691m	691m	CARRIAGEWAY	Pothole (POTH)	CAT 1	16/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 NB WHIRLIES RBT - WHIRLIES BYPASS
SW85-541139-237284289	1,002m	1,002m	CARRIAGEWAY	Pothole (POTH)	CAT 1	16/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 NB WHIRLIES RBT - WHIRLIES BYPASS
SW85-541139-237284290	1,003m	1,003m	CARRIAGEWAY	Pothole (POTH)	CAT 1	16/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 NB WHIRLIES RBT - WHIRLIES BYPASS

Safety Inspection of A725 & A726 Glasgow East V1 on 24 February 2020*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 02 March 2020**

SW85-547129-237302607	486m	486m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	03/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 SB BETWEEN SLIP TO WHIRLIES & MAVOUR RBT
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------------	------------	---

15020/08 : AGAINST: WHIRLIES BP TO SLIP TO CALDERWOOD RD**Safety Inspection of A725 & A726 Tannochside V1 on 06 February 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 13 February 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 20 February 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 27 February 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 06 March 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 13 March 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 20 March 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 27 March 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 03 April 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 10 April 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 17 April 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 24 April 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 28 April 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 05 May 2017***No defects recorded*

Safety Inspection of A725 & A726 Tannochside V1 on 30 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 01 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 08 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 15 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 November 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 November 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 November 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 26 November 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 31 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 07 January 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 14 January 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 21 January 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 28 January 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 04 February 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 11 February 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 18 February 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 25 February 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 04 March 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 11 March 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 18 March 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 25 March 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 01 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 08 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 15 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 18 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 26 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 29 April 2019

SW85-500796-236613307	441m	441m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	30/04/2019	Completed Defects	30/04/2019	A725 NB BETWEEN WHIRLIES RBT & PED XING
-----------------------	------	------	-------------	--------------------------	-------	------------	----------------------	------------	--

Safety Inspection of A725 & A726 Glasgow East V1 on 03 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 13 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 20 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 27 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 June 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 June 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 June 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 June 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 01 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 08 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 15 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 22 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 29 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 05 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 12 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 19 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 26 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 09 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 16 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 23 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 30 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 07 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 14 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 21 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 28 October 2019

SW85-535935-237064518	152m	152m	GULLY	Blockage (BLOK)	CAT 1	25/11/2019	Completed Defects	09/11/2019	A725 WHIRLIES BYPASS - RBT
SW85-535935-237064519	139m	139m	GULLY	Blockage (BLOK)	CAT 1	25/11/2019	Completed Defects	09/11/2019	A725 WHIRLIES BYPASS-RBT
SW85-535935-237064520	127m	127m	GULLY	Blockage (BLOK)	CAT 1	25/11/2019	Completed Defects	09/11/2019	A725 WHIRLIES BYPASS - RBT

Safety Inspection of A725 & A726 Glasgow East V1 on 04 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 11 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 18 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 25 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 09 December 2019

SW85-537396-237210705	20m	20m	GULLY	Blockage (BLOK)	CAT 1	06/01/2020	Completed Defects	23/12/2019	A725 CROSBASKET TO WHIRLIES
SW85-537396-237210706	44m	44m	GULLY	Blockage (BLOK)	CAT 1	06/01/2020	Completed Defects	23/12/2019	A725 W/B CROSSBASKET TO WHIRLIES
SW85-537396-237210707	65m	65m	GULLY	Blockage (BLOK)	CAT 1	06/01/2020	Completed Defects	23/12/2019	A725 W/B CROSSBASKET TO WHIRLIES
SW85-537396-237210708	91m	91m	GULLY	Blockage (BLOK)	CAT 1	06/01/2020	Completed Defects	23/12/2019	A725 W/B CROSSBASKET TO WHIRLIES
SW85-537396-237210709	113m	113m	GULLY	Blockage (BLOK)	CAT 1	06/01/2020	Completed Defects	23/12/2019	A725 W/B CROSSBASKET TO WHIRLIES

Safety Inspection of A725 & A726 Glasgow East V1 on 16 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 30 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 06 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 13 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 20 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 27 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 March 2020

No defects recorded

15025/05 : WITH: WHIRLIES BYPASS TO HAMILTON ROAD OFF SLIP

Safety Inspection of A725 & A726 Tannochside V1 on 06 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 28 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 08 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 15 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 26 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 July 2017

SW85-281916-235256356	1,350m	0m	FENCES_AND_BARRIERS	Accident damage (ACCD)	CAT 1	31/07/2017	Completed Defects	05/08/2017	A725 SB 100M TO START OF SLIP TO CROSSBASKETS BLANTYRE
-----------------------	--------	----	---------------------	------------------------	-------	------------	-------------------	------------	--

Safety Inspection of A725 & A726 Tannochside V1 on 10 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 31 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 07 August 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 14 August 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 21 August 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 28 August 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 04 September 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 11 September 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 18 September 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 25 September 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 02 October 2017

<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Tannochside V1 on 09 October 2017										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Tannochside V1 on 16 October 2017										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Tannochside V1 on 23 October 2017										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Tannochside V1 on 30 October 2017										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Tannochside V1 on 06 November 2017										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Tannochside V1 on 13 November 2017										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Tannochside V1 on 20 November 2017										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Tannochside V1 on 26 November 2017										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Tannochside V1 on 04 December 2017										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Tannochside V1 on 11 December 2017										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Tannochside V1 on 18 December 2017										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Tannochside V1 on 22 December 2017										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Tannochside V1 on 29 December 2017										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Tannochside V1 on 05 January 2018										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Tannochside V1 on 08 January 2018										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Tannochside V1 on 15 January 2018										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Tannochside V1 on 22 January 2018										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Tannochside V1 on 29 January 2018										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Tannochside V1 on 05 February 2018										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Tannochside V1 on 12 February 2018										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Tannochside V1 on 19 February 2018										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Tannochside V1 on 26 February 2018										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Tannochside V1 on 05 March 2018										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Tannochside V1 on 12 March 2018										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Tannochside V1 on 19 March 2018										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Tannochside V1 on 26 March 2018										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Tannochside V1 on 29 March 2018										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Tannochside V1 on 05 April 2018										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Tannochside V1 on 09 April 2018										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Tannochside V1 on 16 April 2018										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Tannochside V1 on 23 April 2018										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Tannochside V1 on 30 April 2018										
SW85-342637-235669161	157m	157m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	01/05/2018	Completed Defects	30/04/2018	A725 WHIRLIES BYPASS TO HAMILTON OFF SLIP @ BUS STOP CENTRE LINE	

Safety Inspection of A725 & A726 Tannochside V1 on 04 May 2018*No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 11 May 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 14 May 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 21 May 2018**

SW85-351720-235705989	34m	1m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	22/05/2018	Completed Defects	21/05/2018	A725 W/B WHIRKIES BYPASS TO HAMILTON OFFSLIP
-----------------------	-----	----	-------------	-----------------------	-------	------------	-------------------	------------	--

SW85-351720-235705990	47m	47m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	22/05/2018	Completed Defects	21/05/2018	A725 W/B WHIRLIES BYPASS TO HAMILTON OFFSLIP @ ROAD SIGN
-----------------------	-----	-----	-------------	-----------------------	-------	------------	-------------------	------------	--

Safety Inspection of A725 & A726 Tannochside V1 on 28 May 2018*No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 04 June 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 11 June 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 18 June 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 25 June 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 02 July 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 09 July 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 23 July 2018**

SW85-382484-235917040	194m	194m	TREE	Overhanging/o vergrown (OVER)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A725
-----------------------	------	------	------	-------------------------------	-------	------------	-----------------------	------------	------

SW85-382484-235917044	1,281m	1,281m	TREE	Overhanging/o vergrown (OVER)	CAT 1	24/07/2018	Awaiting CCMS Permanent	23/07/2018	A725 WHIRLIES BYPASS TO CROSSBASKETS
-----------------------	--------	--------	------	-------------------------------	-------	------------	-------------------------	------------	--------------------------------------

Safety Inspection of A725 & A726 Tannochside V1 on 30 July 2018*No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 06 August 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 13 August 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 20 August 2018**

SW85-395871-235961110	750m	750m	GULLY	Other (OTHR)	CAT 1	21/08/2018	Completed Defects	20/08/2018	A725 NB AT CROSSBASKETS
-----------------------	------	------	-------	--------------	-------	------------	-------------------	------------	-------------------------

Safety Inspection of A725 & A726 Tannochside V1 on 27 August 2018

SW85-399086-235988026	1,050m	1,050m	FENCES_AND_BARRIERS	Accident damage (ACCD)	CAT 1	24/09/2018	Completed Defects	21/09/2018	A725 CROSSBASKETS TO WHIRLIES ON CENTRE VERGE
-----------------------	--------	--------	---------------------	------------------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Tannochside V1 on 03 September 2018*No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 10 September 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 17 September 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 24 September 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 01 October 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 08 October 2018**

SW85-418817-236111663	470m	470m	GULLY	Blockage (BLOK)	CAT 1	05/11/2018	Completed Defects	07/12/2018	A725 BETWEEN WHIRLIES BYPASS & CROSSBASKETS W/B
-----------------------	------	------	-------	-----------------	-------	------------	-------------------	------------	---

SW85-418817-236111666	313m	313m	GULLY	Blockage (BLOK)	CAT 1	05/11/2018	Completed Defects	07/12/2018	A725 BETWEEN CROSSBASKET & WHIRLIES BYPASS 15M AFTER "CALDERGLEN COUNTRY PARK" SIGN
-----------------------	------	------	-------	-----------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Tannochside V1 on 15 October 2018*No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 22 October 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 29 October 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 05 November 2018**

SW85-426396-236186634	211m	211m	GULLY	Blockage (BLOK)	CAT 1	06/11/2018	Completed Defects	06/11/2018	A725 WHIRLIES BYPASS TO CROSSBASKETS
SW85-426396-236186635	280m	280m	GULLY	Blockage (BLOK)	CAT 1	06/11/2018	Completed Defects	06/11/2018	A725 WHIRLIES BYPASS TO CROSSBASKETS
SW85-426396-236186636	303m	303m	GULLY	Blockage (BLOK)	CAT 1	06/11/2018	Completed Defects	06/11/2018	A725 WHIRLIES BYPASS TO CROSSBASKETS

Safety Inspection of A725 & A726 Tannochside V1 on 12 November 2018*No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 19 November 2018***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 26 November 2018***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 03 December 2018***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 10 December 2018**

SW85-427281-236262806	500m	700m	GULLY	Silted (SILT)	CAT 1	07/01/2019	Completed Defects	11/01/2019	
-----------------------	------	------	-------	---------------	-------	------------	-------------------	------------	--

Safety Inspection of A725 & A726 Glasgow East V1 on 17 December 2018*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 24 December 2018***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 31 December 2018***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 07 January 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 14 January 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 21 January 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 28 January 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 04 February 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 11 February 2019**

SW85-429789-236315517	1,019m	1,019m	CARRIAGEWAY	Pothole (POTH)	CAT 1	11/03/2019	Completed Defects	05/03/2019	A725 FROM WHIRLIES BYPASS TO HIGH BLANTYRE OFFSLIP @ ICE WARNING SIGN
SW85-429789-236315518	1,051m	1,051m	CARRIAGEWAY	Pothole (POTH)	CAT 1	11/03/2019	Completed Defects	05/03/2019	A725 FROM WHIRLIES BYPASS TO HIGH BLANTYRE OFFSLIP @ WEATHER STATION
SW85-429789-236315519	1,090m	1,090m	CARRIAGEWAY	Pothole (POTH)	CAT 1	11/03/2019	Completed Defects	05/03/2019	A725 FROM WHIRLIES BYPASS TO HIGH BLANTYRE OFFSLIP @ 60MPH SIGN

Safety Inspection of A725 & A726 Glasgow East V1 on 18 February 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 25 February 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 04 March 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 11 March 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 18 March 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 25 March 2019***No defects recorded*

Safety Inspection of A725 & A726 Glasgow East V1 on 01 April 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 08 April 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 15 April 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 18 April 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 26 April 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 29 April 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 03 May 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 10 May 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 13 May 2019**

SW85-507967-236671090	857m	857m	GULLY	Blockage (BLOK)	CAT 1	10/06/2019	Completed Defects	22/05/2019	A725 SB WHIRLIES BYPASS TO WHIRLIES RBT
SW85-507967-236671091	837m	837m	GULLY	Blockage (BLOK)	CAT 1	10/06/2019	Completed Defects	22/05/2019	A725 SB FROM BLANTYRE TO WHIRLIES RBT
SW85-507967-236671092	740m	740m	GULLY	Blockage (BLOK)	CAT 1	10/06/2019	Completed Defects	22/05/2019	A725 SB BTWN BLANTYRE & WHIRLIES RBT
SW85-507967-236671093	646m	646m	GULLY	Blockage (BLOK)	CAT 1	10/06/2019	Completed Defects	22/05/2019	A725 SB BETWEEN BLANTYRE & WHIRLIES

Safety Inspection of A725 & A726 Glasgow East V1 on 20 May 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 27 May 2019**

SW85-513744-236806861	609m	609m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	28/05/2019	Completed Defects	27/05/2019	A725 EB PRIOR TO HAMILTON RD OFFSLIP @ OSL NSWT
SW85-518356-236809580	177m	177m	GULLY	Blockage (BLOK)	CAT 1	01/07/2019	Completed Defects	11/06/2019	A725 SB TO WHIRLIES RBT @ BUSSTOP NUMBER 6150768

Safety Inspection of A725 & A726 Glasgow East V1 on 10 June 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 17 June 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 24 June 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 01 July 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 08 July 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 15 July 2019**

SW85-531171-236909039	4m	107m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 1	12/08/2019	Awaiting CCMS Permanent	01/01/9999	A725 NB FROM WHIRLIES RBT TO WHIRLIES BYPASS
-----------------------	----	------	--------------------	-----------------------------------	-------	------------	-------------------------	------------	--

Safety Inspection of A725 & A726 Glasgow East V1 on 22 July 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 29 July 2019**

SW85-531693-236919958	1,026m	1,026m	FENCES_AND_BARRIERS	Accident damage (ACCD)	CAT 1	26/08/2019	Completed Defects	02/08/2019	A725 NB FROM WHIRLIES TO BLANTYRE OFFSLIP, OPPOSITE ICE SIGN IN CENTRAL RESERVATION
SW85-531693-236919959	1,175m	1,175m	TRAFFIC_SIGNS	Graffiti - Offensive (OFFS)	CAT 1	26/08/2019	Completed Defects	15/08/2019	A725 EB BETWEEN WHIRLIES AND BLANTYRE OFFSLIP, 10M AFTER LAYBY ON SIGN

Safety Inspection of A725 & A726 Glasgow East V1 on 05 August 2019

SW85-532050-236921281	32m	32m	GULLY	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	22/08/2019	A725 CROSSBKET TO WHIRLIES PASSTHE BUS STOP
-----------------------	-----	-----	-------	-----------------	-------	------------	-----------------------	------------	---

Safety Inspection of A725 & A726 Glasgow East V1 on 12 August 2019

SW85-532342-236938475	94m	94m	GULLY	Cracked or broken (IBCK)	CAT 1	09/09/2019	Completed Defects	03/10/2019	A725 NB AFTER BYPASS
SW85-532342-236938476	165m	165m	GULLY	Cracked or broken (IBCK)	CAT 1	09/09/2019	Completed Defects	02/10/2019	A725 AT BUS STOP 6150769
SW85-532342-236938474	79m	79m	GULLY	Cracked or broken (IBCK)	CAT 1	09/09/2019	Completed Defects	03/10/2019	A725 NB AFTER WHIRLIES BYPASS

Safety Inspection of A725 & A726 Glasgow East V1 on 19 August 2019

SW85-532712-236963103	626m	626m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/09/2019	Completed Defects	20/08/2019	A725 BETWEEN WHIRLIES TO HAMILTON RD OFFSLIP
SW85-532712-236963104	140m	140m	GULLY	Blockage (BLOK)	CAT 1	16/09/2019	Completed Defects	02/10/2019	A725 EB BETWEEN WHIRLIES ON TO BUSTOP
SW85-532712-236963105	166m	166m	GULLY	Cracked or broken (IBCK)	CAT 1	16/09/2019	Completed Defects	02/10/2019	A725 WB WHIRLIES BYPASS TO WHIRLIES RBT @ BUS STOP

Safety Inspection of A725 & A726 Glasgow East V1 on 26 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 September 2019

SW85-533358-237005017	173m	173m	GULLY	Cracked or broken (IBCK)	CAT 1	30/09/2019	Completed Defects	28/11/2019	A725 CRAIGHEAD ON SLIP
-----------------------	------	------	-------	--------------------------	-------	------------	-------------------	------------	------------------------

Safety Inspection of A725 & A726 Glasgow East V1 on 09 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 16 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 23 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 30 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 07 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 14 October 2019

SW85-535241-237054113	301m	30m	GULLY	Blockage (BLOK)	CAT 1	11/11/2019	Completed Defects	08/11/2019	A725 WB WHIRLIES BYPASS 50M PRIOR TO BUS STOP
-----------------------	------	-----	-------	-----------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Glasgow East V1 on 21 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 28 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 04 November 2019

SW85-536320-237072770	1,024m	1,042m	FENCES_AND_BARRIERS	Accident damage (ACCD)	CAT 1	04/12/2019	Completed Defects	23/11/2019	A725 EB WHIRLIES BYPASS TO HAMILTON RD OFF @ ICE WARNING SIGN
-----------------------	--------	--------	---------------------	------------------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Glasgow East V1 on 11 November 2019

SW85-536545-237152184	197m	197m	CARRIAGEWAY	Excessive muck (MUCK)	CAT 1	12/11/2019	Completed Defects	12/11/2019	A725 EB WHIRLIES BYPASS TO HAMILTON RD OFFSLIP
SW85-536545-237152185	881m	881m	GULLY	Difference in level with road (IDLV)	CAT 1	09/12/2019	Completed Defects	26/11/2019	A725 EB WHIRLIES BYPASS TO HAMILTON RD OFF - LAST NS GULLY BEFORE BEND
SW85-536545-237152186	782m	782m	GULLY	Difference in level with road (IDLV)	CAT 1	09/12/2019	Completed Defects	26/11/2019	A725 EB WHIRLIES BYPASS TO HAMILTON RD OFF
SW85-536545-237152187	480m	480m	GULLY	Difference in level with road (IDLV)	CAT 1	09/12/2019	Completed Defects	26/11/2019	A725 EB WHIRLIES BYPASS TO HAMILTON RD OFF
SW85-536545-237152188	279m	279m	GULLY	Blockage (BLOK)	CAT 1	09/12/2019	Completed Defects	26/11/2019	A725 EB WHIRLIES BYPASS TO HAMILTON RD OFF

Safety Inspection of A725 & A726 Glasgow East V1 on 18 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 25 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 December 2019

No defects recorded
Safety Inspection of A725 & A726 Glasgow East V1 on 09 December 2019
SW85-537396-237210699 348m 348m GULLY Blockage (BLOK) CAT 1 06/01/2020 Completed Defects 23/12/2019 A725 W/B CROSSBASKET TO WHIRLIES BYPASS

Safety Inspection of A725 & A726 Glasgow East V1 on 16 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 30 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 06 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 13 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 20 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 27 January 2020

SW85-538825-237248072 1,067m 1,067m CARRIAGEWAY Pothole (POTH) CAT 1 24/02/2020 Completed Defects 12/02/2020 A725 NB BETWEEN WHIRLIES RBT ON - CROSSBASKETS

SW85-538825-237248073 1,328m 1,328m CARRIAGEWAY Pothole (POTH) CAT 1 24/02/2020 Completed Defects 12/02/2020 A725 NB BETWEEN WHIRLIES RBT ON - CROSSBASKETS

SW85-538825-237248074 1,383m 1,383m CARRIAGEWAY Pothole (POTH) CAT 1 24/02/2020 Completed Defects 12/02/2020 A725 NB BETWEEN WHIRLIES RBT ON - CROSSBASKETS

Safety Inspection of A725 & A726 Glasgow East V1 on 03 February 2020

SW85-539154-237252890 1,465m 1,465m GULLY Difference in level with road (IDLV) CAT 1 02/03/2020 Awaiting CCMS Permanent 01/01/9999 A725 NB CROSSBASKETS OFFSLIP

SW85-539154-237252891 1,482m 1,482m GULLY Blockage (BLOK) CAT 1 02/03/2020 Awaiting CCMS Permanent 01/01/9999 A725 NB CROSSBASKETS OFF

Safety Inspection of A725 & A726 Glasgow East V1 on 10 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 March 2020

No defects recorded

15025/06 : AGAINST: CROSSBASKET TO WHIRLES BYPASS

Safety Inspection of A725 & A726 Tannochside V1 on 06 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 28 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 08 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 15 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 26 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 July 2017

SW85-282503-235265804	1,163m	0m	TRAFFIC_SIGNS	Obscured sign (OBSG)	CAT 1	18/07/2017	Completed Defects	17/07/2017	A725 WB AT CALDERWOOD TO WHIRLIES
-----------------------	--------	----	---------------	-------------------------	-------	------------	----------------------	------------	--------------------------------------

Safety Inspection of A725 & A726 Tannochside V1 on 24 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 31 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 07 August 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 14 August 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 21 August 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 28 August 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 04 September 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 11 September 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 18 September 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 25 September 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 02 October 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 09 October 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 16 October 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 23 October 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 30 October 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 November 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 November 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 November 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 26 November 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 04 December 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 11 December 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 18 December 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 December 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 December 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 January 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 08 January 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 15 January 2018

SW85-317600-235518227	1,667m	1,667m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/02/2018	Completed Defects	31/01/2018	A725 WB WHIRLIES BYPASS TO A749 RBT
-----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	-------------------------------------

SW85-317600-235518228	1,631m	1,631m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/02/2018	Completed Defects	31/01/2018	A725 WB WHIRLIES BYPASS TO A749 RBT
-----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	-------------------------------------

Safety Inspection of A725 & A726 Tannochside V1 on 22 January 2018

SW85-317755-235529039	138m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/02/2018	Completed Defects	07/02/2018	A725 WB CROSSBASKETS TO WHIRLIES BYPASS LANE 1 OS WT
-----------------------	------	----	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A725 & A726 Tannochside V1 on 29 January 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 February 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 February 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 February 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 26 February 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 March 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 March 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 March 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 26 March 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 March 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 April 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 09 April 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 16 April 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 23 April 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 30 April 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 04 May 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 11 May 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 14 May 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 21 May 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 28 May 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 04 June 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 11 June 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 18 June 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 25 June 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 02 July 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 09 July 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 16 July 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 23 July 2018

SW85-382484-235917038	42m	42m	TREE	Overhanging/o vergrown (OVER)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A725
-----------------------	-----	-----	------	-------------------------------------	-------	------------	--------------------------	------------	------

SW85-382484-235917039	719m	719m	TREE	Overhanging/o vergrown (OVER)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A725
-----------------------	------	------	------	-------------------------------------	-------	------------	--------------------------	------------	------

Safety Inspection of A725 & A726 Tannochside V1 on 30 July 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 06 August 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 13 August 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 20 August 2018

SW85-395871-235961109	386m	396m	FENCES_AND_BA RRIERS	Accident damage (ACCD)	CAT 1	17/09/2018	Completed Defects	29/09/2018	A725 SB AT BEND AT CROSSBASKETS
-----------------------	------	------	-------------------------	------------------------------	-------	------------	----------------------	------------	------------------------------------

Safety Inspection of A725 & A726 Tannochside V1 on 27 August 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 03 September 2018

SW85-402507-235991316	1,750m	1,750m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/09/2018	Completed Defects	03/09/2018	A725 CROSSBASKET TO WHIRLIES
-----------------------	--------	--------	-------------	--------------------------	-------	------------	----------------------	------------	---------------------------------

Safety Inspection of A725 & A726 Tannochside V1 on 10 September 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 17 September 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 24 September 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 01 October 2018

SW85-415532-236101528	430m	430m	FENCES_AND_BA RRIERS	Accident damage (ACCD)	CAT 1	29/10/2018	Completed Defects	17/10/2018	A725 CROSSBASKET TO WHIRLIES AT BEND
-----------------------	------	------	-------------------------	------------------------------	-------	------------	----------------------	------------	---

Safety Inspection of A725 & A726 Tannochside V1 on 08 October 2018

SW85-418817-236111662	816m	816m	GULLY	Blockage (BLOK)	CAT 1	05/11/2018	Completed Defects	09/10/2018	A725 W/B CROSSBASKETS TO WHIRLIES BYPASS, 2 GULLIES BEFORE 60MPH SIGN
-----------------------	------	------	-------	--------------------	-------	------------	----------------------	------------	---

SW85-418817-236111664	998m	998m	GULLY	Blockage (BLOK)	CAT 1	05/11/2018	Completed Defects	09/10/2018	A725 BETWEEN CROSSBASKETS & WHIRLIES BYPASS 50M BEFORE "CALDERGLEN COUNTRY PARK" SIGN
-----------------------	------	------	-------	--------------------	-------	------------	----------------------	------------	---

SW85-418817-236111665	1,046m	1,046m	GULLY	Blockage (BLOK)	CAT 1	05/11/2018	Completed Defects	09/10/2018	A725 BETWEEN CROSSBASKETS & WHIRLIES BYPASS 15M FROM "CALDERGLEN COUNTRY PARK" SIGN
-----------------------	--------	--------	-------	--------------------	-------	------------	----------------------	------------	---

Safety Inspection of A725 & A726 Tannochside V1 on 15 October 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 22 October 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 29 October 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 05 November 2018

SW85-426396-236186637	1,688m	1,688m	GULLY	Blockage (BLOK)	CAT 1	06/11/2018	Completed Defects	06/11/2018	A725 CROSSBASKETS JCT TO WHIRLIES BYPASS
-----------------------	--------	--------	-------	--------------------	-------	------------	----------------------	------------	---

SW85-426396-236186638	1,714m	1,714m	GULLY	Blockage (BLOK)	CAT 1	06/11/2018	Completed Defects	06/11/2018	A725 CROSSBASKETS JCT TO WHIRLIES BYPASS
-----------------------	--------	--------	-------	--------------------	-------	------------	----------------------	------------	---

SW85-426396-236186639	1,755m	1,755m	GULLY	Blockage (BLOK)	CAT 1	06/11/2018	Completed Defects	06/11/2018	A72 CROSSBASKETS JCT TO WHIRLIESBYPASS
SW85-426396-236186640	1,781m	1,781m	GULLY	Blockage (BLOK)	CAT 1	06/11/2018	Completed Defects	06/11/2018	A725 CROSSBASKETS JCT TO WHIRLIES BYPASS
Safety Inspection of A725 & A726 Tannochside V1 on 12 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 19 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 26 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 03 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 10 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 17 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 24 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 31 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 07 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 14 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 21 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 28 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 04 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 11 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 18 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 25 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 04 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 11 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 18 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 25 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 01 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 08 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 15 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 18 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 26 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 29 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 03 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 10 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 13 May 2019									
SW85-507967-236671084	241m	241m	GULLY	Blockage (BLOK)	CAT 1	10/06/2019	Completed Defects	22/05/2019	A725 SB BETWEEN BLANTYRE & WHIRLIES
SW85-507967-236671085	264m	264m	GULLY	Blockage	CAT 1	10/06/2019	Completed	22/05/2019	A725 SB BTWN BTYRE &

				(BLOK)			Defects		WHIRLIES
SW85-507967-236671086	308m	308m	GULLY	Blockage (BLOK)	CAT 1	10/06/2019	Completed Defects	22/05/2019	A725 SB BETWEEN BLANTYRE & WHIRLIES RBT
SW85-507967-236671087	329m	329m	GULLY	Blockage (BLOK)	CAT 1	10/06/2019	Completed Defects	22/05/2019	A725 SB BETWEEN BLANTYRE & WHIRLIES RBT
SW85-507967-236671088	400m	400m	GULLY	Blockage (BLOK)	CAT 1	10/06/2019	Completed Defects	22/05/2019	A725 SB BETWEEN BLANTYRE & WHIRLIES RBT
SW85-507967-236671089	474m	474m	GULLY	Blockage (BLOK)	CAT 1	10/06/2019	Completed Defects	22/05/2019	A725 SB BETWEEN BLANTYRE & WHIRLIES RBT
Safety Inspection of A725 & A726 Glasgow East V1 on 20 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 27 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 03 June 2019									
SW85-518356-236809581	1,777m	1,777m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/06/2019	Completed Defects	03/06/2019	A725 SB WHIRLIES BYPASS TO KINGSWAY RBT
SW85-518356-236809582	1,773m	1,773m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/06/2019	Completed Defects	03/06/2019	A725 SB WHIRLIES BYPASS TO KINGSWAY RBT
SW85-518356-236809583	1,776m	1,776m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/06/2019	Completed Defects	03/06/2019	A725 SB WHIRLIES BYPASS TO KINGSWAY RBT
SW85-518356-236809584	1,773m	1,773m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/06/2019	Completed Defects	03/06/2019	A725 SB WHIRLIES BYPASS TO KINGSWAY RBT
SW85-518356-236809585	1,770m	1,770m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/06/2019	Completed Defects	03/06/2019	A725 SB WHIRLIES BYPASS TO KINGSWAY RBT
Safety Inspection of A725 & A726 Glasgow East V1 on 10 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 17 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 24 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 01 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 08 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 15 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 22 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 29 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 05 August 2019									
SW85-532050-236921279	1,300m	1,300m	GULLY	Blockage (BLOK)	CAT 1	02/09/2019	Completed Defects	22/08/2019	A725 CROSSBASKET TO WHIRLIES @ BUS STOP
SW85-532050-236921280	1,323m	1,323m	GULLY	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	22/08/2019	A725 CROSSBAKET TO WHIRLIES OASSED THE BUS STOP
Safety Inspection of A725 & A726 Glasgow East V1 on 12 August 2019									
SW85-532342-236938479	109m	109m	GULLY	Blockage (BLOK)	CAT 1	09/09/2019	Completed Defects	30/08/2019	A725 SB 90M AFTER LAYBY
SW85-532342-236938480	1,522m	1,522m	GULLY	Cracked or broken (IBCK)	CAT 1	09/09/2019	Completed Defects	30/08/2019	A725 SB AT BYPASS
SW85-532342-236938481	1,600m	1,600m	GULLY	Blockage (BLOK)	CAT 1	09/09/2019	Completed Defects	30/08/2019	A725 SB AT SPLIT JCT
SW85-532342-236938477	33m	33m	GULLY	Blockage (BLOK)	CAT 1	09/09/2019	Completed Defects	30/08/2019	A725 SB 40M AFTER LAYBY

SW85-532342-236938478	68m	68m	GULLY	Blockage (BLOK)	CAT 1	09/09/2019	Completed Defects	30/08/2019	A725 SB 60M AFTER LAYBY
-----------------------	-----	-----	-------	--------------------	-------	------------	----------------------	------------	-------------------------

Safety Inspection of A725 & A726 Glasgow East V1 on 19 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 26 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 09 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 16 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 23 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 30 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 07 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 14 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 21 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 28 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 04 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 11 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 18 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 25 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 09 December 2019

SW85-537396-237210698	1,048m	1,048m	GULLY	Blockage (BLOK)	CAT 1	06/01/2020	Completed Defects	23/12/2019	A725 W/B CROSSBASKET TO WHIRLIES BYPASS
-----------------------	--------	--------	-------	--------------------	-------	------------	----------------------	------------	--

SW85-537396-237210700	999m	999m	GULLY	Blockage (BLOK)	CAT 1	06/01/2020	Completed Defects	23/12/2019	A725 W/B CROSSBASKET TO WHIRLIES BYPASS
-----------------------	------	------	-------	--------------------	-------	------------	----------------------	------------	--

SW85-537396-237210701	1,553m	1,553m	GULLY	Blockage (BLOK)	CAT 1	06/01/2020	Completed Defects	23/12/2019	A725 W/B CROSSBASKET TO WHIRLIES BYPASS
-----------------------	--------	--------	-------	--------------------	-------	------------	----------------------	------------	--

SW85-537396-237210702	1,572m	1,572m	GULLY	Blockage (BLOK)	CAT 1	06/01/2020	Completed Defects	23/12/2019	A725 CROSSBASKET TO HIRLIES BYPASS
-----------------------	--------	--------	-------	--------------------	-------	------------	----------------------	------------	---------------------------------------

SW85-537396-237210703	1,598m	1,598m	GULLY	Blockage (BLOK)	CAT 1	06/01/2020	Completed Defects	23/12/2019	A725 W/B CROSSBASKET TO WHIRLIES BYPASS
-----------------------	--------	--------	-------	--------------------	-------	------------	----------------------	------------	--

SW85-537396-237210704	1,616m	1,616m	GULLY	Blockage (BLOK)	CAT 1	06/01/2020	Completed Defects	23/12/2019	A725 W/B CROSSBASKET TO WHIRLES
-----------------------	--------	--------	-------	--------------------	-------	------------	----------------------	------------	------------------------------------

Safety Inspection of A725 & A726 Glasgow East V1 on 16 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 30 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 06 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 13 January 2020

SW85-538413-237239868	1,643m	1,643m	CARRIAGEWAY	Excessive muck (MUCK)	3RD PTY	10/02/2020	Awaiting CCMS Permanent	01/01/9999	A725 WB BETWEEN ONSLIP FROM DOUGLAS ST TO WHIRLIES RBT
-----------------------	--------	--------	-------------	--------------------------	---------	------------	----------------------------	------------	--

Safety Inspection of A725 & A726 Glasgow East V1 on 20 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 27 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 February 2020

SW85-539432-237270401	1,006m	1,006m	GULLY	Blockage (BLOK)	CAT 1	09/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 SB BETWEEN CROSSBASKETS & WHIRLIES RBT. PRIOR TO BUS STOP
SW85-539432-237270402	1,028m	1,028m	GULLY	Blockage (BLOK)	CAT 1	09/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 SB BETWEEN CROSSBASKETS & WHIRLIES RBT, PRIOR TO BUS STOP
SW85-539432-237270403	1,053m	1,053m	GULLY	Blockage (BLOK)	CAT 1	09/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 SB BETWEEN CROSSBASKETS & WHIRLIES RBT, PRIOR TO BUS STOP
SW85-539432-237270404	1,081m	1,081m	GULLY	Blockage (BLOK)	CAT 1	09/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 SB BTWN CROSSBASKETS & WHIRLIES
SW85-539432-237270405	1,080m	1,080m	GULLY	Blockage (BLOK)	CAT 1	09/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 SB BTWN CROSSBASKETS & WHIRLIES
SW85-539432-237270406	1,099m	1,099m	GULLY	Blockage (BLOK)	CAT 1	09/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 SB BTWN CROSSBASKETS & WHIRLIES
SW85-539432-237270407	1,119m	1,119m	GULLY	Blockage (BLOK)	CAT 1	09/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 SB BTWN CROSSBASKETS & WHIRLIES
SW85-539432-237270408	1,145m	1,145m	GULLY	Blockage (BLOK)	CAT 1	09/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 SB BTWN CROSSBASKETS & WHIRLIES
SW85-539432-237270409	1,184m	1,184m	GULLY	Blockage (BLOK)	CAT 1	09/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 SB BTWN CROSSBASKETS & WHIRLIES
SW85-539432-237270410	1,201m	1,201m	GULLY	Blockage (BLOK)	CAT 1	09/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 SB BTWN CROSSBASKETS & WHIRLIES
SW85-539432-237270411	1,674m	1,674m	GULLY	Blockage (BLOK)	CAT 1	09/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 SB BTWN CROSSBASKETS & WHIRLIES @ BEND
SW85-539432-237270412	1,644m	1,644m	GULLY	Blockage (BLOK)	CAT 1	09/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 SB BTWN CROSSBASKETS & WHIRLIES
SW85-539432-237270413	1,624m	1,624m	GULLY	Blockage (BLOK)	CAT 1	09/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 SB BTWN CROSSBASKETS & WHIRLIES
SW85-539432-237270414	1,599m	1,599m	GULLY	Blockage (BLOK)	CAT 1	09/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 SB BTWN CROSSBASKETS & WHIRLIES
SW85-539432-237270415	1,574m	1,574m	GULLY	Blockage (BLOK)	CAT 1	09/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 SB BTWN CROSSBASKETS & WHIRLIES
SW85-539432-237270416	1,552m	1,552m	GULLY	Blockage (BLOK)	CAT 1	09/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 SB BTWN CROSSBASKETS & WHIRLIES
SW85-539432-237270417	1,528m	1,528m	GULLY	Blockage (BLOK)	CAT 1	09/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 SB BTWN CROSSBASKETS & WHIRLIES

Safety Inspection of A725 & A726 Glasgow East V1 on 17 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 March 2020

No defects recorded

15025/41 : WITH: HAMILTON RD OFF SLIP TO DOUGLAS RD OFF SLIP

Safety Inspection of A725 & A726 Tannochside V1 on 06 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 28 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 08 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 15 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 26 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 31 July 2017

SW85-282816-235284859	672m	0m	FENCES_AND_BARRIERS	Accident damage (ACCD)	CAT 1	28/08/2017	Completed Defects	24/08/2017	A725 EB BETWEEN DOUGLAS ST AND CROSSBASKETS
-----------------------	------	----	---------------------	------------------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Tannochside V1 on 07 August 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 14 August 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 21 August 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 28 August 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 04 September 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 11 September 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 18 September 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 25 September 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 02 October 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 09 October 2017

Safety Inspection of A725 & A726 Tannochside V1 on 14 May 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 21 May 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 28 May 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 04 June 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 11 June 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 18 June 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 25 June 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 02 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 09 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 16 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 23 July 2018

SW85-382484-235917045	479m	479m	TREE	Overhanging/o vergrown (OVER)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A725
-----------------------	------	------	------	-------------------------------------	-------	------------	--------------------------	------------	------

Safety Inspection of A725 & A726 Tannochside V1 on 30 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 01 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 08 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 15 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 November 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 November 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 November 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 26 November 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 December 2018

Safety Inspection of A725 & A726 Glasgow East V1 on 05 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 12 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 19 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 26 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 09 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 16 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 23 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 30 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 07 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 14 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 21 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 28 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 04 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 11 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 18 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 25 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 09 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 16 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 30 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 06 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 13 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 20 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 27 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 March 2020

No defects recorded

15025/42 : AGAINST: DOUGLAS ST TO CROSSBASKETS

Safety Inspection of A725 & A726 Tannochside V1 on 06 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 February 2017

Safety Inspection of A725 & A726 Tannochside V1 on 09 October 2017*No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 16 October 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 23 October 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 30 October 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 06 November 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 13 November 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 20 November 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 26 November 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 04 December 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 11 December 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 18 December 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 22 December 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 29 December 2017***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 05 January 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 08 January 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 15 January 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 22 January 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 29 January 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 05 February 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 12 February 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 19 February 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 26 February 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 05 March 2018**

SW85-325627-235551437	119m	0m	FENCES_AND_BARRIERS	Accident damage (ACCD)	CAT 1	02/04/2018	Completed Defects	28/03/2018	A725 WB EK EXPRESSWAY AT BLANTYRE ONSLIP TO CROSSBASKETS JCT C RESERVE
SW85-325627-235551438	847m	0m	FENCES_AND_BARRIERS	Accident damage (ACCD)	CAT 1	02/04/2018	Completed Defects	28/03/2018	A725 WB EK EXPRESSWAY BLANTYRE SLIP TO CROSSBASKETS C RESERVE

Safety Inspection of A725 & A726 Tannochside V1 on 12 March 2018*No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 19 March 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 26 March 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 29 March 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 05 April 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 09 April 2018**

SW85-336420-235613791	11m	0m	FENCES_AND_BARRIERS	Accident damage (ACCD)	CAT 1	07/05/2018	Completed Defects	02/05/2018	A725 WB MAIN C/WAY BLANTYRE SLIP TO CROSSBASKETS JCT C RESERVE
-----------------------	-----	----	---------------------	------------------------	-------	------------	-------------------	------------	--

No defects recorded
Safety Inspection of A725 & A726 Glasgow East V1 on 03 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 31 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 07 January 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 14 January 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 21 January 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 28 January 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 04 February 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 11 February 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 18 February 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 25 February 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 04 March 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 11 March 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 18 March 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 25 March 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 01 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 08 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 15 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 18 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 26 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 29 April 2019

SW85-500796-236613309	70m	70m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	30/04/2019	Completed Defects	30/04/2019	A725 SB AFTER H.BLANTYRE ONSLIP IN MAIN C/WAY
SW85-500796-236613310	279m	279m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	30/04/2019	Completed Defects	30/04/2019	A725 SB AFTER H.BLANTYRE ONSLIP IN MAIN C/WAY NSL NSWT
SW85-500796-236613311	540m	540m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	30/04/2019	Completed Defects	30/04/2019	A725 SB AFTER H.BLANTYRE ONSLIP IN MAIN C/WAY
SW85-500796-236613312	570m	570m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	30/04/2019	Completed Defects	30/04/2019	A725 SB AFTER H.BLANTYRE ONSLIP IN MAIN C/WAY

Safety Inspection of A725 & A726 Glasgow East V1 on 03 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 13 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 20 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 27 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 June 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 June 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 June 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 June 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 01 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 08 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 15 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 22 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 29 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 05 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 12 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 19 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 26 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 09 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 16 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 23 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 30 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 07 October 2019

SW85-535030-237037835	580m	580m	GULLY	Missing (MISS)	CAT 1	04/11/2019	Awaiting CCMS Permanent Date	01/01/9999	A725 EB EK EXPRESSWAY AFTER OVER BRIDGE NSIDE
-----------------------	------	------	-------	----------------	-------	------------	------------------------------------	------------	--

Safety Inspection of A725 & A726 Glasgow East V1 on 14 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 21 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 28 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 04 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 11 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 18 November 2019

SW85-536773-237162895	680m	680m	FENCES_AND_BA RRIERS	Missing (MISS)	3RD PTY	19/11/2019	Awaiting CCMS Permanent Date	01/01/9999	A725 WB DOUGLAS ST- CROSSBASKETS NEARSIDE BOUNDARY FENCE
-----------------------	------	------	-------------------------	----------------	---------	------------	------------------------------------	------------	--

Safety Inspection of A725 & A726 Glasgow East V1 on 25 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 09 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 16 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 30 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 06 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 13 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 20 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 27 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 March 2020

No defects recorded

15025/72 : AGAINST: OFF SLIP TO ON SLIP DOUGLAS ST

Safety Inspection of A725 & A726 Tannochside V1 on 06 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 February 2017

SW77245341-235057614	383m	388m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/03/2017	Completed Defects	17/03/2017	A725 SB BETWEEN DOUGLAS ST OFF - ON
----------------------	------	------	-------------	-------------------	-------	------------	----------------------	------------	--

Safety Inspection of A725 & A726 Tannochside V1 on 27 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 March 2017

SW85-249869-235067209	117m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	03/04/2017	Completed Defects	04/04/2017	INFILL POTHOLE
-----------------------	------	----	-------------	-------------------	-------	------------	----------------------	------------	----------------

SW85-249869-235067210	127m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	03/04/2017	Completed Defects	04/04/2017	A725 EB 200M PAST DOUGLAS ST ONSLIP TO RAITH
-----------------------	------	----	-------------	-------------------	-------	------------	----------------------	------------	---

Safety Inspection of A725 & A726 Tannochside V1 on 13 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 28 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 08 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 15 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 June 2017

No defects recorded

<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 05 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 12 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 19 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 26 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 05 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 12 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 19 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 26 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 29 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 05 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 09 April 2018									
SW85-336420-235613790	8m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/05/2018	Completed Defects	10/04/2018	A725 WB MAIN C/WAY PRIOR TO BLANTYRE MAIN ST OFFSLIP NS WT
Safety Inspection of A725 & A726 Tannochside V1 on 16 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 23 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 30 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 04 May 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 11 May 2018									
SW85-347336-235705985	175m	175m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	12/05/2018	Completed Defects	12/05/2018	A725 FROM BLANTYRE ON SLIP TO RAITH @60 MPH SIGN 20 MTRS BEFORE TO 20 MTRS PAST 60 SIGN
Safety Inspection of A725 & A726 Tannochside V1 on 14 May 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 21 May 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 28 May 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 04 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 11 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 18 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 25 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 02 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 09 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 16 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 23 July 2018									
SW85-382484-235917030	123m	123m	TREE	Overhanging/o vergrown (OVER)	CAT 1	24/07/2018	Completed Defects	23/07/2018	A725 @OFFSLIP TO ONSLIP DOUGLAS ST
SW85-382484-235917031	130m	130m	FENCES_AND_BARRIERS	Accident damage (ACCD)	CAT 1	20/08/2018	Completed Defects	31/07/2018	A725 @ OFFSLIP TO ONSLIP DOUGLAS STREET ON MAIN C/W CENTRE RES
Safety Inspection of A725 & A726 Tannochside V1 on 30 July 2018									
SW85-385720-235921489	124m	124m	CARRIAGEWAY	Pothole VIAFIX	CAT 1	31/07/2018	Completed	30/07/2018	A725 150 MTRS PASS ONSLIP

				(POTV)			Defects		FROM DOUGLAS ST TO RAITH @ 60 MPH SIGN
SW85-385720-235921490	89m	89m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	31/07/2018	Completed Defects	30/07/2018	A725 200 MTRS PASS ONSLIP FROM DOUGLAS ST TO RAITH 50 MTRS PASS 60MPH SIGN

Safety Inspection of A725 & A726 Tannochside V1 on 06 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 September 2018

SW85-405761-236052249	244m	244m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/09/2018	Completed Defects	10/09/2018	A725 DOUGLAS ST ONSLIP TO MAIN ST OFF N/S/L @ BRIDGE
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	--

Safety Inspection of A725 & A726 Tannochside V1 on 17 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 01 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 08 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 15 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 November 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 November 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 November 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 26 November 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 31 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 07 January 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 14 January 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 21 January 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 28 January 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 04 February 2019

SW85-429263-236292013	42m	42m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	05/02/2019	Completed Defects	04/02/2019	A725 EB ONSLIP BEYOND SOUTH LANARKSHIRE CREMATORIUM
-----------------------	-----	-----	-------------	-----------------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Glasgow East V1 on 11 February 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 18 February 2019

Safety Inspection of A725 & A726 Glasgow East V1 on 30 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 07 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 14 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 21 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 28 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 04 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 11 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 18 November 2019

SW85-536773-237162894	65m	65m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 1	16/12/2019	Completed Defects	06/12/2019	A725 WB OFF TO DOUGLAS ST
-----------------------	-----	-----	---------------	-----------------------------------	-------	------------	-------------------	------------	---------------------------

Safety Inspection of A725 & A726 Glasgow East V1 on 25 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 09 December 2019

SW85-537396-237210710	531m	531m	FENCES_AND_BARRIERS	Accident damage (ACCD)	CAT 1	06/01/2020	Awaiting CCMS Permanent	01/01/9999	A725 W/B DOUGLAS ST OFF TO ONSLIP
-----------------------	------	------	---------------------	------------------------	-------	------------	-------------------------	------------	-----------------------------------

Safety Inspection of A725 & A726 Glasgow East V1 on 16 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 30 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 06 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 13 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 20 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 27 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 March 2020

No defects recorded

15025/79 : WITH: DOUGLAS RD ON SLIP TO MAIN ST OFF SLIP

Safety Inspection of A725 & A726 Tannochside V1 on 06 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 March 2017

No defects recorded

SW85-253495-235071846	175m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	17/04/2017	Completed Defects	07/04/2017	A725 WB EK EXPRESSWAY AT UNDERBRIDGE OF DOUGLAS ST LANE 2 NS WT
-----------------------	------	----	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Tannochside V1 on 27 March 2017

<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 03 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 10 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 17 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 24 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 28 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 05 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 08 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 15 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 22 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 29 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 05 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 12 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 19 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 26 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 03 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 10 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 17 July 2017									
SW85-282503-235265799	653m	0m	TRAFFIC_SIGNS	Obscured sign (OBSG)	CAT 1	18/07/2017	Completed Defects	17/07/2017	A725 EB ONSLIP TO OFF TO HAMILTON
Safety Inspection of A725 & A726 Tannochside V1 on 24 July 2017									
SW85-282696-235281222	514m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	21/08/2017	Completed Defects	19/08/2017	A725 EB EK EXPRESSWAY TO MAIN ST BLANTYRE
SW85-282696-235281223	564m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	21/08/2017	Completed Defects	19/08/2017	A725 EB EK EXPRESSWAY TO MAIN ST BLANTYRE
Safety Inspection of A725 & A726 Tannochside V1 on 31 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 07 August 2017									
SW85-283357-235299835	262m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	04/09/2017	Completed Defects	30/08/2017	A725 EB EK EXPRESSWAY 100M PAST DOUGLAS ST ONSLIP
SW85-283357-235299836	272m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	04/09/2017	Completed Defects	30/08/2017	A725 EB EK EXPRESSWAY 110M PAST DOUGLAS ST ONSLIP
Safety Inspection of A725 & A726 Tannochside V1 on 14 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 21 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 28 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 04 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 11 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 18 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 25 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 02 October 2017									

<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 09 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 16 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 23 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 30 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 06 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 13 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 20 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 26 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 04 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 11 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 18 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 22 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 29 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 05 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 08 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 15 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 22 January 2018									
SW85-317755-235529040	539m	539m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/02/2018	Completed Defects	07/02/2018	A725 EB MAIN C/WAY FROM DOUGLAS ST ONSLIP BLANTYRE TO OFFSLIP HAMILTON
Safety Inspection of A725 & A726 Tannochside V1 on 29 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 05 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 12 February 2018									
SW85-319332-235534922	857m	857m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/02/2018	Completed Defects	13/02/2018	A725 EB DOULS ST ONSLIP TO 5M PRIOR TO OFFSLIP TO HAMILTON LANE 1
Safety Inspection of A725 & A726 Tannochside V1 on 19 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 26 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 05 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 12 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 19 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 26 March 2018									
SW85-331213-235603158	338m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/03/2018	Completed Defects	27/03/2018	A725 EB EK EXPRESSWAY AT 60MPH SIGN PAST DOUGLAS ST ONSLIP CENTRE LINE
SW85-331213-235603159	348m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/03/2018	Completed Defects	27/03/2018	A725 EB EK EXPRESSWAY AT 60MPH SIGN PAST DOUGLAS ST ONSLIP CENTRE LINE
SW85-331213-235603160	363m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/03/2018	Completed Defects	27/03/2018	A725 EB EK EXPRESSWAY AT 60MPH SIGN PAST DOUGLAS ST ONSLIP CENTRE LINE
Safety Inspection of A725 & A726 Tannochside V1 on 29 March 2018									

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 April 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 09 April 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 16 April 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 23 April 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 30 April 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 04 May 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 11 May 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 14 May 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 21 May 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 28 May 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 04 June 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 11 June 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 18 June 2018

SW85-365643-235853362	432m	432m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	19/06/2018	Completed Defects	21/06/2018	A725 E/B ONSLIP TO OFFSLIP TO HAMILTON
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	--

Safety Inspection of A725 & A726 Tannochside V1 on 25 June 2018

SW85-369136-235853364	563m	563m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	26/06/2018	Completed Defects	25/06/2018	A725 E/B BLANTYRE ON SLIP TO OFF N/S/L
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	--

SW85-369136-235853365	583m	583m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	26/06/2018	Completed Defects	25/06/2018	A725 E/B BLNTYRE ONSLIP TO OFF N/S/L
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	--------------------------------------

Safety Inspection of A725 & A726 Tannochside V1 on 02 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 09 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 16 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 23 July 2018

SW85-382484-235917046	510m	510m	TREE	Overhanging/o vergrown (OVER)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A725
-----------------------	------	------	------	-------------------------------	-------	------------	-----------------------	------------	------

SW85-382484-235917047	569m	569m	TREE	Overhanging/o vergrown (OVER)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A725
-----------------------	------	------	------	-------------------------------	-------	------------	-----------------------	------------	------

Safety Inspection of A725 & A726 Tannochside V1 on 30 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 01 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 08 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 15 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 November 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 November 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 November 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 26 November 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 31 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 07 January 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 14 January 2019

SW85-428154-236270545	733m	733m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/02/2019	Completed Defects	30/01/2019	A725 EB BETWEEN DOUGLAS STREET ONSLIP & BLANTYRE OFF SLIP
SW85-428154-236270546	820m	820m	CARRIAGEWAY	Pothole (POTH)	CAT 1	11/02/2019	Completed Defects	30/01/2019	A725 EB BETWEEN DOUGLAS STREET ONSLIP & BLANTYRE OFF SLIP

Safety Inspection of A725 & A726 Glasgow East V1 on 21 January 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 28 January 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 04 February 2019

SW85-429263-236292012	396m	396m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	05/02/2019	Completed Defects	04/02/2019	A725 EB ONSLIP BEYOND SOUTH LANARKSHIRE CREMATORIUM
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Glasgow East V1 on 11 February 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 18 February 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 25 February 2019

SW85-434998-236328627	598m	598m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/03/2019	Completed Defects	21/03/2019	A725 EB BETWEEN ONSLIP FROM DOUGLAS ST TO OFFSLIP TO MAIN ST
SW85-434998-236328628	596m	596m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/03/2019	Completed Defects	21/03/2019	A725 EB BETWEEN ONSLIP FROM DOUGLAS ST TO OFFSLIP TO MAIN ST
SW85-434998-236328629	284m	284m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/03/2019	Completed Defects	21/03/2019	A725 EB BETWEEN ONSLIP FROM DOUGLAS ST TO OFFSLIP TO MAIN ST, IN CENTRE LINE

Safety Inspection of A725 & A726 Glasgow East V1 on 04 March 2019

SW85-439166-236336879	875m	875m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	05/03/2019	Completed Defects	05/03/2019	A725 NB OFF SLIP TO MAIN ST.
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	------------------------------

Safety Inspection of A725 & A726 Glasgow East V1 on 11 March 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 18 March 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 25 March 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 01 April 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 08 April 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 15 April 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 18 April 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 26 April 2019**

SW85-496955-236588321	296m	296m	CARRIAGEWAY	Pothole (POTH)	CAT 1	24/05/2019	Completed Defects	08/05/2019	A725 WB BETWEEN BLANTYRE ON & A724 OFF TO HAMILTON
-----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A725 & A726 Glasgow East V1 on 29 April 2019

SW85-500796-236613313	906m	906m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	30/04/2019	Completed Defects	30/04/2019	A725 NB BLANTYRE OFFSLIP @ TOP OF SLIP
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	--

SW85-500796-236613314	768m	768m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	30/04/2019	Completed Defects	30/10/2019	A725 NB 40M PRIOR TO BLANTYRE OFFSLIP @ LANE 2 NSWT
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	---

SW85-500796-236613315	423m	423m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	30/04/2019	Completed Defects	30/04/2019	A725 NB PRIOR TO BLANTYRE OFFSLIP @ 20M PRIOR TO C/BRIDGE, GLSGW, CARLISLE SIGN
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	---

SW85-500796-236613316	562m	562m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	30/04/2019	Completed Defects	30/10/2019	A725 NB PRIOR TO BLANTYRE OFFSLIP @ C/BRIDGE, GLASGOW, CRLISLE SIGN
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Glasgow East V1 on 03 May 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 10 May 2019**

SW85-506485-236633009	706m	706m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/05/2019	Completed Defects	10/05/2019	A725 NB @ PRIOR TO BLANTYRE OFFSLIP MAIN ST B7012
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	---

SW85-506485-236633010	753m	735m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/05/2019	Completed Defects	10/05/2019	A725 NB @ PRIOR TO BLANTYRE OFFSLIP MAIN ST B7012
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	---

SW85-506485-236633011	913m	913m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/06/2019	Completed Defects	21/05/2019	A725 NB @ BLANTYRE OFFSLIP MAIN ST B7012
-----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A725 & A726 Glasgow East V1 on 13 May 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 20 May 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 27 May 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 03 June 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 10 June 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 17 June 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 24 June 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 01 July 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 08 July 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 15 July 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 22 July 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 29 July 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 05 August 2019**

No defects recorded
Safety Inspection of A725 & A726 Glasgow East V1 on 12 August 2019
No defects recorded
Safety Inspection of A725 & A726 Glasgow East V1 on 19 August 2019
No defects recorded
Safety Inspection of A725 & A726 Glasgow East V1 on 26 August 2019
No defects recorded
Safety Inspection of A725 & A726 Glasgow East V1 on 02 September 2019
No defects recorded
Safety Inspection of A725 & A726 Glasgow East V1 on 09 September 2019
No defects recorded
Safety Inspection of A725 & A726 Glasgow East V1 on 16 September 2019
No defects recorded
Safety Inspection of A725 & A726 Glasgow East V1 on 23 September 2019
No defects recorded
Safety Inspection of A725 & A726 Glasgow East V1 on 30 September 2019
No defects recorded
Safety Inspection of A725 & A726 Glasgow East V1 on 07 October 2019
No defects recorded
Safety Inspection of A725 & A726 Glasgow East V1 on 14 October 2019
No defects recorded
Safety Inspection of A725 & A726 Glasgow East V1 on 21 October 2019
No defects recorded
Safety Inspection of A725 & A726 Glasgow East V1 on 28 October 2019
No defects recorded
Safety Inspection of A725 & A726 Glasgow East V1 on 04 November 2019
No defects recorded
Safety Inspection of A725 & A726 Glasgow East V1 on 11 November 2019
No defects recorded
Safety Inspection of A725 & A726 Glasgow East V1 on 18 November 2019
No defects recorded
Safety Inspection of A725 & A726 Glasgow East V1 on 25 November 2019
No defects recorded
Safety Inspection of A725 & A726 Glasgow East V1 on 02 December 2019
No defects recorded
Safety Inspection of A725 & A726 Glasgow East V1 on 09 December 2019
No defects recorded
Safety Inspection of A725 & A726 Glasgow East V1 on 16 December 2019
No defects recorded
Safety Inspection of A725 & A726 Glasgow East V1 on 30 December 2019
No defects recorded
Safety Inspection of A725 & A726 Glasgow East V1 on 06 January 2020
No defects recorded
Safety Inspection of A725 & A726 Glasgow East V1 on 13 January 2020
No defects recorded
Safety Inspection of A725 & A726 Glasgow East V1 on 20 January 2020
No defects recorded
Safety Inspection of A725 & A726 Glasgow East V1 on 27 January 2020
No defects recorded
Safety Inspection of A725 & A726 Glasgow East V1 on 03 February 2020
No defects recorded
Safety Inspection of A725 & A726 Glasgow East V1 on 10 February 2020
No defects recorded
Safety Inspection of A725 & A726 Glasgow East V1 on 17 February 2020
No defects recorded
Safety Inspection of A725 & A726 Glasgow East V1 on 24 February 2020
No defects recorded
Safety Inspection of A725 & A726 Glasgow East V1 on 02 March 2020
No defects recorded

15030/05 : WITH: MAIN STREET OFF SLIP TO ON SLIP

Safety Inspection of A725 & A726 Tannochside V1 on 06 February 2017
No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 13 February 2017
No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 20 February 2017
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 14 May 2018*No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 21 May 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 28 May 2018**

SW85-354701-235705987	83m	83m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	29/05/2018	Completed Defects	28/05/2018	A725 OFFSLIP TO HAMILTON
-----------------------	-----	-----	-------------	-----------------------	-------	------------	-------------------	------------	--------------------------

Safety Inspection of A725 & A726 Tannochside V1 on 04 June 2018*No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 11 June 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 18 June 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 25 June 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 02 July 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 09 July 2018**

SW85-375960-235871408	57m	57m	TREE	Overhanging/o vergrown (OVER)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	E/B OFFSLIP TO MAIN ST
-----------------------	-----	-----	------	-------------------------------	-------	------------	-----------------------	------------	------------------------

SW85-375960-235871409	64m	64m	TREE	Overhanging/o vergrown (OVER)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	E/B OFFSLIP TO MAIN ST
-----------------------	-----	-----	------	-------------------------------	-------	------------	-----------------------	------------	------------------------

Safety Inspection of A725 & A726 Tannochside V1 on 16 July 2018

SW85-379248-235909994	328m	328m	FENCES_AND_BARRIERS	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Completed Defects	14/11/2018	A725 OFFSLIP TO ONSLIP TO MAIN STREET ON BRIDGE
-----------------------	------	------	---------------------	---	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Tannochside V1 on 23 July 2018*No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 30 July 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 06 August 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 13 August 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 20 August 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 27 August 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 03 September 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 10 September 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 17 September 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 24 September 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 01 October 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 08 October 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 15 October 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 22 October 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 29 October 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 05 November 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 12 November 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 19 November 2018***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 26 November 2018**

<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 03 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 10 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 17 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 24 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 31 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 07 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 14 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 21 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 28 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 04 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 11 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 18 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 25 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 04 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 11 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 18 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 25 March 2019									
SW85-456925-236487668	371m	371m	STRUCTURE	Graffiti - Offensive (OFFS)	CAT 1	26/03/2019	Completed Defects	26/03/2019	A725 NB HIGH BLANTYRE BETWEEN OFF & ON, AT RBT @ MAIN ST
Safety Inspection of A725 & A726 Glasgow East V1 on 01 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 08 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 15 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 18 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 26 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 29 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 03 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 10 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 13 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 20 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 27 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 03 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 10 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 17 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 24 June 2019									
<i>No defects recorded</i>									

Safety Inspection of A725 & A726 Glasgow East V1 on 01 July 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 08 July 2019**

SW85-530970-236892999	316m	316m	STRUCTURE	Graffiti - Offensive (OFFS)	CAT 1	05/08/2019	Completed Defects	23/07/2019	A725 WB @ H. BLANTYRE MAIN STREET @ STRUCTURE UPRIGHT
SW85-530970-236893000	317m	316m	STRUCTURE	Graffiti - Offensive (OFFS)	CAT 1	05/08/2019	Completed Defects	23/07/2019	A725 WB @ H. BLANTYRE MAIN STREET @ STRUCTURE UPRIGHT
SW85-530970-236893002	324m	324m	STRUCTURE	Graffiti - Offensive (OFFS)	CAT 1	05/08/2019	Completed Defects	23/07/2019	A725 WB @ H. BLANTYRE MAIN STREET @ STRUCTURE UPRIGHT
SW85-530970-236893003	325m	325m	STRUCTURE	Graffiti - Offensive (OFFS)	CAT 1	05/08/2019	Completed Defects	23/07/2019	A725 WB @ H. BLANTYRE MAIN STREET @ STRUCTURE UPRIGHT

Safety Inspection of A725 & A726 Glasgow East V1 on 15 July 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 22 July 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 29 July 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 05 August 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 12 August 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 19 August 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 26 August 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 02 September 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 09 September 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 16 September 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 23 September 2019**

SW85-534451-237024634	267m	267m	STRUCTURE	Graffiti - Offensive (OFFS)	CAT 1	21/10/2019	Completed Defects	18/10/2019	A725 EB OFF TO MAIN ST
-----------------------	------	------	-----------	-----------------------------------	-------	------------	----------------------	------------	------------------------

Safety Inspection of A725 & A726 Glasgow East V1 on 30 September 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 07 October 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 14 October 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 21 October 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 28 October 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 04 November 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 11 November 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 18 November 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 25 November 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 02 December 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 09 December 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 16 December 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 30 December 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 06 January 2020***No defects recorded*

Safety Inspection of A725 & A726 Glasgow East V1 on 13 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 20 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 27 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 March 2020

No defects recorded

15030/06 : AGAINST: OFF SLIP TO ON SLIP MAIN STREET

Safety Inspection of A725 & A726 Tannochside V1 on 06 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 28 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 08 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 15 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 26 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 July 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 24 July 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 31 July 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 07 August 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 14 August 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 21 August 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 28 August 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 04 September 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 11 September 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 18 September 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 25 September 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 02 October 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 09 October 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 16 October 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 23 October 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 30 October 2017

SW85-315746-235433877	369m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/11/2017	Completed Defects	06/11/2017	A725 WB EK EXPRESSWAY BETWEEN BLANTYRE MAIN ST OVERBRIDGE AND ONSLIP
SW85-315746-235433878	403m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/11/2017	Completed Defects	06/11/2017	A725 WB BETWEEN BLANTYRE MAIN ST OVERBRIDGE AND ONSLIP

Safety Inspection of A725 & A726 Tannochside V1 on 06 November 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 13 November 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 20 November 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 26 November 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 04 December 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 11 December 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 18 December 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 22 December 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 29 December 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 05 January 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 08 January 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 15 January 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 22 January 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 29 January 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 05 February 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 12 February 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 19 February 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 26 February 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 05 March 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 12 March 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 19 March 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 26 March 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 29 March 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 05 April 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 09 April 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 16 April 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 23 April 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 30 April 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 04 May 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 11 May 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 14 May 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 21 May 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 28 May 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 04 June 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 11 June 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 18 June 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 25 June 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 02 July 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 09 July 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 16 July 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 23 July 2018

SW85-382484-235917035	364m	364m	TREE	Overhanging/o vergrown (OVER)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A725
-----------------------	------	------	------	-------------------------------------	-------	------------	--------------------------	------------	------

Safety Inspection of A725 & A726 Tannochside V1 on 30 July 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 06 August 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 13 August 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 20 August 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 27 August 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 03 September 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 10 September 2018

No defects recorded

No defects recorded
Safety Inspection of A725 & A726 Glasgow East V1 on 03 May 2019

SW85-504794-236617197	605m	605m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/05/2019	Completed Defects	03/05/2019	A726 SB BETWEEN ONSLIP FROM B7012 TO OFF SLIP TO DOUGLAS STREET
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Glasgow East V1 on 10 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 13 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 20 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 27 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 June 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 June 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 June 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 June 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 01 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 08 July 2019

SW85-530970-236893001	292m	292m	STRUCTURE	Graffiti - Offensive (OFFS)	CAT 1	05/08/2019	Completed Defects	23/07/2019	A725 WB @ H. BLANTYRE MAIN STREET @ STRUCTURE UPRIGHT
-----------------------	------	------	-----------	-----------------------------	-------	------------	-------------------	------------	---

SW85-530970-236892998	292m	292m	STRUCTURE	Graffiti - Offensive (OFFS)	CAT 1	05/08/2019	Completed Defects	23/07/2019	A725 WB @ H. BLANTYRE MAIN STREET @ STRUCTURE UPRIGHT
-----------------------	------	------	-----------	-----------------------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Glasgow East V1 on 15 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 22 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 29 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 05 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 12 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 19 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 26 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 09 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 16 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 23 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 30 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 07 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 14 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 21 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 28 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 04 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 11 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 18 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 25 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 09 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 16 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 30 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 06 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 13 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 20 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 27 January 2020

SW85-538825-237248065	317m	317m	CARRIAGEWAY	Pothole (POTH)	CAT 1	24/02/2020	Completed Defects	12/02/2020	A725 SB BETWEEN OFF & ON TO MAIN ST
SW85-538825-237248066	369m	369m	CARRIAGEWAY	Pothole (POTH)	CAT 1	24/02/2020	Completed Defects	12/02/2020	A725 SB BETWEEN OFF & ON TO MAIN ST
SW85-538825-237248067	387m	387m	CARRIAGEWAY	Pothole (POTH)	CAT 1	24/02/2020	Completed Defects	12/02/2020	A725 SB BETWEEN OFF & ON TO MAIN ST
SW85-538825-237248068	438m	438m	CARRIAGEWAY	Pothole (POTH)	CAT 1	24/02/2020	Completed Defects	12/02/2020	A725 SB BETWEEN OFF & ON TO MAIN ST

Safety Inspection of A725 & A726 Glasgow East V1 on 03 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 February 2020

SW85-544128-237284474	316m	316m	FENCES_AND_BARRIERS	Accident damage (ACCD)	CAT 1	23/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 SB BETWEEN MAIN ST OFF & ON SLIP
-----------------------	------	------	---------------------	------------------------	-------	------------	-------------------------	------------	---------------------------------------

Safety Inspection of A725 & A726 Glasgow East V1 on 02 March 2020

No defects recorded

15030/39 : WITH: MAIN ST ON SLIP TO GLASGOW RD ON SLIP

Safety Inspection of A725 & A726 Tannochside V1 on 06 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 April 2017

No defects recorded

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 18 December 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 22 December 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 29 December 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 05 January 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 08 January 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 15 January 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 22 January 2018

SW85-317755-235529038	305m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/02/2018	Completed Defects	30/01/2018	A725 WB MAIN ST END OF ONSLIP FROM BLANTYRE
-----------------------	------	----	-------------	-------------------	-------	------------	----------------------	------------	--

Safety Inspection of A725 & A726 Tannochside V1 on 29 January 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 February 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 February 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 February 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 26 February 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 March 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 March 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 March 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 26 March 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 March 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 April 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 09 April 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 16 April 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 23 April 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 30 April 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 04 May 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 11 May 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 14 May 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 21 May 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 28 May 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 04 June 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 11 June 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 18 June 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 25 June 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 02 July 2018
No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 09 July 2018

Safety Inspection of A725 & A726 Glasgow East V1 on 04 March 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 11 March 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 18 March 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 25 March 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 01 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 08 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 15 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 18 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 26 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 29 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 May 2019

SW85-504794-236617203	748m	748m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/05/2019	Completed Defects	04/05/2019	A725 NB @ ONSLIP FROM A724 GLASGOW ROAD
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Glasgow East V1 on 10 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 13 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 20 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 27 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 June 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 June 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 June 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 June 2019

SW85-529828-236863341	311m	311m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	02/07/2019	Awaiting CCMS Permanent	01/07/2019	A725 W/B ONSLIP FROM MAIN ST
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------------	------------	------------------------------

Safety Inspection of A725 & A726 Glasgow East V1 on 01 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 08 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 15 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 22 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 29 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 05 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 12 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 19 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 26 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 09 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 16 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 23 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 30 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 07 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 14 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 21 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 28 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 04 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 11 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 18 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 25 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 09 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 16 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 30 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 06 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 13 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 20 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 27 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 March 2020

No defects recorded

15030/40 : AGAINST:ON SLIP WBERRY RD TO OFF SLIP MAIN ST

Safety Inspection of A725 & A726 Tannochside V1 on 06 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 09 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 16 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 23 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 30 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 01 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 08 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 15 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 November 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 November 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 November 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 26 November 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 December 2018

SW85-427123-236235026	50m	50m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/12/2018	Completed Defects	03/12/2018	A725 MAIN ST ONSLIP TO WHIRLIES @ TOP OF SLIP
-----------------------	-----	-----	-------------	-----------------------	-------	------------	-------------------	------------	---

SW85-427123-236235027	57m	57m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/12/2018	Completed Defects	03/12/2018	A725 MAIN ST ONSLIP TO WHIRLIES @ TOP OF SLIP
-----------------------	-----	-----	-------------	-----------------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Glasgow East V1 on 10 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 31 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 07 January 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 14 January 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 21 January 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 28 January 2019

SW85-428544-236286478	90m	90m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	29/01/2019	Completed Defects	29/01/2019	A725 SB @ ONSLIP FROM A724 @ END OF SLIP IN CENTRE OF LANE
-----------------------	-----	-----	-------------	-----------------------	-------	------------	-------------------	------------	--

Safety Inspection of A725 & A726 Glasgow East V1 on 04 February 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 11 February 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 18 February 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 25 February 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 04 March 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 11 March 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 18 March 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 25 March 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 01 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 08 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 15 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 18 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 26 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 29 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 13 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 20 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 27 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 June 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 June 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 June 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 June 2019

SW85-529828-236863342	73m	73m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	02/07/2019	Awaiting CCMS Permanent	01/07/2019	A725 W/B ONSLIP FROM MAIN ST
SW85-529828-236863343	73m	73m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	02/07/2019	Awaiting CCMS Permanent	01/07/2019	A725 W/B ONSLIP FROM MAIN ST
SW85-529828-236863344	95m	95m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	02/07/2019	Awaiting CCMS Permanent	01/07/2019	A725 W/B ONSLIP FROM MAIN ST

Safety Inspection of A725 & A726 Glasgow East V1 on 01 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 08 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 15 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 22 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 29 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 05 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 12 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 19 August 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 26 August 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 02 September 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 09 September 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 16 September 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 23 September 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 30 September 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 07 October 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 14 October 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 21 October 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 28 October 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 04 November 2019**

SW85-536320-237072764	86m	86m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	05/11/2019	Completed Defects	04/11/2019	A725 WB ON FROM GLSGW RD
-----------------------	-----	-----	-------------	-----------------------	-------	------------	-------------------	------------	--------------------------

Safety Inspection of A725 & A726 Glasgow East V1 on 11 November 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 18 November 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 25 November 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 02 December 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 09 December 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 16 December 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 30 December 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 06 January 2020***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 13 January 2020***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 20 January 2020***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 27 January 2020**

SW85-538825-237248063	28m	28m	CARRIAGEWAY	Pothole (POTH)	CAT 1	24/02/2020	Completed Defects	06/02/2020	A725 SB @ ONSLIP FRM GLASGOW RD
-----------------------	-----	-----	-------------	----------------	-------	------------	-------------------	------------	---------------------------------

Safety Inspection of A725 & A726 Glasgow East V1 on 03 February 2020*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 10 February 2020***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 17 February 2020***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 24 February 2020**

SW85-544128-237284472	191m	191m	FENCES_AND_BARRIERS	Accident damage (ACCD)	CAT 1	23/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 SB BETWEEN GLASGOW RD ONSLIP - MAIN ST OFFSLIP
-----------------------	------	------	---------------------	------------------------	-------	------------	-------------------------	------------	---

SW85-544128-237284473	379m	379m	FENCES_AND_BARRIERS	Accident damage (ACCD)	CAT 1	23/03/2020	Awaiting CCMS Permanent	01/01/9999	A725 SB OPPOSITE MAIN ST. OFFSLIP @ CENTRAL RESERVATION
-----------------------	------	------	---------------------	------------------------	-------	------------	-------------------------	------------	---

Safety Inspection of A725 & A726 Glasgow East V1 on 02 March 2020*No defects recorded***15032/05 : WITH: GLASGOW RD ON SLIP TO CRAIGHEAD OFF SLIP**

Safety Inspection of A725 & A726 Tannochside V1 on 06 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 28 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 08 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 15 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 26 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 July 2017

SW85-282503-235265800	340m	0m	TRAFFIC_SIGNS	Obscured sign (OBSG)	CAT 1	18/07/2017	Completed Defects	17/07/2017	A725 EB 10M PRIOR TO CRAIGHEAD OFFSLIP TO WHISTLEBERRY
-----------------------	------	----	---------------	-------------------------	-------	------------	----------------------	------------	--

Safety Inspection of A725 & A726 Tannochside V1 on 24 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 31 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 07 August 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 14 August 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 21 August 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 28 August 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 04 September 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 11 September 2017

<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 18 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 25 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 02 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 09 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 16 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 23 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 30 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 06 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 13 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 20 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 26 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 04 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 11 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 18 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 22 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 29 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 05 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 08 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 15 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 22 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 29 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 05 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 12 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 19 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 26 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 05 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 12 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 19 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 26 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 29 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 05 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 09 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 16 April 2018									
SW85-338023-235657756	105m	0m	CARRIAGEWAY	Pothole VIAFIX	CAT 1	17/04/2018	Completed	17/04/2018	A725 EB EK EXPRESSWAY AT

				(POTV)			Defects		GLASGOW RD ONSLIP TO CRAIGHEAD OFFSLIP CENTRE LINE
SW85-338023-235657757	110m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	17/04/2018	Completed Defects	17/04/2018	A725 EB EK EXPRESSWAY GLASGOW RD ONSLIP TO CRAIGHEAD OFFSLIP CENTRE LINE
Safety Inspection of A725 & A726 Tannochside V1 on 23 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 30 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 04 May 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 11 May 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 14 May 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 21 May 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 28 May 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 04 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 11 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 18 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 25 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 02 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 09 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 16 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 23 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 30 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 06 August 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 13 August 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 20 August 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 27 August 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 03 September 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 10 September 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 17 September 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 24 September 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 01 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 08 October 2018									
SW85-418817-236111659	60m	64m	FENCES_AND_BARRIERS	Accident damage (ACCD)	CAT 1	05/11/2018	Completed Defects	09/01/2019	A725 GLASGOW ROAD ONSLIP TO CRAIGHEAD ON MAIN CARRIAGEWAY 100M BEFORE "DAVID LIVINGSTONE CENTRE" SIGN
SW85-418817-236111660	90m	90m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	09/10/2018	Completed Defects	08/10/2018	A725 ONSLIP E/B BETWEEN GLASGOW ROAD & CRAIGHEAD
SW85-418817-236111661	87m	87m	CARRIAGEWAY	Pothole VIAFIX	CAT 1	09/10/2018	Completed	08/10/2018	A725 AT ONSLIP BETWEEN

Safety Inspection of A725 & A726 Tannochside V1 on 15 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 November 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 November 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 November 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 26 November 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 31 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 07 January 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 14 January 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 21 January 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 28 January 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 04 February 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 11 February 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 18 February 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 25 February 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 04 March 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 11 March 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 18 March 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 25 March 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 01 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 08 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 15 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 18 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 26 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 29 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 13 May 2019

Safety Inspection of A725 & A726 Glasgow East V1 on 13 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 20 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 27 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 February 2020

SW85-541139-237284294	204m	204m	CARRIAGEWAY	Pothole (POTH)	CAT 1	18/02/2020	Awaiting CCMS Permanent	01/01/9999	A725 NB BETWEEN GLASGOW RD & CRAIGHEAD OFFSLIP
-----------------------	------	------	-------------	-------------------	-------	------------	----------------------------	------------	---

Safety Inspection of A725 & A726 Glasgow East V1 on 24 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 March 2020

No defects recorded

15032/25 : WITH: CRAIGHEAD OFF SLIP TO ON SLIP

Safety Inspection of A725 & A726 Tannochside V1 on 06 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 28 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 08 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 15 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 26 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 July 2017

Safety Inspection of A725 & A726 Tannochside V1 on 26 February 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 March 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 March 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 March 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 26 March 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 March 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 April 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 09 April 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 16 April 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 23 April 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 30 April 2018

SW85-342637-235669162	50m	50m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	01/05/2018	Completed Defects	30/04/2018	A725 OFFSLIP TO CRAIGHEAD ON SLIP
-----------------------	-----	-----	-------------	--------------------------	-------	------------	----------------------	------------	--------------------------------------

Safety Inspection of A725 & A726 Tannochside V1 on 04 May 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 11 May 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 14 May 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 21 May 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 28 May 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 04 June 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 11 June 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 18 June 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 25 June 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 02 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 09 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 16 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 23 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 30 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 September 2018

No defects recorded

<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 13 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 20 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 27 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 03 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 10 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 17 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 24 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 01 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 08 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 15 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 22 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 29 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 05 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 12 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 19 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 26 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 02 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 09 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 16 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 23 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 30 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 07 October 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 14 October 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 21 October 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 28 October 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 04 November 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 11 November 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 18 November 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 25 November 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 02 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 09 December 2019									
SW85-537396-237210692	257m	257m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	10/12/2019	Awaiting CCMS Permanent	01/01/9999	A725 E/B CRAIGHEAD TO 50 MPH SIGN BEFORE BOTHWELL OVERBRIDGE
Safety Inspection of A725 & A726 Glasgow East V1 on 16 December 2019									
<i>No defects recorded</i>									

Safety Inspection of A725 & A726 Glasgow East V1 on 30 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 06 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 13 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 20 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 27 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 March 2020

No defects recorded

15032/06 : AGAINST: OFF SLIP TO ON SLIP WHISTLEBERRY RD

Safety Inspection of A725 & A726 Tannochside V1 on 06 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 April 2017

SW85-260143-235074800	942m	942m	SAFETY_FENCE	Accident damage (ACCD)	CAT 1	08/05/2017	Completed Defects	10/04/2017	A725 SB BRIDGE OVER MAIN ST BLANTYRE
-----------------------	------	------	--------------	------------------------	-------	------------	-------------------	------------	--------------------------------------

Safety Inspection of A725 & A726 Tannochside V1 on 17 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 28 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 08 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 15 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 26 June 2017

<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 03 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 10 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 17 July 2017									
SW85-282503-235265801	1,150m	0m	TRAFFIC_SIGNS	Obscured sign (OBSG)	CAT 1	18/07/2017	Completed Defects	17/07/2017	A725 WB 100M PRIOR TO BLANTYRE OVERBRIDGE
Safety Inspection of A725 & A726 Tannochside V1 on 24 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 31 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 07 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 14 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 21 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 28 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 04 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 11 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 18 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 25 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 02 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 09 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 16 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 23 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 30 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 06 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 13 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 20 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 26 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 04 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 11 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 18 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 22 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 29 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 05 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 08 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 15 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 22 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 29 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 05 February 2018									

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 12 February 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 19 February 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 26 February 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 05 March 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 12 March 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 19 March 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 26 March 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 29 March 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 05 April 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 09 April 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 16 April 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 23 April 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 30 April 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 04 May 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 11 May 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 14 May 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 21 May 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 28 May 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 04 June 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 11 June 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 18 June 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 25 June 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 02 July 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 09 July 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 16 July 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 23 July 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 30 July 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 06 August 2018
SW85-389315-235930166 985m 965m FENCES_AND_BARRIERS Accident damage (ACCD) CAT 1 03/09/2018 Completed Defects 30/11/2018 A725 E/B GLASGOW RD ONSLIP TO CRAIGHEAD

Safety Inspection of A725 & A726 Tannochside V1 on 13 August 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 20 August 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 27 August 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 03 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 01 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 08 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 15 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 November 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 November 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 November 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 26 November 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 31 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 07 January 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 14 January 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 21 January 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 28 January 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 04 February 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 11 February 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 18 February 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 25 February 2019

SW85-434998-236328618	1,366m	1,366m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	26/02/2019	Completed Defects	25/02/2019	A725 WB ONSLIP FROM BLANTYRE TO WHIRLIES
-----------------------	--------	--------	-------------	-----------------------	-------	------------	-------------------	------------	--

Safety Inspection of A725 & A726 Glasgow East V1 on 04 March 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 11 March 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 18 March 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 25 March 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 01 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 08 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 15 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 18 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 26 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 29 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 13 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 20 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 27 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 June 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 June 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 June 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 June 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 01 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 08 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 15 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 22 July 2019

SW85-531470-236910742	1,354m	1,354m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	23/07/2019	Completed Defects	22/07/2019	A725 WB ON FROM GLSGW RD
-----------------------	--------	--------	-------------	-----------------------	-------	------------	-------------------	------------	--------------------------

SW85-531470-236910747	1,359m	1,359m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	23/07/2019	Completed Defects	22/07/2019	A725 WB GLSGW RD ON
-----------------------	--------	--------	-------------	-----------------------	-------	------------	-------------------	------------	---------------------

Safety Inspection of A725 & A726 Glasgow East V1 on 29 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 05 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 12 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 19 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 26 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 09 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 16 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 23 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 30 September 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 07 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 14 October 2019

SW85-535241-237054112	64m	64m	SAFETY_FENCE	Accident damage (ACCD)	CAT 1	11/11/2019	Completed Defects	03/11/2019	A725 WB 10M AFTER WHISTLEBERRY ONSLIP ON CENTRAL RES
-----------------------	-----	-----	--------------	------------------------	-------	------------	-------------------	------------	--

Safety Inspection of A725 & A726 Glasgow East V1 on 21 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 28 October 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 04 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 11 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 18 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 25 November 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 09 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 16 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 30 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 06 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 13 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 20 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 27 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 March 2020

SW85-547129-237302600	157m	157m	GULLY	Difference in component levels (ICLV)	CAT 1	30/03/2020	Awaiting CCMS Temp Date	01/01/9999	A725 SB BETWEEN WHISTLEBERRY OFFSLIP - ONSLIP FROM GLASGOW RD.
SW85-547129-237302601	518m	518m	GULLY	Difference in component levels (ICLV)	CAT 1	30/03/2020	Awaiting CCMS Temp Date	01/01/9999	A725 SB BETWEEN WHISTLEBERRY OFFSLIP - ONSLIP FROM GLASGOW RD.
SW85-547129-237302602	348m	348m	GULLY	Blockage (BLOK)	CAT 1	30/03/2020	Awaiting CCMS Temp Date	01/01/9999	A725 SB BETWEEN WHISTLEBERRY OFFSLIP - ONSLIP FROM GLASGOW RD.

15032/42 : With: Craighead on Slip to Opp Westbound Off Slip

Safety Inspection of A725 & A726 Tannochside V1 on 06 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 28 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 08 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 15 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 26 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 31 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 07 August 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 14 August 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 21 August 2017

SW85-283749-235321433

251m

0m

CARRIAGEWAY

Pothole
(POTH)

CAT 1

18/09/2017

Completed
Defects

21/08/2017

A725 EB CRAIGHEAD ONSLIP
ON MAIN C/WAY - BOTHWELL
OVERBRIDGE

Safety Inspection of A725 & A726 Tannochside V1 on 28 August 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 04 September 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 11 September 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 18 September 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 25 September 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 02 October 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 09 October 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 16 October 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 23 October 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 30 October 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 November 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 November 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 November 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 26 November 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 04 December 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 11 December 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 18 December 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 22 December 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 29 December 2017

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 05 January 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 08 January 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 15 January 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 22 January 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 29 January 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 05 February 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 12 February 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 19 February 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 26 February 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 05 March 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 12 March 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 19 March 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 26 March 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 29 March 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 05 April 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 09 April 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 16 April 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 23 April 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 30 April 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 04 May 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 11 May 2018
SW85-347336-235705984 207m 207m CARRIAGEWAY Pothole VIAFIX (POTV) CAT 1 12/05/2018 Completed Defects 12/05/2018 A725 CRAIGHEAD TO RAITH@ SIGN CENTRE LINE

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 14 May 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 21 May 2018
SW85-351720-235705987 386m 386m CARRIAGEWAY Pothole VIAFIX (POTV) CAT 1 22/05/2018 Completed Defects 22/05/2018 A725 W/B FROM CRAIGHEAD SLIP TO BOTHWELL BRIDGE @ ROAD SIGN ABOUT 400MTRS BEFORE OVERBRIDGE

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 28 May 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 04 June 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 11 June 2018

No defects recorded
Safety Inspection of A725 & A726 Tannochside V1 on 18 June 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 25 June 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 02 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 09 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 16 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 23 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 30 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 01 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 08 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 15 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 November 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 November 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 November 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 26 November 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 31 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 07 January 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 14 January 2019

SW85-428154-236270547

390m

390m

CARRIAGEWAY

Pothole
(POTH)

CAT 1

11/02/2019

Completed
Defects

31/01/2019

A725 BETWEEN CRAIGHEAD
ONSLIP & M8, BEFORE
BOTHWELL BRIDGE, OSL
NSWT

Safety Inspection of A725 & A726 Glasgow East V1 on 21 January 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 28 January 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 04 February 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 11 February 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 18 February 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 25 February 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 04 March 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 11 March 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 18 March 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 25 March 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 01 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 08 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 15 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 18 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 26 April 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 29 April 2019

SW85-500796-236613304	222m	222m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	30/04/2019	Completed Defects	30/04/2019	A725 NB BETWEEN CRAIGHEAD ONSLIP & BOTHWELL BRIDGE
SW85-500796-236613305	239m	239m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	30/04/2019	Completed Defects	30/04/2019	A725 NB BETWEEN CRAIGHEAD ONSLIP & BOTHWELL BRDGE

Safety Inspection of A725 & A726 Glasgow East V1 on 03 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 13 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 20 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 27 May 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 June 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 June 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 June 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 June 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 01 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 08 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 15 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 22 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 29 July 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 05 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 12 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 19 August 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 26 August 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 02 September 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 09 September 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 16 September 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 23 September 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 30 September 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 07 October 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 14 October 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 21 October 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 28 October 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 04 November 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 11 November 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 18 November 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 25 November 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 02 December 2019**

SW85-537189-237183955	348m	348m	STRUCTURE	Graffiti - Offensive (OFFS)	CAT 1	30/12/2019	Awaiting CCMS Permanent	01/01/9999	A725 AT BOTHWELL OVERBRIDGE
-----------------------	------	------	-----------	-----------------------------	-------	------------	-------------------------	------------	-----------------------------

Safety Inspection of A725 & A726 Glasgow East V1 on 09 December 2019

SW85-537396-237210693	20m	20m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	10/12/2019	Completed Defects	09/12/2019	A725 E/B FROM CRAIGHEAD TO 50 MPH SIGN BEFORE BOTHWELL OVERBRIDGE
-----------------------	-----	-----	-------------	-----------------------	-------	------------	-------------------	------------	---

SW85-537396-237210694	39m	39m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	10/12/2019	Completed Defects	09/12/2019	A725 E/B CRAIGHEAD TO 50MPH SIGN BEFORE BOTHWELL OVERBRIDGE
-----------------------	-----	-----	-------------	-----------------------	-------	------------	-------------------	------------	---

SW85-537396-237210695	67m	67m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	10/12/2019	Completed Defects	09/12/2019	A725 E/B CRAIGHEAD TO 50MPH SIGN BEFORE BOTHWELL OVERBRIDGE
-----------------------	-----	-----	-------------	-----------------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Glasgow East V1 on 16 December 2019

SW85-537603-237210870	372m	372m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/01/2020	Completed Defects	25/02/2020	A725 BETWEEN CRAIGHEAD SLIP - BOTHWELL BR
-----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	---

SW85-537603-237210871	385m	385m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/01/2020	Completed Defects	25/02/2020	A725 CRAIGHEAD SLIP- BOTHWELL BR.
-----------------------	------	------	-------------	----------------	-------	------------	-------------------	------------	-----------------------------------

Safety Inspection of A725 & A726 Glasgow East V1 on 30 December 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 06 January 2020***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 13 January 2020***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 20 January 2020***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 27 January 2020***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 03 February 2020***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 10 February 2020***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 17 February 2020***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 24 February 2020***No defects recorded*

Safety Inspection of A725 & A726 Glasgow East V1 on 02 March 2020

No defects recorded

15032/45 : With Opp Westbound Off Slip to M8PPP Boundary

Safety Inspection of A725 & A726 Tannochside V1 on 06 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 28 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 08 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 15 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 26 June 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 31 July 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 07 August 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 14 August 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 21 August 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 28 August 2017

SW85-283908-235333417

317m

0m

STRUCTURE

Graffiti -
Offensive

CAT 1

25/09/2017

Completed
Defects

09/09/2017

A725 EB UNDER BOTHWELL
OVERBRIDGE

(OFFS)

Safety Inspection of A725 & A726 Tannochside V1 on 04 September 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 11 September 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 18 September 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 25 September 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 02 October 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 09 October 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 16 October 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 23 October 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 30 October 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 November 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 November 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 November 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 26 November 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 04 December 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 11 December 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 18 December 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 December 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 29 December 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 January 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 08 January 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 15 January 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 22 January 2018

SW85-317755-235529041	65m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/02/2018	Completed Defects	23/01/2018	A725 EB APPROX 150M PRIOR TO BOTHWELL OVERBRIDGE LANE 1
SW85-317755-235529042	101m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/02/2018	Completed Defects	23/01/2018	A725 EB APPROX 120M PRIOR TO BOTHWELL OVERBRIDGE LANE 2

Safety Inspection of A725 & A726 Tannochside V1 on 29 January 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 February 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 February 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 February 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 26 February 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 March 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 March 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 19 March 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 26 March 2018

<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 29 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 05 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 09 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 16 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 23 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 30 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 04 May 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 11 May 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 14 May 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 21 May 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 28 May 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 04 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 11 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 18 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 25 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 02 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 09 July 2018									
SW85-375960-235871402	0m	0m	TRAFFIC_SIGNS	Accident damage (ACCD)	CAT 1	06/08/2018	Completed Defects	09/07/2018	A725 W/B @ CRAIGHEAD ONSLIP TO RAITH R/A @ ISLAND
Safety Inspection of A725 & A726 Tannochside V1 on 16 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 23 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 30 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 06 August 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 13 August 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 20 August 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 27 August 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 03 September 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 10 September 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 17 September 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 24 September 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 01 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 08 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 15 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 22 October 2018									
<i>No defects recorded</i>									

Safety Inspection of A725 & A726 Tannochside V1 on 29 October 2018*No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 05 November 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 12 November 2018***No defects recorded***Safety Inspection of A725 & A726 Tannochside V1 on 19 November 2018***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 26 November 2018***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 03 December 2018***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 10 December 2018***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 17 December 2018***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 24 December 2018***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 31 December 2018***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 07 January 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 14 January 2019**

SW85-428154-236270548	88m	88m	CARRIAGEWAY	Pothole (POTH)	CAT 1	11/02/2019	Completed Defects	31/01/2019	A725 BETWEEN CRAIGHEAD ONSLIP & M8, BEFORE BOTHWELL BRIDGE, OSL NSWT
-----------------------	-----	-----	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A725 & A726 Glasgow East V1 on 21 January 2019

SW85-428297-236283779	14m	14m	CARRIAGEWAY	Pothole (POTH)	CAT 1	18/02/2019	Awaiting CCMS Permanent	01/01/9999	A725 FROM CRAIGHEAD TO RAITH INTERCHANGE LANE 2 NSWT
-----------------------	-----	-----	-------------	----------------	-------	------------	-------------------------	------------	--

Safety Inspection of A725 & A726 Glasgow East V1 on 28 January 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 04 February 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 11 February 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 18 February 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 25 February 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 04 March 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 11 March 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 18 March 2019**

SW85-450767-236466931	35m	35m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	19/03/2019	Completed Defects	19/03/2019	A725 NB 100M PRIOR TO BOTHWELL BRIDGE @ TEMP 50MPH SIGN
-----------------------	-----	-----	-------------	-----------------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Glasgow East V1 on 25 March 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 01 April 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 08 April 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 15 April 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 18 April 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 26 April 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 29 April 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 03 May 2019**

SW85-504794-236617194	58m	58m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/05/2019	Completed Defects	04/05/2019	A725 SB AFTER BOTHWELL BRIDGE OSL PRIOR TO 60MPH
-----------------------	-----	-----	-------------	-----------------------	-------	------------	-------------------	------------	--

Safety Inspection of A725 & A726 Glasgow East V1 on 10 May 2019										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Glasgow East V1 on 13 May 2019										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Glasgow East V1 on 20 May 2019										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Glasgow East V1 on 27 May 2019										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Glasgow East V1 on 03 June 2019										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Glasgow East V1 on 10 June 2019										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Glasgow East V1 on 17 June 2019										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Glasgow East V1 on 24 June 2019										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Glasgow East V1 on 01 July 2019										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Glasgow East V1 on 08 July 2019										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Glasgow East V1 on 15 July 2019										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Glasgow East V1 on 22 July 2019										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Glasgow East V1 on 29 July 2019										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Glasgow East V1 on 05 August 2019										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Glasgow East V1 on 12 August 2019										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Glasgow East V1 on 19 August 2019										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Glasgow East V1 on 26 August 2019										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Glasgow East V1 on 02 September 2019										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Glasgow East V1 on 09 September 2019										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Glasgow East V1 on 16 September 2019										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Glasgow East V1 on 23 September 2019										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Glasgow East V1 on 30 September 2019										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Glasgow East V1 on 07 October 2019										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Glasgow East V1 on 14 October 2019										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Glasgow East V1 on 21 October 2019										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Glasgow East V1 on 28 October 2019										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Glasgow East V1 on 04 November 2019										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Glasgow East V1 on 11 November 2019										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Glasgow East V1 on 18 November 2019										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Glasgow East V1 on 25 November 2019										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Glasgow East V1 on 02 December 2019										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Glasgow East V1 on 09 December 2019										
<i>No defects recorded</i>										
Safety Inspection of A725 & A726 Glasgow East V1 on 16 December 2019										
SW85-537603-237210872	18m	18m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/01/2020	Completed Defects	25/02/2020	A725 CRAIGHEAD-BOTHWELL BR.	

SW85-537603-237210869	7m	7m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/01/2020	Completed Defects	25/02/2020	A725 BETWEEN CRAIGHEAD SLIP & BOTHWELL BRIDGE, PRIOR TO OVERBRIDGE
-----------------------	----	----	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A725 & A726 Glasgow East V1 on 30 December 2019

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 06 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 13 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 20 January 2020

SW85-538602-237243168	0m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	17/02/2020	Awaiting CCMS Permanent	01/01/9999	A726 EB BTWN EAGLESHAM RBT - WEST MAINS RBT
-----------------------	----	----	-------------	----------------	-------	------------	-------------------------	------------	---

Safety Inspection of A725 & A726 Glasgow East V1 on 27 January 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 03 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 10 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 February 2020

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 02 March 2020

No defects recorded

15032/61 : Against: M8PPP Boundary to Whistleberry Road

Safety Inspection of A725 & A726 Tannochside V1 on 06 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 February 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 20 March 2017

SW85-253495-235071845	329m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	17/04/2017	Completed Defects	07/04/2017	A725 WB FROM WHISTLEBERRY 200M PAST BOTHWELL OVERBRIDGE LANE 1 OS WT
-----------------------	------	----	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A725 & A726 Tannochside V1 on 27 March 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 28 April 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 08 May 2017

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 15 May 2017

SW85-272660-235157446	415m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/06/2017	Completed Defects	09/06/2017	A725 NB BETWEEN BOTHWELL OVERBRIDGE TO WHISTLEBERRY LANE 2 OS WT
-----------------------	------	----	-------------	----------------	-------	------------	-------------------	------------	--

Safety Inspection of A725 & A726 Tannochside V1 on 22 May 2017

No defects recorded

SW85-317422-235515698	302m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/02/2018	Completed Defects	24/01/2018	A725 WB 150M PAST BOTHWELL OVERBRIDGE LANE 1 OS WT
Safety Inspection of A725 & A726 Tannochside V1 on 15 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 22 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 29 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 05 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 12 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 19 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 26 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 05 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 12 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 19 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 26 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 29 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 05 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 09 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 16 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 23 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 30 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 04 May 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 11 May 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 14 May 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 21 May 2018									
SW85-351720-235705984	176m	17m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	22/05/2018	Completed Defects	21/05/2018	A725 FROM RAITH TO WHISTLEBERRY OFFSLIP
SW85-351720-235705985	25m	25m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	22/05/2018	Completed Defects	21/05/2018	A725 @BOTHWELL BRIDGE ON N/S/L
Safety Inspection of A725 & A726 Tannochside V1 on 28 May 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 04 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 11 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 18 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 25 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 02 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 09 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 16 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Tannochside V1 on 23 July 2018									
SW85-382484-235917033	82m	82m	TREE	Overhanging/o	CAT 2	01/01/9999	Cat 2 Awaiting	01/01/9999	A725

vergrown
(OVER)

Action

Safety Inspection of A725 & A726 Tannochside V1 on 30 July 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 06 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 13 August 2018

SW85-392547-235950820	75m	75m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	14/08/2018	Completed Defects	14/08/2018	A725 CRAIGHEAD TO RAITH @BOTHWELL BRIDGE HALF WAY ON BRIDGE O/S/RIBLINE
-----------------------	-----	-----	-------------	-----------------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Tannochside V1 on 20 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 27 August 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 03 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 10 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 17 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 24 September 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 01 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 08 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 15 October 2018

SW85-422048-236141658	21m	21m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/10/2018	Completed Defects	15/10/2018	A725 W/B ON BOTHWELL BRIDGE
-----------------------	-----	-----	-------------	-----------------------	-------	------------	-------------------	------------	-----------------------------

Safety Inspection of A725 & A726 Tannochside V1 on 22 October 2018

SW85-425292-236143463	211m	211m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	23/10/2018	Completed Defects	22/10/2018	A725 40M BEYOND OVERBRIDGE TO WHISTLEBERRY SLIP ON LANE 1 O/S/W/T
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	---

SW85-425292-236143464	256m	256m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	23/10/2018	Completed Defects	22/10/2018	A725 60M BEYOND OVERBRIDGE TO WHISTLEBERRY SLIP ON LANE 1 O/S/W/T
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Tannochside V1 on 29 October 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 05 November 2018

No defects recorded

Safety Inspection of A725 & A726 Tannochside V1 on 12 November 2018

SW85-426526-236228414	51m	51m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	13/11/2018	Completed Defects	12/11/2018	A725 NB TO WHISTLEBERRY SLIP @ BRIDGE
-----------------------	-----	-----	-------------	-----------------------	-------	------------	-------------------	------------	---------------------------------------

Safety Inspection of A725 & A726 Tannochside V1 on 19 November 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 26 November 2018

SW85-426838-236228414	386m	386m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	27/11/2018	Completed Defects	27/11/2018	A725 TO WHISTLEBERRY OFF SLIP NSL NSWT
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	--

SW85-426838-236228415	384m	384m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	27/11/2018	Completed Defects	27/11/2018	A725 TO WHISTLEBERRY SLIP NSL OSWT
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	------------------------------------

Safety Inspection of A725 & A726 Glasgow East V1 on 03 December 2018

SW85-427123-236235025	36m	36m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/12/2018	Completed Defects	03/12/2018	A725 RAITH TO CRAIGHEAD @ BOTHWELL OVERBRIDGE N/S/L
-----------------------	-----	-----	-------------	-----------------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Glasgow East V1 on 10 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 17 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 24 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 31 December 2018

No defects recorded

Safety Inspection of A725 & A726 Glasgow East V1 on 07 January 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 14 January 2019**

SW85-428154-236270541	330m	330m	CARRIAGEWAY	Pothole (POTH)	CAT 1	11/02/2019	Completed Defects	01/02/2019	A725 WB BETWEEN BOTHWELL BRIDGE TO CRAIGHEAD SLIP LANE 1
SW85-428154-236270542	414m	414m	CARRIAGEWAY	Pothole (POTH)	CAT 1	11/02/2019	Completed Defects	01/02/2019	A725 WB BETWEEN BOTHWELL BRIDGE & CRAIGHEAD SLIP LANE 2
SW85-428154-236270543	470m	470m	CARRIAGEWAY	Pothole (POTH)	CAT 1	11/02/2019	Completed Defects	01/02/2019	A725 WB BETWEEN BOTHWELL BRIDGE & CRAIGHEAD SLIP

Safety Inspection of A725 & A726 Glasgow East V1 on 21 January 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 28 January 2019**

SW85-428544-236286474	25m	25m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	29/01/2019	Awaiting CCMS Permanent	28/01/2019	A725 ON BOTHWELL BRIDGE NSL OSWT
-----------------------	-----	-----	-------------	-----------------------	-------	------------	-------------------------	------------	----------------------------------

Safety Inspection of A725 & A726 Glasgow East V1 on 04 February 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 11 February 2019**

SW85-429789-236315515	25m	25m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	12/02/2019	Awaiting CCMS Permanent	01/01/9999	A725 WB ON BOTHWELL BRIDGE
-----------------------	-----	-----	-------------	-----------------------	-------	------------	-------------------------	------------	----------------------------

Safety Inspection of A725 & A726 Glasgow East V1 on 18 February 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 25 February 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 04 March 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 11 March 2019**

SW85-444815-236365168	45m	45m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	12/03/2019	Completed Defects	11/03/2019	A725 SB BOTHWELL BRIDGE
SW85-444815-236365169	23m	23m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	12/03/2019	Completed Defects	11/03/2019	A725 SB @ BOTHWELL BRIDGE

Safety Inspection of A725 & A726 Glasgow East V1 on 18 March 2019

SW85-450767-236466921	39m	39m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/04/2019	Completed Defects	19/03/2019	A725 SB @ BOTHWELL BRIDGE
-----------------------	-----	-----	-------------	----------------	-------	------------	-------------------	------------	---------------------------

Safety Inspection of A725 & A726 Glasgow East V1 on 25 March 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 01 April 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 08 April 2019**

SW85-472843-236487668	51m	51m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	09/04/2019	Completed Defects	09/04/2019	A725 SB @ BOTHWELL BRIDGE NSL
-----------------------	-----	-----	-------------	-----------------------	-------	------------	-------------------	------------	-------------------------------

Safety Inspection of A725 & A726 Glasgow East V1 on 15 April 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 18 April 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 26 April 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 29 April 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 03 May 2019**

SW85-504794-236617195	338m	338m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/05/2019	Completed Defects	04/05/2019	A725 SB AFTER BOTHWELL BRIDGE LANE 1
-----------------------	------	------	-------------	-----------------------	-------	------------	-------------------	------------	--------------------------------------

Safety Inspection of A725 & A726 Glasgow East V1 on 10 May 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 13 May 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 20 May 2019***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 27 May 2019**

<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 03 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 10 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 17 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 24 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 01 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 08 July 2019									
SW85-530970-236893004	246m	246m	TRAFFIC_SIGNS	Obscured sign (OBSG)	CAT 1	09/07/2019	Completed Defects	08/07/2019	A725 WB BETWEEN BOTHWELL BR. & WHISTLEBERRY SLIP
Safety Inspection of A725 & A726 Glasgow East V1 on 15 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 22 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 29 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 05 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 12 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 19 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 26 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 02 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 09 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 16 September 2019									
SW85-534029-237014768	347m	347m	TRAFFIC_SIGNS	Obscured sign (OBSG)	CAT 1	14/10/2019	Completed Defects	08/10/2019	A725 WB BETWEEN BOTHWELL BRIDGE - WHISTLEBERRY OFFSLIP
SW85-534029-237014769	438m	438m	TRAFFIC_SIGNS	Obscured sign (OBSG)	CAT 1	14/10/2019	Completed Defects	08/10/2019	A725 WB BETWEEN BOTHWELL BRIDGE - WHISTLEBERRY OFFSLIP
Safety Inspection of A725 & A726 Glasgow East V1 on 23 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 30 September 2019									
SW85-534645-237034233	13m	13m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	01/10/2019	Completed Defects	30/09/2019	A725 WB ON BOTHWELL BRIDGE
Safety Inspection of A725 & A726 Glasgow East V1 on 07 October 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 14 October 2019									
SW85-535241-237054111	25m	25m	CARRIAGEWAY	Pothole (POTH)	CAT 1	11/11/2019	Completed Defects	15/10/2019	A725 WB ON BOTHWELL BRIDGE
Safety Inspection of A725 & A726 Glasgow East V1 on 21 October 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 28 October 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 04 November 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 11 November 2019									
<i>No defects recorded</i>									
Safety Inspection of A725 & A726 Glasgow East V1 on 18 November 2019									
SW85-536773-237162892	343m	343m	GULLY	Missing (MISS)	CAT 1	16/12/2019	Completed Defects	05/02/2020	A725 WB BETWEEN BOTHWELL BRIDGE - WHISTLEBERRY OFF, OS
Safety Inspection of A725 & A726 Glasgow East V1 on 25 November 2019									
<i>No defects recorded</i>									

Safety Inspection of A725 & A726 Glasgow East V1 on 02 December 2019

SW85-537189-237183950	8m	8m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	03/12/2019	Completed Defects	03/12/2019	A725 ON BOTHWELL BRIDGE
-----------------------	----	----	-------------	-----------------------	-------	------------	-------------------	------------	-------------------------

Safety Inspection of A725 & A726 Glasgow East V1 on 09 December 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 16 December 2019**

SW85-537603-237210873	506m	506m	FENCES_AND_BARRIERS	Accident damage (ACCD)	CAT 1	13/01/2020	Completed Defects	23/01/2020	A725 SB @ BEGINING WHISTLEBERRY OFFSLIP
-----------------------	------	------	---------------------	------------------------	-------	------------	-------------------	------------	---

Safety Inspection of A725 & A726 Glasgow East V1 on 30 December 2019*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 06 January 2020***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 13 January 2020***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 20 January 2020***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 27 January 2020***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 03 February 2020**

SW85-539154-237252889	37m	37m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/03/2020	Awaiting CCMS Temp Date	01/01/9999	A725 SB BOTHWELL BRIDGE
-----------------------	-----	-----	-------------	----------------	-------	------------	-------------------------	------------	-------------------------

Safety Inspection of A725 & A726 Glasgow East V1 on 10 February 2020*No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 17 February 2020***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 24 February 2020***No defects recorded***Safety Inspection of A725 & A726 Glasgow East V1 on 02 March 2020***No defects recorded*

