

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/11/2019 and 12/12/2019, and defects raised outside of inspections on the same Section(s) during this period.

(Road is 'M90'.)
(Section Code is 15530/71)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
15530/71 : AGAINST: ENTRY SLIP FROM A912 TO GLENFARG OBRIDGE									
Safety Patrol of M90 & A92 Safety on 01 November 2019									
NE122535943-237068497	8,033m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	02/11/2019	Completed Defects	01/11/2019	31/9 +40 JUST BEFORE GLENFARG OVERBRIDGE S/B
NE122535943-237068498	8,311m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	29/11/2019	Completed Defects	21/11/2019	31/6 +45 @ GLENFARG OVERBRIDGE S/B
Safety Inspection of M90 & A92 Safety on 05 November 2019									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 08 November 2019									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 12 November 2019									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 15 November 2019									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 19 November 2019									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 22 November 2019									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 26 November 2019									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 29 November 2019									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 03 December 2019									
<i>No defects recorded</i>									
Safety Patrol of M90 & A92 Safety on 06 December 2019									
<i>No defects recorded</i>									
Safety Inspection of M90 & A92 Safety on 10 December 2019									
<i>No defects recorded</i>									