

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/01/2017 and 12/05/2020, and defects raised outside of inspections on the same Section(s) during this period.

(Section Code is 16540/34) Or

(Section Code is 16540/50) Or

(Section Code is 16540/71)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
16540/34 : NURSERY COTTAGES ACCESS TO ABHAINN MHOR BRIDG									
Safety Inspection of A83 Safety Inverary - Campbeltown on 05 January 2017									
NWG5228631-235030196	792m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	06/01/2017	Completed Defects	05/01/2017	KILMICHAEL BEG BENDS, W/B C/WAY
Safety Inspection of A83 Safety Inverary - Campbeltown on 12 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 19 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 26 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 02 February 2017									
NWG5240365-235046133	647m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/03/2017	Completed Defects	08/03/2017	KILMICHAEL BENDS, E/B C/WAY
Safety Inspection of A83 Safety Inverary - Campbeltown on 09 February 2017									
NWG5242681-235053124	715m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	10/02/2017	Completed Defects	09/02/2017	KILMICHAEL BENDS, W/B C/WAY
Safety Inspection of A83 Safety Inverary - Campbeltown on 16 February 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 23 February 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 02 March 2017									
NWG21246823-235058771	672m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	03/03/2017	Completed Defects	02/03/2017	KILMICHAEL BEG BENDS, E/B C/WAY
NWG21246823-235058772	795m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	03/03/2017	Completed Defects	02/03/2017	KILMICHAEL BEG BENDS, W/B C/WAY
NWG21246823-235058773	802m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	03/03/2017	Completed Defects	02/03/2017	KILMICHAEL BEG BENDS, W/B C/WAY
NWG21246823-235058774	830m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	03/03/2017	Completed Defects	02/03/2017	KILMICHAEL BEG BENDS, W/B C/WAY
Safety Inspection of A83 Safety Inverary - Campbeltown on 09 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 16 March 2017									
NWG21250946-235068446	635m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/04/2017	Completed Defects	13/04/2017	KILMICHAEL BEG BENDS, E/B C/WAY
Safety Inspection of A83 Safety Inverary - Campbeltown on 23 March 2017									
NWG21252930-235072796	2,678m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	24/03/2017	Completed Defects	23/03/2017	WEST SIDE OF ARDCASTLE ACCESS, E/B C/WAY
NWG21252930-235072797	2,736m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/04/2017	Completed Defects	20/04/2017	WEST SIDE OF ARDCASTLE ACCESS, E/B C/WAY
NWG21252930-235072798	2,533m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	24/03/2017	Completed Defects	23/03/2017	EAST SIDE OF ARDCASTLE ACCESS, E/B C/WAY
Safety Inspection of A83 Safety Inverary - Campbeltown on 30 March 2017									
NWG21254941-235072799	801m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	31/03/2017	Completed Defects	30/03/2017	KILMICHAEL BEG BENDS, W/B C/WAY

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A83 Safety Inverary - Campbeltown on 06 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 13 April 2017									
NWG21259618-235075695	666m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	14/04/2017	Completed Defects	13/04/2017	KILMICHAEL BENDS, E/B C/WAY
NWG21259618-235075696	679m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	14/04/2017	Completed Defects	13/04/2017	KILMICHAEL BENDS, E/B C/WAY
NWG21259618-235075697	717m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	14/04/2017	Completed Defects	13/04/2017	KILMICHAEL BENDS, W/B C/WAY
NWG21259618-235075698	793m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	14/04/2017	Completed Defects	13/04/2017	KILMICHAEL BENDS, W/B C/WAY
NWG21259618-235075700	3,694m	0m	GRIP	Flood nuisance to properties (NPRP)	CAT 1	11/05/2017	Completed Defects	24/04/2017	EAST SIDE OF BEECH COTTAGE ACCESS, EAST OF LOCHGAIR. (W/B VERGE)
Safety Inspection of A83 Safety Inverary - Campbeltown on 20 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 27 April 2017									
NWG21263621-235096402	2,527m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	28/04/2017	Completed Defects	23/05/2017	JUST EAST OF ARDCASTLE ACCESS, E/B C/WAY
Safety Inspection of A83 Safety Inverary - Campbeltown on 04 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 11 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 18 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 25 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 01 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 08 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 15 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 22 June 2017									
NW31280288-235211678	4,046m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	23/06/2017	Completed Defects	22/06/2017	JUST WEST OF ASKNISH COTTAGE ACCESS, W/B C/WAY.
NW31280288-235211679	4,090m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 1	20/07/2017	Completed Defects	20/07/2017	JUST WEST OF ASKNISH COTTAGE ACCESS, W/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 29 June 2017									
<i>No defects recorded</i>									
Detailed Inspection TEMPLATE of A83 SHIRA BRIDGE TO A83 C43 (BRAE ROAD) JUNCTION on 20 June 2017									
NW80253085-427	3,524m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST WEST OF ARDCASTLE ACCESS, E/B C/WAY.
NW80253085-428	3,647m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	11/09/2019	GORTONRONACH STRAIGHT, W/B C/WAY.
NW80253085-429	3,143m	0m	GRIP	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	GORTONRONACH STRAIGHT, W/B VERGE
NW80253085-430	3,108m	0m	GRIP	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	GORTONRONACH STRAIGHT, E/B VERGE
NW80253085-397	754m	0m	BOLLARDS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	KILMICHAEL BEG BENDS, W/B VERGE.
NW80253085-398	578m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	KILMICHAEL BEG BENDS, E/B C/WAY.

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW80253085-399	481m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	KILMICHAEL BEG BENDS, W/B CWAY.
NW80253085-400	527m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	KILMICHAEL BEG BENDS, E/B VERGE.
NW80253085-401	474m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	KILMICHAEL BEG BENDS, E/B CWAY.
NW80253085-402	561m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	KILMICHAEL BEG BENDS, E/B CWAY.
NW80253085-403	1,823m	0m	BOLLARDS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF KILMICHAEL BEG, W/B VERGE.
NW80253085-404	1,594m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF KILMICHAEL BEG, W/B VERGE.
NW80253085-405	2,729m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST WEST OF ARDCASTLE ACCESS, W/B CWAY.
NW80253085-406	2,829m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST WEST OF ARDCASTLE ACCESS, W/B CWAY.
NW80253085-407	2,929m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST WEST OF ARDCASTLE ACCESS, W/B CWAY.
NW80253085-408	2,724m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST WEST OF ARDCASTLE ACCESS, E/B CWAY.
NW80253085-409	2,824m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST WEST OF ARDCASTLE ACCESS, E/B CWAY.
NW80253085-410	2,924m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST WEST OF ARDCASTLE ACCESS, E/B CWAY.
NW80253085-411	3,024m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST WEST OF ARDCASTLE ACCESS, E/B CWAY.
NW80253085-412	2,690m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF ARDCASTLE ACCESS, W/B CWAY.
NW80253085-413	2,782m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST WEST OF ARDCASTLE ACCESS, W/B CWAY.
NW80253085-414	2,708m	0m	GRIP	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF ARDCASTLE ACCESS, W/B VERGE.
NW80253085-415	2,838m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST WEST OF ARDCASTLE ACCESS, W/B CWAY.
NW80253085-416	2,852m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST WEST OF ARDCASTLE ACCESS, W/B CWAY.
NW80253085-417	2,699m	0m	GRIP	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF ARDCASTLE ACCESS, E/B VERGE.

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW80253085-418	2,875m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST WEST OF ARDCASTLE ACCESS, W/B CWAY.
NW80253085-419	2,695m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF ARDCASTLE ACCESS, E/B CWAY.
NW80253085-420	2,691m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF ARDCASTLE ACCESS, E/B CWAY.
NW80253085-421	2,690m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF ARDCASTLE ACCESS, E/B CWAY.
NW80253085-422	2,688m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF ARDCASTLE ACCESS, E/B CWAY.
NW80253085-423	3,124m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST WEST OF ARDCASTLE ACCESS, E/B CWAY.
NW80253085-424	3,224m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST WEST OF ARDCASTLE ACCESS, E/B CWAY.
NW80253085-425	3,324m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST WEST OF ARDCASTLE ACCESS, E/B CWAY.
NW80253085-426	3,424m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST WEST OF ARDCASTLE ACCESS, E/B CWAY.
NW80253085-431	3,692m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	11/09/2019	GORTONRONACH STRAIGHT, W/B CWAY.
NW80253085-432	3,720m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	GORTONRONACH STRAIGHT, E/B CWAY.
NW80253085-433	4,198m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST EAST OF GLASHAN BURN ACCESS, E/B VERGE.
NW80253085-434	4,219m	0m	VERGE	Dead, dying or damaged areas (DPDY)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST EAST OF GLASHAN BURN ACCESS, E/B VERGE.
NW80253085-435	3,867m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST EAST OF GLASHAN BURN ACCESS, E/B CWAY.
NW80253085-436	4,137m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST EAST OF GLASHAN BURN ACCESS, W/B CWAY.
NW80253085-437	4,129m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST EAST OF GLASHAN BURN ACCESS, W/B CWAY.
NW80253085-438	4,141m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST EAST OF GLASHAN BURN ACCESS, W/B CWAY.
NW80253085-439	4,099m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST EAST OF GLASHAN BURN ACCESS, W/B CWAY.

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW80253085-440	4,158m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST EAST OF GLASHAN BURN ACCESS, W/B C/WAY.
NW80253085-441	4,211m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST EAST OF GLASHAN BURN ACCESS, W/B C/WAY.
NW80253085-442	4,230m	0m	CARRIAGEWAY	Patch - material cracking (PMCK)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST EAST OF GLASHAN BURN ACCESS, W/B C/WAY.
NW80253085-443	4,230m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST EAST OF GLASHAN BURN ACCESS, W/B C/WAY.
NW80253085-444	4,230m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST EAST OF GLASHAN BURN ACCESS, W/B C/WAY.
NW80253085-445	4,240m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	EAST SIDE OF GLASHAN BURN ACCESS, W/B C/WAY.

Annual Detailed Inspection - Carriageways of A83 SHIRA BRIDGE TO A83 C43 (BRAE ROAD) JUNCTION

No defects recorded

Detailed Inspection - Covers, Gratings and Frames of A83 SHIRA BRIDGE TO A83 C43 (BRAE ROAD) JUNCTION

No defects recorded

Detailed Inspection - Kerbs, Channels, Edgings of A83 SHIRA BRIDGE TO A83 C43 (BRAE ROAD) JUNCTION

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 06 July 2017

NWG30-281800-235255902	2,970m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	07/07/2017	Completed Defects	06/07/2017	JUST WEST OF ARDCASTLE, W/B C/WAY.
------------------------	--------	----	-------------	-----------------------	-------	------------	-------------------	------------	------------------------------------

Safety Inspection of A83 Safety Inverary - Campbeltown on 13 July 2017

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 20 July 2017

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 27 July 2017

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 03 August 2017

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown (Awaiting Return)

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 17 August 2017

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 24 August 2017

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 31 August 2017

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 07 September 2017

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 14 September 2017

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 21 September 2017

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 28 September 2017

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 05 October 2017

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 12 October 2017

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 19 October 2017

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 26 October 2017

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 02 November 2017

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 09 November 2017

No defects recorded



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A83 Safety Inverary - Campbeltown on 16 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 23 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 30 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 07 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 14 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 21 December 2017									
NWG11316951-235496247	537m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	18/01/2018	Completed Defects	18/01/2018	EAST SIDE OF KILMICHAEL BEG BENDS, E/B C/WAY
Safety Inspection of A83 Safety Inverary - Campbeltown on 28 December 2017									
NWG11317071-235512886	4,037m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	29/12/2017	Completed Defects	28/12/2017	JUST EAST OF LOCHGAIR, W/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 04 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 11 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 18 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 25 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 01 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 08 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 14 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 21 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 28 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 07 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 14 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 21 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 28 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 04 April 2018									
NW122332659-235615928	4,052m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	05/04/2018	Completed Defects	04/04/2018	JUST EAST OF LOCHGAIR, W/B C/WAY.
NW122332659-235615929	4,042m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	05/04/2018	Completed Defects	04/04/2018	JUST EAST OF LOCHGAIR, W/B C/WAY.
NW122332659-235615930	4,040m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	05/04/2018	Completed Defects	04/04/2018	JUST EAST OF LOCHGAIR, E/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown (Awaiting Return)									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 18 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 25 April 2018									
NW122339456-235662632	538m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	26/04/2018	Completed Defects	25/04/2018	KILMICHAEL BENDS, E/B C/WAY.
NW122339456-235662633	539m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	26/04/2018	Completed Defects	25/04/2018	KILMICHAEL BENDS, E/B C/WAY.
NW122339456-235662634	546m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	26/04/2018	Completed Defects	25/04/2018	KILMICHAEL BENDS, E/B C/WAY.

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW122339456-235662635	547m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	26/04/2018	Completed Defects	25/04/2018	KILMICHAEL BENDS, E/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 02 May 2018									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 09 May 2018									
NW33344801-235712588	4,117m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	10/05/2018	Completed Defects	09/05/2018	GLASHAN BURN, W/B C/WAY.
NW33344801-235712589	4,114m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	10/05/2018	Completed Defects	09/05/2018	GLASHAN BURN, E/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 16 May 2018									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 23 May 2018									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 30 May 2018									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 06 June 2018									
NW122357180-235825591	3,589m	0m	CATCHPIT	Missing (MISS)	CAT 1	04/07/2018	Completed Defects	15/06/2018	GORTONRONACH ACCESS, EAST OF LOCHGAIR. (E/B VERGE)
Detailed Inspection TEMPLATE of A83 SHIRA BRIDGE TO A83 C43 (BRAE ROAD) JUNCTION on 30 April 2018									
NWG11328946-969	711m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B VERGE)
NWG11328946-970	649m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B VERGE)
NWG11328946-971	576m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN MINARD WEST 40MPH SIGNS & NURSERY COTTAGES ACCESS. (W/B C/WAY)
NWG11328946-972	564m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (E/B C/WAY)
NWG11328946-973	560m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (E/B C/WAY)
NWG11328946-974	558m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (E/B C/WAY)
NWG11328946-975	525m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B C/WAY)
NWG11328946-976	517m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (E/B C/WAY)
NWG11328946-977	505m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (E/B VERGE)
NWG11328946-978	485m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (E/B C/WAY)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG11328946-979	465m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (CENTRE LINE)
NWG11328946-980	418m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B C/WAY)
NWG11328946-981	366m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B C/WAY)
NWG11328946-982	272m	0m	VERGE	Dead, dying or damaged areas (DPDY)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B VERGE)
NWG11328946-983	277m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (E/B C/WAY)
NWG11328946-984	266m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (E/B C/WAY)
NWG11328946-985	201m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (E/B C/WAY)
NWG11328946-986	157m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B C/WAY)
NWG11328946-987	149m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (CENTRE LINE)
NWG11328946-988	90m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B C/WAY)
NWG11328946-989	170m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B C/WAY)
NWG11328946-990	232m	0m	Culvert	Free flow impeded (FRFL)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	230M WEST OF NURSERY COTTAGES ACCESS. (E/B VERGE)
NWG11328946-991	456m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B C/WAY)
NWG11328946-992	547m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (E/B C/WAY)
NWG11328946-993	1,541m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (E/B VERGE)
NWG11328946-994	1,515m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B VERGE)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG11328946-995	1,526m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B VERGE)
NWG11328946-996	1,828m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B VERGE)
NWG11328946-997	1,831m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B VERGE)
NWG11328946-998	2,004m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B VERGE)
NWG11328946-999	2,697m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B C/WAY)
NWG11328946-1000	2,704m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (E/B C/WAY)
NWG11328946-1001	2,704m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B C/WAY)
NWG11328946-1002	2,704m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (E/B C/WAY)
NWG11328946-1003	2,761m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B VERGE)
NWG11328946-1004	2,863m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B C/WAY)
NWG11328946-1005	2,905m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B C/WAY)
NWG11328946-1006	3,033m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B C/WAY)
NWG11328946-1007	3,088m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B C/WAY)
NWG11328946-1008	3,139m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B VERGE)
NWG11328946-1009	3,207m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B C/WAY)
NWG11328946-1010	3,258m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B C/WAY)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG11328946-1011	3,371m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B C/WAY)
NWG11328946-1012	3,358m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (E/B C/WAY)
NWG11328946-1013	3,100m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (E/B C/WAY)
NWG11328946-1014	2,762m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (E/B C/WAY)
NWG11328946-1015	3,600m	0m	BOLLARDS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	OUTSIDE GORTONRONACH ACCESS, E/B VERGE.
NWG11328946-1016	3,623m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B C/WAY)
NWG11328946-1017	3,524m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B C/WAY)
NWG11328946-1018	3,654m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B C/WAY)
NWG11328946-1019	3,680m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (E/B C/WAY)
NWG11328946-1020	3,697m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (E/B C/WAY)
NWG11328946-1021	3,672m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B C/WAY)
NWG11328946-1022	4,215m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (E/B VERGE)
NWG11328946-1023	4,217m	0m	ROAD_MARKINGS_LONG	Missing node marker (MIRF)	CAT 2	01/01/9999	Completed Defects	11/09/2019	ABHAINN MHOR BRIDGE.
NWG11328946-1024	4,202m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (E/B VERGE)
NWG11328946-1025	4,109m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (E/B C/WAY)
NWG11328946-1026	4,123m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (E/B C/WAY)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG11328946-1027	4,117m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (E/B C/WAY)
NWG11328946-1028	4,071m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (E/B C/WAY)
NWG11328946-1029	4,075m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (E/B C/WAY)
NWG11328946-1030	4,037m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (E/B C/WAY)
NWG11328946-1031	4,027m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (E/B C/WAY)
NWG11328946-1032	3,878m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (E/B C/WAY)
NWG11328946-1033	3,904m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B C/WAY)
NWG11328946-1034	3,967m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B C/WAY)
NWG11328946-1035	4,040m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B C/WAY)
NWG11328946-1036	3,975m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (CENTRE LINE)
NWG11328946-1037	4,060m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B C/WAY)
NWG11328946-1038	4,112m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B C/WAY)
NWG11328946-1039	4,116m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B C/WAY)
NWG11328946-1040	4,122m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B C/WAY)
NWG11328946-1041	4,174m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (W/B VERGE)
NWG11328946-1042	4,236m	0m	VERGE	Dead, dying or damaged areas (DPDY)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN NURSERY COTTAGES ACCESS & ABHAINN MHOR BRIDGE. (E/B VERGE)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Annual Detailed Inspection - Carriageways of A83 SHIRA BRIDGE TO A83 C43 (BRAE ROAD) JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection - Covers, Gratings and Frames of A83 SHIRA BRIDGE TO A83 C43 (BRAE ROAD) JUNCTION									
<i>No defects recorded</i>									
Detailed Inspection - Kerbs, Channels, Edgings of A83 SHIRA BRIDGE TO A83 C43 (BRAE ROAD) JUNCTION									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 13 June 2018									
NWG11360543-235843261	2,931m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	14/06/2018	Completed Defects	13/06/2018	JUST WEST OF ARDCASTLE, W/B C/WAY.
NWG11360543-235843262	2,960m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	14/06/2018	Completed Defects	13/06/2018	JUST WEST OF ARDCASTLE, W/B C/WAY.
NWG11360543-235843263	2,961m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	14/06/2018	Completed Defects	13/06/2018	JUST WEST OF ARDCASTLE, W/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 20 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 27 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 04 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 11 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 18 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 25 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 01 August 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 08 August 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 15 August 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 22 August 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 29 August 2018									
NWG11398207-235983469	717m	0m	BOLLARDS	Missing (MISS)	CAT 1	26/09/2018	Completed Defects	14/09/2018	KILMICHAEL BEG BENDS. (W/B C/WAY)
NWG11398207-235983470	585m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	30/08/2018	Completed Defects	29/08/2018	KILMICHAEL BEG BENDS. (W/B C/WAY)
Safety Inspection of A83 Safety Inverary - Campbeltown on 05 September 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 12 September 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 19 September 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 26 September 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 03 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 10 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 17 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 31 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 07 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 14 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 21 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 28 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 05 December 2018									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 12 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 19 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 21 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 28 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 04 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 09 January 2019									
NW122427924-236270728	181m	0m	TRAFFIC_SIGNS	Pointing wrong way (RWAY)	CAT 1	10/01/2019	Completed Defects	09/01/2019	KILMICHEAL BEG E/B VERGE
Safety Inspection of A83 Safety Inverary - Campbeltown on 16 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 23 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 30 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 06 February 2019									
NWG23-429030-236305328	2,961m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	07/02/2019	Completed Defects	06/02/2019	WEST OF ARDCASTLE
NWG23-429030-236305329	2,966m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	07/02/2019	Completed Defects	06/02/2019	WEST ARDCASTLE
NWG23-429030-236305330	4,036m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	07/02/2019	Completed Defects	06/02/2019	WEST OF ARDCASTLE
Safety Inspection of A83 Safety Inverary - Campbeltown on 13 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 20 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 27 February 2019									
NWG23-434346-236335210	524m	0m	TRAFFIC_SIGNS	Accident damage (ACCD)	CAT 1	27/03/2019	Completed Defects	27/03/2019	KILMICHAEL BEG BENDS, E/B VERGE.
Safety Inspection of A83 Safety Inverary - Campbeltown on 06 March 2019									
NWG23-437822-236341761	4,112m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	07/03/2019	Completed Defects	06/03/2019	JUST EAST OF GLASHAN BURN ACCESS, LOCHGAIR. (W/B C/WAY)
Safety Inspection of A83 Safety Inverary - Campbeltown on 13 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 20 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 27 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 03 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 10 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 17 April 2019									
NW38479961-236571895	4,114m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/04/2019	Completed Defects	17/04/2019	(A83) EAST OF LOCH GAIR
NW38479961-236571896	4,106m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/04/2019	Completed Defects	17/04/2019	(A83) EAST OF LOCHGAIR
Safety Inspection of A83 Safety Inverary - Campbeltown on 24 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 01 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 08 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 15 May 2019									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A83 Safety Inverary - Campbeltown on 22 May 2019									
NW38510041-236680880	4,039m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) EAST OF LOCH GAIR
NW38510041-236680881	4,045m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) EAST OF LOCH GAIR
NW38510041-236680882	4,047m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) EAST OF LOCH GAIR
NW38510041-236680883	4,039m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) EAST OF LOCH GAIR
NW38510041-236680884	4,032m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) EAST OF LOCH GAIR
Safety Inspection of A83 Safety Inverary - Campbeltown on 29 May 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 05 June 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 12 June 2019									
NW38522455-236825613	4,032m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	13/06/2019	Completed Defects	12/06/2019	EAST OF LOCHGAIR, W/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 19 June 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 26 June 2019									
No defects recorded									
Annual Detailed Inspection - Carriageways of INVY 06 A83									
No defects recorded									
Detailed Inspection - Covers, Gratings and Frames of INVY 06 A83									
No defects recorded									
Detailed Inspection - Kerbs, Channels, Edgings of INVY 06 A83									
No defects recorded									
Detailed Inspection TEMPLATE of INVY 06 A83 on 31 May 2019									
NW38510547-927	18m	0m	GRIP	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B VERGE.
NW38510547-928	46m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-929	87m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-931	149m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, CENTRE LINE.
NW38510547-932	174m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-933	195m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B C/WAY.
NW38510547-934	238m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B VERGE.
NW38510547-935	266m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B C/WAY.
NW38510547-936	274m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW38510547-937	280m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B C/WAY.
NW38510547-938	360m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-939	399m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, CENTRE LINE.
NW38510547-940	419m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-941	441m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B C/WAY.
NW38510547-942	446m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-943	462m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B VERGE.
NW38510547-944	832m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-945	847m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B C/WAY.
NW38510547-946	912m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B C/WAY.
NW38510547-947	933m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B C/WAY.
NW38510547-948	1,042m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-949	1,536m	0m	BOLLARDS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B VERGE.
NW38510547-950	1,563m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B VERGE.
NW38510547-951	1,320m	1,400m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B VERGE.
NW38510547-952	1,841m	0m	BOLLARDS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B VERGE.
NW38510547-953	1,829m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B VERGE.
NW38510547-954	1,754m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B C/WAY.

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW38510547-955	1,585m	0m	BOLLARDS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B VERGE.
NW38510547-956	1,572m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B VERGE.
NW38510547-957	1,569m	1,689m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B VERGE.
NW38510547-958	1,739m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B C/WAY.
NW38510547-959	1,851m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B VERGE.
NW38510547-960	2,493m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B VERGE.
NW38510547-961	2,489m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B VERGE.
NW38510547-962	2,696m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B C/WAY.
NW38510547-963	2,700m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-967	2,701m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-964	2,708m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B C/WAY.
NW38510547-965	2,704m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B VERGE.
NW38510547-966	2,706m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B VERGE.
NW38510547-978	3,160m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-979	3,233m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-980	3,271m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-982	3,301m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B VERGE.
NW38510547-983	3,297m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B VERGE.
NW38510547-984	3,372m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-985	3,374m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW38510547-986	3,388m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B C/WAY.
NW38510547-987	3,364m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B C/WAY.
NW38510547-988	3,314m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B C/WAY.
NW38510547-989	3,301m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B C/WAY.
NW38510547-990	3,271m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B C/WAY.
NW38510547-991	3,174m	0m	FILTER_DRAIN	Silted (SILT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B VERGE.
NW38510547-992	3,104m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B C/WAY.
NW38510547-993	2,762m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B C/WAY.
NW38510547-994	2,706m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B C/WAY.
NW38510547-995	3,596m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-997	3,607m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B VERGE.
NW38510547-968	2,798m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, CENTRE LINE.
NW38510547-969	2,856m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-970	2,883m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-971	2,895m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B VERGE.
NW38510547-972	2,906m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-973	2,910m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, CENTRE LINE.
NW38510547-974	2,962m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, CENTRE LINE.
NW38510547-975	3,041m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW38510547-976	3,090m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-977	3,138m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-981	3,283m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-996	3,601m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B C/WAY.
NW38510547-998	3,575m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-999	3,642m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-1000	3,808m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, CENTRE LINE.
NW38510547-1001	3,845m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-1005	3,849m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-1002	3,846m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B C/WAY.
NW38510547-1003	3,904m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-1004	3,897m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B C/WAY.
NW38510547-1006	3,856m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-1007	3,888m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-1008	3,895m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B C/WAY.
NW38510547-930	153m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-1009	3,941m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, CENTRE LINE.
NW38510547-1010	3,958m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW38510547-1011	3,955m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-1012	4,036m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-1013	4,032m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B C/WAY.
NW38510547-1014	4,049m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-1015	4,053m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, CENTRE LINE.
NW38510547-1016	4,072m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-1017	4,103m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-1018	4,113m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-1019	4,124m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B C/WAY.
NW38510547-1020	4,141m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B C/WAY.
NW38510547-1021	4,148m	0m	BOLLARDS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B VERGE.
NW38510547-1022	4,106m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, W/B VERGE.
NW38510547-1023	4,071m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) BETWEEN NURSERY COTTAGES & ABHAINN MHOR BRIDGE, E/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 03 July 2019									
NW38530255-236891790	4,116m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/07/2019	Completed Defects	03/07/2019	EAST OF LOCHGAIR VILLAGE, W/B C/WAY.
NW38530255-236891791	4,125m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 1	31/07/2019	Completed Defects	31/07/2019	EAST OF LOCHGAIR VILLAGE, W/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 10 July 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 17 July 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 24 July 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 31 July 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 07 August 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 14 August 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 21 August 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 28 August 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 04 September 2019									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW38533036-236994454	1,643m	0m	BOLLARDS	Damaged (DAMG)	CAT 1	02/10/2019	Completed Defects	20/09/2019	WEST OF KILMICHAEL BEG, W/B VERGE.
NW38533036-236994455	1,779m	0m	BOLLARDS	Damaged (DAMG)	CAT 1	02/10/2019	Completed Defects	20/09/2019	WEST OF KILMICHAEL BEG, W/B VERGE.
Safety Inspection of A83 Safety Inverary - Campbeltown on 11 September 2019									
NW33533758-237014209	269m	0m	CATCHPIT	Blockage (BLOK)	CAT 1	09/10/2019	Completed Defects	09/10/2019	A83 N/B AFTER KILMICHAEL BEG
Safety Inspection of A83 Safety Inverary - Campbeltown on 18 September 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 25 September 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 02 October 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 09 October 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 16 October 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 23 October 2019									
NW38535477-237062415	171m	0m	TRAFFIC_SIGNS	Pointing wrong way (RWAY)	CAT 1	24/10/2019	Completed Defects	23/10/2019	JUST WEST OF NURSERY COTTAGES, E/B VERGE.
Safety Inspection of A83 Safety Inverary - Campbeltown on 30 October 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 06 November 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 13 November 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 20 November 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 27 November 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 04 December 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 11 December 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 18 December 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 24 December 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 31 December 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 07 January 2020									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 14 January 2020									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 22 January 2020									
NW38538540-237244960	3,630m	0m	GRIP	Flood nuisance to properties (NPRP)	CAT 2		Cat 2 Awaiting Action		(A83) BEECH COTAGE, EAST OF LOCHGAIR VILLAGE, W/B VERGE.
Safety Inspection of A83 Safety Inverary - Campbeltown on 29 January 2020									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 05 February 2020									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 11 February 2020									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 18 February 2020									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 25 February 2020									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 03 March 2020									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 10 March 2020									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 17 March 2020									
No defects recorded									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A83 Safety Inverary - Campbeltown on 24 March 2020									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 31 March 2020									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 07 April 2020									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 14 April 2020									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 21 April 2020									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 28 April 2020									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 05 May 2020									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 12 May 2020									
<i>No defects recorded</i>									
16540/50 : ABHAINN MHOR BRIDGE TO PORT ANN ACCESS									
Safety Inspection of A83 Safety Inverary - Campbeltown on 05 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 12 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 19 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 26 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 02 February 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 09 February 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 16 February 2017									
NWG5243223-235053144	100m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	17/02/2017	Completed Defects	16/02/2017	OUTSIDE GLASHAN BURN ACCESS, W/B C/WAY
Safety Inspection of A83 Safety Inverary - Campbeltown on 23 February 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 02 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 09 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 16 March 2017									
NWG21250946-235068447	3,617m	0m	TRAFFIC_SIGNS	Accident damage (ACCD)	CAT 1	13/04/2017	Completed Defects	31/03/2017	2KM EAST OF PORT ANN, W/B VERGE
Safety Inspection of A83 Safety Inverary - Campbeltown on 23 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 30 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 06 April 2017									
NWG21256924-235074579	2,063m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 1	04/05/2017	Completed Defects	03/05/2017	EAST KAMES, WEST OF LOCHGAIR EB
Safety Inspection of A83 Safety Inverary - Campbeltown on 13 April 2017									
NWG21259618-235075699	104m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	14/04/2017	Completed Defects	13/04/2017	OUTSIDE GLASHAN BURN ACCESS, E/B C/WAY
Safety Inspection of A83 Safety Inverary - Campbeltown on 20 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 27 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 04 May 2017									
NWG21265987-235136704	119m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 1	01/06/2017	Completed Defects	01/06/2017	OUTSIDE GLASHAN BURN ACCESS.
Safety Inspection of A83 Safety Inverary - Campbeltown on 11 May 2017									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A83 Safety Inverary - Campbeltown on 18 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 25 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 01 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 08 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 15 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 22 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 29 June 2017									
<i>No defects recorded</i>									
Detailed Inspection TEMPLATE of A83 SHIRA BRIDGE TO A83 C43 (BRAE ROAD) JUNCTION on 20 June 2017									
NW80253085-446	23m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST EAST OF GLASHAN BURN ACCESS, W/B C/WAY.
NW80253085-447	63m	0m	CARRIAGEWAY	Patch - material cracking (PMCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST EAST OF GLASHAN BURN ACCESS, W/B C/WAY.
NW80253085-448	59m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST EAST OF GLASHAN BURN ACCESS, W/B C/WAY.
NW80253085-449	75m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST EAST OF GLASHAN BURN ACCESS, W/B C/WAY.
NW80253085-450	83m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST EAST OF GLASHAN BURN ACCESS, W/B C/WAY.
NW80253085-451	68m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST EAST OF GLASHAN BURN ACCESS, W/B C/WAY.
NW80253085-452	86m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST EAST OF GLASHAN BURN ACCESS, E/B C/WAY.
NW80253085-453	83m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST EAST OF GLASHAN BURN ACCESS, E/B C/WAY.
NW80253085-455	91m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST SIDE OF GLASHAN BURN ACCESS, E/B C/WAY.
NW80253085-456	75m	0m	BOLLARDS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST SIDE OF GLASHAN BURN ACCESS, E/B VERGE..
NW80253085-457	122m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF GLASHAN BURN ACCESS, W/B C/WAY.
NW80253085-458	167m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF GLASHAN BURN ACCESS, E/B C/WAY.
NW80253085-459	200m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF GLASHAN BURN ACCESS, E/B C/WAY.
NW80253085-460	234m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF GLASHAN BURN ACCESS, W/B C/WAY.
NW80253085-461	246m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF GLASHAN BURN ACCESS, W/B C/WAY.
NW80253085-462	279m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF GLASHAN BURN ACCESS, E/B C/WAY.

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW80253085-463	284m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF GLASHAN BURN ACCESS, W/B C/WAY.
NW80253085-464	299m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF GLASHAN BURN ACCESS, W/B C/WAY.
NW80253085-465	321m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF GLASHAN BURN ACCESS, E/B C/WAY.
NW80253085-466	358m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF GLASHAN BURN ACCESS, W/B C/WAY.
NW80253085-471	591m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST EAST OF LOCHGAIR, E/B VERGE.
NW80253085-472	622m	0m	BOLLARDS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST EAST OF LOCHGAIR, E/B VERGE.
NW80253085-473	496m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST EAST OF LOCHGAIR, W/B C/WAY.
NW80253085-474	725m	0m	FILTER_DRAIN	Silted (SILT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST OUTSIDE LOCHGAIR EAST 40MPH SIGNS, E/B VERGE.
NW80253085-475	732m	0m	GULLY	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	@ LOCHGAIR EAST 40MPH SIGNS, E/B VERGE.
NW80253085-476	778m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST OUTSIDE LOCHGAIR EAST 40MPH SIGNS, W/B VERGE.
NW80253085-477	1,676m	0m	BOLLARDS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, W/B VERGE.
NW80253085-478	1,682m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, W/B VERGE.
NW80253085-479	1,616m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, E/B C/WAY.
NW80253085-480	1,618m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, CENTRE LINE.
NW80253085-481	1,688m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, E/B C/WAY.
NW80253085-482	1,704m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, CENTRE LINE.
NW80253085-467	406m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF GLASHAN BURN ACCESS, W/B VERGE.
NW80253085-468	443m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST WEST OF GLASHAN BURN ACCESS, W/B C/WAY.
NW80253085-469	451m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST WEST OF GLASHAN BURN ACCESS, E/B C/WAY.
NW80253085-470	511m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST WEST OF GLASHAN BURN ACCESS, E/B C/WAY.
NW80253085-483	1,698m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, W/B C/WAY.

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW80253085-484	1,696m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, E/B C/WAY.
NW80253085-485	1,714m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, E/B C/WAY.
NW80253085-486	1,704m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, CENTRE LINE.
NW80253085-487	1,723m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, CENTRE LINE.
NW80253085-488	1,744m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, E/B C/WAY.
NW80253085-489	1,759m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, E/B C/WAY.
NW80253085-490	1,766m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, W/B C/WAY.
NW80253085-491	1,797m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, E/B C/WAY.
NW80253085-492	1,818m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, W/B C/WAY.
NW80253085-493	1,836m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, W/B C/WAY.
NW80253085-494	1,820m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, E/B C/WAY.
NW80253085-495	2,036m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF LOCHGAIR, E/B C/WAY.
NW80253085-496	2,030m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF LOCHGAIR, W/B C/WAY.
NW80253085-497	2,059m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF LOCHGAIR, E/B C/WAY.
NW80253085-498	2,528m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MIDDLE KAMES, E/B VERGE.
NW80253085-499	2,567m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	10/06/2019	MIDDLE KAMES, W/B C/WAY.
NW80253085-500	2,590m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	10/06/2019	MIDDLE KAMES, W/B C/WAY.
NW80253085-501	3,036m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF MIDDLE KAMES, W/B VERGE.
NW80253085-502	2,786m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	10/06/2019	JUST WEST OF MIDDLE KAMES ACCESS, W/B C/WAY.
NW80253085-503	2,839m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF MIDDLE KAMES, E/B VERGE.
NW80253085-504	3,635m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF MIDDLE KAMES, W/B VERGE.

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW80253085-505	4,066m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF MIDDLE KAMES, E/B VERGE.
NW80253085-510	5,013m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST EAST OF PORT ANN, W/B VERGE.
NW80253085-507	4,837m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST EAST OF PORT ANN, E/B VERGE.
NW80253085-508	5,396m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST EAST OF PORT ANN, W/B VERGE.
NW80253085-509	5,389m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST EAST OF PORT ANN, W/B VERGE.
NW80253085-511	5,016m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST EAST OF PORT ANN, W/B VERGE.
NW80253085-454	90m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST SIDE OF GLASHAN BURN ACCESS, W/B C/WAY.
NW80253085-512	5,235m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST EAST OF PORT ANN, E/B VERGE.
Annual Detailed Inspection - Carriageways of A83 SHIRA BRIDGE TO A83 C43 (BRAE ROAD) JUNCTION									
No defects recorded									
Detailed Inspection - Covers, Gratings and Frames of A83 SHIRA BRIDGE TO A83 C43 (BRAE ROAD) JUNCTION									
No defects recorded									
Detailed Inspection - Kerbs, Channels, Edgings of A83 SHIRA BRIDGE TO A83 C43 (BRAE ROAD) JUNCTION									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 06 July 2017									
NWG30-281800-235255903	1,624m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	03/08/2017	Completed Defects	01/08/2017	JUST WEST OF LOCHGAIR.
Safety Inspection of A83 Safety Inverary - Campbeltown on 13 July 2017									
NWG30-282247-235257232	1,872m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	14/07/2017	Completed Defects	13/07/2017	OUTSIDE KNOCK COTTAGE, W/B C/WAY.
NWG30-282247-235257231	1,870m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	14/07/2017	Completed Defects	13/07/2017	OUTSIDE KNOCK COTTAGE, E/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 20 July 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 27 July 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 03 August 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown (Awaiting Return)									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 17 August 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 24 August 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 31 August 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 07 September 2017									
NW31284755-235363866	1,949m	0m	MANHOLE	Difference in component levels (ICLV)	3RD PTY	05/10/2017	Awaiting CCMS Temp Date	01/01/9999	OUTSIDE LORAN HOUSE ACCESS, WEST OF LOCHGAIR. (W/B C/WAY)
Safety Inspection of A83 Safety Inverary - Campbeltown on 14 September 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 21 September 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 28 September 2017									
NWG11314882-235380147	108m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	29/09/2017	Completed Defects	28/09/2017	OUTSIDE GLASHAN BURN, EAST OF LOCHGAIR, W/B C/WAY.

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG11314882-235380148	109m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	29/09/2017	Completed Defects	28/09/2017	OUTSIDE GLASHAN BURN ACCESS, EAST OF LOCHGAIR, W/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 05 October 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 12 October 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 19 October 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 26 October 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 02 November 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 09 November 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 16 November 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 23 November 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 30 November 2017									
NWG11316430-235483559	48m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	01/12/2017	Completed Defects	30/11/2017	JUST EAST OF GLASHAN BURN ACCESS, W/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 07 December 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 14 December 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 21 December 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 28 December 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 04 January 2018									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 11 January 2018									
NWG11317396-235513652	1,602m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 1	08/02/2018	Completed Defects	08/02/2018	JUST WEST OF LOCHGAIR, E/B C/WAY.
NWG11317396-235513653	1,620m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	12/01/2018	Completed Defects	11/01/2018	JUST WEST OF LOCHGAIR, E/B C/WAY.
NWG11317396-235513654	1,619m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	12/01/2018	Completed Defects	11/01/2018	JUST WEST OF LOCHGAIR, E/B C/WAY.
NWG11317396-235513655	1,697m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 1	08/02/2018	Completed Defects	08/02/2018	JUST WEST OF LOCHGAIR, CENTRE LINE.
Safety Inspection of A83 Safety Inverary - Campbeltown on 18 January 2018									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 25 January 2018									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 01 February 2018									
NWG11318017-235531606	104m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	02/02/2018	Completed Defects	01/02/2018	GLASHAN BURN ACCESS, EAST OF LOCHGAIR. (E/B C/WAY)
NWG11318017-235531607	111m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/02/2018	Completed Defects	19/02/2018	GLASHAN BURN ACCESS, EAST OF LOCHGAIR. (W/B C/WAY)
NWG11318017-235531608	116m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	02/02/2018	Completed Defects	01/02/2018	GLASHAN BURN ACCESS, EAST OF LOCHGAIR. (W/B C/WAY)
NWG11318017-235531609	125m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	02/02/2018	Completed Defects	01/02/2018	GLASHAN BURN ACCESS, EAST OF LOCHGAIR. (W/B C/WAY)
NWG11318017-235531610	110m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	02/02/2018	Completed Defects	01/02/2018	GLASHAN BURN ACCESS, EAST OF LOCHGAIR. (E/B C/WAY)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG11318017-235531611	1,870m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	02/02/2018	Completed Defects	01/02/2018	OUTSIDE KNOCK COTTAGE, LOCHGAIR. (E/B C/WAY)
Safety Inspection of A83 Safety Inverary - Campbeltown on 08 February 2018									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 14 February 2018									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 21 February 2018									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 28 February 2018									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 07 March 2018									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 14 March 2018									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 21 March 2018									
NW122328664-235596645	2,936m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	22/03/2018	Completed Defects	21/03/2018	MIDDLE KAMES, E/B C/WAY.
NW122328664-235596646	2,879m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	22/03/2018	Completed Defects	21/03/2018	MIDDLE KAMES, E/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 28 March 2018									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 04 April 2018									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown (Awaiting Return)									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 18 April 2018									
NW122337478-235656079	522m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	19/04/2018	Completed Defects	18/04/2018	JUST EAST OF LOCHGAIR, W/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 25 April 2018									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 02 May 2018									
NW122341824-235689811	527m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	03/05/2018	Completed Defects	02/05/2018	EAST SIDE OF LOCHGAIR, W/B C/WAY.
NW122341824-235689812	808m	0m	TRAFFIC_SIGNS	Obscured sign (OBSG)	CAT 1	03/05/2018	Completed Defects	02/05/2018	LOCHGAIR EAST, W/B VERGE.
NW122341824-235689813	2,829m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	03/05/2018	Completed Defects	02/05/2018	KAMES BENDS, W/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 09 May 2018									
NW33344801-235712587	33m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	10/05/2018	Completed Defects	09/05/2018	GLASHAN BURN, E/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 16 May 2018									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 23 May 2018									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 30 May 2018									
NW122353811-235815110	4,571m	0m	TRAFFIC_SIGNS	Pointing wrong way (RWAY)	CAT 1	31/05/2018	Completed Defects	30/05/2018	JUST EAST OF PORT ANN, W/B VERGE.
Safety Inspection of A83 Safety Inverary - Campbeltown on 06 June 2018									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 13 June 2018									
No defects recorded									
Detailed Inspection TEMPLATE of A83 SHIRA BRIDGE TO A83 C43 (BRAE ROAD) JUNCTION on 30 April 2018									
NWG11328946-1052	770m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B VERGE)
NWG11328946-1053	831m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG11328946-1054	2,077m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1044	439m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1045	493m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1046	491m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B VERGE)
NWG11328946-1055	2,015m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1048	662m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B VERGE)
NWG11328946-1049	705m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B VERGE)
NWG11328946-1050	674m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B VERGE)
NWG11328946-1051	669m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B VERGE)
NWG11328946-1056	2,000m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1057	1,959m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1058	1,961m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1059	1,929m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1060	1,909m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1061	1,756m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B VERGE)
NWG11328946-1062	1,723m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B VERGE)
NWG11328946-1063	1,723m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B VERGE)
NWG11328946-1064	1,983m	0m	ROAD_MARKINGS _LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (CENTRE LINE)
NWG11328946-1065	2,011m	0m	ROAD_MARKINGS _LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1066	2,192m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG11328946-1067	2,181m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1068	2,131m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1069	2,141m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1070	2,235m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1071	2,239m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1076	2,413m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1077	2,459m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1078	2,449m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1079	2,475m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1072	2,266m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1073	2,230m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (CENTRE LINE)
NWG11328946-1074	2,189m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B VERGE)
NWG11328946-1075	2,496m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B VERGE)
NWG11328946-1080	2,475m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (CENTRE LINE)
NWG11328946-1081	2,485m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1082	2,511m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1083	2,534m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	10/06/2019	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1084	2,558m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	10/06/2019	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1085	2,574m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	10/06/2019	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1086	2,580m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	10/06/2019	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG11328946-1087	2,594m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	10/06/2019	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1088	2,598m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1089	2,596m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1090	3,289m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1091	3,175m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B VERGE)
NWG11328946-1092	3,141m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1093	3,002m	0m	TRAFFIC_SIGNS	Obscured sign (OBSG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B VERGE)
NWG11328946-1094	2,979m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B VERGE)
NWG11328946-1095	2,953m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1096	2,922m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1097	2,821m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	10/06/2019	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1098	2,819m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	10/06/2019	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1099	2,821m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B VERGE)
NWG11328946-1108	3,570m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B VERGE)
NWG11328946-1109	4,117m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B VERGE)
NWG11328946-1110	3,305m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1111	3,293m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B VERGE)
NWG11328946-1112	3,795m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B VERGE)
NWG11328946-1113	3,794m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B VERGE)
NWG11328946-1114	4,332m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B VERGE)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG11328946-1115	4,325m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1116	4,494m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1117	5,043m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1118	5,017m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1119	4,989m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (CENTRE LINE)
NWG11328946-1120	4,867m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B VERGE)
NWG11328946-1121	4,867m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B VERGE)
NWG11328946-1122	4,772m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B VERGE)
NWG11328946-1123	5,001m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B VERGE)
NWG11328946-1124	5,003m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B VERGE)
NWG11328946-1125	5,089m	0m	VERGE	Dead, dying or damaged areas (DPDY)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B VERGE)
NWG11328946-1126	5,218m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B VERGE)
NWG11328946-1127	5,673m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B VERGE)
NWG11328946-1100	2,821m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	10/06/2019	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (CENTRE LINE)
NWG11328946-1101	2,838m	0m	VERGE	Dead, dying or damaged areas (DPDY)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B VERGE)
NWG11328946-1102	2,762m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1103	2,749m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	10/06/2019	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1104	2,761m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1105	2,943m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B VERGE)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG11328946-1106	3,084m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (CENTRE LINE)
NWG11328946-1107	3,586m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1128	5,267m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B VERGE)
NWG11328946-1129	5,354m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B VERGE)
NWG11328946-1047	723m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B VERGE)
NWG11328946-1043	440m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)

Annual Detailed Inspection - Carriageways of A83 SHIRA BRIDGE TO A83 C43 (BRAE ROAD) JUNCTION

No defects recorded

Detailed Inspection - Covers, Gratings and Frames of A83 SHIRA BRIDGE TO A83 C43 (BRAE ROAD) JUNCTION

No defects recorded

Detailed Inspection - Kerbs, Channels, Edgings of A83 SHIRA BRIDGE TO A83 C43 (BRAE ROAD) JUNCTION

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 20 June 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 27 June 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 04 July 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 11 July 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 18 July 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 25 July 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 01 August 2018

NW122384825-235928477	3,555m	0m	TRAFFIC_SIGNS	Obscured sign (OBSG)	CAT 1	02/08/2018	Completed Defects	01/08/2018	KAMES, W/B VERGE.
-----------------------	--------	----	---------------	----------------------	-------	------------	-------------------	------------	-------------------

Safety Inspection of A83 Safety Inverary - Campbeltown on 08 August 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 15 August 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 22 August 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 29 August 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 05 September 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 12 September 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 19 September 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 26 September 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 03 October 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 10 October 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 17 October 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 31 October 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 07 November 2018

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 14 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 21 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 28 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 05 December 2018									
NWG11426982-236234670	2,742m	0m	SAFETY_FENCE	Accident damage (ACCD)	CAT 1	02/01/2019	Completed Defects	09/01/2019	MIDDLE KAMES, W/B VERGE.
NWG11426982-236234671	2,850m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	06/12/2018	Completed Defects	05/12/2018	MIDDLE KAMES, W/B C/WAY
NWG11426982-236234672	2,861m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/01/2019	Completed Defects	27/12/2018	MIDDLE KAMES, W/B VERGE.
Safety Inspection of A83 Safety Inverary - Campbeltown on 12 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 19 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 21 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 28 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 04 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 09 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 16 January 2019									
NW122428073-236273499	2,814m	0m	TRAFFIC_SIGNS	Accident damage (ACCD)	CAT 1	13/02/2019	Completed Defects	25/01/2019	MIDDLE KAMES, WEST OF LCHGAIR. (E/B VERGE)
NW122428073-236273500	2,818m	0m	BOLLARDS	Accident damage (ACCD)	CAT 1	13/02/2019	Completed Defects	25/01/2019	MIDDLE KAMES, WEST OF LOCHGAIR. (E/B VERGE)
Safety Inspection of A83 Safety Inverary - Campbeltown on 23 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 30 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 06 February 2019									
NWG23-429030-236305331	2,853m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/03/2019	Completed Defects	04/03/2019	MIDDLE KAMES WEST OF LOCH GAIR
NWG23-429030-236305332	2,907m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	07/02/2019	Completed Defects	06/02/2019	MIDDLE KAMES WEST OF LOCHGAIR
NWG23-429030-236305333	2,863m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/03/2019	Completed Defects	04/03/2019	MIDDLE KAMES WEST OF LOCHGAIR
NWG23-429030-236305334	2,488m	0m	TRAFFIC_SIGNS	Accident damage (ACCD)	CAT 1	06/03/2019	Completed Defects	05/03/2019	MIDDLE KAMES WEST OF LOCHGAIR
Safety Inspection of A83 Safety Inverary - Campbeltown on 13 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 20 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 27 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 06 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 13 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 20 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 27 March 2019									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A83 Safety Inverary - Campbeltown on 03 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 10 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 17 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 24 April 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 01 May 2019									
NW38498780-236608982	859m	0m	TRAFFIC_SIGNS	Physical condition of fittings (COFT)	CAT 1	02/05/2019	Completed Defects	01/05/2019	(A83) LOCHGAIR
Safety Inspection of A83 Safety Inverary - Campbeltown on 08 May 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 15 May 2019									
NW38506951-236666058	445m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST EAST OF LOCHGAIR, E/B C/WAY.
NW38506951-236666059	465m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST EAST OF LOCHGAIR, E/B C/WAY.
NW38506951-236666060	477m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST EAST OF LOCHGAIR, W/B C/WAY.
NW38506951-236666061	487m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST EAST OF LOCHGAIR, W/B C/WAY.
NW38506951-236666062	492m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST EAST OF LOCHGAIR, W/B C/WAY.
NW38506951-236666063	510m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST EAST OF LOCHGAIR, W/B C/WAY.
NW38506951-236666064	519m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST EAST OF LOCHGAIR, W/B C/WAY.
NW38506951-236666065	520m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST EAST OF LOCHGAIR, E/B C/WAY.
NW38506951-236666066	522m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	JUST EAST OF LOCHGAIR, W/B C/WAY.
NW38506951-236666067	527m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST EAST OF LOCHGAIR, W/B C/WAY.
NW38506951-236666068	542m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST EAST OF LOCHGAIR, W/B C/WAY.
NW38506951-236666088	764m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/05/2019	Completed Defects	15/05/2019	EAST SIDE OF LOCHGAIR VILLAGE, W/B C/WAY.
NW38506951-236666089	837m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/05/2019	Completed Defects	15/05/2019	EAST SIDE OF LOCHGAIR VILLAGE, W/B C/WAY.
NW38506951-236666090	837m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST SIDE OF LOCHGAIR VILLAGE, W/B C/WAY.
NW38506951-236666091	783m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	09/09/2019	EAST SIDE OF LOCHGAIR VILLAGE, W/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 22 May 2019									
<i>No defects recorded</i>									
Annual Detailed Inspection - Carriageways of INVY 05 A83									
<i>No defects recorded</i>									
Detailed Inspection - Covers, Gratings and Frames of INVY 05 A83									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Detailed Inspection - Kerbs, Channels, Edgings of INVY 05 A83									
<i>No defects recorded</i>									
Detailed Inspection TEMPLATE of INVY 05 A83 on 29 May 2019									
NW38490749-1	48m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B VERGE.
NW38490749-2	176m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B VERGE.
NW38490749-3	192m	0m	DITCH	Silted (SILT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B VERGE.
NW38490749-4	439m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-5	439m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	11/09/2019	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-6	603m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B VERGE.
NW38490749-7	661m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B VERGE.
NW38490749-8	749m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B VERGE.
NW38490749-9	764m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-10	792m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B VERGE.
NW38490749-11	831m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-12	788m	0m	GRIP	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B VERGE.
NW38490749-13	1,297m	0m	GRIP	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B VERGE.
NW38490749-14	1,324m	0m	GRIP	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B VERGE.
NW38490749-15	1,686m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B VERGE.
NW38490749-16	1,686m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B VERGE.
NW38490749-17	1,903m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-18	1,903m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-19	1,959m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-20	1,959m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW38490749-21	1,993m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-22	2,026m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-23	2,076m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-24	2,075m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-25	2,129m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-26	2,162m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-27	2,172m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-28	2,174m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-29	2,040m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-30	2,120m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-31	2,237m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-32	2,269m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-33	2,271m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-34	2,298m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-35	2,306m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-36	2,379m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-37	2,398m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-38	2,402m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, GENTTE LINE.
NW38490749-39	2,413m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW38490749-40	2,445m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-41	2,449m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-42	2,455m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-43	2,507m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B VERGE.
NW38490749-44	2,543m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	10/06/2019	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-45	2,559m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	10/06/2019	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-46	2,563m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	10/06/2019	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-47	2,573m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	10/06/2019	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-48	2,580m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	10/06/2019	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-49	2,647m	0m	VERGE	Overhanging/overgrown (OVER)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) MIDDLE KAMES. LINK/SECTION BETWEEN ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B VERGE.
NW38490749-50	2,670m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-51	2,669m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-52	2,719m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	10/06/2019	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-53	2,731m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	10/06/2019	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-54	2,755m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	10/06/2019	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-55	2,780m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-56	2,791m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	10/06/2019	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-57	2,797m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	10/06/2019	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, CENTRE LINE.
NW38490749-58	2,896m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B VERGE.
NW38490749-59	2,907m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	10/06/2019	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW38490749-60	2,908m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	10/06/2019	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-61	2,921m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-62	2,860m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	10/06/2019	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-63	2,949m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-64	2,957m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-65	2,958m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B VERGE.
NW38490749-66	3,289m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-67	1m	0m	REFERENCE_MARKER_POINT	Missing node marker (MIRF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE EAST OF LOCHGAR.
NW38490749-68	3,292m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-69	3,303m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B VERGE.
NW38490749-70	3,339m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-71	3,365m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-72	3,412m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-73	3,420m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-74	3,420m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-75	4,170m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B VERGE.
NW38490749-76	4,145m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B VERGE.
NW38490749-77	4,051m	0m	VERGE	Dead, dying or damaged areas (DPDY)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B VERGE.
NW38490749-78	3,928m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-79	3,903m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B VERGE.

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW38490749-80	3,876m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B VERGE.
NW38490749-81	3,882m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-82	3,860m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-83	3,793m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, CENTRE LINE.
NW38490749-84	3,640m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-85	3,617m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, CENTRE LINE.
NW38490749-86	3,608m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-87	3,590m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-88	3,570m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-89	3,587m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-90	3,601m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B VERGE.
NW38490749-91	3,889m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-92	3,938m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-93	3,943m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-94	3,981m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-95	4,030m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-96	4,062m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-97	4,104m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B VERGE.
NW38490749-98	4,997m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, CENTRE LINE.

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW38490749-99	5,077m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B VERGE.
NW38490749-100	4,817m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B VERGE.
NW38490749-101	4,325m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, /B C/WAY.
NW38490749-102	4,487m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-103	4,497m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-104	4,827m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B VERGE.
NW38490749-105	5,054m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-106	5,016m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-107	5,017m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B VERGE.
NW38490749-108	5,255m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-110	5,530m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-111	5,510m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-112	5,354m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-113	5,354m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B VERGE.
NW38490749-114	5,299m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B VERGE.
NW38490749-115	5,327m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-116	5,362m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.

Safety Inspection of A83 Safety Inverary - Campbeltown on 29 May 2019

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 05 June 2019

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 12 June 2019

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 19 June 2019

No defects recorded

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A83 Safety Inverary - Campbeltown on 26 June 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 03 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 10 July 2019									
NW38530849-236899462	1,539m	0m	TRAFFIC_SIGNS	Obscured sign (OBSG)	CAT 1	11/07/2019	Completed Defects	10/07/2019	KNOCK W/B
Safety Inspection of A83 Safety Inverary - Campbeltown on 17 July 2019									
NW38531054-236908929	2,370m	0m	TRAFFIC_SIGNS	Obscured sign (OBSG)	CAT 1	18/07/2019	Completed Defects	17/07/2019	EAST KAMES
NW38531054-236908930	3,864m	0m	TRAFFIC_SIGNS	Obscured sign (OBSG)	CAT 1	18/07/2019	Completed Defects	17/07/2019	SOUTH OF MIDDLE KAMES
Safety Inspection of A83 Safety Inverary - Campbeltown on 24 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 31 July 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 07 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 14 August 2019									
NW38532237-236936914	1,957m	0m	MANHOLE	Difference in component levels (ICLV)	3RD PTY	11/09/2019	Awaiting CCMS Temp Date	01/01/9999	(A83) OPPOSITE LORAN HOUSE ACCESS, WEST OF LOCHGAIR. (W/B C/WAY)
Safety Inspection of A83 Safety Inverary - Campbeltown on 21 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 28 August 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 04 September 2019									
NW38533036-236994456	707m	0m	BOLLARDS	Damaged (DAMG)	CAT 1	02/10/2019	Completed Defects	02/10/2019	JUST EAST OF LOCHGAIR, E/B VERGE.
NW38533036-236994457	1,646m	0m	BOLLARDS	Damaged (DAMG)	CAT 1	02/10/2019	Completed Defects	02/10/2019	WEST OF LOCHAIR, W/B VERGE.
Safety Inspection of A83 Safety Inverary - Campbeltown on 11 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 18 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 25 September 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 02 October 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 09 October 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 16 October 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 23 October 2019									
NW38535477-237062416	976m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 1	20/11/2019	Completed Defects	20/11/2019	LOCHGAIR VILLAGE, W/B VERGE.
NW38535477-237062417	5,410m	0m	BOLLARDS	Missing (MISS)	CAT 1	20/11/2019	Completed Defects	19/11/2019	EAST SIDE OF PORT ANN, W/B VERGE.
NW38535477-237062418	4,153m	0m	BOLLARDS	Missing (MISS)	CAT 1	20/11/2019	Completed Defects	19/11/2019	EAST OF PORT ANN, E/B VERGE.
Safety Inspection of A83 Safety Inverary - Campbeltown on 30 October 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 06 November 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 13 November 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 20 November 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 27 November 2019									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A83 Safety Inverary - Campbeltown on 04 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 11 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 18 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 24 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 31 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 07 January 2020									
<i>No defects recorded</i>									
NW38538313-237225454	854m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 1	11/02/2020	Completed Defects	11/02/2020	(A83) EAST SIDE OF LOCHAIR VILLAGE, W/B VERGE.
Safety Inspection of A83 Safety Inverary - Campbeltown on 22 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 29 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 05 February 2020									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 11 February 2020									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 18 February 2020									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 25 February 2020									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 03 March 2020									
NW33545779-237294877	1,959m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/03/2020	Completed Defects	03/03/2020	A83 W/B KNOCK COTTAGE
NW33545779-237294878	1,909m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/03/2020	Completed Defects	03/03/2020	A83 W/B KNOCK COTTAGE
Safety Inspection of A83 Safety Inverary - Campbeltown on 10 March 2020									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 17 March 2020									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 24 March 2020									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 31 March 2020									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 07 April 2020									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 14 April 2020									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 21 April 2020									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 28 April 2020									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 05 May 2020									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 12 May 2020									
<i>No defects recorded</i>									
16540/71 : PORT ANN ACCESS TO CASTLETON									
Safety Inspection of A83 Safety Inverary - Campbeltown on 05 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 12 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 19 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 26 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 02 February 2017									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A83 Safety Inverary - Campbeltown on 09 February 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 16 February 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 23 February 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 02 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 09 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 16 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 23 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 30 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 06 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 13 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 20 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 27 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 04 May 2017 NWG21265987-235136705	2,169m	0m	MANHOLE	Cracked or broken (IBCK)	3RD PTY	01/06/2017	Awaiting CCMS Temp Date	01/01/9999	1KM NORTH OF CASTLETON, N/B C/WAY
Safety Inspection of A83 Safety Inverary - Campbeltown on 11 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 18 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 25 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 01 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 08 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 15 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 22 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 29 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 06 July 2017									
<i>No defects recorded</i>									
Detailed Inspection TEMPLATE of A83 SHIRA BRIDGE TO A83 C43 (BRAE ROAD) JUNCTION on 20 June 2017									
NW80253085-528	2,107m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BALLIBEG STRAIGHT EAST OF CASTLETON, W/B C/WAY.
NW80253085-529	2,131m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BALLIBEG STRAIGHT EAST OF CASTLETON, W/B C/WAY.
NW80253085-530	2,144m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BALLIBEG STRAIGHT EAST OF CASTLETON, W/B C/WAY.
NW80253085-531	1,831m	0m	GRIP	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BALLIBEG STRAIGHT EAST OF CASTLETON, W/B VERGE.
NW80253085-532	1,880m	0m	GRIP	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BALLIBEG STRAIGHT EAST OF CASTLETON, E/B VERGE.
NW80253085-533	1,850m	0m	ROAD_MARKINGS _LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BALLIBEG STRAIGHT EAST OF CASTLETON, W/B C/WAY.

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW80253085-534	1,950m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BALLIBEG STRAIGHT EAST OF CASTLETON, W/B C/WAY.
NW80253085-535	2,220m	0m	GRIP	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BALLIBEG STRAIGHT EAST OF CASTLETON, W/B VERGE.
NW80253085-536	2,225m	0m	GRIP	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BALLIBEG STRAIGHT EAST OF CASTLETON, E/B VERGE.
NW80253085-537	2,252m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BALLIBEG STRAIGHT EAST OF CASTLETON, E/B C/WAY.
NW80253085-538	2,228m	0m	DITCH	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BALLIBEG STRAIGHT EAST OF CASTLETON, E/B VERGE
NW80253085-539	2,371m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BALLIBEG STRAIGHT EAST OF CASTLETON, E/B C/WAY.
NW80253085-552	2,836m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CASTLETON, CENTRE LINE.
NW80253085-553	2,829m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CASTLETON, W/B C/WAY.
NW80253085-554	2,978m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CASTLETON, W/B C/WAY.
NW80253085-555	2,972m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CASTLETON, W/B C/WAY.
NW80253085-556	2,998m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CASTLETON, E/B C/WAY.
NW80253085-557	3,007m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CASTLETON, E/B C/WAY.
NW80253085-558	3,029m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CASTLETON, CENTRE LINE.
NW80253085-559	3,058m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CASTLETON, CENTRE LINE.
NW80253085-513	111m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF PORT ANN, E/B VERGE.
NW80253085-514	129m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF PORT ANN, E/B VERGE.
NW80253085-515	138m	0m	ROAD_STUDS	Missing "catseye" (MISC)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF PORT ANN JCT, CENTRE LINE.
NW80253085-540	2,380m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BALLIBEG STRAIGHT EAST OF CASTLETON, E/B C/WAY.
NW80253085-541	2,397m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BALLIBEG STRAIGHT EAST OF CASTLETON, E/B C/WAY.
NW80253085-542	2,497m	0m	GRIP	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CASTLETON, W/B VERGE.
NW80253085-543	2,692m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CASTLETON, W/B C/WAY.

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW80253085-516	417m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF PORT ANN, W/B VERGE.
NW80253085-517	540m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF PORT ANN, W/B VERGE.
NW80253085-518	1,032m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF PORT ANN, W/B VERGE.
NW80253085-519	1,349m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF PORT ANN, W/B VERGE.
NW80253085-544	2,755m	0m	GRIP	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CASTLETON, W/B VERGE.
NW80253085-545	2,735m	0m	GRIP	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CASTLETON, E/B VERGE.
NW80253085-546	2,794m	0m	GRIP	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CASTLETON, W/B VERGE.
NW80253085-547	2,777m	0m	GRIP	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CASTLETON, E/B VERGE.
NW80253085-520	697m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF PORT ANN, E/B VERGE.
NW80253085-521	1,131m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF PORT ANN, E/B VERGE.
NW80253085-522	1,988m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BALLIBEG STRAIGHT EAST OF CASTLETON, E/B C/WAY.
NW80253085-523	2,016m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BALLIBEG STRAIGHT EAST OF CASTLETON, E/B C/WAY.
NW80253085-548	2,809m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CASTLETON, E/B C/WAY.
NW80253085-549	2,808m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CASTLETON, W/B C/WAY.
NW80253085-550	2,814m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CASTLETON, E/B C/WAY.
NW80253085-551	2,814m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CASTLETON, W/B C/WAY.
NW80253085-524	2,053m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BALLIBEG STRAIGHT EAST OF CASTLETON, E/B C/WAY.
NW80253085-525	2,036m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BALLIBEG STRAIGHT EAST OF CASTLETON, W/B C/WAY.
NW80253085-526	2,077m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BALLIBEG STRAIGHT EAST OF CASTLETON, W/B C/WAY.
NW80253085-527	2,071m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BALLIBEG STRAIGHT EAST OF CASTLETON, E/B C/WAY.
NW80253085-560	3,128m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST SIDE OF CASTLETON ACCESS, W/B C/WAY.

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW80253085-561	3,140m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST SIDE OF CASTLETON ACCESS, E/B C/WAY.
NW80253085-562	3,140m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST SIDE OF CASTLETON ACCESS.
NW80253085-563	3,147m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST SIDE OF CASTLETON ACCESS, E/B C/WAY.
NW80253085-564	3,163m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST SIDE OF CASTLETON ACCESS, W/B C/WAY.
NW80253085-565	3,159m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST SIDE OF CASTLETON ACCESS, E/B C/WAY.
NW80253085-566	3,203m	0m	FOOTWAY	Overgrown by vegetation (OVGV)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	OPPOSITE CASTLETON ACCESS, E/B FOOTWAY.
Annual Detailed Inspection - Carriageways of A83 SHIRA BRIDGE TO A83 C43 (BRAE ROAD) JUNCTION									
No defects recorded									
Detailed Inspection - Covers, Gratings and Frames of A83 SHIRA BRIDGE TO A83 C43 (BRAE ROAD) JUNCTION									
No defects recorded									
Detailed Inspection - Kerbs, Channels, Edgings of A83 SHIRA BRIDGE TO A83 C43 (BRAE ROAD) JUNCTION									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 13 July 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 20 July 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 27 July 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 03 August 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown (Awaiting Return)									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 17 August 2017									
NW31283440-235302183	913m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/08/2017	Completed Defects	17/08/2017	WEST OF PORT ANN, E/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 24 August 2017									
NWG11283727-235326685	678m	0m	TRAFFIC_SIGNS	Accident damage (ACCD)	CAT 1	21/09/2017	Completed Defects	18/09/2017	OPPOSITE BLUE ROCKS ACCESS, WEST OF PORT ANN. (E/B VERGE)
NWG11283727-235326686	671m	0m	BOLLARDS	Accident damage (ACCD)	CAT 1	21/09/2017	Completed Defects	18/09/2017	OPPOSITE BLUE ROCKS ACCESS, WEST OF PORT ANN. (E/B VERGE)
NWG11283727-235326687	3,096m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	25/08/2017	Completed Defects	24/08/2017	CASTLETON, E/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 31 August 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 07 September 2017									
NW31284755-235363863	3,102m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST SIDE EAST OF CASTLETON, BOTH SIDES OF C/WAY.
NW31284755-235363864	2,358m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	EAST OF CASTLETON, BOTH SIDES OF C/WAY.
NW31284755-235363865	2,447m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST EAST OF CASTLETON, W/B VERGE.
Safety Inspection of A83 Safety Inverary - Campbeltown on 14 September 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 21 September 2017									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 28 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 05 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 12 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 19 October 2017									
NWG11315441-235427450	3,107m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	20/10/2017	Completed Defects	19/10/2017	CASTLETON, E/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 26 October 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 02 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 09 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 16 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 23 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 30 November 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 07 December 2017									
NWG11316623-235487821	3,105m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	08/12/2017	Completed Defects	07/12/2017	CASTLETON, E/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 14 December 2017									
NW122316784-235487825	3,038m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	15/12/2017	Completed Defects	14/12/2017	JUST EAST OF CASTLETON, E/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 21 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 28 December 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 04 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 11 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 18 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 25 January 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 01 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 08 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 14 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 21 February 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 28 February 2018									
NW122322560-235550102	3,107m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	01/03/2018	Completed Defects	28/02/2018	CASTLETON, E/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 07 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 14 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 21 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 28 March 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 04 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown (Awaiting Return)									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 18 April 2018									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 25 April 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 02 May 2018									
NW122341824-235689814	179m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	PORT ANNE, E/B VERGE.
NW122341824-235689815	1,011m	0m	BOLLARDS	Damaged (DAMG)	CAT 1	30/05/2018	Completed Defects	18/05/2018	1KM WEST OF PORT ANNE, W/B VERGE.
NW122341824-235689816	1,850m	0m	TRAFFIC_SIGNS	Pointing wrong way (RWAY)	CAT 1	03/05/2018	Completed Defects	02/05/2018	1.8KM WEST OF PORT ANNE, E/B VERGE.
Safety Inspection of A83 Safety Inverary - Campbeltown on 09 May 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 16 May 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 23 May 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 30 May 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 06 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 13 June 2018									
<i>No defects recorded</i>									
Detailed Inspection TEMPLATE of A83 SHIRA BRIDGE TO A83 C43 (BRAE ROAD) JUNCTION on 30 April 2018									
NWG11328946-1130	153m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN & CASTLETON. (W/B C/WAY)
NWG11328946-1131	197m	0m	ROAD_STUDS	Missing "catseye" (MISC)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST SIDE PORT ANN ACCESS. (CENTRE LINE)
NWG11328946-1132	325m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS& CASTLETON. (W/B VERGE)
NWG11328946-1133	816m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS& CASTLETON. (W/B VERGE)
NWG11328946-1134	997m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS& CASTLETON. (W/B VERGE)
NWG11328946-1135	935m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	19/06/2019	BETWEEN PORT ANN ACCESS& CASTLETON. (W/B C/WAY)
NWG11328946-1136	909m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	19/06/2019	BETWEEN PORT ANN ACCESS& CASTLETON. (E/B C/WAY)
NWG11328946-1137	1,439m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS& CASTLETON. (W/B VERGE)
NWG11328946-1138	810m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS& CASTLETON. (E/B VERGE)
NWG11328946-1139	685m	0m	SCRUB	Obstructed sightline (OBSL)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	ACHNABA ACCESS, W/B VERGE. (BLUE ROCKS)
NWG11328946-1140	1,909m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1141	1,884m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG11328946-1142	1,828m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1143	1,825m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1167	1,804m	0m	GRIP	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B VERGE)
NWG11328946-1168	1,942m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1169	2,375m	0m	GRIP	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B VERGE)
NWG11328946-1144	1,822m	0m	VERGE	Dead, dying or damaged areas (DPDY)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B VERGE)
NWG11328946-1145	1,876m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1146	1,914m	0m	CATCHPIT	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B VERGE)
NWG11328946-1170	2,388m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1147	1,912m	0m	CATCHPIT	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B VERGE)
NWG11328946-1148	2,018m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1149	2,045m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1150	2,043m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1151	2,094m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1152	2,115m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1153	2,199m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1154	2,245m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1155	2,265m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1156	2,328m	0m	GRIP	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B VERGE)
NWG11328946-1157	2,292m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG11328946-1158	2,167m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1159	2,167m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1160	2,159m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1161	2,105m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1162	1,996m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1163	1,983m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1164	1,956m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1165	1,950m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1166	1,980m	0m	GRIP	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B VERGE)
NWG11328946-1171	2,406m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1172	2,415m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1173	2,433m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1174	2,463m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1175	2,470m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1176	2,469m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1177	2,483m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B VERGE)
NWG11328946-1178	2,494m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B VERGE)
NWG11328946-1179	2,509m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1180	2,554m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1181	2,736m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1182	2,760m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG11328946-1183	2,799m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1184	2,809m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1185	2,868m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1186	2,894m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1187	2,937m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1188	2,934m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1189	2,990m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1190	3,027m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1191	3,026m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1192	3,026m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (CENTRE LINE)
NWG11328946-1193	3,038m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B VERGE)
NWG11328946-1194	3,038m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B VERGE)
NWG11328946-1195	3,031m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1196	3,034m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1197	3,079m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1198	3,077m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1199	3,077m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1200	3,096m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG11328946-1201	3,096m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1202	3,105m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1203	3,105m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1204	3,106m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1205	3,122m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1206	3,134m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1207	3,104m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1208	3,035m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1209	3,030m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1210	3,022m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B VERGE)
NWG11328946-1211	3,010m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1212	2,998m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1213	2,952m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1214	2,924m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1215	2,881m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1216	2,863m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1217	2,838m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1218	2,826m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1219	2,808m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1220	2,792m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1221	2,787m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG11328946-1222	2,743m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1223	2,737m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1224	2,740m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1225	2,703m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1226	2,704m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1227	2,670m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (CENTRE LINE)
NWG11328946-1228	2,673m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1229	2,623m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1230	2,628m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1231	2,580m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1232	2,581m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1233	2,550m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1234	2,543m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1261	3,105m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1235	2,514m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1236	3,173m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)
NWG11328946-1237	3,173m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (W/B C/WAY)
NWG11328946-1238	3,173m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN PORT ANN ACCESS & CASTLETON. (E/B C/WAY)

Annual Detailed Inspection - Carriageways of A83 SHIRA BRIDGE TO A83 C43 (BRAE ROAD) JUNCTION

No defects recorded

Detailed Inspection - Covers, Gratings and Frames of A83 SHIRA BRIDGE TO A83 C43 (BRAE ROAD) JUNCTION

No defects recorded

Detailed Inspection - Kerbs, Channels, Edgings of A83 SHIRA BRIDGE TO A83 C43 (BRAE ROAD) JUNCTION

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 20 June 2018

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 27 June 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 04 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 11 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 18 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 25 July 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 01 August 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 08 August 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 15 August 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 22 August 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 29 August 2018									
NWG11398207-235983471	133m	0m	TRAFFIC_SIGNS	Missing (MISS)	CAT 1	26/09/2018	Completed Defects	26/09/2018	PORT ANN. (E/B VERGE)
Safety Inspection of A83 Safety Inverary - Campbeltown on 05 September 2018									
NWG11401465-236024753	3,043m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	06/09/2018	Completed Defects	05/09/2018	JUST EAST OF CASTLETON, E/B C/WAY.
NWG11401465-236024754	3,028m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	06/09/2018	Completed Defects	05/09/2018	JUST EAST OF CASTLETON, W/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 12 September 2018									
NWG11404872-236052672	757m	0m	TRAFFIC_SIGNS	Accident damage (ACCD)	CAT 1	10/10/2018	Completed Defects	21/09/2018	WEST SIDE OF BLUE ROCKS ACCESS, PORT ANN. (E/B VERGE)
NWG11404872-236052673	754m	0m	BOLLARDS	Accident damage (ACCD)	CAT 1	10/10/2018	Completed Defects	21/09/2018	WEST SIDE OF BLUE ROCKS ACCESS, PORT ANN. (E/B VERGE)
Safety Inspection of A83 Safety Inverary - Campbeltown on 19 September 2018									
NWG11408072-236060230	3,065m	0m	CARRIAGEWAY	Flooding (FLOD)	CAT 1	17/10/2018	Completed Defects	02/10/2018	EAST SIDE OF CASTLETON. (BOTH SIDES OF C/WAY)
Safety Inspection of A83 Safety Inverary - Campbeltown on 26 September 2018									
NW122411290-236081716	3,020m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	27/09/2018	Completed Defects	26/09/2018	CASTLETON, W/B C/WAY.
NW122411290-236081737	198m	0m	TRAFFIC_SIGNS	Pointing wrong way (RWAY)	CAT 1	27/09/2018	Completed Defects	26/09/2018	PORT ANN E/B VERGE.
Safety Inspection of A83 Safety Inverary - Campbeltown on 03 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 10 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 17 October 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 31 October 2018									
NW122425993-236178904	217m	0m	TRAFFIC_SIGNS	Pointing wrong way (RWAY)	CAT 1	01/11/2018	Completed Defects	31/10/2018	PORT ANN, E/B VERGE.
NW122425993-236178905	352m	0m	BOLLARDS	Damaged (DAMG)	CAT 1	28/11/2018	Completed Defects	15/11/2018	PORT ANN, W/B VERGE
Safety Inspection of A83 Safety Inverary - Campbeltown on 14 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 21 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 28 November 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 05 December 2018									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 12 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 19 December 2018									
NW122427406-236264307	897m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	28/02/2019	ACHNABA, WEST OF PORT ANN. (E/B C/WAY)
NW122427406-236264308	899m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	28/02/2019	ACHNABA, WEST OF PORT ANN. (W/B C/WAY)
NW122427406-236264309	1,703m	0m	BOLLARDS	Damaged (DAMG)	CAT 1	16/01/2019	Completed Defects	04/01/2019	WEST OF PORT ANN. (E/B VERGE)
NW122427406-236264310	3,019m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	20/12/2018	Completed Defects	19/12/2018	CASTLETON, W/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 21 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 28 December 2018									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 04 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 09 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 16 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 23 January 2019									
NW122428263-236284244	3,018m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	24/01/2019	Completed Defects	23/01/2019	NEAR CASTLETON, W/B C/WAY.
NW122428263-236284245	3,109m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	24/01/2019	Completed Defects	23/01/2019	NEAR CASTLETON, E/B C/WAY.
NW122428263-236284246	3,111m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	24/01/2019	Completed Defects	23/01/2019	NEAR CASTLETON, CENTRE LINE.
Safety Inspection of A83 Safety Inverary - Campbeltown on 30 January 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 06 February 2019									
NWG23-429030-236305335	3,104m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	07/02/2019	Completed Defects	06/02/2019	CASTLETON E/B
NWG23-429030-236305336	3,109m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	07/02/2019	Completed Defects	06/02/2019	CASTLETON E/B
NWG23-429030-236305337	3,117m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	07/02/2019	Completed Defects	06/02/2019	CASTLETON E/B
Safety Inspection of A83 Safety Inverary - Campbeltown on 13 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 20 February 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 27 February 2019									
NWG23-434346-236335211	3,035m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	28/02/2019	Completed Defects	27/02/2019	CASTLETON, W/B C/WAY.
NWG23-434346-236335212	3,030m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	28/02/2019	Completed Defects	27/02/2019	CASTLETON, E/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 06 March 2019									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 13 March 2019									
NWG23-443368-236345166	3,020m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	14/03/2019	Completed Defects	13/03/2019	(A83) CASTLETON
NWG23-443368-236345167	3,021m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	10/04/2019	Completed Defects	10/04/2019	(A83) CASTLETON

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG23-443368-236345168	3,117m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	10/04/2019	Completed Defects	10/04/2019	(A83) CASTLETON
Safety Inspection of A83 Safety Inverary - Campbeltown on 20 March 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 27 March 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 03 April 2019									
NW38462056-236494095	3,107m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/04/2019	Completed Defects	03/04/2019	CASTLETON, E/B C/WAY.
NW38462056-236494096	3,116m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/04/2019	Completed Defects	03/04/2019	CASTLETON, CENTRE LINE.
NW38462056-236494097	3,053m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/04/2019	Completed Defects	03/04/2019	CASTLETON, CENTRE LINE.
NW38462056-236494098	3,035m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/04/2019	Completed Defects	03/04/2019	CASTLETON, E/B C/WAY.
NW38462056-236494099	3,035m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/04/2019	Completed Defects	03/04/2019	CASTLETON, E/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 10 April 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 17 April 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 24 April 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 01 May 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 08 May 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 15 May 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 22 May 2019									
No defects recorded									
Annual Detailed Inspection - Carriageways of INVY 05 A83									
No defects recorded									
Detailed Inspection - Covers, Gratings and Frames of INVY 05 A83									
No defects recorded									
Detailed Inspection - Kerbs, Channels, Edgings of INVY 05 A83									
No defects recorded									
Detailed Inspection TEMPLATE of INVY 05 A83 on 29 May 2019									
NW38490749-109	30m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-121	225m	0m	ROAD_STUDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , CENTRE LINE.
NW38490749-122	267m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B VERGE.
NW38490749-123	297m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-118	90m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B C/WAY.
NW38490749-119	90m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B C/WAY.

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW38490749-120	90m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B C/WAY.
NW38490749-124	381m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B VERGE.
NW38490749-125	222m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) JUST WEST OF PORT ANN ACCESS, E/B VERGE.
NW38490749-126	829m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	19/06/2019	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-127	838m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	19/06/2019	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , CENTRE LINE.
NW38490749-128	876m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 2	01/01/9999	Completed Defects	19/06/2019	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-129	884m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	19/06/2019	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-130	885m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	19/06/2019	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-131	899m	0m	CARRIAGEWAY	Patch - material cracking (PMCK)	CAT 2	01/01/9999	Completed Defects	19/06/2019	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-132	902m	0m	CARRIAGEWAY	Patch - material cracking (PMCK)	CAT 2	01/01/9999	Completed Defects	19/06/2019	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-133	908m	0m	CARRIAGEWAY	Patch - material cracking (PMCK)	CAT 2	01/01/9999	Completed Defects	19/06/2019	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-134	944m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	19/06/2019	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B C/WAY.
NW38490749-135	1,001m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	19/06/2019	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B C/WAY.
NW38490749-136	1,033m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B C/WAY.
NW38490749-137	1,047m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	19/06/2019	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B C/WAY.
NW38490749-138	1,112m	0m	VERGE	Dead, dying or damaged areas (DPDY)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B VERGE.
NW38490749-139	1,128m	0m	TRAFFIC_SIGNS	Obscured sign (OBSG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B VERGE.
NW38490749-140	1,150m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B VERGE.
NW38490749-141	1,150m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	19/06/2019	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B C/WAY.
NW38490749-142	1,167m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	19/06/2019	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW38490749-143	1,297m	0m	VERGE	Dead, dying or damaged areas (DPDY)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B VERGE.
NW38490749-144	1,429m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B VERGE.
NW38490749-145	1,249m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B VERGE.
NW38490749-146	1,013m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B VERGE.
NW38490749-147	719m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B VERGE.
NW38490749-148	1,721m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B VERGE.
NW38490749-149	1,647m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-150	1,612m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-151	1,621m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-152	1,799m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-153	1,932m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B C/WAY.
NW38490749-154	1,879m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-155	1,836m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-156	1,836m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B C/WAY.
NW38490749-157	1,912m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B C/WAY.
NW38490749-158	2,113m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B C/WAY.
NW38490749-159	2,129m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B C/WAY.
NW38490749-160	2,146m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B C/WAY.
NW38490749-161	2,162m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B C/WAY.
NW38490749-162	2,187m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B C/WAY.

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW38490749-163	2,255m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-164	2,178m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-165	2,157m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-166	2,144m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-167	2,113m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-168	1,986m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-169	1,943m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-170	2,361m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B VERGE.
NW38490749-171	2,393m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B VERGE.
NW38490749-172	2,477m	0m	GRIP	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B VERGE.
NW38490749-173	2,910m	0m	GRIP	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B VERGE.
NW38490749-174	2,798m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-175	2,805m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-176	2,832m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-189	3,025m	0m	CARRIAGEWAY	Trench RI - material cracking (TMCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-190	3,029m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-191	3,028m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B C/WAY.
NW38490749-192	3,037m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-193	3,035m	0m	CARRIAGEWAY	Patch - material cracking (PMCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B C/WAY.
NW38490749-194	3,052m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , CENTRE LINE.

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW38490749-195	3,072m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , CENTRE LINE.
NW38490749-196	3,075m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B C/WAY.
NW38490749-197	3,103m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B C/WAY.
NW38490749-198	3,101m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-199	3,110m	0m	CARRIAGEWAY	Trench RI - material cracking (TMCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-200	3,111m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-201	3,109m	0m	CARRIAGEWAY	Patch - material cracking (PMCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B C/WAY.
NW38490749-202	3,117m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , CENTRE LINE.
NW38490749-203	3,126m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B C/WAY.
NW38490749-204	3,148m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , CENTRE LINE.
NW38490749-205	3,146m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-206	3,167m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , CENTRE LINE.
NW38490749-207	3,152m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B C/WAY.
NW38490749-177	2,841m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-178	2,873m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-179	2,881m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-180	2,888m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-181	2,911m	0m	GRIP	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B VERGE.
NW38490749-182	3,049m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B C/WAY.
NW38490749-183	3,026m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B C/WAY.

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW38490749-184	3,025m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , CENTRE LINE.
NW38490749-185	3,015m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-186	3,015m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , E/B C/WAY.
NW38490749-187	3,021m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B C/WAY.
NW38490749-188	3,024m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B C/WAY.
NW38490749-117	140m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) BETWEEN PORT ANN ACCESS & CASTLETON , W/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 29 May 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 05 June 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 12 June 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 19 June 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 26 June 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 03 July 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 10 July 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 17 July 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 24 July 2019									
NW38531333-236912446	2,168m	0m	MANHOLE	Flooding (FLOD)	3RD PTY	21/08/2019	Third Party Defects	01/01/9999	EAST OF CASTLETON E/B
Safety Inspection of A83 Safety Inverary - Campbeltown on 31 July 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 07 August 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 14 August 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 21 August 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 28 August 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 04 September 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 11 September 2019									
NW33533758-237014210	600m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	12/09/2019	Completed Defects	11/09/2019	A83 S/B BEFORE BLUE ROCKS
NW33533758-237014211	3,035m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	12/09/2019	Completed Defects	11/09/2019	A83 N/B BEFORE BALLIBEG
NW33533758-237014212	3,037m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	12/09/2019	Completed Defects	11/09/2019	A83 N/B BEFORE BALIBEG
NW33533758-237014213	3,122m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	12/09/2019	Completed Defects	11/09/2019	A83 S/B AT CASTLETON

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW33533758-237014214	3,124m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		A83 S/B CASTLETON
Safety Inspection of A83 Safety Inverary - Campbeltown on 18 September 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 25 September 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 02 October 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 09 October 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 16 October 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 23 October 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 30 October 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 06 November 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 13 November 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 20 November 2019									
NW33536648-237163002	276m	0m	REMOVE_ANIMAL	Carcass of dead animal (DEAD)	CAT 1	21/11/2019	Completed Defects	20/11/2019	A83 W/B PORT ANN
Safety Inspection of A83 Safety Inverary - Campbeltown on 27 November 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 04 December 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 11 December 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 18 December 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 24 December 2019									
NW38537692-237216080	3,115m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	25/12/2019	Completed Defects	24/12/2019	(A83) CASTLETON, CENTRE LINE.
NW38537692-237216081	3,109m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	25/12/2019	Completed Defects	24/12/2019	(A83) CASTLETON, CENTRE LINE.
NW38537692-237216082	3,105m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	25/12/2019	Completed Defects	24/12/2019	(A83) CASTLETON, E/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 31 December 2019									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 07 January 2020									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 14 January 2020									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 22 January 2020									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 29 January 2020									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 05 February 2020									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 11 February 2020									
NW33539330-237266324	223m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 1	10/03/2020	Completed Defects	09/03/2020	A83 E/B PORT ANN
Safety Inspection of A83 Safety Inverary - Campbeltown on 18 February 2020									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 25 February 2020									
NW38542823-237286343	3,105m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	26/02/2020	Completed Defects	25/02/2020	(A83) EAST OF CASTLETON, E/B C/WAY.
NW38542823-237286344	3,108m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	26/02/2020	Completed Defects	25/02/2020	(A83) EAST OF CASTLETON, E/B C/WAY.

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW38542823-237286345	3,078m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	26/02/2020	Completed Defects	25/02/2020	(A83) EAST OF CASTLETON, CENTRE LINE.
NW38542823-237286346	3,037m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	26/02/2020	Completed Defects	25/02/2020	(A83) EAST OF CASTLETON, E/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 03 March 2020									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 10 March 2020									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 17 March 2020									
NW33551827-237327324	3,108m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/03/2020	Completed Defects	17/03/2020	A83 - E/B - CASTLETON
NW33551827-237327325	3,103m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/03/2020	Completed Defects	17/03/2020	A83 - E/B - CASTLETON
NW33551827-237327326	3,100m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/03/2020	Completed Defects	17/03/2020	A83 - E/B - CASTLETON
NW33551827-237327327	3,111m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/03/2020	Completed Defects	17/03/2020	A83 - E/B - CASTLETON
NW33551827-237327328	3,116m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/03/2020	Completed Defects	17/03/2020	A83 - E/B - CASTLETON
Safety Inspection of A83 Safety Inverary - Campbeltown on 24 March 2020									
NW38554782-237329112	3,111m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	25/03/2020	Completed Defects	24/03/2020	(A83) CASTLETON, E/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 31 March 2020									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 07 April 2020									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 14 April 2020									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 21 April 2020									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 28 April 2020									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 05 May 2020									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 12 May 2020									
No defects recorded									