

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/01/2020 and 02/03/2020, and defects raised outside of inspections on the same Section(s) during this period.

(Road is 'A96',)
(Section Code is 17675/00) Or

(Section Code is 17675/13)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
17675/00 : JUNCTION A95 CRAIGELLACHIE TO JCT B9017 NEWMILL									
Safety Inspection of A95.A96 SAFETY INSPECTION on 02 January 2020									
No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 09 January 2020									
NE11-538159-237222437	356m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/02/2020	Completed Defects	30/01/2020	SB BFR HAUGHS BRIDGE
NE11-538159-237222438	356m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2		Cat 2 Awaiting Action		SB BFR HAUGHS BRIDGE
Safety Inspection of A95.A96 SAFETY INSPECTION on 16 January 2020									
No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 23 January 2020									
No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 30 January 2020									
No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 06 February 2020									
No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 13 February 2020									
No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 20 February 2020									
No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 27 February 2020									
NE11543331-237291158	501m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	28/02/2020	Completed Defects	27/02/2020	SB BFR A95 JCT
17675/13 : JUNCTION B9017 NEWMILL TO JUNCTION B9016 BUCKIE									
Safety Inspection of A95.A96 SAFETY INSPECTION on 02 January 2020									
No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 09 January 2020									
No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 16 January 2020									
No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 23 January 2020									
No defects recorded									
Safety Inspection of A95.A96 SAFETY INSPECTION on 30 January 2020									
NE11538772-237249936	464m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/02/2020	Completed Defects	25/02/2020	NB BFR B9016 JTN
NE11538772-237249937	466m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/02/2020	Completed Defects	25/02/2020	NB BFR B9016 JTN
NE11538772-237249938	466m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/02/2020	Completed Defects	25/02/2020	NB BFR B9016 JTN
NE11538772-237249939	464m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 2		Cat 2 Awaiting Action		NB BFR B9016 JTN
NE11538772-237249940	467m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 2		Cat 2 Awaiting Action		NB BFR B9016 JTN
NE11538772-237249941	464m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 2		Cat 2 Awaiting Action		NB BFR B9016 JTN
Safety Inspection of A95.A96 SAFETY INSPECTION on 06 February 2020									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 13 February 2020									
<i>No defects recorded</i>									
Safety Inspection of A95.A96 SAFETY INSPECTION on 20 February 2020									
NE11540391-237278610	346m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/03/2020	Completed Defects	19/03/2020	NB BFR LITTLE FORGIE
Safety Inspection of A95.A96 SAFETY INSPECTION on 27 February 2020									
<i>No defects recorded</i>									