

Action Date	Actions Taken
19/12/2019 14:55:00	ISU have requested a Sweeper via the Supervisor re Mud on the C/Way.
19/12/2019 14:55:00	HGV off road on its side in a field. Police in attendance dealing.
19/12/2019 15:28:00	D/G Supervisor update - HGV is Off Road but unable to be recovered at this stage. It is Eastbound at the top of the climbing lane and has caused quite a bit of verge damage so far. Police have stated that the company is arranging the Recovery. Still to establish if loaded or not and if so what with. With regards to the Recovery TM will have to be put out. The area where the vehicle has come to rest would appear to be marshy.
19/12/2019 15:34:00	Traffic Scotland updated.
19/12/2019 15:53:00	D/G Supervisor update - Recovery Company are bringing down a Rotator from Stirling due to the resting place of the HGV, bottom of a steep embankment. To facilitate the recovery it will require the A75 to be Closed at Allanton Rbt Northbound and Haugh of Urr Southbound running the traffic via Dalbeattie. The Closure points will be manned at all times to assist any vehicular traffic which is lost or unsure of the Diversion Route.
19/12/2019 15:53:00	The vehicle is loaded but unaware with what so far. Time factor for the start will be 23:00 Hrs for 2/3 Hrs. Traffic Scotland aware.
19/12/2019 23:24:00	A75 is now closed in both directions and diversion is in place. Diversion is via Dalbeattie.
19/12/2019 23:28:00	Traffic Scotland updated.
19/12/2019 23:33:00	sent - A75 is closed in both directions between Allanton rbt and Haugh of Urr junction for recovery of an HGV involved in an RTC earlier today. A local diversion, via Dalbeattie is in place. The road is expected to be closed for a couple of hours .
19/12/2019 23:34:00	Tweeted.
20/12/2019 01:38:00	HGV recovered and road now opened.
20/12/2019 01:42:00	Traffic Scotland informed.
20/12/2019 01:44:00	ISR sent - HGV recovered and road now fully reopened.
20/12/2019 01:46:00	Tweeted.
20/12/2019 01:57:00	Passed to Dumfries for DCP.

[Roadwork: SW20172620](#)


**Operating Company Contract:**


South West Unit - Transerv

A75 East of Collier

**Roadwork Identifier:** SW20172620

**Route:**

 **Start:** A75 - Mousewald Ldge Jct to Forthorwald Jct (55.06271°, -3.48425°)

 **End:** A75 - Mousewald Ldge Jct to Forthorwald Jct (55.06130°, -3.48788°)

**Direction:**

Eastbound

**SRWR Reference Number:**

2385838 2386184

**Diversions:****Westbound**

Closure of A75 at Annan Bypass West (B721) leaves taking left onto B721 towards Annan – at B723 junction take left – continue on B723 towards Lockerbie passing through Kettleholm – first roundabout on approach to Lockerbie – proceed straight through onto B7076 – travel parallel with A74 (M) – take right onto slip road to A709 then right onto Dumfries Road, Lockerbie (A709) – continue to Lochmaben travelling on Lockerbie Road, High Street and then continuing left onto Bruce Street (all on A709) – continue on A709 to the A75 Dumfries Bypass – to rejoin the A75.

**Eastbound**

Commence on A75 at Dumfries Bypass (A709), take left at roundabout onto A709 – continue on A709 to Bruce Street Lochmaben – continue right onto High Street (A709) then Lockerbie Road – continue on A709 to Dumfries Road Lockerbie – continue across A74(M) and B7076 – take left onto B7076 loop (after Annandale Avenue) then left again onto B7076 southbound – continue to roundabout and take 2nd exit onto B723 (southbound) passing through Kettleholm – continue to junction Annan ByPass West – take left to rejoin A75.

**Estimated Delay:**

1 - Little or No Delay, 3 - Off Peak Hours


**Emergency Reason:**

Weather

**Works Periods:**

Work Start	Work End	Work Description
14/12/2017 19:00	15/12/2017 02:00	Road Closure
21/12/2017 19:00	22/12/2017 02:00	Road Closure

**Works Activities:**

Work Activity Type	Contractors	Completion
Emergency Works	D & G Commercial Services (Primary) 	4 of 4 Completed

**Communication Logs:**

Log Type	Details
----------	---------

Roadwork: SW/2018/6623


**Operating Company Contract:**

South West Unit - Transerv

A75 Carrutherstown

**Roadwork Identifier:** SW/2018/6623

**Route:**

 **Start:** A75 - Ws2+1 End Carrutherstown to B752 Access (55.03198°, -3.40446°)

 **End:** A75 - Ws2+1 End Carrutherstown to B752 Access (55.03207°, -3.40503°)

**Direction:**

Westbound

**SRWR Reference Number:**

2538577

**Diversion:**

Fullw Diversion signs exit next Right into Carrutherstown

**Estimated Delay:**

1 - Little or No Delay, 3 - Off Peak Hours

**Works Periods:**

Work start	Work End	Work Management
29/10/2018 09:30	29/10/2018 15:30	Road Closure

**Works Activities:**

Work Activity Type	Committee	UTILITIES
Sign Installation/Repairs	Scotland Transerv (Primary) 	1 of 1 Completed.

**Communication Logs:**

Log Type	Description
Note	A75 Total closure of the left turn in to Carrutherson Village from the A75 WB
Status Update	Roadwork status changed to "Requires Clarification", Reason given: Please clarify direction.

**Draft Media Release (optional):**

[Home](#) / [View Roadwork](#) / [SW/2018/4340, SW/2018/4341](#)


**Operating Company Contract:**  
South West Unit - Transerv

A75 Voldbank to Justenices

**Roadwork Identifier:** SW/2018/4340

**Route:**

 Start: A75 - B722 O'Bridge to Annan Jct West (54.99502°, -3.20002°)

 End: A75 - B7020 Jct to Jct Ladyfield (55.00161°, -3.30894°)

**Direction:**

Eastbound

**SRWR Reference Number:**

2407930 2407931

**Diversion:**

Eastbound traffic on the A75 at Dumfries will be informed whilst on the Dumfries bypass of the works, and directed to the A709 road to Lockerbie.

**Estimated Delay:**

3 - Moderate Delay, 1 - At All Times

**Emergency Reason:**

Carriageway Defect

**Works Periods:**

Work Start	Work End	Traffic Management
06/04/2018 19:00	13/04/2018 06:00	Road Closure

**Works Activities:**

Works Activity Type	Contractors	Start/End
Resurfacing	James Findlay Contracting (Primary) 	12 of 12 Completed.

**Communication Logs:**

Log Type	Details
Log Type: Note	Description: Weekend total closure and overnight closures for resurfacing.
Log Type: VMS Update Request	Description: VMS request VMS Location: VMS/Q5
Log Type: VMS Update Request	Description: VMS request VMS Location: VMS/Q1

Draft Media Release (optional):

A75 Justenlees to Violethank

Roadwork Identifier: SW/2018/4341

**Route:**

- **Start: A75** (55.00184°, -3.30081°)
- **End: A75** (54.99535°, -3.27980°)

**Direction:**

Westbound

**SRWR Reference Number:**

2407930 2407931

**Diversion:**

Westbound traffic will be diverted off of the A75 at the Stapleton Road Junction and will proceed through Annan then B723 and A709 to Dumfries and vice versa .

**Estimated Delay:**

3 - Moderate Delay, 1 - At All Times

**Emergency Reason:**

Carriageway Defect

**Works Periods:**

Work Start	Work End	Team/Management
06/04/2018 19:00	13/04/2018 06:00	Road Closure

**Works Activities:**

Works Activity Type	Contractors	Status
Resurfacing	James Findlay Contracting (Primary)	12 of 12 Completed.

**Communication Logs:**

Log Type	Details
----------	---------

There are no communications logs to display.

Draft Media Release (optional):

Roadworks: SW/2018/4718, SW/2018/4719

**Operating Company Contract:**

South West Unit - Transov

A75 Hardrigg		
<b>Roadwork Identifier:</b> SW/2018/4718		
<b>Route:</b>		
	<b>Start:</b> A75 - Annan Jct East to B722 O'Bridge	(54.98516°, -3.23125°)
	<b>End:</b> A75 - Eastriggs Jct to Annan Jct East	(54.99292°, -3.20471°)
<b>Direction:</b>		
Eastbound		
<b>SRWR Reference Number:</b>		
2410676		
<b>Diversions:</b>		
Eastbound - Turn Right off of A75 and then onto B721 and head through Annan onto Eastriggs, continue towards Gretna, re-join A75 using B721.		
Westbound - Off A75 onto B721 turn right to continue on B721 through Eastriggs and onto Annan and continue on B721 to re-join A75		
<b>Estimated Delay:</b>		
2 - Slight Delay, 3 - Off Peak Hours		
<b>Works Periods:</b>		
<b>Work Start</b>	<b>Work End</b>	<b>Traffic Management</b>
18/05/2018 19:00	28/05/2018 06:00	Road Closure
<b>Works Activities:</b>		
<b>Work Activity Type</b>	<b>Contractors</b>	<b>Progress</b>
Resurfacing	Scotland TransServ (Primary) 	16 of 16 Completed.
<b>Communication Logs:</b>		
<b>Log Type</b>	<b>Content</b>	
Log Type: Note	Description: resurfacing works	
<b>Draft Media Release (optional):</b>		

A75 Hardrigg		
<b>Roadwork Identifier:</b> SW/2018/4719		
<b>Route:</b>		



Start: A75

(54.99269°, -3.20589°)



End: A75

(54.99555°, -3.23782°)

**Direction:**

Westbound

**SRWR Reference Number:**

2410675

**Diversion:**

Eastbound - Turn Right off of A75 and then onto B721 and head through Annan onto Eastriggs, continue towards Gretna, re-join A75 using B721.

Westbound - Off A75 onto B721 turn right to continue on B721 through Eastriggs and onto Annan and continue on B721 to re-join A75

**Estimated Delay:**

2 - Slight Delay, 3 - Off Peak Hours

**Works Periods:**

Work Start	Work End	Traffic Management
18/05/2018 19:00	28/05/2018 06:00	Road Closure

**Works Activities:**

Works Activity Type	Contractor	Progress
Resurfacing	Scotland Transerv (Primary)	11 of 16 Completed. 5 of 16 Cancelled.

**Communication Logs:**

Log Type	Details
----------	---------

There are no communications logs to display.

**Draft Media Release (optional):**


Roadworks: SW/2018/5003, SW/2018/5004


**Operating Company Contract:**

South West Unit - Transerv

A75 The Glan

Roadwork Identifier: SW/2018/5003

**Route:**
 Start: A75 - Drummore Roundabout to End Of Dual Carriageway (55.05537°, -3.71850°)

 End: A75 - End Carronh Loaning Rbt In Start 3 Lane Carriageway (55.06137°, -3.65622°)
**Direction:**

Eastbound

**SRWR Reference Number:**

LA2470541

**Diversion:**

Westbound – A75, U225n, A711, B794, A75 Eastbound – A75, B794, A711, U225n, A75


**Estimated Delay:**

3 - Moderate Delay, 3 - Off Peak Hours

**Works Periods:**

Work Start	Work End	Traffic Management
22/06/2018 19:00	23/06/2018 08:00	Road Closure

**Works Activities:**

Work activity type	Contractors	CRANES
Resurfacing	Scotland TranServ (Primary) 	2 of 2 Completed

**Communication Logs:**

Log Type	Details
There are no communications logs to display.	

**Draft Media Release (optional):**

A75 The Glan

Roadwork Identifier: SW/2018/5004

**Route:**
 Start: A75 (55.06120°, -3.65583°)

 End: A75 (55.05571°, -3.71905°)
**Direction:**

Westbound

**SRWR Reference Number:**



LA2470541

**Diversion:**

Westbound – A75, U225n, A711, B794, A75 Eastbound – A75, B794, A711, U225n, A75

**Estimated Delay:**

3 - Moderate Delay, 3 - Off Peak Hours

**Works Periods:**

Work Start	Work End	Traffic Management
22/06/2018 19:00	23/06/2018 06:00	Road Closure

**Works Activities:**

Works activity type	Contractors	STATUS
Resurfacing	Scotland TransServ (Primary) 	2 of 2 Completed.

**Communication Logs:**

Log Type	Details
----------	---------

There are no communications logs to display.

Draft Media Release (optional):

Roadworks: SW/2018/5650, SW/2018/5651

**Operating Company Contract:**

South West Unit - Transerv

A75 The Glen

Roadwork Identifier: SW/2018/5650

**Route:**
 Start: A75 (55.06137°, -3.65650°)

 End: A75 (55.05582°, -3.71859°)
**Direction:**

Westbound

**SRWR Reference Number:**

2410769

**Diversion:**

No Diversion


**Estimated Delay:**

1 - Little or No Delay, 3 - At All Times

**Works Periods:**

Work Start	Work End	Public Management
24/08/2018 19:00	27/08/2018 06:00	Lane Closure

**Works Activities:**

Works Activity Type	Contractor's	Stages
Resurfacing	Breedon Aggregates Ltd (Primary) 	4 of 4 Completed

**Communication Logs:**


Log type	Media
There are no communications logs to display.	

Draft Media Release (optional):

A75 The Glen

Roadwork Identifier: SW/2018/5651

**Route:**
 Start: A75 - Drummore Roundabout to End of Dual Carriageway (55.05582°, -3.71839°)

 End: A75 - End Garraeh Loaning RBL to Start 3 Lane Carriageway (55.06137°, -3.65645°)
**Direction:**

Eastbound

**SRWR Reference Number:**

2410769

**Diversion:**

SUR: A75 - B794 - A711 - U225 - A75

**Estimated Delay:**

3 - Moderate Delay, 1 - At All Times

**Works Periods:**

Work-Start	Work-End	Traffic/other comments
24/08/2018 19:00	27/08/2018 06:00	Road Closure

**Works Activities:**

Works activity type	Contractors	Progress
Resurfacing	Breedon Aggregates Ltd (Primary) <a href="#">[A]</a>	4 of 4 Completed.

**Communication Logs:**

Log Type	Details
----------	---------

There are no communications logs to display.

**Draft Media Release (optional):**

[Roadwork: SW/2018/5772, SW/2018/5773](#)


**Operating Company Contract:**


South West Unit - Transery

A75 The Glen

Roadwork Identifier: SW/2018/5772

**Route:**

 Start: A75 - Drummore Roundabout to End Of Deul Carriageway (55.05589°, -3.71857°)

 End: A75 - Start Garroch Loaning Rbt to End Garroch Loaning Rbt (55.06135°, -3.65607°)

**Direction:**

Eastbound

**SRWR Reference Number:**

2410769

**Diversion:**

Eastbound: A75 - B794 - A711 - U225 - A75


**Estimated Delay:**

3 - Moderate Delay, 3 - Off Peak Hours

**Works Periods:**

Work Start	Work End	Utility Management
29/08/2018 19:00	30/08/2018 06:00	Road Closure

**Works Activities:**

Work Activity Type	Contractors	Status
Resurfacing	Breedon Aggregates Ltd (Primary) 	2 of 2 Completed

**Communication Logs:**

Log Type

There are no communications logs to display.

**Draft Media Release (optional):**

A75 The Glen

Roadwork Identifier: SW/2018/5773

**Route:**

 Start: A75 (55.08121°, -3.65600°)

 End: A75 (55.05572°, -3.71853°)

**Direction:**

Westbound

**SRWR Reference Number:**

2410769

**Diversion:**

No Diversion


**Estimated Delay:**

3 - Moderate Delay, 3 - Off Peak Hours

**Works Periods:**

Work Start	Work End	Traffic Management
29/08/2018 19:00	30/08/2018 06:00	Road Closure

**Works Activities:**

Work Activity Type	Contractors	Status
Resurfacing	Breedon Aggregates Ltd (Primary) 	2 of 2 Completed

**Communication Logs:**

Log Type	Message
----------	---------

There are no communications logs to display.

**Draft Media Release (optional):**

Filter by location SW/2018/5983, SW/2018/5984


### Operating Company Contract:

South West Unit - Transerv

A75 Barmcross to Ringford

**Roadwork Identifier:** SW/2018/5983

#### Route:

 **Start:** A75 - A711 Jct in Barmcross Layby (54.90831°, -4.00721°)

 **End:** A75 - Barmcross Layby to Jct Ringford East (54.90121°, -4.03102°)

#### Direction:

Eastbound

#### SRWR Reference Number:

2497096

#### Diversion:

A75, A711, A762, A75


#### Estimated Delay:

3 - Moderate Delay, 3 - Off Peak Hours

#### Works Periods:

Work Start	Work End	Traffic Management
04/10/2018 19:00	05/10/2018 06:00	Convoy Working
05/10/2018 19:00	12/10/2018 07:00	Road Closure

#### Works Activities:

Works Activity Type	Contractors	Milestones
Resurfacing	Scotland Transerv (Primary) 	14 of 14 Completed

#### Communication Logs:

Log Type  Filter

There are no communications logs to display.

#### Draft Media Release (optional):

A75 Barmcross to Ringford

**Roadwork Identifier:** SW/2018/5984

#### Route:

 **Start:** A75 (54.90831°, -4.00721°)

 **End:** A75 (54.90121°, -4.03102°)

#### Direction:

Westbound

**SRWR Reference Number:**

2497096

**Diversion:**

A75 A762 A/11 A/5


**Estimated Delay:**

3 - Moderate Delay, 3 - Off Peak Hours

**Works Periods:**

Work Start	Work End	Queue Management
04/10/2018 19:00	05/10/2018 06:00	Convoy Working
05/10/2018 19:00	12/10/2018 07:00	Road Closure

**Works Activities:**

Works Activity Type	Contractor	Statuses
Resurfacing	Scotland Transerv (Primary) 	14 of 14 Completed.

**Communication Logs:**

Log Type	Details
----------	---------

There are no communications logs to display.

**Draft Media Release (optional):**

Roadworks: SW/2018/5621, SW/2018/5622

**Operating Company Contract:**

South West Unit - Transov

A77 Slair Drive

**Roadwork Identifier:** SW/2018/5621

**Route:**

● **Start:** A77 (54.90349°, -5.01749°)

■ **End:** A77 (54.90504°, -5.01838°)

**Direction:**  
Northbound

**SRWR Reference Number:**  
2410764

**Diversion:**  
Leave A77 at Innamrossan A/51 Jct - cont A751 to A751 onton Road - cont A75 - A77 Slair Drive Jct

**Estimated Delay:**  
2 - Slight Delay, 2 - Peak Hours

**Works Periods:**

Work Start	Work End	Traffic Management
06/08/2018 07:00	10/08/2018 18:00	Road Closure

**Works Activities:**

Work Activity Type	Contractors	Progress
Resurfacing	Breedon Aggregates Ltd (Primary) <a href="#">[a]</a>	5 of 5 Completed

**Communication Logs:**

Log Type	Details
There are no communications logs to display.	

**Draft Media Release (optional):**

A77 Slair Drive

**Roadwork Identifier:** SW/2018/5622

**Route:**

● **Start:** A77 - A75 Jct to A718 Jct (54.90504°, -5.01819°)

■ **End:** A75 - 40 Mph Xroads to A75 Jct (54.90351°, -5.01741°)

**Direction:**  
Southbound

**SRWR Reference Number:**



2410764

**Diversion:**

Leave A77 at Innermessan A751 Jct - cont A751 to A75 London Road - cont A75 - A77 Stair Drive Jct

**Estimated Delay:**

2 - Slight Delay, 2 - Peak Hours

**Works Periods:**

Work Start	Work End	Traffic Management
08/08/2018 07:00	10/08/2018 18:00	Road Closure

**Works Activities:**

Work Activity Type	Contractors	Status
Resurfacing	Breedon Aggregates Ltd (Primary) 	5 of 5 Completed

**Communication Logs:**

Log Type	Details
----------	---------

There are no communications logs to display.

Draft Media Release (optional):

Roadworks: SW/2019/8127, SW/2019/8128


**Operating Company Contract:**


South West Unit - Transerv

A75 Burnside to Ladyfield

Roadwork Identifier: SW/2019/8127

**Route:**

 **Start:** A75 - Annan Jct West to B7020 Jct (54.99597°, -3.28539°)

 **End:** A75 - B7020 Jct to Jct Ladyfield (55.00354°, -3.31562°)

**Direction:**

Westbound

**SRWR Reference Number:**

2595142

**Diversion:**

A75 - B721 - B723 - B7076 - A709 - A75

**Estimated Delay:**

3 - Moderate Delay, 1 - At All Times


**Emergency Reason:**

Late Programmed Works

**Works Periods:**

Work Start	Work End	Traffic Management
15/03/2019 19:00	22/03/2019 06:00	Road Closure
22/03/2019 19:00	23/03/2019 06:00	Portable Traffic Lights (TTLs)

**Works Activities:**

Work Activity Type	Contractors	Status
Resurfacing	Breedon Aggregates Ltd (Primary) 	14 of 14 Completed

**Communication Logs:**

Log Type	Units
Log Type: Note	Description: Total closure for weekend becoming night shift closures during week
Log Type: Note	Description: Total closure not required on Fri 22 - this will be 3 way TTL

Draft Media Release (optional):

A75 Burnside to Ladyfield

Roadwork Identifier: SW/2019/8128

Route:

 Start: A75 (54.99597°, -3.28639°)

 End: A75 (55.00354°, -3.31562°)

Direction:

Eastbound

SRWR Reference Number:

2595142

Diversion:

A75 - A709 - B7076 - B723 - B721 - A75

Estimated Delay:

3 - Moderate Delay, 1 - At All Times

Emergency Reason:

Late Programmed Works

Works Periods:

Work Start	Work End	Traffic Management
15/03/2019 19:00	22/03/2019 06:00	Road Closure
22/03/2019 19:00	23/03/2019 06:00	Portable Traffic Lights (TTLS)

Works Activities:

Works Activity Type	Contractors	Stations
Resurfacing	Breadon Aggregates Ltd (Primary) 	14 of 14 Completed

Communication Logs:

Log Type	Details
Log Type: Note	Description: Total closure not required on Fri 22 - this will be 3 way TTL

Draft Media Release (optional):

Workworkset: SW/2018/5652, SW/2018/5653

**Operating Company Contract:**

South West Unit - Transco

A75 The Glen

**Roadwork Identifier:** SW/2018/5652

**Route:**

- **Start:** A75 - Drummore Roundabout to End Of Dual Carriageway (55.05587°, -3.71857°)
- **End:** A75 - End Garroch Loaning Rbt to Start 3 Lane Carriageway (55.08133°, -3.65632°)

**Direction:**  
Eastbound

**SRWR Reference Number:**  
2410789

**Diversion:**  
Eastbound closure of A75 The Glen

**SDR:** A75 - B794 - A711 - U225 - A75

**Estimated Delay:**  
3 - Moderate Delay, 3 - Off Peak Hours

**Works Periods:**

Work Start	Work End	Traffic Management
27/08/2018 19:00	29/08/2018 06:00	Road Closure

**Works Activities:**

Work Activity Type	Contractors	Status
Resurfacing	Breedon Aggregates Ltd (Primary)	4 of 4 Completed

**Communication Logs:**

Log Type	Created
There are no communications logs to display.	

**Draft Media Release (optional):**

A75 The Glen

**Roadwork Identifier:** SW/2018/5653

**Route:**

- **Start:** A75 (55.08132°, -3.65623°)
- **End:** A75 (55.05573°, 3.71846°)

**Direction:**  
Westbound

**SRWR Reference Number:**

2410769

**Diversion:**

No Diversion


**Estimated Delay:**

3 - Moderate Delay, 3 - Off Peak Hours

**Works Periods:**

Work Start	Work End	Traffic Management
27/08/2018 19:00	29/08/2018 06:00	Lane Closure

**Works Activities:**

Works Activity Type	Contractor	Statuses
Resurfacing	Breedon Aggregates Ltd (Primary) 	3 of 3 Completed.

**Communication Logs:**

Log Type	Details
----------	---------

There are no communications logs to display.

**Draft Media Release (optional):**


Roadwork: SW/2018/5985, SW/2018/5985


**Operating Company Contract:**

South West Unit - Transrv

A75 Ram Hill, Castle Douglas

Roadwork Identifier: SW/2018/5985

**Route:**
 **Start:** A75 - B/94 Junction to Start Of Climbing Lane (54.97712°, -3.88881°)

 **End:** A75 - Allanton Rd to Allanton Rd (54.95811°, -3.91788°)
**Direction:**

Eastbound

**SRWR Reference Number:**

2523737

**Diversion:**

A75, B794 haugh of Ur, A745, A75


**Estimated Delay:**

3 - Moderate Delay, 3 - Off Peak Hours

**Works Periods:**

Work Start	Work End	Traffic Management
30/09/2018 19:00	05/10/2018 07:00	Road Closure

**Works Activities:**

Works Activity Type	Completion	Status
Resurfacing	Scotland Transerv (Primary) 	10 of 10 Completed

**Communication Logs:**

View Logs [Message](#)

There are no communications logs to display.

**Draft Media Release (optional):**

A75 Ram Hill, Castle Douglas

Roadwork Identifier: SW/2018/5985

**Route:**
 **Start:** A75 (54.97712°, -3.88881°)

 **End:** A75 (54.95811°, -3.91788°)
**Direction:**

Westbound

**SRWR Reference Number:**

Not Specified

**Diversion:**

A75,A745,B794 Haugh of Urr,A75


**Estimated Delay:**

3 - Moderate Delay, 3 - Off Peak Hours

**Works Periods:**

Work Start	Work End	Traffic Management
30/09/2018 19:00	05/10/2018 07:00	Road Closure

**Works Activities:**

Work Activity Type	Contractors	Statuses
Resurfacing	Scotland TransServ (Primary) 	10 of 10 Completed.

**Communication Logs:**

Log Type	Details
----------	---------

There are no communications logs to display.

**Draft Media Release (optional):**

https://cms.traffic.scotland.co.uk/Roadworks/Roadwork/Index/32925?active=SW%2F2018%2F6482


**Operating Company Contract:**


South West Unit - Transerv

A75 Crocketford to Auchencrooch Loch

Roadwork Identifier: SW/2018/6482

**Route:**

 Start: A75 - Jct Branchedleys to Jct Lairdlaugh (55.01383°, -3.83270°)

 End: A75 - Jct Branchedleys to Jct Lairdlaugh (55.02762°, -3.83904°)

**Direction:**

Westbound

**SRWR Reference Number:**

2510126

**Diversion:**

Eastbound - A75, B794, A711, U225n, A75  
Westbound - A75, U225n, A711, B794, A75

**Estimated Delay:**

3 - Moderate Delay, 1 - At All Times

**Works Periods:**

Work Start	Work End	Traffic Management
28/10/2018 19:00	29/10/2018 06:00	Road Closure

**Works Activities:**

Work Activity Type	Contractor	Status
Resurfacing	Breedon Aggregates Ltd (Primary) 	4 of 4 Completed

**Communication Logs:**

Add Type:

There are no communications logs to display.

**Draft Media Release (optional):**

A75 Crocketford to Auchencrooch Loch

Roadwork Identifier: SW/2018/6483

**Route:**

 Start: A75 (55.02755°, -3.83987°)

 End: A75 (55.03381°, -3.83266°)

**Direction:**

Eastbound

**SRWR Reference Number:**



2510126

**Diversion:**

Eastbound – A75, B794, A711, U225n, A75  
 Westbound – A75, U225n, A711, B794, A75

**Estimated Delay:**

3 - Moderate Delay, 1 - At All Times

**Works Periods:**

Work Start	Work End	Traffic Management
26/10/2018 19:00	29/10/2018 06:00	Road Closure

**Works Activities:**

Work Activity Type	Contractors	Progress
Resurfacing	Breedon Aggregates Ltd (Primary)	4 of 4 Completed.

**Communication Logs:**Log Type: [Events](#)

There are no communications logs to display.

**Draft Media Release (optional):****A75 Crocketford to Auchanreoch Loch**

Roadwork Identifier: SW/2018/6484

**Route:**

Start: A75	(55.03362°, -1.83307°)
End: A75	(55.02757°, -3.84005°)

**Direction:**

Westbound

**SRWR Reference Number:**

2510126

**Diversion:**

Eastbound – A75, B794, A711, U225n, A75  
 Westbound – A75, U225n, A711, B794, A75

**Estimated Delay:**

3 - Moderate Delay, 3 - Off Peak Hours

**Works Periods:**

Work Start	Work End	Traffic Management
29/10/2018 19:00	30/10/2018 06:00	Road Closure

**Works Activities:**

Work Activity Type	Contractors	Progress
Resurfacing	Breedon Aggregates Ltd (Primary)	2 of 2 Completed.

## Communication Logs:

Log type

Search

There are no communications logs to display.

## Draft Media Release (optional):

## A75 Crockerford to Auchincrook Loch

Roadwork Identifier: SW/2018/6485

## Route:

 Start: A75 (55.02760°, -3.83982°)

 End: A75 (55.03380°, -3.83297°)

## Direction:

Eastbound

## SRWR Reference Number:

2510126

## Diversion:

Eastbound – A75, B794, A711, U225n, A75  
 Westbound – A75, U225n, A711, B794, A75

## Estimated Delay:

3 - Moderate Delay, 3 - Off Peak Hours

## Works Periods:

Work Start	Work End	Traffic Management
29/10/2018 19:00	30/10/2018 06:00	Road Closure

## Works Activities:

Work Activity Type	Contributor	Progress
Resurfacing	Breedon Aggregates Ltd (Primary) 	2 of 2 Completed.

## Communication Logs:

Log type

Search

There are no communications logs to display.

## Draft Media Release (optional):

## Roadworks SW/2019/10997, SW/2019/10998


## Operating Company Contract:


South West Unit - Transerv

A75 Springholm

Roadwork Identifier: SW/2019/10997

## Route:

 Start: A75 - Jct Lairdlaugh to Auchenreoch Br (55.01453°, -3.86398°)

 End: A75 - Auchenreoch Br to Jct Garmartin (55.00430°, -3.87115°)

## Direction:

Eastbound

## SRWR Reference Number:

2682009 2682010

## Diversion:

Eastbound – A75, B794, A711, U225n, A76

Westbound – A75, U225n, A711, A745, A75

## Estimated Delay:

3 - Moderate Delay, 1 - At All Times

## Emergency Reason:

Late Programmed Works

## Works Periods:

Work Start	Work End	Traffic Management
10/10/2019 19:00	24/10/2019 06:00	Road Closure

## Works Activities:

WORKS ACTIVITY TYPE	COMPANIES	PROGRESS
Resurfacing	Bredon Aggregates Ltd (Secondary)  Markon (Secondary)  Phoenix (Secondary)  Scotland Transerv (Primary) 	26 of 26 Completed

## Communication Logs:

Log Type	Date
----------	------

There are no communications logs to display.

## Draft Media Release (optional):

A75 Springholm

Roadwork Identifier: SW/2019/10998

## Route:

 **Start: A/5** (55.01463°, -3.86398°)

 **End: A75** (55.00430°, -3.87115°)

**Direction:**  
Westbound

**SRWR Reference Number:**  
2682009 2682010

**Diversion:**  
No Diversion

**Estimated Delay:**  
3 - Moderate Delay, 1 - At All Times

**Emergency Reason:**  
Late Programmed Works

**Works Periods:**

Work Start	Work End	Traffic Management
10/10/2019 19:00	24/10/2019 06:00	Road Closure

**Works Activities:**

Works Activity Type	Contractors	Status
Resurfacing	Breedon Aggregates Ltd (Secondary) 	26 of 26 Completed.
	Markon (Secondary) 	
	Phoenix (Secondary) 	
	Scotland Transerv (Primary) 	

**Communication Logs:**

[View Log](#) [Details](#)

There are no communications logs to display.


**Draft Media Release (optional):**


Roadworks: SW/2019/10060, SW/2019/10061

**Operating Company Contract:**

South West Unit - Transov

A75 Ramhill

**Roadwork Identifier:** SW/2019/10060**Route:**
 **Start:** A75 - B794 Junction to Start Of Climbing Lane (54.97671°, -3.88999°)

 **End:** A75 - B794 Junction to Start Of Climbing Lane (54.97774°, -3.88798°)
**Direction:**

Eastbound

**SRWR Reference Number:**

2638052

**Diversion:**

Eastbound diversion route

- Second exit on to A745 towards Castle Douglas;
- Straight through Hillowton roundabout to remain on A745;
- First exit to remain on A745 (Oakwell Road);
- Continue on A745;
- Left on to A711 (Craignair Road);
- Continue on A711 (Craignair Street);
- Continue on A711 (John Street);
- Continue on A711;
- Left at Cargenbridge roundabout
- Continue on A75, diversion end;


**Estimated Delay:**

3 - Moderate Delay, 1 - At All Times

**Works Periods:**

Work Start	Work End	Traffic Management
15/07/2019 06:01	28/08/2019 18:59	Portable Traffic Lights (TTLs)
15/07/2019 19:00	16/07/2019 06:00	Convoy Working
16/07/2019 19:00	20/07/2019 06:00	Road Closure
22/07/2019 19:00	25/07/2019 06:00	Convoy Working
01/08/2019 19:00	03/08/2019 06:00	Convoy Working
05/08/2019 19:00	07/08/2019 06:00	Convoy Working
07/08/2019 19:00	10/08/2019 06:00	Road Closure
12/08/2019 19:00	14/08/2019 06:00	Convoy Working
21/08/2019 19:00	24/08/2019 06:00	Convoy Working
26/08/2019 19:00	29/08/2019 06:00	Road Closure

**Works Activities:**

Work Activity Type	Contractors	Completion
Bridge Joint Repairs	Diack Macaulay (Primary) 	133 of 133 Completed

Work Activity Type	Location	Status
Resurfacing	Diack Macaulay (Primary)	133 of 133 Completed.
<b>Communication Logs:</b>		
Log Type	Overview	
Log Type: VMS Update Request	Description: VMS request	VMS Location: VMS/Q5
Log Type: VMS Update Request	Description: VMS request	VMS Location: VMS/Q12
Log Type: Note	Description: complete Thurs 29/08	
Draft Media Release (optional):		

## A75 Ramhill

Roadwork Identifier: SW/2019/10061

## Route:

Start: A75 (54.97774°, -3.88798°)

End: A75 (54.97687°, -3.88962°)

## Direction:

Westbound

## SRWR Reference Number:

2636052

## Diversion:

Westbound diversion route:

- Left on to B794 towards Dalboattie;
- Right on to A711 (Craignair Road);
- Right on to A745 towards Castle Douglas;
- Third exit at roundabout to remain on A745 (Ernespie Road);
- Straight through Hillowton roundabout to remain on A745;
- First exit to re-join A75 westbound.

## Estimated Delay:

3 - Moderate Delay, 1 - At All Times

## Works Periods:

Work Start	Work End	Traffic Management
15/07/2019 06:01	28/08/2019 18:59	Portable Traffic Lights (TTLS)
15/07/2019 19:00	16/07/2019 06:00	Convoy Working
16/07/2019 19:00	20/07/2019 06:00	Road Closure
22/07/2019 19:00	25/07/2019 06:00	Convoy Working
01/08/2019 19:00	03/08/2019 06:00	Convoy Working

Work Start	Work End	Work Description
05/08/2019 19:00	07/08/2019 06:00	Convoy Working
07/08/2019 19:00	10/08/2019 06:00	Road Closure
12/08/2019 00:00	13/08/2019 23:59	Convoy Working
21/08/2019 19:00	24/08/2019 06:00	Convoy Working
26/08/2019 00:00	29/08/2019 06:00	Road Closure

**Works Activities:**

Works Activity Type	Contractors	Closures
Bridge Joint Repairs	Diack Macaulay (Primary) 	133 of 133 Completed.
Resurfacing	Diack Macaulay (Primary) 	133 of 133 Completed.

**Communication Logs:**

Log Type	Details
Log Type: VMS Update Request	Description: VMS request  VMS Location: VMS/Q9



Draft Media Release (optional):

Roadworks: SW/2019/10019, SW/2019/10020, SW/2019/10021, SW/2019/10022

**Operating Company Contract:**

South West Unit - Transerv

A77 Innermessan, Stranraer		
<b>Roadwork Identifier:</b> SW/2019/10019		
<b>Route:</b>		
 <b>Start: A77</b>	(54.92910°, -4.98747°)	
 <b>End: A77</b>	(54.92576°, -4.98766°)	
<b>Direction:</b> Northbound		
<b>SRWR Reference Number:</b> 2667186 2667189 2667193		
<b>Diversion:</b> No Diversion		
<b>Estimated Delay:</b> 2 - Slight Delay, 2 - Peak Hours		
<b>Works Periods:</b>		
<b>Work Start</b>	<b>Work End</b>	<b>Traffic Management</b>
03/08/2019 07:00	04/08/2019 19:00	Convoy Working
<b>Works Activities:</b>		
<b>Work Activity Type</b>	<b>Contractors</b>	<b>Stations</b>
Carriageway Patching	Breedon Aggregates Ltd (Primary) 	2 of 2 Completed
<b>Communication Logs:</b>		
<b>Log Type</b>	<b>Details</b>	
There are no communications logs to display.		
<b>Draft Media Release (optional):</b>		

A77 Innermessan, Stranraer		
<b>Roadwork Identifier:</b> SW/2019/10020		
<b>Route:</b>		
 <b>Start: A77</b>	(54.92910°, -4.98747°)	
 <b>End: A77</b>	(54.92576°, -4.98766°)	
<b>Direction:</b> Southbound		
<b>SRWR Reference Number:</b> 2667186 2667189 2667193		



**Diversion:**

No Diversion


**Estimated Delay:**

2 - Slight Delay, 2 - Peak Hours

**Works Periods:**

Work Start	Work End	Traffic Management
03/08/2019 07:00	04/08/2019 18:00	Convoy Working



**Works Activities:**

Works Activity Type	Contractors	Status
Carriageway Patching	Breedon Aggregates Ltd (Primary) 	2 of 2 Completed.

**Communication Logs:**

Log Type	Element
There are no communications logs to display.	

**Draft Media Release (optional):****A751 NB****Roadwork Identifier:** SW/2019/10021**Route:**

	<b>Start:</b> A751 - A75 Jct to A77 Jct	(54.90512°, -4.97625°)
	<b>End:</b> A751 - A75 Jct to A77 Jct	(54.92759°, -4.98621°)

**Direction:**

Northbound

**SRWR Reference Number:**

2667186 2667189 2667193

**Diversion:**

from A75/A751 Jct follow A75 into Stranraer and turn right on to A77 Stair drive. Proceed for 200m, turn right on to A77 cairnryan rd. Head north on A77


**Estimated Delay:**

3 - Moderate Delay, 2 - Peak Hours

**Works Periods:**

Work Start	Work End	Traffic Management
03/08/2019 07:00	04/08/2019 18:00	Road Closure

**Works Activities:**

Works Activity Type	Contractors	Status
Carriageway Patching	Breedon Aggregates Ltd (Primary) 	2 of 2 Completed.

**Communication Logs:**

Log Type: 00001

There are no communications logs to display.

Draft Media Release (optional):

A751 SB

**Roadwork Identifier:** SW/2019/10022

**Route:**

● Start: A751 (51.92806°, -1.98590°)

■ End: A751 (51.90483°, -4.97642°)

**Direction:**

Southbound

**SRWR Reference Number:**

2667186 2667189 2667193

**Diversion:**

from A77/A751 jct follow A77 into Stranraer and turn left on to A77 Stair drive. Proceed for 200m, turn left on to A75 London rd. Head east on A75


**Estimated Delay:**

3 - Moderate Delay, 2 - Peak Hours

**Works Periods:**

Work Start	Work End	Work Description
03/08/2019 07:00	04/08/2019 19:00	Road Closure

**Works Activities:**

Work Activity Type	Contractor	Status
Carriageway Patching	Breedon Aggregates Ltd (Primary) 	2 of 2 Completed

**Communication Logs:**

Log Type	Description
VMS Update Request	VMS request VMS Location: VMS/07

Draft Media Release (optional):


Home » [Viewing SW/2020/12871](#) » [SW/2020/12872](#)


**Operating Company Contract:**

South West Unit - Transerv

A75 Terraghtie to Glen Dual

**Roadwork Identifier:** SW/2020/12871**Route:**

 **Start:** A75 - End Carrach Luaring Rd to Start 3 Lane Carriageway (55.06117°, -3.65662°)

 **End:** A75 - Drummora Roundabout to End Of Dual Carriageway (55.05587°, -3.71806°)

**Direction:**

Eastbound

**SRWR Reference Number:**

2747518

**Diversion:**

Eastbound - A75, B794, A711, U225n, A75

Westbound - A75, U225n, A711, A745, A75


**Estimated Delay:**

3 - Moderate Delay, 1 - At All Times

**Works Periods:**

Work Start	Work End	Traffic Management
21/02/2020 19:00	26/02/2020 06:00	Road Closure
24/02/2020 06:01	25/02/2020 18:59	Contrailow

**Works Activities:**

Works Activity Type	Contractors	Progress
Resurfacing	Breedon Aggregates Ltd (Primary) 	10 of 10 Completed

**Communication Logs**

Log Type	Description
Note	Road Closure EB and WB on A75 Terraghtie becoming a Contrailow for Re-surfacing

**Draft Media Release (optional):**

A75 Terraghtie to Glen Dual

**Roadwork Identifier:** SW/2020/12872**Route:**

 **Start:** A75 (55.06117°, -3.65662°)

 **End:** A75 (55.05587°, -3.71806°)

**Direction:**

Westbound

**SRWR Reference Number:**

2747518

**Diversion:**

No Diversion

**Estimated Delay:**

3 - Moderate Delay, 1 - At All Times

**Works Periods:**

Work Start	Work End	Traffic Management
21/02/2020 19:00	26/02/2020 06:00	Road Closure
24/02/2020 06:01	25/02/2020 18:59	Contraflow

**Works Activities:**

Works Activity Type	Contractors	Status
Resurfacing	Breedon Aggregates Ltd (Primary) 	10 of 10 Completed.

**Communication Logs:**

Log Type	Details
Log Type: Note	Description: Road Closure E/B and W/B on A75 Terraughlie becoming a Contraflow for Re-surfacing

**Draft Media Release (optional):**


Roadwork: SW/2019/11157


**Operating Company Contract:**

South West Unit - Transerv

A75 Edinburgh Rbt A701

Roadwork Identifier: SW/2019/11157

**Route:**
 **Start:** A75 - Edinburgh Rd Rbt A701 to Edinburgh Rd Rbt A701 (55.08595°, -3.59527°)

 **End:** A75 - Edinburgh Rd Rbt A701 to Glasgow Rd Rbt A76 (55.07867°, -3.62445°)
**Direction:**

Westbound

**SRWR Reference Number:**

Not Specified

**Diversion:**

Edinburgh Rd - Glasgow St - Glasgow Rd - A75 - LND


**Estimated Delay:**

1 - Little or No Delay, 3 - Off Peak Hours

**Works Periods:**

Work Case	Work Start	Traffic Management
16/10/2019 20:00	17/10/2019 06:00	Road Closure
23/10/2019 20:00	24/10/2019 06:00	Road Closure

**Works Activities:**

Work Activity Type	Comments	Progress
Lighting Works	Scotland Transerv (Primary) 	4 of 4 Completed

**Communication Logs:**

Log Type	Message
Log Type: Note	<b>Description:</b> Total closure WB A75 Edinburgh Rd Rbt to Glasgow Rbt with safety Zone coming from EB traffic for lighting column renewal.

Draft Media Release (optional):

Route: SW/2019/11759, SW/2019/11760, SW/2019/11761, SW/2019/11762


#### Operating Company Contract:


South West Unit - Transerv

#### A75 Gretna Bypass

**Roadwork Identifier:** SW/2019/11759

#### Route:

 Start: M74 - Start Of Chevrons to End Of MWay Sign (55.00055°, -3.06453°)

 End: A75 - End Of MWay Sign to End Of Chevrons (55.00008°, -3.06937°)

#### Direction:

Westbound

#### SRWR Reference Number:

2730453 2730456

#### Diversion:

Glasgow Rd off slip - Turn right onto Glasgow Rd - Circle R&L - Glasgow Rd WB On slip End.

#### Estimated Delay:

1 - Little or No Delay, 3 - Off Peak Hours


#### Emergency Reason:

Late Programmed Works

#### Works Periods:

Work Start	Work End	Traffic Management
03/12/2019 20:00	04/12/2019 06:00	Road Closure
06/12/2019 20:00	07/12/2019 06:00	Road Closure

#### Works Activities:

Work Activity Type	Contractors	Progress
Lighting Works	Scotland Transerv (Primary) 	4 of 4 Completed.

#### Communication Logs:

Log Type	Description
Log Type: Note	Description: Total closure of the A75 WB between Glasgow road slips with associated lane closures in both directions for lighting works.

#### Draft Media Release (optional):

#### A75 Gretna Bypass off slip EB

**Roadwork Identifier:** SW/2019/11760

#### Route:

 Start: A75 (55.00035°, -3.06776°)

 End: A75 (55.00087°, -3.06378°)

Direction:  
Fastbound

SRWR Reference Number:  
Not Specified


Diversion:  
No Diversion

Estimated Delay:  
1 - Little or No Delay, 3 - Off Peak Hours

Works Periods:

Work Start	Work End	Traffic Management
03/12/2019 20:00	07/12/2019 06:00	Lane Closure

Works Activities:

Work Activity Type	Contractor	Staffing
Lighting Works	Scotland Transerv (Primary) 	8 of 8 Completed.

Communication Logs:

Log Type	Message
Note	Description: lane closures for lighting works

Draft Media Release (optional):

A75 Grains Bypass E/B

Roadwork Identifier: SW2019/11761

Route:

 Start: A75 (54.89617°, -3.08890°)

 End: M74 (55.00080°, -3.06315°)

Direction:  
Fastbound

SRWR Reference Number:  
2610414

Diversion:  
No Diversion

Estimated Delay:  
1 - Little or No Delay, 3 - Off Peak Hours

Works Periods:

Work Start	Work End	Traffic Management
03/12/2019 20:00	07/12/2019 06:00	Lane Closure

Works Activities:

Works Activity type	Contractor	Progress
Lighting Works	Scotland TranServ (Primary) 	8 of 8 Completed.

**Communication Logs:**

Log Type	Description
Log Type: Note	Description: lane closures for lighting works

Draft Media Release (optional):

A75 Gretna Bypass Glasgow Road on slip

Roadwork Identifier: SW/2019/11762

**Route:**

- Start: M74 (55.00041°, -3.06532°)
- End: A75 (54.99600°, -3.08898°)

**Direction:**  
Westbound

**SRWR Reference Number:**  
Not Specified

**Diversion:**  
No Diversion

**Estimated Delay:**  
1 - Little or No Delay, 3 - Off Peak Hours

**Works Periods:**

Work Start	Work End	Traffic Management
03/12/2019 20:00	07/12/2019 06:00	Lane Closure

**Works Activities:**

Works Activity type	Contractor	Progress
Lighting Works	Scotland TranServ (Primary) 	8 of 8 Completed.

**Communication Logs:**

Log Type	Description
Log Type: Note	Description: lane closures for lighting works with Glasgow Rd on slip being brought to a merge to provide lane closure

Draft Media Release (optional):



Roadworks: SW/2019/10471, SW/2019/10472, SW/2019/10473, SW/2019/10474 ... SW/2019/10570


**Operating Company Contract:**

South West Unit - Transov

A75 west of Annan

**Roadwork Identifier:** SW/2019/10471**Route:**

 **Start:** A75 (54.99593°, -3.27323°)

 **End:** A75 (54.99711°, -3.26564°)

**Direction:**

Eastbound

**SRWR Reference Number:**

2665071

**Diversion:**

No Diversion


**Estimated Delay:**

2 - Slight Delay, 1 - At All Times

**Works Periods:**

Work Start	Work End	Traffic Management
30/08/2019 06:00	30/08/2019 18:59	Portable Traffic Lights (TTLS)

**Works Activities:**

Work Activity Type	Contractors	Status
Resurfacing	Breedon Aggregates Ltd (Primary) 	1 of 1 Completed


**Communication Logs:**

Log Type	Details
There are no communications logs to display.	

**Draft Media Release (optional):**

A75 west of Annan

**Roadwork Identifier:** SW/2019/10472**Route:**

 **Start:** A75 - B722 O'Bridge to Annan Jct West (54.99594°, -3.27338°)

 **End:** A75 - B722 O'Bridge to Annan Jct West (54.99707°, -3.26816°)

**Direction:**

Eastbound

**SRWR Reference Number:**

2665071

**Diversion:**  
Exit A75 to B721 - at Rbt take exit to Stapleton Road B6357 - rejoin A75

**Estimated Delay:**  
2 - Slight Delay, 1 - At All Times

**Works Periods:**

Work Start	Work End	Traffic Management
29/08/2019 19:00	02/09/2019 06:00	Road Closure

**Works Activities:**

Work Activity Type	Contractors	Stages
Resurfacing	Breedon Aggregates Ltd (Primary)	6 of 6 Completed.

**Communication Logs:**

Log Type	Details
VMS Update Request	Description: VMS request VMS Location: VMS/Q6

**Draft Media Release (optional):**

A75 west of Annan

Roadwork Identifier: SW/2019/10473

**Route:**

- Start: A75 (54.99721°, -3.28453°)
- End: A75 (54.99561°, -3.27477°)

**Direction:**  
Westbound

**SRWR Reference Number:**  
2655971

**Diversion:**  
Exit A75 taking slip road and left at Jct onto B76357 Stapleton Road  
take 2nd exit of Rbt on B721 through Annan - rejoin A75

**Estimated Delay:**  
2 - Slight Delay, 1 - At All Times

**Works Periods:**

Work Start	Work End	Traffic Management
29/08/2019 19:00	02/09/2019 06:00	Road Closure

**Works Activities:**

Work Activity Type	Contractors	Stages
Resurfacing	Breedon Aggregates Ltd (Primary)	6 of 6 Completed.

## Communication Logs:

Log Type	Details
----------	---------

There are no communications logs to display.

## Draft Media Release (optional):

## A75 west of Annan

Roadwork Identifier: SW/2019/10474

## Route:

 Start: A75 (54.99594°, -3.27336°)

 End: A75 (54.99707°, -3.26645°)

## Direction:

Eastbound

## SRWR Reference Number:

265597\*

## Diversion:

Exit A75 to B721 - at R91 take exit to Stapleton Road B6357 - rejoin A75

## Estimated Delay:

2 - Slight Delay, 1 - At All Times

## Works Periods:

Work Start	Work End	Traffic Management
02/09/2019 19:00	05/09/2019 06:00	Road Closure

## Works Activities:

Works Activity Type	Contractors	Progress
Resurfacing	Breedon Aggregates Ltd (Primary) 	6 of 6 Completed.

## Communication Logs:

Log Type	Details
----------	---------

Log Type	Description	VMS Location
VMS Update Request	VMS request	VMS/Q1

## Draft Media Release (optional):

## A75 west of Annan

Roadwork Identifier: SW/2019/10570

## Route:

 Start: A75 (54.99707°, -3.26645°)

 End: A75 (54.99563°, -3.27482°)

**Direction:**

Westbound

**SRWR Reference Number:**

2655971

**Diversion:**

No Diversion


**Estimated Delay:**

2 - Slight Delay, 1 - At All Times

**Works Periods:**

Work Start	Work End	Traffic Management
02/09/2019 19:00	05/09/2019 06:00	Road Closure

**Works Activities:**

Work Activity Type	Contributor	Status
Resurfacing	Bredon Aggregates Ltd (Primary) 	6 of 6 Completed.

**Communication Logs:**

Log Type	Details
----------	---------

There are no communications logs to display.

**Draft Media Release (optional):**

Roadworks: SW/2020/15103, SW/2020/15187

**Operating Company Contract:**

South West Unit - Transarv

## A75 Ovgang to Collin

Roadwork Identifier: SW/2020/15103

**Route:**
 **Start:** (55.06581°, -3.51217°)

 **End:** A75 (55.06300°, -3.49695°)
**Direction:**

Eastbound

**SRWR Reference Number:**

02747284

**Diversion:**

Eastbound - A75,B721,B723,B7076,A709,A75

Westbound - A75,A709,B7076,B723,B721,A75

**Estimated Delay:**

3 - Moderate Delay, 1 - At All Times

**Works Periods:**

Work Start	Work End	Traffic Management
24/07/2020 19:00	27/07/2020 06:00	Road Closure

**Works Activities:**

Works Activity Type	Contractor	Status
Resurfacing	Breedon Aggregates Ltd (Primary) 	4 of 4 Completed.

**Communication Logs:**


Log Type	Date
----------	------


There are no communications logs to display.

Draft Media Release (optional):

## A75 Ovgang to Collin

Roadwork Identifier: SW/2020/15187

**Route:**
 **Start:** A75 - Torthorwald Jct to Start Halching (55.08299°, -3.49701°)

 **End:** A75 - Start Halching to East Bulnosc (55.06579°, -3.51212°)
**Direction:**

Westbound

**SRWR Reference Number:**

02747284

**Diversion:**

Eastbound - A75,B721,B723,B7076,A709,A75  
Westbound - A75,A709,B7076,B723,B721,A75


**Estimated Delay:**

J - Moderate Delay, 1 - At All Times

**Works Periods:**

Work Start	Work End	Traffic Management
24/07/2020 19:00	27/07/2020 06:00	Road Closure

**Works Activities:**

Work Activity Type	Contractors	Status
Resurfacing	Breedon Aggregates Ltd (Primary) 	4 of 4 Completed.

**Communication Logs:**

Log Type	Details
There are no communications logs to display.	

**Draft Media Release (optional):**