

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/01/2017 and 28/08/2020, and defects raised outside of inspections on the same Section(s) during this period.

(Road is 'A83',)
(Section Code is 16540/50) ch1200m>3600m

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
16540/50 : ABHAINN MHOR BRIDGE TO PORT ANN ACCESS									
Safety Inspection of A83 Safety Inverary - Campbeltown on 05 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 12 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 19 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 26 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 02 February 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 09 February 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 16 February 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 23 February 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 02 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 09 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 16 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 23 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 30 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 06 April 2017									
NWG21256924-235074579	2,063m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 1	04/05/2017	Completed Defects	03/05/2017	EAST KAMES, WEST OF LOCHGAIR EB
Safety Inspection of A83 Safety Inverary - Campbeltown on 13 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 20 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 27 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 04 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 11 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 18 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 25 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 01 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 08 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 15 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 22 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 29 June 2017									
<i>No defects recorded</i>									

Detailed Inspection TEMPLATE of A83 SHIRA BRIDGE TO A83 C43 (BRAE ROAD) JUNCTION on 20 June 2017

NW80253085-477	1,676m	0m	BOLLARDS	Loss of surface / paint covering (LOPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, W/B VERGE.
NW80253085-478	1,682m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, W/B VERGE.
NW80253085-479	1,616m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, E/B C/WAY.
NW80253085-480	1,618m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, CENTRE LINE.
NW80253085-481	1,688m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, E/B C/WAY.
NW80253085-482	1,704m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, CENTRE LINE.
NW80253085-483	1,698m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, W/B C/WAY.
NW80253085-484	1,696m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, E/B C/WAY.
NW80253085-485	1,714m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, E/B C/WAY.
NW80253085-486	1,704m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, CENTRE LINE.
NW80253085-487	1,723m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, CENTRE LINE.
NW80253085-488	1,744m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, E/B C/WAY.
NW80253085-489	1,759m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, E/B C/WAY.
NW80253085-490	1,766m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, W/B C/WAY.
NW80253085-491	1,797m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, E/B C/WAY.
NW80253085-492	1,818m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, W/B C/WAY.
NW80253085-493	1,836m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, W/B C/WAY.
NW80253085-494	1,820m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF LOCHGAIR, E/B C/WAY.
NW80253085-495	2,036m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF LOCHGAIR, E/B C/WAY.
NW80253085-496	2,030m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF LOCHGAIR, W/B C/WAY.
NW80253085-497	2,059m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WEST OF LOCHGAIR, E/B C/WAY.

NW80253085-498	2,528m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	MIDDLE KAMES, E/B VERGE.
NW80253085-499	2,567m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	10/06/2019	MIDDLE KAMES, W/B C/WAY.
NW80253085-500	2,590m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	10/06/2019	MIDDLE KAMES, W/B C/WAY.
NW80253085-501	3,036m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF MIDDLE KAMES, W/B VERGE.
NW80253085-502	2,786m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	10/06/2019	JUST WEST OF MIDDLE KAMES ACCESS, W/B C/WAY.
NW80253085-503	2,839m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST WEST OF MIDDLE KAMES, E/B VERGE.

Safety Inspection of A83 Safety Inverary - Campbeltown on 06 July 2017

NWG30-281800-235255903	1,624m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	03/08/2017	Completed Defects	01/08/2017	JUST WEST OF LOCHGAIR.
------------------------	--------	----	-------------	-------------------	-------	------------	----------------------	------------	------------------------

Safety Inspection of A83 Safety Inverary - Campbeltown on 13 July 2017

NWG30-282247-235257232	1,872m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	14/07/2017	Completed Defects	13/07/2017	OUTSIDE KNOCK COTTAGE, W/B C/WAY.
------------------------	--------	----	-------------	--------------------------	-------	------------	----------------------	------------	--------------------------------------

NWG30-282247-235257231	1,870m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	14/07/2017	Completed Defects	13/07/2017	OUTSIDE KNOCK COTTAGE, E/B C/WAY.
------------------------	--------	----	-------------	--------------------------	-------	------------	----------------------	------------	--------------------------------------

Safety Inspection of A83 Safety Inverary - Campbeltown on 20 July 2017

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 27 July 2017

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 03 August 2017

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown (Awaiting Return)

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 17 August 2017

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 24 August 2017

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 31 August 2017

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 07 September 2017

NW31284755-235363866	1,949m	0m	MANHOLE	Difference in component levels (ICLV)	3RD PTY	05/10/2017	Awaiting CCMS Temp Date	01/01/9999	OUTSIDE LORAN HOUSE ACCESS, WEST OF LOCHGAIR. (W/B C/WAY)
----------------------	--------	----	---------	---	---------	------------	----------------------------	------------	---

Safety Inspection of A83 Safety Inverary - Campbeltown on 14 September 2017

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 21 September 2017

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 28 September 2017

Safety Inspection of A83 Safety Inverary - Campbeltown on 05 October 2017

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 12 October 2017

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 19 October 2017

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 26 October 2017

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 02 November 2017

No defects recorded
Safety Inspection of A83 Safety Inverary - Campbeltown on 09 November 2017

No defects recorded
Safety Inspection of A83 Safety Inverary - Campbeltown on 16 November 2017

No defects recorded
Safety Inspection of A83 Safety Inverary - Campbeltown on 23 November 2017

No defects recorded
Safety Inspection of A83 Safety Inverary - Campbeltown on 30 November 2017

Safety Inspection of A83 Safety Inverary - Campbeltown on 07 December 2017
No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 14 December 2017
No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 21 December 2017
No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 28 December 2017
No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 04 January 2018
No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 11 January 2018

NWG11317396-235513652	1,602m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 1	08/02/2018	Completed Defects	08/02/2018	JUST WEST OF LOCHGAIR, E/B C/WAY.
NWG11317396-235513653	1,620m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	12/01/2018	Completed Defects	11/01/2018	JUST WEST OF LOCHGAIR, E/B C/WAY.
NWG11317396-235513654	1,619m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	12/01/2018	Completed Defects	11/01/2018	JUST WEST OF LOCHGAIR, E/B C/WAY.
NWG11317396-235513655	1,697m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 1	08/02/2018	Completed Defects	08/02/2018	JUST WEST OF LOCHGAIR, CENTRE LINE.

Safety Inspection of A83 Safety Inverary - Campbeltown on 18 January 2018

No defects recorded
Safety Inspection of A83 Safety Inverary - Campbeltown on 25 January 2018

No defects recorded
Safety Inspection of A83 Safety Inverary - Campbeltown on 01 February 2018

NWG11318017-235531606	104m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	02/02/2018	Completed Defects	01/02/2018	GLASHAN BURN ACCESS, EAST OF LOCHGAIR. (E/B C/WAY)
NWG11318017-235531611	1,870m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	02/02/2018	Completed Defects	01/02/2018	OUTSIDE KNOCK COTTAGE, LOCHGAIR. (E/B C/WAY)

Safety Inspection of A83 Safety Inverary - Campbeltown on 08 February 2018

No defects recorded
Safety Inspection of A83 Safety Inverary - Campbeltown on 14 February 2018

No defects recorded
Safety Inspection of A83 Safety Inverary - Campbeltown on 21 February 2018

No defects recorded
Safety Inspection of A83 Safety Inverary - Campbeltown on 28 February 2018

No defects recorded
Safety Inspection of A83 Safety Inverary - Campbeltown on 07 March 2018

No defects recorded
Safety Inspection of A83 Safety Inverary - Campbeltown on 14 March 2018

No defects recorded
Safety Inspection of A83 Safety Inverary - Campbeltown on 21 March 2018

NW122328664-235596645	2,936m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	22/03/2018	Completed Defects	21/03/2018	MIDDLE KAMES, E/B C/WAY.
NW122328664-235596646	2,879m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	22/03/2018	Completed Defects	21/03/2018	MIDDLE KAMES, E/B C/WAY.

Safety Inspection of A83 Safety Inverary - Campbeltown on 28 March 2018

No defects recorded
Safety Inspection of A83 Safety Inverary - Campbeltown on 04 April 2018

No defects recorded
Safety Inspection of A83 Safety Inverary - Campbeltown (Awaiting Return)

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 18 April 2018**Safety Inspection of A83 Safety Inverary - Campbeltown on 25 April 2018***No defects recorded***Safety Inspection of A83 Safety Inverary - Campbeltown on 02 May 2018**

NW122341824-235689813	2,829m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	03/05/2018	Completed Defects	02/05/2018	KAMES BENDS, W/B C/WAY.
-----------------------	--------	----	-------------	-----------------------	-------	------------	-------------------	------------	-------------------------

Safety Inspection of A83 Safety Inverary - Campbeltown on 09 May 2018**Safety Inspection of A83 Safety Inverary - Campbeltown on 16 May 2018***No defects recorded***Safety Inspection of A83 Safety Inverary - Campbeltown on 23 May 2018***No defects recorded***Safety Inspection of A83 Safety Inverary - Campbeltown on 30 May 2018****Safety Inspection of A83 Safety Inverary - Campbeltown on 06 June 2018***No defects recorded***Safety Inspection of A83 Safety Inverary - Campbeltown on 13 June 2018***No defects recorded***Detailed Inspection TEMPLATE of A83 SHIRA BRIDGE TO A83 C43 (BRAE ROAD) JUNCTION on 30 April 2018**

NWG11328946-1054	2,077m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1055	2,015m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1056	2,000m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1057	1,959m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1058	1,961m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1059	1,929m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1060	1,909m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1061	1,756m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B VERGE)
NWG11328946-1062	1,723m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B VERGE)
NWG11328946-1063	1,723m	0m	GRIP	Blockage (BLOK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B VERGE)
NWG11328946-1064	1,983m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (CENTRE LINE)
NWG11328946-1065	2,011m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1066	2,192m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1067	2,181m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)

NWG11328946-1068	2,131m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1069	2,141m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1070	2,235m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1071	2,239m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1076	2,413m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1077	2,459m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1078	2,449m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1079	2,475m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1072	2,266m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1073	2,230m	0m	ROAD_MARKINGS _LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (CENTRE LINE)
NWG11328946-1074	2,189m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B VERGE)
NWG11328946-1075	2,496m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B VERGE)
NWG11328946-1080	2,475m	0m	ROAD_MARKINGS _LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (CENTRE LINE)
NWG11328946-1081	2,485m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1082	2,511m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1083	2,534m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	10/06/2019	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1084	2,558m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	10/06/2019	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1085	2,574m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	10/06/2019	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1086	2,580m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	10/06/2019	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1087	2,594m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	10/06/2019	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)

NWG11328946-1088	2,598m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1089	2,596m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1090	3,289m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1091	3,175m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B VERGE)
NWG11328946-1092	3,141m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1093	3,002m	0m	TRAFFIC_SIGNS	Obscured sign (OBSG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B VERGE)
NWG11328946-1094	2,979m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B VERGE)
NWG11328946-1095	2,953m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1096	2,922m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1097	2,821m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	10/06/2019	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1098	2,819m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	10/06/2019	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1099	2,821m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B VERGE)
NWG11328946-1108	3,570m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B VERGE)
NWG11328946-1110	3,305m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1111	3,293m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B VERGE)
NWG11328946-1112	3,795m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B VERGE)
NWG11328946-1113	3,794m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B VERGE)
NWG11328946-1100	2,821m	0m	ROAD_MARKINGS _LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	10/06/2019	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (CENTRE LINE)
NWG11328946-1101	2,838m	0m	VERGE	Dead, dying or damaged areas (DPDY)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B VERGE)
NWG11328946-1102	2,762m	0m	CARRIAGEWAY	Bituminous	CAT 2	01/01/9999	Cat 2 Awaiting	01/01/9999	BETWEEN ABHAINN MHOR

				surfacing fretting (BFRT)			Action		BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1103	2,749m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	10/06/2019	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B C/WAY)
NWG11328946-1104	2,761m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)
NWG11328946-1105	2,943m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (E/B VERGE)
NWG11328946-1106	3,084m	0m	ROAD_MARKINGS _LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (CENTRE LINE)
NWG11328946-1107	3,586m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BETWEEN ABHAINN MHOR BRIDGE & PORT ANN. (W/B C/WAY)

Safety Inspection of A83 Safety Inverary - Campbeltown on 20 June 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 27 June 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 04 July 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 11 July 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 18 July 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 25 July 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 01 August 2018

NW122384825-235928477	3,555m	0m	TRAFFIC_SIGNS	Obscured sign (OBSG)	CAT 1	02/08/2018	Completed Defects	01/08/2018	KAMES, W/B VERGE.
-----------------------	--------	----	---------------	-------------------------	-------	------------	----------------------	------------	-------------------

Safety Inspection of A83 Safety Inverary - Campbeltown on 08 August 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 15 August 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 22 August 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 29 August 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 05 September 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 12 September 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 19 September 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 26 September 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 03 October 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 10 October 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 17 October 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 31 October 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 07 November 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 14 November 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 21 November 2018

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 28 November 2018

<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 05 December 2018									
NWG11426982-236234670	2,742m	0m	SAFETY_FENCE	Accident damage (ACCD)	CAT 1	02/01/2019	Completed Defects	09/01/2019	MIDDLE KAMES, W/B VERGE.
NWG11426982-236234671	2,850m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	06/12/2018	Completed Defects	05/12/2018	MIDDLE KAMES, W/B C/WAY
NWG11426982-236234672	2,861m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/01/2019	Completed Defects	27/12/2018	MIDDLE KAMES, W/B VERGE.

Safety Inspection of A83 Safety Inverary - Campbeltown on 12 December 2018
No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 19 December 2018
No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 21 December 2018
No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 28 December 2018
No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 04 January 2019
No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 09 January 2019
No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 16 January 2019

NW122428073-236273499	2,814m	0m	TRAFFIC_SIGNS	Accident damage (ACCD)	CAT 1	13/02/2019	Completed Defects	25/01/2019	MIDDLE KAMES, WEST OF LCHGAIR. (E/B VERGE)
NW122428073-236273500	2,818m	0m	BOLLARDS	Accident damage (ACCD)	CAT 1	13/02/2019	Completed Defects	25/01/2019	MIDDLE KAMES, WEST OF LOCHGAIR. (E/B VERGE)

Safety Inspection of A83 Safety Inverary - Campbeltown on 23 January 2019
No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 30 January 2019
No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 06 February 2019

NWG23-429030-236305331	2,853m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/03/2019	Completed Defects	04/03/2019	MIDDLE KAMES WEST OF LOCH GAIR
NWG23-429030-236305332	2,907m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	07/02/2019	Completed Defects	06/02/2019	MIDDLE KAMES WEST OF LOCHGAIR
NWG23-429030-236305333	2,863m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/03/2019	Completed Defects	04/03/2019	MIDDLE KAMES WEST OF LOCHGAIR
NWG23-429030-236305334	2,488m	0m	TRAFFIC_SIGNS	Accident damage (ACCD)	CAT 1	06/03/2019	Completed Defects	05/03/2019	MIDDLE KAMES WEST OF LOCHGAIR

Safety Inspection of A83 Safety Inverary - Campbeltown on 13 February 2019
No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 20 February 2019
No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 27 February 2019
No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 06 March 2019
No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 13 March 2019
No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 20 March 2019
No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 27 March 2019
No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 03 April 2019
No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 10 April 2019
No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 17 April 2019
No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 24 April 2019

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 01 May 2019

Safety Inspection of A83 Safety Inverary - Campbeltown on 08 May 2019

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 15 May 2019

Safety Inspection of A83 Safety Inverary - Campbeltown on 22 May 2019

No defects recorded

Detailed Inspection TEMPLATE of INVY 05 A83 on 29 May 2019

NW38490749-13	1,297m	0m	GRIP	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B VERGE.
NW38490749-14	1,324m	0m	GRIP	Weed growth (WEED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B VERGE.
NW38490749-15	1,686m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B VERGE.
NW38490749-16	1,686m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B VERGE.
NW38490749-17	1,903m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-18	1,903m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-19	1,959m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-20	1,959m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-21	1,993m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-22	2,026m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-23	2,076m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-24	2,075m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-25	2,129m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-26	2,162m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-27	2,172m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-28	2,174m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-29	2,040m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-30	2,120m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.

NW38490749-31	2,237m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-32	2,269m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-33	2,271m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-34	2,298m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-35	2,306m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-36	2,379m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-37	2,398m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-38	2,402m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, CENTTE LINE.
NW38490749-39	2,413m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-40	2,445m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-41	2,449m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-42	2,455m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-43	2,507m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B VERGE.
NW38490749-44	2,543m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	10/06/2019	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-45	2,559m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	10/06/2019	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-46	2,563m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	10/06/2019	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-47	2,573m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	10/06/2019	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-48	2,580m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	10/06/2019	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-49	2,647m	0m	VERGE	Overhanging/overgrown (OVER)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) MIDDLE KAMES. LINK/SECTION BETWEEN ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B VERGE.
NW38490749-50	2,670m	0m	CARRIAGEWAY	Bituminous	CAT 2	01/01/9999	Cat 2 Awaiting	01/01/9999	(A83) ABHAINN MHOR BRIDGE

				surfacing fretting (BFRT)			Action		& PORT ANN ACCESS, W/B C/WAY.
NW38490749-51	2,669m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-52	2,719m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	10/06/2019	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-53	2,731m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	10/06/2019	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-54	2,755m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Completed Defects	10/06/2019	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-55	2,780m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-56	2,791m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	10/06/2019	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-57	2,797m	0m	ROAD_MARKINGS _LONG	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Completed Defects	10/06/2019	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, CENTRE LINE.
NW38490749-58	2,896m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B VERGE.
NW38490749-59	2,907m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	10/06/2019	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-60	2,908m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	10/06/2019	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-61	2,921m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-62	2,860m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	10/06/2019	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-63	2,949m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-64	2,957m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-65	2,958m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B VERGE.
NW38490749-66	3,289m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-68	3,292m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-69	3,303m	0m	GRIP	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B VERGE.
NW38490749-70	3,339m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-71	3,365m	0m	CARRIAGEWAY	Bituminous	CAT 2	01/01/9999	Cat 2 Awaiting	01/01/9999	(A83) ABHAINN MHOR BRIDGE

NW38490749-72	3,412m	0m	ROAD_MARKS_TR ANS_SP	surfacing fretting (BFRT) Wear (for example erosion) (WEAR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	& PORT ANN ACCESS, W/B C/WAY. (A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-73	3,420m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-74	3,420m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, E/B C/WAY.
NW38490749-87	3,590m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-88	3,570m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-89	3,587m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B C/WAY.
NW38490749-90	3,601m	0m	BOLLARDS	Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A83) ABHAINN MHOR BRIDGE & PORT ANN ACCESS, W/B VERGE.

Safety Inspection of A83 Safety Inverary - Campbeltown on 29 May 2019

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 05 June 2019

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 12 June 2019

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 19 June 2019

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 26 June 2019

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 03 July 2019

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 10 July 2019

NW38530849-236899462	1,539m	0m	TRAFFIC_SIGNS	Obscured sign (OBSG)	CAT 1	11/07/2019	Completed Defects	10/07/2019	KNOCK W/B
----------------------	--------	----	---------------	-------------------------	-------	------------	----------------------	------------	-----------

Safety Inspection of A83 Safety Inverary - Campbeltown on 17 July 2019

NW38531054-236908929	2,370m	0m	TRAFFIC_SIGNS	Obscured sign (OBSG)	CAT 1	18/07/2019	Completed Defects	17/07/2019	EAST KAMES
----------------------	--------	----	---------------	-------------------------	-------	------------	----------------------	------------	------------

Safety Inspection of A83 Safety Inverary - Campbeltown on 24 July 2019

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 31 July 2019

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 07 August 2019

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 14 August 2019

NW38532237-236936914	1,957m	0m	MANHOLE	Difference in component levels (ICLV)	3RD PTY	11/09/2019	Awaiting CCMS Temp Date	01/01/9999	(A83) OPPOSITE LORAN HOUSE ACCESS, WEST OF LOCHGAIR. (W/B C/WAY)
----------------------	--------	----	---------	---	---------	------------	----------------------------	------------	--

Safety Inspection of A83 Safety Inverary - Campbeltown on 21 August 2019

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 28 August 2019

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 04 September 2019

NW38533036-236994457	1,646m	0m	BOLLARDS	Damaged (DAMG)	CAT 1	02/10/2019	Completed Defects	02/10/2019	WEST OF LOCHAIR, W/B VERGE.
----------------------	--------	----	----------	-------------------	-------	------------	----------------------	------------	--------------------------------

Safety Inspection of A83 Safety Inverary - Campbeltown on 11 September 2019

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 18 September 2019

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 25 September 2019

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 02 October 2019

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 09 October 2019

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 16 October 2019

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 23 October 2019

Safety Inspection of A83 Safety Inverary - Campbeltown on 30 October 2019

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 06 November 2019

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 13 November 2019

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 20 November 2019

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 27 November 2019

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 04 December 2019

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 11 December 2019

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 18 December 2019

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 24 December 2019

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 31 December 2019

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 07 January 2020

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 14 January 2020

Safety Inspection of A83 Safety Inverary - Campbeltown on 22 January 2020

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 29 January 2020

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 05 February 2020

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 11 February 2020

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 18 February 2020

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 25 February 2020

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 03 March 2020

NW33545779-237294877	1,959m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/03/2020	Completed Defects	03/03/2020	A83 W/B KNOCK COTTAGE
----------------------	--------	----	-------------	-----------------------	-------	------------	-------------------	------------	-----------------------

NW33545779-237294878	1,909m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/03/2020	Completed Defects	03/03/2020	A83 W/B KNOCK COTTAGE
----------------------	--------	----	-------------	-----------------------	-------	------------	-------------------	------------	-----------------------

Safety Inspection of A83 Safety Inverary - Campbeltown on 10 March 2020

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 17 March 2020

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 24 March 2020

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 31 March 2020

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 07 April 2020

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 14 April 2020

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 21 April 2020

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 28 April 2020

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 05 May 2020

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 12 May 2020

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 19 May 2020

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 26 May 2020

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 02 June 2020

NW38591365-237562812	2,223m	0m	TRAFFIC_SIGNS	Obscured sign (OBSG)	CAT 1	03/06/2020	Completed Defects	02/06/2020	(A83) EAST KAMES, E/B VERGE.
----------------------	--------	----	---------------	----------------------	-------	------------	-------------------	------------	------------------------------

Safety Inspection of A83 Safety Inverary - Campbeltown on 09 June 2020

No defects recorded

Safety Inspection of A83 Safety Inverary - Campbeltown on 16 June 2020

NW38600763-237607967	2,344m	0m	TRAFFIC_SIGNS	Obscured sign (OBSG)	CAT 1	17/06/2020	Completed Defects	16/06/2020	(A83) EAST KAMES, W/B VERGE.
----------------------	--------	----	---------------	----------------------	-------	------------	-------------------	------------	------------------------------

Detailed Inspection TEMPLATE of INYV 05 A83 on 17 June 2020

NW33568453-31	1,281m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		A83 - E/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
---------------	--------	----	-------------------------	-----------------------------------	-------	--	-----------------------	--	---

NW33568453-32	1,319m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		A83 - E/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
---------------	--------	----	-------------------------	-----------------------------------	-------	--	-----------------------	--	---

NW33568453-33	1,317m	0m	SCRUB	Overhanging/o vergrown (OVER)	CAT 2		Cat 2 Awaiting Action		A83 - W/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
---------------	--------	----	-------	-------------------------------	-------	--	-----------------------	--	---

NW33568453-34	1,331m	0m	GRIP	Weed growth (WEED)	CAT 2		Cat 2 Awaiting Action		A83 - W/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
---------------	--------	----	------	--------------------	-------	--	-----------------------	--	---

NW33568453-35	1,426m	0m	SCRUB	Overhanging/o vergrown (OVER)	CAT 2		Cat 2 Awaiting Action		A83 - W/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
---------------	--------	----	-------	-------------------------------	-------	--	-----------------------	--	---

NW33568453-36	1,510m	0m	SCRUB	Overhanging/o vergrown (OVER)	CAT 2		Cat 2 Awaiting Action		A83 - W/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
---------------	--------	----	-------	-------------------------------	-------	--	-----------------------	--	---

NW33568453-37	1,608m	0m	SCRUB	Overhanging/o vergrown (OVER)	CAT 2		Cat 2 Awaiting Action		A83 - W/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
---------------	--------	----	-------	-------------------------------	-------	--	-----------------------	--	---

NW33568453-38	1,632m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		A83 - W/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
---------------	--------	----	-------------------------	-----------------------------------	-------	--	-----------------------	--	---

NW33568453-39	1,720m	0m	BOLLARDS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		A83 - W/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
---------------	--------	----	----------	----------------	-------	--	-----------------------	--	---

NW33568453-40	1,717m	0m	DITCH	Weed growth (WEED)	CAT 2		Cat 2 Awaiting Action		A83 - E/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
---------------	--------	----	-------	--------------------	-------	--	-----------------------	--	---

NW33568453-41	1,770m	0m	GRIP	Weed growth (WEED)	CAT 2		Cat 2 Awaiting Action		A83 - E/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
---------------	--------	----	------	--------------------	-------	--	-----------------------	--	---

NW33568453-42	1,738m	0m	SCRUB	Overhanging/o vergrown (OVER)	CAT 2		Cat 2 Awaiting Action		A83 - E/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
---------------	--------	----	-------	-------------------------------	-------	--	-----------------------	--	---

NW33568453-43	1,738m	0m	SCRUB	Overhanging/o vergrown (OVER)	CAT 2		Cat 2 Awaiting Action		A83 - W/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
---------------	--------	----	-------	-------------------------------	-------	--	-----------------------	--	---

NW33568453-44	1,844m	0m	GRIP	Weed growth (WEED)	CAT 2		Cat 2 Awaiting Action		A83 - W/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
---------------	--------	----	------	--------------------	-------	--	-----------------------	--	---

NW33568453-45	1,864m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion)	CAT 2		Cat 2 Awaiting Action		A83 - E/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
---------------	--------	----	-------------------------	----------------------------	-------	--	-----------------------	--	---

NW33568453-46	1,909m	0m	CARRIAGEWAY	(WEAR) Bituminous surfacing fretting (BFRT)	CAT 2	Cat 2 Awaiting Action	A83 - W/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-47	1,909m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	Cat 2 Awaiting Action	A83 - E/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-48	1,959m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	Cat 2 Awaiting Action	A83 - W/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-49	1,962m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	Cat 2 Awaiting Action	A83 - E/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-50	1,977m	0m	BOLLARDS	Missing (MISS)	CAT 2	Cat 2 Awaiting Action	A83 - E/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-51	1,986m	0m	SCRUB	Overhanging/o vergrown (OVER)	CAT 2	Cat 2 Awaiting Action	A83 - E/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-52	2,034m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	Cat 2 Awaiting Action	A83 - W/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-53	2,080m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	Cat 2 Awaiting Action	A83 - E/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-54	2,087m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	Cat 2 Awaiting Action	A83 - W/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-55	2,117m	0m	ROAD_MARKINGS _LONG	Wear (for example erosion) (WEAR)	CAT 2	Cat 2 Awaiting Action	A83 - E/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-56	2,118m	0m	ROAD_MARKINGS _LONG	Wear (for example erosion) (WEAR)	CAT 2	Cat 2 Awaiting Action	A83 - W/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-57	2,117m	0m	ROAD_MARKINGS _LONG	Wear (for example erosion) (WEAR)	CAT 2	Cat 2 Awaiting Action	A83 - C/L - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-58	2,156m	0m	SCRUB	Overhanging/o vergrown (OVER)	CAT 2	Cat 2 Awaiting Action	A83 - E/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-59	2,209m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	Cat 2 Awaiting Action	A83 - E/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-60	2,208m	0m	GRIP	Weed growth (WEED)	CAT 2	Cat 2 Awaiting Action	A83 - E/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-61	2,355m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	Cat 2 Awaiting Action	A83 - W/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-62	2,319m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	Cat 2 Awaiting Action	A83 - W/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-63	2,300m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2	Cat 2 Awaiting Action	A83 - W/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-64	2,275m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	Cat 2 Awaiting Action	A83 - E/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-65	2,396m	0m	CARRIAGEWAY	Bituminous surfacing	CAT 2	Cat 2 Awaiting Action	A83 - W/B - ABHAINN MHOR BR. TO PORT ANN ACCESS

NW33568453-66	2,396m	0m	CARRIAGEWAY	fretting (BFRT) Bituminous surfacing	CAT 2	Cat 2 Awaiting Action	A83 - E/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-67	2,452m	0m	CARRIAGEWAY	fretting (BFRT) Bituminous surfacing	CAT 2	Cat 2 Awaiting Action	A83 - E/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-68	2,463m	0m	BOLLARDS	Loss of surface / paint covering (LOPT)	CAT 2	Cat 2 Awaiting Action	A83 - E/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-69	2,501m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	Cat 2 Awaiting Action	A83 - E/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-70	2,501m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	Cat 2 Awaiting Action	A83 - W/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-71	2,575m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	Cat 2 Awaiting Action	A83 - W/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-72	2,608m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	Cat 2 Awaiting Action	A83 - E/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-73	2,609m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	Cat 2 Awaiting Action	A83 - W/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-74	2,610m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	Cat 2 Awaiting Action	A83 - E/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-75	2,646m	0m	FILTER_DRAIN	Weed growth (WEED)	CAT 2	Cat 2 Awaiting Action	A83 - E/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-76	2,681m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	Cat 2 Awaiting Action	A83 - W/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-77	2,718m	0m	Culvert	Free flow impeded (FRFL)	CAT 2	Cat 2 Awaiting Action	A83 - E/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-78	2,728m	0m	FILTER_DRAIN	Weed growth (WEED)	CAT 2	Cat 2 Awaiting Action	A83 - E/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-79	2,788m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	Cat 2 Awaiting Action	A83 - E/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-80	2,958m	0m	FILTER_DRAIN	Weed growth (WEED)	CAT 2	Cat 2 Awaiting Action	A83 - E/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-81	3,035m	0m	BOLLARDS	Loss of surface / paint covering (LOPT)	CAT 2	Cat 2 Awaiting Action	A83 - W/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-82	3,285m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	Cat 2 Awaiting Action	A83 - W/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-83	3,319m	0m	SCRUB	Overhanging/overgrown (OVER)	CAT 2	Cat 2 Awaiting Action	A83 - W/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-84	3,424m	0m	SCRUB	Overhanging/overgrown (OVER)	CAT 2	Cat 2 Awaiting Action	A83 - E/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-85	3,410m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2	Cat 2 Awaiting Action	A83 - W/B - ABHAINN MHOR BR. TO PORT ANN ACCESS
NW33568453-86	3,594m	0m	CARRIAGEWAY	Bituminous	CAT 2	Cat 2 Awaiting	A83 - W/B - ABHAINN MHOR

				surfacing fretting (BFRT)		Action	BR. TO PORT ANN ACCESS	
Safety Inspection of A83 Safety Inverary - Campbeltown on 23 June 2020								
NW38601221-237644093	1,536m	0m	TRAFFIC_SIGNS	Obscured sign (OBSG)	CAT 1	24/06/2020	Completed Defects	23/06/2020 (A83) WEST OF LOCHGAIR, W/B VERGE.
Safety Inspection of A83 Safety Inverary - Campbeltown on 30 June 2020								
<i>No defects recorded</i>								
Safety Inspection of A83 Safety Inverary - Campbeltown on 07 July 2020								
<i>No defects recorded</i>								
Safety Inspection of A83 Safety Inverary - Campbeltown on 14 July 2020								
<i>No defects recorded</i>								
Safety Inspection of A83 Safety Inverary - Campbeltown on 21 July 2020								
<i>No defects recorded</i>								
Safety Inspection of A83 Safety Inverary - Campbeltown on 28 July 2020								
<i>No defects recorded</i>								
Safety Inspection of A83 Safety Inverary - Campbeltown on 04 August 2020								
<i>No defects recorded</i>								
Safety Inspection of A83 Safety Inverary - Campbeltown on 11 August 2020								
<i>No defects recorded</i>								
Safety Inspection of A83 Safety Inverary - Campbeltown on 18 August 2020								
<i>No defects recorded</i>								
Safety Inspection of A83 Safety Inverary - Campbeltown on 25 August 2020								
<i>No defects recorded</i>								