

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/01/2017 and 31/12/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Road is 'A9',)
(Section Code is 10434/68)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
10434/68 : JCT (R) TO GUAY TO START OF DUAL CWAY									
Safety Inspection of A9 Safety Dalwhinnie & A889 on 02 January 2017									
Safety Inspection of A9 Safety Dalwhinnie & A889 on 09 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A9 Safety Dalwhinnie & A889 on 16 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A9 Safety Dalwhinnie & A889 on 23 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A9 Safety Dalwhinnie & A889 on 30 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A9 Safety Dalwhinnie & A889 on 06 February 2017									
NWG5242676-235049570	957m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 1	06/03/2017	Completed Defects	03/03/2017	JUST SOUTH OF KINDALLACHAN JCT, N/B C/WAY
Safety Inspection of A9 Safety Dalwhinnie & A889 on 13 February 2017									
<i>No defects recorded</i>									
Safety Inspection of A9 Safety Dalwhinnie & A889 on 20 February 2017									
<i>No defects recorded</i>									
Safety Inspection of A9 Safety Dalwhinnie & A889 on 27 February 2017									
<i>No defects recorded</i>									
Safety Inspection of A9 Safety Dalwhinnie & A889 on 06 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A9 Safety Dalwhinnie & A889 on 13 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A9 Safety Dalwhinnie & A889 on 20 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A9 Safety Dalwhinnie & A889 on 27 March 2017									
Safety Inspection of A9 Safety Dalwhinnie & A889 on 03 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A9 Safety Dalwhinnie & A889 on 10 April 2017									
Safety Inspection of A9 Safety Dalwhinnie & A889 on 17 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A9 Safety Dalwhinnie & A889 on 24 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A9 Safety Dalwhinnie & A889 on 01 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A9 Safety Dalwhinnie & A889 on 08 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A9 Safety Dalwhinnie & A889 on 15 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A9 Safety Dalwhinnie & A889 on 22 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A9 Safety Dalwhinnie & A889 on 29 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A9 Safety Dalwhinnie & A889 on 05 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A9 Safety Dalwhinnie & A889 on 12 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A9 Safety Dalwhinnie & A889 on 19 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A9 Safety Dalwhinnie & A889 on 26 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A9 Safety Dalwhinnie & A889 on 03 July 2017									

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 10 July 2017

Safety Inspection of A9 Safety Dalwhinnie & A889 on 17 July 2017

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 24 July 2017

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 31 July 2017

Safety Inspection of A9 Safety Dalwhinnie & A889 on 07 August 2017

NW31283112-235297609	961m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	08/08/2017	Completed Defects	07/08/2017	KINDALLACHAN SB BUS STOP
----------------------	------	----	-------------	-----------------------	-------	------------	-------------------	------------	--------------------------

Safety Inspection of A9 Safety Dalwhinnie & A889 on 14 August 2017

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 21 August 2017

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 28 August 2017

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 04 September 2017

Safety Inspection of A9 Safety Dalwhinnie & A889 on 11 September 2017

Safety Inspection of A9 Safety Dalwhinnie & A889 on 18 September 2017

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 25 September 2017

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 02 October 2017

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 09 October 2017

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 16 October 2017

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 23 October 2017

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 30 October 2017

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 06 November 2017

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 13 November 2017

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 20 November 2017

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 27 November 2017

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 04 December 2017

No defects recorded

Detailed Inspection TEMPLATE of A9 JCT (R) TO GUAY TO FASKALLY SB EXIT SLIP on 08 December 2017

NWG11253151-13	961m	0m	CARRIAGEWAY	Cracking around ironwork (CKIR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	STH OF KINDALLACHAN
----------------	------	----	-------------	---------------------------------	-------	------------	-----------------------	------------	---------------------

NWG11253151-14	962m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	BUS BAY STH OF KINDALLACHAN
----------------	------	----	-------------	--------------------------------------	-------	------------	-----------------------	------------	-----------------------------

NWG11253151-15	961m	0m	CARRIAGEWAY	Patch - material cracking	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	STH OF KINDALLACHAN
----------------	------	----	-------------	---------------------------	-------	------------	-----------------------	------------	---------------------

NWG11253151-16	1,004m	0m	CARRIAGEWAY	Patch - material cracking	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	STH OF KINDALLACHAN
----------------	--------	----	-------------	---------------------------	-------	------------	-----------------------	------------	---------------------

NWG11253151-17	953m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	STH OF KINDALLACHAN
----------------	------	----	-------------	--------------------------------------	-------	------------	-----------------------	------------	---------------------

NWG11253151-18	949m	0m	CARRIAGEWAY	Single crack (CRCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	STH OF KINDALLACHAN
----------------	------	----	-------------	---------------------	-------	------------	-----------------------	------------	---------------------

NWG11253151-19	946m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	STH OF KINDALLACHAN
----------------	------	----	-------------	---------------------------	-------	------------	-----------------------	------------	---------------------

NWG11253151-20	911m	0m	CARRIAGEWAY	Cracking	CAT 2	01/01/9999	Cat 2 Awaiting	01/01/9999	STH OF KINDALLACHAN
----------------	------	----	-------------	----------	-------	------------	----------------	------------	---------------------

				around ironwork (CKIR)			Action		
NWG11253151-21	907m	0m	CARRIAGEWAY	Patch - material cracking	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	STH OF KINDALLACHAN
NWG11253151-22	920m	0m	FOOTWAY	Bituminous surfacing - local cracking (BLCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	STH OF KINDALLACHAN
NWG11253151-23	919m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	STH OF KINDALLACHAN

Safety Inspection of A9 Safety Dalwhinnie & A889 on 11 December 2017

Safety Inspection of A9 Safety Dalwhinnie & A889 on 18 December 2017

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 22 December 2017

Safety Inspection of A9 Safety Dalwhinnie & A889 on 29 December 2017

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 05 January 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 08 January 2018

Safety Inspection of A9 Safety Dalwhinnie & A889 on 15 January 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 22 January 2018

Safety Inspection of A9 Safety Dalwhinnie & A889 on 29 January 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 05 February 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 09 February 2018

Safety Inspection of A9 Safety Dalwhinnie & A889 on 13 February 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 20 February 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 27 February 2018

NW122322551-235549012	958m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 1	27/03/2018	Completed Defects	07/03/2018	SOUTH KINDALLACHAN JCT N/B C/WAY
-----------------------	------	----	-------------	---	-------	------------	----------------------	------------	-------------------------------------

Safety Inspection of A9 Safety Dalwhinnie & A889 on 06 March 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 13 March 2018

Safety Inspection of A9 Safety Dalwhinnie & A889 on 20 March 2018

Safety Inspection of A9 Safety Dalwhinnie & A889 on 27 March 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 03 April 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 10 April 2018

Safety Inspection of A9 Safety Dalwhinnie & A889 on 17 April 2018

Safety Inspection of A9 Safety Dalwhinnie & A889 on 24 April 2018

Safety Inspection of A9 Safety Dalwhinnie & A889 on 01 May 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 08 May 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 15 May 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 22 May 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 29 May 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 05 June 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 12 June 2018

Safety Inspection of A9 Safety Dalwhinnie & A889 on 19 June 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 26 June 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 03 July 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 10 July 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 17 July 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 24 July 2018

Detailed Inspection TEMPLATE of A9 JCT (R) TO GUAY TO FASKALLY SB EXIT SLIP on 27 July 2018

Safety Inspection of A9 Safety Dalwhinnie & A889 on 31 July 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 07 August 2018

Safety Inspection of A9 Safety Dalwhinnie & A889 on 14 August 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 21 August 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 28 August 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 04 September 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 11 September 2018

Detailed Inspection TEMPLATE of A9 Safety Dalwhinnie & A889 on 13 September 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 18 September 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 25 September 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 02 October 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 09 October 2018

Safety Inspection of A9 Safety Dalwhinnie & A889 on 16 October 2018

Safety Inspection of A9 Safety Dalwhinnie & A889 on 23 October 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 30 October 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 06 November 2018

Safety Inspection of A9 Safety Dalwhinnie & A889 on 13 November 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 20 November 2018

Safety Inspection of A9 Safety Dalwhinnie & A889 on 27 November 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 04 December 2018

Safety Inspection of A9 Safety Dalwhinnie & A889 on 11 December 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 18 December 2018

NW122427404-236264113

1,057m

0m

Bus_Stop

Lack of bus
shelter

Awaiting CCMS
Permanent

KINDALLACHAN NB BUS
SHELTER

Safety Inspection of A9 Safety Dalwhinnie & A889 on 21 December 2018

No defects recorded

Safety Inspection of A9 Safety Dalwhinnie & A889 on 28 December 2018

No defects recorded