

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/12/2019 and 31/01/2020, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'WITH: JCT 20 SLIP OFF WB M8 TO JCT 22 M77 INT'.) Or

(Section is 'With: M74 WB On slip at M8 Jn 21','With: 3-lane Dedicated Cway to M8 WB & M77 SB','With:Link road from M74 EB Off slip to M74 WB','With: WB Entry slip to dedicated M8 Cway','With: End of 3-Lane to Dedicated Cway to M8 WB'.)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
14260/05 : WITH: JCT 20 SLIP OFF WB M8 TO JCT 22 M77 INT									
Safety Inspection of M8 Glasgow East V1 on 03 December 2019									
SW85-537226-237175725	681m	681m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/12/2019	Completed Defects	03/12/2019	M8 J20 TO J22 120MTR PASS H/M107
SW85-537226-237175724	678m	678m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/12/2019	Completed Defects	03/12/2019	M8 J20 TO J22 120 MTR PASS H/M 107
SW85-537226-237175723	660m	660m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/12/2019	Completed Defects	03/12/2019	M8 W/B J20 TO J22 100MTS PASS H/M 107
Safety Patrol of M8 Glasgow East V1 on 07 December 2019									
<i>No defects recorded</i>									
Safety Inspection of M8 Glasgow East V1 on 10 December 2019									
SW85-537418-237210717	123m	123m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/12/2019	Completed Defects	11/12/2019	M8 W/B J20 TO J22 @ OVERBRIDGE
SW85-537418-237210716	107m	107m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/12/2019	Completed Defects	11/12/2019	M8 W/B J20 TO J22 @ OVERBRIDGE
SW85-537418-237210725	678m	678m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/12/2019	Completed Defects	11/12/2019	M8 W/B J20 TO J22 250MTRS PASS SOS BOX 758W
SW85-537418-237210724	680m	68m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/12/2019	Completed Defects	11/12/2019	M8 W/B J20 TO J22 ABOUT 250MTR PASS SOS BOX 758W
SW85-537418-237210723	313m	313m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/12/2019	Completed Defects	11/12/2019	M8 W/B J20 TO J22 @ OVERBRIDGES
SW85-537418-237210722	294m	294m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/12/2019	Completed Defects	11/12/2019	M8 W/B J20 TO J22 LANE 1@OVERBRIDGES
SW85-537418-237210721	261m	261m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/12/2019	Completed Defects	11/12/2019	M8 W/B J20 TO J22 @ OVERBRIDGES
SW85-537418-237210720	222m	222m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/12/2019	Completed Defects	11/12/2019	M8 W/B J20 TO J22 @ OVERBRIDGE
SW85-537418-237210719	140m	140m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/12/2019	Completed Defects	11/12/2019	M8 W/B J20 TO J22 @ OVERBRIDGE
SW85-537418-237210718	135m	135m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/12/2019	Completed Defects	11/12/2019	M8 W/B J20 TO J22 @ OVERBRIDGE
Night Safety Inspection 14 day - Signs and lighting of M8 Glasgow East V1 on 10 December 2019									
SW83-537434-237175192	251m	0m	TRAFFIC_SIGNS	Lamp failure (LAMP)	CAT 1	11/12/2019	Completed Defects	10/12/2019	M8 CARNOUSTIE ST ONSLIP W/B
Safety Patrol of M8 Glasgow East V1 on 14 December 2019									
<i>No defects recorded</i>									
Safety Inspection of M8 Glasgow East V1 on 17 December 2019									
SW85-537622-237211814	997m	998m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/12/2019	Completed Defects	18/12/2019	M8 WB AFTER JCT 20 LANE 2
Safety Patrol of M8 Glasgow East V1 on 21 December 2019									
<i>No defects recorded</i>									
Night Safety Inspection 14 day - Signs and lighting of M8 Glasgow East V1 on 21 December 2019									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
Safety Inspection of M8 Glasgow East V1 on 23 December 2019 <i>No defects recorded</i>									
Safety Patrol of M8 Glasgow East V1 on 28 December 2019 <i>No defects recorded</i>									
Safety Inspection of M8 Glasgow East V1 on 31 December 2019 <i>No defects recorded</i>									
Night Safety Inspection 14 day - Signs and lighting of M8 Glasgow East V1 on 04 January 2020 <i>No defects recorded</i>									
Safety Patrol of M8 Glasgow East V1 on 04 January 2020 <i>No defects recorded</i>									
Safety Inspection of M8 Glasgow East V1 on 07 January 2020									
SW85-538223-237221939	313m	313m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	08/01/2020	Completed Defects	08/01/2020	M8 W/B J20 TO J22 JUST AFTER WEST ST OFF
SW85-538223-237221938	326m	326m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	08/01/2020	Completed Defects	08/01/2020	M8 W /B J20 TOJ22 JUST AFTER WEST ST
SW85-538223-237221937	274m	274m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	08/01/2020	Completed Defects	08/01/2020	M8 W/B J20TO J22 JUST AFTER WEST ST OFF
SW85-538223-237221936	302m	302m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	08/01/2020	Completed Defects	08/01/2020	M8 W/B J20 TO J22 LANE 1 JUST AFTER WEST ST OFF
SW85-538223-237221935	282m	282m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	08/01/2020	Completed Defects	08/01/2020	M8 W/B J20 TO J22 JUST AFTER WEST ST OFF
SW85-538223-237221930	665m	665m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	08/01/2020	Completed Defects	08/01/2020	M8 W/B J20 TOJ22 @ BRIDGE JOINT
Safety Patrol of M8 Glasgow East V1 on 11 January 2020 <i>No defects recorded</i>									
Safety Inspection of M8 Glasgow East V1 on 14 January 2020 <i>No defects recorded</i>									
Night Safety Inspection 14 day - Signs and lighting of M8 Glasgow East V1 on 14 January 2020 <i>No defects recorded</i>									
Safety Patrol of M8 Glasgow East V1 on 18 January 2020 <i>No defects recorded</i>									
Safety Inspection of M8 Glasgow East V1 on 21 January 2020									
SW85-538622-237246251	304m	304m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/02/2020	Completed Defects	22/01/2020	M8 W/B JUST AFTER KINGSTON BRIDGE
SW85-538622-237246250	282m	282m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/02/2020	Completed Defects	22/01/2020	M8 W/B JUST AFTER KINGSTON BRIDGE
SW85-538622-237246249	274m	274m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/02/2020	Completed Defects	22/01/2020	M8 W/B JST AFTER KINGSTON BRIDGE LANES 1
Safety Patrol of M8 Glasgow East V1 on 25 January 2020 <i>No defects recorded</i>									
Safety Inspection of M8 Glasgow East V1 on 28 January 2020 <i>No defects recorded</i>									
Night Safety Inspection 14 day - Signs and lighting of M8 Glasgow East V1 on 28 January 2020 <i>No defects recorded</i>									
10798/61 : With: End of 3-Lane to Dedicated Cway to M8 W/B									
Safety Patrol of M74 Glasgow East V1 on 01 December 2019 <i>No defects recorded</i>									
Safety Inspection of M74 Main on 04 December 2019 <i>No defects recorded</i>									
Safety Patrol of M74 Glasgow East V1 on 08 December 2019 <i>No defects recorded</i>									
Safety Inspection of M74 Main on 11 December 2019 <i>No defects recorded</i>									
Night Safety Inspection 14 day - Signs and lighting of M74 Glasgow East V1 on 12 December 2019 <i>No defects recorded</i>									
Safety Patrol of M74 Glasgow East V1 on 15 December 2019 <i>No defects recorded</i>									
Safety Inspection of M74 Main on 18 December 2019									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
No defects recorded									
Safety Inspection of M74 Main on 20 December 2019									
No defects recorded									
Safety Patrol of M74 Glasgow East V1 on 22 December 2019									
No defects recorded									
Night Safety Inspection 14 day - Signs and lighting of M74 Glasgow East V1 on 23 December 2019									
No defects recorded									
Safety Patrol of M74 Glasgow East V1 on 23 December 2019									
No defects recorded									
Safety Inspection of M74 Main on 29 December 2019									
No defects recorded									
Safety Patrol of M74 Glasgow East V1 on 30 December 2019									
No defects recorded									
Safety Inspection of M74 Main on 03 January 2020									
No defects recorded									
Night Safety Inspection 14 day - Signs and lighting of M74 Glasgow East V1 on 06 January 2020									
No defects recorded									
Safety Patrol of M74 Glasgow East V1 on 06 January 2020									
No defects recorded									
Safety Inspection of M74 Main on 08 January 2020									
No defects recorded									
Safety Patrol of M74 Glasgow East V1 on 12 January 2020									
No defects recorded									
Night Safety Inspection 14 day - Signs and lighting of M74 Glasgow East V1 on 15 January 2020									
No defects recorded									
Safety Inspection of M74 Main on 15 January 2020									
No defects recorded									
Safety Patrol of M74 Glasgow East V1 on 19 January 2020									
No defects recorded									
Safety Inspection of M74 Main on 22 January 2020									
No defects recorded									
Safety Patrol of M74 Glasgow East V1 on 26 January 2020									
No defects recorded									
Night Safety Inspection 14 day - Signs and lighting of M74 Glasgow East V1 on 27 January 2020									
No defects recorded									
Safety Inspection of M74 Main on 29 January 2020									
No defects recorded									

10798/74 : With: WB Entry slip to dedicated M8 Cway

Safety Patrol of M74 Glasgow East V1 on 01 December 2019									
No defects recorded									
Safety Inspection of M74 Slips on 05 December 2019									
No defects recorded									
Safety Patrol of M74 Glasgow East V1 on 08 December 2019									
No defects recorded									
Night Safety Inspection 14 day - Signs and lighting of M74 Glasgow East V1 on 12 December 2019									
No defects recorded									
Safety Inspection of M74 Slips on 12 December 2019									
No defects recorded									
Safety Patrol of M74 Glasgow East V1 on 15 December 2019									
No defects recorded									
Safety Inspection of M74 Slips on 19 December 2019									
No defects recorded									
Safety Inspection of M74 Slips on 20 December 2019									
No defects recorded									
Safety Patrol of M74 Glasgow East V1 on 22 December 2019									
No defects recorded									
Night Safety Inspection 14 day - Signs and lighting of M74 Glasgow East V1 on 23 December 2019									
No defects recorded									
Safety Patrol of M74 Glasgow East V1 on 23 December 2019									
No defects recorded									
Safety Inspection of M74 Slips on 27 December 2019									
No defects recorded									
Safety Patrol of M74 Glasgow East V1 on 30 December 2019									
No defects recorded									
Safety Inspection of M74 Slips on 03 January 2020									
No defects recorded									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
Night Safety Inspection 14 day - Signs and lighting of M74 Glasgow East V1 on 06 January 2020									
<i>No defects recorded</i>									
Safety Patrol of M74 Glasgow East V1 on 06 January 2020									
<i>No defects recorded</i>									
Safety Inspection of M74 Slips on 10 January 2020									
<i>No defects recorded</i>									
Safety Patrol of M74 Glasgow East V1 on 12 January 2020									
<i>No defects recorded</i>									
Night Safety Inspection 14 day - Signs and lighting of M74 Glasgow East V1 on 15 January 2020									
<i>No defects recorded</i>									
Safety Inspection of M74 Slips on 16 January 2020									
<i>No defects recorded</i>									
Safety Patrol of M74 Glasgow East V1 on 19 January 2020									
<i>No defects recorded</i>									
Safety Inspection of M74 Slips on 23 January 2020									
<i>No defects recorded</i>									
Safety Patrol of M74 Glasgow East V1 on 26 January 2020									
<i>No defects recorded</i>									
Night Safety Inspection 14 day - Signs and lighting of M74 Glasgow East V1 on 27 January 2020									
<i>No defects recorded</i>									
Safety Inspection of M74 Slips on 30 January 2020									
<i>No defects recorded</i>									
10799/13 : With:Link road from M74 EB Off slip to M74 WB									
Safety Patrol of M74 Glasgow East V1 on 01 December 2019									
<i>No defects recorded</i>									
Safety Inspection of M74 Slips on 05 December 2019									
<i>No defects recorded</i>									
Safety Patrol of M74 Glasgow East V1 on 08 December 2019									
<i>No defects recorded</i>									
Night Safety Inspection 14 day - Signs and lighting of M74 Glasgow East V1 on 12 December 2019									
<i>No defects recorded</i>									
Safety Inspection of M74 Slips on 12 December 2019									
<i>No defects recorded</i>									
Safety Patrol of M74 Glasgow East V1 on 15 December 2019									
<i>No defects recorded</i>									
Safety Inspection of M74 Slips on 19 December 2019									
<i>No defects recorded</i>									
Safety Inspection of M74 Slips on 20 December 2019									
<i>No defects recorded</i>									
Safety Patrol of M74 Glasgow East V1 on 22 December 2019									
<i>No defects recorded</i>									
Night Safety Inspection 14 day - Signs and lighting of M74 Glasgow East V1 on 23 December 2019									
<i>No defects recorded</i>									
Safety Patrol of M74 Glasgow East V1 on 23 December 2019									
<i>No defects recorded</i>									
Safety Inspection of M74 Slips on 27 December 2019									
<i>No defects recorded</i>									
Safety Patrol of M74 Glasgow East V1 on 30 December 2019									
<i>No defects recorded</i>									
Safety Inspection of M74 Slips on 03 January 2020									
<i>No defects recorded</i>									
Night Safety Inspection 14 day - Signs and lighting of M74 Glasgow East V1 on 06 January 2020									
<i>No defects recorded</i>									
Safety Patrol of M74 Glasgow East V1 on 06 January 2020									
<i>No defects recorded</i>									
Safety Inspection of M74 Slips on 10 January 2020									
<i>No defects recorded</i>									
Safety Patrol of M74 Glasgow East V1 on 12 January 2020									
<i>No defects recorded</i>									
Night Safety Inspection 14 day - Signs and lighting of M74 Glasgow East V1 on 15 January 2020									
<i>No defects recorded</i>									
Safety Inspection of M74 Slips on 16 January 2020									
<i>No defects recorded</i>									
Safety Patrol of M74 Glasgow East V1 on 19 January 2020									
<i>No defects recorded</i>									
Safety Inspection of M74 Slips on 23 January 2020									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Patrol of M74 Glasgow East V1 on 26 January 2020									
<i>No defects recorded</i>									
Night Safety Inspection 14 day - Signs and lighting of M74 Glasgow East V1 on 27 January 2020									
<i>No defects recorded</i>									
Safety Inspection of M74 Slips on 30 January 2020									
<i>No defects recorded</i>									
10799/15 : With: M74 WB On slip at M8 Jn 21									
Safety Patrol of M74 Glasgow East V1 on 01 December 2019									
<i>No defects recorded</i>									
Safety Inspection of M74 Slips on 05 December 2019									
<i>No defects recorded</i>									
Safety Patrol of M74 Glasgow East V1 on 08 December 2019									
<i>No defects recorded</i>									
Night Safety Inspection 14 day - Signs and lighting of M74 Glasgow East V1 on 12 December 2019									
<i>No defects recorded</i>									
Safety Inspection of M74 Slips on 12 December 2019									
<i>No defects recorded</i>									
Safety Patrol of M74 Glasgow East V1 on 15 December 2019									
<i>No defects recorded</i>									
Safety Inspection of M74 Slips on 19 December 2019									
<i>No defects recorded</i>									
Safety Inspection of M74 Slips on 20 December 2019									
<i>No defects recorded</i>									
Safety Patrol of M74 Glasgow East V1 on 22 December 2019									
<i>No defects recorded</i>									
Night Safety Inspection 14 day - Signs and lighting of M74 Glasgow East V1 on 23 December 2019									
<i>No defects recorded</i>									
Safety Patrol of M74 Glasgow East V1 on 23 December 2019									
<i>No defects recorded</i>									
Safety Inspection of M74 Slips on 27 December 2019									
<i>No defects recorded</i>									
Safety Patrol of M74 Glasgow East V1 on 30 December 2019									
<i>No defects recorded</i>									
Safety Inspection of M74 Slips on 03 January 2020									
<i>No defects recorded</i>									
Night Safety Inspection 14 day - Signs and lighting of M74 Glasgow East V1 on 06 January 2020									
<i>No defects recorded</i>									
Safety Patrol of M74 Glasgow East V1 on 06 January 2020									
<i>No defects recorded</i>									
Safety Inspection of M74 Slips on 10 January 2020									
<i>No defects recorded</i>									
Safety Patrol of M74 Glasgow East V1 on 12 January 2020									
<i>No defects recorded</i>									
Night Safety Inspection 14 day - Signs and lighting of M74 Glasgow East V1 on 15 January 2020									
<i>No defects recorded</i>									
Safety Inspection of M74 Slips on 16 January 2020									
<i>No defects recorded</i>									
Safety Patrol of M74 Glasgow East V1 on 19 January 2020									
<i>No defects recorded</i>									
Safety Inspection of M74 Slips on 23 January 2020									
<i>No defects recorded</i>									
Safety Patrol of M74 Glasgow East V1 on 26 January 2020									
<i>No defects recorded</i>									
Night Safety Inspection 14 day - Signs and lighting of M74 Glasgow East V1 on 27 January 2020									
<i>No defects recorded</i>									
Safety Inspection of M74 Slips on 30 January 2020									
<i>No defects recorded</i>									

10799/05 : With: 3-lane Dedicated Cway to M8 WB & M77 SB

Safety Patrol of M74 Glasgow East V1 on 01 December 2019

No defects recorded

Safety Inspection of M8 Glasgow East V1 on 03 December 2019

No defects recorded

Safety Patrol of M8 Glasgow East V1 on 07 December 2019

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
No defects recorded									
Safety Patrol of M74 Glasgow East V1 on 08 December 2019									
No defects recorded									
Safety Inspection of M8 Glasgow East V1 on 10 December 2019									
No defects recorded									
Night Safety Inspection 14 day - Signs and lighting of M8 Glasgow East V1 on 10 December 2019									
No defects recorded									
Night Safety Inspection 14 day - Signs and lighting of M74 Glasgow East V1 on 12 December 2019									
No defects recorded									
Safety Patrol of M8 Glasgow East V1 on 14 December 2019									
No defects recorded									
Safety Patrol of M74 Glasgow East V1 on 15 December 2019									
No defects recorded									
Safety Inspection of M8 Glasgow East V1 on 17 December 2019									
No defects recorded									
Safety Patrol of M8 Glasgow East V1 on 21 December 2019									
No defects recorded									
Night Safety Inspection 14 day - Signs and lighting of M8 Glasgow East V1 on 21 December 2019									
No defects recorded									
Safety Patrol of M74 Glasgow East V1 on 22 December 2019									
No defects recorded									
Night Safety Inspection 14 day - Signs and lighting of M74 Glasgow East V1 on 23 December 2019									
No defects recorded									
Safety Patrol of M74 Glasgow East V1 on 23 December 2019									
No defects recorded									
Safety Inspection of M8 Glasgow East V1 on 23 December 2019									
No defects recorded									
Safety Patrol of M8 Glasgow East V1 on 28 December 2019									
No defects recorded									
Safety Patrol of M74 Glasgow East V1 on 30 December 2019									
No defects recorded									
Safety Inspection of M8 Glasgow East V1 on 31 December 2019									
No defects recorded									
Safety Patrol of M8 Glasgow East V1 on 04 January 2020									
No defects recorded									
Night Safety Inspection 14 day - Signs and lighting of M8 Glasgow East V1 on 04 January 2020									
No defects recorded									
Night Safety Inspection 14 day - Signs and lighting of M74 Glasgow East V1 on 06 January 2020									
No defects recorded									
Safety Patrol of M74 Glasgow East V1 on 06 January 2020									
No defects recorded									
Safety Inspection of M8 Glasgow East V1 on 07 January 2020									
No defects recorded									
Safety Patrol of M8 Glasgow East V1 on 11 January 2020									
No defects recorded									
Safety Patrol of M74 Glasgow East V1 on 12 January 2020									
No defects recorded									
Night Safety Inspection 14 day - Signs and lighting of M8 Glasgow East V1 on 14 January 2020									
No defects recorded									
Safety Inspection of M8 Glasgow East V1 on 14 January 2020									
No defects recorded									
Night Safety Inspection 14 day - Signs and lighting of M74 Glasgow East V1 on 15 January 2020									
No defects recorded									
Safety Patrol of M8 Glasgow East V1 on 18 January 2020									
No defects recorded									
Safety Patrol of M74 Glasgow East V1 on 19 January 2020									
No defects recorded									
Safety Inspection of M8 Glasgow East V1 on 21 January 2020									
SW85-538622-237246252	182m	182m	STRUCTURE	Pothole around Expansion Joint (PEXP)	CAT 1	18/02/2020	Completed Defects	11/03/2020	M8 W/B JCT 20/22 400YDS PRIOR TO OFF TO M77 LANE 2 @ BRIDGE JOINT
Safety Patrol of M8 Glasgow East V1 on 25 January 2020									
No defects recorded									
Safety Patrol of M74 Glasgow East V1 on 26 January 2020									
No defects recorded									
Night Safety Inspection 14 day - Signs and lighting of M74 Glasgow East V1 on 27 January 2020									
No defects recorded									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
Safety Inspection of M8 Glasgow East V1 on 28 January 2020									
No defects recorded									
Night Safety Inspection 14 day - Signs and lighting of M8 Glasgow East V1 on 28 January 2020									
No defects recorded									