

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/10/2020 and 22/12/2020, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'AGAINST:EB SINGLE CWAY TO KILBARCHAN','WITH:WB KILBARCHAN TO SINGLE CWAY','AGAINST: EB ON SLIP FROM KILBARCHAN ROAD','WITH: WB OFF SLIP TO KILBARCHAN ROAD','AGAINST: EB KILBARCHAN JCT TO BARROCHAN JCT','WITH:WB BARROCHAN JCT TO KILBARCHAN JCT','AGAINST: EB OFF SLIP TO B789 BARROCHAN RD','WITH: WB ON SLIP FROM B789 BARROCHAN RD','AGAINST: EB ON SLIP FROM B789 BARROCHAN RD','WITH: WB OFF SLIP TO B789 BARROCHAN RD','AGAINST: EB WEST TO EAST BARROCHAN JUNCTION','AGAINST: ON SLIP BARROCHAN JCT TO LINCLIVE JCT','WITH: LINCLIVE JCT TO OFF SLIP BARRUCHAN JCT','AGAINST: EB OFF SLIP TO LINCLIVE ROUNDABOUT','WITH: WB ON SLIP FROM LINCLIVE ROUNDABOUT','WITH: WB EAST TO WEST BARROCHAN JUNCTION','AGAINST: EB ON SLIP FROM LINCLIVE ROUNDABOUT','WITH: WB OFF SLIP TO LINCLIVE ROUNDABOUT','AGAINST: EB OFF SLIP TO ON SLIP LINCLIVE JCT','WITH: WB OFF SLIP TO ON SLIP LINCLIVE JCT','AGAINST: EB E LINCLIVE JCT TO M8 ST. JAMES VIADUCT','WITH: WB M8 ST.JAMES VIAD TO OFF SLIP LINCLIVE JCT','AGAINST: EB OFF SLIP TO A761 RBT ST. JAMES INT','WITH: WB SLIP FROM A761 RBT ST. JAMES INT',) Or

(Section is 'AGAINST: M8 EB OFF SLIP TO A737 RBT','WITH: SLIP ON TO M8 WB A737 INTERCHANGE','AGAINST: SLIP OFF M8 EB TO MID POINT A737 BRIDGES','WITH: MID POINT A737 BRIDGES TO SLIP RD ENTRY','AGAINST:MID POINT A737 BRIDGE TO SLIP FROM A737','WITH: OFF SLIP TO A737 TO MID POINT A737 BRIDGES','AGAINST: A737 2 WAY SLIP TO ENTRY M8 EB','WITH: SLIP TO A737 RBT','AGAINST: SLIP FROM A737 INT TO SLIP OFF M8 EB','WITH: A937 WB ENTRY SLIP TO A937 INT OFF SLIP','AGAINST: BARNSFORD ROAD TO 2 WAY SLIP','WITH: SLIP FROM A737 TO ENTRY M8 WB','AGAINST: A737 INT RBT TO ENTRY M8 EB','WITH: M8 TO A737 ELEVATED SECTION WB','AGAINST: A737 TO M8 ELEVATED SECTION EB','WITH: AIRPORT RBT (S) TO M8 WB','AGAINST: SLIP RD ENTRY TO AIRPORT UNDERPASS','WITH: AIRPORT UNDERPASS TO SLIP RD ENTRY','WITH: SLIP RD OFF M8 WB TO AIRPORT RBT','AGAINST: AIRPORT INTERCHANGE BRIDGE EASTBOUND','AGAINST: SLIP FROM AIRPORT EASTBOUND ONTO M8','WITH: END OF VIADUCT WBND TO SLIP RD TO APORT','HERMISTON ROUNDABOUT',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	---------	-------	-----------	-------------	-----------------	--------------------------	----------------	-----------------	----------------------

13714/77 : WITH: END OF VIADUCT WBND TO SLIP RD TO APORT

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 12 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 26 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 09 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 23 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 07 December 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 19 December 2020

No defects recorded

13715/05 : WITH: AIRPORT UNDERPASS TO SLIP RD ENTRY

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 12 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 26 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 09 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 23 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 07 December 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 19 December 2020

No defects recorded

13716/05 : WITH: A937 WB ENTRY SLIP TO A937 INT OFF SLIP

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 12 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 26 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 09 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 23 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 07 December 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 19 December 2020

No defects recorded

13716/55 : WITH: OFF SLIP TO A737 TO MID POINT A737 BRIDGES

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 12 October 2020

NSW76-606316-237887243	173m	0m	TRAFFIC_SIGNS	Lamp failure (LAMP)	CAT 1	14/10/2020	Completed Defects	13/10/2020	M8 29 WB OFFRAMP
------------------------	------	----	---------------	------------------------	-------	------------	----------------------	------------	------------------

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 26 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 09 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 23 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 07 December 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 19 December 2020

No defects recorded

13717/00 : WITH: MID POINT A737 BRIDGES TO SLIP RD ENTRY

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 12 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 26 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 09 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 23 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 07 December 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 19 December 2020

No defects recorded

13717/02 : AGAINST: SLIP OFF M8 EB TO MID POINT A737 BRIDGES

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 12 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 26 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 09 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 23 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 07 December 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 19 December 2020

No defects recorded

13716/56 : AGAINST: MID POINT A737 BRIDGE TO SLIP FROM A737

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 12 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 26 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 09 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 23 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 07 December 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 19 December 2020

No defects recorded

13716/06 : AGAINST: SLIP FROM A737 INT TO SLIP OFF M8 EB

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 12 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 26 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 09 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 23 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 07 December 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 19 December 2020

No defects recorded

13715/06 : AGAINST: SLIP RD ENTRY TO AIRPORT UNDERPASS

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 12 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 26 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 09 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 23 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 07 December 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 19 December 2020

No defects recorded

13714/88 : AGAINST: AIRPORT INTERCHANGE BRIDGE EASTBOUND

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 12 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 26 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 09 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 23 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 07 December 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 19 December 2020

No defects recorded

13714/87 : AGAINST: SLIP FROM AIRPORT EASTBOUND ONTO M8

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 12 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 26 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 09 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 23 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 07 December 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 19 December 2020

No defects recorded

13714/95 : WITH: SLIP RD OFF M8 WB TO AIRPORT RBT

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 12 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 26 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 09 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 23 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 07 December 2020

NSW76-608592-237968811	167m	0m	TRAFFIC_SIGNS	Lamp failure (LAMP)	CAT 1	09/12/2020	Completed Defects	08/12/2020	M8 JCT 28 OFFSLIP WB OS VERGE
NSW76-608592-237968812	164m	0m	TRAFFIC_SIGNS	Lamp failure (LAMP)	CAT 1	09/12/2020	Completed Defects	08/12/2020	M8 JCT 28 OFFSLIP WB NS VERGE

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 19 December 2020

No defects recorded

13715/11 : WITH: AIRPORT RBT (S) TO M8 WB

13715/90 : AGAINST: BARNSFORD ROAD TO 2 WAY SLIP**Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 12 October 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 26 October 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 09 November 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 23 November 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 07 December 2020**

NSW76-608592-237968820	64m	0m	TRAFFIC_SIGNS	Lamp failure (LAMP)	CAT 1	09/12/2020	Completed Defects	08/12/2020	M8 JCT 28A ONSLIP EB NS VERGE FROM A737
------------------------	-----	----	---------------	------------------------	-------	------------	----------------------	------------	--

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 19 December 2020*No defects recorded***13716/11 : WITH: SLIP TO A737 RBT****Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 12 October 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 26 October 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 09 November 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 23 November 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 07 December 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 19 December 2020***No defects recorded***13716/12 : AGAINST: A737 2 WAY SLIP TO ENTRY M8 EB****Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 12 October 2020**

NSW76-606316-237887239	85m	0m	TRAFFIC_SIGNS	Lamp failure (LAMP)	CAT 1	13/10/2020	Completed Defects	13/10/2020	M8 EB J29 ONRAMP
------------------------	-----	----	---------------	------------------------	-------	------------	----------------------	------------	------------------

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 26 October 2020*No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 09 November 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 23 November 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 07 December 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 19 December 2020***No defects recorded***13717/03 : WITH: SLIP ON TO M8 WB A737 INTERCHANGE****Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 12 October 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 26 October 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 09 November 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 23 November 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 07 December 2020**

NSW76-608592-237968813	113m	0m	TRAFFIC_SIGNS	Lamp failure (LAMP)	CAT 1	09/12/2020	Completed Defects	08/12/2020	M8 JCT 29 ONSLIP WB OS VERGE
------------------------	------	----	---------------	------------------------	-------	------------	----------------------	------------	---------------------------------

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 19 December 2020

NSW76-608951-237968797	58m	0m	TRAFFIC_SIGNS	Lamp failure (LAMP)	CAT 1	20/12/2020	Completed Defects	20/12/2020	m8 wlb j29 onslip offside verge
------------------------	-----	----	---------------	------------------------	-------	------------	----------------------	------------	---------------------------------

13717/49 : AGAINST: M8 EB OFF SLIP TO A737 RBT**Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 12 October 2020***No defects recorded*

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 26 October 2020*No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 09 November 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 23 November 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 07 December 2020**

NSW76-608592-237968814	177m	0m	TRAFFIC_SIGNS	Lamp failure (LAMP)	CAT 1	09/12/2020	Completed Defects	08/12/2020	M8 JCT 29 OFFSLIP EB NS VERGE
------------------------	------	----	---------------	---------------------	-------	------------	-------------------	------------	-------------------------------

NSW76-608592-237968815	167m	0m	TRAFFIC_SIGNS	Lamp failure (LAMP)	CAT 1	09/12/2020	Completed Defects	08/12/2020	M8 JCT 29 OFFSLIP EB OS VERGE
------------------------	------	----	---------------	---------------------	-------	------------	-------------------	------------	-------------------------------

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 19 December 2020

NSW76-608951-237968800	244m	0m	TRAFFIC_SIGNS	Lamp failure (LAMP)	CAT 1	21/12/2020	Completed Defects	20/12/2020	m8 e/b j29 offslip n\ls
------------------------	------	----	---------------	---------------------	-------	------------	-------------------	------------	-------------------------

NSW76-608951-237968801	244m	0m	TRAFFIC_SIGNS	Lamp failure (LAMP)	CAT 1	21/12/2020	Completed Defects	20/12/2020	m8 e/b j29 offslip o\ls
------------------------	------	----	---------------	---------------------	-------	------------	-------------------	------------	-------------------------

14310/05 : WITH: WB M8 ST.JAMES VIAD TO OFF SLIP LINCLIVE JCT**Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 15 October 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 29 October 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 12 November 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 25 November 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 10 December 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 21 December 2020***No defects recorded***14310/06 : AGAINST: EB E LINCLIVE JCT TO M8 ST. JAMES VIADUCT****Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 15 October 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 29 October 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 12 November 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 25 November 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 10 December 2020**

NSW76-608637-237925883	1,436m	0m	TRAFFIC_SIGNS	Lamp failure (LAMP)	CAT 1	11/12/2020	Completed Defects	10/12/2020	A737 OFFSLIP TO ST JAMES INT OS VERGE
------------------------	--------	----	---------------	---------------------	-------	------------	-------------------	------------	---------------------------------------

NSW76-608637-237925884	1,434m	0m	TRAFFIC_SIGNS	Lamp failure (LAMP)	CAT 1	11/12/2020	Completed Defects	10/12/2020	A737 NB OFFSLIP TO ST JAMES INT NS VERGE
------------------------	--------	----	---------------	---------------------	-------	------------	-------------------	------------	--

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 21 December 2020*No defects recorded***14315/05 : WITH: WB OFF SLIP TO ON SLIP LINCLIVE JCT****Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 15 October 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 29 October 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 12 November 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 25 November 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 10 December 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 21 December 2020***No defects recorded***14315/06 : AGAINST: EB OFF SLIP TO ON SLIP LINCLIVE JCT**

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 15 October 2020*No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 29 October 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 12 November 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 25 November 2020**

NSW76-608183-237925871	305m	0m	TRAFFIC_SIGNS	Lamp failure (LAMP)	CAT 1	26/11/2020	Completed Defects	26/11/2020	a737 linwood e/b off ramp
------------------------	------	----	---------------	---------------------	-------	------------	-------------------	------------	---------------------------

NSW76-608183-237925872	305m	0m	TRAFFIC_SIGNS	Lamp failure (LAMP)	CAT 1	26/11/2020	Completed Defects	26/11/2020	a737 linwood off ramp e/b
------------------------	------	----	---------------	---------------------	-------	------------	-------------------	------------	---------------------------

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 10 December 2020*No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 21 December 2020***No defects recorded***14315/09 : WITH: WB OFF SLIP TO LINCLIVE ROUNDABOUT****Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 15 October 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 29 October 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 12 November 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 25 November 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 10 December 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 21 December 2020***No defects recorded***14315/10 : AGAINST: EB ON SLIP FROM LINCLIVE ROUNDABOUT****Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 15 October 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 29 October 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 12 November 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 25 November 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 10 December 2020**

NSW76-608637-237925882	15m	0m	TRAFFIC_SIGNS	Lamp failure (LAMP)	CAT 1	11/12/2020	Completed Defects	10/12/2020	A737 LINWOOD ONSLIP NB NS VERGE
------------------------	-----	----	---------------	---------------------	-------	------------	-------------------	------------	---------------------------------

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 21 December 2020*No defects recorded***14315/17 : WITH: WB ON SLIP FROM LINCLIVE ROUNDABOUT****Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 15 October 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 29 October 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 12 November 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 25 November 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 10 December 2020**

NSW76-608637-237925886	11m	0m	TRAFFIC_SIGNS	Lamp failure (LAMP)	CAT 1	11/12/2020	Completed Defects	10/12/2020	A737 LINWOOD ONSLIP SB NS VERGE
------------------------	-----	----	---------------	---------------------	-------	------------	-------------------	------------	---------------------------------

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 21 December 2020*No defects recorded***14315/18 : AGAINST: EB OFF SLIP TO LINCLIVE ROUNDABOUT****Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 15 October 2020***No defects recorded***Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 29 October 2020***No defects recorded*

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 12 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 25 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 10 December 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 21 December 2020

No defects recorded

14315/39 : WITH: LINCLIVE JCT TO OFF SLIP BARRUCHAN JCT

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 15 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 29 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 12 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 25 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 10 December 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 21 December 2020

No defects recorded

14315/40 : AGAINST: ON SLIP BARROCHAN JCT TO LINCLIVE JCT

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 15 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 29 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 12 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 25 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 10 December 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 21 December 2020

No defects recorded

14320/09 : WITH: WB OFF SLIP TO B789 BARROCHAN RD

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 15 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 29 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 12 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 25 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 10 December 2020

NSW76-608637-237925887	359m	0m	TRAFFIC_SIGNS	Lamp failure (LAMP)	CAT 1	11/12/2020	Completed Defects	10/12/2020	A737 JOHNSTONE OFFSLIP SB OS VERGE
------------------------	------	----	---------------	------------------------	-------	------------	----------------------	------------	---------------------------------------

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 21 December 2020

No defects recorded

14320/10 : AGAINST: EB ON SLIP FROM B789 BARROCHAN RD

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 15 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 29 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 12 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 25 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 10 December 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 21 December 2020

No defects recorded

14320/05 : WITH: WB EAST TO WEST BARROCHAN JUNCTION

14320/60 : AGAINST: EB KILBARCHAN JCT TO BARROCHAN JCT

- Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 15 October 2020
No defects recorded
- Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 29 October 2020
No defects recorded
- Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 12 November 2020
No defects recorded
- Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 25 November 2020
No defects recorded
- Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 10 December 2020
No defects recorded
- Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 21 December 2020
No defects recorded

14325/09 : WITH: WB OFF SLIP TO KILBARCHAN ROAD

- Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 15 October 2020
No defects recorded
- Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 29 October 2020
No defects recorded
- Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 12 November 2020
No defects recorded
- Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 25 November 2020
No defects recorded
- Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 10 December 2020
No defects recorded
- Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 21 December 2020
No defects recorded

14325/10 : AGAINST: EB ON SLIP FROM KILBARCHAN ROAD

- Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 15 October 2020
No defects recorded
- Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 29 October 2020
No defects recorded
- Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 12 November 2020
No defects recorded
- Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 25 November 2020
No defects recorded
- Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 10 December 2020
No defects recorded
- Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 21 December 2020
No defects recorded

14325/05 : WITH:WB KILBARCHAN TO SINGLE CWAY

- Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 15 October 2020
No defects recorded
- Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 29 October 2020
No defects recorded
- Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 12 November 2020
No defects recorded
- Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 25 November 2020
No defects recorded
- Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 10 December 2020
No defects recorded
- Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 21 December 2020
No defects recorded

NSW76-608637-237925881	118m	0m	TRAFFIC_SIGNS	Lamp failure (LAMP)	CAT 1	11/12/2020	Completed Defects	10/12/2020	A737 SB MAIN CARRIAGEWAY AFTER KILBARCHAN OFFSLIP NS VERGE
------------------------	------	----	---------------	---------------------	-------	------------	-------------------	------------	--

14325/06 : AGAINST:EB SINGLE CWAY TO KILBARCHAN

- Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 15 October 2020
No defects recorded
- Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 29 October 2020
No defects recorded
- Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 12 November 2020
No defects recorded
- Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 25 November 2020
No defects recorded

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 10 December 2020

NSW76-608637-237925880	5m	0m	TRAFFIC_SIGNS	Lamp failure (LAMP)	CAT 1	11/12/2020	Completed Defects	10/12/2020	A737 NB APPROACH TO START OF DUAL CARRIAGEWAY CENTRE ISLAND
------------------------	----	----	---------------	------------------------	-------	------------	----------------------	------------	--

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 21 December 2020

No defects recorded

14310/03 : WITH: WB SLIP FROM A761 RBT ST. JAMES INT

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 15 October 2020

NSW76-606344-237809872	366m	0m	LIGHTING_POINT	No electricity supply (NOSP)	CAT 1	16/10/2020	Completed Defects	15/10/2020	a737 e/b carriageway to join m8 and e/b off ramp to st james ont
------------------------	------	----	----------------	---------------------------------	-------	------------	----------------------	------------	---

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 29 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 12 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 25 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 10 December 2020

NSW76-608637-237925885	493m	0m	TRAFFIC_SIGNS	Lamp failure (LAMP)	CAT 1	11/12/2020	Completed Defects	10/12/2020	A737 SB ONSLIP FROM ST JAMES INT NS VERGE
------------------------	------	----	---------------	------------------------	-------	------------	----------------------	------------	--

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 21 December 2020

No defects recorded

14310/04 : AGAINST: EB OFF SLIP TO A761 RBT ST. JAMES INT

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 15 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 29 October 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 12 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 25 November 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 10 December 2020

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 21 December 2020

No defects recorded