

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/12/2019 and 15/08/2020, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'B705 CATRINE RD JUNCTION TO B743 MANSEFIELD RD JCT','50M NTH OF JCT HIGHCLEWS TO B705 CATRINE RD','B713 JUNCTION TO 50M NTH JCT HIGHCLEWS','END OF EXIT FROM AUCHINLECK RBT TO B713 JUNCTION','AGAINST: SOUTHBOUND APPROACH TO AUCHINLECK RBT','WITH: EXIT FROM AUCHINLECK ROUNDABOUT','B7063 AUCHINLECK ROUNDABOUT',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
13270/06 : B7063 AUCHINLECK ROUNDABOUT									
Safety Inspection of A76 & A77 Ayr North V1 on 03 December 2019									
SW82537227-237176781	64m	64m	Drainage Ancillary Items	Other (OTHR)	CAT 2		Cat 2 Awaiting Action		A76 AUCHINLECK RBT DITCH CLEARANCE
Safety Inspection of A76 & A77 Ayr North V1 on 10 December 2019									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 17 December 2019									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 24 December 2019									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 31 December 2019									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 07 January 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 14 January 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 21 January 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 28 January 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 04 February 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 11 February 2020									
SW82539451-237271124	80m	80m	GULLY	Other (OTHR)	CAT 1	12/02/2020	Completed Defects	11/02/2020	a76 templeton rbt. (done)
Safety Inspection of A76 & A77 Ayr North V1 on 18 February 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 25 February 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 03 March 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 10 March 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 17 March 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 24 March 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 31 March 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 07 April 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 14 April 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 21 April 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 28 April 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 05 May 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 12 May 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 19 May 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 26 May 2020									
No defects recorded									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
Safety Inspection of A76 & A77 Ayr North V1 on 02 June 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 09 June 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 16 June 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 23 June 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 30 June 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 07 July 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 14 July 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 21 July 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 28 July 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 04 August 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 11 August 2020									
<i>No defects recorded</i>									

13270/07 : WITH: EXIT FROM AUCHINLECK ROUNDABOUT

Safety Inspection of A76 & A77 Ayr North V1 on 03 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 10 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 17 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 24 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 31 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 07 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 14 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 21 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 28 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 04 February 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 11 February 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 18 February 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 25 February 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 03 March 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 10 March 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 17 March 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 24 March 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 31 March 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 07 April 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 14 April 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 21 April 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 28 April 2020									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 05 May 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 12 May 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 19 May 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 26 May 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 02 June 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 09 June 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 16 June 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 23 June 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 30 June 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 07 July 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 14 July 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 21 July 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 28 July 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 04 August 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 11 August 2020									
<i>No defects recorded</i>									
13270/09 : END OF EXIT FROM AUCHINLECK RBT TO B713 JUNCTION									
Safety Inspection of A76 & A77 Ayr North V1 on 03 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 10 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 17 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 24 December 2019									
SW82537799-237221639	2,939m	2,940m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	25/12/2019	Completed Defects	24/12/2019	A76 S/B C/W AT LAYBY NORTH OF KENSTY SOUTH OF MAUCLINE
SW82537799-237221640	2,939m	2,940m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	25/12/2019	Completed Defects	24/12/2019	A76 N/B C/W AT LAYBY SOUTH OF CATRINE JCT
Safety Inspection of A76 & A77 Ayr North V1 on 31 December 2019									
SW82537974-237222069	3,004m	3,004m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	01/01/2020	Completed Defects	31/12/2019	a78 prior to layby south of jct for catrine south of vmachline
SW82537974-237222070	2,997m	2,997m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	01/01/2020	Completed Defects	31/12/2019	a78 prior to layby south of jct for catrine south of vmachline
Safety Inspection of A76 & A77 Ayr North V1 on 07 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 14 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 21 January 2020									
SW82538623-237246254	2,818m	2,818m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	22/01/2020	Completed Defects	21/01/2020	a76 n/b c/w approx 100m south of layby south of catrine jct
Safety Inspection of A76 & A77 Ayr North V1 on 28 January 2020									
SW82538875-237250057	3,116m	3,116m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	29/01/2020	Completed Defects	28/01/2020	a76 n/b c/w approx 100m south of jct for catrine

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
SW82538875-237250058	3,116m	3,116m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	29/01/2020	Completed Defects	28/01/2020	a76 n/b c/w approx 100m south of jct for catrine
SW82538875-237250059	3,116m	3,116m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	29/01/2020	Completed Defects	28/01/2020	a76 n/b c/w approx 100m south of jct for catrine
Safety Inspection of A76 & A77 Ayr North V1 on 04 February 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 11 February 2020									
SW82539451-237271125	3,178m	3,178m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	12/02/2020	Completed Defects	12/02/2020	a76 approx 70m south of jct for catrine s/b. (not done)
SW82539451-237271126	3,190m	3,190m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	12/02/2020	Completed Defects	12/02/2020	a76 s/b c/w approx 100m south of jct for catrine not done
SW82539451-237271127	3,089m	3,089m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	12/02/2020	Completed Defects	12/02/2020	a76 s/b c/w approx 125m south of jct for catrine. not done
SW82539451-237271128	3,124m	3,124m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	12/02/2020	Completed Defects	12/02/2020	a76 s/b c/w approx 100m south of jct for catrine. not done
Safety Inspection of A76 & A77 Ayr North V1 on 18 February 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 25 February 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 03 March 2020									
SW82547569-237304529	2,963m	2,963m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/03/2020	Completed Defects	03/03/2020	a76 s/b c/w opposite lsyby south of catrine. (not done)
SW82547569-237304530	3,090m	3,060m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/03/2020	Completed Defects	03/03/2020	a76 s/b c/w approx 30m north of bridge deck south of jct for catrine. (not done)
SW82547569-237304531	3,076m	3,076m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/03/2020	Completed Defects	03/03/2020	a76 s/b c/w approx 30m north of bridge deck south of jct for catrine. (not done)
SW82547569-237304532	2,984m	2,984m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/03/2020	Completed Defects	03/03/2020	a76 n/b c/w prior to bridge deck south of jct for catrine (not done)
Safety Inspection of A76 & A77 Ayr North V1 on 10 March 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 17 March 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 24 March 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 31 March 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 07 April 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 14 April 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 21 April 2020									
SW82568858-237354885	1,774m	1,774m	TRAFFIC_SIGNS	Other (OTHR)	CAT 1	19/05/2020	Completed Defects	15/05/2020	a76 n/b c/w at layby nth of littke eitdith
Safety Inspection of A76 & A77 Ayr North V1 on 28 April 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 05 May 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 12 May 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 19 May 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 26 May 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 02 June 2020									
SW82594128-237591146	3,018m	3,018m	INVASIVE_SPECIES	Other (OTHR)	CAT 2		Cat 2 Awaiting Action		a76 nb vergè at bridge deck sth of catrine jct.

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
Safety Inspection of A76 & A77 Ayr North V1 on 09 June 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 16 June 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 23 June 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 30 June 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 07 July 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 14 July 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 21 July 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 28 July 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 04 August 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 11 August 2020									
<i>No defects recorded</i>									
13270/54 : B713 JUNCTION TO 50M NTH JCT HIGHCLEWS									
Safety Inspection of A76 & A77 Ayr North V1 on 03 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 10 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 17 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 24 December 2019									
SW82537799-237221641	701m	702m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	25/12/2019	Completed Defects	24/12/2019	A76 N/B C/W 50M PRIOR TO HOWFORD BRIDGE
Safety Inspection of A76 & A77 Ayr North V1 on 31 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 07 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 14 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 21 January 2020									
SW82538623-237246253	567m	567m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	22/01/2020	Completed Defects	21/01/2020	a76 s/b c/w approx 200m south of howford bridge
Safety Inspection of A76 & A77 Ayr North V1 on 28 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 04 February 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 11 February 2020									
SW82539451-237271129	617m	617m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	12/02/2020	Completed Defects	11/02/2020	a76 n/b c/w approx 50 south of howford bridge (not done)
Safety Inspection of A76 & A77 Ayr North V1 on 18 February 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 25 February 2020									
SW82544526-237291858	680m	680m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	26/02/2020	Completed Defects	25/02/2020	a76 s/b c/w just south of howford bridge
Safety Inspection of A76 & A77 Ayr North V1 on 03 March 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 10 March 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 17 March 2020									
SW82553538-237328337	768m	768m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/03/2020	Completed Defects	17/03/2020	a76 n/b howford bridge south of mauchline. ISU
SW82553538-237328338	573m	573m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/03/2020	Completed Defects	18/03/2020	a76 s/b c/w south of howford bridge south of mauchline. (night shift)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
Safety Inspection of A76 & A77 Ayr North V1 on 24 March 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 31 March 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 07 April 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 14 April 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 21 April 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 28 April 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 05 May 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 12 May 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 19 May 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 26 May 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 02 June 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 09 June 2020									
SW82598719-237597053	768m	768m	CARRIAGEWAY	Pothole (POTH)	CAT 1	10/06/2020	Completed Defects	09/06/2020	a78 nb cw howfodr bridge sth of mauchline
Safety Inspection of A76 & A77 Ayr North V1 on 16 June 2020									
SW82601136-237639285	767m	767m	CARRIAGEWAY	Pothole (POTH)	CAT 1	14/07/2020	Completed Defects	09/07/2020	a76 nb cw howford bridge sth of mauchline
SW82601136-237639286	905m	912m	FENCES_AND_BARRIERS	Accident damage (ACCD)	CAT 1	14/07/2020	Completed Defects	02/07/2020	a76 sb howford bridge sth of mauchline
Safety Inspection of A76 & A77 Ayr North V1 on 23 June 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 30 June 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 07 July 2020									
SW82602588-237688146	767m	767m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	08/07/2020	Completed Defects	07/07/2020	a76 nb cw howford bridge
Safety Inspection of A76 & A77 Ayr North V1 on 14 July 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 21 July 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 28 July 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 04 August 2020									
SW82603727-237743684	794m	794m	GULLY	Blockage (BLOK)	CAT 1	05/08/2020	Completed Defects	04/08/2020	a76 sb cw howford bridge
Safety Inspection of A76 & A77 Ayr North V1 on 11 August 2020									
<i>No defects recorded</i>									
13270/75 : 50M NTH OF JCT HIGHCLEWS TO B705 CATRINE RD									
Safety Inspection of A76 & A77 Ayr North V1 on 03 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 10 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 17 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 24 December 2019									
SW82537799-237221642	1,128m	1,129m	GULLY	Blockage (BLOK)	CAT 1	25/12/2019	Completed Defects	24/12/2019	A76 S/B 500M SOUTH OF MAUCHLINE

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
SW82537799-237221643	1,226m	1,227m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	25/12/2019	Completed Defects	24/12/2019	A76 ON CENTRE LINE 350M SOUTH OF MAUCHLINE
SW82537799-237221644	1,256m	1,257m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	25/12/2019	Completed Defects	24/12/2019	A76 ON CENTRE LINE 245M SOUTH OF MAUCHLINE
Safety Inspection of A76 & A77 Ayr North V1 on 31 December 2019									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 07 January 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 14 January 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 21 January 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 28 January 2020									
SW82538875-237250060	696m	696m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/02/2020	Completed Defects	09/04/2020	a76 n/b c/w approx 800msouth of mauchline
SW82538875-237250061	660m	660m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/02/2020	Completed Defects	09/04/2020	a76 n/b c/w approx 800msouth of mauchline. 3mx1m
Safety Inspection of A76 & A77 Ayr North V1 on 04 February 2020									
SW82539189-237255287	820m	820m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	05/02/2020	Completed Defects	05/02/2020	a76 s/b c/w approx 250m north of kingencluegh farm south of mauchline (not done)
Safety Inspection of A76 & A77 Ayr North V1 on 11 February 2020									
SW82539451-237271130	1,262m	1,262m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	12/02/2020	Completed Defects	11/02/2020	a76 n/b c/w approx 320m south of mauchline. (done)
Safety Inspection of A76 & A77 Ayr North V1 on 18 February 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 25 February 2020									
SW82544526-237291859	1,240m	1,240m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	24/03/2020	Completed Defects	28/02/2020	a76 s/b c/w mauchline southgateway. (not done)
SW82544526-237291861	1,212m	1,212m	MANHOLE	Difference in level with road (IDLV)	3RD PTY	24/03/2020	Awaiting CCMS Temp Date	01/01/9999	a76 s/b c/w approx 350yards south of mauchline sth gateway
Safety Inspection of A76 & A77 Ayr North V1 on 03 March 2020									
SW82547569-237304533	1,373m	1,373m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/03/2020	Completed Defects	03/03/2020	a76 centreline approx 200 yards south of mauchline. (not done)
Safety Inspection of A76 & A77 Ayr North V1 on 10 March 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 17 March 2020									
SW82553538-237328339	1,402m	1,402m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/03/2020	Completed Defects	18/03/2020	a76 n/b c/w approx 200 yards south of mauchline. (night shift)
SW82553538-237328340	1,484m	1,484m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/03/2020	Completed Defects	18/03/2020	a76 n/b c/w approx 80 yards south of mauchline. (night shift)
Safety Inspection of A76 & A77 Ayr North V1 on 24 March 2020									
No defects recorded									
Safety Inspection of A76 Adhoc Mauchline on 30 March 2020									
SW82559589-237340491	1,273m	1,273m	GULLY	Blockage (BLOK)	CAT 1	27/04/2020	Completed Defects	21/04/2020	ch-1273
SW82559589-237340492	1,271m	1,271m	GULLY	Blockage (BLOK)	CAT 1	27/04/2020	Completed Defects	21/04/2020	1271
SW82559589-237340493	1,327m	1,327m	GULLY	Blockage (BLOK)	CAT 1	27/04/2020	Completed Defects	21/04/2020	1327
SW82559589-237340494	1,372m	1,372m	GULLY	Blockage (BLOK)	CAT 1	27/04/2020	Completed Defects	21/04/2020	
SW82559589-237340495	1,425m	1,425m	GULLY	Blockage (BLOK)	CAT 1	27/04/2020	Completed Defects	21/04/2020	

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
SW82559589-237340496	1,477m	1,477m	GULLY	Blockage (BLOK)	CAT 1	27/04/2020	Completed Defects	21/04/2020	
SW82559589-237340497	1,475m	1,475m	GULLY	Blockage (BLOK)	CAT 1	27/04/2020	Completed Defects	21/04/2020	
SW82559589-237340498	1,522m	1,522m	GULLY	Blockage (BLOK)	CAT 1	27/04/2020	Completed Defects	21/04/2020	
SW82559589-237340499	1,525m	1,525m	GULLY	Blockage (BLOK)	CAT 1	27/04/2020	Completed Defects	21/04/2020	
SW82559589-237340500	1,574m	1,574m	GULLY	Blockage (BLOK)	CAT 1	27/04/2020	Completed Defects	21/04/2020	
Safety Inspection of A76 & A77 Ayr North V1 on 31 March 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 07 April 2020									
SW82562655-237351796	925m	925m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	08/04/2020	Completed Defects	07/04/2020	a76 n/b approx 50m south of glendale cottafe sth pf mauchline
Safety Inspection of A76 & A77 Ayr North V1 on 14 April 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 21 April 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 28 April 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 05 May 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 12 May 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 19 May 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 26 May 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 02 June 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 09 June 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 16 June 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 23 June 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 30 June 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 07 July 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 14 July 2020									
SW82602812-237690176	0m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	15/07/2020	Completed Defects	14/07/2020	A76 MAUCHLINE STH GATEWAY CENTRE LINE POTHLES
SW82602812-237690177	1,435m	1,436m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	15/07/2020	Completed Defects	14/07/2020	A76 MAUCHLINE STH GATEWAY CENTRE LINE POTHLES
SW82602812-237690178	1,454m	1,455m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	15/07/2020	Completed Defects	14/07/2020	A76 MAUCHLINE STH GATEWAY CENTRE LINE POTHLES
Safety Inspection of A76 & A77 Ayr North V1 on 21 July 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 28 July 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 04 August 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 11 August 2020									
No defects recorded									

13274/05 : B705 CATRINE RD JUNCTION TO B743 MANSEFIELD RD JCT

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
Safety Inspection of A76 & A77 Ayr North V1 on 03 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 10 December 2019									
SW82537419-237210748	95m	95m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	07/01/2020	Completed Defects	10/12/2019	a76 approx 300m norrh of mauchline south gateway opposite bus stop
Safety Inspection of A76 & A77 Ayr North V1 on 17 December 2019									
SW82537623-237211833	0m	0m	CARRIAGEWAY	Miscellaneous surface Defects (MSRF)	CAT 1	14/01/2020	Completed Defects	28/01/2020	A76 approx outside 99 pathead, new cumnock
SW82537623-237211834	237m	237m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/12/2019	Completed Defects	17/12/2019	a76 s/b c/w approx 75m south of thames petrol station
Safety Inspection of A76 & A77 Ayr North V1 on 24 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 31 December 2019									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 07 January 2020									
SW82538224-237222488	96m	96m	GULLY	Difference in level with road (IDLV)	CAT 1	04/02/2020	Completed Defects	28/01/2020	a76 s/b c/w no. 27 kilmarnock rd, mauchline
Safety Inspection of A76 & A77 Ayr North V1 on 14 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 21 January 2020									
SW82538623-237246255	98m	98m	CARRIAGEWAY	Pothole (POTH)	CAT 1	18/02/2020	Completed Defects	21/01/2020	a76 approx 50m north of b705 junction, mauchline
Safety Inspection of A76 & A77 Ayr North V1 on 28 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 04 February 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 11 February 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 18 February 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 25 February 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 03 March 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 10 March 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 17 March 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 & A77 Ayr North V1 on 24 March 2020									
SW82556464-237336130	327m	328m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	25/03/2020	Completed Defects	24/03/2020	A76 AT PETROL STATION MAUCHLINE
SW82556464-237336131	327m	327m	TRAFFIC_SIGNS	Electrical condition (COEL)	CAT 1	21/04/2020	Completed Defects	28/03/2020	A76 AT PETROL STATION MAUCHLINE
Safety Inspection of A76 Adhoc Mauchline on 30 March 2020									
SW82559589-237340501	8m	8m	GULLY	Blockage (BLOK)	CAT 1	27/04/2020	Completed Defects	21/04/2020	
SW82559589-237340502	97m	97m	GULLY	Blockage (BLOK)	CAT 1	27/04/2020	Completed Defects	21/04/2020	
SW82559589-237340503	98m	98m	GULLY	Blockage (BLOK)	CAT 1	27/04/2020	Completed Defects	21/04/2020	
SW82559589-237340504	184m	184m	GULLY	Blockage (BLOK)	CAT 1	27/04/2020	Completed Defects	08/04/2020	slot drain
SW82559589-237340505	184m	184m	GULLY	Blockage (BLOK)	CAT 1	27/04/2020	Completed Defects	21/04/2020	

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
SW82559589-237340506	190m	190m	GULLY	Blockage (BLOK)	CAT 1	27/04/2020	Completed Defects	21/04/2020	
SW82559589-237340507	206m	206m	GULLY	Blockage (BLOK)	CAT 1	27/04/2020	Completed Defects	21/04/2020	
SW82559589-237340508	249m	249m	GULLY	Blockage (BLOK)	CAT 1	27/04/2020	Completed Defects	21/04/2020	
SW82559589-237340509	307m	307m	GULLY	Blockage (BLOK)	CAT 1	27/04/2020	Completed Defects	21/04/2020	
SW82559589-237340510	343m	343m	GULLY	Blockage (BLOK)	CAT 1	27/04/2020	Completed Defects	21/04/2020	
SW82559589-237340511	348m	348m	GULLY	Blockage (BLOK)	CAT 1	27/04/2020	Completed Defects	21/04/2020	
Safety Inspection of A76 & A77 Ayr North V1 on 31 March 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 07 April 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 14 April 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 21 April 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 28 April 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 05 May 2020									
SW82576311-237489071	230m	230m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/06/2020	Completed Defects	29/05/2020	A76 approx 10m sth of jct for Glebe Avenue, Mauchline
Safety Inspection of A76 & A77 Ayr North V1 on 12 May 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 19 May 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 26 May 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 02 June 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 09 June 2020									
SW82598719-237597055	130m	130m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	10/06/2020	Completed Defects	09/06/2020	a76 sb cw outside 24 kilmarnock rd, mauchline
SW82598719-237597056	94m	94m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	10/06/2020	Completed Defects	09/06/2020	a76 sb cw outside no 30. kilmarnock rd, mauchline
Safety Inspection of A76 & A77 Ayr North V1 on 16 June 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 23 June 2020									
SW82601679-237646744	45m	45m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	24/06/2020	Completed Defects	23/06/2020	a76 sb at jct for catrine, mauchline
Safety Inspection of A76 & A77 Ayr North V1 on 30 June 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 07 July 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 14 July 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 21 July 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 28 July 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 04 August 2020									
No defects recorded									
Safety Inspection of A76 & A77 Ayr North V1 on 11 August 2020									
No defects recorded									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
------------------	---------	-------	-----------	-------------	-----------------	---------------------	----------------	-----------------	----------------------

13270/08 : AGAINST: SOUTHBOUND APPROACH TO AUCHINLECK RBT

Safety Inspection of A76 & A77 Ayr North V1 on 03 December 2019
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 10 December 2019
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 17 December 2019
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 24 December 2019
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 31 December 2019
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 07 January 2020
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 14 January 2020
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 21 January 2020
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 28 January 2020
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 04 February 2020
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 11 February 2020
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 18 February 2020
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 25 February 2020
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 03 March 2020
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 10 March 2020
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 17 March 2020
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 24 March 2020
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 31 March 2020
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 07 April 2020
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 14 April 2020
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 21 April 2020
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 28 April 2020
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 05 May 2020
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 12 May 2020
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 19 May 2020
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 26 May 2020
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 02 June 2020
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 09 June 2020
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 16 June 2020
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 23 June 2020
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 30 June 2020
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 07 July 2020
No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 14 July 2020
No defects recorded

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	------------------------	----------------	--------------------	----------------------

Safety Inspection of A76 & A77 Ayr North V1 on 21 July 2020

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 28 July 2020

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 04 August 2020

No defects recorded

Safety Inspection of A76 & A77 Ayr North V1 on 11 August 2020

No defects recorded

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 16/08/2020 and 30/11/2020, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'B705 CATRINE RD JUNCTION TO B743 MANSEFIELD RD JCT','50M NTH OF JCT HIGHCLEWS TO B705 CATRINE RD','B713 JUNCTION TO 50M NTH JCT HIGHCLEWS','END OF EXIT FROM AUCHINLECK RBT TO B713 JUNCTION','AGAINST: SOUTHBOUND APPROACH TO AUCHINLECK RBT','WITH: EXIT FROM AUCHINLECK ROUNDABOUT','B7063 AUCHINLECK ROUNDABOUT',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
13270/06 : B7063 AUCHINLECK ROUNDABOUT									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 29 September 2020 <i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 02 October 2020 <i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 06 October 2020 <i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 09 October 2020 <i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 13 October 2020 <i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 16 October 2020 <i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 20 October 2020 <i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 23 October 2020 <i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 27 October 2020 <i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 30 October 2020 <i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 03 November 2020 <i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 06 November 2020 <i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 10 November 2020 <i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 13 November 2020 <i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 17 November 2020 <i>No defects recorded</i>									
NSW75608012-237935582	69m	69m	KERB	Other (OTHR)	CAT 1	18/12/2020	Awaiting CCMS Permanent Date	01/01/9999	A76 at templeton b
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 24 November 2020 <i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 27 November 2020 <i>No defects recorded</i>									

13270/07 : WITH: EXIT FROM AUCHINLECK ROUNDABOUT

Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 29 September 2020
No defects recorded

Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 02 October 2020
No defects recorded

Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 06 October 2020
No defects recorded

Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 09 October 2020
No defects recorded

Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 13 October 2020
No defects recorded

Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 16 October 2020
No defects recorded

Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 20 October 2020
No defects recorded

Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 23 October 2020
No defects recorded

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 27 October 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 30 October 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 03 November 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 06 November 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 10 November 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 13 November 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 17 November 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 20 November 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 24 November 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 27 November 2020									
<i>No defects recorded</i>									
13270/09 : END OF EXIT FROM AUCHINLECK RBT TO B713 JUNCTION									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 29 September 2020									
NSW75605814-237836897	1,541m	1,541m	CARRIAGEWAY	Miscellaneous surface Defects (MSRF)	CAT 1	27/10/2020	Completed Defects	03/11/2020	a76 nb cw approx 100m sth of glennifer far sth of ochiltree
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 02 October 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 06 October 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 09 October 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 13 October 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 16 October 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 20 October 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 23 October 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 27 October 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 30 October 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 03 November 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 06 November 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 10 November 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 13 November 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 17 November 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 20 November 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 24 November 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 27 November 2020									
<i>No defects recorded</i>									
13270/54 : B713 JUNCTION TO 50M NTH JCT HIGHCLEWS									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 29 September 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 02 October 2020									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 06 October 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 09 October 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 13 October 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 16 October 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 20 October 2020									
NSW75606648-237900848	405m	405m	CARRIAGEWAY	Pothole (POTH)	CAT 1	17/11/2020	Completed Defects	11/11/2020	a76 sb cw approx 150m sth of howford bridge
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 23 October 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 27 October 2020									
NSW75606858-237909554	765m	765m	CARRIAGEWAY	Pothole (POTH)	CAT 1	24/11/2020	Completed Defects	06/11/2020	a76 nb cw howford bridge sth of mauchline
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 30 October 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 03 November 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 06 November 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 10 November 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 13 November 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 17 November 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 20 November 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 24 November 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 27 November 2020									
<i>No defects recorded</i>									
13270/75 : 50M NTH OF JCT HIGHCLEWS TO B705 CATRINE RD									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 29 September 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 02 October 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 06 October 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 09 October 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 13 October 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 16 October 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 20 October 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 23 October 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 27 October 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 30 October 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 03 November 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 06 November 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 10 November 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 13 November 2020									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
------------------	---------	-------	-----------	-------------	-----------------	---------------------	----------------	-----------------	----------------------

Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 17 November 2020

No defects recorded

Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 20 November 2020

No defects recorded

Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 24 November 2020

No defects recorded

Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 27 November 2020

No defects recorded

13274/05 : B705 CATRINE RD JUNCTION TO B743 MANSEFIELD RD JCT

Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 29 September 2020

No defects recorded

Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 02 October 2020

No defects recorded

Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 06 October 2020

No defects recorded

Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 09 October 2020

No defects recorded

Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 13 October 2020

No defects recorded

Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 16 October 2020

No defects recorded

Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 20 October 2020

No defects recorded

Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 23 October 2020

No defects recorded

Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 27 October 2020

No defects recorded

Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 30 October 2020

No defects recorded

Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 03 November 2020

No defects recorded

Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 06 November 2020

No defects recorded

Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 10 November 2020

No defects recorded

Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 13 November 2020

No defects recorded

Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 17 November 2020

No defects recorded

Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 20 November 2020

No defects recorded

Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 24 November 2020

No defects recorded

Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 27 November 2020

No defects recorded

13270/08 : AGAINST: SOUTHBOUND APPROACH TO AUCHINLECK RBT

Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 29 September 2020

No defects recorded

Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 02 October 2020

No defects recorded

Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 06 October 2020

No defects recorded

Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 09 October 2020

No defects recorded

Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 13 October 2020

No defects recorded

Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 16 October 2020

No defects recorded

Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 20 October 2020

No defects recorded

Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 23 October 2020

No defects recorded

Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 27 October 2020

No defects recorded

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 30 October 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 03 November 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 06 November 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 10 November 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 13 November 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 17 November 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 20 November 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A78_A76 Ayr Safety Inspection Route on 24 November 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A78_A76 Ayr Winter Safety Patrol Route on 27 November 2020									
<i>No defects recorded</i>									