

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/06/2020 and 31/07/2020, and defects raised outside of inspections on the same Section(s) during this period.

(Road is 'A90',)
(Section Code is 12430/85)

| Defect Reference | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|----------------------------------------------------------------|------------|----------|---------------|-------------------------|--------------------|-----------------------------|----------------------|--------------------|----------------------|
| 12430/85 : JN R B9033 St Combs to Start 1 Way (WB) | | | | | | | | | |
| Safety Inspection of A96.A90 SAFETY INSPECTION on 01 June 2020 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A96.A90 SAFETY INSPECTION on 08 June 2020 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A96.A90 SAFETY INSPECTION on 15 June 2020 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A96.A90 SAFETY INSPECTION on 22 June 2020 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A96.A90 SAFETY INSPECTION on 29 June 2020 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A96.A90 SAFETY INSPECTION on 06 July 2020 | | | | | | | | | |
| NE131602278-237681268 | 2,069m | 0m | TRAFFIC_SIGNS | Obscured sign (OBSG) | CAT 1 | 07/07/2020 | Completed Defects | 06/07/2020 | NB AT LONMAY |
| Safety Inspection of A96.A90 SAFETY INSPECTION on 13 July 2020 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A96.A90 SAFETY INSPECTION on 20 July 2020 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |
| Safety Inspection of A96.A90 SAFETY INSPECTION on 27 July 2020 | | | | | | | | | |
| <i>No defects recorded</i> | | | | | | | | | |