

Defect Reference	Item Category	Item Detail	Defect Category	Road	Section	Comments	Status	Perm Repair Date	Chainage	Instruction Time
NSW73-617618-238009323	Carriageways	Pothole (POTH)	CATEGORY 1	A76	13206/15	CAT 1 1ST TIME PERM POTHOLE	Completed Defects	02/03/2021 11:55:00	Chainage: 1882m	02/03/2021 11:52:00
NSW73-624542-238019665	Carriageways	Pothole (POTH)	CATEGORY 1	A76	13206/15	CAT 1 1ST TIME PERM POTHOLE	Completed Defects	19/03/2021 14:30:00	Chainage: 1755m	19/03/2021 11:50:00
NSW73-624542-238019666	Carriageways	Pothole (POTH)	CATEGORY 1	A76	13206/15	CAT 1 1ST TIME PERM POTHOLE	Completed Defects	19/03/2021 14:30:00	Chainage: 1753m	19/03/2021 11:52:00
NSW73-610235-237996922	Carriageways	Pothole (POTH)	CATEGORY 1	A76	13206/29	CAT 1 1ST TIME PERM POTHOLE	Completed Defects	29/01/2021 17:40:00	Chainage: 71m	29/01/2021 12:23:00
NSW73-617618-238009322	Carriageways	Pothole (POTH)	CATEGORY 1	A76	13206/29	CAT 1 1ST TIME PERM POTHOLE	Completed Defects	02/03/2021 11:55:00	Chainage: 45m	02/03/2021 11:46:00
NSW73-624542-238019664	Carriageways	Pothole (POTH)	CATEGORY 1	A76	13206/29	CAT 1 1ST TIME PERM POTHOLE	Completed Defects	19/03/2021 14:30:00	Chainage: 33m	19/03/2021 11:49:00
D-NSW20237882545	Carriageways	Pothole (POTH)	CATEGORY 1	A76	13206/37	CAT1 28 DAY POTHOLE 12M X 2M X 45MM. 12M X 150MM CONT. 2 ROAD STUDS.	Completed Defects	28/10/2020 16:30:00	559	07/10/2020 08:57:01
SW79-542465-237284344	Carriageways	Pothole VIAFIX (POTV)	CATEGORY 1	A76	13206/15	CAT 1 POTHOLE VIAFIX REPAIR	Completed Defects	20/02/2020 15:15:00	Chainage: 421m	20/02/2020 15:03:00
SW79-542465-237284345	Carriageways	Pothole VIAFIX (POTV)	CATEGORY 1	A76	13206/15	CAT 1 POTHOLE VIAFIX REPAIR	Completed Defects	20/02/2020 15:15:00	Chainage: 412m	20/02/2020 16:59:00
SW79-548466-237304223	Carriageways	Pothole VIAFIX (POTV)	CATEGORY 1	A76	13206/15	CAT 1 POTHOLE VIAFIX REPAIR	Completed Defects	05/03/2020 15:05:00	Chainage: 320m	05/03/2020 15:01:00
SW80-602211-237668238	Carriageways	Pothole VIAFIX (POTV)	CATEGORY 1	A76	13206/15	CAT1 VIA FIX 1ST TIME PERM POTHOLE	Completed Defects	02/07/2020 13:30:00	Chainage: 753m	02/07/2020 13:27:00
NSW73-608404-237935559	Covers, Gratings and Frames	Rocking under load (IRLD)	THIRD PARTY	A76	13206/37	3RD PARTY SUNKEN BT MANHOLE	Awaiting CCMS Temp Date	Unrepaired	Chainage: 891m	01/12/2020 13:18:00
D-SW20237329146	Gullies, Catchpits, Interceptors, Soakaways, Manholes and Oil Separators	Blockage (BLOK)	CATEGORY 1	A76	13206/15	Blocked grips with standing water. 89161	Completed Defects	17/03/2020 21:30:00	?	17/03/2020 22:39:18
D-SW20237224157	Carriageways	Debris in traffic Lane (DBTL)	CATEGORY 1	A76	13206/15	Mud On C/way	Completed Defects	07/01/2020 13:55:00	?	07/01/2020 14:28:43
D-NSW20237913652	Carriageways	Debris in traffic Lane (DBTL)	CATEGORY 1	A76	13206/15	debris	Completed Defects	29/10/2020 08:45:00	?	30/10/2020 00:48:03
NSW73-608009-237935555	Carriageways	Debris in traffic Lane (DBTL)	CATEGORY 1	A76	13206/15	CAT 1 1ST TIME PERM DEBRIS ON C/WAY	Completed Defects	20/11/2020 13:30:00	Chainage: 409m	20/11/2020 10:36:00
D-NSW21238047377	Carriageways	Debris in traffic Lane (DBTL)	CATEGORY 1	A76	13206/15	3617 - Debris from RTC	Completed Defects	08/04/2021 22:00:00	?	08/04/2021 22:06:47
NSW73-646070-4	Road Markings	Wear (for example erosion)	CATEGORY 1	A76	13206/15	CAT 1 FADED DOUBLE SOLID CENTRE LINE	Completed Defects	22/07/2021 13:00:00	Chainage: 1200m	29/06/2021 16:08:00
D-NSW21238156166	Road Markings	Wear (for example erosion)	CATEGORY 2	A76	13206/37	CAT 2 CORRODED CENTRE LINE	Cat 2 Awaiting Action	Unrepaired	643	31/05/2021 14:48:45
NSW73-646070-5	Road Markings	Wear (for example erosion)	CATEGORY 1	A76	13206/37	CAT 1 FADED DOUBLE SOLID CENTRE LINE	Completed Defects	22/07/2021 12:00:00	Chainage: 5m	29/06/2021 16:11:00

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/01/2020 and 17/08/2021, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'Subsidence Scheme to Thrushlands Junction','Subsidence Scheme South to North point','Bridge over Burn to Subsidence Scheme South','BRIDGE OVER BURN TO JCT (R) TO THRUSHLANDS','JCT (L) DRUMLANRIG PARK TO BRIDGE OVER BURN',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
13206/15 : JCT (L) DRUMLANRIG PARK TO BRIDGE OVER BURN									
Safety Inspection of A76 - A701 Safety on 07 January 2020									
No defects recorded									
Safety Inspection of A76 - A701 Safety on 09 January 2020									
No defects recorded									
Safety Inspection of A76 - A701 Safety on 16 January 2020									
No defects recorded									
Safety Inspection of A76 - A701 Safety on 23 January 2020									
No defects recorded									
Safety Inspection of A76 - A701 Safety on 30 January 2020									
No defects recorded									
Safety Inspection of A76 - A701 Safety on 06 February 2020									
No defects recorded									
Safety Inspection of A76 - A701 Safety on 13 February 2020									
No defects recorded									
Safety Inspection of A76 - A701 Safety on 20 February 2020									
SW79-542465-237284344	421m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	21/02/2020	Completed Defects	20/02/2020	A76 S/B C/WAY @ DRUMLANRIG N JCT
SW79-542465-237284345	412m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	21/02/2020	Completed Defects	20/02/2020	A76 S/B C/WAY @ DRUMLANRIG N JCT
Safety Inspection of A76 - A701 Safety on 27 February 2020									
No defects recorded									
Safety Inspection of A76 - A701 Safety on 05 March 2020									
SW79-548466-237304223	320m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	06/03/2020	Completed Defects	05/03/2020	A76 N/B C/WAY @ DRUMLANRIG N JCT
Safety Inspection of A76 - A701 Safety on 12 March 2020									
No defects recorded									
Safety Inspection of A76 - A701 Safety on 19 March 2020									
No defects recorded									
Safety Inspection of A76 - A701 Safety on 26 March 2020									
No defects recorded									
Safety Inspection of A76 - A701 Safety on 02 April 2020									
No defects recorded									
Safety Inspection of A76 - A701 Safety on 09 April 2020									
No defects recorded									
Safety Inspection of A76 - A701 Safety on 16 April 2020									
No defects recorded									
Safety Inspection of A76 - A701 Safety on 23 April 2020									
No defects recorded									
Safety Inspection of A76 - A701 Safety on 30 April 2020									
No defects recorded									
Safety Inspection of A76 - A701 Safety on 07 May 2020									
No defects recorded									
Safety Inspection of A76 - A701 Safety on 14 May 2020									
No defects recorded									
Safety Inspection of A76 - A701 Safety on 21 May 2020									
No defects recorded									
Safety Inspection of A76 - A701 Safety on 28 May 2020									
No defects recorded									
Safety Inspection of A76 - A701 Safety on 04 June 2020									
No defects recorded									
Safety Inspection of A76 - A701 Safety on 11 June 2020									
No defects recorded									
Safety Inspection of A76 - A701 Safety on 18 June 2020									
No defects recorded									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A76 - A701 Safety on 25 June 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 02 July 2020									
SW80-602211-237668238	753m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	03/07/2020	Completed Defects	02/07/2020	A76 N/B C/WAY NORTH OF DRUMLANRIG
Safety Inspection of A76 - A701 Safety on 09 July 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 16 July 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 23 July 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 30 July 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 06 August 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 13 August 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 29 September 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 01 October 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 06 October 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 09 October 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 13 October 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 16 October 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 20 October 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 23 October 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 27 October 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 30 October 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 03 November 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 06 November 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 10 November 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 13 November 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 17 November 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 20 November 2020									
NSW73-608009-237935555	409m	0m	CARRIAGEWAY	Debris in traffic Lane (DBTL)	CAT 1	21/11/2020	Completed Defects	20/11/2020	A76 S/B AND N/B C/WAY @ DRUMLANRIG CASTLE N JCT
Safety Inspection of NSW A76 Safety Inspection Route on 24 November 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 27 November 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 01 December 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 04 December 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 08 December 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 11 December 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 15 December 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 18 December 2020									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 21 December 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 24 December 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 28 December 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 31 December 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 04 January 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 05 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 08 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 08 January 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 12 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 15 January 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 19 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 22 January 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 26 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 29 January 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 02 February 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 05 February 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 09 February 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 12 February 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 16 February 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 19 February 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 23 February 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 26 February 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 02 March 2021									
NSW73-617618-238009323	1,882m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	03/03/2021	Completed Defects	02/03/2021	A76 N/B C/WAY 1KM N OF DRUMLANRIG
Safety Patrol of NSW A76 Winter Safety Patrol Route on 05 March 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 09 March 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 12 March 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 16 March 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 19 March 2021									
NSW73-624542-238019665	1,755m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/03/2021	Completed Defects	19/03/2021	A76 N/B 1KM N OF DRUMLANRIG
NSW73-624542-238019666	1,753m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/03/2021	Completed Defects	19/03/2021	A76 CENTRE LINE 1KM N OF DRUMLANRIG
Safety Inspection of NSW A76 Safety Inspection Route on 23 March 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 26 March 2021									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of NSW A76 Safety Inspection Route on 30 March 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 06 April 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 13 April 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 15 April 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 22 April 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 29 April 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 06 May 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 13 May 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 20 May 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 27 May 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 03 June 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 10 June 2021									
NSW73-665762-238159378	1,405m	0m	TREE	Overhanging/ov ergrown (OVER)	CAT 1	11/06/2021	Completed Defects	10/06/2021	A76 N/B C/WAY 1KM N OF DRUMLANRIG
Safety Inspection of NSW A76 Safety Inspection Route on 17 June 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 24 June 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 01 July 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 08 July 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 15 July 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 22 July 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 29 July 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 05 August 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 12 August 2021									
<i>No defects recorded</i>									
13206/27 : BRIDGE OVER BURN TO JCT (R) TO THRUSHLANDS									
Safety Inspection of A76 - A701 Safety on 07 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 09 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 16 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 23 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 30 January 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 06 February 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 13 February 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 20 February 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 27 February 2020									
SW79-545396-237291092	1,175m	0m	Culvert	Free flow impeded (FRFL)	CAT 1	28/02/2020	Completed Defects	27/02/2020	A76 S/B VERGE 600M SOUTH OF HELLS CORNER

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A76 - A701 Safety on 05 March 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 12 March 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 19 March 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 26 March 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 02 April 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 09 April 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 16 April 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 23 April 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 30 April 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 07 May 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 14 May 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 21 May 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 28 May 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 04 June 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 11 June 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 18 June 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 25 June 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 02 July 2020									
SW80-602211-237668239	1,638m	0m	KERB	Damaged (DAMG)	CAT 1	30/07/2020	Completed Defects	18/07/2020	A76 N/B LAYBY @ HELLS CAULDRON
SW80-602211-237668240	1,643m	0m	CARRIAGEWAY	Detritus / Refuse (DETR)	3RD PTY	03/07/2020	Awaiting CCMS Permanent Date	02/07/2020	A76 N/B LAYBY AT HELLS CAULDRON
Safety Inspection of A76 - A701 Safety on 09 July 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 16 July 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 23 July 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 30 July 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 06 August 2020									
<i>No defects recorded</i>									
Safety Inspection of A76 - A701 Safety on 13 August 2020									
<i>No defects recorded</i>									
13206/29 : Bridge over Burn to Subsidence Scheme South									
Safety Inspection of NSW A76 Safety Inspection Route on 29 September 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 01 October 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 06 October 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 09 October 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 13 October 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 16 October 2020									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of NSW A76 Safety Inspection Route on 20 October 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 23 October 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 27 October 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 30 October 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 03 November 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 06 November 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 10 November 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 13 November 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 17 November 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 20 November 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 24 November 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 27 November 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 01 December 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 04 December 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 08 December 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 11 December 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 15 December 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 18 December 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 21 December 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 24 December 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 28 December 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 31 December 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 04 January 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 05 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 08 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 08 January 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 12 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 15 January 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 19 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 22 January 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 26 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 29 January 2021									
NSW73-610235-237996922	71m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	30/01/2021	Completed Defects	29/01/2021	A76 S/B C/WAY 2KM NORTH OF DRUMLNRIG
Safety Inspection of NSW A76 Safety Inspection Route on 02 February 2021									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 05 February 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 09 February 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 12 February 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 16 February 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 19 February 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 23 February 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 26 February 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 02 March 2021									
NSW73-617618-238009322	45m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	03/03/2021	Completed Defects	02/03/2021	A76 S/B C/WAY 1KM N OF DRUMANRIG
Safety Patrol of NSW A76 Winter Safety Patrol Route on 05 March 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 09 March 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 12 March 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 16 March 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 19 March 2021									
NSW73-624542-238019664	33m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/03/2021	Completed Defects	19/03/2021	A76 CENTRE LINE 1KM N OF DRUMLANRIG
Safety Inspection of NSW A76 Safety Inspection Route on 23 March 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 26 March 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 30 March 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 06 April 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 13 April 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 15 April 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 22 April 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 29 April 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 06 May 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 13 May 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 20 May 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 27 May 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 03 June 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 10 June 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 17 June 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 24 June 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 01 July 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 08 July 2021									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	---------	-------	-----------	-------------	-----------------	--------------------------	----------------	-----------------	----------------------

Safety Inspection of NSW A76 Safety Inspection Route on 15 July 2021

No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 22 July 2021

No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 29 July 2021

No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 05 August 2021

No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 12 August 2021

No defects recorded

13206/33 : Subsidence Scheme South to North point

Safety Inspection of NSW A76 Safety Inspection Route on 29 September 2020

No defects recorded

Safety Patrol of NSW A76 Winter Safety Patrol Route on 01 October 2020

No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 06 October 2020

No defects recorded

Safety Patrol of NSW A76 Winter Safety Patrol Route on 09 October 2020

No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 13 October 2020

No defects recorded

Safety Patrol of NSW A76 Winter Safety Patrol Route on 16 October 2020

No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 20 October 2020

No defects recorded

Safety Patrol of NSW A76 Winter Safety Patrol Route on 23 October 2020

No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 27 October 2020

No defects recorded

Safety Patrol of NSW A76 Winter Safety Patrol Route on 30 October 2020

No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 03 November 2020

No defects recorded

Safety Patrol of NSW A76 Winter Safety Patrol Route on 06 November 2020

No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 10 November 2020

No defects recorded

Safety Patrol of NSW A76 Winter Safety Patrol Route on 13 November 2020

No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 17 November 2020

No defects recorded

Safety Patrol of NSW A76 Winter Safety Patrol Route on 20 November 2020

No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 24 November 2020

No defects recorded

Safety Patrol of NSW A76 Winter Safety Patrol Route on 27 November 2020

No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 01 December 2020

No defects recorded

Safety Patrol of NSW A76 Winter Safety Patrol Route on 04 December 2020

No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 08 December 2020

No defects recorded

Safety Patrol of NSW A76 Winter Safety Patrol Route on 11 December 2020

No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 15 December 2020

No defects recorded

Safety Patrol of NSW A76 Winter Safety Patrol Route on 18 December 2020

No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 21 December 2020

No defects recorded

Safety Patrol of NSW A76 Winter Safety Patrol Route on 24 December 2020

No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 28 December 2020

No defects recorded

Safety Patrol of NSW A76 Winter Safety Patrol Route on 31 December 2020

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 04 January 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 05 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 08 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 08 January 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 12 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 15 January 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 19 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 22 January 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 26 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 29 January 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 02 February 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 05 February 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 09 February 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 12 February 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 16 February 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 19 February 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 23 February 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 26 February 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 02 March 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 05 March 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 09 March 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 12 March 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 16 March 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 19 March 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 23 March 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 26 March 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 30 March 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 06 April 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 13 April 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 15 April 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 22 April 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 29 April 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 06 May 2021									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of NSW A76 Safety Inspection Route on 13 May 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 20 May 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 27 May 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 03 June 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 10 June 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 17 June 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 24 June 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 01 July 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 08 July 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 15 July 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 22 July 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 29 July 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 05 August 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 12 August 2021									
<i>No defects recorded</i>									

13206/37 : Subsidence Scheme to Thrushlands Junction

Safety Inspection of NSW A76 Safety Inspection Route on 29 September 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 01 October 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 06 October 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 09 October 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 13 October 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 16 October 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 20 October 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 23 October 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 27 October 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 30 October 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 03 November 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 06 November 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 10 November 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 13 November 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 17 November 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 20 November 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 24 November 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 27 November 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 01 December 2020									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NSW73-608404-237935559	891m	0m	MANHOLE	Rocking under load (IRLD)	3RD PTY	29/12/2020	Awaiting CCMS Temp Date	01/01/9999	A76 S/B C/WAY 300M SOUTH OF ENTERKINFOOT COTTAGE
Safety Patrol of NSW A76 Winter Safety Patrol Route on 04 December 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 08 December 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 11 December 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 15 December 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 18 December 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 21 December 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 24 December 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 28 December 2020									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 31 December 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 04 January 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 05 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 08 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 08 January 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 12 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 15 January 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 19 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 22 January 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 26 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 29 January 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 02 February 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 05 February 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 09 February 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 12 February 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 16 February 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 19 February 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 23 February 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 26 February 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 02 March 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 05 March 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 09 March 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 12 March 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 16 March 2021									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of NSW A76 Winter Safety Patrol Route on 19 March 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 23 March 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 26 March 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 30 March 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 06 April 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 13 April 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 15 April 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 22 April 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 29 April 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 06 May 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 13 May 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 20 May 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 27 May 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 03 June 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 10 June 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 17 June 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 24 June 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 01 July 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 08 July 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 15 July 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 22 July 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 29 July 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 05 August 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 12 August 2021									
<i>No defects recorded</i>									

Road	Section	Operational Area	Maintenance Activity Name	Frequency	Min Month	Max Month	Last Completion Date	No of items within Spec	No of items outwith Spec	No of items overdue	Total no of active items	No of Cuts in last 12 months	Required No of Cuts
A76	13206/07	South	Cyclic - Bulk Lamp Chng, Clean and Inspect - Lit Signs etc.	24	1	12	10/04/2020	15	0	0	15		
A76	13206/07	South	Cyclic - Cleaning - Signs, Hazard and Marker posts	24	1	12	10/04/2020	12	0	0	12		
A76	13206/07	South	Cyclic - Cleaning - Signs, Hazard and Marker posts	24	1	12	10/04/2020	3	0	0	3		
A76	13206/07	South	Cyclic - Cleaning - Signs, Hazard and Marker posts	24	1	12	10/04/2020	86	0	0	86		
A76	13206/07	South	Cyclic - Grass Cutting High freq - Grassed Areas	0	3	11	01/05/2021	5,281	1,440		6,722	11	14
A76	13206/07	South	Cyclic - Grass Cutting Low freq - Grassed Areas	0	3	11	29/04/2021	19,591	0		19,591	3	3
A76	13206/07	South	Cyclic - Grass Cutting Med freq - Grassed Areas	0	3	11	28/04/2021	8,916	0		8,916	8	7
A76	13206/15	South	Cyclic - Cleaning - Signs, Hazard and Marker posts	24	1	12	10/04/2020	1	0	0	1		
A76	13206/15	South	Cyclic - Cleaning - Signs, Hazard and Marker posts	24	1	12	10/04/2020	166	0	0	166		
A76	13206/15	South	Cyclic - Grass Cutting High freq - Grassed Areas	0	3	11	01/05/2021	4,083	1,113		5,197	11	14
A76	13206/15	South	Cyclic - Grass Cutting Low freq - Grassed Areas	0	3	11	29/04/2021	5,765	0		5,765	3	3

Road	Section	Operational Area	Maintenance Activity Name	Frequency	Min Month	Max Month	Last Completion Date	Total no of active items
A76	13206/07	South	Cyclic - Cleansing N/S - Catchpit (12 month)	12	1	12	09/12/2020	7
A76	13206/07	South	Cyclic - Cleansing O/S - Catchpit (12 month)	12	1	12	24/01/2021	2
A76	13206/07	South	Cyclic - Cleansing O/S - Catchpit (12 month)	12	1	12	25/03/2021	2
A76	13206/15	South	Cyclic - Cleansing O/S - Catchpit (12 month)	12	1	12	25/03/2021	4
A76	13206/15	South	Cyclic - Cleansing O/S - Catchpit (12 month)	12	1	12	25/03/2021	4
A76	13206/07	South	Cyclic - Cleaning - Signs, Hazard and Marker posts	24	1	12	10/04/2020	12
A76	13206/07	South	Cyclic - Cleaning - Signs, Hazard and Marker posts	24	1	12	10/04/2020	3
A76	13206/07	South	Cyclic - Cleaning - Signs, Hazard and Marker posts	24	1	12	10/04/2020	86
A76	13206/15	South	Cyclic - Cleaning - Signs, Hazard and Marker posts	24	1	12	10/04/2020	1
A76	13206/15	South	Cyclic - Cleaning - Signs, Hazard and Marker posts	24	1	12	10/04/2020	166
A76	13206/15	South	Cyclic - Harrowing adjacent CW - Filter Material	36	1	12	07/07/2019	133
A76	13206/07	South	Cyclic - Cleansing N/S - Gully (12 month)	12	1	12	18/12/2020	6
A76	13206/07	South	Cyclic - Cleansing O/S - Gully (12 month)	12	1	12	18/12/2020	8
A76	13206/07	South	Cyclic - Cleansing O/S - Gully (12 month)	12	1	12	18/12/2020	8
A76	13206/15	South	Cyclic - Cleansing N/S - Gully (12 month)	12	1	12	18/12/2020	1
A76	13206/15	South	Cyclic - Cleansing O/S - Gully (12 month)	12	1	12	18/12/2020	7
A76	13206/15	South	Cyclic - Cleansing O/S - Gully (12 month)	12	1	12	18/12/2020	7



TS Monitoring Management of Incidents Report (for export)

MOI Reference	OC Incident Reference	Incident Classification	Incident Type	Response Type	Road Name	SECTION_CODE	YSP	Direction of Travel	Disruption Caused	Disruption Type	Weather Conditions	Diversion use	Road Condition	Tris Attendance	Time response req	Start Time	Initial Response Da	Secondary Reasons	Contingency Respo	End Of Incident	Duration of Incident	Police Force	Police Ref	Description	Incident log
MOI-SW20100699	86214	?	Litter/Debris/Animals	Response required by Unit	A76	13206/15	CL1	Both	N	?	RAINING WITH HIGH WINDS	Please Select	WET OR DAMP	N	07/01/2020 12:54:00	07/01/2020 12:53:00	07/01/2020 13:35:00	01/01/9999 00:00:00	01/01/9999 00:00:00	07/01/2020 13:55:00	0 days 1 hours 2 mins	Please Select	?	Mud On C/way	?
MOI-SW20105337	89161	Minor	Flooding	Response required by Unit	A76	13206/15	CL1	Both	N	?	RAINING NO HIGH WINDS	Please Select	WET OR DAMP	N	17/03/2020 19:35:00	17/03/2020 19:35:00	17/03/2020 20:30:00	01/01/9999 00:00:00	01/01/9999 00:00:00	17/03/2020 21:30:00	0 days 1 hours 55 mins	Dumfries and Galloway		Flooding on carriageway.	Grips cleared,flood boards in place and water receded.



TS Monitoring Management of Incidents Report (for export)

MOI Reference	OC Incident Reference	Incident Classification	Incident Type	Response Type	Road Name	SECTION CODE	NSP	Direction of Travel	Disruption Caused	Disruption Type	Weather Conditions	Diversion Used	Road Condition	Traffic Attendance	Time response req	Start Time	Initial Response Da	Secondary Respon	Contingency Respo	End Of Incident	Duration of Incident	Police Force	Police Ref	Description	Incident Log	OC_UNIT_NAME
MOI-NSW20118522	303623	?	Litter/Debris/Animals	Response required by Unit	A76	13206/15	L1	Northbound	N	?	RAINING NO HIGH WINDS	Please Select	WET OR DAMP	N	20/11/2020 10:30:00	20/11/2020 10:30:00	20/11/2020 10:30:00	01/01/9999 00:00:00	01/01/9999 00:00:00	20/11/2020 10:40:00	0 days 0 hours 10 mins	Please Select	?	Verge over run - Route Inspector	?	NEW SOUTH WEST
MOI-NSW21127821	3617	Minor	Road Traffic Collision	Response required by Unit	A76	13206/15	CL1	Southbound	N	?	FINE NO HIGH WINDS	Please Select	DRY	N	08/04/2021 20:49:00	08/04/2021 20:49:00	08/04/2021 21:20:00	01/01/9999 00:00:00	01/01/9999 00:00:00	08/04/2021 22:00:00	0 days 1 hours 11 mins	Glasgow	3069	Debris uplift from RTC	Debris uplifted	NEW SOUTH WEST
MOI-NSW20119249	304032	Minor	Other	Response required by Unit	A76	13206/37	CL1	Southbound	N	?	FINE NO HIGH WINDS	Please Select	DRY	N	01/12/2020 13:15:00	01/12/2020 13:15:00	01/12/2020 13:15:00	01/01/9999 00:00:00	01/01/9999 00:00:00	01/12/2020 13:20:00	0 days 0 hours 5 mins	No	?	Sunken manhole	Passed to BT	NEW SOUTH WEST
MOI-NSW21128456	3810	Critical	Road Traffic Collision	Response required by Unit	A76	13206/37	CL1	Both	Y	1 - FULL ROAD CLOSURE (BOTH DIRECTIONS OF DUAL)	FINE NO HIGH WINDS	None	DRY	N	17/04/2021 16:10:00	17/04/2021 16:10:00	17/04/2021 17:30:00	01/01/9999 00:00:00	01/01/9999 00:00:00	17/04/2021 23:10:00	0 days 7 hours 0 mins	Dumfries and Galloway	2221	RTC	RTC - Pedestrian struck - Isu attend - no debris - no DCP	NEW SOUTH WEST