

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/10/2020 and 04/10/2021, and defects raised outside of inspections on the same Section(s) during this period.

(Road is 'A92',)
(Section Code is 13315/05) Or

(Section Code is 13315/06) Or

(Section Code is 13310/75)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
13310/75 : BROUGHTY FERRY ROAD TO GREENDYKES ROAD									
Safety Patrol of A90 SAFETY PATROL on 01 October 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 05 October 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 08 October 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 12 October 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 15 October 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 19 October 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 22 October 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 26 October 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 29 October 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 02 November 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 05 November 2020									
NE14-607222-237913634	314m	0m	REMOVE_ANIMAL	Carcass of dead animal (DEAD)	CAT 1	06/11/2020	Completed Defects	05/11/2020	@ TAYVIEW HOTEL E/B
Safety Inspection of A90 SAFETY INSPECTION on 09 November 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 12 November 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 16 November 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 19 November 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 23 November 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 26 November 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 30 November 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 03 December 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 07 December 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 10 December 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 14 December 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 17 December 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 21 December 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 24 December 2020									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
Safety Inspection of A90 SAFETY INSPECTION on 28 December 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 31 December 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 04 January 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 07 January 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 11 January 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 14 January 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 18 January 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 21 January 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 25 January 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 28 January 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 01 February 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 04 February 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 08 February 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 11 February 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 15 February 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 18 February 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 22 February 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 25 February 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 01 March 2021									
NE14-615919-238007734	239m	0m	BOLLARDS	Physical condition of fittings (COFT)	CAT 1	29/03/2021	Completed Defects	15/03/2021	@ CAROLINA HOUSE W/B
Safety Patrol of A90 SAFETY PATROL on 04 March 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 08 March 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 11 March 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 15 March 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 18 March 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 22 March 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 25 March 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 29 March 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 01 April 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 05 April 2021									
NE14-630235-238044890	318m	0m	MANHOLE	Rocking under load (IRLD)	3RD PTY	03/05/2021	Awaiting CCMS Permanent Date	01/01/9999	@ CAROLINA HOUSE W/B
NE14-630235-238044891	40m	0m	TRAFFIC_SIGNS	Missing (MISS)	CAT 1	03/05/2021	Completed Defects	20/04/2021	@ BROUGHTY FERRY RD JCT E/B
Safety Patrol of A90 SAFETY PATROL on 08 April 2021									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
Safety Inspection of A90 SAFETY INSPECTION on 12 April 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 15 April 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 19 April 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 22 April 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 26 April 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 29 April 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 03 May 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 06 May 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 10 May 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 13 May 2021									
NE14-647967-238111998	558m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2		Cat 2 Awaiting Action		@ BROUGHTY FERRY RD / GREENDYKES JCT E/B
NE14-647967-238111997	561m	0m	CARRIAGEWAY	Cracking around ironwork (CKIR)	CAT 1	10/06/2021	Completed Defects	29/05/2021	@ BROUGHTY FERRY RD / GREENDYKES JCT E/B
Safety Inspection of A90 SAFETY INSPECTION on 17 May 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 20 May 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 24 May 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 27 May 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 31 May 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 03 June 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 07 June 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 10 June 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 14 June 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 17 June 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 21 June 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 24 June 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 28 June 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 01 July 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 05 July 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 08 July 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 12 July 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 15 July 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 19 July 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 22 July 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 26 July 2021									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 29 July 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 02 August 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 05 August 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 09 August 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 12 August 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 16 August 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 19 August 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 23 August 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 26 August 2021									
NE122-710148-238305107	548m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 1	23/09/2021	Completed Defects	15/09/2021	JCT BROUGHTY FERRY RD TO GREENDYKES RD N/B
Safety Inspection of A90 SAFETY INSPECTION on 30 August 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 02 September 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 06 September 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 09 September 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 13 September 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 16 September 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 20 September 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 23 September 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 27 September 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 30 September 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 04 October 2021									
<i>No defects recorded</i>									
13315/05 : WITH:GREENDYKES ROAD TO CRAIGIE AVENUE RBT									
Safety Patrol of A90 SAFETY PATROL on 01 October 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 05 October 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 08 October 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 12 October 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 15 October 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 19 October 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 22 October 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 26 October 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 29 October 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 02 November 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 05 November 2020									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 09 November 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 12 November 2020									
NE14-607447-237922220	8m	8m	MANHOLE	Rocking under load (IRLD)	3RD PTY	10/12/2020	Awaiting CCMS Permanent Date	01/01/9999	AT START OF GREENDYES RD - ON EXIT FROM TRAFFIC LIGHTS EB
Safety Inspection of A90 SAFETY INSPECTION on 16 November 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 19 November 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 23 November 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 26 November 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 30 November 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 03 December 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 07 December 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 10 December 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 14 December 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 17 December 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 21 December 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 24 December 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 28 December 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 31 December 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 04 January 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 07 January 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 11 January 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 14 January 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 18 January 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 21 January 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 25 January 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 28 January 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 01 February 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 04 February 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 08 February 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 11 February 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 15 February 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 18 February 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 22 February 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 25 February 2021									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
Safety Inspection of A90 SAFETY INSPECTION on 01 March 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 04 March 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 08 March 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 11 March 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 15 March 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 18 March 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 22 March 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 25 March 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 29 March 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 01 April 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 05 April 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 08 April 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 12 April 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 15 April 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 19 April 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 22 April 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 26 April 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 29 April 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 03 May 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 06 May 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 10 May 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 13 May 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 17 May 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 20 May 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 24 May 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 27 May 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 31 May 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 03 June 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 07 June 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 10 June 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 14 June 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 17 June 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 21 June 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 24 June 2021									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
------------------	---------	-------	-----------	-------------	-----------------	---------------------	----------------	-----------------	----------------------

No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 28 June 2021
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 01 July 2021
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 05 July 2021
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 08 July 2021
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 12 July 2021
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 15 July 2021
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 19 July 2021
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 22 July 2021
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 26 July 2021
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 29 July 2021
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 02 August 2021
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 05 August 2021
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 09 August 2021
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 12 August 2021
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 16 August 2021
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 19 August 2021
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 23 August 2021
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 26 August 2021
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 30 August 2021
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 02 September 2021
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 06 September 2021
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 09 September 2021
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 13 September 2021
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 16 September 2021
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 20 September 2021
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 23 September 2021
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 27 September 2021
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 30 September 2021
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 04 October 2021
No defects recorded

13315/06 : AGAINST:CRAIGIE AVE RBT TO GREENDYKES RD

Safety Patrol of A90 SAFETY PATROL on 01 October 2020
No defects recorded
Safety Inspection of A90 SAFETY INSPECTION on 05 October 2020
No defects recorded
Safety Patrol of A90 SAFETY PATROL on 08 October 2020
No defects recorded

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
Safety Inspection of A90 SAFETY INSPECTION on 12 October 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 15 October 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 19 October 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 22 October 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 26 October 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 29 October 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 02 November 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 05 November 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 09 November 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 12 November 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 16 November 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 19 November 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 23 November 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 26 November 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 30 November 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 03 December 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 07 December 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 10 December 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 14 December 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 17 December 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 21 December 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 24 December 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 28 December 2020									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 31 December 2020									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 04 January 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 07 January 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 11 January 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 14 January 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 18 January 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 21 January 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 25 January 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 28 January 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 01 February 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 04 February 2021									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 08 February 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 11 February 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 15 February 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 18 February 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 22 February 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 25 February 2021									
<i>No defects recorded</i>									
NE14-615919-238007735	104m	0m	GULLY	Rocking under load (IRLD)	CAT 1	29/03/2021	Completed Defects	14/03/2021	AFTER CRAIGIE AVE RBT GREENDYKES RD S/B
Safety Patrol of A90 SAFETY PATROL on 04 March 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 08 March 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 11 March 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 15 March 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 18 March 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 22 March 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 25 March 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 29 March 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 01 April 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 05 April 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 08 April 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 12 April 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 15 April 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 19 April 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 22 April 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 26 April 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 29 April 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 03 May 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 06 May 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 10 May 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 13 May 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 17 May 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 20 May 2021									
<i>No defects recorded</i>									
Safety Inspection of A90 SAFETY INSPECTION on 24 May 2021									
<i>No defects recorded</i>									
Safety Patrol of A90 SAFETY PATROL on 27 May 2021									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
NE14-655218-238139685	220m	0m	GULLY	Rocking under load (IRLD)	CAT 1	24/06/2021	Completed Defects	22/06/2021	@ BUS STOP GREENDYKES RD S/B
NE14-655218-238139686	219m	0m	KERB	Damaged (DAMG)	CAT 2		Cat 2 Awaiting Action		@ BUS STOP GREENDYKES RD S/B

Safety Inspection of A90 SAFETY INSPECTION on 31 May 2021

No defects recorded

Safety Patrol of A90 SAFETY PATROL on 03 June 2021

No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 07 June 2021

No defects recorded

Safety Patrol of A90 SAFETY PATROL on 10 June 2021

No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 14 June 2021

No defects recorded

Safety Patrol of A90 SAFETY PATROL on 17 June 2021

No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 21 June 2021

No defects recorded

Safety Patrol of A90 SAFETY PATROL on 24 June 2021

No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 28 June 2021

No defects recorded

Safety Patrol of A90 SAFETY PATROL on 01 July 2021

No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 05 July 2021

No defects recorded

Safety Patrol of A90 SAFETY PATROL on 08 July 2021

No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 12 July 2021

No defects recorded

Safety Patrol of A90 SAFETY PATROL on 15 July 2021

No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 19 July 2021

No defects recorded

Safety Patrol of A90 SAFETY PATROL on 22 July 2021

No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 26 July 2021

No defects recorded

Safety Patrol of A90 SAFETY PATROL on 29 July 2021

No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 02 August 2021

No defects recorded

Safety Patrol of A90 SAFETY PATROL on 05 August 2021

No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 09 August 2021

No defects recorded

Safety Patrol of A90 SAFETY PATROL on 12 August 2021

No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 16 August 2021

No defects recorded

Safety Patrol of A90 SAFETY PATROL on 19 August 2021

No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 23 August 2021

No defects recorded

Safety Patrol of A90 SAFETY PATROL on 26 August 2021

No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 30 August 2021

No defects recorded

Safety Patrol of A90 SAFETY PATROL on 02 September 2021

No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 06 September 2021

No defects recorded

Safety Patrol of A90 SAFETY PATROL on 09 September 2021

No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 13 September 2021

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	------------------------	----------------	--------------------	----------------------

No defects recorded

Safety Patrol of A90 SAFETY PATROL on 16 September 2021

No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 20 September 2021

No defects recorded

Safety Patrol of A90 SAFETY PATROL on 23 September 2021

No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 27 September 2021

No defects recorded

Safety Patrol of A90 SAFETY PATROL on 30 September 2021

No defects recorded

Safety Inspection of A90 SAFETY INSPECTION on 04 October 2021

No defects recorded