

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 11/10/2021 and 26/10/2021, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'AGAINST:MID POINT A737 BRIDGE TO SLIP FROM A737','AGAINST: A737 2 WAY SLIP TO ENTRY M8 EB','WITH: OFF SLIP TO A737 TO MID POINT A737 BRIDGES','WITH: SLIP TO A737 RBT','AGAINST: SLIP FROM A737 INT TO SLIP OFF M8 EB','WITH: A937 WB ENTRY SLIP TO A937 INT OFF SLIP','AGAINST: BARNSFORD ROAD TO 2 WAY SLIP','WITH: SLIP FROM A737 TO ENTRY M8 WB','WITH: M8 TO A737 ELEVATED SECTION WB','AGAINST: A737 TO M8 ELEVATED SECTION EB','WITH: AIRPORT RBT (S) TO M8 WB','AGAINST: SLIP RD ENTRY TO AIRPORT UNDERPASS','WITH: AIRPORT UNDERPASS TO SLIP RD ENTRY','AGAINST: AIRPORT INTERCHANGE BRIDGE EASTBOUND','WITH: END OF VIADUCT WBND TO SLIP RD TO APORT','AGAINST: A737 INT RBT TO ENTRY M8 EB',) Or

(Section is 'AGAINST: EB OFF SLIP TO A761 RBT ST. JAMES INT','WITH: WB SLIP FROM A761 RBT ST. JAMES INT',)

| Defect Reference | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|------------------|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|
|------------------|---------|-------|-----------|-------------|-----------------|--------------------------|----------------|-----------------|----------------------|

13714/77 : WITH: END OF VIADUCT WBND TO SLIP RD TO APORT

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 11 October 2021

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 25 October 2021

No defects recorded

13715/05 : WITH: AIRPORT UNDERPASS TO SLIP RD ENTRY

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 11 October 2021

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 25 October 2021

No defects recorded

13716/05 : WITH: A937 WB ENTRY SLIP TO A937 INT OFF SLIP

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 11 October 2021

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 25 October 2021

No defects recorded

13716/55 : WITH: OFF SLIP TO A737 TO MID POINT A737 BRIDGES

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 11 October 2021

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 25 October 2021

No defects recorded

13716/56 : AGAINST:MID POINT A737 BRIDGE TO SLIP FROM A737

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 11 October 2021

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 25 October 2021

No defects recorded

13716/06 : AGAINST: SLIP FROM A737 INT TO SLIP OFF M8 EB

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 11 October 2021

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 25 October 2021

No defects recorded

13715/06 : AGAINST: SLIP RD ENTRY TO AIRPORT UNDERPASS

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 11 October 2021

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 25 October 2021

No defects recorded

13714/88 : AGAINST: AIRPORT INTERCHANGE BRIDGE EASTBOUND

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 11 October 2021

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 25 October 2021

No defects recorded

| Defect Reference | Start m | End m | Item Type | Item Detail | Defect Category | Required Completion Date | Current Status | Completion Date | Location Description |
|------------------|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|
|------------------|------------|----------|-----------|-------------|--------------------|-----------------------------|----------------|--------------------|----------------------|

13715/11 : WITH: AIRPORT RBT (S) TO M8 WB

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 11 October 2021

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 25 October 2021

No defects recorded

13715/12 : AGAINST: A737 TO M8 ELEVATED SECTION EB

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 11 October 2021

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 25 October 2021

No defects recorded

13715/45 : WITH: M8 TO A737 ELEVATED SECTION WB

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 11 October 2021

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 25 October 2021

No defects recorded

13715/48 : AGAINST: A737 INT RBT TO ENTRY M8 EB

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 11 October 2021

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 25 October 2021

No defects recorded

13715/85 : WITH: SLIP FROM A737 TO ENTRY M8 WB

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 11 October 2021

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 25 October 2021

No defects recorded

13715/90 : AGAINST: BARNSFORD ROAD TO 2 WAY SLIP

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 11 October 2021

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 25 October 2021

No defects recorded

13716/11 : WITH: SLIP TO A737 RBT

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 11 October 2021

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 25 October 2021

No defects recorded

13716/12 : AGAINST: A737 2 WAY SLIP TO ENTRY M8 EB

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 11 October 2021

No defects recorded

Night Safety Inspection 14 day - Signs and lighting of NSW M8 & M77 Polmadie Night Inspection Route on 25 October 2021

No defects recorded

14310/03 : WITH: WB SLIP FROM A761 RBT ST. JAMES INT

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 14 October 2021

No defects recorded

14310/04 : AGAINST: EB OFF SLIP TO A761 RBT ST. JAMES INT

Night Safety Inspection 14 day - Signs and lighting of NSW A737_A738 Night Inspection Route on 14 October 2021

No defects recorded