

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/01/2021 and 11/01/2022, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'Subsidence Scheme to Thrushlands Junction','Subsidence Scheme South to North point','Bridge over Burn to Subsidence Scheme South','BRIDGE OVER BURN TO JCT (R) TO THRUSHLANDS','JCT (L) DRUMLANRIG PARK TO BRIDGE OVER BURN',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
13206/15 : JCT (L) DRUMLANRIG PARK TO BRIDGE OVER BURN									
Safety Inspection of NSW A76 Safety Inspection Route on 04 January 2021									
No defects recorded									
Safety Inspection of NSW A76 Safety Inspection Route on 05 January 2021									
No defects recorded									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 08 January 2021									
No defects recorded									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 08 January 2021									
No defects recorded									
Safety Inspection of NSW A76 Safety Inspection Route on 12 January 2021									
No defects recorded									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 15 January 2021									
No defects recorded									
Safety Inspection of NSW A76 Safety Inspection Route on 19 January 2021									
No defects recorded									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 22 January 2021									
No defects recorded									
Safety Inspection of NSW A76 Safety Inspection Route on 26 January 2021									
No defects recorded									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 29 January 2021									
No defects recorded									
Safety Inspection of NSW A76 Safety Inspection Route on 02 February 2021									
No defects recorded									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 05 February 2021									
No defects recorded									
Safety Inspection of NSW A76 Safety Inspection Route on 09 February 2021									
No defects recorded									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 12 February 2021									
No defects recorded									
Safety Inspection of NSW A76 Safety Inspection Route on 16 February 2021									
No defects recorded									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 19 February 2021									
No defects recorded									
Safety Inspection of NSW A76 Safety Inspection Route on 23 February 2021									
No defects recorded									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 26 February 2021									
No defects recorded									
Safety Inspection of NSW A76 Safety Inspection Route on 02 March 2021									
NSW73-617618-238009323	1,882m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	03/03/2021	Completed Defects	02/03/2021	A76 N/B C/WAY 1KM N OF DRUMLANRIG
Safety Patrol of NSW A76 Winter Safety Patrol Route on 05 March 2021									
No defects recorded									
Safety Inspection of NSW A76 Safety Inspection Route on 09 March 2021									
No defects recorded									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 12 March 2021									
No defects recorded									
Safety Inspection of NSW A76 Safety Inspection Route on 16 March 2021									
No defects recorded									
Detailed Inspection TEMPLATE of NSW A76 Dumfries Detail Inspection Route on 10 March 2021									
NSW92-621123-428	15m	15m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2		Cat 2 Awaiting Action		JUNCTION
NSW92-621123-429	32m	32m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2		Cat 2 Awaiting Action		

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NSW92-621123-430	73m	73m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2		Cat 2 Awaiting Action		
NSW92-621123-431	334m	334m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2		Cat 2 Awaiting Action		
NSW92-621123-432	404m	604m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2		Cat 2 Awaiting Action		
NSW92-621123-433	568m	568m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2		Cat 2 Awaiting Action		
NSW92-621123-434	580m	680m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2		Cat 2 Awaiting Action		
NSW92-621123-435	977m	1,077m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2		Cat 2 Awaiting Action		
NSW92-621123-436	1,053m	1,153m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2		Cat 2 Awaiting Action		
NSW92-621123-437	973m	973m	TRAFFIC_SIGNS	Other (OTHR)	CAT 2		Cat 2 Awaiting Action		AT JUNCTION
NSW92-621123-438	1,230m	1,330m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2		Cat 2 Awaiting Action		
NSW92-621123-439	1,274m	1,284m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		
NSW92-621123-440	1,552m	1,652m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2		Cat 2 Awaiting Action		
NSW92-621123-441	1,755m	1,805m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2		Cat 2 Awaiting Action		
NSW92-621123-442	1,772m	1,872m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2		Cat 2 Awaiting Action		
NSW92-621123-443	2,004m	2,104m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2		Cat 2 Awaiting Action		
Safety Patrol of NSW A76 Winter Safety Patrol Route on 19 March 2021									
NSW73-624542-238019665	1,755m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/03/2021	Completed Defects	19/03/2021	A76 N/B 1KM N OF DRUMLANRIG
NSW73-624542-238019666	1,753m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/03/2021	Completed Defects	19/03/2021	A76 CENTRE LINE 1KM N OF DRUMLANRIG
Safety Inspection of NSW A76 Safety Inspection Route on 23 March 2021									
No defects recorded									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 26 March 2021									
No defects recorded									
Safety Inspection of NSW A76 Safety Inspection Route on 30 March 2021									
No defects recorded									
Safety Inspection of NSW A76 Safety Inspection Route on 06 April 2021									
No defects recorded									
Safety Inspection of NSW A76 Safety Inspection Route on 13 April 2021									
No defects recorded									
Safety Inspection of NSW A76 Safety Inspection Route on 15 April 2021									
No defects recorded									
Safety Inspection of NSW A76 Safety Inspection Route on 22 April 2021									
No defects recorded									
Safety Inspection of NSW A76 Safety Inspection Route on 29 April 2021									
No defects recorded									
Safety Inspection of NSW A76 Safety Inspection Route on 06 May 2021									
No defects recorded									
Safety Inspection of NSW A76 Safety Inspection Route on 13 May 2021									
No defects recorded									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of NSW A76 Safety Inspection Route on 20 May 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 27 May 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 03 June 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 10 June 2021									
NSW73-665762-238159378	1,405m	0m	TREE	Overhanging/ov ergrown (OVER)	CAT 1	11/06/2021	Completed Defects	10/06/2021	A76 N/B C/WAY 1KM N OF DRUMLANRIG
Detailed Inspection TEMPLATE of NSW A76 Dumfries Detail Inspection Route on 17 June 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 17 June 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 24 June 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 01 July 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 08 July 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 15 July 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 22 July 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 29 July 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 05 August 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 12 August 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 19 August 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 26 August 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 02 September 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 09 September 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 16 September 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 23 September 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 30 September 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 04 October 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 07 October 2021									
NSW73-737003-238409533	1,856m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2		Cat 2 Awaiting Action		A76 S/B VERGE 600M S OF ENTERKINFOOT
Safety Patrol of NSW A76 Winter Safety Patrol Route on 11 October 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 14 October 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 18 October 2021									
NSW74-743305-238427520	1,282m	0m	VERGE	Overhanging/ov ergrown (OVER)	CAT 2		Cat 2 Awaiting Action		A76 N/B VERGE 40M NORTH OF MENNOCK N GATEWAY
Safety Inspection of NSW A76 Safety Inspection Route on 21 October 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 25 October 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 28 October 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 01 November 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 04 November 2021									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 08 November 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 11 November 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 15 November 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 18 November 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 22 November 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 25 November 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 29 November 2021									
NSW73-766167-238468537	1,537m	0m	VERGE	Other (OTHR)	CAT 2		Cat 2 Awaiting Action		A76 S/B VERGE NEXT TO LAYBY 1500M N OF DRUMLANRIG
Safety Inspection of NSW A76 Safety Inspection Route on 02 December 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 06 December 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 09 December 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 13 December 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 16 December 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 20 December 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 23 December 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 27 December 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 30 December 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 03 January 2022									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 06 January 2022									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 10 January 2022									
<i>No defects recorded</i>									
13206/29 : Bridge over Burn to Subsidence Scheme South									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 31 December 2020									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 04 January 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 05 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 08 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 08 January 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 12 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 15 January 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 19 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 22 January 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 26 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 29 January 2021									
NSW73-610235-237996922	71m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	30/01/2021	Completed Defects	29/01/2021	A76 S/B C/WAY 2KM NORTH OF DRUMLNRIG

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of NSW A76 Safety Inspection Route on 02 February 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 05 February 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 09 February 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 12 February 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 16 February 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 19 February 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 23 February 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 26 February 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 02 March 2021									
NSW73-617618-238009322	45m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	03/03/2021	Completed Defects	02/03/2021	A76 S/B C/WAY 1KM N OF DRUMANRIG
Safety Patrol of NSW A76 Winter Safety Patrol Route on 05 March 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 09 March 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 12 March 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 16 March 2021									
<i>No defects recorded</i>									
Detailed Inspection TEMPLATE of NSW A76 Dumfries Detail Inspection Route on 10 March 2021									
NSW92-621123-444	83m	133m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2		Cat 2 Awaiting Action		
Safety Patrol of NSW A76 Winter Safety Patrol Route on 19 March 2021									
NSW73-624542-238019664	33m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/03/2021	Completed Defects	19/03/2021	A76 CENTRE LINE 1KM N OF DRUMLANRIG
Safety Inspection of NSW A76 Safety Inspection Route on 23 March 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 26 March 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 30 March 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 06 April 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 13 April 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 15 April 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 22 April 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 29 April 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 06 May 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 13 May 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 20 May 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 27 May 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 03 June 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 10 June 2021									
<i>No defects recorded</i>									
Detailed Inspection TEMPLATE of NSW A76 Dumfries Detail Inspection Route on 17 June 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 17 June 2021									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 24 June 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 01 July 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 08 July 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 15 July 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 22 July 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 29 July 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 05 August 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 12 August 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 19 August 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 26 August 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 02 September 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 09 September 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 16 September 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 23 September 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 30 September 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 04 October 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 07 October 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 11 October 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 14 October 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 18 October 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 21 October 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 25 October 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 28 October 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 01 November 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 04 November 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 08 November 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 11 November 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 15 November 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 18 November 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 22 November 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 25 November 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 29 November 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 02 December 2021									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of NSW A76 Winter Safety Patrol Route on 06 December 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 09 December 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 13 December 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 16 December 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 20 December 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 23 December 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 27 December 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 30 December 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 03 January 2022									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 06 January 2022									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 10 January 2022									
<i>No defects recorded</i>									

13206/33 : Subsidence Scheme South to North point

Safety Inspection of NSW A76 Safety Inspection Route on 04 January 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 05 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 08 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 08 January 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 12 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 15 January 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 19 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 22 January 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 26 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 29 January 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 02 February 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 05 February 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 09 February 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 12 February 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 16 February 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 19 February 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 23 February 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 26 February 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 02 March 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 05 March 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 09 March 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 12 March 2021									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 16 March 2021
No defects recorded

Safety Patrol of NSW A76 Winter Safety Patrol Route on 19 March 2021
No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 23 March 2021
No defects recorded

Safety Patrol of NSW A76 Winter Safety Patrol Route on 26 March 2021
No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 30 March 2021
No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 06 April 2021
No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 13 April 2021
No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 15 April 2021
No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 22 April 2021
No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 29 April 2021
No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 06 May 2021
No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 13 May 2021
No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 20 May 2021
No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 27 May 2021
No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 03 June 2021
No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 10 June 2021
No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 17 June 2021
No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 24 June 2021
No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 01 July 2021
No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 08 July 2021
No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 15 July 2021
No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 22 July 2021
No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 29 July 2021
No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 05 August 2021
No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 12 August 2021
No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 19 August 2021
No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 26 August 2021
No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 02 September 2021
No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 09 September 2021
No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 16 September 2021
No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 23 September 2021
No defects recorded

Safety Inspection of NSW A76 Safety Inspection Route on 30 September 2021
No defects recorded

Safety Patrol of NSW A76 Winter Safety Patrol Route on 04 October 2021
No defects recorded

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of NSW A76 Safety Inspection Route on 07 October 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 11 October 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 14 October 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 18 October 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 21 October 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 25 October 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 28 October 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 01 November 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 04 November 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 08 November 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 11 November 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 15 November 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 18 November 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 22 November 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 25 November 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 29 November 2021									
NSW73-766167-238468535	945m	0m	VERGE	Other (OTHR)	CAT 2		Cat 2 Awaiting Action		A76 S/B VERGE 500M S OF HELLS CAULDRON LAYBY
NSW73-766167-238468536	58m	0m	VERGE	Other (OTHR)	CAT 2		Cat 2 Awaiting Action		A76 N/B VERGE 100M START PHEASANT VALLEY SOUTH END SUBSIDENCE SCHEME
Safety Inspection of NSW A76 Safety Inspection Route on 02 December 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 06 December 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 09 December 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 13 December 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 16 December 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 20 December 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 23 December 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 27 December 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 30 December 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 03 January 2022									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 06 January 2022									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 10 January 2022									
<i>No defects recorded</i>									
13206/37 : Subsidence Scheme to Thrushlands Junction									
Safety Inspection of NSW A76 Safety Inspection Route on 04 January 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 05 January 2021									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of NSW A76 Winter Safety Patrol Route on 08 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 08 January 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 12 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 15 January 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 19 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 22 January 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 26 January 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 29 January 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 02 February 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 05 February 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 09 February 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 12 February 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 16 February 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 19 February 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 23 February 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 26 February 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 02 March 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 05 March 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 09 March 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 12 March 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 16 March 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 19 March 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 23 March 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 26 March 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 30 March 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 06 April 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 13 April 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 15 April 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 22 April 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 29 April 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 06 May 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 13 May 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 20 May 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 27 May 2021									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	---------	-------	-----------	-------------	-----------------	--------------------------	----------------	-----------------	----------------------

<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 03 June 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 10 June 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 17 June 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 24 June 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 01 July 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 08 July 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 15 July 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 22 July 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 29 July 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 05 August 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 12 August 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 19 August 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 26 August 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 02 September 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 09 September 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 16 September 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 23 September 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 30 September 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 04 October 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 07 October 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 11 October 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 14 October 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 18 October 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 21 October 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 25 October 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 28 October 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 01 November 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 04 November 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 08 November 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 11 November 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 15 November 2021									
<i>No defects recorded</i>									
Safety Inspection of NSW A76 Safety Inspection Route on 18 November 2021									
<i>No defects recorded</i>									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 22 November 2021									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NSW73-762375-238465789	447m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	20/12/2021	Completed Defects	25/11/2021	A76 NB C\WAY @ WITCHES CAULDRAN LAYBE
NSW73-762375-238465790	449m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2		Cat 2 Awaiting Action		A67 N/B C\WAY @ HELLS CAULDRAN LAYBE
Safety Inspection of NSW A76 Safety Inspection Route on 25 November 2021									
NSW74-764018-238466299	583m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/12/2021	Completed Defects	13/12/2021	A76 N/B C\WAY 50M N OF HELLS CAULDRON LAYBY
NSW74-764018-238466300	699m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/12/2021	Completed Defects	13/12/2021	A76 N/B C\WAY 50M N OF HELLS CAULDRON
Safety Patrol of NSW A76 Winter Safety Patrol Route on 29 November 2021									
NSW73-766167-238468534	364m	0m	VERGE	Other (OTHR)	CAT 2		Cat 2 Awaiting Action		A76 S/B VERGE 100M S OF HELLS CAULDRON LAYBY
Safety Inspection of NSW A76 Safety Inspection Route on 02 December 2021									
No defects recorded									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 06 December 2021									
No defects recorded									
Safety Inspection of NSW A76 Safety Inspection Route on 09 December 2021									
No defects recorded									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 13 December 2021									
No defects recorded									
Safety Inspection of NSW A76 Safety Inspection Route on 16 December 2021									
No defects recorded									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 20 December 2021									
No defects recorded									
Safety Inspection of NSW A76 Safety Inspection Route on 23 December 2021									
No defects recorded									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 27 December 2021									
No defects recorded									
Safety Inspection of NSW A76 Safety Inspection Route on 30 December 2021									
No defects recorded									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 03 January 2022									
No defects recorded									
Safety Inspection of NSW A76 Safety Inspection Route on 06 January 2022									
No defects recorded									
Safety Patrol of NSW A76 Winter Safety Patrol Route on 10 January 2022									
No defects recorded									