Road Nai Section	ion Code	Defect Reference	Description	Location Description	Asset Type	Defect Category	Defect Date Defect Action Type	Due Date	Repair Date	Complete Date	Element Reference	Defect Status	First Defect Action Status
A8 13865	55/55	D-22-SW-00186	321127-Pothole	A8 W/B Bogston station pedestrian crossing	Carriageway	CAT1	11/04/2022 Deferred - Permanent	t 09/05/2022	12/04/2022	12/04/2022	E-22-SW-00692-C	Closed	Complete - On Time
A8 13865	55/55	D-22-SW-03269	Pothole x2. Approximately (1m x 0.5m) and (0.5m x0.5m)	A8 Westbound, Traffic lights at Bogston Station, Left permanent lane 1, at o	c: Carriageway	CAT1	06/09/2022 Deferred - Permanen	t 04/10/2022			E-22-SW-04928-C	Open	Open