

M74 10798/18 - Against: 2-Lane left turn exit slip to Polmadie Rd	763795 NSW M74 Slips Polmadie Safety Patrol Route (R) - Safety Patrol on 02/06/2022	No Defects Recorded	0
M74 10798/18 - Against: 2-Lane left turn exit slip to Polmadie Rd	763911 NSW M74 Slips Polmadie Safety Inspection Route (R) - Safety Inspection on 11/07/2022	No Defects Recorded	0
M74 10798/18 - Against: 2-Lane left turn exit slip to Polmadie Rd	764005 NSW M74 Slips Polmadie Safety Inspection Route (R) - Safety Inspection on 23/06/2022	No Defects Recorded	0
M74 10798/18 - Against: 2-Lane left turn exit slip to Polmadie Rd	912646 NSW M74 Slips Polmadie Safety Inspection Route (R) - Safety Inspection on 25/07/2022	No Defects Recorded	0
M74 10798/18 - Against: 2-Lane left turn exit slip to Polmadie Rd	912766 NSW M74 Slips Polmadie Safety Inspection Route (R) - Safety Inspection on 19/07/2022	No Defects Recorded	0
M74 10798/18 - Against: 2-Lane left turn exit slip to Polmadie Rd	912802 NSW M74 Slips Polmadie Safety Inspection Route (R) - Safety Inspection on 02/08/2022	No Defects Recorded	0
M74 10798/18 - Against: 2-Lane left turn exit slip to Polmadie Rd	942251 NSW M74 Slips Polmadie Safety Inspection Route (R) - Safety Inspection on 15/09/2022	No Defects Recorded	0
M74 10798/18 - Against: 2-Lane left turn exit slip to Polmadie Rd	942289 NSW M74 Slips Polmadie Safety Inspection Route (R) - Safety Inspection on 09/08/2022	No Defects Recorded	0
M74 10798/18 - Against: 2-Lane left turn exit slip to Polmadie Rd	942348 NSW M74 Slips Polmadie Safety Patrol Route (R) - Safety Patrol on 10/06/2022	No Defects Recorded	0
M74 10798/18 - Against: 2-Lane left turn exit slip to Polmadie Rd	942398 NSW M74 Slips Polmadie Safety Inspection Route (R) - Safety Inspection on 16/08/2022	No Defects Recorded	0
M74 10798/18 - Against: 2-Lane left turn exit slip to Polmadie Rd	942409 NSW M74 Slips Polmadie Safety Patrol Route (R) - Safety Patrol on 23/06/2022	No Defects Recorded	0
M74 10798/18 - Against: 2-Lane left turn exit slip to Polmadie Rd	951584 NSW M74 Slips Polmadie Safety Inspection Route (R) - Safety Inspection on 23/08/2022	No Defects Recorded	0
M74 10798/18 - Against: 2-Lane left turn exit slip to Polmadie Rd	951629 NSW M74 Slips Polmadie Safety Patrol Route (R) - Safety Patrol on 30/06/2022	No Defects Recorded	0
M74 10798/18 - Against: 2-Lane left turn exit slip to Polmadie Rd	951687 NSW M74 Slips Polmadie Safety Inspection Route (R) - Safety Inspection on 05/09/2022	No Defects Recorded	0
M74 10798/18 - Against: 2-Lane left turn exit slip to Polmadie Rd	951761 NSW M74 Slips Polmadie Safety Patrol Route (R) - Safety Patrol on 28/07/2022	No Defects Recorded	0
M74 10798/18 - Against: 2-Lane left turn exit slip to Polmadie Rd	951808 NSW M74 Slips Polmadie Safety Inspection Route (R) - Safety Inspection on 26/09/2022	No Defects Recorded	0
M74 10798/18 - Against: 2-Lane left turn exit slip to Polmadie Rd	951865 NSW M74 Slips Polmadie Safety Patrol Route (R) - Safety Patrol on 04/08/2022	No Defects Recorded	0
M74 10798/18 - Against: 2-Lane left turn exit slip to Polmadie Rd	951883 NSW M74 Slips Polmadie Safety Inspection Route (R) - Safety Inspection on 20/09/2022	No Defects Recorded	0
M74 10798/18 - Against: 2-Lane left turn exit slip to Polmadie Rd	951978 NSW M74 Slips Polmadie Safety Patrol Route (R) - Safety Patrol on 12/08/2022	No Defects Recorded	0
M74 10798/18 - Against: 2-Lane left turn exit slip to Polmadie Rd	952007 NSW M74 Slips Polmadie Safety Inspection Route (R) - Safety Inspection on 12/09/2022	No Defects Recorded	0
M74 10798/18 - Against: 2-Lane left turn exit slip to Polmadie Rd	952053 NSW M74 Slips Polmadie Safety Patrol Route (R) - Safety Patrol on 25/08/2022	No Defects Recorded	0
M74 10798/18 - Against: 2-Lane left turn exit slip to Polmadie Rd	952073 NSW M74 Slips Polmadie Safety Inspection Route (R) - Safety Inspection on 03/10/2022	No Defects Recorded	0
M74 10798/18 - Against: 2-Lane left turn exit slip to Polmadie Rd	952167 NSW M74 Slips Polmadie Safety Inspection Route (R) - Safety Inspection on 10/10/2022	No Defects Recorded	0
M74 10798/18 - Against: 2-Lane left turn exit slip to Polmadie Rd	952201 NSW M74 Slips Polmadie Safety Patrol Route (R) - Safety Patrol on 02/09/2022	No Defects Recorded	0
M74 10798/18 - Against: 2-Lane left turn exit slip to Polmadie Rd	952221 NSW M74 Slips Polmadie Safety Patrol Route (R) - Safety Patrol on 08/09/2022	No Defects Recorded	0
M74 10798/18 - Against: 2-Lane left turn exit slip to Polmadie Rd	952241 NSW M74 Slips Polmadie Safety Patrol Route (R) - Safety Patrol on 30/09/2022	No Defects Recorded	0
M74 10798/18 - Against: 2-Lane left turn exit slip to Polmadie Rd	952307 NSW M74 Slips Polmadie Safety Inspection Route (R) - Safety Inspection on 17/10/2022	No Defects Recorded	0

Applied filters:

Road is M74

SectionSlicer is 10796/55 - With: WB Exit slip to Polmadie Rd, 10796/56 -

Against: Merge to EB entry slip, 10796/57 - Against: EB Entry slip from

Polmadie Rd, 10798/11 - With: Polmadie Rd to WB Entry slip, 10798/12 -

With: Polmadie Rd to WB entry slip (left), 10798/14 - With: WB Entry

slip from Polmadie Rd, 10798/17 - Against: EB Exit slip to Polmadie Rd,

or 10798/18 - Against: 2-Lane left turn exit slip to Polmadie Rd

Inspection Activity is Gully - Surface Visual Condition, Safety Inspection,

or Safety Patrol