

Incident	Contract	Occurred	Issued	Arrived	Closed	Source	Responder	Category	Type	Description	Route	Direction	Junction	Coordinates	Marker Post	Link/Sect	Location Description	Damage	Debris	Spillage	Fuel	Medics	Fire/Rescue	Police	Police Incident	Disruption	Dis Description	Dis Lanes Affected	Disruption Duration	Fatal	Live Lane	Crossing	Rolling Block	Incident ID
ASW300422-2020	ASW	26/08/2020	10:44	10:44	10:50	TANGO 1	TANGO 1 (TRISS)	Minor	Pothole	2 potholes	M74	Southbound		261077, 662050		10796/06	M74 J1a - J2 s/b											0 00:00						300422
ASW300715-2020	ASW	02/09/2020	14:57	15:05	15:15	Amey Route Inspector	TANGO 1 (TRISS)	Minor	Asset Damage	Barrier Damage	M74	Northbound	1 (a)			10796/06	M74 200 mtrs prior to Junction 1(a)											0 00:00						300715
ASW301375-2020	ASW	20/09/2020	06:50	06:50	06:55	TANGO 1	TANGO 1 (TRISS)	Minor	Pothole	Pothole	M74	Southbound	1A to 2	260544, 662168		10796/52	M74(S) J 1A-2											0 00:00						301375
ASW307259-2021	ASW	18/02/2021	11:40	11:45	11:50	Amey Office Employee	TANGO 1 (TRISS)	Minor	Pothole	TEMP 2259: Pothole	M74	Southbound	1A	258920, 663248		10798/06	M74 s/b prior to J1A											0 00:00						307259
ASW307983-2021	ASW	13/03/2021	07:40	07:40	07:50	TANGO 1	TANGO 1 (TRISS)	Minor	Asset Damage	TEMP 2983: Damaged Nadics box	M74	Northbound	1A			10796/51	M74 n/b J1A	Y										0 00:00						307983
ASW317183-2021	ASW	18/12/2021	16:49	16:50	16:55	Trunk Roads Cust Care	TANGO 1 (TRISS)	Minor	Pothole	Pothole (No Trace)	M74	Southbound	1a exit slip				M74 S/B J1a exit/entry slip											0 00:00						317183
ASW332010-2023	ASW	18/01/2023	21:00	21:00	22:00	Amey Operational Employee	OTHER	Minor	Pothole	Pothole	M74	Northbound	2 to 1a	261043, 662025		10796/05	M74 N/B J2 - 1a on lane 1											0 00:00						332010
ASW334397-2023	ASW	09/03/2023	12:05	12:10	12:20	Member of Public	TANGO 1 (TRISS)	Minor	Pothole	Pothole - no trace	M74	Southbound	1A	259089, 663117		10798/06	M74S just before J1A, lane 1											0 00:00						334397