

Location	Task	Asset Id or Section - Chainage & Asset Type	Defect Information	Defects Raised	Defect Action	Repair Date
M8 14255/05 - WITH: ENTRY M8 WB TO JCT 20 OFF SLIP	Total			0		
M8 14255/05 - WITH: ENTRY M8 WB TO JCT 20 OFF SLIP	1206308 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 02/11/2022	Total		0		
M8 14255/05 - WITH: ENTRY M8 WB TO JCT 20 OFF SLIP	1206308 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 02/11/2022	No Defects Recorded		0		
M8 14255/05 - WITH: ENTRY M8 WB TO JCT 20 OFF SLIP	1206706 AD-HOC M8 East Polmadie safety inspection (craig) - Safety Inspection on 31/10/2022	Total		0		
M8 14255/05 - WITH: ENTRY M8 WB TO JCT 20 OFF SLIP	1206706 AD-HOC M8 East Polmadie safety inspection (craig) - Safety Inspection on 31/10/2022	No Defects Recorded		0		