

Defect Reference	Defect Category	Asset Type	Action	Repair Status	Element	Defect Status	Location	Defect Date	Due Date	Owner	3rd Party Owner	Unit	Road Section	Created By	XSP Chainage
NE122609810-237995779	CAT2	Traffic Sign	Permanent	Open		Open			18/01/2021	Unknown		North East	A972 13415/13	Iris Data Migration	L1
NE122604140-140	CAT2	Kerbs	Permanent	Open		Open			11/11/2020	Unknown		North East	A972 13415/13	System Administrator	LE
NE122604140-139	CAT2	Traffic Sign	Permanent	Open		Open			11/11/2020	Unknown		North East	A972 13415/13	System Administrator	L1
NE122604140-138	CAT2	Kerbs	Permanent	Open		Open			11/11/2020	Unknown		North East	A972 13415/13	System Administrator	LE
NE122604140-137	CAT2	Road Marking Transverse & Special	Permanent	Open		Open			11/11/2020	Unknown		North East	A972 13415/13	System Administrator	CL2
NE122604140-136	CAT2	Road Marking Transverse & Special	Permanent	Open		Open			11/11/2020	Unknown		North East	A972 13415/13	System Administrator	CL1
NE122604140-135	CAT2	Traffic Sign	Permanent	Open		Open			11/11/2020	Unknown		North East	A972 13415/13	System Administrator	R1
NE122604140-133	CAT2	Road Marking Transverse & Special	Permanent	Open		Open			11/11/2020	Unknown		North East	A972 13415/13	System Administrator	CL1
NE122604140-134	CAT2	Road Marking Transverse & Special	Permanent	Open		Open			11/11/2020	Unknown		North East	A972 13415/13	System Administrator	CL2
NE122604140-132	CAT2	Traffic Sign	Permanent	Open		Open			11/11/2020	Unknown		North East	A972 13415/13	System Administrator	L3
NE122604140-131	CAT2	Traffic Sign	Permanent	Open		Open			11/11/2020	Unknown		North East	A972 13415/13	System Administrator	R1
NE122604140-130	CAT2	Pedestrian Guardrail	Permanent	Open		Open			11/11/2020	Unknown		North East	A972 13415/13	System Administrator	L1

Defect Reference	Defect Category	Asset Type	Action	Repair Status	Element	Defect Status	Location	Defect Date	Due Date	Owner	3rd Party Owner	Unit	Road Section	Created By	XSP Chainage
NE122604140-101	CAT2	Road Marking Longitudinal	Permanent	Open		Open			11/11/2020	Unknown		North East	A972 13415/12	System Administrator	CC
NE122604140-102	CAT2	Road Marking Transverse & Special	Permanent	Open		Open			11/11/2020	Unknown		North East	A972 13415/12	System Administrator	CL1
NE122604140-103	CAT2	Road Marking Transverse & Special	Permanent	Open		Open			11/11/2020	Unknown		North East	A972 13415/12	System Administrator	CL2
NE122604140-104	CAT2	Road Marking Longitudinal	Permanent	Open		Open			11/11/2020	Unknown		North East	A972 13415/12	System Administrator	CC
NE122604140-105	CAT2	Traffic Sign	Permanent	Open		Open			11/11/2020	Unknown		North East	A972 13415/12	System Administrator	L3
NE122604140-106	CAT2	Traffic Sign	Permanent	Open		Open			11/11/2020	Unknown		North East	A972 13415/12	System Administrator	L3
NE122604140-107	CAT2	Road Marking Transverse & Special	Permanent	Open		Open			11/11/2020	Unknown		North East	A972 13415/12	System Administrator	L1
NE122604140-108	CAT2	Road Marking Longitudinal	Permanent	Open		Open			11/11/2020	Unknown		North East	A972 13415/12	System Administrator	CC
NE122604140-109	CAT2	Traffic Sign	Permanent	Open		Open			11/11/2020	Unknown		North East	A972 13415/12	System Administrator	L1
NE122604140-111	CAT2	Traffic Sign	Permanent	Open		Open			11/11/2020	Unknown		North East	A972 13415/12	System Administrator	L1
NE122604140-110	CAT2	Traffic Sign	Permanent	Open		Open			11/11/2020	Unknown		North East	A972 13415/12	System Administrator	L1

Inspection Defect Summary Report



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
13415/13 : Against: A90 Junction to Pitkerro Rd Rbt									
Detailed Inspection TEMPLATE of A972 DETAIL 1 2016 on 10 November 2020									
NE122604140-135	435m	0m	TRAFFIC_SIGNS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		PRIOR TO PITKERRO RD RBT E/B
NE122604140-132	41m	0m	TRAFFIC_SIGNS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		FORFAR RD LIGHTS A90 JCT E/B
NE122604140-139	537m	0m	TRAFFIC_SIGNS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		PRIOR TO PITKERRO RB RBT E/B
NE122604140-140	546m	0m	KERB	Damaged (DAMG)	CAT 2		Cat 2 Awaiting Action		PITKERRO RD RBT E/B
NE122604140-131	17m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2		Cat 2 Awaiting Action		FORFAR RD LIGHTS A90 JCT E/B
NE122604140-138	528m	0m	KERB	Damaged (DAMG)	CAT 2		Cat 2 Awaiting Action		PRIOR TO PITKERRO RB RBT E/B
NE122604140-130	2m	0m	PEDESTRIAN_GU ARDRAIL	Damaged / deformed - fence / barrier (DAMM)	CAT 2		Cat 2 Awaiting Action		FORFAR RD LIGHTS A90 JCT E/B
NE122604140-137	460m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		PRIOR TO PITKERRO RB RBT E/B
NE122604140-133	53m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		FORFAR RD LIGHTS A90 JCT E/B O/S SHELL GARAGE
NE122604140-134	52m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		FORFAR RD LIGHTS A90 JCT E/B O/S SHELL GARAGE



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE122604140-136	457m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		PRIOR TO PITKERRO RB RBT E/B
Reactive Defect Recorded 26/11/2020 11:25:25									
D-NE20237940856	0m	0m	TRAFFIC_SIGNS	Lamp failure (LAMP)	CAT 1	22/12/2020	Completed Defects	24/11/2020	A972, 13415/13, Against: A90 Junction to Pitkerro Rd Rbt, 98m , Right Off Carriageway 1, VX42S06 VX42S07
Weekly Patrol of A972 signs 2 on 18 January 2021									
NE122609810-237995779	31m	0m	TRAFFIC_SIGNS	Other (OTHR)	CAT 2		Cat 2 Awaiting Action		A90 FORFAR RD LIGHTS SHELL GARAGE DUNDEE E/B
Reactive Defect Recorded 22/03/2021 10:49:51									
D-NE21238034820	0m	0m	LIGHTING_POINT	Lamp failure (LAMP)	CAT 1	14/04/2021	Completed Defects	17/03/2021	Dundee
Safety Inspection of A90 SAFETY INSPECTION on 21 June 2021									
NE14-669457-238180196	84m	0m	GULLY	Difference in component levels (ICLV)	CAT 1	22/06/2021	Completed Defects	21/06/2021	SHELL GARAGE FORFAR RD E/B
Safety Patrol of A90 SAFETY PATROL on 07 October 2021									
NE122-735161-238408892	279m	0m	TRAFFIC_SIGNS	Pointing wrong way (RWAY)	CAT 2		Cat 2 Awaiting Action		KINGSWAY APPROACH PITKERRO RDBT N/B
Weekly Patrol of A90 SAFETY INSPECTION on 27 October 2021									
NE7-721681-238364952	306m	0m	CABINET	Other (OTHR)	CAT 2		Cat 2 Awaiting Action		AFTER FORFAR RD LIGHTS E/B
NE7-721681-238364950	276m	0m	FOOTWAY	Bituminous surfacing - local cracking (BLCK)	CAT 2		Cat 2 Awaiting Action		AFTER FORFAR RD LIGHTS E/B
NE7-721681-238364946	86m	0m	GULLY	Cracked or broken (IBCK)	CAT 2		Cat 2 Awaiting Action		AFTER FORFAR RD LIGHTS E/B
NE7-721681-238364940	38m	0m	TRAFFIC_SIGNS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		AFTER FORFAR RD LIGHTS E/B
NE7-721681-238364958	536m	0m	KERB	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		APPROACHING PITKERRO RBT E/B
NE7-721681-238364960	552m	0m	KERB	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		APPROACHING PITKERRO RBT E/B

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE7-721681-238364959	540m	0m	TRAFFIC_SIGNS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		APPROACHING PITKERRO RBT E/B
NE7-721681-238364955	434m	0m	TRAFFIC_SIGNS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		APPROACHING PITKERRO RBT E/B
NE7-721681-238364953	336m	0m	TRAFFIC_SIGNS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		AFTER FORFAR RD LIGHTS E/B
NE7-721681-238364942	52m	0m	TRAFFIC_SIGNS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		AFTER FORFAR RD LIGHTS E/B
NE7-721681-238364947	90m	0m	Drainage Ancillary Items	Blockage (BLOK)	CAT 2		Cat 2 Awaiting Action		AFTER FORFAR RD LIGHTS E/B
NE7-721681-238364951	284m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2		Cat 2 Awaiting Action		AFTER FORFAR RD LIGHTS E/B
NE7-721681-238364948	107m	0m	KERB	Damaged (DAMG)	CAT 2		Cat 2 Awaiting Action		AFTER FORFAR RD LIGHTS E/B
NE7-721681-238364935	28m	0m	KERB	Damaged (DAMG)	CAT 2		Cat 2 Awaiting Action		AFTER FORFAR RD LIGHTS E/B
NE7-721681-238364945	61m	0m	CARRIAGEWAY	Detritus / Refuse (DETR)	CAT 2		Cat 2 Awaiting Action		AFTER FORFAR RD LIGHTS E/B
NE7-721681-238364933	5m	0m	CARRIAGEWAY	Detritus / Refuse (DETR)	CAT 2		Cat 2 Awaiting Action		@ FORFAR RD LIGHTS E/B
NE7-721681-238364949	183m	0m	VERGE	Litter Grade C (LITC)	CAT 2		Cat 2 Awaiting Action		AFTER FORFAR RD LIGHTS E/B
NE7-721681-238364954	171m	0m	CENTRAL_RESERVE	Litter Grade C (LITC)	CAT 2		Cat 2 Awaiting Action		AFTER FORFAR RD LIGHTS E/B
NE7-721681-238364961	549m	0m	FENCES_AND_BARRIERS	Accident damage (ACCD)	CAT 2		Cat 2 Awaiting Action		APPROACHING PITKERRO RBT E/B
NE7-721681-238364932	4m	0m	PEDESTRIAN_GUARDRAIL	Accident damage (ACCD)	CAT 2		Cat 2 Awaiting Action		@ FORFAR RD LIGHTS E/B
NE7-721681-238364936	40m	0m	TRAFFIC_SIGNS	Accident damage (ACCD)	CAT 2		Cat 2 Awaiting Action		AFTER FORFAR RD LIGHTS E/B

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE7-721681-238364937	32m	0m	SAFETY_FENCE	Damaged / deformed - fence / barrier (DAMM)	CAT 2		Cat 2 Awaiting Action		@ SHELL GARAGE ENTRANCE
NE7-721681-238364943	54m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		AFTER FORFAR RD LIGHTS E/B
NE7-721681-238364941	50m	0m	CARRIAGEWAY	Cracking around ironwork (CKIR)	CAT 2		Cat 2 Awaiting Action		AFTER FORFAR RD LIGHTS E/B
NE7-721681-238364944	53m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		AFTER FORFAR RD LIGHTS E/B
NE7-721681-238364934	23m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		@FORFAR RD LIGHTS E/B
NE7-721681-238364956	458m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		APPROACHING PITKERRO RBT E/B
NE7-721681-238364957	462m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		APPROACHING PITKERRO RBT E/B
NE7-721681-238364939	32m	0m	TRAFFIC_SIGNS	Physical condition of fittings (COFT)	CAT 2		Cat 2 Awaiting Action		AFTER FORFAR RD LIGHTS E/B
NE7-721681-238364938	32m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2		Cat 2 Awaiting Action		AFTER FORFAR RD LIGHTS E/B
Safety Patrol of A90 SAFETY PATROL on 11 November 2021									
NE7-754858-238459900	94m	0m	GULLY	Cracked or broken (IBCK)	CAT 1	09/12/2021	Completed Defects	23/11/2021	@ SHELL GARAGE E/B
Safety Inspection of A90 SAFETY INSPECTION on 29 November 2021									
NE7-764494-238466650	283m	0m	TRAFFIC_SIGNS	Pointing wrong way (RWAY)	CAT 2		Cat 2 Awaiting Action		APPROACHING PITKERRO RBT E/B
Safety Inspection of A90 SAFETY INSPECTION on 27 December 2021									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE6-779144-238500596	169m	0m	LIGHTING_POINT	Exposed wiring (EXPW)	CAT 1	28/12/2021	Completed Defects	27/12/2021	East of Forfar Junction E/B

Inspection Defect Summary Report



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
13415/14 : With:Start of 3-lane to A90 Junction									
Reactive Defect Recorded 01/10/2020 10:24:24									
D-NE20237865853	0m	0m	TRAFFIC_SIGNAL S	Other (OTHR)	CAT 1	26/11/2020	Completed Defects	02/10/2020	A972, 13415/14, With:Start of 3-lane to A90 Junction, 252m , Left Off Carriageway 1, VXT52
D-NE20237868789	0m	0m	BOLLARDS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A90 Bollard Centre Res opposite VX4108 Dundee
Reactive Defect Recorded 20/10/2020 11:26:10									
D-NE20237905052	0m	0m	TRAFFIC_SIGNAL S	Other (OTHR)	CAT 1	16/11/2020	Completed Defects	21/10/2020	A972, 13415/14, With:Start of 3-lane to A90 Junction, 252m , Left Off Carriageway 1, VXT52
Detailed Inspection TEMPLATE of A972 DETAIL 1 2016 on 10 November 2020									
NE122604140-117	102m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		MARTIN STREET JCT W/B
NE122604140-118	102m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		MARTIN STREET W/B
NE122604140-122	150m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		FORFAR RD LIGHTS A90 JCT W/B
NE122604140-123	154m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		FORFAR RD LIGHTS A90 JCT W/B
NE122604140-124	159m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		FORFAR RD LIGHTS A90 JCT W/B

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE122604140-126	182m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		FORFAR RD LIGHTS A90 JCT W/B
NE122604140-127	183m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		FORFAR RD LIGHTS A90 JCT W/B
NE122604140-113	6m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		EAST OF MARTIN STREET W/B
NE122604140-119	114m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2		Cat 2 Awaiting Action		MARTIN STREER JCT W/B
NE122604140-120	124m	0m	TRAFFIC_SIGNS	Dirty sign (DIRT)	CAT 2		Cat 2 Awaiting Action		MARTIN STREET JCT W/B
NE122604140-121	123m	0m	TRAFFIC_SIGNS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		MARTIN STREET JCT W/B
NE122604140-125	181m	0m	TRAFFIC_SIGNS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		FORFAR RD LIGHTS A90 JCT W/B
NE122604140-128	239m	0m	GULLY	Blockage (BLOK)	CAT 2		Cat 2 Awaiting Action		FORFAR RD LIGHTS A90 JCT W/B
NE122604140-129	242m	0m	TRAFFIC_SIGNS	Missing (MISS)	CAT 2		Cat 2 Awaiting Action		FORFAR RD LIGHTS A90 JCT W/B
NE122604140-112	0m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		EAST OF MARTIN STREET W/B
NE122604140-116	53m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		EAST OF MARTIN STREET W/B
NE122604140-115	48m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		EAST OF MARTIN STREET W/B

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE122604140-114	12m	0m	ROAD_MARKINGS_HATCHED	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		EAST OF MARTIN STREET W/B
Reactive Defect Recorded 07/12/2020 14:47:21									
D-NE20237970766	0m	0m	TRAFFIC_SIGNALS	Other (OTHR)	CAT 1	04/01/2021	Completed Defects	08/12/2020	A972, 13415/14, With:Start of 3-lane to A90 Junction, 252m , Left Off Carriageway 1, VXT52
Reactive Defect Recorded 14/01/2021 12:11:03									
D-NE21237995772	0m	0m	TRAFFIC_SIGNALS	Other (OTHR)	CAT 1	11/02/2021	Completed Defects	15/01/2021	A972, 13415/14, With:Start of 3-lane to A90 Junction, 252m , Left Off Carriageway 1, VXT52
Reactive Defect Recorded 03/03/2021 10:06:49									
D-NE21238010320	0m	0m	TRAFFIC_SIGNALS	Other (OTHR)	CAT 1	29/03/2021	Completed Defects	02/03/2021	A972, 13415/14, With:Start of 3-lane to A90 Junction, 252m , Left Off Carriageway 1, VXT52
Safety Inspection of A90 SAFETY INSPECTION on 05 April 2021									
NE14-630235-238044892	255m	0m	BOLLARDS	Accident damage (ACCD)	CAT 1	03/05/2021	Completed Defects	19/04/2021	@ FORFAR RD LIGHTS
Reactive Defect Recorded 29/04/2021 10:54:16									
D-NE21238103631	0m	0m	TRAFFIC_SIGNALS	Other (OTHR)	CAT 1	26/05/2021	Completed Defects	29/04/2021	DUNDEE Kingsway/Forfar Road
Reactive Defect Recorded 03/05/2021 11:45:40									
D-NE21238108522	0m	0m	TRAFFIC_SIGNALS	Other (OTHR)	CAT 1	29/05/2021	Completed Defects	04/05/2021	Forfar Road lights kingsway at shell garage
Reactive Defect Recorded 31/05/2021 14:29:40									
D-NE21238156146	0m	0m	TRAFFIC_SIGNALS	Other (OTHR)	CAT 1	31/05/2021	Completed Defects	04/05/2021	A90 DUNDEE, KINGSWAY FORFAR ROAD
Reactive Defect Recorded 07/06/2021 12:31:23									
D-NE21238160351	0m	0m	TRAFFIC_SIGNALS	Other (OTHR)	CAT 1	02/07/2021	Completed Defects	04/06/2021	A90 Kingsway/Forfar Road, Dundee
Reactive Defect Recorded 08/07/2021 13:14:27									
D-NE21238214317	249m	249m	TRAFFIC_SIGNALS	Other (OTHR)	CAT 1	05/08/2021	Completed Defects	08/07/2021	Kingsway / Forfar Rd
Reactive Defect Recorded 18/08/2021 15:59:23									
D-NE21238299207	0m	0m	TRAFFIC_SIGNALS	Other (OTHR)	CAT 1	15/09/2021	Completed Defects	19/08/2021	A90, DUNDEE, Kingsway/Forfar Road
Reactive Defect Recorded 04/10/2021 12:37:39									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
D-NE21238409524	0m	0m	TRAFFIC_SIGNALS	Condition of buttons / detectors (CBDT)	CAT 1	01/11/2021	Completed Defects	06/10/2021	A90, Dundee, Kingsway/Forfar Road
Weekly Patrol of A90 SAFETY INSPECTION on 27 October 2021									
NSE02-721681-238364906	4m	0m	ROAD_MARKS_TRANSVERSE	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		APPR FORFAR RD LIGHTS WB
NSE02-721681-238364907	7m	0m	ROAD_MARKS_TRANSVERSE	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		APPR FORFAR RD LIGHTS WB
NSE02-721681-238364908	9m	0m	ROAD_MARKS_TRANSVERSE	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		APPR FORFAR RD LIGHTS WB
NSE02-721681-238364909	16m	0m	ROAD_MARKINGS_HATCHED	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		APPR FORFAR RD LIGHTS WB
NSE02-721681-238364913	52m	0m	ROAD_MARKS_TRANSVERSE	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		APPR FORFAR RD LIGHTS WB
NSE02-721681-238364914	52m	0m	ROAD_MARKS_TRANSVERSE	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		APPR FORFAR RD LIGHTS WB
NSE02-721681-238364915	54m	0m	ROAD_MARKS_TRANSVERSE	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		APPR FORFAR RD LIGHTS WB
NSE02-721681-238364912	31m	0m	FOOTWAY	Other (OTHR)	CAT 2		Cat 2 Awaiting Action		APPR FORFAR RD LIGHTS WB
NSE02-721681-238364925	213m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		APPR FORFAR RD LIGHTS WB

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NSE02-721681-238364924	202m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		APPR FORFAR RD LIGHTS WB
NSE02-721681-238364911	29m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		APPR FORFAR RD LIGHTS WB
NSE02-721681-238364910	23m	0m	ROAD_MARKINGS_LONG	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		APPR FORFAR RD LIGHTS WB
NSE02-721681-238364916	102m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		APPR FORFAR RD LIGHTS WB
NSE02-721681-238364917	104m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		APPR FORFAR RD LIGHTS WB
NSE02-721681-238364918	152m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		APPR FORFAR RD LIGHTS WB
NSE02-721681-238364919	151m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		APPR FORFAR RD LIGHTS WB
NSE02-721681-238364920	148m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		APPR FORFAR RD LIGHTS WB
NSE02-721681-238364921	189m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		APPR FORFAR RD LIGHTS WB
NSE02-721681-238364922	189m	0m	ROAD_MARKS_TRANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		APPR FORFAR RD LIGHTS WB

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NSE02-721681-238364923	185m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		APPR FORFAR RD LIGHTS WB
NSE02-721681-238364926	224m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		APPR FORFAR RD LIGHTS WB
NSE02-721681-238364927	224m	0m	ROAD_MARKS_TR ANS_SP	Wear (for example erosion) (WEAR)	CAT 2		Cat 2 Awaiting Action		APPR FORFAR RD LIGHTS WB
NSE02-721681-238364928	240m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2		Cat 2 Awaiting Action		APPR FORFAR RD LIGHTS WB
NSE02-721681-238364929	258m	0m	TRAFFIC_SIGNS	Loss of surface / paint covering (LOPT)	CAT 2		Cat 2 Awaiting Action		APPR FORFAR RD LIGHTS WB
Reactive Defect Recorded 09/11/2021 10:54:34									
D-NE21238462535	0m	0m	TRAFFIC_SIGNAL S	Other (OTHR)	CAT 1	07/12/2021	Completed Defects	09/11/2021	A90, Dundee, Forfar Rd (A90) / Claverhouse Road
Reactive Defect Recorded 12/11/2021 15:33:23									
D-NE21238463813	0m	0m	TRAFFIC_SIGNAL S	Other (OTHR)	CAT 1	07/12/2021	Completed Defects	09/11/2021	A90, Dundee,
Reactive Defect Recorded 06/12/2021 12:08:19									
D-NE21238486058	0m	0m	TRAFFIC_SIGNAL S	Lamp failure (LAMP)	CAT 1	03/01/2022	Completed Defects	06/12/2021	A90, Kingsway/Forfar Road
D-NE21238486060	0m	0m	TRAFFIC_SIGNAL S	Condition of buttons / detectors (CBDT)	CAT 1	03/01/2022	Completed Defects	06/12/2021	A90, Dundee, Kingsway/Forfar Road VXT52 A90, Dundee, Claverhouse/Fintry ST800 VXT53
Reactive Defect Recorded 06/01/2022 15:01:13									
D-NE22238502327	0m	0m	TRAFFIC_SIGNAL S	Lamp failure (LAMP)	CAT 1	01/02/2022	Completed Defects	20/01/2022	A972, 13415/14, With:Start of 3-lane to A90 Junction, 252m , Left Off Carriageway 1, VXT52
Safety Patrol of A90 SAFETY PATROL on 03 February 2022									
NE7-800643-238550693	261m	0m	TREE	Overhanging/overgrown (OVER)	CAT 1	03/03/2022	Awaiting CCMS Permanent Date	11/02/2022	@154 KINGSWAY W/B

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE7-800643-238550694	211m	0m	TREE	Overhanging/overgrown (OVER)	CAT 1	03/03/2022	Completed Defects	11/02/2022	AT FORFAR RD LIGHTS W/B
Reactive Defect Recorded 11/02/2022 10:28:10									
D-NE22238558591	0m	0m	TRAFFIC_SIGNALS	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A972, 13415/14, With:Start of 3-lane to A90 Junction, 252m , Left Off Carriageway 1, VXT52
Reactive Defect Recorded 07/03/2022 15:26:04									
D-NE22238601550	0m	0m	TRAFFIC_SIGNALS	Condition poles / caps / heads / boards (PLCD)	CAT 1	29/03/2022	Completed Defects	01/03/2022	A90, Dundee, Kingsway/forfar road
Reactive Defect Recorded 08/04/2022 11:53:01									
D-NE22238646451	0m	0m	TRAFFIC_SIGNALS	Lamp failure (LAMP)	CAT 1	04/05/2022	Completed Defects	07/04/2022	A90, DUNDEE
D-NE22238646453	0m	0m	TRAFFIC_SIGNALS	Condition of buttons / detectors (CBDT)	CAT 1	04/05/2022	Completed Defects	07/04/2022	A90, DUNDEE
Safety Inspection of A90 SAFETY INSPECTION on 23 May 2022									
NE7-859943-238772043	211m	0m	BOLLARDS	Obscured sign (OBSG)	CAT 1	24/05/2022	Completed Defects	23/05/2022	@ FORFAR RD JCT W/B
Reactive Defect Recorded 01/06/2022 15:56:04									
D-NE22238793062	0m	0m	TRAFFIC_SIGNALS	Condition of buttons / detectors (CBDT)	CAT 1	21/06/2022	Completed Defects	27/05/2022	A90 DUNDEE
Reactive Defect Recorded 01/08/2022 09:27:43									
D-NE22238885300	0m	0m	TRAFFIC_SIGNALS	Alignment or obscuration (ALOB)	CAT 1	29/08/2022	Awaiting CCMS Permanent Date	01/01/9999	A90, Dundee
Reactive Defect Recorded 08/08/2022 12:40:40									
D-NE22238894551	0m	0m	DETECTOR_LOOP	Condition of loop / feeder (CLOF)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A90, Dundee

Location	Task	Asset Id or Section - Chainage & Asset Type	Defect Information	Status	Defects Raised	Defect Action	Repair Date
A972 13415/12 - With: Pitkerro Rd Rbt to Start of 3-lane c/way	Total						0
	1205091 Safety Patrol A90/A92/A972 (R) - Safety Patrol on 21/10/2022	Total		redacted 11(2)			0
		No Defects Recorded					0
	1205092 Safety Patrol A90/A92/A972 (R) - Safety Patrol on 28/10/2022	Total		redacted 11(2)			0
		No Defects Recorded					0
	1205093 Safety Patrol A90/A92/A972 (R) - Safety Patrol on 07/11/2022	Total		redacted 11(2)			0
		No Defects Recorded					0
	1205094 Safety Patrol A90/A92/A972 (R) - Safety Patrol on 11/11/2022	Total		redacted 11(2)			0
		No Defects Recorded					0
	1205095 Safety Patrol A90/A92/A972 (R) - Safety Patrol on 18/11/2022	Total		redacted 11(2)			0
		No Defects Recorded					0
	1205096 Safety Patrol A90/A92/A972 (R) - Safety Patrol on 28/11/2022	Total		redacted 11(2)			0
		No Defects Recorded					0
	1205097 Safety Patrol A90/A92/A972 (R) - Safety Patrol on 05/12/2022	Total		redacted 11(2)			0
		No Defects Recorded					0
	1205098 Safety Patrol A90/A92/A972 (R) - Safety Patrol on 09/12/2022	Total		redacted 11(2)			0
		No Defects Recorded					0
	1205100 Safety Inspection A90/A92/A972 (R) - Safety Inspection on 13/09/2022	Total		redacted 11(2)			0
		No Defects Recorded					0
	1205106 Safety Inspection A90/A92/A972 (R) - Safety Inspection on 25/10/2022	Total		redacted 11(2)			0
		No Defects Recorded					0
	1205107 Safety Inspection A90/A92/A972 (R) - Safety Inspection on 01/11/2022	Total		redacted 11(2)			0
		No Defects Recorded					0
	1205108 Safety Inspection A90/A92/A972 (R) - Safety Inspection on 10/11/2022	Total		redacted 11(2)			0
		No Defects Recorded					0
	1205109 Safety Inspection A90/A92/A972 (R) - Safety Inspection on 15/11/2022	Total		redacted 11(2)			0
		No Defects Recorded					0
	1205110 Safety Inspection A90/A92/A972 (R) - Safety Inspection on 22/11/2022	Total		redacted 11(2)			0
		No Defects Recorded					0
	1205111 Safety Inspection A90/A92/A972 (R) - Safety Inspection on 29/11/2022	Total		redacted 11(2)			0
		No Defects Recorded					0
	1205112 Safety Inspection A90/A92/A972 (R) - Safety Inspection on 06/12/2022	Total		redacted 11(2)			0
		No Defects Recorded					0
	1205216 Safety Inspection A90/A92/A972 (R) - Safety Inspection on 13/12/2022	Total		redacted 11(2)			0
		No Defects Recorded					0
	1205308 Safety Inspection A90/A92/A972 (R) - Safety Inspection on 20/12/2022	Total		redacted 11(2)			0
		No Defects Recorded					0
	1205572 Blair - A90 Dundee to Aberdeen/A92/A972 - Safety Patrol (JH) - Safety Patrol on 16/09/2022	Total		redacted 11(2)			0
		No Defects Recorded					0
	1337765 A90,A972,A92 Safety Patrol - Safety Patrol on 16/12/2022	Total		redacted 11(2)			0
		No Defects Recorded					0
	1337787 A90,A92,A972 Safety patrol 23.12.2022 - Safety Patrol on 23/12/2022	Total		redacted 11(2)			0
		No Defects Recorded					0
	1337904 A90,A92,A972 Safety inspection 27.12.2022 - Safety Inspection on 27/12/2022	Total		redacted 11(2)			0
		No Defects Recorded					0
	1337958 A90,A972,A92 Safety patrol - Safety Patrol on 30/12/2022	Total		redacted 11(2)			0
		No Defects Recorded					0
	1337971 A90,A972,A92 Safety inspection 03.01.2023 - Safety Inspection on 03/01/2023	Total		redacted 11(2)			0
		No Defects Recorded					0
	1338039 A90,A972,A92 Sfety patrol - Safety Patrol on 06/01/2023	Total		redacted 11(2)			0
		No Defects Recorded					0
	1338061 A90/A972/A92 Safety Inspection - Safety Inspection on 10/01/2023	Total		redacted 11(2)			0
		No Defects Recorded					0
	1338174 A90/A972 Safety Patrol - Safety Patrol on 13/01/2023	Total		redacted 11(2)			0
		No Defects Recorded					0
	1338505 A90/A972/A92 Safety Inspection - Safety Inspection on 17/01/2023	Total		redacted 11(2)			0
		No Defects Recorded					0
	1338510 A90/A972/A92 Safety Patrol - Safety Patrol on 20/01/2023	Total		redacted 11(2)			0
		No Defects Recorded					0
	1338706 A90/A972/A92 Safety Inspection - Safety Inspection on 24/01/2023	Total		redacted 11(2)			0
		No Defects Recorded					0
	1338792 A90/A972/A92 Safety Patrol - Safety Patrol on 27/01/2023	Total		redacted 11(2)			0
		No Defects Recorded					0
	1338851 A90/A92/A972 Safety Inspection - Safety Inspection on 31/01/2023	Total		redacted 11(2)			0
		No Defects Recorded					0
	1339089 A90/A972/A92 Safety Patrol - Safety Patrol on 03/02/2023	Total		redacted 11(2)			0
		No Defects Recorded					0

A972 13415/13 - Against: A90 Junction to Pitkerro Rd Rbt

1339136 A90/A972/A92 Safety Inspection - Safety Inspection on 07/02/2023	Total	redacted 11(2)	0
	No Defects Recorded		0
1339233 A90/A972/A92 Safety Patrol - Safety Patrol on 10/02/2023	Total	redacted 11(2)	0
	No Defects Recorded		0
1339291 A90/A972/A92 Safety Inspection - Safety Inspection on 14/02/2023	Total	redacted 11(2)	0
	No Defects Recorded		0
1339430 A90/A972/A902 Safety Patrol - Safety Patrol on 17/02/2023	Total	redacted 11(2)	0
	No Defects Recorded		0
1339469 A90/A972/A92 Safety Inspection - Safety Inspection on 21/02/2023	Total	redacted 11(2)	0
	No Defects Recorded		0
1339474 A90/A972/A92 Safety Patrol - Safety Patrol on 24/02/2023	Total	redacted 11(2)	0
	No Defects Recorded		0
Total			
1205091 Safety Patrol A90/A92/A972 (R) - Safety Patrol on 21/10/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1205092 Safety Patrol A90/A92/A972 (R) - Safety Patrol on 28/10/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1205093 Safety Patrol A90/A92/A972 (R) - Safety Patrol on 07/11/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1205094 Safety Patrol A90/A92/A972 (R) - Safety Patrol on 11/11/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1205095 Safety Patrol A90/A92/A972 (R) - Safety Patrol on 18/11/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1205096 Safety Patrol A90/A92/A972 (R) - Safety Patrol on 28/11/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1205097 Safety Patrol A90/A92/A972 (R) - Safety Patrol on 05/12/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1205098 Safety Patrol A90/A92/A972 (R) - Safety Patrol on 09/12/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1205100 Safety Inspection A90/A92/A972 (R) - Safety Inspection on 13/09/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1205106 Safety Inspection A90/A92/A972 (R) - Safety Inspection on 25/10/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1205107 Safety Inspection A90/A92/A972 (R) - Safety Inspection on 01/11/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1205108 Safety Inspection A90/A92/A972 (R) - Safety Inspection on 10/11/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1205109 Safety Inspection A90/A92/A972 (R) - Safety Inspection on 15/11/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1205110 Safety Inspection A90/A92/A972 (R) - Safety Inspection on 22/11/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1205111 Safety Inspection A90/A92/A972 (R) - Safety Inspection on 29/11/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1205112 Safety Inspection A90/A92/A972 (R) - Safety Inspection on 06/12/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1205216 Safety Inspection A90/A92/A972 (R) - Safety Inspection on 13/12/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1205308 Safety Inspection A90/A92/A972 (R) - Safety Inspection on 20/12/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1205572 Blair - A90 Dundee to Aberdeen/A92/A972 - Safety Patrol (JH) - Safety Patrol on 16/09/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1337765 A90,A972,A92 Safety Patrol - Safety Patrol on 16/12/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1337787 A90,A92,A972 Safety patrol 23.12.2022 - Safety Patrol on 23/12/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1337904 A90,A92,A972 Safety inspection 27.12.2022 - Safety Inspection on 27/12/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1337958 A90,A972,A92 Safety patrol - Safety Patrol on 30/12/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1337971 A90,A972,A92 Safety inspection 03.01.2023 - Safety Inspection on 03/01/2023	Total	redacted 11(2)	0
	No Defects Recorded		0
1338039 A90,A972,A92 Sfty patrol - Safety Patrol on 06/01/2023	Total	redacted 11(2)	0
	No Defects Recorded		0
1338061 A90/A972/A92 Safety Inspection - Safety Inspection on 10/01/2023	Total	redacted 11(2)	0
	No Defects Recorded		0
1338174 A90/A972 Safety Patrol - Safety Patrol on 13/01/2023	Total	redacted 11(2)	0
	No Defects Recorded		0
1338505 A90/A972/A92 Safety Inspection - Safety Inspection on 17/01/2023	Total	redacted 11(2)	0
	No Defects Recorded		0

1338510 A90/A972/A92 Safety Patrol - Safety Patrol on 20/01/2023	No Defects Recorded		0
	Total	redacted 11(2)	0
1338706 A90/A972/A92 Safety Inspection - Safety Inspection on 24/01/2023	No Defects Recorded		0
	Total	redacted 11(2)	0
1338792 A90/A972/A92 Safety Patrol - Safety Patrol on 27/01/2023	No Defects Recorded		0
	Total	redacted 11(2)	0
1338851 A90/A92/A972 Safety Inspection - Safety Inspection on 31/01/2023	No Defects Recorded		0
	Total	redacted 11(2)	0
1339089 A90/A972/A92 Safety Patrol - Safety Patrol on 03/02/2023	No Defects Recorded		0
	Total	redacted 11(2)	0
1339136 A90/A972/A92 Safety Inspection - Safety Inspection on 07/02/2023	No Defects Recorded		0
	Total	redacted 11(2)	0
1339233 A90/A972/A92 Safety Patrol - Safety Patrol on 10/02/2023	No Defects Recorded		0
	Total	redacted 11(2)	0
1339291 A90/A972/A92 Safety Inspection - Safety Inspection on 14/02/2023	No Defects Recorded		0
	Total	redacted 11(2)	0
1339430 A90/A972/A902 Safety Patrol - Safety Patrol on 17/02/2023	No Defects Recorded		0
	Total	redacted 11(2)	0
1339469 A90/A972/A92 Safety Inspection - Safety Inspection on 21/02/2023	No Defects Recorded		0
	Total	redacted 11(2)	0
1339474 A90/A972/A92 Safety Patrol - Safety Patrol on 24/02/2023	No Defects Recorded		0
	Total	redacted 11(2)	0
	No Defects Recorded		0

Applied filters:SectionSlicer is 13415/12 - With: Pitkerro Rd Rbt to Start of 3-lane c/way or 13415/13 - Against: A90 Junction to Pitkerro Rd RbtInspection Activity is Safety Inspection or Safety PatrolDate is on or after 01/04/2022 00:00:00 and is before 01/03/2023 00:00:00

Location	Task	Asset Id or Section - Chainage & Asset Type	Defect Information	Status	Defects Raised	Defect Action	Repair Date
A972 13415/13 - Against: A90 Junction to Pitkerro Rd Rbt	Total				0		
	1205091 Safety Patrol A90/A92/A972 (R) - Safety Patrol on 21/10/2022	Total		George Duncan	0		
		No Defects Recorded			0		
	1205092 Safety Patrol A90/A92/A972 (R) - Safety Patrol on 28/10/2022	Total		Dylan Clemison NE	0		
		No Defects Recorded			0		
	1205093 Safety Patrol A90/A92/A972 (R) - Safety Patrol on 07/11/2022	Total		Blair Shaw	0		
		No Defects Recorded			0		
	1205094 Safety Patrol A90/A92/A972 (R) - Safety Patrol on 11/11/2022	Total		Dylan Clemison NE	0		
		No Defects Recorded			0		
	1205095 Safety Patrol A90/A92/A972 (R) - Safety Patrol on 18/11/2022	Total		Dylan Clemison NE	0		
		No Defects Recorded			0		
	1205096 Safety Patrol A90/A92/A972 (R) - Safety Patrol on 28/11/2022	Total		Dylan Clemison NE	0		
		No Defects Recorded			0		
	1205097 Safety Patrol A90/A92/A972 (R) - Safety Patrol on 05/12/2022	Total		George Duncan	0		
		No Defects Recorded			0		
	1205098 Safety Patrol A90/A92/A972 (R) - Safety Patrol on 09/12/2022	Total		Dylan Clemison NE	0		
		No Defects Recorded			0		
	1205100 Safety Inspection A90/A92/A972 (R) - Safety Inspection on 13/09/2022	Total		Blair Shaw	0		
		No Defects Recorded			0		
	1205106 Safety Inspection A90/A92/A972 (R) - Safety Inspection on 25/10/2022	Total		Blair Shaw	0		
		No Defects Recorded			0		
	1205107 Safety Inspection A90/A92/A972 (R) - Safety Inspection on 01/11/2022	Total		Dylan Clemison NE	0		
		No Defects Recorded			0		
	1205108 Safety Inspection A90/A92/A972 (R) - Safety Inspection on 10/11/2022	Total		Dylan Clemison NE	0		
		No Defects Recorded			0		
	1205109 Safety Inspection A90/A92/A972 (R) - Safety Inspection on 15/11/2022	Total		George Duncan	0		
		No Defects Recorded			0		
	1205110 Safety Inspection A90/A92/A972 (R) - Safety Inspection on 22/11/2022	Total		George Duncan	0		
		No Defects Recorded			0		
	1205111 Safety Inspection A90/A92/A972 (R) - Safety Inspection on 29/11/2022	Total		George Duncan	0		
		No Defects Recorded			0		
	1205112 Safety Inspection A90/A92/A972 (R) - Safety Inspection on 06/12/2022	Total		Dylan Clemison NE	0		
		No Defects Recorded			0		
	1205216 Safety Inspection A90/A92/A972 (R) - Safety Inspection on 13/12/2022	Total		George Duncan	0		
		No Defects Recorded			0		
	1205308 Safety Inspection A90/A92/A972 (R) - Safety Inspection on 20/12/2022	Total		Blair Shaw	0		
		No Defects Recorded			0		
	1205572 Blair - A90 Dundee to Aberdeen/A92/A972 - Safety Patrol (JH) - Safety Patrol on 16/09/2022	Total		Bradie Heggie	0		
		No Defects Recorded			0		
	1337765 A90,A92,A92 Safety Patrol - Safety Patrol on 16/12/2022	Total		Blair Shaw	0		
		No Defects Recorded			0		
	1337787 A90,A92,A972 Safety patrol 23.12.2022 - Safety Patrol on 23/12/2022	Total		Blair Shaw	0		
		No Defects Recorded			0		
	1337904 A90,A92,A972 Safety inspection 27.12.2022 - Safety Inspection on 27/12/2022	Total		George Duncan	0		
		No Defects Recorded			0		
	1337958 A90,A972,A92 Safety patrol - Safety Patrol on 30/12/2022	Total		George Duncan	0		
		No Defects Recorded			0		
	1337971 A90,A972,A92 Safety inspection 03.01.2023 - Safety Inspection on 03/01/2023	Total		George Duncan	0		
		No Defects Recorded			0		
	1338039 A90,A972,A92 Sfety patrol - Safety Patrol on 06/01/2023	Total		George Duncan	0		
		No Defects Recorded			0		
	1338061 A90/A972/A92 Safety Inspection - Safety Inspection on 10/01/2023	Total		George Duncan	0		
		No Defects Recorded			0		
	1338174 A90/A972 Safety Patrol - Safety Patrol on 13/01/2023	Total		Dylan Clemison NE	0		
		No Defects Recorded			0		
	1338505 A90/A972/A92 Safety Inspection - Safety Inspection on 17/01/2023	Total		Dylan Clemison NE	0		
		No Defects Recorded			0		
	1338510 A90/A972/A92 Safety Patrol - Safety Patrol on 20/01/2023	Total		Dylan Clemison NE	0		
		No Defects Recorded			0		
	1338706 A90/A972/A92 Safety Inspection - Safety Inspection on 24/01/2023	Total		George Duncan	0		
		No Defects Recorded			0		
	1338792 A90/A972/A92 Safety Patrol - Safety Patrol on 27/01/2023	Total		George Duncan	0		
		No Defects Recorded			0		
	1338851 A90/A92/A972 Safety Inspection - Safety Inspection on 31/01/2023	Total		George Duncan	0		
		No Defects Recorded			0		
	1339089 A90/A972/A92 Safety Patrol - Safety Patrol on 03/02/2023	Total		George Duncan	0		
		No Defects Recorded			0		
	1339136 A90/A972/A92 Safety Inspection - Safety Inspection on 07/02/2023	Total		George Duncan	0		
		No Defects Recorded			0		
	1339233 A90/A972/A92 Safety Patrol - Safety Patrol on 10/02/2023	Total		George Duncan	0		
		No Defects Recorded			0		
	1339291 A90/A972/A92 Safety Inspection - Safety Inspection on 14/02/2023	Total		George Duncan	0		
		No Defects Recorded			0		
	1339430 A90/A972/A902 Safety Patrol - Safety Patrol on 17/02/2023	Total		Blair Shaw	0		
		No Defects Recorded			0		
	1339469 A90/A972/A92 Safety Inspection - Safety Inspection on 21/02/2023	Total		Blair Shaw	0		
		No Defects Recorded			0		
	1339474 A90/A972/A92 Safety Patrol - Safety Patrol on 24/02/2023	Total		Blair Shaw	0		
		No Defects Recorded			0		

Applied filters:SectionSlicer is 13415/13 - Against: A90 Junction to Pitkerro Rd RbtInspection Activity is Footway category A - Visual Condition, Footway category B - Visual Condition, Safety Inspection, or Safety Patrol