

Location	Task	Asset Id or Section - Chainage & Asset Type	Defect Information	Status	Defects Raised	Defect Action	Repair Date
MB 14215/06 - AGAINST JCT 11 EB OFF SLIP TO ENTRY SLIP	Total				4		
	1140670 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 06/02/2023	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1140697 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 13/02/2023	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1161500 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 20/02/2023	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1163013 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 27/02/2023	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1163228 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 06/03/2023	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1163343 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 13/03/2023	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1163374 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 20/03/2023	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1163436 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 27/03/2023	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1204993 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 03/04/2023	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1205212 M8 Safety Inspection 06-09-22 - Safety Inspection on 06/09/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1205253 9-9-22 redacted 11(2) M8 Polmadie Safety Patrol - Safety Patrol on 13/09/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1205256 M8 Polmadie - Safety Inspection (redacted 11(2)) - Safety Inspection on 09/09/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1205257 M8 Polmadie - Safety Inspection (redacted 11(2)) (R) - Safety Inspection on 16/09/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1205258 M8 Polmadie - Safety Inspection (redacted 11(2)) (R) - Safety Inspection on 20/09/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1205259 M8 Polmadie - Safety Inspection (redacted 11(2)) (R) - Safety Inspection on 23/09/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1205729 M8 East Safety Inspection 27/9/2022 - Safety Inspection on 27/09/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1205758 AD HOC - M8 Safety Patrol 30-9-22 (redacted 11(2)) - Safety Patrol on 30/09/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1206145 NSW M8 Polmadie Safety Inspection Route (Mon) - Safety Inspection on 04/10/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1206146 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 11/10/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1206148 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 21/11/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1206149 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 05/12/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1206150 NSW M8 Polmadie Safety Patrol Route (Thur) - Safety Patrol on 07/10/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1206151 M8 Polmadie, Safety Patrol, 12/01/23 - Safety Patrol on 12/01/2023	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1206152 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 23/02/2023	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1206155 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 10/11/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1206156 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 17/11/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1206157 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 24/11/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1206159 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 08/12/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1206160 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 15/12/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1206161 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 22/12/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1206162 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 29/12/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1206163 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 05/01/2023	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1206305 NSW M8 Polmadie Night Inspection Route (14 day) - Night Time Illuminated Safety Inspection on 05/10/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1206306 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 16/11/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1206308 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 02/11/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1206519 M8 Polmadie, Safety Inspection, 18/10/22 - Safety Inspection on 18/10/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1206523 NSW M8 Polmadie Night Time Illuminated Safety Inspection Route (R) - Night Time Illuminated Safety Inspection on 19/10/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1206566 (Ad-Hoc) M8 Polmadie Safety Inspection - Safety Inspection on 24/10/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1206567 (Ad-Hoc) M8 Polmadie, Safety Patrol - Safety Patrol on 27/10/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1206590 M8 Polmadie - Safety Patrol, Oct 21 - Safety Patrol on 21/10/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1206696 M8 East Road markings night visual condition - Road Marking Hatched - Visual Condition on 28/10/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1206696 M8 East Road markings night visual condition - Road Marking Hatched - Visual Condition on 29/10/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1206696 M8 East Road markings night visual condition - Road Marking Longitudinal - Visual Condition on 28/10/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1206696 M8 East Road markings night visual condition - Road Marking Longitudinal - Visual Condition on 29/10/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1206696 M8 East Road markings night visual condition - Road Marking Transverse & Special - Visual Condition on 28/10/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1206696 M8 East Road markings night visual condition - Road Marking Transverse & Special - Visual Condition on 29/10/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1206706 AD-HOC M8 East Polmadie safety inspection (redacted 11(2)) - Safety Inspection on 31/10/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1206751 M8 Safety Patrol, Nov 3 - Safety Patrol on 03/11/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1206823 AD-HOC M8 Polmadie Safety Inspection 7-11-22 - Safety Inspection on 07/11/2022	Total		redacted 11(2)	0		
		No Defects Recorded			0		
	1206935 AD-HOC M8 Safety Inspection 14-11-22 (redacted 11(2)) - Safety Inspection on 14/11/2022	Total		redacted 11(2)	0		
	No Defects Recorded			0			
1207028 NSW M8 Polmadie Safety Inspection Route (Mon) - Safety Inspection on 12/12/2022	Total		redacted 11(2)	0			
	No Defects Recorded			0			
1207029 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 19/12/2022	Total		redacted 11(2)	0			
	No Defects Recorded			0			

1339199 M8 jct 10 to 15 gullies catchpits and manholes - Manhole - Surface Visual Condition on 20/02/2023	Total No Defects Recorded	redacted 11(2)	0	
1339224 M8 Polmadie Safety Patrol - Safety Patrol on 09/02/2023	Total No Defects Recorded	redacted 11(2)	0	
1339386 AD-HOC M8 Polmadie Safety Patrol 16-2-23 (redacted 11(2)) - Safety Patrol on 16/02/2023	Total No Defects Recorded	redacted 11(2)	0	
1339482 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 08/03/2023	Total No Defects Recorded	redacted 11(2)	0	
1340962 02/03/2023 - General Inspection M8 - Highmast Light General Inspection on 03/03/2023	Total No Defects Recorded	redacted 11(2)	3	
1340962 02/03/2023 - General Inspection M8 - Highmast Light General Inspection on 07/03/2023	- Asset : 1442103 High Mast Lights (Span) - Defect Ref : D-22-SW-18407 - Asset : 1442103 High Mast Lights (Span) - Defect Ref : D-22-SW-18408 - Asset : 1442103 High Mast Lights (Span) - Defect Ref : D-22-SW-18409 Total No Defects Recorded	N No Action Monitor Only - N - CAT2 Open Open Open N No Action Monitor Only - N - CAT2 redacted 11(2)	1 1 1 1 1 3	Cat 2 Action Cat 2 Action Cat 2 Action Cat 2 Action
1340962 02/03/2023 - General Inspection M8 - Retaining Wall General Inspection on 08/03/2023	- Asset : 1442103 High Mast Lights (Span) - Defect Ref : D-22-SW-18407 - Asset : 1442103 High Mast Lights (Span) - Defect Ref : D-22-SW-18408 - Asset : 1442103 High Mast Lights (Span) - Defect Ref : D-22-SW-18409 Total No Defects Recorded	N No Action Monitor Only - N - CAT2 Open Open Open N No Action Monitor Only - N - CAT2 redacted 11(2)	1 1 1 1 1 3	Cat 2 Action Cat 2 Action Cat 2 Action Cat 2 Action
1340962 02/03/2023 - General Inspection M8 - Signs Signals General Inspection on 03/03/2023	- Asset : 1442103 High Mast Lights (Span) - Defect Ref : D-22-SW-18407 - Asset : 1442103 High Mast Lights (Span) - Defect Ref : D-22-SW-18408 - Asset : 1442103 High Mast Lights (Span) - Defect Ref : D-22-SW-18409 Total No Defects Recorded	N No Action Monitor Only - N - CAT2 Open Open Open N No Action Monitor Only - N - CAT2 redacted 11(2)	1 1 1 1 1 3	Cat 2 Action Cat 2 Action Cat 2 Action Cat 2 Action
1340962 02/03/2023 - General Inspection M8 - Signs Signals General Inspection on 07/03/2023	- Asset : 1442103 High Mast Lights (Span) - Defect Ref : D-22-SW-18407 - Asset : 1442103 High Mast Lights (Span) - Defect Ref : D-22-SW-18408 - Asset : 1442103 High Mast Lights (Span) - Defect Ref : D-22-SW-18409 Total No Defects Recorded	N No Action Monitor Only - N - CAT2 Open Open Open N No Action Monitor Only - N - CAT2 redacted 11(2)	1 1 1 1 1 3	Cat 2 Action Cat 2 Action Cat 2 Action Cat 2 Action
1340969 M8 Polmadie safety patrol, 2nd March - Safety Patrol on 02/03/2023	Total No Defects Recorded	redacted 11(2)	0	
1341086 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 22/03/2023	Total No Defects Recorded	redacted 11(2)	0	
1341222 M8 Polmadie Safety Patrol - Safety Patrol on 09/03/2023	Total No Defects Recorded	redacted 11(2)	0	
1341440 M8 east safety patrol, 16th March - Safety Patrol on 16/03/2023	Total No Defects Recorded	redacted 11(2)	0	
1341694 M8 Polmadie Safety Patyrol - Safety Patrol on 23/03/2023	Total No Defects Recorded	redacted 11(2)	0	
1341921 M8 Polmadie Safety Patrol, 30th March - Safety Patrol on 30/03/2023	Total No Defects Recorded	redacted 11(2)	0	
1342162 NSW M8 Polmadie Night Inspection Route (28 day) - Night Time Illuminated Safety Inspection on 05/04/2023	Total No Defects Recorded	redacted 11(2)	0	
1342323 NSW M8 Polmadie Safety Patrol Route (Thur 06-04-23) - Safety Patrol on 06/04/2023	Total No Defects Recorded	redacted 11(2)	0	
763172 NSW M8 Polmadie Safety Patrol Route (R) - Safety Patrol on 14/10/2022	Total No Defects Recorded	redacted 11(2)	0	
763454 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 12/04/2022	Total No Defects Recorded	redacted 11(2)	0	
763455 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 18/04/2022	Total No Defects Recorded	redacted 11(2)	0	
763456 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 19/04/2022	Total No Defects Recorded	redacted 11(2)	0	
763457 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 25/04/2022	Total No Defects Recorded	redacted 11(2)	0	
763458 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 28/04/2022	Total No Defects Recorded	redacted 11(2)	0	
763459 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 02/05/2022	Total No Defects Recorded	redacted 11(2)	0	
763460 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 04/05/2022	Total No Defects Recorded	redacted 11(2)	0	
763461 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 09/05/2022	Total No Defects Recorded	redacted 11(2)	0	
763462 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 12/05/2022	Total No Defects Recorded	redacted 11(2)	0	
763463 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 16/05/2022	Total No Defects Recorded	redacted 11(2)	0	
763464 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 17/05/2022	Total No Defects Recorded	redacted 11(2)	0	
763465 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 23/05/2022	Total No Defects Recorded	redacted 11(2)	0	
763466 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 26/05/2022	Total No Defects Recorded	redacted 11(2)	0	
763516 NSW M8 Polmadie Safety Patrol Route (R) - Safety Patrol on 27/05/2022	Total No Defects Recorded	redacted 11(2)	0	
763520 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 31/05/2022	Total No Defects Recorded	redacted 11(2)	0	
763937 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 06/06/2022	Total No Defects Recorded	redacted 11(2)	0	
764008 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 07/06/2022	Total No Defects Recorded	redacted 11(2)	0	
912677 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 10/06/2022	Total No Defects Recorded	redacted 11(2)	0	
912721 NSW M8 Polmadie Night Inspection Route - Night Time Illuminated Safety Inspection on 19/05/2022	Total No Defects Recorded	redacted 11(2)	0	
912722 NSW M8 Polmadie Night Inspection Route (R) - Night Time Illuminated Safety Inspection on 15/06/2022	Total No Defects Recorded	redacted 11(2)	0	
912782 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 14/06/2022	Total No Defects Recorded	redacted 11(2)	0	
912818 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 17/06/2022	Total No Defects Recorded	redacted 11(2)	0	
942258 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 21/06/2022	Total No Defects Recorded	redacted 11(2)	0	
942296 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 27/06/2022	Total No Defects Recorded	redacted 11(2)	0	
942368 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 30/06/2022	Total No Defects Recorded	redacted 11(2)	0	
942396 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 01/07/2022	Total No Defects Recorded	redacted 11(2)	0	
951525 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 05/07/2022	Total No Defects Recorded	redacted 11(2)	1	
951593 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 12/07/2022	MB east bound junction 11 off to on slip lane 3, at sos box 662E - Asset : 14215/06 - 255 Carriageway - Defect Ref : D-22-SW-01519	Pothole - POTH - CAT1	Closed redacted 11(2)	1 0
951647 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 19/07/2022	Total No Defects Recorded	redacted 11(2)	0	
			0	Temporary, Deferred - 05/07/2022 Permanent - 30/07/2022

M8 14215/16 - AGAINST: SLIP RD OFF M8 EB AT JCT 11

951695 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 22/07/2022	Total	0	redacted 11(2)	0
951759 NSW M8 Polmadie Safety Patrol Route (R) - Safety Patrol on 08/07/2022	No Defects Recorded	0	redacted 11(2)	0
951815 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 26/07/2022	Total	0	redacted 11(2)	0
951871 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 29/07/2022	No Defects Recorded	0	redacted 11(2)	0
951893 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 02/08/2022	Total	0	redacted 11(2)	0
951986 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 05/08/2022	No Defects Recorded	0	redacted 11(2)	0
952014 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 09/08/2022	Total	0	redacted 11(2)	0
952062 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 12/08/2022	No Defects Recorded	0	redacted 11(2)	0
952085 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 16/08/2022	Total	0	redacted 11(2)	0
952115 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 19/08/2022	No Defects Recorded	0	redacted 11(2)	0
952174 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 23/08/2022	Total	0	redacted 11(2)	0
952205 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 29/08/2022	No Defects Recorded	0	redacted 11(2)	0
952220 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 01/09/2022	Total	0	redacted 11(2)	0
952257 NSW M8 Polmadie Safety Patrol Route (R) - Safety Patrol on 15/07/2022	No Defects Recorded	0	redacted 11(2)	0
952327 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 02/09/2022	Total	0	redacted 11(2)	0
952347 NSW M8 Polmadie Night Inspection Route 12/07/22 - Night Time Illuminated Safety Inspection on 13/07/2022	No Defects Recorded	0	redacted 11(2)	0
952348 NSW M8 Polmadie Night Inspection Route 09/08/22 - Night Time Illuminated Safety Inspection on 10/08/2022	Total	0	redacted 11(2)	0
952349 NSW M8 Polmadie Night Inspection Route 06/09/22 - Night Time Illuminated Safety Inspection on 07/09/2022	No Defects Recorded	0	redacted 11(2)	0
952377 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 09/01/2023	Total	0	redacted 11(2)	0
Total	No Defects Recorded	0	redacted 11(2)	6
1140670 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 06/02/2023	Total	0	redacted 11(2)	0
1140697 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 13/02/2023	No Defects Recorded	0	redacted 11(2)	0
1161500 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 20/02/2023	Total	0	redacted 11(2)	0
1163013 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 27/02/2023	No Defects Recorded	0	redacted 11(2)	0
1163228 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 06/03/2023	Total	0	redacted 11(2)	0
1163343 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 13/03/2023	No Defects Recorded	0	redacted 11(2)	0
1163374 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 20/03/2023	Total	0	redacted 11(2)	0
1163436 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 27/03/2023	No Defects Recorded	0	redacted 11(2)	0
1204993 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 03/04/2023	Total	0	redacted 11(2)	0
1205212 M8 Safety Inspection 06-09-22 - Safety Inspection on 06/09/2022	No Defects Recorded	0	redacted 11(2)	0
1205253 9-9-22 redacted 11(2) M8 Polmadie Safety Patrol - Safety Patrol on 13/09/2022	Total	0	redacted 11(2)	0
1205256 M8 Polmadie - Safety Inspection (redacted 11(2)) - Safety Inspection on 09/09/2022	No Defects Recorded	0	redacted 11(2)	0
1205257 M8 Polmadie - Safety Inspection (redacted 11(2)) (R) - Safety Inspection on 16/09/2022	Total	0	redacted 11(2)	0
1205258 M8 Polmadie - Safety Inspection (redacted 11(2)) (R) - Safety Inspection on 20/09/2022	No Defects Recorded	0	redacted 11(2)	1
1205259 M8 Polmadie - Safety Inspection (redacted 11(2)) (R) - Safety Inspection on 23/09/2022	Total	0	redacted 11(2)	0
1205729 M8 East Safety Inspection 27/9/2022 - Safety Inspection on 27/09/2022	No Defects Recorded	0	redacted 11(2)	0
1205758 AD HOC - M8 Safety Patrol 30-9-22 (redacted 11(2)) - Safety Patrol on 30/09/2022	Total	0	redacted 11(2)	0
1206145 NSW M8 Polmadie Safety Inspection Route (Mon) - Safety Inspection on 04/10/2022	No Defects Recorded	0	redacted 11(2)	0
1206146 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 11/10/2022	Total	0	redacted 11(2)	0
1206148 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 21/11/2022	No Defects Recorded	0	redacted 11(2)	0
1206149 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 05/12/2022	Total	0	redacted 11(2)	0
1206150 NSW M8 Polmadie Safety Patrol Route (Thur) - Safety Patrol on 07/10/2022	No Defects Recorded	0	redacted 11(2)	0
1206151 M8 Polmadie, Safety Patrol, 12/01/23 - Safety Patrol on 12/01/2023	Total	0	redacted 11(2)	0
1206152 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 23/02/2023	No Defects Recorded	0	redacted 11(2)	0
1206155 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 10/11/2022	Total	0	redacted 11(2)	0
1206156 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 17/11/2022	No Defects Recorded	0	redacted 11(2)	0
1206157 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 24/11/2022	Total	0	redacted 11(2)	0
1206159 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 08/12/2022	No Defects Recorded	0	redacted 11(2)	0
1206160 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 15/12/2022	Total	0	redacted 11(2)	0
1206161 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 22/12/2022	No Defects Recorded	0	redacted 11(2)	0
1206162 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 29/12/2022	Total	0	redacted 11(2)	0
1206163 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 05/01/2023	No Defects Recorded	0	redacted 11(2)	0
1206305 NSW M8 Polmadie Night Inspection Route (14 day) - Night Time Illuminated Safety Inspection on 05/10/2022	Total	0	redacted 11(2)	0

M8 Jct 11 E/B off slip - Asset : 14215/16 - 47 Carriageway - Defect Ref : D-22-SW-03480

Failed Patch/Trench - PATH - CAT1

Closed 1 Temporary, Deferred - 20/09/2022
Permanent 13/10/2022

1206306 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety inspection on 16/11/2022	No Defects Recorded Total		0		
1206308 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety inspection on 02/11/2022	No Defects Recorded Total		0		
1206519 M8 Polmadie, Safety Inspection. 18/10/22 - Safety Inspection on 18/10/2022	No Defects Recorded Total		0		
1206523 NSW M8 Polmadie Night Time Illuminated Safety Inspection Route (R) - Night Time Illuminated Safety inspection on 19/10/2022	No Defects Recorded Total		0		
1206566 (Ad-Hoc) M8 Polmadie Safety Inspection - Safety Inspection on 24/10/2022	No Defects Recorded Total		0		
1206567 (Ad-Hoc) M8 Polmadie, Safety Patrol - Safety Patrol on 27/10/2022	No Defects Recorded Total		0		
1206590 M8 Polmadie - Safety Patrol, Oct 21 - Safety Patrol on 21/10/2022	No Defects Recorded Total		0		
1206696 M8 East Road markings night visual condition - Road Marking Hatched - Visual Condition on 28/10/2022	No Defects Recorded Total		0		
1206696 M8 East Road markings night visual condition - Road Marking Hatched - Visual Condition on 29/10/2022	- Asset : 1342204 Road Marking Longitudinal - Defect Ref : D-22-SW-05101 Total	Missing - MISS - CAT2	1		Cat 2 Action
1206696 M8 East Road markings night visual condition - Road Marking Longitudinal - Visual Condition on 28/10/2022	- Asset : 1342204 Road Marking Longitudinal - Defect Ref : D-22-SW-05101 Total	Missing - MISS - CAT2	1		Cat 2 Action
1206696 M8 East Road markings night visual condition - Road Marking Longitudinal - Visual Condition on 29/10/2022	- Asset : 1342204 Road Marking Longitudinal - Defect Ref : D-22-SW-05101 Total	Missing - MISS - CAT2	1		Cat 2 Action
1206696 M8 East Road markings night visual condition - Road Marking Transverse & Special - Visual Condition on 28/10/2022	- Asset : 1342204 Road Marking Longitudinal - Defect Ref : D-22-SW-05101 Total	Missing - MISS - CAT2	1		Cat 2 Action
1206696 M8 East Road markings night visual condition - Road Marking Transverse & Special - Visual Condition on 29/10/2022	- Asset : 1342204 Road Marking Longitudinal - Defect Ref : D-22-SW-05101 Total	Missing - MISS - CAT2	1		Cat 2 Action
1206706 AD-HOC M8 East Polmadie safety inspection (redacted 11(2)) - Safety inspection on 31/10/2022	No Defects Recorded Total		0		
1206751 M8 Safety Patrol, Nov 3 - Safety Patrol on 03/11/2022	No Defects Recorded Total		0		
1206823 AD-HOC M8 Polmadie Safety Inspection 7-11-22 - Safety inspection on 07/11/2022	No Defects Recorded Total		0		
1206935 AD-HOC M8 Safety Inspection 14-11-22 (redacted 11(2)) - Safety inspection on 14/11/2022	M8 E/B J11 off-slip, centre - Asset : 14215/16 - 20 Carriageway - Defect Ref : D-22-SW-05343 Total	Pothole - POTH - CAT1	1	Temporary, Deferred - 08/11/2022	Permanent - 29/11/2022
1207028 NSW M8 Polmadie Safety Inspection Route (Mon) - Safety Inspection on 12/12/2022	No Defects Recorded Total		0		
1207029 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety inspection on 19/12/2022	No Defects Recorded Total		0		
1207097 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety inspection on 14/12/2022	No Defects Recorded Total		0		
1207102 NSW M8 Safety Routine Electrical Inspection - Cable Chamber - Routine Electrical Inspection on 28/11/2022	No Defects Recorded Total		0		
1207102 NSW M8 Safety Routine Electrical Inspection - Cable Chamber - Routine Electrical Inspection on 29/11/2022	No Defects Recorded Total		0		
1207102 NSW M8 Safety Routine Electrical Inspection - Electrical Component of Bollard - Routine Electrical Inspection on 29/11/2022	No Defects Recorded Total		0		
1207102 NSW M8 Safety Routine Electrical Inspection - Electrical Component of Cabinet/Pillar - Routine Electrical Inspection on 28/11/2022	No Defects Recorded Total		0		
1207102 NSW M8 Safety Routine Electrical Inspection - Electrical Component of Cabinet/Pillar - Routine Electrical Inspection on 29/11/2022	No Defects Recorded Total		0		
1207102 NSW M8 Safety Routine Electrical Inspection - Electrical Component of Traffic Sign - Routine Electrical Inspection on 28/11/2022	No Defects Recorded Total		0		
1207102 NSW M8 Safety Routine Electrical Inspection - Electrical Component of Traffic Sign - Routine Electrical Inspection on 29/11/2022	No Defects Recorded Total		0		
1207102 NSW M8 Safety Routine Electrical Inspection - Lighting Point - Routine Electrical Inspection on 28/11/2022	No Defects Recorded Total		0		
1207102 NSW M8 Safety Routine Electrical Inspection - Lighting Point - Routine Electrical Inspection on 29/11/2022	No Defects Recorded Total		0		
1207102 NSW M8 Safety Routine Electrical Inspection - Weather Station - Routine Electrical Inspection on 28/11/2022	No Defects Recorded Total		0		
1207108 Ad-Hoc M8 Safety Inspection - Safety Inspection on 28/11/2022	No Defects Recorded Total		0		
1337497 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety inspection on 28/12/2022	No Defects Recorded Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Cable Chamber - Routine Electrical Inspection on 11/12/2022	m8 jst11 offslip e/b - Asset : 1055160 Electrical - Traffic Sign - Defect Ref : D-22-SW-06297 Total	Lamp failures - LAMP - CAT1	1	Permanent	28/12/2022
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Cable Chamber - Routine Electrical Inspection on 12/12/2022	No Defects Recorded Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Cable Chamber - Routine Electrical Inspection on 13/12/2022	No Defects Recorded Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Cable Chamber - Routine Electrical Inspection on 16/12/2022	No Defects Recorded Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Cable Chamber - Routine Electrical Inspection on 17/12/2022	No Defects Recorded Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Bollard - Routine Electrical Inspection on 11/12/2022	No Defects Recorded Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Bollard - Routine Electrical Inspection on 13/12/2022	No Defects Recorded Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Bollard - Routine Electrical Inspection on 16/12/2022	No Defects Recorded Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Cabinet/Pillar - Routine Electrical Inspection on 09/12/2022	No Defects Recorded Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Cabinet/Pillar - Routine Electrical Inspection on 11/12/2022	No Defects Recorded Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Cabinet/Pillar - Routine Electrical Inspection on 12/12/2022	No Defects Recorded Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Cabinet/Pillar - Routine Electrical Inspection on 13/12/2022	No Defects Recorded Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Cabinet/Pillar - Routine Electrical Inspection on 14/12/2022	No Defects Recorded Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Cabinet/Pillar - Routine Electrical Inspection on 16/12/2022	No Defects Recorded Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Cabinet/Pillar - Routine Electrical Inspection on 17/12/2022	No Defects Recorded Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Cabinet/Pillar - Routine Electrical Inspection on 18/12/2022	No Defects Recorded Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Traffic Sign - Routine Electrical Inspection on 09/12/2022	No Defects Recorded Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Traffic Sign - Routine Electrical Inspection on 11/12/2022	No Defects Recorded Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Traffic Sign - Routine Electrical Inspection on 12/12/2022	No Defects Recorded Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Traffic Sign - Routine Electrical Inspection on 13/12/2022	No Defects Recorded Total		0		

1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Traffic Sign - Routine Electrical Inspection on 14/12/2022	No Defects Recorded Total	0	0	0
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Traffic Sign - Routine Electrical Inspection on 16/12/2022	No Defects Recorded Total	0	0	0
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Traffic Sign - Routine Electrical Inspection on 17/12/2022	No Defects Recorded Total	0	0	0
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Traffic Sign - Routine Electrical Inspection on 18/12/2022	No Defects Recorded Total	0	0	0
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Lighting Point - Routine Electrical Inspection on 11/12/2022	No Defects Recorded Total	0	0	0
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Lighting Point - Routine Electrical Inspection on 12/12/2022	No Defects Recorded Total	0	0	0
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Lighting Point - Routine Electrical Inspection on 13/12/2022	No Defects Recorded Total	0	0	0
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Lighting Point - Routine Electrical Inspection on 14/12/2022	No Defects Recorded Total	0	0	0
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Lighting Point - Routine Electrical Inspection on 16/12/2022	No Defects Recorded Total	0	0	0
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Lighting Point - Routine Electrical Inspection on 17/12/2022	No Defects Recorded Total	0	0	0
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Lighting Point - Routine Electrical Inspection on 18/12/2022	No Defects Recorded Total	0	0	0
1337501 M8 Safety patrol, Dec 1 - Safety Patrol on 02/12/2022	No Defects Recorded Total	0	0	0
1337670 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 26/12/2022	No Defects Recorded Total	0	0	0
1337672 M8 road sweeper - Litter/Refuse Sweeping on 13/04/2023	No Defects Recorded Total	0	0	0
1337812 Monday 23rd - M8 East - safety inspection. - Safety Inspection on 23/01/2023	No Defects Recorded Total	0	0	0
1337906 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 11/01/2023	No Defects Recorded Total	0	0	0
1337982 AD-HOC M8 Polmadie inspection 02/01/2023 - Safety Inspection on 02/01/2023	No Defects Recorded Total	0	0	0
1338066 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 25/01/2023	No Defects Recorded Total	0	0	0
1338498 M8 Polmadie, Safety Inspection, 16/01/23 - Safety Inspection on 17/01/2023	No Defects Recorded Total	0	0	0
1338520 Weather station inspections/validation - Weather Station - RCD Test on 17/01/2023	No Defects Recorded Total	0	0	0
1338520 Weather station inspections/validation - Weather Station - RCD Test on 18/01/2023	No Defects Recorded Total	0	0	0
1338520 Weather station inspections/validation - Weather Station - Visual Condition on 17/01/2023	No Defects Recorded Total	0	0	0
1338520 Weather station inspections/validation - Weather Station - Visual Condition on 18/01/2023	No Defects Recorded Total	0	0	0
1338601 M8 East Safety Patrol 19th Jan - Safety Patrol on 19/01/2023	No Defects Recorded Total	0	0	0
1338639 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 08/02/2023	No Defects Recorded Total	0	0	0
1338767 NSW M8 Polmadie Weather station BS7671, Routine Insp, RCD test and Visual Condition - Electrical Component of Cabinet/Pillar - Periodic Electrical Inspection and Testing - BS7671 on 27/01/2023	No Defects Recorded Total	0	0	0
1338767 NSW M8 Polmadie Weather station BS7671, Routine Insp, RCD test and Visual Condition - Weather Station - Periodic Electrical Inspection and Testing - BS7671 on 27/01/2023	No Defects Recorded Total	0	0	0
1338767 NSW M8 Polmadie Weather station BS7671, Routine Insp, RCD test and Visual Condition - Weather Station - RCD Test on 27/01/2023	No Defects Recorded Total	0	0	0
1338767 NSW M8 Polmadie Weather station BS7671, Routine Insp, RCD test and Visual Condition - Weather Station - Routine Electrical Inspection on 27/01/2023	No Defects Recorded Total	0	0	0
1338767 NSW M8 Polmadie Weather station BS7671, Routine Insp, RCD test and Visual Condition - Weather Station - Visual Condition on 27/01/2023	No Defects Recorded Total	0	0	0
1338782 M8 East, Safety Patrol, 26th Jan - Safety Patrol on 26/01/2023	No Defects Recorded Total	0	0	0
1338843 M8 Polmadie, Safety Inspection, 30/01/23 - Safety Inspection on 30/01/2023	No Defects Recorded Total	0	0	0
1339078 M8 West - Safety Patrol - 2nd Jan - Safety Patrol on 02/02/2023	No Defects Recorded Total	0	0	0
1339152 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 22/02/2023	No Defects Recorded Total	0	0	0
1339224 M8 Polmadie Safety Patrol - Safety Patrol on 09/02/2023	No Defects Recorded Total	0	0	0
1339386 AD-HOC M8 Polmadie Safety Patrol 16-2-23 (redacted 11(2)) - Safety Patrol on 16/02/2023	No Defects Recorded Total	0	0	0
1339482 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 08/03/2023	No Defects Recorded Total	0	0	0
1340969 M8 Polmadie safety patrol, 2nd March - Safety Patrol on 02/03/2023	No Defects Recorded Total	0	0	0
1341086 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 22/03/2023	No Defects Recorded Total	0	0	0
1341222 M8 Polmadie Safety Patrol - Safety Patrol on 09/03/2023	No Defects Recorded Total	0	0	0
1341440 M8 east safety patrol, 16th March - Safety Patrol on 16/03/2023	No Defects Recorded Total	0	0	0
1341694 M8 Polmadie Safety Patyrol - Safety Patrol on 23/03/2023	No Defects Recorded Total	0	0	0
1341921 M8 Polmadie Safety Patrol, 30th March - Safety Patrol on 30/03/2023	No Defects Recorded Total	0	0	1
1342162 NSW M8 Polmadie Night Inspection Route (28 day) - Night Time Illuminated Safety Inspection on 05/04/2023	M8 E/8 111 offslip at ADS, lane 1 nearside - Asset : 14215/16 - 294 Carriageway - Defect Ref : D-22-SW-19388 Total	Failed Patch/Trench - PATH - CAT1	Open	Temporary, Deferred - 31/03/2023
1342323 NSW M8 Polmadie Safety Patrol Route (Thur 06-04-23) - Safety Patrol on 06/04/2023	No Defects Recorded Total	0	0	0
763172 NSW M8 Polmadie Safety Patrol Route (R) - Safety Patrol on 14/10/2022	No Defects Recorded Total	0	0	0
763454 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 12/04/2022	M8 jct 11 off slip e/b - Asset : 14215/16 - 419 Carriageway - Defect Ref : D-22-SW-04788 Total	Failed Patch/Trench - PATH - CAT1	Closed	Permanent 15/10/2023
763455 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 18/04/2022	No Defects Recorded Total	0	0	0
763456 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 19/04/2022	No Defects Recorded Total	0	0	0
763457 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 25/04/2022	No Defects Recorded Total	0	0	0
763458 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 28/04/2022	No Defects Recorded Total	0	0	0
763459 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 02/05/2022	No Defects Recorded Total	0	0	0

1205253 9-9-22 redacted 11(2) M8 Polmadie Safety Patrol - Safety Patrol on 13/09/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1205256 M8 Polmadie - Safety Inspection (redacted 11(2)) - Safety Inspection on 09/09/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1205257 M8 Polmadie - Safety Inspection (redacted 11(2)) (R) - Safety Inspection on 16/09/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1205258 M8 Polmadie - Safety Inspection (redacted 11(2)) (R) - Safety Inspection on 20/09/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1205259 M8 Polmadie - Safety Inspection (redacted 11(2)) (R) - Safety Inspection on 23/09/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1205729 M8 East Safety Inspection 27/9/2022 - Safety Inspection on 27/09/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1205758 AD HOC - M8 Safety Patrol 30-9-22 (redacted 11(2)) - Safety Patrol on 30/09/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1206145 NSW M8 Polmadie Safety Inspection Route (Mon) - Safety Inspection on 04/10/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1206146 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 11/10/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1206148 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 21/11/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1206149 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 05/12/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1206150 NSW M8 Polmadie Safety Patrol Route (Thur) - Safety Patrol on 07/10/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1206151 M8 Polmadie, Safety Patrol, 12/01/23 - Safety Patrol on 12/01/2023	Total	redacted 11(2)	0
	No Defects Recorded		0
1206152 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 23/02/2023	Total	redacted 11(2)	0
	No Defects Recorded		0
1206155 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 10/11/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1206156 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 17/11/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1206157 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 24/11/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1206159 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 08/12/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1206160 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 15/12/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1206161 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 22/12/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1206162 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 29/12/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1206163 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 05/01/2023	Total	redacted 11(2)	0
	No Defects Recorded		0
1206305 NSW M8 Polmadie Night Inspection Route (14 day) - Night Time Illuminated Safety Inspection on 05/10/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1206306 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 16/11/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1206308 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 02/11/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1206519 M8 Polmadie, Safety Inspection, 18/10/22 - Safety Inspection on 18/10/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1206523 NSW M8 Polmadie Night Time Illuminated Safety Inspection Route (R) - Night Time Illuminated Safety Inspection on 19/10/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1206566 (Ad-Hoc) M8 Polmadie Safety Inspection - Safety Inspection on 24/10/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1206567 (Ad-Hoc) M8 Polmadie, Safety Patrol - Safety Patrol on 27/10/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1206590 M8 Polmadie - Safety Patrol, Oct 21 - Safety Patrol on 21/10/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1206696 M8 East Road markings night visual condition - Road Marking Hatched - Visual Condition on 28/10/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1206696 M8 East Road markings night visual condition - Road Marking Hatched - Visual Condition on 29/10/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1206696 M8 East Road markings night visual condition - Road Marking Longitudinal - Visual Condition on 28/10/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1206696 M8 East Road markings night visual condition - Road Marking Longitudinal - Visual Condition on 29/10/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1206696 M8 East Road markings night visual condition - Road Marking Transverse & Special - Visual Condition on 28/10/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1206696 M8 East Road markings night visual condition - Road Marking Transverse & Special - Visual Condition on 29/10/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1206706 AD-HOC M8 East Polmadie safety inspection (redacted 11(2)) - Safety Inspection on 31/10/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1206751 M8 Safety Patrol, Nov 3 - Safety Patrol on 03/11/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1206823 AD-HOC M8 Polmadie Safety Inspection 7-11-22 - Safety Inspection on 07/11/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1206935 AD-HOC M8 Safety Inspection 14-11-22 (redacted 11(2)) - Safety Inspection on 14/11/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1207028 NSW M8 Polmadie Safety Inspection Route (Mon) - Safety Inspection on 12/12/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1207029 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 19/12/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1207097 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 14/12/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1207102 NSW M8 Safety Routine Electrical Inspection - Cable Chamber - Routine Electrical Inspection on 28/11/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1207102 NSW M8 Safety Routine Electrical Inspection - Cable Chamber - Routine Electrical Inspection on 29/11/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1207102 NSW M8 Safety Routine Electrical Inspection - Electrical Component of Bollard - Routine Electrical Inspection on 29/11/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1207102 NSW M8 Safety Routine Electrical Inspection - Electrical Component of Cabinet/Pillar - Routine Electrical Inspection on 28/11/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1207102 NSW M8 Safety Routine Electrical Inspection - Electrical Component of Cabinet/Pillar - Routine Electrical Inspection on 29/11/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1207102 NSW M8 Safety Routine Electrical Inspection - Electrical Component of Traffic Sign - Routine Electrical Inspection on 28/11/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1207102 NSW M8 Safety Routine Electrical Inspection - Electrical Component of Traffic Sign - Routine Electrical Inspection on 29/11/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1207102 NSW M8 Safety Routine Electrical Inspection - Lighting Point - Routine Electrical Inspection on 28/11/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1207102 NSW M8 Safety Routine Electrical Inspection - Lighting Point - Routine Electrical Inspection on 29/11/2022	Total	redacted 11(2)	0
	No Defects Recorded		0
1207102 NSW M8 Safety Routine Electrical Inspection - Weather Station - Routine Electrical Inspection on 28/11/2022	Total	redacted 11(2)	0
	No Defects Recorded		0

	- Asset : 1440974 Retaining Walls (Over 150cm) (Span) - Defect Ref : D-22-SW-18458 - Asset : 1440974 Retaining Walls (Over 150cm) (Span) - Defect Ref : D-22-SW-18459	N No Action Monitor Only - N - CAT2 N No Action Monitor Only - N - CAT2	Open Open	1 1	Cat 2 Action Cat 2 Action
1340962 02/03/2023 - General Inspection M8 - Signs Signals General Inspection on 03/03/2023	Total - Asset : 1440974 Retaining Walls (Over 150cm) (Span) - Defect Ref : D-22-SW-18455 - Asset : 1440974 Retaining Walls (Over 150cm) (Span) - Defect Ref : D-22-SW-18456 - Asset : 1440974 Retaining Walls (Over 150cm) (Span) - Defect Ref : D-22-SW-18457 - Asset : 1440974 Retaining Walls (Over 150cm) (Span) - Defect Ref : D-22-SW-18458 - Asset : 1440974 Retaining Walls (Over 150cm) (Span) - Defect Ref : D-22-SW-18459	redacted 11(2) N No Action Monitor Only - N - CAT2 Cyclic Maint - Graffiti removal - 115g - CAT1	redacted 11(2) Open Open	5 1 1	Cat 2 Action Cat 2 Action Cat 2 Action
1340962 02/03/2023 - General Inspection M8 - Signs Signals General Inspection on 07/03/2023	Total - Asset : 1440974 Retaining Walls (Over 150cm) (Span) - Defect Ref : D-22-SW-18455 - Asset : 1440974 Retaining Walls (Over 150cm) (Span) - Defect Ref : D-22-SW-18456 - Asset : 1440974 Retaining Walls (Over 150cm) (Span) - Defect Ref : D-22-SW-18457 - Asset : 1440974 Retaining Walls (Over 150cm) (Span) - Defect Ref : D-22-SW-18458 - Asset : 1440974 Retaining Walls (Over 150cm) (Span) - Defect Ref : D-22-SW-18459	N No Action Monitor Only - N - CAT2 Cyclic Maint - Graffiti removal - 115g - CAT1 N No Action Monitor Only - N - CAT2 N No Action Monitor Only - N - CAT2	redacted 11(2) Open Open Open	5 1 1 1	Cat 2 Action Cat 2 Action Cat 2 Action Cat 2 Action
1340969 M8 Polmadie safety patrol, 2nd March - Safety Patrol on 02/03/2023	Total No Defects Recorded	N No Action Monitor Only - N - CAT2	redacted 11(2)	0	Cat 2 Action
1341086 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 22/03/2023	Total No Defects Recorded		redacted 11(2)	0	
1341222 M8 Polmadie Safety Patrol - Safety Patrol on 09/03/2023	Total No Defects Recorded		redacted 11(2)	0	
1341440 M8 east safety patrol, 16th March - Safety Patrol on 16/03/2023	Total No Defects Recorded		redacted 11(2)	0	
1341694 M8 Polmadie Safety Patrol - Safety Patrol on 23/03/2023	Total No Defects Recorded		redacted 11(2)	0	
1341921 M8 Polmadie Safety Patrol, 30th March - Safety Patrol on 30/03/2023	Total No Defects Recorded		redacted 11(2)	0	
1342162 NSW M8 Polmadie Night Inspection Route (28 day) - Night Time Illuminated Safety Inspection on 05/04/2023	Total No Defects Recorded		redacted 11(2)	0	
1342323 NSW M8 Polmadie Safety Patrol Route (Thur 06-04-23) - Safety Patrol on 06/04/2023	Total No Defects Recorded		redacted 11(2)	0	
763172 NSW M8 Polmadie Safety Patrol Route (R) - Safety Patrol on 14/10/2022	Total No Defects Recorded		redacted 11(2)	0	
763454 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 12/04/2022	Total No Defects Recorded		redacted 11(2)	0	
763455 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 18/04/2022	Total No Defects Recorded		redacted 11(2)	0	
763456 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 19/04/2022	Total No Defects Recorded		redacted 11(2)	0	
763457 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 25/04/2022	Total No Defects Recorded		redacted 11(2)	0	
763458 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 28/04/2022	Total No Defects Recorded		redacted 11(2)	0	
763459 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 02/05/2022	Total No Defects Recorded		redacted 11(2)	0	
763460 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 04/05/2022	Total No Defects Recorded		redacted 11(2)	0	
763461 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 09/05/2022	Total No Defects Recorded		redacted 11(2)	0	
763462 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 12/05/2022	Total No Defects Recorded		redacted 11(2)	0	
763463 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 16/05/2022	Total No Defects Recorded		redacted 11(2)	0	
763464 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 17/05/2022	Total No Defects Recorded		redacted 11(2)	0	
763465 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 23/05/2022	Total No Defects Recorded		redacted 11(2)	0	
763466 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 26/05/2022	Total No Defects Recorded		redacted 11(2)	0	
763516 NSW M8 Polmadie Safety Patrol Route (R) - Safety Patrol on 27/05/2022	Total No Defects Recorded		redacted 11(2)	0	
763520 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 31/05/2022	Total No Defects Recorded		redacted 11(2)	0	
763937 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 06/06/2022	Total No Defects Recorded		redacted 11(2)	0	
764008 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 07/06/2022	Total No Defects Recorded		redacted 11(2)	0	
912677 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 10/06/2022	Total No Defects Recorded		redacted 11(2)	0	
912721 NSW M8 Polmadie Night Inspection Route - Night Time Illuminated Safety Inspection on 19/05/2022	Total No Defects Recorded		redacted 11(2)	0	
912722 NSW M8 Polmadie Night Inspection Route (R) - Night Time Illuminated Safety Inspection on 15/06/2022	Total No Defects Recorded		redacted 11(2)	0	
912782 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 14/06/2022	Total No Defects Recorded		redacted 11(2)	0	
912818 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 17/06/2022	Total No Defects Recorded		redacted 11(2)	0	
942258 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 21/06/2022	Total No Defects Recorded		redacted 11(2)	0	
942296 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 27/06/2022	Total No Defects Recorded		redacted 11(2)	0	
942368 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 30/06/2022	Total No Defects Recorded		redacted 11(2)	0	
942396 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 01/07/2022	Total No Defects Recorded		redacted 11(2)	0	
951525 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 05/07/2022	Total No Defects Recorded		redacted 11(2)	0	
951593 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 12/07/2022	Total No Defects Recorded		redacted 11(2)	0	
951647 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 19/07/2022	Total No Defects Recorded		redacted 11(2)	0	
951695 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 22/07/2022	Total No Defects Recorded		redacted 11(2)	0	
951759 NSW M8 Polmadie Safety Patrol Route (R) - Safety Patrol on 08/07/2022	Total No Defects Recorded		redacted 11(2)	0	
951815 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 26/07/2022	Total No Defects Recorded		redacted 11(2)	0	
951871 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 29/07/2022	Total No Defects Recorded		redacted 11(2)	0	
951893 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 02/08/2022	Total No Defects Recorded		redacted 11(2)	0	
951986 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 05/08/2022	Total No Defects Recorded		redacted 11(2)	0	
952014 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 09/08/2022	Total No Defects Recorded		redacted 11(2)	0	
952062 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 12/08/2022	Total No Defects Recorded		redacted 11(2)	0	

952085 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 16/08/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
952115 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 19/08/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
952174 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 23/08/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
952205 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 29/08/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
952220 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 01/09/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
952257 NSW M8 Polmadie Safety Patrol Route (R) - Safety Patrol on 15/07/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
952327 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 02/09/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
952347 NSW M8 Polmadie Night Inspection Route 12/07/22 - Night Time Illuminated Safety Inspection on 13/07/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
952348 NSW M8 Polmadie Night Inspection Route 09/08/22 - Night Time Illuminated Safety Inspection on 10/08/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
952349 NSW M8 Polmadie Night Inspection Route 06/09/22 - Night Time Illuminated Safety Inspection on 07/09/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
952377 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 09/01/2023	Total		redacted 11(2)	0
	No Defects Recorded			0
M8 14220/05 - WITH: M8 WB JCT 12 OFF SLIP TO ENTRY SLIP	Total			4
1140670 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 06/02/2023	Total		redacted 11(2)	0
	No Defects Recorded			0
1140697 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 13/02/2023	Total		redacted 11(2)	0
	No Defects Recorded			0
1161500 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 20/02/2023	Total		redacted 11(2)	0
	No Defects Recorded			0
1163013 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 27/02/2023	Total		redacted 11(2)	0
	No Defects Recorded			0
1163228 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 06/03/2023	Total		redacted 11(2)	0
	No Defects Recorded			0
1163343 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 13/03/2023	Total		redacted 11(2)	0
	No Defects Recorded			0
1163374 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 20/03/2023	Total		redacted 11(2)	0
	No Defects Recorded			0
1163436 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 27/03/2023	Total		redacted 11(2)	0
	No Defects Recorded			0
1204993 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 03/04/2023	Total		redacted 11(2)	0
	No Defects Recorded			0
1205212 M8 Safety Inspection 06-09-22 - Safety Inspection on 06/09/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
1205253 9-9-22 redacted 11(2) M8 Polmadie Safety Patrol - Safety Patrol on 13/09/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
1205256 M8 Polmadie - Safety Inspection (redacted 11(2)) - Safety Inspection on 09/09/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
1205257 M8 Polmadie - Safety Inspection (redacted 11(2)) (R) - Safety Inspection on 16/09/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
1205258 M8 Polmadie - Safety Inspection (redacted 11(2)) (R) - Safety Inspection on 20/09/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
1205259 M8 Polmadie - Safety Inspection (redacted 11(2)) (R) - Safety Inspection on 23/09/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
1205729 M8 East Safety Inspection 27/9/2022 - Safety Inspection on 27/09/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
1205758 AD HOC - M8 Safety Patrol 30-9-22 (redacted 11(2)) - Safety Patrol on 30/09/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
1206145 NSW M8 Polmadie Safety Inspection Route (Mon) - Safety Inspection on 04/10/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
1206146 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 11/10/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
1206148 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 21/11/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
1206149 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 05/12/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
1206150 NSW M8 Polmadie Safety Patrol Route (Thur) - Safety Patrol on 07/10/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
1206151 M8 Polmadie, Safety Patrol, 12/01/23 - Safety Patrol on 12/01/2023	Total		redacted 11(2)	0
	No Defects Recorded			0
1206152 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 23/02/2023	Total		redacted 11(2)	0
	No Defects Recorded			0
1206155 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 10/11/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
1206156 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 17/11/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
1206157 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 24/11/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
1206159 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 08/12/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
1206160 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 15/12/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
1206161 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 22/12/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
1206162 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 29/12/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
1206163 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 05/01/2023	Total		redacted 11(2)	0
	No Defects Recorded			0
1206305 NSW M8 Polmadie Night Inspection Route (14 day) - Night Time Illuminated Safety Inspection on 05/10/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
1206306 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 16/11/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
1206308 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 02/11/2022	Total		redacted 11(2)	1
	No Defects Recorded			0
1206519 M8 Polmadie, Safety Inspection, 18/10/22 - Safety Inspection on 18/10/2022	m8 centre res on approach to jct 12 w/b off ramp - Asset : 743424 Lighting Point - Defect Ref : D-22-SW-05199			
	Total			1
	No Defects Recorded			0
1206523 NSW M8 Polmadie - Night Time Illuminated Safety Inspection Route (R) - Night Time Illuminated Safety Inspection on 19/10/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
1206566 (Ad-Hoc) M8 Polmadie Safety Inspection - Safety Inspection on 24/10/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
1206567 (Ad-Hoc) M8 Polmadie, Safety Patrol - Safety Patrol on 27/10/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
1206590 M8 Polmadie - Safety Patrol, Oct 21 - Safety Patrol on 21/10/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
1206696 M8 East Road markings night visual condition - Road Marking Hatched - Visual Condition on 28/10/2022	Total		redacted 11(2)	0
	No Defects Recorded			0
		Lamp failures - LAMP - CAT1	Closed	1
			Deferred - Permanent, Temporary	02/11/2023

1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Lighting Point - Routine Electrical Inspection on 17/12/2022	No Defects Recorded	0
	Total	0
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Lighting Point - Routine Electrical Inspection on 18/12/2022	No Defects Recorded	0
	Total	0
1337501 M8 Safety patrol, Dec 1 - Safety Patrol on 02/12/2022	No Defects Recorded	0
	Total	0
1337670 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 26/12/2022	No Defects Recorded	0
	Total	0
1337672 M8 road sweeper - Litter/Refuse Sweeping on 13/04/2023	No Defects Recorded	0
	Total	0
1337812 Monday 23rd - M8 East - safety inspection. - Safety Inspection on 23/01/2023	No Defects Recorded	0
	Total	0
1337906 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 11/01/2023	No Defects Recorded	0
	Total	0
1337982 AD-HOC M8 Polmadie Inspection 02/01/2023 - Safety Inspection on 02/01/2023	No Defects Recorded	0
	Total	0
1338066 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 25/01/2023	No Defects Recorded	0
	Total	0
1338498 M8 Polmadie, Safety Inspection, 16/01/23 - Safety Inspection on 17/01/2023	No Defects Recorded	0
	Total	0
1338520 Weather station inspections/validation - Weather Station - RCD Test on 17/01/2023	No Defects Recorded	0
	Total	0
1338520 Weather station inspections/validation - Weather Station - RCD Test on 18/01/2023	No Defects Recorded	0
	Total	0
1338520 Weather station inspections/validation - Weather Station - Visual Condition on 17/01/2023	No Defects Recorded	0
	Total	0
1338520 Weather station inspections/validation - Weather Station - Visual Condition on 18/01/2023	No Defects Recorded	0
	Total	0
1338601 M8 East Safety Patrol 19th Jan - Safety Patrol on 19/01/2023	No Defects Recorded	0
	Total	0
1338639 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 08/02/2023	No Defects Recorded	0
	Total	0
1338767 NSW M8 Polmadie Weather station B57671, Routine Insp, RCD test and Visual Condition - Electrical Component of Cabinet/Pillar - Periodic Electrical Inspection and Testing - B57671 on 27/01/2023	No Defects Recorded	0
	Total	0
1338767 NSW M8 Polmadie Weather station B57671, Routine Insp, RCD test and Visual Condition - Weather Station - Periodic Electrical Inspection and Testing - B57671 on 27/01/2023	No Defects Recorded	0
	Total	0
1338767 NSW M8 Polmadie Weather station B57671, Routine Insp, RCD test and Visual Condition - Weather Station - RCD Test on 27/01/2023	No Defects Recorded	0
	Total	0
1338767 NSW M8 Polmadie Weather station B57671, Routine Insp, RCD test and Visual Condition - Weather Station - Routine Electrical Inspection on 27/01/2023	No Defects Recorded	0
	Total	0
1338767 NSW M8 Polmadie Weather station B57671, Routine Insp, RCD test and Visual Condition - Weather Station - Visual Condition on 27/01/2023	No Defects Recorded	0
	Total	0
1338782 M8 East, Safety Patrol, 26th Jan - Safety Patrol on 26/01/2023	No Defects Recorded	0
	Total	0
1338843 M8 Polmadie, Safety Inspection, 30/01/23 - Safety Inspection on 30/01/2023	No Defects Recorded	0
	Total	0
1339078 M8 West - Safety Patrol - 2nd Jan - Safety Patrol on 02/02/2023	No Defects Recorded	0
	Total	0
1339152 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 22/02/2023	No Defects Recorded	0
	Total	0
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Catchpit - Cleaning on 13/02/2023	No Defects Recorded	0
	Total	0
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Catchpit - Cleaning on 14/02/2023	No Defects Recorded	0
	Total	0
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Catchpit - Cleaning on 15/02/2023	No Defects Recorded	0
	Total	0
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Catchpit - Cleaning on 20/02/2023	No Defects Recorded	0
	Total	0
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Catchpit - Cleaning on 28/03/2023	No Defects Recorded	0
	Total	0
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Catchpit - Internal Inspection on 13/02/2023	No Defects Recorded	0
	Total	0
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Catchpit - Internal Inspection on 14/02/2023	No Defects Recorded	0
	Total	0
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Catchpit - Internal Inspection on 15/02/2023	No Defects Recorded	0
	Total	0
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Catchpit - Internal Inspection on 20/02/2023	No Defects Recorded	0
	Total	0
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Catchpit - Internal Inspection on 28/03/2023	No Defects Recorded	0
	Total	0
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Catchpit - Surface Visual Condition on 13/02/2023	No Defects Recorded	0
	Total	0
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Catchpit - Surface Visual Condition on 14/02/2023	No Defects Recorded	0
	Total	0
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Catchpit - Surface Visual Condition on 15/02/2023	No Defects Recorded	0
	Total	0
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Catchpit - Surface Visual Condition on 20/02/2023	No Defects Recorded	0
	Total	0
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Catchpit - Surface Visual Condition on 28/03/2023	No Defects Recorded	0
	Total	0
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Gully - Cleaning on 09/02/2023	No Defects Recorded	0
	Total	0
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Gully - Cleaning on 10/02/2023	No Defects Recorded	0
	Total	0
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Gully - Cleaning on 14/02/2023	No Defects Recorded	0
	Total	0
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Gully - Cleaning on 16/02/2023	No Defects Recorded	0
	Total	0
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Gully - Cleaning on 28/03/2023	No Defects Recorded	0
	Total	0
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Gully - Cleaning on 29/03/2023	No Defects Recorded	0
	Total	0
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Gully - Surface Visual Condition on 09/02/2023	No Defects Recorded	0
	Total	0
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Gully - Surface Visual Condition on 10/02/2023	No Defects Recorded	0
	Total	0
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Gully - Surface Visual Condition on 14/02/2023	No Defects Recorded	0
	Total	0
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Gully - Surface Visual Condition on 16/02/2023	No Defects Recorded	0
	Total	0
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Gully - Surface Visual Condition on 28/03/2023	No Defects Recorded	0
	Total	0
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Gully - Surface Visual Condition on 29/03/2023	No Defects Recorded	0
	Total	0
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Manhole - Cleaning on 13/02/2023	No Defects Recorded	0
	Total	0

1339199 M8 jct 10 to 15 gullies catchpits and manholes - Manhole - Cleaning on 14/02/2023	No Defects Recorded Total		0		
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Manhole - Cleaning on 15/02/2023	No Defects Recorded Total		0		
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Manhole - Cleaning on 20/02/2023	No Defects Recorded Total		0		
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Manhole - Internal Inspection on 13/02/2023	No Defects Recorded Total		0		
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Manhole - Internal Inspection on 14/02/2023	No Defects Recorded Total		0		
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Manhole - Internal Inspection on 15/02/2023	No Defects Recorded Total		0		
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Manhole - Internal Inspection on 20/02/2023	No Defects Recorded Total		0		
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Manhole - Surface Visual Condition on 13/02/2023	No Defects Recorded Total		0		
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Manhole - Surface Visual Condition on 14/02/2023	No Defects Recorded Total		0		
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Manhole - Surface Visual Condition on 15/02/2023	No Defects Recorded Total		0		
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Manhole - Surface Visual Condition on 20/02/2023	No Defects Recorded Total		0		
1339224 M8 Polmadie Safety Patrol - Safety Patrol on 09/02/2023	No Defects Recorded Total		0		
1339386 AD-HDC M8 Polmadie Safety Patrol 16-2-23 (redacted 11(2)) - Safety Patrol on 16/02/2023	No Defects Recorded Total		0		
1339482 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 08/03/2023	No Defects Recorded Total		0		
1340962 02/03/2023 - General Inspection M8 - Highmast Light General Inspection on 03/03/2023	No Defects Recorded Total		0		
1340962 02/03/2023 - General Inspection M8 - Highmast Light General Inspection on 07/03/2023	- Asset : 1440435 Signs/Signal Gantries (Span) - Defect Ref : D-22-SW-18297 - Asset : 1440435 Signs/Signal Gantries (Span) - Defect Ref : D-22-SW-18298 Total	N No Action Monitor Only - N - CAT2 N No Action Monitor Only - N - CAT2	Open Open	1 1	Cat 2 Action Cat 2 Action
1340962 02/03/2023 - General Inspection M8 - Retaining Wall General Inspection on 08/03/2023	- Asset : 1440435 Signs/Signal Gantries (Span) - Defect Ref : D-22-SW-18297 - Asset : 1440435 Signs/Signal Gantries (Span) - Defect Ref : D-22-SW-18298 Total	N No Action Monitor Only - N - CAT2 N No Action Monitor Only - N - CAT2	Open Open	1 1	Cat 2 Action Cat 2 Action
1340962 02/03/2023 - General Inspection M8 - Signs Signals General Inspection on 03/03/2023	- Asset : 1440435 Signs/Signal Gantries (Span) - Defect Ref : D-22-SW-18297 - Asset : 1440435 Signs/Signal Gantries (Span) - Defect Ref : D-22-SW-18298 Total	N No Action Monitor Only - N - CAT2 N No Action Monitor Only - N - CAT2	Open Open	1 1	Cat 2 Action Cat 2 Action
1340962 02/03/2023 - General Inspection M8 - Signs Signals General Inspection on 07/03/2023	- Asset : 1440435 Signs/Signal Gantries (Span) - Defect Ref : D-22-SW-18297 - Asset : 1440435 Signs/Signal Gantries (Span) - Defect Ref : D-22-SW-18298 Total	N No Action Monitor Only - N - CAT2 N No Action Monitor Only - N - CAT2	Open Open	1 1	Cat 2 Action Cat 2 Action
1340969 M8 Polmadie safety patrol, 2nd March - Safety Patrol on 02/03/2023	No Defects Recorded Total		0		
1341086 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 22/03/2023	No Defects Recorded Total		0		
1341222 M8 Polmadie Safety Patrol - Safety Patrol on 09/03/2023	No Defects Recorded Total		0		
1341440 M8 east safety patrol, 16th March - Safety Patrol on 16/03/2023	No Defects Recorded Total		0		
1341694 M8 Polmadie Safety Patrol - Safety Patrol on 23/03/2023	No Defects Recorded Total		0		
1341921 M8 Polmadie Safety Patrol, 30th March - Safety Patrol on 30/03/2023	No Defects Recorded Total		0		
1342162 NSW M8 Polmadie Night Inspection Route (28 day) - Night Time Illuminated Safety Inspection on 05/04/2023	No Defects Recorded Total		0		
1342323 NSW M8 Polmadie Safety Patrol Route (Thur 06-04-23) - Safety Patrol on 06/04/2023	No Defects Recorded Total		0		
763172 NSW M8 Polmadie Safety Patrol Route (R) - Safety Patrol on 14/10/2022	No Defects Recorded Total		0		
763454 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 12/04/2022	No Defects Recorded Total		0		
763455 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 18/04/2022	No Defects Recorded Total		0		
763456 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 19/04/2022	No Defects Recorded Total		0		
763457 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 25/04/2022	No Defects Recorded Total		0		
763458 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 28/04/2022	No Defects Recorded Total		0		
763459 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 02/05/2022	No Defects Recorded Total		0		
763460 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 04/05/2022	No Defects Recorded Total		0		
763461 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 09/05/2022	No Defects Recorded Total		0		
763462 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 12/05/2022	M8 jct 12 both sides - Asset : 14220/05 - O Carriageway - Defect Ref : D-22-SW-00594 Total	Other - OTHR - CAT1	Closed	1	Deferred - Permanent, Temporary
763463 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 16/05/2022	No Defects Recorded Total		0		
763464 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 17/05/2022	No Defects Recorded Total		0		
763465 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 23/05/2022	No Defects Recorded Total		0		
763466 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 26/05/2022	No Defects Recorded Total		0		
763516 NSW M8 Polmadie Safety Patrol Route (R) - Safety Patrol on 27/05/2022	No Defects Recorded Total		0		
763520 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 31/05/2022	No Defects Recorded Total		0		
763937 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 06/06/2022	No Defects Recorded Total		0		
764008 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 07/06/2022	No Defects Recorded Total		0		
912677 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 10/06/2022	No Defects Recorded Total		0		
912721 NSW M8 Polmadie Night Inspection Route - Night Time Illuminated Safety Inspection on 19/05/2022	No Defects Recorded Total		0		
912722 NSW M8 Polmadie Night Inspection Route (R) - Night Time Illuminated Safety Inspection on 15/06/2022	No Defects Recorded Total		0		
912782 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 14/06/2022	No Defects Recorded Total		0		

1206157 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 24/11/2022	No Defects Recorded	0
	Total	0
1206159 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 08/12/2022	No Defects Recorded	0
	Total	0
1206160 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 15/12/2022	No Defects Recorded	0
	Total	0
1206161 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 22/12/2022	No Defects Recorded	0
	Total	0
1206162 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 29/12/2022	No Defects Recorded	0
	Total	0
1206163 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 05/01/2023	No Defects Recorded	0
	Total	0
1206305 NSW M8 Polmadie Night Inspection Route (14 day) - Night Time Illuminated Safety Inspection on 05/10/2022	No Defects Recorded	0
	Total	0
1206306 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 16/11/2022	No Defects Recorded	0
	Total	0
1206308 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 02/11/2022	No Defects Recorded	0
	Total	0
1206519 M8 Polmadie, Safety Inspection. 18/10/22 - Safety Inspection on 18/10/2022	No Defects Recorded	0
	Total	0
1206523 NSW M8 Polmadie Night Time Illuminated Safety Inspection Route (R) - Night Time Illuminated Safety Inspection on 19/10/2022	No Defects Recorded	0
	Total	0
1206566 (Ad-Hoc) M8 Polmadie Safety Inspection. - Safety Inspection on 24/10/2022	No Defects Recorded	0
	Total	0
1206567 (Ad-Hoc) M8 Polmadie, Safety Patrol - Safety Patrol on 27/10/2022	No Defects Recorded	0
	Total	0
1206590 M8 Polmadie - Safety Patrol, Oct 21 - Safety Patrol on 21/10/2022	No Defects Recorded	0
	Total	0
1206696 M8 East Road markings night visual condition - Road Marking Hatched - Visual Condition on 28/10/2022	No Defects Recorded	0
	Total	0
1206696 M8 East Road markings night visual condition - Road Marking Hatched - Visual Condition on 29/10/2022	No Defects Recorded	0
	Total	0
1206696 M8 East Road markings night visual condition - Road Marking Longitudinal - Visual Condition on 28/10/2022	No Defects Recorded	0
	Total	0
1206696 M8 East Road markings night visual condition - Road Marking Longitudinal - Visual Condition on 29/10/2022	No Defects Recorded	0
	Total	0
1206696 M8 East Road markings night visual condition - Road Marking Transverse & Special - Visual Condition on 28/10/2022	No Defects Recorded	0
	Total	0
1206696 M8 East Road markings night visual condition - Road Marking Transverse & Special - Visual Condition on 29/10/2022	No Defects Recorded	0
	Total	0
1206706 AD-HOC M8 East Polmadie safety inspection (redacted 11(2)) - Safety Inspection on 31/10/2022	No Defects Recorded	0
	Total	0
1206751 M8 Safety Patrol, Nov 3 - Safety Patrol on 03/11/2022	No Defects Recorded	0
	Total	0
1206823 AD-HOC M8 Polmadie Safety Inspection 7-11-22 - Safety Inspection on 07/11/2022	No Defects Recorded	0
	Total	0
1206935 AD-HOC M8 Safety Inspection 14-11-22 (redacted 11(2)) - Safety Inspection on 14/11/2022	No Defects Recorded	0
	Total	0
1207028 NSW M8 Polmadie Safety Inspection Route (Mon) - Safety Inspection on 12/12/2022	No Defects Recorded	0
	Total	0
1207029 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 19/12/2022	No Defects Recorded	0
	Total	0
1207097 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 14/12/2022	No Defects Recorded	0
	Total	0
1207102 NSW M8 Safety Routine Electrical Inspection - Cable Chamber - Routine Electrical Inspection on 28/11/2022	No Defects Recorded	0
	Total	0
1207102 NSW M8 Safety Routine Electrical Inspection - Cable Chamber - Routine Electrical Inspection on 29/11/2022	No Defects Recorded	0
	Total	0
1207102 NSW M8 Safety Routine Electrical Inspection - Electrical Component of Bollard - Routine Electrical Inspection on 29/11/2022	No Defects Recorded	0
	Total	0
1207102 NSW M8 Safety Routine Electrical Inspection - Electrical Component of Cabinet/Pillar - Routine Electrical Inspection on 28/11/2022	No Defects Recorded	0
	Total	0
1207102 NSW M8 Safety Routine Electrical Inspection - Electrical Component of Cabinet/Pillar - Routine Electrical Inspection on 29/11/2022	No Defects Recorded	0
	Total	0
1207102 NSW M8 Safety Routine Electrical Inspection - Electrical Component of Traffic Sign - Routine Electrical Inspection on 28/11/2022	No Defects Recorded	0
	Total	0
1207102 NSW M8 Safety Routine Electrical Inspection - Electrical Component of Traffic Sign - Routine Electrical Inspection on 29/11/2022	No Defects Recorded	0
	Total	0
1207102 NSW M8 Safety Routine Electrical Inspection - Lighting Point - Routine Electrical Inspection on 28/11/2022	No Defects Recorded	0
	Total	0
1207102 NSW M8 Safety Routine Electrical Inspection - Lighting Point - Routine Electrical Inspection on 29/11/2022	No Defects Recorded	0
	Total	0
1207102 NSW M8 Safety Routine Electrical Inspection - Weather Station - Routine Electrical Inspection on 28/11/2022	No Defects Recorded	0
	Total	0
1207108 Ad-Hoc M8 Safety Inspection - Safety Inspection on 28/11/2022	No Defects Recorded	0
	Total	0
1337497 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 28/12/2022	No Defects Recorded	0
	Total	0
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Cable Chamber - Routine Electrical Inspection on 11/12/2022	No Defects Recorded	0
	Total	0
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Cable Chamber - Routine Electrical Inspection on 12/12/2022	No Defects Recorded	0
	Total	0
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Cable Chamber - Routine Electrical Inspection on 13/12/2022	No Defects Recorded	0
	Total	0
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Cable Chamber - Routine Electrical Inspection on 16/12/2022	No Defects Recorded	0
	Total	0
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Cable Chamber - Routine Electrical Inspection on 17/12/2022	No Defects Recorded	0
	Total	0
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Bollard - Routine Electrical Inspection on 11/12/2022	No Defects Recorded	0
	Total	0
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Bollard - Routine Electrical Inspection on 13/12/2022	No Defects Recorded	0
	Total	0
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Bollard - Routine Electrical Inspection on 16/12/2022	No Defects Recorded	0
	Total	0
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Cabinet/Pillar - Routine Electrical Inspection on 09/12/2022	No Defects Recorded	0
	Total	0
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Cabinet/Pillar - Routine Electrical Inspection on 11/12/2022	No Defects Recorded	0
	Total	0
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Cabinet/Pillar - Routine Electrical Inspection on 12/12/2022	No Defects Recorded	0
	Total	0
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Cabinet/Pillar - Routine Electrical Inspection on 13/12/2022	No Defects Recorded	0
	Total	0
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Cabinet/Pillar - Routine Electrical Inspection on 14/12/2022	No Defects Recorded	0
	Total	0
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Cabinet/Pillar - Routine Electrical Inspection on 16/12/2022	No Defects Recorded	0
	Total	0

1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Cabinet/Pillar - Routine Electrical Inspection on 17/12/2022	No Defects Recorded		0		
	Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Cabinet/Pillar - Routine Electrical Inspection on 18/12/2022	No Defects Recorded		0		
	Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Traffic Sign - Routine Electrical Inspection on 09/12/2022	No Defects Recorded		0		
	Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Traffic Sign - Routine Electrical Inspection on 11/12/2022	No Defects Recorded		0		
	Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Traffic Sign - Routine Electrical Inspection on 12/12/2022	No Defects Recorded		0		
	Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Traffic Sign - Routine Electrical Inspection on 13/12/2022	No Defects Recorded		0		
	Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Traffic Sign - Routine Electrical Inspection on 14/12/2022	No Defects Recorded		0		
	Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Traffic Sign - Routine Electrical Inspection on 16/12/2022	No Defects Recorded		0		
	Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Traffic Sign - Routine Electrical Inspection on 17/12/2022	No Defects Recorded		0		
	Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Electrical Component of Traffic Sign - Routine Electrical Inspection on 18/12/2022	No Defects Recorded		0		
	Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Lighting Point - Routine Electrical Inspection on 11/12/2022	No Defects Recorded		0		
	Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Lighting Point - Routine Electrical Inspection on 12/12/2022	No Defects Recorded		0		
	Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Lighting Point - Routine Electrical Inspection on 13/12/2022	No Defects Recorded		0		
	Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Lighting Point - Routine Electrical Inspection on 14/12/2022	No Defects Recorded		0		
	Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Lighting Point - Routine Electrical Inspection on 16/12/2022	No Defects Recorded		0		
	Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Lighting Point - Routine Electrical Inspection on 17/12/2022	No Defects Recorded		0		
	Total		0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Lighting Point - Routine Electrical Inspection on 18/12/2022	No Defects Recorded		0		
	Total		0		
1337501 M8 Safety patrol, Dec 1 - Safety Patrol on 02/12/2022	No Defects Recorded		0		
	Total		0		
1337670 NSW M8 Polmadie safety Inspection Route (Mon) (R) - Safety Inspection on 26/12/2022	No Defects Recorded		0		
	Total		0		
1337672 M8 road sweeper - Litter/Refuse Sweeping on 13/04/2023	No Defects Recorded		0		
	Total		0		
1337812 Monday 23rd - M8 East - safety inspection. - Safety Inspection on 23/01/2023	No Defects Recorded		0		
	Total		0		
1337906 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 11/01/2023	No Defects Recorded		0		
	Total		0		
1337982 AD-HOC M8 Polmadie Inspection 02/01/2023 - Safety Inspection on 02/01/2023	No Defects Recorded		0		
	Total		0		
1338066 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 25/01/2023	No Defects Recorded		0		
	Total		0		
1338498 M8 Polmadie, Safety Inspection, 16/01/23 - Safety Inspection on 17/01/2023	No Defects Recorded		0		
	Total		0		
1338520 Weather station inspections/validation - Weather Station - RCD Test on 17/01/2023	No Defects Recorded		0		
	Total		0		
1338520 Weather station inspections/validation - Weather Station - RCD Test on 18/01/2023	No Defects Recorded		0		
	Total		0		
1338520 Weather station inspections/validation - Weather Station - Visual Condition on 17/01/2023	No Defects Recorded		0		
	Total		0		
1338520 Weather station inspections/validation - Weather Station - Visual Condition on 18/01/2023	No Defects Recorded		0		
	Total		0		
1338601 M8 East Safety Patrol 19th Jan - Safety Patrol on 19/01/2023	No Defects Recorded		0		
	Total		0		
1338639 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 08/02/2023	No Defects Recorded		0		
	Total		0		
1338767 NSW M8 Polmadie Weather station B57671, Routine Insp, RCD test and Visual Condition - Electrical Component of Cabinet/Pillar - Periodic Electrical Inspection and Testing - B57671 on 27/01/2023	No Defects Recorded		0		
	Total		0		
1338767 NSW M8 Polmadie Weather station B57671, Routine Insp, RCD test and Visual Condition - Weather Station - Periodic Electrical Inspection and Testing - B57671 on 27/01/2023	No Defects Recorded		0		
	Total		0		
1338767 NSW M8 Polmadie Weather station B57671, Routine Insp, RCD test and Visual Condition - Weather Station - RCD Test on 27/01/2023	No Defects Recorded		0		
	Total		0		
1338767 NSW M8 Polmadie Weather station B57671, Routine Insp, RCD test and Visual Condition - Weather Station - Routine Electrical Inspection on 27/01/2023	No Defects Recorded		0		
	Total		0		
1338767 NSW M8 Polmadie Weather station B57671, Routine Insp, RCD test and Visual Condition - Weather Station - Visual Condition on 27/01/2023	No Defects Recorded		0		
	Total		0		
1338782 M8 East, Safety Patrol, 26th Jan - Safety Patrol on 26/01/2023	No Defects Recorded		0		
	Total		0		
1338843 M8 Polmadie, Safety Inspection, 30/01/23 - Safety Inspection on 30/01/2023	No Defects Recorded		0		
	Total		0		
1339078 M8 West - Safety Patrol - 2nd Jan - Safety Patrol on 02/02/2023	No Defects Recorded		0		
	Total		0		
1339152 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 22/02/2023	No Defects Recorded		0		
	Total		0		
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Catchpit - Cleaning on 13/02/2023	No Defects Recorded		0		
	Total		2		
	m8 jct 12 - Asset : 565581 Gully - Defect Ref : D-22-SW-17838	Blockage - BLOK - CAT2	Open	1	Cat 2 Action
	m8 jct 12 to 13 - Asset : 565579 Gully - Defect Ref : D-22-SW-17839	Blockage - BLOK - CAT2	Open	1	Cat 2 Action
	Total			2	
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Catchpit - Cleaning on 14/02/2023	No Defects Recorded		0		
	Total		2		
	m8 jct 12 - Asset : 565581 Gully - Defect Ref : D-22-SW-17838	Blockage - BLOK - CAT2	Open	1	Cat 2 Action
	m8 jct 12 to 13 - Asset : 565579 Gully - Defect Ref : D-22-SW-17839	Blockage - BLOK - CAT2	Open	1	Cat 2 Action
	Total			2	
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Catchpit - Cleaning on 15/02/2023	No Defects Recorded		0		
	Total		2		
	m8 jct 12 - Asset : 565581 Gully - Defect Ref : D-22-SW-17838	Blockage - BLOK - CAT2	Open	1	Cat 2 Action
	m8 jct 12 to 13 - Asset : 565579 Gully - Defect Ref : D-22-SW-17839	Blockage - BLOK - CAT2	Open	1	Cat 2 Action
	Total			2	
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Catchpit - Cleaning on 20/02/2023	No Defects Recorded		0		
	Total		2		
	m8 jct 12 - Asset : 565581 Gully - Defect Ref : D-22-SW-17838	Blockage - BLOK - CAT2	Open	1	Cat 2 Action
	m8 jct 12 to 13 - Asset : 565579 Gully - Defect Ref : D-22-SW-17839	Blockage - BLOK - CAT2	Open	1	Cat 2 Action
	Total			2	
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Catchpit - Cleaning on 28/03/2023	No Defects Recorded		0		
	Total		2		
	m8 jct 12 - Asset : 565581 Gully - Defect Ref : D-22-SW-17838	Blockage - BLOK - CAT2	Open	1	Cat 2 Action
	m8 jct 12 to 13 - Asset : 565579 Gully - Defect Ref : D-22-SW-17839	Blockage - BLOK - CAT2	Open	1	Cat 2 Action
	Total			2	
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Catchpit - Internal Inspection on 13/02/2023	No Defects Recorded		0		
	Total		2		
	m8 jct 12 - Asset : 565581 Gully - Defect Ref : D-22-SW-17838	Blockage - BLOK - CAT2	Open	1	Cat 2 Action
	m8 jct 12 to 13 - Asset : 565579 Gully - Defect Ref : D-22-SW-17839	Blockage - BLOK - CAT2	Open	1	Cat 2 Action
	Total			2	
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Catchpit - Internal Inspection on 15/02/2023	No Defects Recorded		0		
	Total		2		
	m8 jct 12 - Asset : 565581 Gully - Defect Ref : D-22-SW-17838	Blockage - BLOK - CAT2	Open	1	Cat 2 Action
	m8 jct 12 to 13 - Asset : 565579 Gully - Defect Ref : D-22-SW-17839	Blockage - BLOK - CAT2	Open	1	Cat 2 Action
	Total			2	
1339199 M8 jct 10 to 15 gullies catchpits and manholes - Catchpit - Internal Inspection on 20/02/2023	No Defects Recorded		0		
	Total		2		
	m8 jct 12 - Asset : 565581 Gully - Defect Ref : D-22-SW-17838	Blockage - BLOK - CAT2	Open	1	Cat 2 Action
	m8 jct 12 to 13 - Asset : 565579 Gully - Defect Ref : D-22-SW-17839	Blockage - BLOK - CAT2	Open	1	Cat 2 Action
	Total			2	

		No Defects Recorded	0
	952062 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 12/08/2022	Total	0
		No Defects Recorded	0
	952085 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 16/08/2022	Total	0
		No Defects Recorded	0
	952115 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 19/08/2022	Total	0
		No Defects Recorded	0
	952174 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 23/08/2022	Total	0
		No Defects Recorded	0
	952205 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 29/08/2022	Total	0
		No Defects Recorded	0
	952220 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 01/09/2022	Total	0
		No Defects Recorded	0
	952257 NSW M8 Polmadie Safety Patrol Route (R) - Safety Patrol on 15/07/2022	Total	0
		No Defects Recorded	0
	952327 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 02/09/2022	Total	0
		No Defects Recorded	0
	952347 NSW M8 Polmadie Night Inspection Route 12/07/22 - Night Time Illuminated Safety Inspection on 13/07/2022	Total	0
		No Defects Recorded	0
	952348 NSW M8 Polmadie Night Inspection Route 09/08/22 - Night Time Illuminated Safety Inspection on 10/08/2022	Total	0
		No Defects Recorded	0
	952349 NSW M8 Polmadie Night Inspection Route 06/09/22 - Night Time Illuminated Safety Inspection on 07/09/2022	Total	0
		No Defects Recorded	0
	952377 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 09/01/2023	Total	0
		No Defects Recorded	0
M8 14220/10 - AGAINST: JCT 12 GARTLOCH RD TO SLIP RD ENTRY	Total		1
	1140670 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 06/02/2023	Total	0
		No Defects Recorded	0
	1140697 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 13/02/2023	Total	0
		No Defects Recorded	0
	1161500 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 20/02/2023	Total	0
		No Defects Recorded	0
	1163013 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 27/02/2023	Total	0
		No Defects Recorded	0
	1163228 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 06/03/2023	Total	0
		No Defects Recorded	0
	1163343 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 13/03/2023	Total	0
		No Defects Recorded	0
	1163374 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 20/03/2023	Total	0
		No Defects Recorded	0
	1163436 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 27/03/2023	Total	0
		No Defects Recorded	0
	1204993 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 03/04/2023	Total	0
		No Defects Recorded	0
	1205212 M8 Safety Inspection 06-09-22 - Safety Inspection on 06/09/2022	Total	0
		No Defects Recorded	0
	1205253 9-9-22 redacted 11(2) M8 Polmadie Safety Patrol - Safety Patrol on 13/09/2022	Total	0
		No Defects Recorded	0
	1205256 M8 Polmadie - Safety Inspection (redacted 11(2)) - Safety inspection on 09/09/2022	Total	0
		No Defects Recorded	0
	1205257 M8 Polmadie - Safety Inspection (redacted 11(2)) (R) - Safety Inspection on 16/09/2022	Total	0
		No Defects Recorded	0
	1205258 M8 Polmadie - Safety Inspection (redacted 11(2)) (R) - Safety Inspection on 20/09/2022	Total	0
		No Defects Recorded	0
	1205259 M8 Polmadie - Safety Inspection (redacted 11(2)) (R) - Safety Inspection on 23/09/2022	Total	0
		No Defects Recorded	0
	1205279 M8 East Safety Inspection 27/9/2022 - Safety Inspection on 27/09/2022	Total	0
		No Defects Recorded	0
	1205758 AD HOC - M8 Safety Patrol 30-9-22 (redacted 11(2)) - Safety Patrol on 30/09/2022	Total	0
		No Defects Recorded	0
	1206145 NSW M8 Polmadie Safety Inspection Route (Mon) - Safety Inspection on 04/10/2022	Total	0
		No Defects Recorded	0
	1206146 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 11/10/2022	Total	0
		No Defects Recorded	0
	1206148 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 21/11/2022	Total	0
		No Defects Recorded	0
	1206149 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 05/12/2022	Total	0
		No Defects Recorded	0
	1206150 NSW M8 Polmadie Safety Patrol Route (Thur) - Safety Patrol on 07/10/2022	Total	0
		No Defects Recorded	0
	1206151 M8 Polmadie, Safety Patrol, 12/01/23 - Safety Patrol on 12/01/2023	Total	0
		No Defects Recorded	0
	1206152 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 23/02/2023	Total	0
		No Defects Recorded	0
	1206155 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 10/11/2022	Total	0
		No Defects Recorded	0
	1206156 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 17/11/2022	Total	0
		No Defects Recorded	0
	1206157 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 24/11/2022	Total	0
		No Defects Recorded	0
	1206159 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 08/12/2022	Total	0
		No Defects Recorded	0
	1206160 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 15/12/2022	Total	0
		No Defects Recorded	0
	1206161 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 22/12/2022	Total	0
		No Defects Recorded	0
	1206162 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 29/12/2022	Total	0
		No Defects Recorded	0
	1206163 NSW M8 Polmadie Safety Patrol Route (Thur) (R) - Safety Patrol on 05/01/2023	Total	0
		No Defects Recorded	0
	1206305 NSW M8 Polmadie Night Inspection Route (14 day) - Night Time Illuminated Safety Inspection on 05/10/2022	Total	0
		No Defects Recorded	0
	1206306 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 16/11/2022	Total	0
		No Defects Recorded	0
	1206308 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 02/11/2022	Total	0
		No Defects Recorded	0
	1206519 M8 Polmadie, Safety Inspection, 18/10/22 - Safety Inspection on 18/10/2022	Total	0
		No Defects Recorded	0
	1206523 NSW M8 Polmadie - Night Time Illuminated Safety Inspection Route (R) - Night Time Illuminated Safety Inspection on 19/10/2022	Total	0
		No Defects Recorded	0
	1206566 (Ad-Hoc) M8 Polmadie Safety Inspection, - Safety Inspection on 24/10/2022	Total	0
		No Defects Recorded	0
	1206567 (Ad-Hoc) M8 Polmadie, Safety Patrol - Safety Patrol on 27/10/2022	Total	0
		No Defects Recorded	0
	1206590 M8 Polmadie - Safety Patrol, Oct 21 - Safety Patrol on 21/10/2022	Total	0
		No Defects Recorded	0

1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Lighting Point - Routine Electrical Inspection on 16/12/2022	Total No Defects Recorded	redacted 11(2)	0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Lighting Point - Routine Electrical Inspection on 17/12/2022	Total No Defects Recorded	redacted 11(2)	0		
1337500 NSW M8 Polmadie safety Routine Electrical Inspection - Lighting Point - Routine Electrical Inspection on 18/12/2022	Total No Defects Recorded	redacted 11(2)	0		
1337501 M8 Safety patrol, Dec 1 - Safety Patrol on 02/12/2022	Total No Defects Recorded	redacted 11(2)	0		
1337670 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 26/12/2022	Total No Defects Recorded	redacted 11(2)	0		
1337672 M8 road sweeper - Litter/Refuse Sweeping on 13/04/2023	Total No Defects Recorded	redacted 11(2)	0		
1337812 Monday 23rd - M8 East - safety inspection. - Safety Inspection on 23/01/2023	Total No Defects Recorded	redacted 11(2)	0		
1337906 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 11/01/2023	Total No Defects Recorded	redacted 11(2)	0		
1337982 AD-HOC M8 Polmadie inspection 02/01/2023 - Safety Inspection on 02/01/2023	Total No Defects Recorded	redacted 11(2)	0		
1338066 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 25/01/2023	Total No Defects Recorded	redacted 11(2)	0		
1338498 M8 Polmadie, Safety Inspection, 16/01/23 - Safety Inspection on 17/01/2023	Total No Defects Recorded	redacted 11(2)	0		
1338520 Weather station inspections/validation - Weather Station - RCD Test on 17/01/2023	Total No Defects Recorded	redacted 11(2)	0		
1338520 Weather station inspections/validation - Weather Station - RCD Test on 18/01/2023	Total No Defects Recorded	redacted 11(2)	0		
1338520 Weather station inspections/validation - Weather Station - Visual Condition on 17/01/2023	Total No Defects Recorded	redacted 11(2)	0		
1338520 Weather station inspections/validation - Weather Station - Visual Condition on 18/01/2023	Total No Defects Recorded	redacted 11(2)	0		
1338601 M8 East Safety Patrol 19th Jan - Safety Patrol on 19/01/2023	Total No Defects Recorded	redacted 11(2)	0		
1338639 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 08/02/2023	Total No Defects Recorded	redacted 11(2)	0		
1338767 NSW M8 Polmadie Weather station B57671, Routine Insp, RCD test and Visual Condition - Electrical Component of Cabinet/Pillar - Periodic Electrical Inspection and Testing - B57671 on 27/01/2023	Total No Defects Recorded	redacted 11(2)	0		
1338767 NSW M8 Polmadie Weather station B57671, Routine Insp, RCD test and Visual Condition - Weather Station - Periodic Electrical Inspection and Testing - B57671 on 27/01/2023	Total No Defects Recorded	redacted 11(2)	0		
1338767 NSW M8 Polmadie Weather station B57671, Routine Insp, RCD test and Visual Condition - Weather Station - RCD Test on 27/01/2023	Total No Defects Recorded	redacted 11(2)	0		
1338767 NSW M8 Polmadie Weather station B57671, Routine Insp, RCD test and Visual Condition - Weather Station - Routine Electrical Inspection on 27/01/2023	Total No Defects Recorded	redacted 11(2)	0		
1338767 NSW M8 Polmadie Weather station B57671, Routine Insp, RCD test and Visual Condition - Weather Station - Visual Condition on 27/01/2023	Total No Defects Recorded	redacted 11(2)	0		
1338782 M8 East, Safety Patrol, 26th Jan - Safety Patrol on 26/01/2023	Total No Defects Recorded	redacted 11(2)	0		
1338843 M8 Polmadie, Safety Inspection, 30/01/23 - Safety Inspection on 30/01/2023	Total No Defects Recorded	redacted 11(2)	1		
1339078 M8 West - Safety Patrol - 2nd Jan - Safety Patrol on 02/02/2023	Total No Defects Recorded	redacted 11(2)	0		
1339152 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 22/02/2023	Total No Defects Recorded	redacted 11(2)	0		
1339224 M8 Polmadie Safety Patrol - Safety Patrol on 09/02/2023	Total No Defects Recorded	redacted 11(2)	0		
1339386 AD-HOC M8 Polmadie Safety Patrol 16-2-23 (redacted 11(2)) - Safety Patrol on 16/02/2023	Total No Defects Recorded	redacted 11(2)	0		
1339482 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 08/03/2023	Total No Defects Recorded	redacted 11(2)	0		
1340969 M8 Polmadie safety patrol, 2nd March - Safety Patrol on 02/03/2023	Total No Defects Recorded	redacted 11(2)	0		
1341086 NSW M8 Polmadie Night Inspection Route (14 day) (R) - Night Time Illuminated Safety Inspection on 22/03/2023	Total No Defects Recorded	redacted 11(2)	0		
1341222 M8 Polmadie Safety Patrol - Safety Patrol on 09/03/2023	Total No Defects Recorded	redacted 11(2)	0		
1341440 M8 east safety patrol, 16th March - Safety Patrol on 16/03/2023	Total No Defects Recorded	redacted 11(2)	0		
1341694 M8 Polmadie Safety Patyrol - Safety Patrol on 23/03/2023	Total No Defects Recorded	redacted 11(2)	0		
1341921 M8 Polmadie Safety Patrol, 30th March - Safety Patrol on 30/03/2023	Total No Defects Recorded	redacted 11(2)	0		
1342162 NSW M8 Polmadie Night Inspection Route (28 day) - Night Time Illuminated Safety Inspection on 05/04/2023	Total No Defects Recorded	redacted 11(2)	0		
1342323 NSW M8 Polmadie Safety Patrol Route (Thur 06-04-23) - Safety Patrol on 06/04/2023	Total No Defects Recorded	redacted 11(2)	0		
763172 NSW M8 Polmadie Safety Patrol Route (R) - Safety Patrol on 14/10/2022	Total No Defects Recorded	redacted 11(2)	0		
763454 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 12/04/2022	Total No Defects Recorded	redacted 11(2)	0		
763455 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 18/04/2022	Total No Defects Recorded	redacted 11(2)	0		
763456 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 19/04/2022	Total No Defects Recorded	redacted 11(2)	0		
763457 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 25/04/2022	Total No Defects Recorded	redacted 11(2)	0		
763458 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 28/04/2022	Total No Defects Recorded	redacted 11(2)	0		
763459 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 02/05/2022	Total No Defects Recorded	redacted 11(2)	0		
763460 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 04/05/2022	Total No Defects Recorded	redacted 11(2)	0		
763461 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 09/05/2022	Total No Defects Recorded	redacted 11(2)	0		
763462 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 12/05/2022	Total No Defects Recorded	redacted 11(2)	0		
763463 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 16/05/2022	Total No Defects Recorded	redacted 11(2)	0		
763464 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 17/05/2022	Total No Defects Recorded	redacted 11(2)	0		
763465 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 23/05/2022	Total No Defects Recorded	redacted 11(2)	0		
763466 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 26/05/2022	Total No Defects Recorded	redacted 11(2)	0		
763516 NSW M8 Polmadie Safety Patrol Route (R) - Safety Patrol on 27/05/2022	Total No Defects Recorded	redacted 11(2)	0		
763520 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 31/05/2022	Total No Defects Recorded	redacted 11(2)	0		

Wrong Facing - WFAC - CAT1

Permanent 26/01/2022

763937 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 06/06/2022	Total	0	redacted 11(2)	0
764008 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 07/06/2022	No Defects Recorded	0	redacted 11(2)	0
912677 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 10/06/2022	Total	0	redacted 11(2)	0
912721 NSW M8 Polmadie Night Inspection Route - Night Time Illuminated Safety Inspection on 19/05/2022	No Defects Recorded	0	redacted 11(2)	0
912722 NSW M8 Polmadie Night Inspection Route (R) - Night Time Illuminated Safety Inspection on 15/06/2022	Total	0	redacted 11(2)	0
912782 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 14/06/2022	No Defects Recorded	0	redacted 11(2)	0
912818 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 17/06/2022	Total	0	redacted 11(2)	0
942258 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 21/06/2022	No Defects Recorded	0	redacted 11(2)	0
942296 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 27/06/2022	Total	0	redacted 11(2)	0
942368 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 30/06/2022	No Defects Recorded	0	redacted 11(2)	0
942396 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 01/07/2022	Total	0	redacted 11(2)	0
951525 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 05/07/2022	No Defects Recorded	0	redacted 11(2)	0
951593 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 12/07/2022	Total	0	redacted 11(2)	0
951647 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 19/07/2022	No Defects Recorded	0	redacted 11(2)	0
951695 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 22/07/2022	Total	0	redacted 11(2)	0
951759 NSW M8 Polmadie Safety Patrol Route (R) - Safety Patrol on 08/07/2022	No Defects Recorded	0	redacted 11(2)	0
951815 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 26/07/2022	Total	0	redacted 11(2)	0
951871 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 29/07/2022	No Defects Recorded	0	redacted 11(2)	0
951893 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 02/08/2022	Total	0	redacted 11(2)	0
951986 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 05/08/2022	No Defects Recorded	0	redacted 11(2)	0
952014 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 09/08/2022	Total	0	redacted 11(2)	0
952062 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 12/08/2022	No Defects Recorded	0	redacted 11(2)	0
952085 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 16/08/2022	Total	0	redacted 11(2)	0
952115 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 19/08/2022	No Defects Recorded	0	redacted 11(2)	0
952174 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 23/08/2022	Total	0	redacted 11(2)	0
952205 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 29/08/2022	No Defects Recorded	0	redacted 11(2)	0
952220 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 01/09/2022	Total	0	redacted 11(2)	0
952257 NSW M8 Polmadie Safety Patrol Route (R) - Safety Patrol on 15/07/2022	No Defects Recorded	0	redacted 11(2)	0
952327 NSW M8 Polmadie Safety Inspection Route (R) - Safety Inspection on 02/09/2022	Total	0	redacted 11(2)	0
952347 NSW M8 Polmadie Night Inspection Route 12/07/22 - Night Time Illuminated Safety Inspection on 13/07/2022	No Defects Recorded	0	redacted 11(2)	0
952348 NSW M8 Polmadie Night Inspection Route 09/08/22 - Night Time Illuminated Safety Inspection on 10/08/2022	Total	0	redacted 11(2)	0
952349 NSW M8 Polmadie Night Inspection Route 06/09/22 - Night Time Illuminated Safety Inspection on 07/09/2022	No Defects Recorded	0	redacted 11(2)	0
952377 NSW M8 Polmadie Safety Inspection Route (Mon) (R) - Safety Inspection on 09/01/2023	Total	0	redacted 11(2)	0
	No Defects Recorded	0		0

Applied filters:SectorSlicer is 14215/06 - AGAINST:JCT 11 EB OFF SLIP TO ENTRY SLIP, 14215/16 - AGAINST: SLIP RD OFF M8 EB AT JCT 11, 14215/40 - AGAINST: EB M8 JCT 12 OFF SLIP TO JCT 11 ON SLIP, 14220/05 - WITH: M8 WB JCT 12 OFF SLIP TO ENTRY SLIP, 14220/06 - AGAINST: EB JCT 12 OFF SLIP TO ENTRY SLIP, or 14220/10 - AGAINST: JCT 12 GARTLOCH RD TO SLIP RD ENTRYDate is on or after 06/04/2022 00:00:00 and is before 07/04/2023 00:00:00