

Site	Current Site Status	Compliance monitoring visit frequency and dates	Community liaison meeting frequency and dates	Technical working group meeting frequency and dates	Ad hoc visits / inspections	Any formal enforcement actions?	Comments
Glenmuckloch	Coaling finished, restoration nearing completion	Last restoration visit 10/02/2017	Annual in ATH era	N/A	N/A	No	